



5020 Chesebro Road, Suite 200, Agoura Hills, CA 91301-4316 Tel. 818-597-3407, Fax 818-597-8001, www.aspeneg.com

PROJECT MEMORANDUM SDG&E'S SUNRISE POWERLINK PROJECT

To: Billie Blanchard, Project Manager, CPUC **From:** Vida Strong, Aspen Project Manager

Date: April 6, 2012

Subject: Weekly Report 79 – March 18 to March 24, 2012

INTRODUCTION

This report provides a summary of the construction and compliance activities associated with the SDG&E Sunrise Powerlink Project. This report is organized as follows:

- Transmission Line Construction
- Substation Construction and Upgrades
- Construction Yards and Other Workspaces

A summary of the Notices to Proceed with construction and Variance Request activity are also provided (see Tables 1 and 2, respectively, near the end of this report). Finally, a summary of Temporary Extra Workspace and non-compliance activity are provided in Tables 3 and 4, respectively.

CPUC/Aspen Environmental Monitors (EM): Cassandra Garza, Brian Woodward, Valerie Yep.

TRANSMISSION LINE CONSTRUCTION

Summary of Activity:

1. Link 1, 500 kV Overhead Transmission Line:

Non-Federal Lands:

- Vegetation maintenance occurred at Towers EP215, EP217-1 and EP218-1.
- Micropile drilling, pull testing, trimming, and cap work were conducted at EP254-3 (see Figures 1 and 2).
- Tower assembly took place at EP220-1 pull site, EP221-2, EP221A, EP225-1, EP228 (see Figure 3), EP237-1, and EP249-1.
- QA/QC occurred at EP219-1, EP220-1, from EP228 to EP230-1, from EP233-1 to EP236-1, EP239-1, EP240, EP245-1, and EP252-1.
- Snub installation was conducted at EP237-1 pull site.
- Sockline, hardline, and conductor were pulled from EP219-1 to EP220-1.
- Sagging took place at EP220-1 and from EP20-1 pull site to EP226-1 pull site.
- Insulator work was conducted at EP220-1 pull site and EP220-1.
- Jumpers were installed at EP220-1, EP223-1, and EP224-1.
- Dead-end work occurred at EP220-1 and EP223-1.
- Equipment was demobilized from EP220-1 pull site.
- Sockline, hardline, and conductor were flown for all phases from EP220-1 pull site to EP226-1 pull site (see Figure 4).

BLM Lands:

• Micropile capping work occurred at EP144, EP146, EP147, EP188-1, EP194-3, EP246, and EP249-1.





- Tower assembly was conducted at EP145 and from EP191-1 to EP195-2.
- QA/QC took place from EP171 to EP180, EP246, and EP247.
- Fiber optic work and fiber slicing was conducted at EP177.

2. Link 2, 500 kV Overhead Transmission Line:

Non-Federal Lands:

- Grading occurred at EP83, EP89-1, and EP91 pull sites and access roads.
- Micropile drilling occurred at EP48, EP50 (see Figure 5), EP62A-1, EP78, and EP83.
- Micropile grouting occurred at EP82 and EP88-2.
- Micropile capping work occurred at EP79.
- Conventional drilling occurred at EP65-1.
- Tower assembly occurred at EP1-3, EP67, EP84, EP85-2, and EP91.
- Ground resistance testing occurred at EP86-1, EP104-2, and EP105-2.
- Cleanup occurred at EP93.

BLM Lands:

- Vegetation maintenance occurred at EP71 and EP74-1.
- Grading occurred at EP98-1 and EP101-2 pull site.
- Access road improvements occurred from EP94-N to EP101-2-PS-E.
- Micropile drilling occurred at EP48-2, EP50, EP53-1, EP71, EP72, EP73, EP74-1, EP75-2, and EP76-2.
- Tower assembly occurred at EP68.
- Ground resistance testing occurred at EP103-2.

US Forest Service Lands:

- During this reporting period, the PALs were as follows: Monday: A, Tuesday: A, Wednesday: B, Thursday: B, Friday: B, and Saturday: B. Work activities ended each day in accordance with the Fire Plan and the approved EV letter as appropriate.
- Vegetation maintenance occurred at EP57-2 and EP58-1.
- Access road construction/maintenance occurred at EP9-1-N.
- Gate work occurred at EP35-1-N.
- Micropile drilling occurred at EP21-1, EP23-2, EP29-2, EP33-1, EP35-1, EP57, EP58-2, and EP115-1 (see Figure 6).
- Grouting occurred at EP19-1, EP20-2, EP21-1, EP22-1, EP25-2, EP28-3, EP31-1, EP33, EP34-1, EP35-1, EP118-2, EP120A, EP121-3, EP122-1, EP123-1, EP124, and EP129.
- Micropile trimming occurred at EP114-2.
- Micropile pull testing occurred at EP18, EP19-1, EP20-2, EP22-1, EP28-3, EP29-2, and EP114-2.
- Micropile capping occurred at EP2-3, EP5-2, EP7-1, EP8-2, EP13-3, EP14-1, EP16-1, EP17, EP18, EP28-3, EP116-1, and EP117-2.
- Conventional drilling occurred at EP36-1.
- Equipment was demobilized at EP11-3.
- Tower assembly occurred at EP109-1, EP112A-1, and EP113-5 (see Figure 7).
- QA/QC occurred at EP113-5.
- Ground resistance testing occurred at EP112A-1, EP113-5, and EP122-3.

- 3. Link 4, 220 kV Underground Transmission Line (non-federal lands only):
 - Revitalization occurred along Alpine Boulevard.
 - Vault work, equipment set-up, test set up, and high voltage testing occurred at the Loritz Property.
 - Sealing and hydroseeding occurred at the Bauer driveway.
 - Fiber splicing occurred at Vaults V2R, V15R, and V20R.
 - Storm drain repair occurred east of West Willows Road.
 - Coolant testing occurred within the bore pit.

4. Link 5:

Non-Federal Lands, 220 kV Overhead Transmission Line:

- Grading occurred at Tower CP43-1 pull site north.
- Final grading occurred at CP15-1 pull site east and CP43-1 pull site.
- Class II base was spread at CP15-1 pull site east.
- Micropile capping work occurred at EP35-2.
- Ground rod installation occurred at CP28-1 and CP33-2.
- Ground resistance testing occurred at CP74-2.
- QA/QC occurred at CP33A, CP34-2, and CP41-2 to CP48-2.
- Guard structure installation occurred at CP36-1, CP43-1, CP44-1, and CP53.
- Wire preparation occurred at CP43-1 and CP49-1.
- Traveler work occurred at CP51-2, CP52, CP54-1, and CP55.
- Sockline, hardline, and conductor were pulled on the north side from CP56-1 to CP65-1.
- Sagging occurred from CP56-1 to CP65-1.
- Deadend work occurred from CP58-1 to CP65-1.
- Splicing occurred at CP82-1.
- Cleanup occurred at CP47-2, CP51-2, CP52, and CP55.
- Restoration occurred at CP43-1 pull sites.

BLM Lands, 220 kV Overhead Transmission Line:

• No work occurred during this reporting period.

MCAS Miramar (Federal) Lands, 220 kV Overhead Transmission Line:

- Final grading occurred at CP15-1 pull sites.
- Cleanup at CP15-1.
- Restoration began at CP14 and CP15-1.

MCAS Miramar (Federal) Lands, 69 kV Reconductoring Line:

• No work occurred during this reporting period.

MCAS Miramar (Federal) Lands, 12 kV Reconductoring Line:

• No work occurred during this reporting period.

US Forest Service Land:

• No work occurred during this reporting period.

Environmental Compliance:

- 1. Biological, Cultural, and Native American monitors were present as applicable during all transmission line construction activities.
- 2. BMPs were installed, refreshed, or maintained on tower sites, access roads, TSAPs, and pads associated with towers on Link 1:

Non-Federal Lands:

- BMP maintenance and installation at tower sites, pull sites, and guard structure sites occurred from EP183 to EP185-2, EP199-3, from EP207 to EP211, from EP213 to EP215, from EP217-1 to EP219-1, EP220-1 guard structure, EP221-2, EP221A, from EP224-1 to EP227, from EP229-1 to EP238-1, from EP239-1 to EP253-2, EP255-2 pull sites and EP255-2.
- BMP maintenance and installation on access roads was conducted from EP183-N to EP185-2-N, EP199-3-N, and from EP207-N to EP220-1-N.
- Weed treatment took place at EP239-1, EP240, EP242, from EP243 to EP245-1 (including the pull site), and EP259.
- Habitat restoration signs were installed at EP219-1, EP296, from EP337 to EP339, EP358, and EP359.

BLM Lands:

- BMP maintenance and installation at tower sites, pull sites, and guard structure sites occurred from EP144 to EP152-2, from EP170 to EP182, from EP186-1 to EP198-3, from EP200-3 to EP205-2, EP195-2, from EP200-3 to EP206-1, EP314, EP315-1, and EP317.
- BMP maintenance and installation on access roads was conducted from EP173-1-N to EP182-N, from EP186-1-N to EP198-3-N, and from EP200-3-N to EP206-1-N.
- Weed treatment took place at EP247 guard structure, EP247, from EP342 to EP348, from EP350 to EP352, from EP354 to EP357, EP360, and EP362-1.
- Habitat restoration signs were installed at EP200A, EP201, EP203, EP204, EP294, EP295, from EP297 to EP299, EP314 pull site, from EP332 to EP336, from EP340 to EP347, EP349, EP351, EP352, from EP354 to EP357, EP360, and EP362-1.
- 3. BMPs were installed or refreshed on access roads, TSAPs, and pads associated with towers on Link 2:

Non-Federal Lands:

• BMP installation and maintenance occurred at EP1-4, EP25-2 to EP27-1, EP30-2 pull site to EP32-1, EP52-1, EP54-1, EP54-1 pull site, EP62A-1, EP64 to EP67 pull site, EP77 to EP81 (including pull site), CY-BARTLETT-E, EP84-E-B, EP83 to EP89-1 (including pull sites), EP91 to EP93 (including pull sites and access roads), EP104-2, EP104-2-N, EP105-2-N, EP105-2 to EP107-3, EP119-2, GS-NF-16, GS-NF-18, GS-NF-22, GS-NF-26, and GS NF 29.

US Forest Service Lands:

• BMP maintenance occurred at EP2-3 to EP9-1, EP9-1 pull site, EP11-3, EP11-3-N, EP12-3, EP12-3 pull sites, EP13-1 to EP16, EP19-1, EP20-2, EP22-1, EP22-1 pull site, EP23-2, EP23-2 pull site, EP24-1, EP34-1 to EP37-2, EP57-2, EP58-2, EP105-2-E-A, EP108-2 to EP113-5 (including the pull sites), EP116-1 to EP118-2 (including pull sites), EP120-4 to EP122-1, EP124, EP124/125 pull site, EP125, EP125-E-B, EP126-1, EP126-1-E, EP127, EP127-E, EP129-E-A, EP129-E-B, EP130-1, EP131, EP131 E, EP138-2-E-A, EP138-2-E-B, EP140-1, EP141, EP141-E-A, EP141 E B, EP141-E-C, EP141-N, EP141 to EP143-1 (including pull sites), and GS-USFS-3.

BLM Lands:

- BMP installation and maintenance occurred from EP39-1, EP41-1, EP42-2, EP42-2 pull site, EP47-2 pull site, EP48, EP50, EP51-1, EP53-3, EP56-4, EP63, EP68 to EP72, EP74-1 to EP76-2, , EP94 to EP99-2 (including access roads), EP103-2, EP103-2-N, EP103A, and EP103A-2-N.
- 4. BMPs were installed or refreshed on Link 4 (non-federal lands only):
 - BMPs were installed and/or refreshed along the entire right-of-way of Link 4.
- 5. BMPs were installed or refreshed on access roads, TSAPs, and pads associated with towers on Link 5:

Non-Federal Lands:

• BMP installation and maintenance occurred from CP15-1 pull site east to CP23, CP23-PS-N-A, CP25-2 to CP31-2 (including pull sites and guard structure), CP32-2, CP33-2, CP36-1, CP36-1 guard structure, CP37-2, CP40-2 to CP46 (including guard structures and pull sites), CP47A-1 to CP49-1, CP49-1-PS-E, CP49-1-PS-N, CP49-1 pull site, CP50-1 to CP53-1, CP56-1 pull site, CP56-1-PS-E-A, CP56-1-PS-E-B, CP65-1-PS-N, CP65-1 pull site, CP71, CP72-2, CP74-2 to CP84, CP85-1, CP86, CP87-1/CP88-1 pull site, CP95-1/CP96-1 pull site, CP98-1, and CP109-1.

BLM Lands:

• No BMP installation or maintenance occurred during this reporting period.

MCAS Miramar (Federal) Lands, 220 kV Overhead Transmission Line

• BMP installation and maintenance occurred at CP2, CP3, and CP6-1 to CP15-1 pull sites.

MCAS Miramar (Federal) Lands, 69 kV Reconductoring Line:

• No BMP activity occurred during the reporting period.

US Forest Service Lands:

- BMP maintenance occurred at CP99-2 and CP100-1.
- 6. One coastal rosy boa (*Charina trivigata*) was relocated from EP228. (Link 1)
- 7. On March 20, 2012, it was noted to the Link Lead that crews were parked off in non-project related areas off of Old Highway 80. Crews were immediately notified and vehicles were moved. (Link 1)
- 8. On March 21, 2012, it was noted that a basket was placed off approved work space (by a helicopter) at EP225. Corrective action was immediately taken. (Link 1)
- 9. On March 22, 2012, it was noted to the Link Lead that a vehicle was parked off approved project area near EP205-1 and that project related personnel was observed smoking in a non-designated area. (Link 1)
- 10. Minor leaks, drips, and releases on USFS lands were submitted to the USFS in a weekly HazMat log.
- 11. Pre-construction surveys were performed throughout Link 1, 2 and 5 with appropriate monitors.

No CPUC Non-Compliance Reports or Project Memoranda were issued during the subject period for transmission line construction activities. Non-Compliance activities for the project to date are summarized in Table 4.

Agency Representatives during Construction (other than EMs):

USFS Representatives: Robert Paul, Ed Wieringa, Jennifer MacDonald, Dana Barre.

SUBSTATION CONSTRUCTION AND UPGRADES

Summary of Activity:

- 1. Suncrest Substation, Link 3 (non-federal lands): Concrete base was poured for a retaining wall on the eastern portion of Bell Bluff Truck Trail (BBTT). The water line was cleaned up along BBTT. Fencing was installed around the water tank. Fill material was spread in the southeast quadrant to bring it to rough grade. Rough grading occurred in the southeast detention basin. The outlet headwall was formed and backfilled in the southeast detention basin. The storm drain was also installed in the southeast detention basin. Insulators and conductors were installed in the 230 kV and 500 kV yards. Coating of the insulators in the 500 kV yard and on the series capacitor occurred. Forms were built and concrete was poured for the retaining wall along the east cut slope. Wiring continued inside of the control shelter. Electrical testing was performed throughout the substation. Irrigation line was installed below Walls 2 and 3 on the southern fill slopes and in the southeast quadrant. The liner was removed from the temporary construction pond.
- 2. Imperial Valley (IV) Substation Upgrade (BLM lands): No Sunrise Powerlink related work occurred during this reporting period.
- 3. San Luis Rey Substation (non-federal lands): Wiring crews worked inside the control house. Crews performed set up, wiring preparation, and bus work inside the 69 kV rack.
- 4. Encina Substation (non-federal lands): Relay and wiring crews worked near the control house.
- 5. Pomerado Substation: (non-federal lands): Equipment staging and 69 kV setup work occurred.
- 6. Sycamore Substation (non-federal lands): Crews worked on 69 kV bus upgrades and wiring new gas circuit breakers in the 69 kV rack.

Environmental Compliance:

- 1. All applicable Biological, Cultural, Paleontological, and Native American monitors have been present during ground disturbing activities at all substations.
- 2. Hydromulch was applied to slopes on the perimeter of the Suncrest Substation pad. Vegetative growth is visible on previously hydromulched slopes (see Figure 8). (Link 3)

No CPUC Non-Compliance Reports or Project Memoranda were issued during the subject period for Substation Construction and Upgrade activities. Non-Compliance activities for the project to date are summarized in Table 4.

Agency Representatives during Construction (Other than CPUC EMs):

None.

CONSTRUCTION YARDS AND OTHER WORKSPACES:

Summary of Activity:

Non-Federal Lands:

- 1. Alpine Construction Yard Equipment/Materials staging, water staging, dust suppression, weed wash station operations, and staging for gate, road, BMP, and ESA crews occurred.
- 2. Alpine Headquarters Vegetation maintenance occurred and helicopters picked up and dropped off personnel.
- 3. AER Yard Yard has been restored.
- 4. Barrett Canyon Yard No activity occurred during the reporting period.
- 5. Bartlett-Hauser Yard Water staging, helicopter operations, weed wash station operations, dust suppression, tower assembly, and staging for micropile, erection, vegetation maintenance, assembly, QC, wire, road, and BMP crews (see Figure 9) occurred.

- 6. Fromm Yard No work occurred at this yard during this reporting period.
- 7. El Monte Yard Driveway work and removal of rumble plates occurred.
- 8. Helix Yard Helicopter operations, weed wash station operations, dust suppression, and staging for assembly, wire, road, BMP, and QC crews occurred.
- 9. Jacumba Valley Ranch (JVR) Yard Helicopter operations, weed wash station, water staging, dust suppression, tower assembly, and water staging. Also used for staging QC, micropile, habitat assessment, and assembly crews.
- 10. Kreutzkamp Yard Helicopter operations, weed wash station operations, water staging, dust suppression, tower assembly, QC at yard, vegetation maintenance, and staging for conventional foundation, assembly, BMP, hauling, road, and erection crews occurred.
- 11. Rough Acres Yard Helicopter operations, tower assembly, water staging, dust suppression, equipment and materials staging, and usage of the weed wash station took place. This yard was also used for staging erection, QC, assembly, hauling, road, wire, micropile, and BMP crews.
- 12. SWAT Yard Water staging, helicopter operations, dust suppression, weed wash station operations, and staging for micropile, vegetation maintenance, conventional foundation, and BMP crews occurred.
- 13. S2 Yard Yard had been restored.
- 14. Sycamore Yard Dust suppression, helicopter operations, water staging, and staging for micropile, road, and BMP crews occurred.
- 15. Wilson Yard Dust suppression and tower assembly occurred in this yard.

Federal Lands (BLM):

- 16. Dunaway Yard Yard has been restored.
- 17. Imperial Valley Yard Yard has been restored.
- 18. McCain Valley Yard Helicopter operations, dust suppression, tower assembly, weed wash station usage, and water staging occurred. The yard was also used to stage BMP crews.
- 19. Plaster City Yard Water staging, tackifier application (see Figure 10), and wildlife fence removal along the yard perimeter occurred.

Federal Lands (USFS):

20. Thing Valley Yard – Helicopter operations (see Figure 11), water staging, dust suppression, tower assembly, hauling of steel, repair earthwork associated with erosion damage to pull site within yard, tackifier application, and staging for BMP, assembly, road, and micropile crews occurred.

Environmental Compliance:

- 1. Biological, Cultural, and Native American monitors have worked with crews at the construction yards to define approved work areas and sites to avoid.
- 2. On March 20, 2012, it was noted to the Link Lead that marker balls were being staged inside of an Environmentally Sensitive Area (ESA) at Jacumba Valley Ranch Yard (see Figure 12). Marker balls were immediately moved outside of the ESA. (Link 1)
- 3. Two coronado skinks (*Plestiodon skiltonianus interparietalis*) and one two-striped garter snake (*Thamnophis hammondii*) were relocated from the vicinity of Kreutzkamp Yard. (Link 2)

No Non-Compliance Reports or Project Memorandums were issued during the subject period for Construction Yards and other workspace activities. Non-Compliance activities for the project to date are summarized in Table 4.

Agency Representatives during Construction (other than CPUC EMs):

None.

CPUC NOTICES TO PROCEED (NTPs)

Table 1 summarizes the CPUC Notice to Proceed activity for the SDG&E Sunrise Powerlink Project to date.

TABLE 1 CPUC NTPs

(Updated 04/06/2012)

| | Date | Date | | |
|---------|-----------|----------|-----------------------|---|
| NTP# | Requested | Issued | Segment | Description |
| #1 | 01/04/10 | 04/28/10 | 25 | San Luis Rey Substation Upgrades |
| #2 | 02/08/10 | 04/29/10 | 23 | South Bay Substation Upgrades |
| #3 | 02/26/10 | 05/20/10 | Yard | Alpine Yard 18 |
| #4 | 01/26/10 | 05/28/10 | Yard | Alpine Yard 18A |
| #5 | 02/05/10 | 09/28/10 | Yard | Rough Acres Yard, Phase 1 |
| #6 | 05/26/10 | 09/28/10 | 24 | Encina Substation Upgrades |
| #7 | 05/28/10 | 09/28/10 | Telecomm | White Star Communication Facility |
| #8 | 06/09/10 | 10/06/10 | Substation | Pomerado Substation Upgrades |
| #9 | 06/09/10 | 10/06/10 | Substation | Scripps Switchyard/Substation Upgrades |
| #10 | 10/13/10 | 11/23/10 | 15 | Link 4, Alpine 230 kV Underground Construction |
| #11 | 10/19/10 | 12/15/10 | 13 | Link 3, Suncrest Substation/Wilson Construction Yard |
| #12 | 11/30/10 | 12/23/10 | Yard | Rough Acres Yard, Phase 2 |
| #13 | 11/09/10 | 01/14/11 | 2-18, 20-22 | Links 1, 2, and 5, overhead construction on non- federal lands |
| BLM #1 | 01/19/11 | 02/03/11 | 1 | Imperial Valley Substation upgrades. |
| BLM #2 | 03/28/11 | 04/04/11 | 2-12, 16-17 | Links 1, 2, and 5 overhead construction on BLM Lands. |
| Miramar | 01/20/11 | 06/28/11 | 22 | Overhead and substation construction. |
| USFS | 07/29/11 | 08/09/11 | 6, 7, 10, 12,14,16 | Links 1, 2, and 5 overhead construction on USFS Lands. |

VARIANCE & TEMPORARY EXTRA WORKSPACE REQUESTS

Variance and Temporary Extra Workspace (TEWS) requests submitted to date are presented in Tables 2 and 3, respectively.

TABLE 2 VARIANCE REQUESTS

(Updated 04/06/2012)

| Variance | Date | | | |
|----------|-----------|-------------|---------|---|
| Request | Requested | Date Issued | Segment | Description |
| #1 | 11/04/10 | 11/10/10 | Yard | Thomas Yard (El Centro, CA) |
| #2 | 12/22/10 | 03/18/11 | Yard | Sycamore Estates Construction Yard. Response to inquiry received 02/23. |

| Variance | Date | | | |
|----------|-----------------------|-----------------|----------------------|--|
| Request | Requested | Date Issued | Segment | Description |
| #3 | 01/06/10 | 01/18/11 | All | Modification to tree trimming requirements. |
| #3 MOD | 01/25/11 | 01/26/11 | All | Modification to brush clearing requirements. |
| #4 | 01/13/11 | 03/01/11 | Yard | Helicopter Temporary Landing Pad area at the Alpine Regional Field Offices. |
| #5 | 02/01/11 | 02/09/11 | Yard | Site improvements at the Wilson Construction yard and along Bell Bluff Trail |
| #6 | 02/01/11 | 03/01/11 | Link 5 | Variance from Mitigation Measure H-1a (CC) to allow work outside of the dry season. |
| #7 | 02/11/11 | 02/17/11 | Link 3 | Additional work areas for construction trailers, parking, etc. |
| #8 | 03/02/11 | 03/08/11 | Link 2 | Alternate access route to Structure EP 27. |
| #9 | 03/29/11 | 04/06/11 | All | Perform construction activities outside of hours allowed by local ordinances with local jurisdiction approval. |
| #10 | 04/04/11 (revised) | 04/14/11 | Link 4 | Additional construction work space at Viejas Creek Bridge. |
| #11 | 04/06/11 | 04/22/11 | Link 1 | Additional workspace east of EP215. |
| #12 | 04/15/11 | 04/25/11 | Link 1 | Additional turnaround along the access road to EP 220-1. |
| #13 | 04/13/11 | 05/06/11 | Links 1 & 2 | Two fiber optic regeneration sites. |
| #14 | 04/28/11 | 05/03/11 | Yards | Change visual screening at Project construction yards from slats to fabric. |
| #15 | 05/12/11 | 05/19/11 | Link 2 | Alternate access to EP 84. |
| #16 | 05/16/11 | 05/21/11 | Link 4 | Additional parking space for use during underground construction. |
| #17 | 05/18/11 | 05/24/11 | Encina Substation | Driveway improvement. |
| #18 | 06/27/11 | 07/14/11 | Link 1 | Gate installation between mile markers 38.5 and 39.5. |
| #18 Mod | 10/03/11 | Under Review | Link 1 | Alternative for installation of Gate #4. |
| #19 | 06/27/11 | 06/29/11 | Link 1 | Installation of training tower at Rough Acres Construction Yard. |
| #20 | 06/28/11 | 08/05/11 | Link 5 | Additional disturbance for access, pull sites and topsoil stockpile at CP48-2 to CP51-2. |
| #21 | 07/07/11 | 07/15/11 | Link 1 | Guard structure from EP255 to Imperial Valley Substation. |
| #22 | 07/08/11 | 08/04/11 | Link 1 | Fromm Construction Yard. Additional information submitted 08/04. |

| Variance | Date | | | |
|---------------|-----------|-------------|------------------------|--|
| Request | Requested | Date Issued | Segment | Description |
| BLM DNA #1 | 07/19/11 | 08/05/11 | Link 1 | Minor modifications to portions of the Project on Bureau of Land Management lands. |
| #23 | 08/15/11 | 10/20/11 | Links 1, 2, & 5 | Additional landing platforms and TSAPS. |
| #24 | 08/25/11 | 08/29/11 | Suncrest Substation | Additional vegetation clearing around construction trailers. |
| #25 | 09/01/11 | 09/09/11 | Links 1 & 5 | Extended use of approved TEWS areas for parking and staging. |
| #26 | 09/15/11 | 09/20/11 | Link 2 | Water tank installation at Barrett Canyon Yard. |
| #27 | 09/20/11 | 10/18/11 | Link 1 | Temporary Staging area near Mountain Springs Grade Road. |
| #28 | 10/19/11 | Denied | Link 3 | Allow work to continue at Suncrest Substation during a Red Flag Warning (RFW) event. |
| #29 | 10/21/11 | 11/01/11 | Links 1, 2, & 5 | Additional guard structures identified for wire pulling activities. |
| #29 Mod | 01/04/12 | 01/06/12 | | Modification to guard structure location. |
| #30 | 11/01/11 | 11/15/11 | Links 1, 2, & 5 | Temporary parking and turnaround areas. |
| #30 Mod | 02/09/12 | 02/09/12 | Links 5 | Modification to perform long lining activities. |
| #31 | 11/08/11 | Retracted | Links 2 & 5 | Request for site specific exemption of Condition 37 of NTP 13. |
| #32 | 11/15/11 | 12/09/11 | Links | Additional workspace for wire pulling activities. |
| #32 Mod | 01/04/12 | 01/06/12 | 1, 2, & 5 | Modification to guard structure location |
| #33 | 11/28/11 | 12/16/11 | Links 1, 2, & 5 | Additional workspace for structure access and wire pulling activities. |
| #34 | 11/29/11 | 12/02/11 | Links 2 & 5 | Extension of allowable work window within GE buffer (MM B-7h). |
| #35 | 12/22/11 | 01/04/12 | Link 5 | Improvements to existing road & drainage, Simpson property. |
| #36 | 01/20/12 | 02/08/12 | Links 1, 2, & 5 | Variance to allow vegetation clearing between January 15 through February 14. |
| #37 | 01/20/12 | 02/08/12 | Links 1, 2, & 5 | Temporary placement of concrete blocks outside of approved work areas. |
| #38 | 02/10/12 | 02/22/12 | Link 5 | Gate installation near CP55. |
| #39 | 02/10/12 | Retracted | Link 5 | Additional work space at CP23 pull site. |
| #40 | 03/20/12 | 03/21/12 | Link 5 | Additional work space near GS-NF-7, San Vicente Reservoir. |

TABLE 3 TEMPORARY EXTRA WORKSPACE (TEWS) REQUESTS (Updated 04/06/2012)

| Request Requested Apple TEWS #1 11/01/10 11, TEWS #2 03/17/11 03, TEWS #3 03/17/11 03, TEWS #4 03/22/11 03, | Date proved // 01/10 // 18/11 // 18/11 // 23/11 // 24/11 // 24/11 // 07/11 | Segment White Star Link 4 Link 4 Link 5 Link 4 | Description Asphalt paved area for vehicle parking and staging Parking on Puetz Valley and Alpine Blvd Parking on Harbison Canyon and Alpine Blvd Storage on One Father Junipero Sierra Trail |
|---|--|--|--|
| TEWS #1 11/01/10 11, TEWS #2 03/17/11 03, TEWS #3 03/17/11 03, TEWS #4 03/22/11 03, | /01/10 /18/11 /18/11 /23/11 /24/11 /24/11 | White Star Link 4 Link 4 Link 5 | Asphalt paved area for vehicle parking and staging Parking on Puetz Valley and Alpine Blvd Parking on Harbison Canyon and Alpine Blvd |
| TEWS #2 03/17/11 03, TEWS #3 03/17/11 03, TEWS #4 03/22/11 03, | /18/11 /18/11 /23/11 /24/11 /24/11 | Link 4 Link 4 Link 5 | Parking on Puetz Valley and Alpine Blvd Parking on Harbison Canyon and Alpine Blvd |
| TEWS #3 03/17/11 03, TEWS #4 03/22/11 03, | /18/11 /23/11 /24/11 /24/11 | Link 4 Link 5 | Parking on Harbison Canyon and Alpine Blvd |
| TEWS #4 03/22/11 03, | /23/11 /24/11 /24/11 | Link 5 | |
| | /24/11 /24/11 | | Storage on One Father Julipero Sierra Hall |
| TEWS #5 03/24/11 03/ | /24/11 | LIIIN 4 | Parking at 3900 Willows Road West |
| | | Link 4 | Parking at 5840 Willows Road East |
| | | Link 2 | Northern access road to EP 79 |
| | /14/11 | Link 2 | Northeast spur of access road to EP 84 |
| | /24/11 | Link 1 | Use of SWPL tower sites for parking (EP331-341) |
| | /24/11 | Link 5 | Parking and pullsite adjacent to Alliant University |
| | /16/11 | Link 1 | Use of alternative access to EP 240, per the |
| | , 10, 11 | ZX Z | request of the landowner at JVR |
| TEWS #12 06/20/11 06/ | /20/11 | Link 1 | Use of SWPL tower sites for parking (EP295-299) |
| TEWS #13 06/30/11 07, | /01/11 | Link 1 | Use of SWPL tower site for parking (EP324) |
| TEWS #14 07/01/11 07/ | /01/11 | Link 1 | Use of SWPL tower sites for parking (EP300, EP302, EP306, EP307, EP312) |
| TEWS #15 07/06/11 07/ | /06/11 | Link 1 | Use of SWPL tower sites for parking (EP294, EP303, EP304, EP305) |
| TEWS #16 06/30/11 07/ | /07/11 | Link 1 | Additional parking along Mountain Springs Grade Road |
| TEWS #17 07/11/11 07, | /12/11 | Link 5 | Parking near CP20 |
| TEWS #18 07/11/11 07, | /12/11 | Link 5 | Parking near CP24 |
| TEWS #19 07/11/11 07, | /12/11 | Link 5 | Parking near CP29 |
| TEWS #20 07/18/11 07, | /19/11 | Link 1 | Parking near EP314 |
| TEWS #21 07/22/11 07, | /25/11 | Link 1 | Parking near EP315 |
| TEWS #22 07/26/11 07, | /26/11 | Link 1 | Parking near EP291-293 |
| TEWS #23 08/05/11 08, | /05/11 | Link 1 | Parking near EP290 |
| TEWS #24 08/09/11 08/ | /10/11 | Link 2 | Parking near EP90/EP91 |
| TEWS #25 09/07/11 09, | /07/11 | Link 5 | Temporary use of access road near El Monte Road (12 kV) |
| TEWS #26 09/13/11 09, | /13/11 | Link 2 | Temporary use of access road near Barrett Substation |
| TEWS #27 09/29/11 09/ | /30/11 | Link 1 | Parking near EP248. |
| TEWS #28 09/28/11 10, | /03/11 | Link 1 | Parking and Staging area adjacent to EP301. |
| TEWS #29 09/13/11 09/ | /13/11 | Link 2 | Placement of Water Tank at Barrett Substation. |
| TEWS #30 10/06/11 10, | /06/11 | Link 1 | Parking and Staging at Chevron Gas Station on Carrizo Gorge Road. |
| TEWS #31 11/09/11 11, | /10/11 | Link 1 | Parking at EP252A-1 and EP254-3-E. |
| TEWS #32 11/09/11 11, | /15/11 | Link 5 | Temporary material and equipment staging area off of Willows Road. |

| TEWS | Date | Date | | |
|----------|-----------|----------|---------|---|
| Request | Requested | Approved | Segment | Description |
| TEWS #33 | 02/09/12 | 02/09/12 | Link 5 | Additional parking area between CP75 to CP88. |
| TEWS #34 | 03/06/12 | 03/06/12 | Link 5 | Additional parking area along Hwy 67. |
| TEWS #35 | 03/26/12 | 03/27/12 | Link 1 | Additional parking area between EP227/EP228. |

NON-COMPLIANCES & INCIDENTS

CPUC and USFS Stop Work Orders, Project Memorandum (PM) and Non-Compliance Reports (NCR), and U.S. Army Corps Non-Compliances (NC) that have been issued to date are presented in Table 4.

TABLE 4
NON-COMPLIANCES (NC) AND PROJECT MEMORANDA (PM)
(Updated 04/06/2012)

| Туре | Date | Location | Description |
|--------------------|----------|------------------------------|--|
| PM #1 | 12/07/10 | Thomas Yard | Failure to report unanticipated biological resources within 48 hours. |
| PM #2 | 02/11/11 | EP 242, Link 1 | Unauthorized ground disturbance at EP 242 |
| NC #1 | 03/08/11 | Suncrest Substation | Army Corp of Engineers issued Non-Compliance for not complying with Special Conditions 19, 21 and 23 of DA Permit SPL-2007-00704-SAS. |
| PM #3 | 03/15/11 | CP 67-3, Link 5 | Staking crews operating and delivered by helicopters within GE Buffer area. |
| PM #4 | 04/06/11 | Swat Yard | Unauthorized Nest Removal from a water truck at SWAT Construction yard. |
| PM #5 | 05/16/11 | EP 340, Link 1 | Operation of water trucks outside of approved disturbance areas at EP 340. |
| PM #6 | 09/16/11 | EP271, Link 1 | Construction activities commenced at EP271 prior to the arrival of biological monitor. |
| Stop Work Order | 09/27/11 | Helicopter Operation s | A pattern of helicopter incidents posed a serious concern for the safety of the general public. |
| PM #7 | 09/28/11 | AER CY | Construction crew entered AER CY prior to Peninsular Bighorn Sheep monitor clearing the site. |
| NCR #1 | 09/28/11 | Link 1 | CPUC issued NCR for breeching a marked Environmentally Sensitive Area (ESA), construction activity without proper monitor present, and failing to communicate the event in a timely fashion. |
| FS NCR #1 | 10/27/11 | Links 2 & 5 | FS SUP Exhibit 4 and Traffic Control Plan violations. |
| NCR #2 | 10/27/11 | Link 1 | Peninsular Bighorn Sheep Construction Monitoring Plan violations. |
| FS NCR #2 | 11/03/11 | Links 2 & 5 | Fire Plan and Traffic Control Plan violations. |

12

| Туре | Date | Location | Description |
|-----------------------|----------|----------------|--|
| FS NCR #3 | 11/30/11 | Links 2 & 5 | Tower assembly, erection and wire stringing work is suspended for towers not associated with GE buffers on the Cleveland National Forest until resolution of all noncompliance colorization issues are agreed upon by the Forest Service |
| NCR #3 | 12/29/11 | Link 1 | Peninsular Bighorn Sheep Construction Monitoring Plan violations. |
| NCR #4 | 01/04/12 | Link 1 | Peninsular Bighorn Sheep Construction Monitoring Plan violations. |
| FS Stop Work Order | 01/07/12 | Links 2 & 5 | Third non-compliance for violating the Forest Service Fire Plan. |
| FS NCR #4 | 02/01/12 | Link 2 | Failure to make timely notification following rope/wire drop between CP100 to CP99. |
| FS NCR #5 | 02/06/12 | Links 2 & 5 | Helicopter incursions into Golden Eagle Habitat Buffers. |
| NCR #5 | 02/08/12 | Link 1 | Construction outside of approved work spaces, intrusion into ESA, and violation of Desert Pavement Plan. |

Other compliance incidents identified by SDG&E monitoring staff and/or crews are presented in Table 5.

TABLE 5 PROJECT INCIDENTS

(Updated 04/06/2012)

| Туре | Date | Location | Description |
|----------|----------|----------------------|--|
| Incident | 11/01/10 | White Star | Delivery of a rebar cage outside of the approved disturbance area. |
| Incident | 02/17/11 | EP 244, Link 1 | Nest incorrectly marked at entrance to EP 244. |
| Incident | 02/18/11 | Alpine HQ | Emergency weather landing and storage of 3 helicopters at Alpine HQ. |
| Incident | 03/12/11 | EP 252, Link 1 | Bulldozer was delivered at site prior to CPUC clearance being given. |
| Incident | 03/15/11 | EP 214, Link 1 | Dewatering approximately 1 gal of groundwater from an excavation hole without having submitted a dewatering plan to the CPUC. |
| Incident | 04/06/11 | JVR 12 kV, Link 1 | Confusion on approved work areas due to varying maps having been distributed to workers and monitors. |
| Incident | 04/07/11 | JVR 12 kV, Link 1 | A site was worked on prior to CPUC EM construction release having been received for the area, no resources were damaged. |
| Incident | 05/05/11 | Link 4 | Three small fires were reported on Link 4 Underground. Fire tools were used by the on-site fire patrol to immediately respond per the Sunrise Fire Plan. Notification to Alpine Fire was made. |

| Туре | Date | Location | Description |
|----------|----------|----------|--|
| Incident | 05/17/11 | Link 1 | BMP crew drove off the road between EP345 and EP346 and park within the ESA boundary. |
| Incident | 06/07/11 | Link 1 | During the aerial delivery of a structure body to EP339, approximately 200 ft outside of Plaster City Yard, the piece fell from the Aircrane. No injuries have been reported. |
| Incident | 06/10/11 | Link 1 | During the aerial delivery of a structure layback to EP 339, at the EP 339 construction site, 3 of the 4 hooks released and caused an emergency placement of the steel at the site. While in the process of placing on the ground, the 4 th hook released and the tower fell to the ground. No injuries have been reported. |
| Incident | 07/07/11 | Link 1 | A project water tanker was stuck on the side of Evan Hughes Highway and released approximately 1,000 gallons of potable water into Coyote Wash, after pulling over to evaluate a bridge crossing. All necessary notifications were made. |
| Incident | 07/07/11 | Link 5 | Construction vehicles, including project fire truck, were noted to be outside of approved disturbance areas at CP40 and CP41. Link leads were notified and immediate corrective action was taken. |
| Incident | 07/11/11 | Link 1 | A skid fell off the KMax Helicopter while en route to a tower site. The skid was within the Project ROW and no injuries were reported. The item was retrieved on foot. |
| Incident | 07/28/11 | Link 1 | Unapproved disturbance of approximately 50'x100' occurred during the grading operations of the AER yard. No resources were impacted. |
| Incident | 08/04/11 | Link 1 | An air compressor was dropped approximately 500 ft north of EP327, from a KMax helicopter while in transit to a micropile site. Approximately 50-60 gallons of diesel was spilled in an area of approximately 75' in diameter. Site has been cleared and appropriate agencies have been contacted. |
| Incident | 08/05/11 | Link 3 | Small fire resulted from excavation activities along BBTT. Burned an area approximately 50'x50' prior to it being extinguished. Notifications were made immediately. |
| Incident | 08/13/11 | Link 2 | Accident along Lyons Valley Rd, where a project truck went off the embankment by 300'. No injuries reported. Assessment team was sent to the site and notifications were made. |
| Incident | 08/15/11 | Link 2 | Sparks caused by loose chain from a project vehicle interacting with the roadway started a 2-acre fire. The fire was extinguished and proper notifications were made. |

| Туре | Date | Location | Description |
|----------|----------|----------|--|
| Incident | 08/18/11 | Link 2 | An unsteady load caused a forklift to fall to its side at EP 91. A small spill of hydraulic fluid took place, all disturbance was contained within the established work area, and no injuries were reported. |
| Incident | 08/22/11 | Link 1 | Crew member threw a rock and knocked down a rock cairn located within an ESA. Appropriate agencies were notified. |
| Incident | 09/08/11 | Link 2 | CPUC EM noted a water truck entering EP91 after not having stopped at designated wash station. Corrective action was taken. |
| Incident | 09/12/11 | Link 5 | Crew performed minor clearing prior to the arrival of biological monitor. |
| Incident | 09/13/11 | Link 5 | Crew performed minor clearing prior to the arrival of biological monitor. |
| Incident | 09/15/11 | Link 5 | Micropile platform at CP67-3 rolled 50' downhill after unstable placement. A helicopter removed from site to limit damage. Minor vegetation damage that was surveyed by onsite biologist. |
| Incident | 09/19/11 | Link 2 | Small fire near EP42 started due to excavator hitting a rock during grading operations. This was immediately put out by onsite personnel using their required fire supplies. |
| Incident | 09/19/11 | Link 2 | 2 Micropile pipes were dropped during helicopter operations near CP107 and rolled down hill to injure a worker trying to stop them. Minor vegetation damage that was surveyed by onsite biologist. |
| Incident | 09/20/11 | Link 1 | Trackout from EP252 was noted to Link Lead and was immediately remedied. |
| Incident | 09/20/11 | Link 1 | Project vehicles were noted to parking outside of the approved project disturbance. Link Lead was notified and vehicles were immediately relocated. |
| Incident | 09/21/11 | Link 1 | Dozer operator drove approximately 260 ft off of ROW near EP322. Area was surveyed Cultural and Biological monitor. |
| Incident | 09/21/11 | Link 3 | Approximately 800 gallons of potable water was released from Northern Sediment basin. Appropriate agencies were notified. |
| Incident | 09/22/11 | Link 3 | Plywood load from helicopter dropped within substation boundaries. No injuries were reported. |
| Incident | 09/23/11 | Link 1 | Improperly covered foundations holes were noted to the Link Lead. Follow up was performed with crews. |
| Incident | 09/26/11 | Link 1 | Straw wattles en route via helicopter dropped into open area. No injuries were reported. |
| Incident | 10/12/11 | Link 1 | A drill rig pulled to the side of the access road near EP185/EP186 and inadvertently crushed vegetation. |

| Туре | Date | Location | Description |
|----------|----------|----------|---|
| Incident | 10/12/11 | Link 4 | Approximately 50 gallons of diesel fuel was released immediately off of Puetz Valley Road Site was cleaned and stained soils removed. Appropriate agencies were contacted. |
| Incident | 10/19/11 | Link 1 | A door fell off a helicopter near Plaster City Yard close to EP332. No injuries were reported. |
| Incident | 11/03/11 | Link 1 | Injury occurred when a tower leg fell onsite. Events surrounding the incident are still undergoing investigation. Disturbance occurred outside of approved areas. Biological/cultural monitors reviewed and found no resources to be damaged. |
| Incident | 11/05/11 | Link 5 | Sediment off ROW at CP55/56 access road. |
| Incident | 11/09/11 | Link 2 | Landing of project helicopter on unapproved disturbance areas. |
| Incident | 11/15/11 | Link 5 | Off ROW incident along access road to CP65/66 pull site. |
| Incident | 11/16/11 | Link 1 | Off ROW incident along access road to EP 226/227 pull site. |
| Incident | 11/16/11 | Link 3 | Trash noted to be blown around during Air Crane activities at the Wilson Yard. |
| Incident | 11/22/11 | Link 5 | Track out noted on El Monte Rd from access in/out of CP64/65 pull site. Street sweeper was dispatched. |
| Incident | 12/03/11 | Link 1 | PBHS habitat violation with low elevation flights in restricted areas. |
| Incident | 12/04/11 | Link 1 | PBHS habitat violation with low elevation flights in restricted areas. |
| Incident | 12/22/11 | Link 1 | PBHS habitat violation with entry into Fromm Yard prior to clearance from PBHS biologists. |
| Incident | 12/27/11 | Link 1 | Two PBHS habitat violation with low elevation flights in restricted areas. |
| Incident | 01/09/12 | Link 2 | Road crew operating without an Arroyo Toad Monitor present at EP50, Arroyo Toad suitable habitat. Crew was retrained of the importance of a monitor being present during operations. |
| Incident | 01/10/12 | Link 2 | Foundation crew damaged an oak tree during mobilization effort at EP49. Crew was retrained. |
| Incident | 01/12/12 | Link 1 | Parking along McCain Valley Rd not in designated disturbance areas. Link Leads corrected immediately. |
| Incident | 01/12/12 | Link 5 | A dozer failure led to disturbance outside of approved ROW by 15 feet near CP59. All personnel were safe and restoration efforts are in process. |
| Incident | 01/13/12 | Link 2 | An unanticipated release of a compressor mid-flight approximately 400ft North of Kruetzkamp CY. No injuries or damage to property occurred. Investigation to helicopter hook system is ongoing. |

| Туре | Date | Location | Description | | |
|----------|----------|----------|--|--|--|
| Incident | 01/17/12 | Link 2 | Crew entered access road to EP73/74, Arroyo Toad suitable habitat, prior to the 2-hr waiting period following dawn and biological monitor clearance. Crew was spoken to and better signage is to be installed. | | |
| Incident | 01/18/12 | Link 1 | Concrete blocks were placed outside of approved disturbance area at EP224/5 prior to the approval of Variance #37. To limit disturbance, blocks have been left, but cannot be used until approval of the variance. | | |
| Incident | 01/18/12 | Link 1 | Assembly crew arrived at EP177 prior to an approved bird survey having been conducted and submitted. Crews were ushered out by onsite avian biologist performing said survey. | | |
| Incident | 01/18/12 | Link 1 | Foundation crew entered PBHS habitat at EP256 outside of approved work window. They were escorted out by monitors at a nearby site upon noticing. GF for crew was released by the project and a standdown with GF and foreman was performed on 01/23/12. | | |
| Incident | 01/19/12 | Link 2 | Bird strike occurred during helicopter operations near EP33. Monitors on board believed the bird to be a swallow, but no remains were found to confirm. | | |
| Incident | 01/20/12 | Link 5 | Wire dropped between CP96 and CP100 during wire operations. No resources were found to be damaged, hurt or killed. | | |
| Incident | 01/20/12 | Link 5 | Gate left open for access road to pull site between CP64/65 and released livestock that was present. Monitors were brought onsite to herd them back into the pen and ensure security of the gate. | | |
| Incident | 01/24/12 | Link 5 | Helicopter breached the GE buffer at Bell Bluff region approximately 621 feet. No resources impacted. | | |
| Incident | 01/25/12 | Link 5 | Helicopter was noted by CPUC EM to have landed outside of approved project workspace. Correction was made immediately and discussion was had with pilot about landing in only approved areas. | | |
| Incident | 01/26/12 | Link 5 | Helicopter breached the GE buffer at the Bell Bluff region approximately 521 feet. No resources impacted. | | |
| Incident | 01/27/12 | Link 2 | Helicopter breached the GE buffer at the Thing Valley region approximately 161 feet. No resources impacted. | | |
| Incident | 01/31/12 | Link 1 | Fuel tanker was refueling a smaller fuel truck for use by project helicopters in unapproved workspace near JVR. Link Lead made immediate correction and spoke to crew. | | |
| Incident | 02/01/12 | Link 2 | Helicopter breached the GE buffer at the Thing Valley region by an unknown amount. No resources impacted. | | |
| Incident | 02/13/12 | Link 2 | Several contractor vehicles were parked outside of the ROW on brush adjacent to Cameron TT near EP109. Link Lead was contacted and item was corrected. | | |

| Туре | Date | Location | Description | | |
|----------|----------|----------|--|--|--|
| Incident | 02/24/12 | Link 2 | Helicopter dragged a long line through vegetation outside of workspace at EP109. Minor vegetation impacts. | | |
| Incident | 02/25/12 | Link 5 | Helicopter experienced a hard landing at the Sycamore CY and damage was incurred. No injuries or impacts were noted. Investigation is ongoing. | | |
| Incident | 02/27/12 | Link 3 | Trash was noted to Link Lead at the Wilson CY. | | |
| Incident | 02/28/12 | Link 1 | Project activities were noted to be occurring in PBHS areas without concurrence from Wildlife Agencies provided to CPUC monitors. Follow up discussion occurred with WA. | | |
| Incident | 02/29/12 | Link 1 | Debris was noted to the Link Lead as being blown around JVR CY during Air Crane operations. | | |
| Incident | 03/02/12 | Link 2 | Kmax helicopter dropped cribbing near EP5. No reports of injuries or impacts. | | |
| Incident | 03/08/12 | Link 1 | Trash in several areas along the ROW, particularly the mylar taping utilized for bird deterrents, has been noted in various locations. Issue is currently being addressed. | | |
| Incident | 03/12/12 | Link 2 | Vehicle was noted to be parked outside approved workspace and within the drip line of an oak tree. | | |
| Incident | 03/14/12 | Link 1 | A helicopter noted to be operating prior to 7am at the Rough Acres Construction Yard. | | |
| Incident | 03/20/12 | Link 1 | Crew vehicles were noted to be parked outside of approved workspaces along Old Hwy 80. Vehicles were immediately moved upon notification. | | |
| Incident | 03/20/12 | Link 1 | Marker balls were being staged inside a noted ESA at the Jacumba Valley Ranch Yard. They were immediately moved outside of the ESA and no impacts were noted. | | |
| Incident | 03/21/12 | Link 1 | Work equipment was placed outside of approved workspace via helicopter ate EP225. Corrective action was immediately taken upon notification. | | |
| Incident | 03/22/12 | Link 1 | Vehicle was noted to be parked outside of approved workspace near EP205-1 and project personnel was observed to be smoking in a non-designated area. | | |
| Incident | 03/27/12 | Link 2 | Vehicle was noted to be parked within a bird buffer near EP90. | | |
| Incident | 03/27/12 | Link 2 | Two helicopters noted to be operating prior to 7am at the SWAT Construction Yard. | | |
| Incident | 03/31/12 | Link 1 | Bulldozer was noted to have parked outside of approved workspace along the access road to EP236. The equipment was moved upon notification to the crew. | | |
| Incident | 04/04/12 | Link 1 | Crew truck was noted to have parked outside of approved workspace along the access road to EP236. Monitors have placed additional signage along the road. | | |

CONSTRUCTION PROGRESS

Table 6 provides a summary of construction progress through the end of the subject reporting period.

TABLE 6 CONSTRUCTION PROGRESS

| Agency | Total Towers | Released for Construction | Foundations Completed | Towers Erected | Wire Installed |
|---------------------------|-----------------|---------------------------|--------------------------|-------------------|-------------------|
| Non-Federal | 169 | 169 | 161 | 139 | 76 |
| Bureau of Land Management | 179 | 179 | 164 | 142 | 116 |
| US Forest Service | 76 | 76 | 63 | 18 | 17 |
| Miramar | 14 | 14 | 14 | 14 | 11 |
| Total | 438 | 438 | 402 | 313 | 220 |

PROJECT PHOTOGRAPHS



Figure 1: K-max delivering water buffalos to Tower EP254-3. (Link 1)



Figure 2: Micropile drilling at Tower EP254-3. (Link 1)



Figure 3: Aircrane "picking" a pre-assembled tower piece for Tower EP228. (Link 1)



Figure 4: Wire stringing operations at Tower EP220-1 pull site. (Link 1)



Figure 5: Helicopter view of micropile drilling at Tower EP50 with Arroyo Toad exclusionary fencing around the site. (Link 2)



Figure 6: Micropile drilling at Tower EP115-1. (Link 2)



Figure 7: Tower assembly at Tower EP113-5. (Link 2)



Figure 8: New vegetative growth on fill slopes at Suncrest Substation. (Link 3)



Figure 9: BMPs at Bartlett Hauser Construction Yard after a storm. (Link 2)



Figure 10: Tackifier and hydromulch application at Plaster City Yard. (Link 1)



Figure 11: Helicopter operations at Thing Valley Construction Yard. (Link 2)



Figure 12: Marker balls staged inside of ESA signage at Jacumba Valley Ranch Yard. (Link 1)