



5020 Chesebro Road, Suite 200, Agoura Hills, CA 91301-4316 Tel. 818-597-3407, Fax 818-597-8001, www.aspeneg.com

#### PROJECT MEMORANDUM SDG&E'S SUNRISE POWERLINK PROJECT

| To:      | Billie Blanchard, Project Manager, CPUC   |
|----------|---|
| From:    | Vida Strong, Aspen Project Manager        |
| Date:    | June 8, 2012                              |
| Subject: | Weekly Report 88 – May 20 to May 26, 2012 |

#### **INTRODUCTION**

This report provides a summary of the construction and compliance activities associated with the SDG&E Sunrise Powerlink Project. This report is organized as follows:

- Transmission Line Construction
- Substation Construction and Upgrades
- Construction Yards and Other Workspaces

A summary of the Notices to Proceed with construction and Variance Request activity are also provided (see Tables 1 and 2, respectively, near the end of this report). Finally, a summary of Temporary Extra Workspace and non-compliance activity are provided in Tables 3 and 4, respectively.

CPUC/Aspen Environmental Monitors (EM): Cassandra Garza, Brian Woodward, Valerie Yep.

#### TRANSMISSION LINE CONSTRUCTION

#### **Summary of Activity:**

1. Link 1, 500 kV Overhead Transmission Line:

Non-Federal Lands:

- Vegetation maintenance occurred at Tower EP215.
- Final grading was conducted at EP220-1-PS-N and EP234-1-E.
- Miscellaneous tower work took place at EP183, EP22102, EP221A, EP230-1, and EP231-1.
- QA/QC occurred at EP221-2.
- Work continued at the EP215 regeneration site.
- Jumper work was conducted at EP255-1.
- Splicing took place at EP215.

#### BLM Lands:

- Final grading occurred at EP170 pull site east, EP171, EP171-N, and EP198-3.
- Miscellaneous tower work was conducted at EP144, EP145, Ep146, EP152-2, and EP189-3.
- QA/QC took place at EP152-2 and EP170.
- Clipping in occurred from EP148 to EP151-2.
- Dead-end work was conducted at EP144, EP146, EP149-1, and EP170.
- Spacers were installed and splicing took place from EP141 to EP170.
- Splicing occurred at EP170.

2. Link 2, 500 kV Overhead Transmission Line:

Non-Federal Lands:

- Vegetation maintenance occurred at EP40-1.
- Access road maintenance was conducted at EP89-1-PS-N and EP89-1-E.
- Micropile capping work took place at EP52-1 and EP119-2.
- Tower assembly occurred at EP32-1, EP52-1, EP62A-1, EP66, EP67, EP77, EP91 pull site west, EP105-2, EP107-3, and EP119-2.
- Miscellaneous tower work was conducted at EP25-2, EP30-2, EP31-1, EP62A-1, EP64, and from EP77 to EP79.
- QA/QC and took place at EP52-1 and EP66.
- Ground rod installation occurred at EP52-1 and EP62A-1.
- Ground resistance testing was conducted at EP32-1, from EP64 to EP67, and EP119-2.
- Regeneration work continued at EP54-1.
- Anchor removal took place at EP119-2.
- Equipment was mobilized to EP67 and EP78 pull sites.
- Guard structure was installed at GS-NF-17.
- Wire preparation work occurred at EP30-2, EP31-1, and EP32-1.
- Sock line was pulled from EP67 to EP78.
- Sock line, hardline, and conductor were pulled from EP22-1 to EP30-2 pull site.
- Sock line and hardline were pulled from EP99-2 to EP113-5.
- Traveler work was conducted at EP67, from EP71 to EP78A, EP78 pull site, and EP101-2.
- Sagging and clipping took place from EP104-2 to EP107-3.
- Spacers were installed at EP25-2, EP26-1, and EP27-1.
- Dead-end work occurred at EP106.
- Guard structure removal was conducted at GS-NF-15 and GS-NF-16.

BLM Lands:

- Fence grounding took place at EP96, EP98, and EP105.
- Micropile capping work occurred at EP48 and EP56-4.
- Tower assembly was conducted at EP39-1, from EP48 to EP51-1, EP53-2, EP56-4, from EP68 to EP73-1, EP75-2, and EP76-2.
- Miscellaneous tower work took place from EP70 to EP72.
- QA/QC occurred from EP49 to EP51, EP63, EP69, and from EP71 to EP75-2.
- Ground rod installation was conducted at EP56-4 and EP63.
- Ground resistance testing took place at EP39-1, EP40-1, and EP68.
- Wire preparation occurred from EP39-1 to EP42.
- Traveler work was conducted at EP68, EP69, and from EP71 to EP78A.
- Insulator work took place from EP68 to EP70.
- Sock line and hardline were pulled from EP30-2 to EP42.
- Sock line was pulled from EP67 to EP78.
- Conductor was pulled form EP101-2 to EP113-5.
- OPGW was flown from EP99-2 to EP113-5.

- Sagging and clipping occurred from EP101-2 to EP103A.
- Dead-end work was conducted at EP103-2 and EP103A.
- Marker ball installation took place at EP144.
- Splicing occurred at EP99-2.

US Forest Service Lands:

- During this reporting period, the PALs were as follows: Monday: D, Tuesday: EV, Wednesday: D, Thursday: C, Friday: C, and Saturday: B. Work activities ended each day in accordance with the Fire Plan and the approved EV letter as appropriate.
- Vegetation maintenance occurred at EP33-1.
- Fence grounding was conducted at EP12-3.
- Micropile capping work took place at EP14-1, EP17-1, EP19-1, EP57-2, EP114-2, EP116-1, EP118-2, and EP122-1.
- Tower assembly occurred at EP14-1, EP17, EP19-1, EP21-1, EP33-1, EP35-1, EP36-1, EP57-1, EP58-2, EP109-1, EP112A-1, EP113-5, EP113-5 pull site, EP114-2, EP115, EP116, EP118-2, EP120-4, EP120A, EP121-3, EP122, EP128, and EP129.
- Miscellaneous tower work was conducted from EP2-3 to EP5-2, EP9-1, and from EP141 to EP146.
- Anchors were installed at EP14-1, EP19-1, EP116, and EP118-2.
- Ground rod installation took place at EP57-2 and EP58-2.
- Ground resistance testing occurred at EP14-1, EP16-1, from EP18-1 to EP21-1, EP33-1, from EP35-1 to EP37-2, and from EP114-2 to EP118-2.
- Equipment was mobilized at EP125 pull site and EP131 pull site.
- Wire preparation was conducted from EP33-1 to EP37-2.
- Sock line and hardline was pulled form EP30-2 to EP42.
- Sock line, hardline, and conductor was pulled from EP22-1 to EP30-2 pull site and from EP125 to EP130.
- OPGW was flown from EP99-2 to EP113-5 and from EP125 to EP131.
- Traveler work took place from EP125 to EP130-1.
- Insulator work occurred from EP125 to EP128, EP129, EP130-1, and EP131 pull site.
- Sagging took place from EP22-1 to EP30-2 pull site.
- Sagging, clipping in, and dead-end work was conducted from EP141 to EP143-1.
- Clipping in and dead-end work took place from EP22-1 to EP30-1.
- Dead-end work occurred at EP24-1, EP112-3, EP141, and EP143-1.
- Dampener work was conducted and marker balls and spacers were installed from EP141 to EP146.
- Jumper work took place at EP141.
- Spacers were installed at EP23-1, EP24-1, EP28-3, and EP29-2.
- Splicing occurred at EP141 and EP146.
- 3. Link 4, 220 kV Underground Transmission Line (non-federal lands only):
  - Revitalization occurred on Alpine Boulevard.
  - Splicing occurred inside Vault V20R.
  - Lightning arresters and jumpers were installed on CP88 at Slay Property.
  - Cooling system work occurred at the Interstate 8 bore site.

- Termination repair, testing setup and electrical testing occurred on the Loritz property.
- Work in the vaults and pavement striping occurred east of South Grade Road.
- Cable work was performed at CP96.

#### 4. Link 5:

Non-Federal Lands, 220 kV Overhead Transmission Line:

- Access road maintenance occurred at CP98-N-A.
- Gate work occurred at CP57.
- Fence grounding occurred at CP20 and CP70-3.
- Rock stabilization occurred at CP47A-1.
- Miscellaneous tower work occurred at/from CP27, CP71 to CP73-1, CP80-2, CP83, CP87-1, CP88, CP107, and CP108.
- QA/QC occurred at CP21, CP22-1, CP24-1 to CP26, CP28-1, CP29-1, CP31-2, CP33A, CP34-2, CP35-2, CP39 to CP42-1, CP44-1 to CP48-2, CP51-2, CP52-1, CP55 to CP57, CP78-2 to CP83, CP107, and CP109-1.
- Ground resistance testing occurred at CP107.
- Restoration occurred at CP31-2, CP31-2 pull site, CP43-1 pull site east, and CP49-1 pull site.
- Hydromulching was conducted at/from CP27, CP35-2, Cp73-2, CP77, CP79-1, CP107, and CP108.

BLM Lands, 220 kV Overhead Transmission Line:

- Miscellaneous tower work occurred from CP59 and CP62A.
- QA/QC occurred at CP50, CP58-1, and CP61-1.

MCAS Miramar (Federal) Lands, 220 kV Overhead Transmission Line:

- Final grade and restoration occurred at CP6-1, CP7, and CP10.
- QA/QC occurred at CP15-1.
- Ground rod repair occurred at CP7.
- Spacers were installed at CP10.
- Cleanup occurred at CP3.

MCAS Miramar (Federal) Lands, 69 kV Reconductoring Line:

• No work occurred during this reporting period.

MCAS Miramar (Federal) Lands, 12 kV Reconductoring Line:

• No work occurred during this reporting period.

US Forest Service Land:

- During this reporting period, the PAL levels were as follows: Monday: D, Tuesday: EV, Wednesday: D, Thursday: C, Friday: C, and Saturday: B. Work activities ended each day in accordance with the Fire Plan and the approved EV letter as appropriate.
- No work occurred during this reporting period.

#### **Environmental Compliance:**

- 1. Biological, Cultural, and Native American monitors were present as applicable during all transmission line construction activities.
- 2. BMPs were installed, refreshed, or maintained on tower sites, access roads, TSAPs, and pads associated with towers on Link 1:

Non-Federal Lands:

- BMP maintenance and installation at tower sites, pull sites, and guard structure sites occurred at EP183, EP185-1, from EP217 to EP224-1, EP231A, EP232-1, from EP235-1 to EP237-1, EP240, from EP242 to EP245-1, from EP252-1 to EP255, and GS-NF-34.
- BMP maintenance and installation on access roads was conducted at EP234-1-E.
- Hydromulching took place at EP199-3, from EP217-1 to EP221-2, EP224-1, EP226-1, EP227-1, EP229-1, EP230-1, from EP232-1 to EP234-1, from EP237-1 to EP240, from EP242 to EP244, EP255 pull site west (see Figure 1), and GS-NF-34.

BLM Lands:

- BMP maintenance and installation at tower sites, pull sites, and guard structure sites occurred from EP144 to EP152-2, EP180 pull sites, from EP170 to EP176, EP186-1, EP187-2, from EP189-3 to EP194-3, EP192-2 pull sites, EP196-2, EP247, and EP251.
- BMP maintenance and installation on access roads was conducted at EP170-N, EP171-N, and from EP179-N to EP185-1-E-A.
- Hydromulching took place at EP197-3, EP246, EP249-1, and EP250.
- 3. BMPs were installed or refreshed on access roads, TSAPs, and pads associated with towers on Link 2:

Non-Federal Lands:

- BMP installation and maintenance occurred at EP-1, EP26-1, EP30-2, EP31-1, EP32-1, EP62A-1, from EP78 to EP82 (including guard structures), EP83-PS-N-A, EP83-PS-N-B, EP83-N, EP83, EP83 pull sites, EP84-E-A, EP84-E-B, EP84-E-C, EP89-1 (including pull sites) (see Figure 2), from EP91 to EP93, EP91 pull sites, GS-NF-14, and GS-NF-17.
- BMPs were removed from EP89-1.
- Hydromulching was conducted at EP83 pull sites and EP89 pull sites.

US Forest Service Lands:

- BMP maintenance occurred from EP3-3 to EP20-2 (including pull sites), from EP22-1 to EP24-1 (including pull site), EP34-1, EP37-2, from EP108-2 to EP110-2, EP111-4, from EP112-3 to EP113-5 (including associated access roads), EP116-1, EP118-2, from EP120-4 to EP125, from EP126-1 to EP131, EP139-1, EP141 pull sites, eP142-1, EP143-1, GS-USFS-2, GS-USFS-3, and GS-USFS-4.
- BMPs were removed from EP131-E, EP131-N, EP138-e-E-A, EP138-2-E-B, EP139-1-E-A, EP139-1-E-B, EP139-1-E-C, EP141-E-A, EP141-E-B, and EP141 pull sites.

BLM Lands:

- BMP installation and maintenance occurred from EP53-3, EP56-4, from EP70 to EP75-2, and from EP94 to EP99-2.
- 4. BMPs were installed or refreshed on Link 4 (non-federal lands only):
  - No BMP activity occurred during this reporting period.
- 5. BMPs were installed or refreshed on access roads, TSAPs, and pads associated with towers on Link 5:

Non-Federal Lands:

• BMP installation and maintenance occurred from CP21 to CP26, CP31-2 pull sites, CP44-1, CP49-1 pull site, CP57, CP59, CP62A, CP75-1 pull site, CP80-2, CP81-1, CP98-1, CP109-1, GS-NF-1, and GS-NF-9.

BLM Lands:

• No BMP activity occurred during this reporting period.

MCAS Miramar (Federal) Lands, 220 kV Overhead Transmission Line

• BMP installation and maintenance occurred at CP2, CP3 pull site, CP8-2, and CP12-1.

MCAS Miramar (Federal) Lands, 69 kV Reconductoring Line:

• No BMP activity occurred during this reporting period.

US Forest Service Lands:

- BMP maintenance occurred at CP99-2 and CP100-1.
- 6. Arroyo toad fence repairs occurred at EP51-1-N and EP67-E. (Link 2)
- 7. One coast patch-nosed snake (*Salvadora hexalepis virgultea*) was found dead on McCain Valley Road near EP187. (Link 1)
- 8. One coast patch-nosed snake (*Salvadora hexalepis virgultea*) was found dead on the access road between EP49 and EP50. One coast patch-nosed snake was relocated from EP74-1-E. One coast horned lizard (*Phrynosoma coronatum blainvilii*) was relocated from EP89. One red diamond rattle-snake (*Crotalus ruber* ruber) was relocated from EP67. (Link 2)
- 9. On March 24, and incident occurred while removing flower pots and guard poles at the EP27-1 guard structure site. Small amounts of vegetation were damaged (see Figure 3). Biological Monitors and an Avian Biologist were immediately onsite to assess any damage. No nests were found. An incident report has been provided. (Link 2.)
- 10. Minor leaks, drips, and releases on USFS lands were submitted to the USFS in a weekly HazMat log.
- 11. Pre-construction surveys were performed throughout Link 1, 2 and 5 with appropriate monitors.

No CPUC Non-Compliance Reports or Project Memoranda were issued during the subject period for transmission line construction activities. Non-Compliance activities for the project to date are summarized in Table 4.

#### Agency Representatives during Construction (other than EMs):

USFS Representatives: Ed Wieringa, Jennifer MacDonald.

#### SUBSTATION CONSTRUCTION AND UPGRADES

#### **Summary of Activity:**

- 1. Suncrest Substation, Link 3 (non-federal lands): Work continued inside of the control shelter and on punch list items. Fence grounding took place. Camera equipment was removed from the east cut slope. Grading of Class 2 base was conducted on the substation pad pull site. Testing of circuit breakers and disconnect switches continued. Wire stringing activities occurred.
- 2. Imperial Valley (IV) Substation Upgrade (BLM lands): Fiber testing occurred within the control house.
- 3. San Luis Rey Substation (non-federal lands): No work occurred during this reporting period. Bird sweeps/surveys were conducted.
- 4. Encina Substation (non-federal lands): Relay and wiring crews performed wiring near the control house.
- 5. Pomerado Substation: (non-federal lands): Crews performed upgrade work which required changing out bus, disconnects, and circuit breakers. Bird sweeps occurred.

#### **Environmental Compliance:**

- 1. All applicable Biological, Cultural, Paleontological, and Native American monitors have been present during ground disturbing activities at all substations.
- 2. Work on the mitigation parcel adjacent to Suncrest Substation occurred. (Link 3)

No CPUC Non-Compliance Reports or Project Memoranda were issued during the subject period for Substation Construction and Upgrade activities. Non-Compliance activities for the project to date are summarized in Table 4.

#### Agency Representatives during Construction (Other than CPUC EMs):

None.

#### CONSTRUCTION YARDS AND OTHER WORKSPACES:

Summary of Activity:

NOTE: Additionally, all active yards typically have miscellaneous activities throughout the day such as materials delivery and staging, equipment mobilization/demobilization, water supply and dust control, port-o-potty maintenance, etc.

Non-Federal Lands:

- 1. Alpine Construction Yard Hub for equipment and materials staging and usage of weed wash station. Yard was also used for staging QC, gate, BMP, regen, and road crews.
- 2. Alpine Headquarters No activity occurred during the reporting period.
- 3. AER Yard Yard has been restored.
- 4. Barrett Canyon Yard No activity occurred during the reporting period.
- 5. Bartlett-Hauser Yard Frequent helicopter operations (including air crane) and weed wash station operations occurred. Yard was also used for staging wire, QC, road, habitat assessment, assembly, hydromulch, grout, erection, and BMP crews.
- 6. Fromm Yard No work occurred at this yard during this reporting period.
- 7. El Monte Yard No activity occurred during the reporting period.
- 8. Helix Yard Occasional helicopter operations and staging for QC, assembly, vegetation maintenance, rock drilling, hydromulching, and BMP crews.
- 9. Jacumba Valley Ranch (JVR) Yard Occasional helicopter operations and weed wash station usage occurred. This yard was also used for staging road and BMP crews.
- 10. Kreutzkamp Yard Intermittent helicopter operations and weed wash station operations took place. This yard was also used for staging erection, regen, and QC crews.
- 11. Rough Acres Yard Frequent helicopter operations (including air crane), materials hauling and staging, and weed wash station usage occurred. This yard was also used for staging road, micropile, BMP, QC, erection, and wire crews.
- 12. SWAT Yard Frequent helicopter operations (including air crane) and weed wash station operations took place. This yard was also used for staging assembly, weed abatement, erection, wire, vegetation maintenance, grout, and BMP crews.
- 13. S2 Yard Yard has been restored.
- 14. Sycamore Yard Occasional helicopter operations and staging for road and BMP crews.
- 15. Wilson Yard Intermittent helicopter operations took place. This yard is also used for staging micropile capping and assembly crews.

Federal Lands (BLM):

- 16. Dunaway Yard Yard has been restored.
- 17. Imperial Valley Yard Yard has been restored.
- 18. McCain Valley Yard Intermittent helicopter operations took place. Various crews staging out of Rough Acres Yard also use this yard for materials.

19. Plaster City Yard – Yard restoration is largely complete.

Federal Lands (USFS):

20. Thing Valley Yard – Occasional helicopter operations took place. This yard was also used for staging tower assembly, wire, and QC crews (see Figure 4).

#### **Environmental Compliance:**

- 1. Biological, Cultural, and Native American monitors have worked with crews at the construction yards to define approved work areas and sites to avoid.
- 2. One coast patch-nosed snake (*Salvadora hexalepis virgultea*) was found dead at Kreutzkamp Yard. One San Diego ring-necked snake was relocated from Kreutzkamp Yard. (Link 2)

No Non-Compliance Reports or Project Memorandums were issued during the subject period for Construction Yards and other workspace activities. Non-Compliance activities for the project to date are summarized in Table 4.

#### Agency Representatives during Construction (other than CPUC EMs):

None.

#### **CPUC NOTICES TO PROCEED (NTPs)**

Table 1 summarizes the CPUC Notice to Proceed activity for the SDG&E Sunrise Powerlink Project to date.

| (Updated 06/08/2012) |           |          |            |   |  |
|----------------------|-----------|----------|------------|---|--|
|                      | Date      | Date     |            |   |  |
| NTP#                 | Requested | Issued   | Segment    | Description   |  |
| #1                   | 01/04/10  | 04/28/10 | 25         | San Luis Rey Substation Upgrades                        |  |
| #2                   | 02/08/10  | 04/29/10 | 23         | South Bay Substation Upgrades                           |  |
| #3                   | 02/26/10  | 05/20/10 | Yard       | Alpine Yard 18  |  |
| #4                   | 01/26/10  | 05/28/10 | Yard       | Alpine Yard 18A   |  |
| #5                   | 02/05/10  | 09/28/10 | Yard       | Rough Acres Yard, Phase 1                               |  |
| #6                   | 05/26/10  | 09/28/10 | 24         | Encina Substation Upgrades                              |  |
| #7                   | 05/28/10  | 09/28/10 | Telecomm   | White Star Communication Facility                       |  |
| #8                   | 06/09/10  | 10/06/10 | Substation | Pomerado Substation Upgrades                            |  |
| #9                   | 06/09/10  | 10/06/10 | Substation | Scripps Switchyard/Substation Upgrades                  |  |
| #10                  | 10/13/10  | 11/23/10 | 15         | Link 4, Alpine 230 kV Underground Construction          |  |
| #11                  | 10/19/10  | 12/15/10 | 13         | Link 3, Suncrest Substation/Wilson Construction Yard    |  |
| #12                  | 11/30/10  | 12/23/10 | Yard       | Rough Acres Yard, Phase 2                               |  |
| #13                  | 11/09/10  | 01/14/11 | 2-18,      | Links 1, 2, and 5, overhead construction on non-federal |  |
|                      |           |          | 20-22      | lands   |  |
| BLM #1               | 01/19/11  | 02/03/11 | 1          | Imperial Valley Substation upgrades.                    |  |
| BLM #2               | 03/28/11  | 04/04/11 | 2-12,      | Links 1, 2, and 5 overhead construction on BLM          |  |
|                      |           |          | 16-17      | Lands.  |  |
| Miramar              | 01/20/11  | 06/28/11 | 22         | Overhead and substation construction.                   |  |
| USFS                 | 07/29/11  | 08/09/11 | 6, 7, 10,  | Links 1, 2, and 5 overhead construction on USFS         |  |
|                      |           |          | 12,14,16   | Lands.  |  |

TABLE 1 CPUC NTPs (Updated 06/08/2012)

# VARIANCE & TEMPORARY EXTRA WORKSPACE REQUESTS

Variance and Temporary Extra Workspace (TEWS) requests submitted to date are presented in Tables 2 and 3, respectively.

| i                   |                       |                | (Opualeu             | 06/08/2012)  |
|---------------------|-----------------------|----------------|----------------------|--|
| Variance<br>Request | Date<br>Requested     | Date<br>Issued | Segment              | Description  |
| #1                  | 11/04/10              | 11/10/10       | Yard                 | Thomas Yard (El Centro, CA)  |
| #2                  | 12/22/10              | 03/18/11       | Yard                 | Sycamore Estates Construction Yard. Response to inquiry received 02/23.  |
| #3                  | 01/06/10              | 01/18/11       | All                  | Modification to tree trimming requirements.  |
| #3 MOD              | 01/25/11              | 01/26/11       | All                  | Modification to brush clearing requirements.   |
| #4                  | 01/13/11              | 03/01/11       | Yard                 | Helicopter Temporary Landing Pad area at the Alpine Regional Field Offices.                                    |
| #5                  | 02/01/11              | 02/09/11       | Yard                 | Site improvements at the Wilson Construction yard and along Bell Bluff Trail                                   |
| #6                  | 02/01/11              | 03/01/11       | Link 5               | Variance from Mitigation Measure H-1a (CC) to allow work outside of the dry season.                            |
| #7                  | 02/11/11              | 02/17/11       | Link 3               | Additional work areas for construction trailers, parking, etc.   |
| #8                  | 03/02/11              | 03/08/11       | Link 2               | Alternate access route to Structure EP 27.   |
| #9                  | 03/29/11              | 04/06/11       | All                  | Perform construction activities outside of hours allowed by local ordinances with local jurisdiction approval. |
| #10                 | 04/04/11<br>(revised) | 04/14/11       | Link 4               | Additional construction work space at Viejas Creek Bridge.   |
| #11                 | 04/06/11              | 04/22/11       | Link 1               | Additional workspace east of EP215.  |
| #12                 | 04/15/11              | 04/25/11       | Link 1               | Additional turnaround along the access road to EP 220-1.   |
| #13                 | 04/13/11              | 05/06/11       | Links<br>1 & 2       | Two fiber optic regeneration sites.  |
| #13 Mod             | 05/08/12              | 05/10/12       | Links<br>1 & 2       | Alter configuration of regeneration sites to meet fire safety requirements.                                    |
| #14                 | 04/28/11              | 05/03/11       | Yards                | Change visual screening at Project construction yards from slats to fabric.                                    |
| #15                 | 05/12/11              | 05/19/11       | Link 2               | Alternate access to EP 84.   |
| #16                 | 05/16/11              | 05/21/11       | Link 4               | Additional parking space for use during underground construction.  |
| #17                 | 05/18/11              | 05/24/11       | Encina<br>Substation | Driveway improvement.  |
| #18                 | 06/27/11              | 07/14/11       | Link 1               | Gate installation between mile markers 38.5 and 39.5.  |

#### TABLE 2 VARIANCE REQUESTS (Updated 06/08/2012)

| Variance      | Date      | Date            |                        |  |
|---------------|-----------|-----------------|------------------------|--|
| Request       | Requested | Issued          | Segment                | Description  |
| #18 Mod       | 10/03/11  | Under<br>Review | Link 1                 | Alternative for installation of Gate #4.   |
| #19           | 06/27/11  | 06/29/11        | Link 1                 | Installation of training tower at Rough Acres<br>Construction Yard.                      |
| #20           | 06/28/11  | 08/05/11        | Link 5                 | Additional disturbance for access, pull sites and topsoil stockpile at CP48-2 to CP51-2. |
| #21           | 07/07/11  | 07/15/11        | Link 1                 | Guard structure from EP255 to Imperial Valley Substation.                                |
| #22           | 07/08/11  | 08/04/11        | Link 1                 | Fromm Construction Yard. Additional information submitted 08/04.                         |
| BLM<br>DNA #1 | 07/19/11  | 08/05/11        | Link 1                 | Minor modifications to portions of the Project on Bureau of Land Management lands.       |
| #23           | 08/15/11  | 10/20/11        | Links<br>1, 2, & 5     | Additional landing platforms and TSAPS.  |
| #24           | 08/25/11  | 08/29/11        | Suncrest<br>Substation | Additional vegetation clearing around construction trailers.                             |
| #25           | 09/01/11  | 09/09/11        | Links<br>1 & 5         | Extended use of approved TEWS areas for parking and staging.                             |
| #26           | 09/15/11  | 09/20/11        | Link 2                 | Water tank installation at Barrett Canyon Yard.  |
| #27           | 09/20/11  | 10/18/11        | Link 1                 | Temporary Staging area near Mountain Springs<br>Grade Road.                              |
| #28           | 10/19/11  | Denied          | Link 3                 | Allow work to continue at Suncrest Substation during a Red Flag Warning (RFW) event.     |
| #29           | 10/21/11  | 11/01/11        | Links<br>1, 2, & 5     | Additional guard structures identified for wire pulling activities.                      |
| #29 Mod       | 01/04/12  | 01/06/12        |                        | Modification to guard structure location.  |
| #30           | 11/01/11  | 11/15/11        | Links<br>1, 2, & 5     | Temporary parking and turnaround areas.  |
| #30 Mod       | 02/09/12  | 02/09/12        | Links 5                | Modification to perform long lining activities.  |
| #31           | 11/08/11  | Retracted       | Links<br>2 & 5         | Request for site specific exemption of Condition 37 of NTP 13.                           |
| #32           | 11/15/11  | 12/09/11        | Links                  | Additional workspace for wire pulling activities.  |
| #32 Mod       | 01/04/12  | 01/06/12        | 1, 2, & 5              | Modification to guard structure location   |
| #33           | 11/28/11  | 12/16/11        | Links<br>1, 2, & 5     | Additional workspace for structure access and wire pulling activities.                   |
| #34           | 11/29/11  | 12/02/11        | Links<br>2 & 5         | Extension of allowable work window within GE buffer (MM B-7h).                           |
| #35           | 12/22/11  | 01/04/12        | Link 5                 | Improvements to existing road & drainage,<br>Simpson property.                           |
| #36           | 01/20/12  | 02/08/12        | Links<br>1, 2, & 5     | Variance to allow vegetation clearing between<br>January 15 through February 14.         |

| Variance<br>Request | Date<br>Requested | Date<br>Issued | Segment            | Description  |
|---------------------|-------------------|----------------|--------------------|--|
| #37                 | 01/20/12          | 02/08/12       | Links<br>1, 2, & 5 | Temporary placement of concrete blocks outside of approved work areas. |
| #38                 | 02/10/12          | 02/22/12       | Link 5             | Gate installation near CP55.   |
| #39                 | 02/10/12          | Retracted      | Link 5             | Additional work space at CP23 pull site.                               |
| #40                 | 03/20/12          | 03/21/12       | Link 5             | Additional work space near GS-NF-7, San Vicente Reservoir.             |
| #41                 | 04/17/12          | 04/27/12       | Link 2             | Cinnamon Drive Road improvements near EP36-1.                          |
| #42                 | 05/09/12          | Retracted      | Link 2             | Temporary concrete anchor block placement.                             |

# TABLE 3 TEMPORARY EXTRA WORKSPACE (TEWS) REQUESTS (Updated 06/08/2012)

| TEWS     | Date      | Date     |            |  |
|----------|-----------|----------|------------|--|
| Request  | Requested | Approved | Segment    | Description  |
| TEWS #1  | 11/01/10  | 11/01/10 | White Star | Asphalt paved area for vehicle parking and staging               |
| TEWS #2  | 03/17/11  | 03/18/11 | Link 4     | Parking on Puetz Valley and Alpine Blvd                          |
| TEWS #3  | 03/17/11  | 03/18/11 | Link 4     | Parking on Harbison Canyon and Alpine Blvd                       |
| TEWS #4  | 03/22/11  | 03/23/11 | Link 5     | Storage on One Father Junipero Sierra Trail                      |
| TEWS #5  | 03/24/11  | 03/24/11 | Link 4     | Parking at 3900 Willows Road West                                |
| TEWS #6  | 03/24/11  | 03/24/11 | Link 4     | Parking at 5840 Willows Road East                                |
| TEWS #7  | 04/06/11  | 04/07/11 | Link 2     | Northern access road to EP 79                                    |
| TEWS #8  | 04/14/11  | 04/14/11 | Link 2     | Northeast spur of access road to EP 84                           |
| TEWS #9  | 05/17/11  | 05/24/11 | Link 1     | Use of SWPL tower sites for parking (EP331-341)                  |
| TEWS #10 | 05/24/11  | 05/24/11 | Link 5     | Parking and pullsite adjacent to Alliant University              |
| TEWS #11 | 06/16/11  | 06/16/11 | Link 1     | Use of alternative access to EP 240, per the                     |
|          |           |          |            | request of the landowner at JVR                                  |
| TEWS #12 | 06/20/11  | 06/20/11 | Link 1     | Use of SWPL tower sites for parking (EP295-299)                  |
| TEWS #13 | 06/30/11  | 07/01/11 | Link 1     | Use of SWPL tower site for parking (EP324)                       |
| TEWS #14 | 07/01/11  | 07/01/11 | Link 1     | Use of SWPL tower sites for parking (EP300,                      |
|          |           |          |            | EP302, EP306, EP307, EP312)                                      |
| TEWS #15 | 07/06/11  | 07/06/11 | Link 1     | Use of SWPL tower sites for parking (EP294, EP303, EP304, EP305) |
| TEWS #16 | 06/30/11  | 07/07/11 | Link 1     | Additional parking along Mountain Springs Grade<br>Road          |
| TEWS #17 | 07/11/11  | 07/12/11 | Link 5     | Parking near CP20  |
| TEWS #18 | 07/11/11  | 07/12/11 | Link 5     | Parking near CP24  |
| TEWS #19 | 07/11/11  | 07/12/11 | Link 5     | Parking near CP29  |
| TEWS #20 | 07/18/11  | 07/19/11 | Link 1     | Parking near EP314   |
| TEWS #21 | 07/22/11  | 07/25/11 | Link 1     | Parking near EP315   |

| TEWS     | Date      | Date     |         |  |
|----------|-----------|----------|---------|--|
| Request  | Requested | Approved | Segment | Description  |
| TEWS #22 | 07/26/11  | 07/26/11 | Link 1  | Parking near EP291-293   |
| TEWS #23 | 08/05/11  | 08/05/11 | Link 1  | Parking near EP290   |
| TEWS #24 | 08/09/11  | 08/10/11 | Link 2  | Parking near EP90/EP91   |
| TEWS #25 | 09/07/11  | 09/07/11 | Link 5  | Temporary use of access road near El Monte Road<br>(12 kV)         |
| TEWS #26 | 09/13/11  | 09/13/11 | Link 2  | Temporary use of access road near Barrett<br>Substation            |
| TEWS #27 | 09/29/11  | 09/30/11 | Link 1  | Parking near EP248.  |
| TEWS #28 | 09/28/11  | 10/03/11 | Link 1  | Parking and Staging area adjacent to EP301.                        |
| TEWS #29 | 09/13/11  | 09/13/11 | Link 2  | Placement of Water Tank at Barrett Substation.                     |
| TEWS #30 | 10/06/11  | 10/06/11 | Link 1  | Parking and Staging at Chevron Gas Station on Carrizo Gorge Road.  |
| TEWS #31 | 11/09/11  | 11/10/11 | Link 1  | Parking at EP252A-1 and EP254-3-E.                                 |
| TEWS #32 | 11/09/11  | 11/15/11 | Link 5  | Temporary material and equipment staging area off of Willows Road. |
| TEWS #33 | 02/09/12  | 02/09/12 | Link 5  | Additional parking area between CP75 to CP88.                      |
| TEWS #34 | 03/06/12  | 03/06/12 | Link 5  | Additional parking area along Hwy 67.                              |
| TEWS #35 | 03/26/12  | 03/27/12 | Link 1  | Additional parking area between EP227/EP228.                       |
| TEWS #36 | 04/26/12  | 04/26/12 | Link 2  | Additional workspace adjacent to Access Road EP11-3-N.             |
| TEWS #37 | 05/25/12  | 05/25/12 | Link 2  | Additional workspace near EP32.                                    |
| TEWS #38 | 05/25/12  | 05/29/12 | Link 2  | Additional workspace adjacent to EP119.                            |

### NON-COMPLIANCES & INCIDENTS

CPUC and USFS Stop Work Orders, Project Memorandum (PM) and Non-Compliance Reports (NCR), and U.S. Army Corps Non-Compliances (NC) that have been issued to date are presented in Table 4.

# TABLE 4 NON-COMPLIANCES (NC) AND PROJECT MEMORANDA (PM) (Updated 06/08/2012)

| Туре  | Date     | Location               | Description   |
|-------|----------|------------------------|---|
| PM #1 | 12/07/10 | Thomas<br>Yard         | Failure to report unanticipated biological resources within 48 hours.   |
| PM #2 | 02/11/11 | EP 242,<br>Link 1      | Unauthorized ground disturbance at EP 242   |
| NC #1 | 03/08/11 | Suncrest<br>Substation | Army Corp of Engineers issued Non-Compliance for not<br>complying with Special Conditions 19, 21 and 23 of DA<br>Permit SPL-2007-00704-SAS. |
| PM #3 | 03/15/11 | CP 67-3,<br>Link 5     | Staking crews operating and delivered by helicopters within GE Buffer area.   |

| Туре                  | Date     | Location                 | Description  |
|-----------------------|----------|--------------------------|--|
| PM #4                 | 04/06/11 | Swat<br>Yard             | Unauthorized Nest Removal from a water truck at SWAT Construction yard.  |
| PM #5                 | 05/16/11 | EP 340,<br>Link 1        | Operation of water trucks outside of approved disturbance areas at EP 340.   |
| PM #6                 | 09/16/11 | EP271,<br>Link 1         | Construction activities commenced at EP271 prior to the arrival of biological monitor.   |
| Stop Work<br>Order    | 09/27/11 | Helicopter<br>Operations | A pattern of helicopter incidents posed a serious concern for the safety of the general public.  |
| PM #7                 | 09/28/11 | AER CY                   | Construction crew entered AER CY prior to Peninsular Bighorn Sheep monitor clearing the site.  |
| NCR #1                | 09/28/11 | Link 1                   | CPUC issued NCR for breeching a marked Environmentally<br>Sensitive Area (ESA), construction activity without proper<br>monitor present, and failing to communicate the event in a<br>timely fashion.  |
| FS NCR #1             | 10/27/11 | Links<br>2 & 5           | FS SUP Exhibit 4 and Traffic Control Plan violations.  |
| NCR #2                | 10/27/11 | Link 1                   | Peninsular Bighorn Sheep Construction Monitoring Plan violations.  |
| FS NCR #2             | 11/03/11 | Links<br>2 & 5           | Fire Plan and Traffic Control Plan violations.   |
| FS NCR #3             | 11/30/11 | Links<br>2 & 5           | Tower assembly, erection and wire stringing work is<br>suspended for towers not associated with GE buffers on<br>the Cleveland National Forest until resolution of all<br>noncompliance colorization issues are agreed upon by the<br>Forest Service |
| NCR #3                | 12/29/11 | Link 1                   | Peninsular Bighorn Sheep Construction Monitoring Plan violations.  |
| NCR #4                | 01/04/12 | Link 1                   | Peninsular Bighorn Sheep Construction Monitoring Plan violations.  |
| FS Stop Work<br>Order | 01/07/12 | Links<br>2 & 5           | Third non-compliance for violating the Forest Service Fire Plan.   |
| FS NCR #4             | 02/01/12 | Link 2                   | Failure to make timely notification following rope/wire drop between CP100 to CP99.  |
| FS NCR #5             | 02/06/12 | Links<br>2 & 5           | Helicopter incursions into Golden Eagle Habitat Buffers.   |
| NCR #5                | 02/08/12 | Link 1                   | Construction outside of approved work spaces, intrusion into ESA, and violation of Desert Pavement Plan.   |
| NCR#6                 | 04/13/12 | Links<br>1, 2, & 5       | Repeated load carrying without appropriate netting.  |

Other compliance incidents identified by SDG&E monitoring staff and/or crews are presented in Table 5.

| Туре     | Date     | Location             | Description   |
|----------|----------|----------------------|---|
| Incident | 11/01/10 | White Star           | Delivery of a rebar cage outside of the approved disturbance area.  |
| Incident | 02/17/11 | EP 244,<br>Link 1    | Nest incorrectly marked at entrance to EP 244.  |
| Incident | 02/18/11 | Alpine HQ            | Emergency weather landing and storage of 3 helicopters at Alpine HQ.  |
| Incident | 03/12/11 | EP 252,<br>Link 1    | Bulldozer was delivered at site prior to CPUC clearance being given.  |
| Incident | 03/15/11 | EP 214,<br>Link 1    | Dewatering approximately 1 gal of groundwater from an excavation hole without having submitted a dewatering plan to the CPUC.   |
| Incident | 04/06/11 | JVR 12 kV,<br>Link 1 | Confusion on approved work areas due to varying maps having been distributed to workers and monitors.   |
| Incident | 04/07/11 | JVR 12 kV,<br>Link 1 | A site was worked on prior to CPUC EM construction release having been received for the area, no resources were damaged.  |
| Incident | 05/05/11 | Link 4               | Three small fires were reported on Link 4 Underground.<br>Fire tools were used by the on-site fire patrol to<br>immediately respond per the Sunrise Fire Plan.<br>Notification to Alpine Fire was made.   |
| Incident | 05/17/11 | Link 1               | BMP crew drove off the road between EP345 and EP346 and park within the ESA boundary.   |
| Incident | 06/07/11 | Link 1               | During the aerial delivery of a structure body to EP339,<br>approximately 200 ft outside of Plaster City Yard, the piece<br>fell from the Aircrane. No injuries have been reported.   |
| Incident | 06/10/11 | Link 1               | During the aerial delivery of a structure layback to EP 339,<br>at the EP 339 construction site, 3 of the 4 hooks released<br>and caused an emergency placement of the steel at the<br>site. While in the process of placing on the ground, the 4 <sup>th</sup><br>hook released and the tower fell to the ground. No injuries<br>have been reported. |
| Incident | 07/07/11 | Link 1               | A project water tanker was stuck on the side of Evan<br>Hughes Highway and released approximately 1,000 gallons<br>of potable water into Coyote Wash, after pulling over to<br>evaluate a bridge crossing. All necessary notifications<br>were made.  |
| Incident | 07/07/11 | Link 5               | Construction vehicles, including project fire truck, were<br>noted to be outside of approved disturbance areas at<br>CP40 and CP41. Link leads were notified and immediate<br>corrective action was taken.  |

#### TABLE 5 PROJECT INCIDENTS (Updated 06/08/2012)

| Туре     | Date     | Location | Description   |
|----------|----------|----------|---|
| Incident | 07/11/11 | Link 1   | A skid fell off the KMax Helicopter while en route to a<br>tower site. The skid was within the Project ROW and no<br>injuries were reported. The item was retrieved on foot.  |
| Incident | 07/28/11 | Link 1   | Unapproved disturbance of approximately 50'x100'<br>occurred during the grading operations of the AER yard.<br>No resources were impacted.  |
| Incident | 08/04/11 | Link 1   | An air compressor was dropped approximately 500 ft<br>north of EP327, from a KMax helicopter while in transit<br>to a micropile site. Approximately 50-60 gallons of diesel<br>was spilled in an area of approximately 75' in diameter.<br>Site has been cleared and appropriate agencies have<br>been contacted. |
| Incident | 08/05/11 | Link 3   | Small fire resulted from excavation activities along BBTT.<br>Burned an area approximately 50'x50' prior to it being<br>extinguished. Notifications were made immediately.  |
| Incident | 08/13/11 | Link 2   | Accident along Lyons Valley Rd, where a project truck<br>went off the embankment by 300'. No injuries reported.<br>Assessment team was sent to the site and notifications<br>were made.   |
| Incident | 08/15/11 | Link 2   | Sparks caused by loose chain from a project vehicle<br>interacting with the roadway started a 2-acre fire. The<br>fire was extinguished and proper notifications were<br>made.  |
| Incident | 08/18/11 | Link 2   | An unsteady load caused a forklift to fall to its side at<br>EP 91. A small spill of hydraulic fluid took place, all<br>disturbance was contained within the established work<br>area, and no injuries were reported.   |
| Incident | 08/22/11 | Link 1   | Crew member threw a rock and knocked down a rock cairn located within an ESA. Appropriate agencies were notified.   |
| Incident | 09/08/11 | Link 2   | CPUC EM noted a water truck entering EP91 after not<br>having stopped at designated wash station. Corrective<br>action was taken.   |
| Incident | 09/12/11 | Link 5   | Crew performed minor clearing prior to the arrival of biological monitor.   |
| Incident | 09/13/11 | Link 5   | Crew performed minor clearing prior to the arrival of biological monitor.   |
| Incident | 09/15/11 | Link 5   | Micropile platform at CP67-3 rolled 50' downhill after<br>unstable placement. A helicopter removed from site to<br>limit damage. Minor vegetation damage that was surveyed<br>by onsite biologist.  |
| Incident | 09/19/11 | Link 2   | Small fire near EP42 started due to excavator hitting a rock during grading operations. This was immediately put out by onsite personnel using their required fire supplies.  |

| Туре     | Date     | Location | Description  |
|----------|----------|----------|--|
| Incident | 09/19/11 | Link 2   | 2 Micropile pipes were dropped during helicopter oper-<br>ations near CP107 and rolled down hill to injure a worker<br>trying to stop them. Minor vegetation damage that was<br>surveyed by onsite biologist.  |
| Incident | 09/20/11 | Link 1   | Trackout from EP252 was noted to Link Lead and was immediately remedied.   |
| Incident | 09/20/11 | Link 1   | Project vehicles were noted to parking outside of the approved project disturbance. Link Lead was notified and vehicles were immediately relocated.  |
| Incident | 09/21/11 | Link 1   | Dozer operator drove approximately 260 ft off of ROW near EP322. Area was surveyed by Cultural and Biological monitor.   |
| Incident | 09/21/11 | Link 3   | Approximately 800 gallons of potable water was released<br>from Northern Sediment basin. Appropriate agencies were<br>notified.  |
| Incident | 09/22/11 | Link 3   | Plywood load from helicopter dropped within substation boundaries. No injuries were reported.  |
| Incident | 09/23/11 | Link 1   | Improperly covered foundations holes were noted to the Link Lead. Follow up was performed with crews.  |
| Incident | 09/26/11 | Link 1   | Straw wattles en route via helicopter dropped into open area. No injuries were reported.   |
| Incident | 10/12/11 | Link 1   | A drill rig pulled to the side of the access road near EP185/EP186 and inadvertently crushed vegetation.   |
| Incident | 10/12/11 | Link 4   | Approximately 50 gallons of diesel fuel was released<br>immediately off of Puetz Valley Road Site was cleaned<br>and stained soils removed. Appropriate agencies were<br>contacted.  |
| Incident | 10/19/11 | Link 1   | A door fell off a helicopter near Plaster City Yard close to EP332. No injuries were reported.   |
| Incident | 11/03/11 | Link 1   | Injury occurred when a tower leg fell onsite. Events<br>surrounding the incident are still undergoing investigation.<br>Disturbance occurred outside of approved areas. Biological/<br>cultural monitors reviewed and found no resources to be<br>damaged. |
| Incident | 11/05/11 | Link 5   | Sediment off ROW at CP55/56 access road.   |
| Incident | 11/09/11 | Link 2   | Landing of project helicopter on unapproved disturbance areas.   |
| Incident | 11/15/11 | Link 5   | Off ROW incident along access road to CP65/66 pull site.   |
| Incident | 11/16/11 | Link 1   | Off ROW incident along access road to EP 226/227 pull site.  |
| Incident | 11/16/11 | Link 3   | Trash noted to be blown around during Air Crane activities at the Wilson Yard.   |
| Incident | 11/22/11 | Link 5   | Track out noted on El Monte Rd from access in/out of CP64/65 pull site. Street sweeper was dispatched.   |

| Туре     | Date     | Location | Description  |  |  |  |
|----------|----------|----------|--|--|--|--|
| Incident | 12/03/11 | Link 1   | PBHS habitat violation with low elevation flights in restricted areas.   |  |  |  |
| Incident | 12/04/11 | Link 1   | PBHS habitat violation with low elevation flights in restricted areas.   |  |  |  |
| Incident | 12/22/11 | Link 1   | PBHS habitat violation with entry into Fromm Yard prior to clearance from PBHS biologists.   |  |  |  |
| Incident | 12/27/11 | Link 1   | Two PBHS habitat violation with low elevation flights in restricted areas.   |  |  |  |
| Incident | 01/09/12 | Link 2   | Road crew operating without an Arroyo Toad Monitor<br>present at EP50, Arroyo Toad suitable habitat. Crew was<br>retrained of the importance of a monitor being present<br>during operations.  |  |  |  |
| Incident | 01/10/12 | Link 2   | Foundation crew damaged an oak tree during mobilization effort at EP49. Crew was retrained.  |  |  |  |
| Incident | 01/12/12 | Link 1   | Parking along McCain Valley Rd not in designated disturbance areas. Link Leads corrected immediately.  |  |  |  |
| Incident | 01/12/12 | Link 5   | A dozer failure led to disturbance outside of approved<br>ROW by 15 feet near CP59. All personnel were safe and<br>restoration efforts are in process.   |  |  |  |
| Incident | 01/13/12 | Link 2   | An unanticipated release of a compressor mid-flight<br>approximately 400ft North of Kruetzkamp CY. No injuries<br>or damage to property occurred. Investigation to helicopter<br>hook system is ongoing.   |  |  |  |
| Incident | 01/17/12 | Link 2   | Crew entered access road to EP73/74, Arroyo Toad<br>suitable habitat, prior to the 2 hr waiting period following<br>dawn and biological monitor clearance. Crew was spoken<br>to and better signage is to be installed.  |  |  |  |
| Incident | 01/18/12 | Link 1   | Concrete blocks were placed outside of approved disturbance<br>area at EP224/5 prior to the approval of Variance #37. To<br>limit disturbance, blocks have been left, but cannot be used<br>until approval of the variance.  |  |  |  |
| Incident | 01/18/12 | Link 1   | Assembly crew arrived at EP177 prior to an approved bir<br>survey having been conducted and submitted. Crews were<br>ushered out by onsite avian biologist performing said<br>survey.  |  |  |  |
| Incident | 01/18/12 | Link 1   | Foundation crew entered PBHS habitat at EP256 outside<br>of approved work window. They were escorted out by<br>monitors at a nearby site upon noticing. GF for crew was<br>released by the project and a standdown with GF and<br>foreman was performed on 01/23/12. |  |  |  |
| Incident | 01/19/12 | Link 2   | Bird strike occurred during helicopter operations near EP33.<br>Monitors on board believed the bird to be a swallow, but<br>no remains were found to confirm.  |  |  |  |

| Туре     | Date     | Location | Description  |  |  |  |
|----------|----------|----------|--|--|--|--|
| Incident | 01/20/12 | Link 5   | Wire dropped between CP96 and CP100 during wire operations. No resources were found to be damaged, hurt or killed.   |  |  |  |
| Incident | 01/20/12 | Link 5   | Gate left open for access road to pull site between<br>CP64/65 and released livestock that was present.<br>Monitors were brought onsite to herd them back into the<br>pen and ensure security of the gate.   |  |  |  |
| Incident | 01/24/12 | Link 5   | Helicopter breached the GE buffer at Bell Bluff region approximately 621 feet. No resources impacted.  |  |  |  |
| Incident | 01/25/12 | Link 5   | Helicopter was noted by CPUC EM to have landed outsid<br>of approved project workspace. Correction was made<br>immediately and discussion was had with pilot about<br>landing in only approved areas.  |  |  |  |
| Incident | 01/26/12 | Link 5   | Helicopter breached the GE buffer at the Bell Bluff region approximately 521 feet. No resources impacted.  |  |  |  |
| Incident | 01/27/12 | Link 2   | Helicopter breached the GE buffer at the Thing Valley region approximately 161 feet. No resources impacted.  |  |  |  |
| Incident | 01/31/12 | Link 1   | Fuel tanker was refueling a smaller fuel truck for use by project helicopters in unapproved workspace near JVR. Link Lead made immediate correction and spoke to creater the second structure of the s |  |  |  |
| Incident | 02/01/12 | Link 2   | Helicopter breached the GE buffer at the Thing Valley region by an unknown amount. No resources impacted.  |  |  |  |
| Incident | 02/13/12 | Link 2   | Several contractor vehicles were parked outside of the ROW on brush adjacent to Cameron TT near EP109. Link Lead was contacted and item was corrected.   |  |  |  |
| Incident | 02/24/12 | Link 2   | Helicopter dragged a long line through vegetation outside of workspace at EP109. Minor vegetation impacts.   |  |  |  |
| Incident | 02/25/12 | Link 5   | Helicopter experienced a hard landing at the Sycamore CY<br>and damage was incurred. No injuries or impacts were<br>noted. Investigation is ongoing.   |  |  |  |
| Incident | 02/27/12 | Link 3   | Trash was noted to Link Lead at the Wilson CY.   |  |  |  |
| Incident | 02/28/12 | Link 1   | Project activities were noted to be occurring in PBHS areas<br>without concurrence from Wildlife Agencies provided to<br>CPUC monitors. Follow up discussion occurred with WA.   |  |  |  |
| Incident | 02/29/12 | Link 1   | Debris was noted to the Link Lead as being blown around JVR CY during Air Crane operations.  |  |  |  |
| Incident | 03/02/12 | Link 2   | Kmax helicopter dropped cribbing near EP5. No reports c injuries or impacts.   |  |  |  |
| Incident | 03/08/12 | Link 1   | Trash in several areas along the ROW, particularly the mylar taping utilized for bird deterrents, has been noted in various locations. Issue is currently being addressed.   |  |  |  |
| Incident | 03/12/12 | Link 2   | Vehicle was noted to be parked outside approved workspace and within the drip line of an oak tree.   |  |  |  |

| Туре     | Date     | Location | Description   |  |  |  |
|----------|----------|----------|---|--|--|--|
| Incident | 03/14/12 | Link 1   | A helicopter noted to be operating prior to 7am at the Rough Acres Construction Yard.   |  |  |  |
| Incident | 03/20/12 | Link 1   | Crew vehicles were noted to be parked outside of<br>approved workspaces along Old Hwy 80. Vehicles were<br>immediately moved upon notification.                     |  |  |  |
| Incident | 03/20/12 | Link 1   | Marker balls were being staged inside a noted ESA at the<br>Jacumba Valley Ranch Yard. They were immediately<br>moved outside of the ESA and no impacts were noted. |  |  |  |
| Incident | 03/21/12 | Link 1   | Work equipment was placed outside of approved<br>workspace via helicopter ate EP225. Corrective action<br>was immediately taken upon notification.                  |  |  |  |
| Incident | 03/22/12 | Link 1   | Vehicle was noted to be parked outside of approved<br>workspace near EP205-1 and project personnel was<br>observed to be smoking in a non-designated area.          |  |  |  |
| Incident | 03/27/12 | Link 2   | Vehicle was noted to be parked within a bird buffer nea EP90.   |  |  |  |
| Incident | 03/27/12 | Link 2   | Two helicopters noted to be operating prior to 7am at the SWAT Construction Yard.   |  |  |  |
| Incident | 03/28/12 | Link 2   | Breaches within the Arroyo Toad exclusionary fencing between EP65 and EP69 were noted to the Link Lead.   |  |  |  |
| Incident | 03/29/12 | Link 1   | Trash at EP190 and dust on McCain Valley Road was note to the Link Lead.  |  |  |  |
| Incident | 03/31/12 | Link 1   | Bulldozer was noted to have parked outside of approved<br>workspace along the access road to EP236. The<br>equipment was moved upon notification to the crew.       |  |  |  |
| Incident | 04/02/12 | Link 1   | Parking occurred in unapproved project areas near S-2<br>Yard. Immediate corrective action was taken upon<br>notification to Link Lead.                             |  |  |  |
| Incident | 04/04/12 | Link 1   | Crew truck was noted to have parked outside of<br>approved workspace along the access road to EP236.<br>Monitors have placed additional signage along the road.     |  |  |  |
| Incident | 04/09/12 | Link 1   | Crews were noted to not being utilizing a designated path<br>(which avoids an ESA) from TSAP to EP137-1. A warning<br>was given and crews were addressed.           |  |  |  |
| Incident | 04/10/12 | Link 1   | Trash was observed at EP187 pull site.  |  |  |  |
| Incident | 04/17/12 | Link 4   | Cement truck was noted to be driving down Alpine Blvd<br>with chutes open. Link Lead was contacted and<br>contractor was informed of the activities.                |  |  |  |
| Incident | 04/20/12 | Link 1   | Bulldozer went off ROW during grading operations near<br>EP255. No sensitive biological or cultural resources were<br>damaged.                                      |  |  |  |
| Incident | 04/24/12 | Link 1   | Dust was noted to be seen at McCain Valley Construction<br>Yard due to Air Crane operations. Coordination was to<br>improve in future operations.                   |  |  |  |

| Туре     | Date     | Location | Description   |  |  |  |
|----------|----------|----------|---|--|--|--|
| Incident | 04/25/12 | Link 2   | Holes were noted in the Arroyo Toad fence along the access road to EP76. Crews were sent out to repair prior to rain event.   |  |  |  |
| Incident | 05/08/12 | Link 2   | Speeding was noted to Link Lead to/from Bartlett<br>Hauser CY.  |  |  |  |
| Incident | 05/16/12 | Link 2   | Dust was noted at Kruetzkamp CY to the Link Lead during air crane operations.   |  |  |  |
| Incident | 05/22/12 | Link 2   | Speeding was noted to Link Lead to/from Bartlett Hauser CY.   |  |  |  |
| Incident | 05/24/12 | Link 2   | During the removal of flower pots and guard poles at the EP27-1 guard structure site, a small amount of vegetation was damaged. No sensitive resources or nests were noted to be damaged after assessment by biological and avian monitors. |  |  |  |


# **CONSTRUCTION PROGRESS**

Table 6 provides a summary of construction progress through the end of the subject reporting period.

| CONSTRUCTION PROGRESS     |                 |                              |                          |                   |                   |
|---------------------------|-----------------|------------------------------|--------------------------|-------------------|-------------------|
| Agency                    | Total<br>Towers | Released for<br>Construction | Foundations<br>Completed | Towers<br>Erected | Wire<br>Installed |
| Non-Federal               | 169             | 169                          | 169                      | 169               | 152               |
| Bureau of Land Management | 179             | 179                          | 179                      | 179               | 147               |
| US Forest Service         | 76              | 76                           | 76                       | 75                | 14                |
| Miramar                   | 14              | 14                           | 14                       | 14                | 30                |
| Total                     | 438             | 438                          | 438                      | 437               | 343               |

TABLE 6 CONSTRUCTION PROGRESS

# **PROJECT PHOTOGRAPHS**



**Figure 1:** Hydromulching at EP255 pull sites. (Link 1)



**Figure 2:** Hydromulching at EP89-1 pull sites. (Link 2)



**Figure 3:** Damaged vegetation from guard structure removal near EP27-1. (Link 2)



Figure 4: Aerial view of Thing Valley Yard. (Link 2)