

---

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00014

From: 12/19/2010 Through: 12/25/2010

---

### INTRODUCTION

During the week of 12/19/2010 through 12/25/2010, construction continued at the Alpine RFO, Alpine Construction Yards, San Luis Rey Substation, Encina Switchyard, the Rough Acres Construction Yard, the Thomas Yard, Link 4 Underground and Link 3, Suncrest Substation.

Note: Holidays with no work: December 23 through 25.

Additional Note: During a six-day time period from December 17 through December 22, a rainfall event with totals up to 7 inches were recorded. Very limited work activity took place during this time.

Pre-Construction Activity with appropriate monitors:

During the week of 12/19/2010 through 12/25/2010, all pre-construction activity was cancelled due to inclement weather conditions.

### ALL LINKS

The following is a summary of construction activity where monitors were on site:

Alpine RFO: Minimal contractor activity on site primarily for the PAR office modular office. All activity was monitored by Link Leads and storm water monitors.

Alpine Construction Yard: Equipment and reel deliveries were made.

San Luis Rey Substation: Only testing being done during this period by SDG&E crews in control room.

Rough Acres Construction Yard: Minimal construction activity due to inclement weather. As weather permitted, tower assembly conducted on the air strip. Inventory of steel continues within the storage barns. Delivery of reels continues.

Encina Switchyard: SDG&E crews on site building disconnects. No ground disturbing work during this period because of inclement weather. BMPs improved at discharge point after an inspection during heavy rain indicated maintenance was needed.

Thomas Yard: Sorting and moving of steel was the main activity. The Link Lead continues to monitor the Burrowing Owls.

Link 4 Underground: Minimal activity during this period due to inclement weather. Repairing of some pot-hole areas conducted near Vault 9 and 13. Access road construction from the Slaughter gate to the driveway approximately 400 west of the Lightner Property APN52303012 and from the Slaughter gate to the driveway, approximately 700 east, was reviewed by the CPUC EM and released for construction.

Link 3 Suncrest Substation: Minimal activity during this period due to inclement weather. No ground disturbing activity. An inspection of BMPs was made during a rain event. BMP improvements were made in several areas.

The Jack and Bore site south of I-8, near Thomas Family Trust APN40221103 was reviewed by the CPUC EM and released for construction.

SWEAP and Wildland Fire Prevention Training, continues to be facilitated at the Ayres Inn in Alpine every Tuesday and Thursday at 7:30 a.m.

During the reporting period of 12/19/2010 to 12/25/2010 a rain event occurred for 5 days with precipitation amounts of over 7 inches recorded in Coastal and Inland areas.

# Sunrise Powerlink Transmission Project

Weekly Monitoring Report No. 00014

From: 12/19/2010 Through: 12/25/2010

## ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: 1</b>								
B-1c								
12/20/2010	Y						Remarks: Rough Acres Activity: TTSI - delivery of one load of reels Don Spires, Erik Strods and myself concluded no deliveries should be stored on the runway due to the heavy volume of rain and to prevent rutting of the airstrip. We told Manny from TTSI to call Brian Telesmanic directly if any deliveries were anticipated.	Rough Acres Phase 1
Mitigation Measure in Compliance? oversight	Y							
12/20/2010	Y						TTSI and Maxim Cranes - Morning tailgate - TTSI/MAXIM accepted 1 load of reels	ROUGH ACRES
Mitigation Measure in Compliance?	Y						Remarks: work activity in compliance	
12/21/2010	Y						No work activities	ROUGH ACRES
Mitigation Measure in Compliance?	Y							

# Sunrise Powerlink Transmission Project

Weekly Monitoring Report No. 00014

From: 12/19/2010 Through: 12/25/2010

## ENVIRONMENTAL MONITORS

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: 1</b>								
B-1c								
12/22/2010	Y						Remarks: No environmental issues	Rough Acres
<b>Mitigation Measure in Compliance? Y</b>								
bio-monitoring								
<b>LINK: 4</b>								
B-1c								
12/21/2010	Y							Vault 19
<b>Mitigation Measure in Compliance? Y</b>								
12/23/2010	Y						Remarks: Monitored Tom Dyke drilling, PAR potholing and tree trimming crews. Drilling dust was controlled and at a very minimum. Vault location was cut, milled and steel plates were placed on the vault location. All construction activities in compliance.	Vault 9
<b>Mitigation Measure in Compliance? Y</b>								
Monitoring								
12/23/2010	N						Conducted biological monitoring	Alpine Blvd
<b>Mitigation Measure in Compliance? Y</b>								
Bio monitoring								
12/24/2010	Y						Remarks: All work was conducted within the Project' ROW boundaries and was compliant.	Vault 19, 17 & 9
<b>Mitigation Measure in Compliance? N</b>								
B-7a								
12/21/2010	Y						All holes were patched before leaving the job site	226+50
<b>Mitigation Measure in Compliance? Y</b>								
compliance								
12/22/2010	Y						Hole patches were repaired before leaving the job site	226+50
<b>Mitigation Measure in Compliance? Y</b>								
compliance								

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00014

From: 12/19/2010 Through: 12/25/2010

### ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: 4</b>								
BIO-APM-3								
12/21/2010	Y						Vehicles remained on Alpine Blvd or within ROW .	226+50
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
ROW								
12/22/2010	Y						Vehicles remained on Alpine Blvd or within ROW .	226+50
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
ROW								
BIO-APM-4								
12/21/2010	Y						Vehicles followed mitigations and remained on Alpine Blvd or within the ROW .	226+50
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
ROW								
12/22/2010	Y						Vehicles followed mitigations and remained on Alpine Blvd or within the ROW .	226+50
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
ROW								
C-1e								
12/23/2010	Y						Work consisted of drilling and potholing at vault 9 and was within compliance	Vault 9 Alpine Blvd
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Cultural								
<b>LINK: NA</b>								
B-1c								
12/20/2010	Y						Remarks: Testing conducted by SDG&E crews in control room. No ground disturbing work because of rain. Site was in compliance.	San Luis Rey
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Mitigation met								
12/20/2010	Y						Remarks: SDG&E crews building disconnects. Drilling by contractor could not be performed because of rain. Site was in compliance. BMPs were improved at discharge point.	Encina
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Mitigation met								

# Sunrise Powerlink Transmission Project

Weekly Monitoring Report No. 00014

From: 12/19/2010 Through: 12/25/2010

## ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
----------------------------	------------	--------------	--------------------------	------------	------------	-------------	---------------	------------

LINK: NA

B-1c

12/21/2010 Y

Mitigation Measure in Compliance? Y

Mitigation met

Remarks: SDG&E crews were building disconnects. Drilling by contractor could not be performed because of rain. Site was in compliance. BMPs improved at discharge point.

San Luis Rey

12/21/2010 Y

Mitigation Measure in Compliance? Y

Mitigation met

Remarks: All testing by SDG&E crews was conducted in the control room. No ground disturbing work because of rain. Site was in compliance.

Encina