Weekly Monitoring Report No. 01468

INTRODUCTION

During the week of 02/13/2011 through 02/19/2011, construction continued at the Alpine RFO, Alpine Construction Yards, San Luis Rey Substation, Encina Switchyard, the Rough Acres Construction Yard Phase I & II Use, the Thomas Yard, Link 4 Underground, Link 3, Suncrest Substation, for NTP No. 13 for Links 1, 2 & 5, non-Federal lands only, and the Imperial Valley Substation.

From: 02/13/2011

Pre-Construction Activity with appropriate monitors:

Monday, 2/14/2011: One crew cleared the line for RPs at EP 139-1 and EP 140-1. One crew conducted boulder surveys at EP 73, EP 86-1 and EP 189-3.

Tuesday, 2/15/2011: Five crews verified tower and reference points at EP 129, EP 130-1, EP 134-1, EP 135, EP 129, EP 130-1, EP 138-2, EP 134-1, EP 135 and EP 138-2. Three crews conducted staking.

Wednesday, 2/16/2011: Four crews verified tower and reference points at EP 98-1, EP 99-2, EP 101-2, EP 121-3, EP 121A-1, EP 122-1, EP 136, EP 137, EP 99-2, EP 101-2, EP 136, EP 137; one crew cleared the line for RPs at EP 139-1 and EP 140-1. Three crews conducted staking.

Thursday, 2/17/2011: Four crews verified tower and reference points at EP 97, EP 108-2, EP 95, EP 96, EP 109-1, EP 95, EP 96, EP 97, EP 98-1, EP 108-2, EP 121-3, EP 121A-1, EP 122-1; one crew cleared the line for RPs at EP 139-1 and EP 140-1. Three crews conducted staking.

Friday, 2/18/1011: Four crews conducted tower staking, verification of reference points at EP 176, EP 178, EP 189-3. One crew conducted topographical staking on Alpine Blvd. near Star Valley Road. Three crews conducted staking.

Saturday, 2/19/2011: Three crews conducted staking for EP 73 tower and 12kV relocations; Seven crews conducted tower staking; Two crews conducted land surveys.

Native American Representatives: The following Representatives monitored during this period at various construction sites: Campo: Dan Mason, Andrea Najera, Albert Quihuis, Frank Salazar. Viejas: Clarence Brown, Frank Brown, Vera Tucker. Cocopah: Alan Hatcher. Jamul: Jesse Pinto. Kumeyaay Native: Dave Elliot Sr., Dave Z. Elliot Jr.

Wildlife Reporting: There were no listed or Species of Special Concern to report dead in Project construction limits during this period.

During this reporting period, a rain event began on 2/16/2011 with precipitation occurring through 2/19/2011. The following precipitation totals have been recorded for this period: Link 1: 2.4 to 4.0 inches; Link 2: 3.95 to 4.35 inches; Link 3: 4.6 inches; Link 4: 2.6 inches; Link 5: 1.65 to 2.3 inches; Alpine HQ/Yard: 2.6 inches; Rough Acres Yard: 4.0 inches, Encina Switchyard: 1.6 inches. Pre-storm inspections were conducted and maintenance of BMPs was conducted as identified. In Link 2 and Link 3, precipitation of up to 3.4 inches was recorded for a 24-hour period, causing a breach in BMPs. (A post-storm inspection identified areas where BMP maintenance and improvement was initiated.) Minor leaks and drips from equipment were contained and cleaned. Leaks and drips are also recorded in the SWPPP log along with reporting to appropriate agencies as needed.

Summary of Construction Yard activities where monitors were on site for any set-up and ground disturbing activities:

JVR: Helicoptor and structure assembly operations are ongoing. Work halted on Saturday, 2/19/2011 due to rain. Erosion control devices (ECDs) functioning properly. Driveway installation conducted. Helix: Crews finished fencing and gate. Access road improvement. Hartung: Site prep completed. Access road improvement. Active red-tailed hawk nest with buffer in place. Bartlett-Hauser Creek: Fencing complete, approval was obtained from the County of San Diego for construction activity at the Bartlett-Hauser Creek Constructions Yards on Sunday, 2/20/2011 and Monday (holiday) 2/21/2011. Kreutzkamp: No activity at this yard. SWAT: Wash station installed and fencing begun. Access road improvement. Limited activity due to rain. S2: Not active; pre-construction

ALL LINKS

Alpine RFO: No ground disturbing work conducted. Alpine Construction Yard: Equipment, reel and monopole deliveries were made.

San Luis Rey Substation: Roel construction was only on site for part of the week. Work conducted on Sunday, with approval from the City of Oceanside, 2/6/2011. Rough Acres Construction Yard: PAR conducting steel tower assembly and moving their activities to the JVR Yard. TTS-I continues to receive steel deliveries. The Wash Station on site is being used several times daily to prevent the spread of weeds. Driveway improvements conducted.

Encina Switchyard: Contractor TBEA on site building a transformer. Contractor Roel has mobilized on site. No excavation planned until after the predicted rain.

Thomas Yard: No ground disturbing work being conducted. The Link Lead monitored for any Burrowing Owls during activity on site. Rain prevented work.

Link 4 Underground: Vaults 3L and 5L were set this week. Excavation continues at the entry pit of the Highway 8 Jack and Bore site. Excavations were conducted at Vaults (V) 3L and 8L. Potholing was conducted on Alpine Blvd. at South Grade Road and at Tavern Rd., V7L and V13L. Trenching was conducted at V7L, V15L, V14L, V18L and East of West Willows Road. BMPs were installed in the Bauer Bridge area. BMPs in other areas checked for any needed maintenance before expected rain. It was determined that the

Page 1 of 61

Weekly Monitoring Report No. 01468

access road from El Capitan Reservoir to the Bauer Property will not be used.

Link 3 Suncrest Substation and Wilson Yard: Rough grading along the access road and pad. Continued installation of the canyon drain in the northern drainage. Sediment basin construction and BMP maintenance was conducted prior to the predicted rain event. The Contractor began preparations to move cultural boulders on the pad site. Approval was obtained from the County of San Diego for construction activity in the Wilson Construction Yard on Sunday, 2/20/2011 and Monday (holiday) 2/21/2011.

From: 02/13/2011

Links 1, 2 & 5, NTP No. 13: Link 1: Conventional foundations conducted at EP 244, EP 218-1, 217-1, EP 215, EP 214, EP 213, EP 211, EP 210 and EP 219-1. Helicopter structure assembly at EP 230-1, EP 245-1, EP 44, EP 238-1, EP 237-1, EP 234-1, EP 232-1, EP 231A, EP 231A, EP 227, EP 199-3, EP 194-2, EP 197-2, EP 195-1. Micropile drilling conducted at EP 238-1, EP 235-1, EP 231A, EP 231-1, EP 229-1, EP 226-1, EP 224-1, EP 223-1, EP 221-A and EP 230-1. Soil borings conducted at EP 84.

Conventional structure assembly at EP 206-1, EP 203-3, EP 200A, EP 205-2, EP 209-1, EP 204-3, EP 202-3, EP 201-3, EP 208, EP 207, EP 218-1, and EP 217-1.

Link 2: Soil boring at EP 84. Access road rough grading at EP 85-2, and EP 84-B.

Link 5: Soil boring at CP 20. Access road rough grading at CP 31-2. Conventional foundation installation began at CP 17-1.

Driveway installations were conducted at EP 245-1 thru EP 244, EP 209-1, EP 219-1 thru EP 210 and pull site.

Imperial Valley Substation Upgrade: Trenching and excavation for foundations continues. A water truck has been utilized for control of dust along the access road. On two occasions, small collections of freshwater mollusks were recovered from the excavated sediments by the Paleontologist. These paleontological discoveries were from the Lake Chuilla sediments. No work was stopped or diverted.

ENVIRONMENTAL MONITORS

LINK: 1

ASM Affiliates, Inc. Adam Giacinto ASM Affiliates, Inc. Isabell Cordova ASM Affiliates, Inc. Jessica Hennessey Patrick Hadel ASM Affiliates, Inc. Rebecca Carson Burns & McDonnell Chambers Group Ana Hernandez Chambers Group Brent Riemer Chambers Group Chris Bugbee Caesara Brungraber Chambers Group

Chambers Group Carina Weber Chambers Group Darin Busby Chambers Group **Drew Engstrom** Chambers Group David Flietner Eliysha Loveless Chambers Group Chambers Group Erik Strods

Chambers Group Gerhard Bombe Chambers Group Garrett Huffman

Chambers Group Ivv Watson

Weekly Monitoring Report No. 01468

ENVIF	RONMEN	TAL M	ONITO	DRS

L	N	:	-
	_ 1	 •	-

Chambers Group John Brooks Hart

Chambers Group John Dicus

Chambers Group Jennifer Edwards

Chambers Group Jeremy J Smith

Chambers Group Kari Kerwin

Chambers Group Melanie Dicus

Chambers Group Michael W. Klein

Chambers Group Ryan Quilley

Chambers Group Robert Thompson

Chambers Group Stephen Clayton

Chambers Group Sean Han

Chambers Group Seth Reimers

Chambers Group Shane Valiere

Chambers Group Tyler Sears

Pangea Biological Amanda Castro

Pangea Biological Don Spires

Pangea Biological Eric Piehel

Pangea Biological Steve Ehrilich

Pangea Biological Scott Rowland

Pangea Biological Tim Cass

San Diego Natural History Museum Christopher S. Plouffe

San Diego Natural History Museum Gino Calvano

LINK: 2

ASM Affiliates, Inc.

Chambers Group

Chambers Group

Chambers Group

Chambers Group

Caesara Brungraber

Chambers Group

Carina Weber

Gerhard Bombe

Page 3 of 61

Chambers Group

Through: 02/19/2011

Weekly Monitoring Report No. 01468

ENVIRONMENTAL MONITORS	
LINK: 2	
Chambers Group	Jennifer Edwards
Chambers Group	Kari Kerwin
Chambers Group	Robert Thompson
Chambers Group	Saraiah Skidmore
Chambers Group	Shane Valiere
Chambers Group	Tyler Sears
Pangea Biological	Amanda Castro
LINK: 3	
ASM Affiliates, Inc.	Lucas Piek
Pangea Biological	Mark Meridith
TRC Solutions, Inc.	Alicia Hill
TRC Solutions, Inc.	Randy Blake
LINK: 4	
ASM Affiliates, Inc.	Daniel Ryan McCarthy
ASM Affiliates, Inc.	Jessica Hennessey
ASM Affiliates, Inc.	Jason Kjolsing
ASM Affiliates, Inc.	Rebekah Loveless
ASM Affiliates, Inc.	Thomas Taylor
Burns & McDonnell	Jeff Smith
Burns & McDonnell	Ken Katsuda
TRC Solutions, Inc.	Katherine Vittum
TRC Solutions, Inc.	Michael Mezey
TRC Solutions, Inc.	Michael Scaffidi
TRC Solutions, Inc.	Nina Allmendinger
LINK: 5	
Chambers Group	Brett Bergman
Chambers Group	Brent Riemer
Chambers Group	Carina Weber

Page 4 of 61

Through: 02/19/2011

Weekly Monitoring Report No. 01468

ENVIRONMENTAL MONITORS

LINK: 5

Chambers Group Ian Maunsell
Chambers Group Jennifer Edwards
Chambers Group Linette Lina
Chambers Group Michael W. Klein

Chambers Group

Chambers Group

Chambers Group

Chambers Group

Chambers Group

Chambers Group

Shane Valiere

San Diego Natural History Museum Christopher S. Plouffe

Tyler Sears

LINK: NA

Chambers Group

ASM Affiliates, Inc. Meagan Papp Jim Gibson Burns & McDonnell Chambers Group Brian Lohstroh Chambers Group Corey Vane **Chambers Group** Fern Hoffman Chambers Group John Kanlund **Chambers Group** Kris Alberts Chambers Group Laurie Gorman **Chambers Group** Tyler Sears

San Diego Natural History Museum

San Diego Natural History Museum

TRC Solutions, Inc.

Bradford O. Riney
Patrick J. Sena
Lauralyn Jensen
Okorie Puryear

Page 5 of 61

Through: 02/19/2011

Weekly Monitoring Report No. 01468

	AL COMPLIANCE						
	AL COMPLIANCE	~		-	_		
Mitigation Measu Date	re A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1							
B-1c							
02/13/20	011 Y					All steel work in compliance	Rough
Mitigation Measu Biomonitoring	re in Compliance? Y						Acres
02/13/20	011 Y					All work compliant	EP 225-1.
Mitigation Measu Bio	re in Compliance? Y						EP230-1
02/14/20	011 Y					All equipment removal from the structure site	EP223-1
Mitigation Measu compliance	re in Compliance? Y					was done in compliance with the Project's mitigation measures and the bio APMs were met.	
						Remarks: Crux crew was dropped off by helicopter at the EP221A TSAP and then walked to EP223-1 to move their micropile equipment via helicopter to EP224.	
02/14/20	011 Y					All steel work done in compliance.	EP 213, EI
Mitigation Measu Bio Monitoring	re in Compliance? Y					Remarks: Bio monitor was present with PAR crew while working in ROW. Crew worked within work site limits and did not impact any ESAs.	214
02/14/20	011 Y					All work in compliance.	STR EP
Mitigation Measu In Compliance	re in Compliance? Y					Remarks: Crux crew was drilling micropiles for tower leg foundation at Leg C. Baxter crew graded (cut out about a foot of soil in a 6 foot diameter circle) around tower legs A,B, and C.	226-1
02/14/20	011 Y					All work completed by road grinding crew was	EP 210 &
Mitigation Measu	re in Compliance? Y					in compliance.	EP 209-1
02/14/20						Monitored drilling at EP224-1.	EP 224-1
Mitigation Measu Biomonitor	re in Compliance? Y					Remarks: All drilling activities in compliance	

From: 02/13/2011

Page 6 of 61

Weekly Monitoring Report No. 01468

ENVIRON	NMENTAL (COMPLIANCE						
Mitigation	n Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1								
B-1c								
	02/14/2011	Y					Monitored drilling activities at EP244-1	EP 244-1
Mitigation monitoring		Compliance? Y					Remarks: All activities in compliance.	
(02/14/2011	Y					Work in yard done in complaince.	Rough
Mitigation biomonitor		Compliance? Y					Remarks: All work done in complaince	Acres
	02/14/2011	Y					Work was in compliance.	EP
Mitigation	n Measure in	Compliance? Y					Remarks: Woodward Bros. Inc. drilling shaft foundations. Quality control checks on rebar stored at EP 243.	243/EP244
(02/14/2011	Y					All activities met mitigation requirements.	EP 219
Mitigation BioMonitor		Compliance? Y					Remarks: Monitored drilling operations at structure site EP 219. All activities were kept within the designated work area and all environmental mitigation measures were followed	
(02/14/2011	Y					All work in compliance	ROUGH
Mitigation compliance		Compliance? Y					Remarks: Rough Acres Ranch (RAR) Contractors-Par, TTSI, Maxim, United. PAR- Tower QA/QC, steel off-loading and materials/bolt organizing, water deliveries to Baker tank. PAR/TTSI- Used water trucks to suppress dust on site. TTSI- off-loaded and organized steel and materials. UNITED- Service toilets. MAXIM Cranes- accepted a load of wire reels, organized wire reels.	
		Y Compliance? Y					All structure assembly operations were done in compliance with the Project's mitigation measures and the bio APMs were met.	JVR CY
- Carpinane	-						Remarks: Steel assembly in the JVR yard.	

From: 02/13/2011

Page 7 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1							
B-1c							
02/14/2011						All work in compliance.	
Mitigation Measure i	n Compliance? Y					Remarks: Micropile drilling at EP238-1	
02/14/2011	Y					Crew members and activities were all compliant	EP220
Mitigation Measure i	n Compliance? Y					Remarks: Wattles were installed around the perimeter and slope correctly. No compliance issues to report.	
02/14/2011	Y					All work done in compliance.	EP213,
Mitigation Measure i oversight	n Compliance? Y					Remarks: Oversight & management of activities PAR 1) Conventional drilling EP219 2) Air track drilling EP220 3) Delivery of foundation forms at EP213 & EP214; Crux 1) Micropile at EP 226-1, 231A, 238-1, 224, 229-1; Woodward Brothers 1) Conventional drilling EP244; Hankins 1) Rough Acres entrance; United Power Contractors 1) 12kv relocation EP215; TTS-I 1) Steele delivery Rough Acres	219, 220, 226-1, 231A,
02/14/2011	Y					All work in compliance.	between
Mitigation Measure i monitoring	n Compliance? Y					Remarks: Monitored the preparations for modular house removal on Desert Rose Ranch Road (Loving property)	EP 227 & EP228
02/14/2011	Y					Project was in compliance.	ROUGH
Mitigation Measure i Bio Monitor	n Compliance? Y					Remarks: Crew added a 4-6" layer of gravel and soil to graded road, and compacted it.	ACRES YARD
02/14/2011	Y					Construction work was in compliance with the	EP229 -
Mitigation Measure i	n Compliance? Y					MMCRP	Jacumba
Bio Monitoring						Remarks: Monitoring micropile drilling	
02/14/2011	Y					Monitored the delivery of steel between Rough	Rough
Mitigation Measure i	n Compliance? Y					Acres and Jacumba Valley construction yards. Remarks: All biological mitigation measures were followed	Acres and Jacumba Valley

From: 02/13/2011

Page 8 of 61

Weekly Monitoring Report No. 01468

ENVIRO	NMENTAL (COMPLIANCE						
Mitigatio	on Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK:	1							
B-1c								
	02/14/2011	Y					All drilling activities in compliance.	EP 231-A
Mitigation monitoring		Compliance? Y						
Mitigatio Foundation		Y Compliance? Y					Monitored assembly of concrete foundations at Structures EP-213, EP-214, and EP-217. All work conducted within approved work areas and within environmental compliance.	
							Remarks: Monitored assembly of concrete foundations at Structures EP-213, EP-214, and EP-217. All work conducted within approved work areas and within environmental compliance.	
	02/15/2011	Y					Drilling In compliance	Rough
Mitigatio biomonite		Compliance? Y					Remarks: All work done within site boundries and in compliance.	Acres
	02/15/2011	Y					In Compliance	ROUGH
Mitigatio complian		Compliance? Y					Remarks: Rough Acres Ranch (RAR) Contractors-Par, TTSI, Maxim, JMB Sanitation, Colwell, SDGE. Colwell- Placed gravel around Baker (Water) tanks to prevent puddling. PAR- Tower QA/QC, steel off-loading and materials/bolt organizing, water deliveries to Baker tank. PAR/TTSI- Used water trucks to suppress dust on site. TTSI- off-loaded and organized steel and materials. Also loaded steel for PAR. JMB- Serviced toilets. MAXIM Cranes- organized wire reels, clean site of trash	ACRES
Mitigatio	02/15/2011 on Measure in	Y Compliance? Y					All work completed by paving crew was in compliance. Remarks: At 1245, paving was completed at the entrance to EP 209-1.	EP 209-1

From: 02/13/2011

Page 9 of 61

Weekly Monitoring Report No. 01468

ENVIRO	NMENTAL (COMPLIANCE						
Mitigatio	on Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1	1							
B-1c								
	02/15/2011	Y					All drilling in compliance.	EP 226-1
Mitigation Complian		Compliance? Y					Remarks: Crew members in compliance	
	02/15/2011	Y					Monitored drilling at EP224-1.	EP 224-1
Mitigation Bio monit		Compliance? Y					Remarks: All drilling activities in compliance	
	02/15/2011	Y					All work in compliance.	between
Mitigatio monitorin		Compliance? Y					Remarks: Monitored the preparations for modular house removal on Desert Rose Ranch Road (Loving property)	EP 227 & EP228
Mitigatio	02/15/2011 on Measure in	Y Compliance? Y					All work completed by paving crew was in compliance.	EP 210
. .		F					Remarks: Paving was completed by the Hankins crew at 1530. All work area was clean and no debris left by paving crew.	
	02/15/2011	Y					Work was in compliance	EP233 and
Mitigatio Bio Moni		Compliance? Y					Remarks: Flagging work was incompliance with the MMCRP	EP234 - Jacumba
	02/15/2011	Y					Project was in compliance	EP 244
Mitigation		Compliance? Y					Remarks: Project was in compliance	
	02/15/2011	Y					All work in compliance.	EP 229-1
Mitigatio	on Measure in	Compliance? Y					Remarks: Bio monitor for EP229-1.	

From: 02/13/2011

Weekly Monitoring Report No. 01468

ENVIRONMEN	NTAL CO	MPLIANCE						
Mitigation Mea Date		B Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1								
B-1c 02/15 Mitigation Mea	5/2011 Y						Oversight & management of activities: PAR 1) Conventional drilling EP219 2) Air Track	EP214-EP2 EP244
oversight	isure in Co	лириансе. 1					drilling EP220 3) Foundation form setup EP214, 217, 218. Woodward Brothers 1) Conventional drilling EP244. Crux 1) Micropile drilling EP226-1, 231A, 238-1, 224-1, 229-1. UPC 1) 12kv relocation EP215.	
							Remarks: All work in compliance	
02/15 Mitigation Mea BioMonitor	5/2011 Y asure in Co					Notified Link Lead	At approximately 1500 hours a small amount of diesel fuel (less than one half gallon) leaked from a mechanics truck onto the access road near structure EP 219. The crew immediately stopped the leak, contained it, and cleaned up the spill with the spill kits on hands. All mitigation measures were followed.	EP 219
							Remarks: All activities were kept within the designated work area and all environmental mitigation measures were followed.	
02/15 Mitigation Mea	5/2011 Y						All work in the approved work zone and in compliance.	EP210, EP209-1
Biomonitoring	isure in Co	лириансе. 1					Remarks: All work monitored and in compliance.	
02/15	5/2011 Y	-					In compliance.	EP 231A
Mitigation Mea In Compliance	asure in Co	ompliance? Y					Remarks: Drilling micropiles and installing rod at tower leg D, STR EP 231-A. Crews installed BMPs. Flagged and relocated 3 barrel cacti out of the way of the drill rig today. Reminded crews to stay out of ESAs.	
02/15	5/2011 Y	-					Area in compliance	Jacumba
Mitigation Mea	asure in Co	ompliance? Y					Remarks: PAR tower assembly and steel delivery at JVR yard. Marina straw wattle installation on west side of yard.	Valley Ranch Yard

From: 02/13/2011

Page 11 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL (COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1							
B-1c							
02/15/2011 Mitigation Measure in						Remarks: Drilling activities and materials offloading were monitored during work efforts for the 12 kV relocation component of the Sunrise Power link near EP 215 and McCain Valley Road. No issues noted.	12 kV relocation site 1
02/15/2011	Y					Work in complience.	EP 238-1
Mitigation Measure in	Compliance? Y					Remarks: Micropile spoils were covered with visqueen prior to anticipated rain event.	
02/16/2011	Y					All work postponed due to weather	JVR Yard
Mitigation Measure in Biological moni	Compliance? Y					Remarks: Work called for rain.	
02/16/2011	Y					All work in compliance.	between
Mitigation Measure in monitoring	Compliance? Y					Remarks: Monitored the preparations for modular house removal on Desert Rose Ranch Road (Loving property)	EP 227 & EP228
02/16/2011	Y					All work in compliance	road to
Mitigation Measure in	Compliance? Y					Remarks: All road work done safely and in compliance	EP-220
02/16/2011	Y					Project in compliance.	Jacumba
Mitigation Measure in Bio Monitor	Compliance? Y					Remarks: Project in compliance.	Valley Ranch (JVR)
02/16/2011	Y					No impacts outside of footprint	EP 215
Mitigation Measure in	Compliance? Y					Remarks: All steel work in compliance	
	Y					All activities met mitigation requirements.	EP 219
Mitigation Measure in BioMonitor	Compliance? Y						
02/16/2011	Y					All mitigation measures were met	EP 217,
Mitigation Measure in Compliance	Compliance? Y					Remarks: All work in compliance.	218, 215

From: 02/13/2011

Page 12 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL (COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1							
B-1c							
02/16/2011	Y					Oversight & management of construction	EP214-219
Mitigation Measure in oversight	Compliance? Y					activities:PAR 1) Conventional drilling EP219 2) Foundation setup EP215 & EP218. Woodward Brothers 1) site cleanup EP244. Hankins 1) access road entrance road work EP244. CRUX 1) Micropile drilling EP238, 231A, 229-1, 226-1, 224-1. UPC 1)12kv relocation EP215	EP244
						Remarks: All work in compliance	
02/16/2011 Mitigation Measure in						Remarks: Biological monitoring took place in the Thomas yard, where Par Electric crews worked to assemble steel structures.	Thomas yard
02/16/2011 Mitigation Measure in						Contractors remained in compliance of all biological mitigation measures.	Jacumba Valley
Compliant	- Companies 1					Remarks: Contractors remained in compliance of all biological mitigation measures during tower assembly.	Ranch Yard
02/16/2011	Y					All observed work was environmentally	EP220
Mitigation Measure in bio monitoring	Compliance? Y					compliant	
02/16/2011	Y					In compliance. No issues.	EP-209
Mitigation Measure in	Compliance? Y					Remarks: Road work in compliance	
02/16/2011	Y					Remarks: Contractors-Par, TTSI. PAR-	ROUGH
Mitigation Measure in compliance	Compliance? Y					materials/bolt organizing, water deliveries to Baker tank. PAR work area not severely affected by heavy rain event. TTSI- organized steel and materials. A heavy rain event and rutting (see photo) in the yard (runway) kept crew from continuing work at 1045. All work in compliance.	ACRES

From: 02/13/2011

Page 13 of 61

Weekly Monitoring Report No. 01468

ENVIRONM	MENTAL (COMPLIANCE						
Mitigation M D	Measure Pate	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1								
B-1c								
		Y					All work in the approved work zone and in	Rough Acres Yard
Mitigation N Biomonitorin		Compliance? Y					compliance. Remarks: All work monitored and in compliance.	Acres Faid
02	2/16/2011	Y					Work in compliance	EP-210
Mitigation N	Measure in	Compliance? Y					Remarks: All work in compliance	
Mitigation N		Y Compliance? Y					all work done in compliance. site left clean. Remarks: Provided biological monitoring for	ep-244
bio.monitorii	ng						Woodward crew. All work done is compliant.	
	2/16/2011						Project in compliance during digging for pole	EP215
Mitigation N Bio Monitor		Compliance? Y					supports. Remarks: Project in compliance.	
02	2/16/2011	Y					All work in compliance	218-1
Mitigation N	Measure in	Compliance? Y					Remarks: All work in compliance	
	2/17/2011 Measure in	Y Compliance? Y					Oversight & management of activities: PAR 1) Conventional drilling EP219 2) Foundation setup EP215 & EP218. Woodward Brothers 1) site cleanup EP244. Hankins 1) access road entrance road work EP244. CRUX 1) Micropile drilling EP238, 231A, 229-1, 226-1, 224-1. UPC 1)12kv relocation EP215.	226-,
							Remarks: All work in compliance	
	2/17/2011 Measure in	Y Compliance? Y					Observed drilling activities at EP-220. All work conducted within approved work limits and within environmental compliance.	EP-220
21111							Remarks: Observed drilling activities at EP-220. All work conducted within approved work limits and within environmental compliance.	

From: 02/13/2011

Page 14 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1							
B-1c							
02/17/2011	Y					Remarks: Biological monitoring took place in	Thomas
Mitigation Measure in	n Compliance? Y					the Thomas Yard, where Par Electric crews worked to assemble steel structures.	Yard
02/17/2011	Y					Remarks: Contractors-Par, TTSI, Hankins,	ROUGH
Mitigation Measure in compliance	n Compliance? Y					Maxim, JMB, United Rentals PAR- QA/QC towers, materials/bolt organizing, water deliveries to Baker tank. TTSI- accepted and organized steel and materials. Maxim- Accepted and placed a load of wire reels. Hankinsprepped the front entrance to construct curbs which will divert water in the proper direction. Loaded up two pieces of machinery to be delivered to JVR. United Rentals- Picked up one skytrak from the site. JMB- serviced toilets	
02/17/2011	Y					All activities met mitigation requirements.	EP 219
Mitigation Measure in BioMonitor	n Compliance? Y					Remarks: All activities were kept within the designated work area and all environmental mitigation measures were followed	
02/17/2011	Y					Drilling in compliance	EP219-EP
Mitigation Measure in Biomonitoring	Compliance? Y					Remarks: Drilling, foundation work done in compliance of all environmental rules	
02/17/2011 Mitigation Measure in						All observed work was environmentally compliant	EP220
biomonitoring	P					Remarks: Work was in compliance during drilling operations.	
02/17/2011	Y					Compliance met	Jacumba
Mitigation Measure in	n Compliance? Y					Remarks: PAR and UPC tower assembly Jacumba Valley Ranch Yard. PAR steel delivery. PAR raked up and collected existing wood chippings to prepare a welding area.	Valley Ranch Yard
02/17/2011	Y					All work was done in compliance.	ep-214
Mitigation Measure in bio. monitoring	Compliance? Y					Remarks: Rebar inspection. All work in compliance.	

From: 02/13/2011

Page 15 of 61

Weekly Monitoring Report No. 01468

ENVIRONMI	ENTAL (COMPLIANCE						
Mitigation M Dat		A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1								
B-1c								
	17/2011						All work in compliance.	EP 215
Mitigation Mo Bio Monitor	easure in	Compliance? Y					Remarks: Crew remained in compliance throughout the day.	
	/17/2011 feasure in	Y Compliance? Y					Contractors in compliance with general and biological mitigation measures including remaining within approved footprint outside of ESAs, no fluids leaks from equipment and vehicles. No sensitive wildlife species harmed.	ep243
							Remarks: Work in compliance with mitigation measures.	
02/	17/2011	Y					All work was in compliance.	EP224-1
Mitigation Mo Bio-monitor	easure in	Compliance? Y					Remarks: Monitored drilling activities.	
	17/2011						All work was within limits, no vehicle idling was observed.	Rough
Mitigation Me Mitigation Me		Compliance? Y					Remarks: All work was in compliance.	Acres entrance to EP-214
02/	/17/2011	Y					All drilling in compliance	EP 231-A
Mitigation Me Compliance M		Compliance? Y					Remarks: Crew in compliance	
02/	/17/2011	Y			1		All mitigation measures are met	Bartlett
Mitigation Mo	easure in	Compliance? Y					Remarks: Area is in compliance	Yard
02/	17/2011	Y					Drilling followed all compliance measures	EP 215
Mitigation Mo	easure in	Compliance? Y					Remarks: Work was in compliance	
	/17/2011						In compliance	226-1
Mitigation Me biomonitoring		Compliance? Y					Remarks: All was in compliance	

Page 16 of 61

Through: 02/19/2011

Weekly Monitoring Report No. 01468

ENVIRONMENTAL (COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1							
B-1c							
02/17/2011						Bio monitor was present throughout	Intersection
Mitigation Measure in Bio monitoring	Compliance? Y					construction activites and all work was in compliance. When a rabbit was found under a tarp covering broken asphalt, the biological monitor was called over and thoroughly checked the area to be sure the rabbit was gone and that there were no others in the rubble pile before the pile was moved.	Gorge Rd
						Remarks: Work was in compliance	
02/18/2011	Y					In Compliance.	STR EP
Mitigation Measure in	Compliance? Y					Remarks: The Crux crew finished installing bar and grout prep work on Leg A and moved the equipment over to Leg D and began drilling the piles. The crew was in compliance.	229-1
02/18/2011	Y					Remarks: Rough Acres Ranch (RAR)- Friday,	ROUGH
Mitigation Measure in compliance	Compliance? Y					Feb 18, 2011 Contractors-Par, TTSI, Maxim, Nordic Rentals, TTSI- organized steel and materials. Maxim- Accepted and placed a load of wire reels. NOrdic Rentals- Delivered water to Baker tanks	ACRES RANCH-(F
02/18/2011	Y					Remarks: Biological monitoring took place in	Thomas
Mitigation Measure in	Compliance? Y					the Thomas yard, where Par Electric crews worked to assemble steel structures	Yard
02/18/2011	Y					Work in compliance	EP219-220
Mitigation Measure in biomonitoring	Compliance? Y					Remarks: Drilling and foundation work in compliance.	
02/18/2011	Y					All activities met mitigation requirements.	EP 219
Mitigation Measure in BioMonitor	Compliance? Y						
02/18/2011	Y					In compliance	EP 231-A
Mitigation Measure in Compliance Met	Compliance? Y					Remarks: Crew in compliance	

From: 02/13/2011

Page 17 of 61

Weekly Monitoring Report No. 01468

ENVIRONM	IENTAL (COMPLIANCE						
Mitigation M Da	Aeasure ate	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1								
	//18/2011 Ieasure in	Y Compliance? Y					Monitored foundation crew at Structures EP-21 and EP-215. Crew was assembling forms for	EP215
Foundations							tower legs. All work conducted within approved work areas and within environmental compliance.	
							Remarks: Monitored foundation crew at Structures EP-211 and EP-215. Crew was assembling forms for tower legs. All work conducted within approved work areas and within environmental compliance.	
		Y Compliance? Y					Contractors in compliance with general and biological mitigation measures including remaining within approved footprint outside of ESAs, no fluids leaks from equipment and vehicles. No sensitive wildlife species harmed.	EP217
							Remarks: All work in compliance.	
	//18/2011 Ieasure in	Y Compliance? Y					Remarks: In compliance with all mitigation measures	JVR
	:/18/2011 Ieasure in	Y Compliance? Y					0700 Tailgate safety meeting with UPC. Digging crew set one anchor and drilled one hole. Work complete at 0900.	12kV nea EP-215
General							Remarks: All was compliant	
		Y Compliance? Y					Oversight & management of activities: PAR 1) Conventional drilling EP219 2) Foundation setup EP215 3) Micropile foundation setup EP231-1, 235-1, 221A 4) Air track drilling EP220 CRUX 1) Micropile drilling EP238-1, 231-A, 229-1, 226-1, 224-1 United Power Contractors 1) 12kv relocation EP215 Hankins 1) Rough Acres entrance 2) Access road entrance for EP244. Remarks: All work in compliance.	EP215, 219, 220, 221A, 224-1, 226-1, 231A, 231-1, 235-1, 238-1, EP244

Page 18 of 61

Through: 02/19/2011

Weekly Monitoring Report No. 01468

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1							
B-1c 02/18/2011 Mitigation Measure in	Y 1 Compliance? Y					Monitored drilling at EP220. Remarks: All work in compliance.	EP220
biomonitoring 02/18/2011 Mitigation Measure in bird nest found		UTM: 578421 x 3610806			Notified Link Lead	All actions today were in compliance. There was no work occuring within the 100' nest buffer, and the section of Carrizo Gorge Rd that crossed through a portion of the buffer was closed to all Sunrise traffic of vehicles over 2 tons. No impacts to the ESA.	EP243
						Remarks: There was confusion regarding the actual GPS coordinates of a cactus wren nest on Carrizo Gorge Road. The nest was field verified today, GPS coordinates taken, and 100' buffer flagged.	
02/18/2011 Mitigation Measure in Bio monitoring	Y 1 Compliance? Y					Bio monitor was present throughout construction activities and all work was in compliance. Remarks: All work in compliance.	Intersection of access road to EP244/245 and Carrize Gorge Rd
02/18/2011 Mitigation Measure in Bio-monitor						All work was in compliance Remarks: Monitored drilling activities	EP224-1
02/18/2011 Mitigation Measure in Bio Monitoring						Monitored micropile tower site preparation. Remarks: Construction work was in compliance with MMCRP	EP231-1, EP235-1, EP221A
02/18/2011 Mitigation Measure in						Remarks: All work in compliance during rebar installation.	226-1
02/18/2011 Mitigation Measure in bio.monitoring						All work done in compliance. Site left clean. No wildlife harmed.	EP238-1

From: 02/13/2011

Page 19 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1							
B-1c							
02/18/2011	Y					All work completed by crew was in compliance.	9C-18
Mitigation Measure in	n Compliance? Y					Remarks: All work completed by crew was in compliance	
02/19/2011	Y					In compliance	JVR Yard
Mitigation Measure in	n Compliance? Y					Remarks: All mitigation measures met; work stopped by Par crews due to unsafe conditions and potential for rutting yard.	
02/19/2011 Mitigation Measure in						All micropile drilling and micropile preparation was canceled due to the weather.	
oversight						Remarks: All work canceled due to weather.	
02/19/2011	Y					In compliance	EP215,
Mitigation Measure in Biomonitoring						Remarks: Tower visits for rebar inspection. In compliance.	243, 244
02/19/2011 Mitigation Measure in						Contractors in compliance with general and biological mitigation measures including remaining within approved footprint outside of ESAs, no fluids leaks from equipment and vehicles. No sensitive wildlife species harmed.	EP214
						Remarks: All work conducted with a biomonitor present.	
02/19/2011 Mitigation Measure in						Remarks: Biological monitoring took place in the Thomas yard, where Par Electric crews planned to assemble steel structures. The work day was called short due to persistent rains. Paved areas within the Thomas yard contained standing water.	Thomas Yard
02/19/2011	Y					Remarks: Due to rain, all crews remained at	JVR
Mitigation Measure in						JVR Yard. There was no biological monitoring at EP 238-1.	
02/19/2011	Y					All work postponed due to weather	JVR Yard
Mitigation Measure in Bio-monitor	n Compliance? Y					Remarks: All work postponed due to weather	

Page 20 of 61

Through: 02/19/2011

Weekly Monitoring Report No. 01468

ENVIRO	ONMENTAL (COM	PLIANCE						
Mitigati	on Measure Date	A (Y/N	B N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK:	1								
B-5a									
	02/16/2011		Sticky Geraea					Work was in compliance.	EP 217,
Mitigation Plants	on Measure in	Com	pliance? Y					Remarks: There were also some Jacumba Milk Vetch plants flagged in area.	218, 215
B-8a									
Mitigatio	02/17/2011 on Measure in		Verdin pliance? Y	634155 3638077			Notified Link Lead	Verdin observed building a nest over 100' outside the footprint; no buffer needed.	Thomas Yard
BIO-APN	M-1								
	02/13/2011	Y					Notified Link	A nest was discovered by the biologist. The	EP226-1
Mitigation biomonit	on Measure in oring	Com	pliance? Y				Lead	Link Lead was notified, workers informed, and a buffer set up.	
	02/14/2011	Y	San Diego Coast Horned Lizard	11 S 571996, 3612912			Notified Link Lead	Lizard relocated safely and uninjured Remarks: Calfiornia Fish and Game biodiversity database	EP224-1
Mitigatio CNDDB	on Measure in	Com	pliance? Y					database	
	02/15/2011	Y	San Diego Coast Horned Lizard	11 S 572025, 3612784			Notified Link Lead	Lizard safe and uninjured Remarks: California Fish and Game biodiversity	EP224-1
Mitigatio CNDDB	on Measure in	Com		3012764				database	
BIO-API	M-3								
	02/13/2011	Y						Dust adequately controlled	EP 225-1
Mitigatio Bio	on Measure in	Com	pliance? Y						EP230-1
Mitigation	02/14/2011 on Measure in rol		pliance? Y					All work in compliance Remarks: PAR/TTSI- Used water trucks to suppress dust on site.	ROUGH ACRES

From: 02/13/2011

Page 21 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1							
BIO-APM-3							
02/14/2011	Y					Dust adequately controlled.	EP 224-1
Mitigation Measure in Biomointor	n Compliance? Y					Remarks: Dust control in compliance.	
02/14/2011 Mitigation Measure in						Contractors in compliance with general and biological mitigation measures including avoiding ESAs, no fluids leaks from equipment or vehicles. No sensitive wildlife species harmed.	EP215
						Remarks: Contractor excavated holes for 12kv relocation near EP215.	
02/14/2011 Mitigation Measure in dust						All fugitive dust was prevented in the construction yard by the frequent application of water to the yard's surface and all vehicle operators obeying the speed limit	JVR CY
						Remarks: Dust control in the JVR yard.	
02/15/2011						Project was in compliance, regular watering was observed	EP 244
Mitigation Measure in BIO MONITOR	i Compuance? Y					Remarks: Project was in compliance	
02/15/2011 Mitigation Measure in						Contractors in compliance with general and biological mitigation measures including avoiding ESAs, no fluids leaks from equipment or vehicles. No sensitive wildlife species harmed.	EP220
						Remarks: Air drill at EP220	
02/15/2011						All work in compliance	ROUGH
Mitigation Measure in dust control	1 Compliance? Y					Remarks: PAR/TTSI- Used water trucks to suppress dust on site.	ACRES
02/15/2011	Y					Dust adequately controlled.	EP 224-1
Mitigation Measure in Biomonitor	1 Compliance? Y					Remarks: Dust control in compliance.	

Page 22 of 61

Through: 02/19/2011

Weekly Monitoring Report No. 01468

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1							
BIO-APM-3							
02/15/2011	Y					Drilling was in compliance.	EP244
Mitigation Measure in biomonitoring	Compliance? Y					Remarks: Regular watering was done on site via a water buffalo	l.
02/17/2011	Y					Water truck was active all day to control dust.	Intersection
Mitigation Measure in Water truck	n Compliance? Y					Remarks: In compliance	of access road to EP244/245 and Carizo Gorge Rd
02/17/2011	Y					Dust minimized by regular watering	Bartlett
Mitigation Measure in Dust Control	Compliance? Y					Remarks: Construction dust minimized	Yard
02/17/2011 Mitigation Measure in Bio-monitor						Minor dust from drilling is unavoidable, as excessive water use may be incompatable with drilling procedures	EP224-1
						Remarks: Monitored dust control during drilling.	
02/17/2011	Y					Micropiling work was in compliance	EP 238-1
Mitigation Measure in Dust control	Compliance? Y					Remarks: Work was in compliance.	
02/17/2011	Y					Drilling in compliance	EP 215
Mitigation Measure in	Compliance? Y					Remarks: All work in compliance.	
02/18/2011						Contractor in compliance with dust control	EP217
Mitigation Measure in	Compliance? Y					measures by use of water truck on roads/pads.	
02/18/2011 Mitigation Measure in Bio-monitor	Y n Compliance? Y					Minor dust from drilling is unavoidable, as excessive water use may be incompatible with drilling procedures. Remarks: Monitored dust control during drilling.	EP224-1

From: 02/13/2011

Page 23 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL (COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1							
BIO-APM-3							
02/18/2011						Water truck was active all day to control dust.	Intersection
Mitigation Measure in Water truck	Compliance? Y					Remarks: Water truck used to stay in compliance	of access road to EP244/245 and Carrizo Gorge Rd
C-1b 02/17/2011 Mitigation Measure in Cultural C-1e						ESA was monitored during construction activities (12kv relocation) by an archaeologist and Native American monitor Remarks: All work in compliance	EP215
02/14/2011	V					All work was done in compliance.	EP-244
Mitigation Measure in cultural						Remarks: All foundation digging work was monitored by a cultural and Native American monitor and deemed in compliance.	Er 211
02/14/2011 Mitigation Measure in In Compliance	_					Monitoring took place of excavation of a hole for the eastern-most pole for the McCain Valley 12 kv line relocation. All activities were in compliance.	Rough Acres
						Remarks: Monitoring took place during excavation of a hole for the eastern-most pole for the McCain Valley 12 kv line relocation. All activities were in compliance.	
02/14/2011 Mitigation Measure in Cultural	Y Compliance? Y					All work observed by Archaeological and Native American Monitors was in compliance Remarks: All work in compliance	McCain Valley rd/Wuetz Property
02/15/2011 Mitigation Measure in						All work observed by Archaeological and Native American Monitors were in compliance	EP219
Cultural						Remarks: Monitored the drilling activities at Pole# EP219 all work preformed and all workers were in compliance	

From: 02/13/2011

Page 24 of 61

Weekly Monitoring Report No. 01468

ENVIRO	NMENTAL (COMPLIANCE						
Mitigatio	on Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1	l							
C-1e								
	02/15/2011	Y					Monitored the excavation of soil by UPC	Rough
Mitigation In Compl		Compliance? Y					contractors of eastern-most pole location for the McCain Valley 12kv pole relocation near 500 kv structure location # 215. All was found to be in compliance.	Acres
							Remarks: Monitored the excavation of soil by UPC contractors of eastern-most pole location for the McCain Valley 12kv pole relocation near 500 kv structure location # 215. All was found to be in compliance.	
	02/15/2011	Y					All work in compliance.	ep-244
Mitigatio cultural	on Measure in	Compliance? Y					Remarks: All foundation digging was monitored by a cultural and Native American monitor and deemed to be in compliance.	
	02/16/2011	Y					All work observed by Archaeological and	McCain
Mitigatio	n Measure in	Compliance? Y					Native American Monitors was in compliance	Valley rd / Wuest
Cultural							Remarks: Work was in compliance.	Property
	02/16/2011	Y					All work in compliance.	ep-243/244
Mitigatio Cultural	n Measure in	Compliance? Y					Remarks: All work monitored by cultural monitor and deemed to be in compliance. No new cultural artifacts recovered.	
	02/17/2011	Y					Monitored foundation setup, drilling and	EP215,
Mitigatio	n Measure in	Compliance? Y					cleanup.	EP218, EP219
Cultural							Remarks: All work observed by Archaeological and Native American Monitor was in compliance	EF219
Miticati	02/17/2011	Y Compliance? V					All work was observed by an archaeological and Native American monitor	EP215
Cultural	on ivieasure in	Compliance? Y					Remarks: All work in compliance	
Cultural							r	

From: 02/13/2011

Weekly Monitoring Report No. 01468

ENVIRONMENTA	L COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1							
C-1e							
02/17/201						Onsite to monitor drilling at site, but the activity was canceled.	EP244
Mitigation Measure cultural	in Compliance? Y					Remarks: All work was monitored by a cultural monitor and deemed in compliance.	
02/18/201	1 Y					In compliance	EP244
Mitigation Measure Cultural	in Compliance? Y					Remarks: All anchor digging was observed by a cultural monitor and in compliance. No new cultural resources were found.	
02/18/201	1 Y					All work observed by Archaeological and	McCain
Mitigation Measure Cultural	in Compliance? Y					Native American Monitors was in compliance	Valley Ro Wuest Property
PAL-1c							
02/14/201	1 Y Paleontologica	al				Work in compliance during foundation drilling.	EP 244
Mitigation Measure Paleo Monitor	in Compliance? Y					Remarks: No fossils were found today.	
02/15/201	1 Y Paleontologica	al				No issues.	EP 244
Mitigation Measure Paleo Monitor	in Compliance? Y					Remarks: No fossils were found today during drilling operations.	
02/16/201	1 Y Paleontologica	al				No digging.	EP 243
Mitigation Measure Paleo Monitor	in Compliance? Y					Remarks: No digging occurred today.	
02/16/201	1 Y					Work was in full compliance.	Jacumba
Mitigation Measure Paleo Monitor	in Compliance? Y					Remarks: No fossils recovered	Yard
WQ-APM-13							
02/14/201	1 Y				Notified Link	Work was in compliance.	EP 238-1
Mitigation Measure	in Compliance? Y				Lead	Remarks: There was a small hydraulic leak from a fitting on the drill rig. Work stopped as the fitting was repaired. The fluid was contained, cleaned up, and bagged for site removal.	

From: 02/13/2011

Page 26 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1							
WQ-APM-13							
02/15/2011	Y	Work was				Remarks: There was a small hydraulic leak from	EP 238-1
Mitigation Measure in	n Compliance? Y	in compliance.				a fitting on the drill rig. Work stopped as the fitting was repaired. The fluid was contained, cleaned up, and bagged for site removal.	
02/16/2011	N					In compliance	EP 217,
Mitigation Measure in Oil leaks	n Compliance? Y					Remarks: It was discussed that only equipment with leaks needed to have plastic under them when left overnight and not every piece of equipment even when there is no leak.	218, 215
LINK: 2							
B-1c							
02/14/2011	Y					Crew remained in compliance throughout the	Kreutz
Mitigation Measure in	n Compliance? Y					day. Remarks: Species observed in the yard included two ferral dogs and a long nosed leopard lizard (Gambelia wislizenii), which was moved to safe habitat when discovered. Multiple scrub jays (Aphelocoma californica), one red shouldered hawk (Buteo lineatus) were observed in proximity to the yard, and killdeer (Charadrius vociferus) were heard.	Kamp Constructi Yard
02/14/2011	Y			1		All mitigation measures were met	Kreutzkan
Mitigation Measure in MMs met	1 Compliance? Y					Remarks: Area is in compliance during wash station building.	Yard
02/14/2011 Mitigation Measure in monitoring						Provided bio monitoring for grading crew along ARD and during construction of water bars. All work done in compliance. Site was left clean Remarks: Provided biological monitoring for grading crew along access road (ARD) and	
Mitigation Measure in						ARD and during construction of water bars. All work done in compliance. Site was left clean	

From: 02/13/2011

Page 27 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 2							
B-1c 02/14/2011 Mitigation Measure i General						Tailgate 0700 with Par and Colwell. The rest of the day was spent watching and monitoring trucks coming and going with rock and gravel to fill road. Colwell graded road, built water bars, and finished wash station. At 1030 a gopher snake was discovered and moved to a safe location away from ROW. Wash station last to be finished at 1600. Remarks: All observed activities were in compliance with project requirements.	Yard
02/14/2011 Mitigation Measure i						The area is in compliance with all APMs and Mitigation Measures are met.	EP 83
02/15/2011 Mitigation Measure i Bio monitoring						Bio monitor was present throughout construction activites and all work was in compliance.	Bartlett Yard
02/15/2011 Mitigation Measure i bio.monitoring						All work was done in compliance. Site was left clean. No wildlife appeared harmed. Remarks: Provided biological monitoring for grading, placing rock, constructing energy dissapators and construction pad for water tanks.	EP-26
02/15/2011 Mitigation Measure i						Area in compliance.	EP 83
02/15/2011 Mitigation Measure i MMs met				1		All mitigation measures were met Remarks: Area is in compliance	Kreutzkam Yard

From: 02/13/2011

Page 28 of 61

Weekly Monitoring Report No. 01468

ENVIRO	NMENTAL (COMP	PLIANCE						
Mitigatio	on Measure Date	A (Y/N	B () Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 2	2								
B-1c									
Mitigatio General/F	02/15/2011 n Measure in encing	Y Comp	pliance? Y					Met with PAR at Kreutzkamp Construction Yard at 0700. Entered gate, had safety meeting and waited for TTSI to arrive. 0740 TTSI arrived to do fence for yard. Very little activity. No problems in placement of posts for fence, all	Kreutzkamp Yard
								was compliant. Left yard and ROW with crew at 1700.	
								Remarks: All was compliant	
Mitigatio Bio monit	02/16/2011 n Measure in	Y Comp	oliance? Y					Bio monitor was present throughout construction activites and all work was in compliance.	Bartlett Yard
Bio mom	02/16/2011	Y	White-throated Woodrat				Flagging installed	The contractors allowed time to survey for woodrat residences before moving onto the	EP85
Mitigatio	n Measure in	Comp	oliance? Y					work site	
Mitigatio	02/16/2011 n Measure in	Y Comp	pliance? Y					All sites visited were in compliance with the APMs and MMs and there were no issues requiring attention.	ALL: EP 24-1, 84, 85, 114, and 115.
Mitigatio	02/16/2011 n Measure in	Y Comp	oliance? Y					Remarks: Muddy roads prevented work today.	SWAT construction yard
Mitigatio	02/16/2011 n Measure in		oliance? Y					Remarks: All mitigation measures met.	EP84
Mitigatio	02/16/2011 n Measure in	Y Comp	Coast Live Oak				Flagging installed	Contractors did an excellent job of avoiding oak trees	EP85
Mitigatio	02/17/2011 n Measure in	Y Comp	oliance? Y					Activity was in compliance	EP85-2

From: 02/13/2011

Page 29 of 61

Weekly Monitoring Report No. 01468

ENVIRO	NMENTAL (COMPLIANCE						
Mitigatio	on Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 2	2							
B-1c								
	02/17/2011	Y					Remarks: Observed ativities were in compliance	EP 83
Mitigatio	on Measure in	Compliance? Y					with project mitigation measures.	
	02/18/2011	Y					Remarks: Monitored Crux with URS at EP84.	EP84
Mitigatio	on Measure in	Compliance? Y					Crux conducted a soil test drill at a depth of about 50 feet. URS collected core samples.	
	02/18/2011	Y					Remarks: Crew remained in compliance during	SWAT
Mitigation Bio Moni		Compliance? Y					fence installation.	construction yard
	02/18/2011	Y					Remarks: All mitigation measures met.	EP84
Mitigatio	on Measure in	Compliance? Y						
	02/19/2011	Y					Remarks: No work activity occurred at the	Bartlett/Ha
Mitigation Bio Moni		Compliance? Y					Bartlett Yard today due to inclement weather.	Const. Yard
B-2a								
	02/14/2011	Y					Work area was staked and flagged	EP 83
Mitigatio	on Measure in	Compliance? Y						
B-7a								
	02/17/2011	Y OTHER		Collision		Notified Link	A woodrat species possibly a dusky-footed	EP85-2
Mitigatio	on Measure in	Compliance? Y				Lead	woodrat was seen dead by a contruction crew member at 11:35a.m. Photo was sent to Link Lead.	

From: 02/13/2011

Page 30 of 61

Weekly Monitoring Report No. 01468

ENVIRO	NMENTAL (COMP	LIANCE						
Mitigatio	on Measure Date	A (Y/N	B) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 2	2								
B-7a									
	02/18/2011	N	Botta's Pocket Gopher		Natural Causes		Notified Link Lead	Remarks: During the course of setting fence posts, laborer found a small dead mammal. The	SWAT construction
Mitigatio Bio Moni	on Measure in tor	Comp	oliance? Y					animal was identified as the common Botta's pocket gopher (Thomomys bottae). Evidenced by missing right ear, skin, and fur on the right side on the neck, the pocket gopher appeared to have died from natural causes (predation) that were not construction related.	yard
BIO-APN	1-3								
	02/14/2011	Y						Dust minimized by regular watering	Kreutzkamp
Mitigation Dust Con	on Measure in trol	Comp	oliance? Y					Remarks: Construction dust was minimized	Yard
	02/14/2011	Y						Water truck on site to control dust	EP 83
Mitigatio	on Measure in	Comp	oliance? Y						
	02/15/2011	Y						Water truck was on-site to control dust; two	Bartlett
Mitigation Water tru	on Measure in ck	Comp	oliance? Y					watering events occurred.	Yard
	02/15/2011	Y						Water truck on site to control dust	EP 83
Mitigatio	on Measure in	Comp	oliance? Y						
	02/15/2011	Y						Dust minimized by regular watering	Kreutzkamŗ
Mitigatio Dust Con	on Measure in trol	Comp	oliance? Y					Remarks: Construction dust minimized	Yard
Mitigatio	02/16/2011 on Measure in		oliance? Y				Flagging installed	Contractor stayed on ROW, allowed bio survey of area before clearing brush, and drove their vehicles under 15 mph off of the pavement	EP85

From: 02/13/2011

Page 31 of 61

Weekly Monitoring Report No. 01468

ENVIRONM	MENTAL (COMPLIANCE						
Mitigation N Da	Measure ate	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 2								
C-1e								
		Y Compliance? Y					Remarks: Monitored the work activities associated with the clearing of vegetation at structures EP-84 and EP-85. Both areas were cleared of vegetation; all activities were in compliance.	EP85-2
		Y Compliance? Y					Remarks: Monitored the work activities associated with the grading of the access roads associated with EP85-2. New access road was graded and existing road was improved. All activities were in compliance.	EP85-2
		Y Compliance? Y					Remarks: Archaeological monitoring took place for activities associated with structure EP 84. The existing access road was re-graded and slightly widened along the eastern edge. Monitoring of the core sampling team at EP 84 was monitored for impacts to the ground at the pad area. The Native American Monitor was present. No cultural material was encountered. All activities were found to be in compliance.	EP 84
	2/15/2011 Measure in	N Compliance? Y					Engines were shut off when not in use.	EP 83
	2/17/2011 Measure in	N Compliance? Y					Idling of machinery was kept to a minimum	EP 83
	2/14/2011	N Compliance? Y					No spills of hazardous materials occurred	EP 83

From: 02/13/2011

Page 32 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL (COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 2							
WQ-APM-13							
02/15/2011	N					There were no spills observed.	EP 83
Mitigation Measure in	Compliance? Y						
02/17/2011	N					No spills of hazardous materials occurred	EP 83
Mitigation Measure in	Compliance? Y						
LINK: 3							
B-1c							
02/14/2011	Y					A biologist was present during sub-drain	Suncrest
Mitigation Measure in Biological	Compliance? Y					installation on the Suncrest Substation pad	substation Pad
02/14/2011	Y					Biological monitoring took place at Suncrest	Suncrest
Mitigation Measure in Bio monitoring	Compliance? Y					substation during dirt disturbance activities and brush chipping in order to minimize impacts to the wildlife. No sensitive species were impacted as a result of today's activities. No nesting bird behavior was observed by the biological monitor nor any nests were found.	
02/15/2011 Mitigation Measure in Bio monitoring						Biological monitoring took place at Suncrest substation during dirt disturbance activities and brush chipping in order to minimize impacts to the wildlife. No sensitive species were impacted as a result of today's activities. The following birds were seen around/near the pad site: Common raven, Western scrub jay, oak titmouse, red tailed hawk, Bewick's wren, wrentit, and California thrasher. No nesting bird behavior was observed by the biological monitor nor any nests were found.	
02/15/2011 Mitigation Measure in Biological						Biologist present during construction of settling pond prepared for possible rain event	Suncrest substation Pad

From: 02/13/2011

Weekly Monitoring Report No. 01468

ENVIRO	NMENTAL (COMPLIANCE						
Mitigation	on Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK:	3							
B-1c								
	02/15/2011	Y					A biologist was present during sub-drain	Suncrest
Mitigation Biologica		Compliance? Y					installation on the Suncrest Substation pad	substation Pad
	02/15/2011	Y					All required monitors were on site during	Suncrest
Mitigatio	on Measure in	Compliance? Y					ground disturbing activities.	substation
	02/16/2011	Y					A biologist was present during dozer work at	Suncrest
Mitigation Biologica		Compliance? Y					blast site on the Suncrest Substation pad	Substation Pad
Mitigation Bio moni		Y Compliance? Y					Biological monitoring took place at Suncrest substation during dirt disturbance activities and brush chipping in order to minimize impacts to the wildlife. No sensitive species were impacted as a result of today's activities. The following birds were seen around/near the pad site: Common raven, Western scrub jay, oak titmouse, red tailed hawk, Bewick's wren, wrentit, bushtit, lesser goldfinch, white crowned sparrow, spotted towhee, California Towhee, and California thrasher. No nesting bird behavior was observed by the biological monitor nor any nests were found.	
Mitigatio	02/17/2011 on Measure in	Y Compliance? Y					Rough grading and erosion control installation activities remained within approved work boundaries.	Suncrest substation
Mitigatio Biologica		Y Compliance? Y					A biologist was present during dozer work on the Suncrest Substation pad	Suncrest substation Pad

From: 02/13/2011

Weekly Monitoring Report No. 01468

ENVIRON	NMENTAL O	COMPLIANCE						
Mitigation		A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 3								
B-1c								
(02/18/2011	Y					Biological monitoring took place at Suncrest	Suncrest
Mitigation Bio monito		Compliance? Y					substation during dirt disturbance activities and brush chipping in order to minimize impacts to the wildlife. No sensitive species were impacted as a result of today's activities. No nesting bird behavior was observed by the biological monitor nor any nests were found.	
	02/18/2011						A biologist was present during dozer work on the Suncrest Substation pad	Suncrest substation
Mitigation Biological	ı Measure in	Compliance? Y					the Suncrest Substation pad	Pad
(02/19/2011	Y					A biologist was present during SWPPP work on	
Mitigation Biological	ı Measure in	Compliance? Y					the Suncrest Substation pad and ROW	substation Pad
B-2a								
(02/14/2011	Y					Construction limits remained clearly staked and	
Mitigation	n Measure in	Compliance? Y					all work activities were kept within approved areas.	substation
B-3a								
(02/14/2011	Y					Vehicles observed along the ROW had been	Suncrest
Mitigation biological	n Measure in	Compliance? Y					washed before coming to the job site	substation access road
(02/15/2011	Y					Vehicles observed along the ROW had been	Suncrest
Mitigation biological	n Measure in	Compliance? Y					washed before coming to the job site	substation access road
	02/16/2011 n Measure in	Y Compliance? Y					Vehicles observed along the ROW had been washed before coming to the job site and were washed leaving job site.	Suncrest substation access road

Page 35 of 61

Through: 02/19/2011

Weekly Monitoring Report No. 01468

ENVIRONMEN	TAL (COMPLIANCE						
Mitigation Meas Date	sure	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 3								
B-3a								_
02/17/		Y					Vehicles observed along the ROW had been washed before coming to the job site and were	Suncrest substation
Mitigation Meas biological	sure in	Compliance? Y					washed leaving job site.	access
02/18/	/2011	Y					Vehicles observed along the ROW had been	Suncrest
Mitigation Meas biological	sure in	Compliance? Y					washed before coming to the job site and were washed leaving job site.	substation access road
02/19/	/2011	Y					Vehicles observed along the ROW had been	Suncrest
Mitigation Meas biological	sure in	Compliance? Y					washed before coming to the job site and were washed leaving job site.	substation access road
B-7a								
02/14/	/2011	Y					Vehicles were checked for wildlife by workers	Suncrest
Mitigation Meas Biological	sure in	Compliance? Y					before moving, no wildlife observed.	substation Pad
02/15/	/2011	Y					Vehicles were checked for wildlife by workers	Suncrest
Mitigation Meas Biological	sure in	Compliance? Y					before moving, no wildlife observed.	Substation Pad
02/16/	/2011	Y					Vehicles were checked for wildlife by workers	Suncrest
Mitigation Meas Biological	sure in	Compliance? Y					before moving, no wildlife observed.	Substation Pad
02/17/	/2011	Y					Vehicles were checked for wildlife by workers	Suncrest
Mitigation Meas Biological	sure in	Compliance? Y					before moving, no wildlife observed.	Substation Pad
02/18/	/2011	Y					Vehicles were checked for wildlife by workers	Suncrest
Mitigation Meas Biological	sure in	Compliance? Y					before moving, no wildlife observed.	substation Pad

From: 02/13/2011

Page 36 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 3							
B-8a							
02/14/2011	Y					Observed ravens, western scrub jay's, a turkey	Suncrest
Mitigation Measure in Biological	n Compliance? Y					vulture, and two red-tailed Hawks interacting. No nesting activity observed. Biologist observed no active nests during monitoring of construction.	substation Pad
02/15/2011	Y					Observed ravens, western scrub jay's, acorn	Suncrest
Mitigation Measure in Biological	n Compliance? Y					woodpecker, and two red-tailed Hawks interacting. No nesting activity observed. Biologist observed no active nests during monitoring of construction.	substation Pad
02/16/2011	Y					Observed ravens and a red-tailed hawk. No	Suncrest
Mitigation Measure in Biological	n Compliance? Y					nesting activity observed. Biologist observed no active nests during monitoring of construction.	substation Pad
02/17/2011	Y					Observed ravens, a turkey vulture, and 2	Suncrest
Mitigation Measure in Biological	n Compliance? Y					red-tailed hawks showing courtship activity. Biologist observed no active nests during monitoring of construction.	substation Pad
02/18/2011	Y					Observed ravens, acorn woodpecker, california	Suncrest
Mitigation Measure in Biological	n Compliance? Y					thrasher, fox sparrow, and a red-tailed hawk. Biologist observed no active nests during monitoring of construction.	substation Pad
02/19/2011	Y					Observed ravens, acorn woodpecker, california	Suncrest
Mitigation Measure in Biological	n Compliance? Y					towhee, house finch, caseine kingbird, and a red-tailed hawk. Biologist observed no active nests during monitoring of construction.	substation Pad
BIO-APM-3							
02/14/2011	Y					No vehicles were observed by biologist	Suncrest
Mitigation Measure in Biological	n Compliance? Y					exceeding 15mph.	substation Pad
02/15/2011	Y					No vehicles were observed by biologist	Suncrest
Mitigation Measure in Biological	n Compliance? Y					exceeding 15mph.	substation Pad

From: 02/13/2011

Page 37 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 3							
BIO-APM-3							
02/16/2011	Y					No vehicles were observed by biologist	Suncrest
Mitigation Measure in Biological	n Compliance? Y					exceeding 15mph.	substation Pad
02/17/2011	Y					No vehicles were observed by biologist	Suncrest
Mitigation Measure i Biological	n Compliance? Y					exceeding 15mph.	substation Pad
02/18/2011	Y					No vehicles were observed by biologist	Suncrest
Mitigation Measure i Biological	n Compliance? Y					exceeding 15mph.	substation Pad
02/19/2011	Y					No vehicles were observed by biologist	Suncrest
Mitigation Measure in Biological	n Compliance? Y					exceeding 15mph.	substation Pad
C-1e							
02/14/2011	Y					ESA cultural resource boundaries remained	Suncrest
Mitigation Measure i	n Compliance? Y					undisturbed during work activity	substation
cultural						Remarks: Suncrest Substation vegetation clearing and grading	
02/15/2011						ESA cultural resource boundaries remained undisturbed during work activity	Suncrest substation
Mitigation Measure is cultural	n Compliance? Y					Remarks: Suncrest Substation grading and Bell Bluff Truck Trail expansion.	substation
02/16/2011	Y					ESA cultural resource boundaries remained	Suncrest
Mitigation Measure i	n Compliance? Y					undisturbed during work activity	substation
cultural						Remarks: Suncrest Substation grading and Bell Bluff Truck Trail expansion	
02/17/2011						ESA cultural resource boundaries remained	Suncrest
Mitigation Measure in	n Compliance? Y					undisturbed during work activity	substation
cultural						Remarks: Suncrest Substation grading and Bell Bluff Truck Trail expansion.	

From: 02/13/2011

Page 38 of 61

Weekly Monitoring Report No. 01468

ENVIRO	NMENTAL (COMPLIANCE						
Mitigatio	n Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 3								
C-1e								
	02/18/2011						ESA cultural resource boundaries remained	Suncrest
Mitigatio cultural	n Measure in	Compliance? Y					undisturbed during work activity Remarks: Suncrest Substation grading and Bell Bluff Truck Trail expansion.	substation
	02/19/2011	Y					ESA cultural resource boundaries remained	Suncrest
_	n Measure in	Compliance? Y					undisturbed during work activity	substation
cultural							Remarks: Rain event canceled heavy equipment activity	
LINK: 4	ļ							
AQ-APM								
	02/14/2011	Y					Carpooled with the Biological monitor to and from the work site.	Vaults 15L
Mitigatio	n Measure in	Compliance? Y					from the work site.	18L, and 5L.
	02/14/2011	Y					The TRC biologist carpooled to the right-of-way	
Mitigatio	n Measure in	Compliance? Y					along with the ASM cultural monitor	Rd. to Star
Carpoolin	g						Remarks: Compliance met	Valley Rd.
	02/15/2011	Y					People from our company carpooled to the site	Alpine
Mitigatio Cultural	n Measure in	Compliance? Y					location.	Blvd, vault 18
	02/17/2011	Y					Carpooled with the Biological monitor to and	Vaults 18L
Mitigatio	n Measure in	Compliance? Y					from the work site.	
	02/18/2011	Y					Carpooled with the Biological monitor to and	Vault 8L
Mitigatio	n Measure in	Compliance? Y					from the work site.	
	02/18/2011						Carpooled to the site location with the biological	
Mitigatio Cultural	n Measure in	Compliance? Y					monitor from TRC.	Blvd, vault 9

From: 02/13/2011

Page 39 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 4							
B-1c							
02/14/2011	Y					Remarks: Installation of BMPs at the Bauer	Bauer
Mitigation Measure in	n Compliance? Y					Bridge has been completed. Staked hay bales and geotextile fabrics were installed along with sections of chain link fence to prevent any sedimentation or soil from entering the waterbody during construction activities related to the bridge replacement. All required monitors were onsite.	Bridge
02/14/2011	Y					The crews remained in compliance with the	E. Victoria
Mitigation Measure in Monitoring	n Compliance? Y					project's mitigation measures while potholing, pouring concrete, excavating, jackhammering, and drilling between E. Victoria Rd and Star Valley Rd	Rd. to Star Valley Rd.
						Remarks: Compliance met	
02/14/2011	Y					Remarks: Crews were in compliance with all	Alpine
Mitigation Measure in Bio monitor	n Compliance? Y					mitigation measures during potholing, excavating, etc. today. No impacts occurred outside the ROW.	Blvd
02/15/2011	Y					All required monitors were onsite during	Alpine
Mitigation Measure in Monitors	n Compliance? Y					construction activities.	Blvd.
02/15/2011	Y					Monitored Pinnick crews while working on	Bauer
Mitigation Measure in Bio Monitoring	n Compliance? Y					crane pad on north side of existing Bauer bridge. Proper BMP's in place at end of day for tomorrows projected rain event	Bridge
02/15/2011	Y					Remarks: Work was completed on setting Vault	Bauer
Mitigation Measure in	n Compliance? Y					#5. The excavation of the "In and Outs" at Vault 7, 15 and trenching at Vault 18 and at Willows Road was ongoing. Excavation of the bore pit for the I-8 crossing continued. Excavations for the footings at the Bauer Bridge were initiated. All required Monitors were present.	Bridge, Alpine Ave.

From: 02/13/2011

Page 40 of 61

Weekly Monitoring Report No. 01468

ENVIRONM	MENTAL (COMPLIANCE						
Mitigation N Da	Measure Pate	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 4								
B-1c								
02	2/15/2011	Y					Remarks: Crews were in compliance with all	Alpine
Mitigation N Bio Monitor		Compliance? Y					mitigation measures during excavating and potholing activities today. No impacts occurred outside the ROW.	Blvd
02	2/15/2011	Y Gopher Snake		Unknown		Notified Link	A gopher snake was observed dead off to the	Vault 15
Mitigation M Snake	Measure in	Compliance? Y				Lead	shoulder of the road. The snake appeared to have been run over by a vehicle.	
							Remarks: The death of the snake was not observed to have been project related but was within the work limits.	
02	2/15/2011	Y					The crews remained in compliance with the	Vaults
Mitigation M Monitoring	Measure in	Compliance? Y					project's mitigation measures while excavating, drilling, backfilling, and pouring concrete between vaults 14 - 19	14-19
							Remarks: Compliance met	
02	2/16/2011	Y					All required monitors were onsite during	Link 4
Mitigation M monitors	Measure in	Compliance? Y					construction	
02	2/16/2011	Y					The crew remained in compliance with the	I8 jacking
Mitigation Monitoring	Measure in	Compliance? Y					project's mitigation measures while excavating around the I8 jacking pit	pit
Monitoring							Remarks: Compliance met	
02	2/16/2011	Y					Remarks: Due to the light rain event, BMP	Bauer
Mitigation N	Measure in	Compliance? Y					maintenance and the bore at I-8 constituted the construction activities along Link 4 today.	Bridge, Alpine Ave.
02	2/17/2011	Y					All required monitors were onsite during	Link 4
Mitigation M monitors	Measure in	Compliance? Y					construction activities	

From: 02/13/2011

Page 41 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTA	L COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 4							
B-1c							
02/17/201	1 Y					Remarks: The installed BMPs at the Bauer	Bauer
Mitigation Measure	in Compliance? Y					Bridge functioned as designed during last night's rain event preventing sediment-laden stormwater from leaving the approved work area. Worked is continuing at the Jack and bore location for the I-8 crossing.	
02/17/201 Mitigation Measure Bio Monitoring						Monitored PAR crews while trenching. All excavations filled properly and topped with asphalt. All observed construction in compliance.	Bauer Bridge, Vault 9, 10, 11
02/17/201 Mitigation Measure Bio Monitor						Remarks: Crews were in compliance with all mitigation measures during excavating, potholing, and other activities today. No impacts occurred outside the ROW	Alpine Blvd
02/17/201 Mitigation Measure Monitoring						The crews remained in compliance with the project's mitigation measures while excavating, pumping out water, pouring concrete, and drilling between vaults 14 - 19	Vaults 14 19
						Remarks: Compliance met	
02/18/201 Mitigation Measure monitors						All required monitors were onsite during construction activities	Link 4
02/18/201 Mitigation Measure						Remarks: The work was undertaken today at the bore pit for the I-8 crossing, Vault #8 (completed) and trenching near Vault #8	Bauer Bridge, I-8 Bore
02/18/201 Mitigation Measure Monitoring						The crews remained in compliance with the project's mitigation measures while excavating, pumping out water, pouring concrete, and drilling between vaults 14 - 19 Remarks: Compliance met	Vaults 14 - 19

From: 02/13/2011

Page 42 of 61

Weekly Monitoring Report No. 01468

ENVIRON	NMENTAL (COMPLIANCE						
0	n Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 4								
B-1c								
	02/18/2011	Y					Monitored PAR crews while trenching. All	Vault 9,
Mitigation Bio Monito		Compliance? Y					excavations filled properly and topped with plates and/or asphalt. All observed construction in compliance.	10, 11
	02/18/2011	Y					Remarks: Crews were in compliance with all	Alpine
Mitigation Bio Monito		Compliance? Y					mitigation measures during rock-breaking, predrilling, etc. today. No impacts occurred outside the ROW.	Blvd
	02/19/2011 n Measure in	Y Compliance? Y					Remarks: Due to the rain event today no construction activities occurred on Link 4. BMP's functioned as intended during the subsequent storm water event.	Bauer Bridge
B-7a								
	02/14/2011	Y					Excavations were properly covered with steel	E. Victoria
Mitigation Excavation		Compliance? Y					plates and/or asphalt at the end of the work day Remarks: Compliance met	Rd. to Star Valley Rd.
	02/14/2011	Y					Excavations were properly covered with steel	E. Victoria
Mitigation Excavation		Compliance? Y					plates and/or asphalt at the end of the work day Remarks: Compliance met	Rd. to Star Valley Rd.
	02/14/2011	Y					Excavations were checked at least three time a	E. Victoria
Mitigation	n Measure in	Compliance? Y					day while monitoring	Rd. to Star
Excavation	1						Remarks: Compliance met	Valley Rd.
	02/15/2011	Y					The crews properly covered all excavations at	Vaults
_		Compliance? Y					the end of the work day.	14-19
Monitoring	g						Remarks: Compliance met	
	02/15/2011						Excavations were checked at least three times a	Vault 18
Mitigation Excavation		Compliance? Y					day while monitoring vaults 14-19 Remarks: Compliance met	and Alpine Blvd/W.W Rd

From: 02/13/2011

Page 43 of 61

Weekly Monitoring Report No. 01468

ENVIRO	NMENTAL (COMPLIANCE						
Mitigatio	on Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 4	1							
B-7a	02/16/2011	Y					The jacking pit was observed at least three times	
Mitigatio Excavatio		Compliance? Y					throughout the work day Remarks: Compliance met	pit
Mitigatio Excavatio		Y Compliance? Y					The crew placed perimeter fencing around the jacking pit at the end of the work day Remarks: Compliance met	I8 jacking pit
Mitigatio Undergro		Y Compliance? Y					Excavations were checked at least three times a day while monitoring vaults 14-19 Remarks: Compliance met	Vault 15, 18, and Alpine Blvd/W.W Rd.
Mitigatio Excavation		Y Compliance? Y					Excavations were properly covered with steel plates and/or asphalt at the end of the work day Remarks: Compliance met	Vault 15, 18, and Alpine Blvd/W.W Rd.
Mitigatio Undergro		Y Compliance? Y					Excavations were checked at least three times a day while monitoring vaults 14-19 Remarks: Compliance met	Vault 15, 18, and Alpine Blvd/W.W Rd.
Mitigatio Excavatio		Y Compliance? Y					Excavations were properly covered with steel plates and/or asphalt at the end of the work day Remarks: Compliance met	Vault 15, 18, and Alpine Blvd/W.W Rd.

From: 02/13/2011

Page 44 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL							
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 4							
B-8a							
02/14/201	1 Y	32.4958 N,			Notified Link	One inactive nest and four potentially active	Viejas
Mitigation Measure Nesting	in Compliance? Y	116.4329 W, 32.4958 N, 116.4331 W, 32.4957 N, 116.4333 W, 32.4959 N, 116.4324 W, 32.4959 N, 116.4325			Lead	nests were observed; Two were being actively used by European starlings and whitewash was observed around the other two. A pair of red-tailed hawks were observed mating on an arroyo willow tree just south of Viejas creek bridge Remarks: European starlings are non-native	Creek and Viejas Creek Bridge
02/15/201 Mitigation Measure		32°49'57'N, 116°43'27'W			Notified Link Lead	A large raptor-sized nest was spotted on a coast live oak tree. It was not observed to be inhabited	
Nesting	in compnance. 1					Remarks: A pair of red-tailed hawks were observed copulating on a tree nearby about 200 feet north of the nest	
02/17/201	1 Y	32°49'59'N,				A potential medium sized nest was located about	Vault 18
Mitigation Measure Nesting	in Compliance? Y	116°43'28'W				35 feet south of the right-of-way Remarks: There were no birds observed in or around the nest	
02/18/201 Mitigation Measure		32°49'59'N, 116°43'25'W				A potential medium sized nest was located about 35 feet south of the right-of-way	Vault 18
Nesting						Remarks: There were no birds observed in or around the nest	
BIO-APM-26							
02/14/201	1 Y					Monitored Pinnick crews while vegetation was	Bauer
Mitigation Measure Bio Monitoring	in Compliance? Y					removed and grading began on north side of existing Bauer bridge. In order to avoid wildlife being caught in excatation overnight, dirt walls were sloped.	Bridge

From: 02/13/2011

Page 45 of 61

Weekly Monitoring Report No. 01468

ENVIRON	MENTAL (COMPLIANCE						
Mitigation I	Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 4								
BIO-APM-	4							
	02/16/2011						The Link Leads carpooled together	Link 4
Mitigation carpool	Measure in	Compliance? Y						
(02/17/2011	Y					The Link Leads carpooled together	Link 4
Mitigation carpool	Measure in	Compliance? Y						
(02/18/2011	Y					The Link Leads carpooled together	Link 4
Mitigation carpool	Measure in	Compliance? Y						
C-1b								
(02/14/2011	Y					ESA was monitored during construction	Link 4
Mitigation Cultural	Measure in	Compliance? Y					activities by an archaeologist and Native American monitor	undergroun
C-1e								
(02/14/2011	Y					The crew was compliant with allowing the	Vaults 15L,
Mitigation	Measure in	Compliance? Y					archaeologist and Native American monitor to observe the excavation and sift through the soil. There were no artifacts found during the day at the excavations.	18L, and 5L.
(02/14/2011	Y					Remarks: Asphalt was removed near the bridge	Bauer
Mitigation Cultural	Measure in	Compliance? Y					at the Bauer property.	Property
(02/14/2011	Y					All work was observed by an archaeological and	
Mitigation Cultural	Measure in	Compliance? Y					Native American monitor	underground
(02/14/2011	Y					PAR conducted trenching and potholing along	Alpine
Mitigation Cultural	Measure in	Compliance? Y					Alpine Boulevard.	Boulevard

From: 02/13/2011

Page 46 of 61

Weekly Monitoring Report No. 01468

ENVIRO	NMENTAL (COMPLIANCE						
	n Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 4								
C-1e								
	02/15/2011	Y					Work was monitored by an archaeological and	Alpine
Mitigatio Cultural	n Measure in	Compliance? Y					Native American monitor and all work was in compliance.	Blvd, vault 18
	02/15/2011	Y					Pinnick excavated at the Bauer property near the	
Mitigatio Cultural	n Measure in	Compliance? Y					bridge. San Diego Erosion installed BMPs at the Bauer property. PAR excavated vault 3.	Bauer property.
	02/15/2011	Y					All work was observed by an archaeological and	Link 4
Mitigatio Cultural	n Measure in	Compliance? Y					Native American monitor	underground
	02/17/2011	Y					The crew was compliant with allowing the	Vaults 18L
Mitigatio	n Measure in	Compliance? Y					archaeologist and Native American monitor to observe the excavation and sift through the soil. There were no artifacts found during the day at the excavations.	
	02/17/2011	Y					PAR excavated vault 8.	Vault 8,
Mitigatio Cultural	n Measure in	Compliance? Y						Alpine Boulevard
	02/18/2011	Y					The crew was compliant with allowing the	Vault 8L
Mitigatio	n Measure in	Compliance? Y					archaeologist and Native American monitor to observe the excavation and sift through the soil. There were no artifacts found during the day at the excavations.	
	02/18/2011	Y					Work was monitored by an archaeological and	Alpine
Mitigatio Cultural	n Measure in	Compliance? Y					Native American monitor and all work was in compliance.	Blvd, vault 9
	02/18/2011	Y					All work was observed by an archaeological and	Link 4
Mitigatio Cultural	n Measure in	Compliance? Y					Native American monitor	underground

From: 02/13/2011

Page 47 of 61

Weekly Monitoring Report No. 01468

ENVIRO	NMENTAL (COMPLIANCE						
Mitigatio	on Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 5	5							
AQ-1a								
	02/15/2011	Y					Remarks: Water truck in use for dust control.	Helix Yard
Mitigatio	on Measure in	Compliance? Y						
	02/18/2011	V					Draw on DMDs arrows and d and limite of	Wilson
Mitigatio		Y Compliance? Y					Proper BMPs were used and limits of construction marked.	Yard
Miligatio	on Measure in	Comphance: 1						
B-12a								
D-12u	02/17/2011	Y					A few small branches were trimmed off of fairly	CP 106-1
Mitigatio		Compliance? Y					young trees absent of any nests, including larger	
9		•					raptor nests.	
B-1c								
	02/14/2011	Y					Remarks: All equipment at site parked on	Helix Yard
Mitigatio	on Measure in	Compliance? Y					visqueen.	
	02/15/2011						Remarks: At the access road near intersection of	
Mitigatio	on Measure in	Compliance? Y					Old HWY 80 and McCain Valley, work site was adjacent to private pasture lands.	of McCain Valley and
							augustin to private passars initias.	Old HWY
								80
	02/15/2011	Y					Remarks: All equipment parked on visqueen.	Helix Yard
Mitigatio	on Measure in	Compliance? Y						
	02/17/2011	V					Remarks: A PAR crew conducted potholing at	Hartung
Mitigatio		Compliance? Y					the access road to Hartung Construction Yard to	
General	m wicasuic III	Comphance: 1					study the depth and characteristics of an existing	
							pipe under the road.	

From: 02/13/2011

Weekly Monitoring Report No. 01468

ENVIRON	NMENTAL (COMPLIANCE						
Mitigation	n Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 5								
B-1c								
	02/17/2011 • Measure in	Y Compliance? Y					Tree-trimming trucks stayed on access roads. Oak branches were laid down flat on the ground 10 ft. from the access road. California Buckwheat was hauled away.	CP 106-1
							Remarks: All trimmed trees were checked for resident wildlife including bird's nests prior to being trimmed.	
	02/17/2011 Measure in	Y Compliance? Y					All work in the approved work zone and in compliance.	Helix Yard
Biomonitor		- Companie - 1					Remarks: All work monitored and in compliance.	
	02/17/2011						Remarks: Equipment and Trucks carrying rebar	CP17
Mitigation Bio Monito		Compliance? Y					were in compliance with the MMCRP	
	02/17/2011						Biological monitor present on site during work	CP51
Mitigation compliance		Compliance? Y					activities Remarks: Hamlet Property house	
	02/17/2011	Y					Remarks: BMP installation of straw wattles and	CP31-2
Mitigation bio-monito		Compliance? Y					wood chips along access road to CP31-2 in presence of bio-monitor. All measures in compliance.	access road
	02/18/2011	Y					Remarks: All mitigation measures followed and	CP-108
Mitigation	Measure in	Compliance? Y					in compliance	
	02/18/2011	Y					All crews were in compliance with the APMs	Wilson
Mitigation	ı Measure in	Compliance? Y					and Mitigation Measures were met Remarks: Was on site at Wilson Yard to monitor an equipment drop-off. Road conditions did not allow for the semi trucks to get into Wilson Yard so they were forced to offload their equipment in another location.	Yard r

Page 49 of 61

Through: 02/19/2011

From: 02/13/2011

Weekly Monitoring Report No. 01468

ENVIRONMENTAL	COMPLI	ANCE						
Mitigation Measure Date	A E		C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 5								
B-1c								
02/18/2011							All mitigation measures are met	Sycamore
Mitigation Measure in MMs met	n Complia	nce? Y					Remarks: Area is in compliance	Sub
02/18/2011	Y						Work in compliance.	69 kVA
Mitigation Measure in	n Complia	nce? Y					Remarks: Straw Wattles were installed at toe of slopes prior to anticipated rain event.	
02/18/2011 Mitigation Measure in Bio monitoring		OTHER ance? Y	32.86907, -116.89175; 32.86966, -116.88990		NA		No new disturbances as a result of gate placement	Helix Yard
02/18/2011 Mitigation Measure in		ince? V					Biological monitor present on site during work activities	CP51
compliance	п сотрпа	inec. 1					Remarks: Hamlet Property house	
B-3a								
02/17/2011							Remarks: Vehicles came to the site clean and	CP 106-1
Mitigation Measure in	n Complia	ince? Y					were washed after work was finished.	
B-8a			-1					
02/17/2011		led-tailed Iawk	515337 E/ 3638993 N				Parent red-tailed hawk on nest	Hartung CY
Mitigation Measure in Bird Nests			3030773 1				Remarks: Construction activity was outside 500-ft buffer zone of active red-tailed hawk nest #117.	
BIO-APM-3								
02/14/2011 Mitigation Measure i		nnce? Y					Remarks: Backhoe moved from CP-17 to paved area at the end of Stonebridge Parkway. No dust issues noted.	
02/18/2011 Mitigation Measure is		nce? Y					Remarks: Fugitive dust was minimized during construction activities by watering.	69 kVA

From: 02/13/2011

Page 50 of 61

Weekly Monitoring Report No. 01468

	<u> </u>					8	
ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 5							
BIO-APM-3							
02/18/2011 Mitigation Measure in Bio monitoring	Y n Compliance? Y	32.86907, -116.89175; 32.86966, -116.88990				Contractor vehicle stayed on approved roads and observed 15mph off pavement speed limit at all times	Helix Ya
BIO-APM-4							
02/14/2011 Mitigation Measure in						Remarks: Backhoe moved from CP-17 to paved area at the end of Stonebridge Parkway. Vehicles stayed on approved roads.	CP-17
02/17/2011	Y					Remarks: No vehicles were parked under the	Hartung
Mitigation Measure in Vehicles on ROW	1 Compliance? Y					driplines of any oak trees.	CY
PAL-1c							
02/14/2011 Mitigation Measure in Paleo Monitor	Y n Compliance? Y					Remarks: No fossils recovered.	Par's Vigilante Yard
02/15/2011 Mitigation Measure in Paleo Monitor						Remarks: No fossils recovered.	Par's Vigilante Yard
LINK: NA							
B-1c 02/14/2011 Mitigation Measure in						In compliance - Biological monitoring took place during work on forms and during demoltion of the concrete foundation.	Encina Substation
Monitoring						Remarks: Biological monitor was on-site during work on forms and demolition.	
02/14/2011 Mitigation Measure in Compliance met	Y 1 Compliance? Y			1		Compliance met bio-monitor on-site. Remarks: SDG&E crews in compliance, bio-monitor on-site.	San Luis Rey Substation

From: 02/13/2011

Page 51 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL (COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: NA							
B-1c							
02/14/2011	Y					Remarks: Roel crew began excavating. No	IV
Mitigation Measure in	Compliance? Y					issues noted	Substation
Bio monitoring							
02/14/2011	Y					Remarks: United Power Company (UPC) crew	Scripps
Mitigation Measure in bio-monitoring	n Compliance? Y					spread 12kV disstribution lines at two existing Reconductor line poles (Z678467 and Z771473). Fresh gravel was imported and spread with a small Cat at the entry gate by underground tie-in pole at Ironwood Drive. Bio-monitor present with crews.	Reconductor line
02/14/2011	Y					Remarks: Site was in compliance during	San Luis
Mitigation Measure in Mitigation met	Compliance? Y					SDG&E 69kV wire testing	Rey
02/14/2011	Y					Remarks: Site was in compliance during control	Encina
Mitigation Measure in Mitigation met	Compliance? Y					house construction and pad demo	
02/14/2011	Y					Remarks: Site was in compliance during	IV Sub
Mitigation Measure in Bio monitor	Compliance? Y					trenching and construction activities	
02/15/2011	Y			1		Bio monitor on-site.	San Luis
Mitigation Measure in Compliance met	Compliance? Y					Remarks: SDG&E crews continued electrical upgrades in the substation. Bio monitor present.	Rey substation
02/15/2011	Y					Remarks: Reconductor crews were in	69kV
Mitigation Measure in	Compliance? Y					compliance.	Reconducto (pg 153, 155)
02/15/2011 Mitigation Measure in Monitoring	Y n Compliance? Y					In compliance - Biological monitoring took place during work on forms and during demolition of the concrete foundation.	Encina Substation
omoring						Remarks: Biological monitor was on-site during work on forms and demolition.	

From: 02/13/2011

Page 52 of 61

Weekly Monitoring Report No. 01468

ENVIRONM	IENTAL (COMPLIANCE						
Mitigation M		A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: NA								
B-1c								
02	2/15/2011	Y					Remarks: Roel crew began excavating. No	IV
Mitigation M Bio monitorin		Compliance? Y					issues noted	substation
02	2/16/2011	Y					In compliance - Biological monitoring took	Encina
Mitigation M	1easure in	Compliance? Y					place, including inspection of trenches.	Substation
Monitoring							Remarks: Biological monitor was on-site.	
02	2/16/2011	Y			1		SDG&E crews working in the substation on	San Luis
Mitigation M Compliance n		Compliance? Y					electrical upgrades. Roel crews installing BMPs. Bio monitor present and on-site for all construction related activities.	Rey substation
							Remarks: SDG&E crews working in the substation on electrical upgrades. Roel crews installing BMPs. Bio monitor present and on-site for all construction related activities.	
02	2/16/2011	Y					Remarks: Roel crew began excavating. No	IV
Mitigation M Bio monitorin		Compliance? Y					issues noted	substation
02	2/16/2011	Y					Remarks: Site was in compliance during	San Luis
Mitigation M Mitigation me		Compliance? Y					SDG&E 69kV confirguration	Rey
02	2/16/2011	Y					Remarks: Site was in compliance	Encina
Mitigation M Mitigation me		Compliance? Y						
02	2/16/2011	Y					Remarks: Site was in compliance during	IV Sub
Mitigation M Bio monitor	Ieasure in	Compliance? Y					trenching and construction activities	
02	2/17/2011	Y					Remarks: All mitigation measures were met by	379524,
Mitigation M	1easure in	Compliance? Y					BMP crew.	379523,87

From: 02/13/2011

Page 53 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: NA							
B-1c							
02/17/2011 Mitigation Measure in	Y n Compliance? Y					Remarks: All mitigation measures met.	69 KV reconducto line pole # 973032, 379524, and 379525.
02/17/2011	Y			1		Bio-monitor on-site compliance met.	San Luis
Mitigation Measure in Compliance met	Compliance? Y					Remarks: DCX and ROEL continued excavating a trench. SDG&E tested new electrical infrastructure.	Rey Substation
02/17/2011 Mitigation Measure in Bio monitoring						Remarks: Roel crew began drilling foundation piers and continued excavations. No issues noted	IV substation
02/17/2011 Mitigation Measure in Monitoring						In compliance - Biological monitoring took place during building of forms, pouring of concrete, and demolition of concrete foundation Remarks: Biological monitor was on-site during	
						demolition, form building, and concrete pouring	
02/18/2011 Mitigation Measure in Bio monitoring	Y a Compliance? Y					Remarks: Roel crew began drilling foundation piers and continued excavations. No issues noted	IV substation
02/18/2011 Mitigation Measure in Monitoring						In compliance - Biological monitoring took place during break-down of forms, backfilling and compression of excavations, and demolition of concrete pad.	Encina Substation
						Remarks: Biological monitor was on-site during demolition, form break-down, and backfilling.	
02/18/2011	Y			1		Bio-monitor on-site compliance met.	San Luis
Mitigation Measure in Compliance met	Compliance? Y					Remarks: ROEL continued excavating a trench. SDG&E completed new electrical infrastructure.	Rey Substation

From: 02/13/2011

Page 54 of 61

Weekly Monitoring Report No. 01468

ENVIRO	NMENTAL (COMPLIANCE						
Mitigatio	n Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: N	NA							
B-1c								
	02/19/2011						In compliance - Biological monitoring took	Encina
Mitigatio Monitorin		Compliance? Y					place during placement of doorways, digging of pads, and demolition of concrete pad.	Substation
Wiomtorm	g						Remarks: Biological monitor was on-site during demolition, pad digging, and door hanging.	
B-2a								
	02/18/2011	Y					Remarks: Project working limits were clearly	69kV
Mitigatio	n Measure in	Compliance? Y					identified.	Reconducto (circuit TL636-639
B-7a								
	02/14/2011						Remarks: Vehicle undersides were checked	IV
Mitigatio under veh		Compliance? Y					before moving. No animals found.	Substation
	02/14/2011	Y					Remarks: Crews installed dirt or 2x4 ramps in	IV
Mitigatio trench ram		Compliance? Y					all open excavations. No issues noted.	substation
	02/14/2011	Y					Remarks: Inspected exposed trenches three	IV
Mitigation trench insp		Compliance? Y					times a day. No animals found.	substation
	02/15/2011	Y					Remarks: Vehicle undersides were checked	IV
Mitigatio under veh		Compliance? Y					before moving. No animals found.	substation
	02/15/2011	Y					Remarks: Crews installed dirt or 2x4 ramps in	IV
Mitigation trench ram		Compliance? Y					all open excavations. No issues noted.	substation
	02/15/2011	Y					Remarks: Inspected exposed trenches three	IV
Mitigation trench insp		Compliance? Y					times a day. No animals found.	substation

From: 02/13/2011

Page 55 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTA	L COMPLIANCE						
Mitigation Measure Date		C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: NA							
B-7a							
02/16/201	1 Y					Remarks: Vehicle undersides were checked	IV
Mitigation Measure under vehicle	in Compliance? Y					before moving. No animals found.	substation
02/16/201	1 Y					Remarks: Crews installed dirt or 2x4 ramps in	IV
Mitigation Measure trench ramp	in Compliance? Y					all open excavations. No issues noted.	substation
02/16/201	1 Y					Remarks: Inspected exposed trenches three	IV
Mitigation Measure trench inspect.	in Compliance? Y					times a day. No animals found.	substation
02/17/201	1 Y					Remarks: Vehicle undersides were checked	IV
Mitigation Measure under vehicle	in Compliance? Y					before moving. No animals found.	substation
02/17/201	1 Y					Remarks: Crews installed dirt or 2x4 ramps in	IV
Mitigation Measure trench ramp	in Compliance? Y					all open excavations. Crews installed plywood covers on drill holes and used straw wattle to cover additional openings. No issues noted.	substation
02/17/201	1 Y					Remarks: Inspected exposed trenches three	IV
Mitigation Measure trench inspect.	in Compliance? Y					times a day. No animals found.	substation
02/18/201	1 Y					Remarks: Vehicle undersides were checked	IV
Mitigation Measure under vehicle	in Compliance? Y					before moving. No animals found.	substation
02/18/201	1 Y					Remarks: Crews installed dirt or 2x4 ramps in	IV
Mitigation Measure trench ramp	in Compliance? Y					all open excavations. Crews installed plywood covers on drill holes and used straw wattle to cover additional openings. No issues noted.	substation
02/18/201	1 Y					Remarks: Inspected exposed trenches three	IV
Mitigation Measure trench inspect.	in Compliance? Y					times a day. No animals found.	substation

Page 56 of 61

Through: 02/19/2011

From: 02/13/2011

Weekly Monitoring Report No. 01468

ENVIRON	MENTAL (COMI	PLIANCE						
Mitigation	Measure Date	A (Y/N	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: NA	A								
B-7a									
(02/18/2011	Y						Remarks: Excavations securely covered when	SLR sub
Mitigation Biology	Measure in	Comp	pliance? Y					not in use to prevent wildlife entrapment and or injury.	
B-7b									
(02/18/2011	Y						Remarks: Only approved existing access roads	69kV
Mitigation	Measure in	Comp	pliance? Y					were used.	Reconduct (circuit TL636-639
B-71									
(02/18/2011	Y	Coastal California Gnatcatcher				Suspend Work	Remarks: Gerry Akin issued a stop work order for all vegetation activities after a report of the Coastal California gnatcatcher in the area.	69kV Reconduct (775592)
Mitigation Worked sto	Measure in opped	Comp	pliance? Y						
B-8a									
(02/14/2011	Y	Mourning Dove				Flagging installed	2 eggs	Scripps
Mitigation bird nest fo	Measure in	Comj	pliance? Y	0490965 3640354				Remarks: Mourning dove nest with two eggs, being incubated at time of discovery. Host plant is an exotic prickly pear (Opuntia sp.). Link Lead was notified and a buffer was installed.	Reconduct line
(02/14/2011	Y	Great Horned	33 12 44 N,			Suspend Work	One owl on nest	San Luis
			Owl	117 20 5 W				Remarks: Great Horned Owl nest monitored by	Rey 230kV
Mitigation Owl Nest	Measure in	Com	pliance? Y					John Kanlund	Area
(02/15/2011	Y	Anna's Hummingbird	490979 3639657				eggs Remarks: Previously identified hummingbird	Scripps Reconducte
_	Measure in	Comp	pliance? Y					nest was observed. Buffer was not disturbed.	(771472)
nest	00/1/2011	**		22.12.4435			C		О т.
	02/16/2011		Great Horned Owl	33 12 44 N, 117 20 5 W			Suspend Work	One owl on nest Remarks: Great Horned Owl nest monitored	San Luis Rey 230kV Area
Mitigation Owl Nest	Measure in	Com	puance? Y						Aica

From: 02/13/2011

Page 57 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: NA							
B-8a							
02/18/2011	Y Great Horned Owl					Remarks: Active great horned owl nest was monitored for impacts from activities within the	SLR sub
Mitigation Measure in Biology	n Compliance? Y					substation. No disturbance to the owl was observed.	
BIO-APM-26							
02/14/2011 Mitigation Measure in						In compliance - one side of each excavated area was sloped to allow escape of wildlife.	Encina Substation
Sloped sides	r					Remarks: Excavations were slanted on one side to allow wildlife to escape during the night.	
02/15/2011 Mitigation Measure in						In compliance - one side of each excavated area was sloped to allow escape of wildlife.	Encina Substation
Sloped sides	ii comphance.					Remarks: Excavations were slanted on one side to allow wildlife to escape during the night.	
02/16/2011 Mitigation Measure in						In compliance - one side of each excavated area is sloped to allow escape of wildlife.	Encina Substation
Sloped sides	п сотриансе: 1					Remarks: Excavations are slanted on one side to allow wildlife to escape during the night.	
02/17/2011 Mitigation Measure in						In compliance - one side of each excavated area is sloped to allow escape of wildlife.	Encina Substation
Sloped sides	a compliance i					Remarks: Excavations are slanted on one side to allow wildlife to escape during the night.	
02/18/2011 Mitigation Measure in						In compliance - one side of each excavated area is sloped to allow escape of wildlife.	Encina Substation
Sloped sides						Remarks: Excavations are slanted on one side to allow wildlife to escape during the night.	
02/19/2011 Mitigation Massura is						In compliance - one side of each excavated area is sloped to allow escape of wildlife.	Encina Substation
Mitigation Measure in Sloped sides	п Сопірпапсе: У					Remarks: Excavations are slanted on one side to allow wildlife to escape during the night.	

From: 02/13/2011

Page 58 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL (C	D	T7	T.	C	11
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: NA							
BIO-APM-3							
02/14/2011 Mitigation Measure in						All individuals were in compliance - drivers kept to the established speed limit.	Encina Substation
Speed limit	Comphance. 1					Remarks: Vehicles observed and complied with speed limit.	
02/15/2011 Mitigation Measure in						All individuals were in compliance - drivers kept to the established speed limit.	Encina Substation
Speed limit	. Сошрашает 1					Remarks: Vehicles observed and complied with speed limit.	
02/16/2011 Mitigation Measure in						All individuals were in compliance - drivers kept to the established speed limit.	Encina Substation
Speed limit	i companior i					Remarks: Vehicles observed and complied with speed limit.	
02/17/2011						All individuals were in compliance - drivers kept to the established speed limit.	Encina Substation
Mitigation Measure in Speed limit	Comphance: Y					Remarks: Vehicles observed and complied with speed limit.	5 4 05 44 01
02/18/2011 Mitigation Measure in						All individuals were in compliance - drivers kept to the established speed limit.	Encina Substation
Speed limit	Comphance: 1					Remarks: Vehicles observed and complied with speed limit.	
02/19/2011 Mitigation Measure in						All individuals were in compliance - drivers kept to the established speed limit.	Encina Substation
Speed limit	F					Remarks: Vehicles observed and complied with speed limit.	
C-1e							
02/14/2011 Mitigation Measure in Cultural, Tribe						Remarks: Cultural and Tribal monitors were present during all excavation	IV Substation
02/14/2011						All work observed by archaeological and Native	
Mitigation Measure in Cultural	Compliance? Y					American Monitors and was in compliance. Remarks: No cultural resources were found during trenching	Substation

From: 02/13/2011

Page 59 of 61

Weekly Monitoring Report No. 01468

	•	<u> </u>						
ENVIRO	NMENTAL (COMPLIANCE						
Mitigatio	n Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: N	NA							
C-1e								
	02/15/2011	Y					All work observed by archaeological and Native	
Mitigatio	n Measure in	Compliance? Y					American monitors and was in compliance.	Substation
Cultural							Remarks: No cultural resources were found during trenching	
Mitigatio	02/16/2011 n Measure in	Y Compliance? Y					All work observed by archaeological and Native American Monitors and was in compliance.	IV Substation
Cultural		P					Remarks: No cultural resources were found during trenching	
	02/16/2011	Y					Remarks: Cultural and Tribal monitors were	IV
Mitigation Cultural, T		Compliance? Y					present during all excavation	Substation
	02/17/2011	Y					All work observed by archaeological and Native	IV
Mitigatio	n Measure in	Compliance? Y					American Monitors and was in compliance.	Substation
Cultural							Remarks: No cultural resources were found during trenching	
Mitigatio	02/18/2011 n Measure in	Y Compliance? Y					All work observed by archaeological and Native American Monitors and was in compliance.	IV Substation
Cultural	n weasure n	Comphance. 1					Remarks: No cultural resources were found during trenching	
N-1a								
	02/15/2011						Compliance met	San Luis
Mitigation Compliance		Compliance? Y					Remarks: SDG&E crews reduced idle time.	Rey substation
PAL-1c								
	02/14/2011	Y					Remarks: Fossils collected from side walls after	IV
Mitigation Paleo visit		Compliance? Y					excavation.	Substation
	02/14/2011	Y					Remarks: No fossils found during excavation	IV
Mitigation Paleo mor		Compliance? Y					-	Substation

From: 02/13/2011

Page 60 of 61

Weekly Monitoring Report No. 01468

ENVIRONMENTAL COMPLIANCE									
Mitigatio	on Measure Date	A B (Y/N) S		C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1	NA			-					
PAL-1c									
	02/15/2011	Y						Remarks: No fossils during site visit.	IV
Mitigation Paleo visi	on Measure in it	Complia	nce? Y						Substation
	02/16/2011	Y						Remarks: No fossils during site visit.	IV
Mitigation Paleo visi	on Measure in it	Complia	nce? Y						Substation
	02/16/2011	Y						Remarks: No fossils found during excavation	IV
Mitigation Paleo mos	on Measure in nitor	Complia	nce? Y						Substation
	02/17/2011	Y						Remarks: No fossils observed during backhoe	San luis re
Mitigation Paleo mos	on Measure in nitor	Complia	nce? Y					excavations at SLR.	substation
	02/17/2011	Y					Notified Link	Remarks: Discovery of fossils during site visit.	IV
Mitigation Paleo visi	on Measure in it	Complia	nce? Y				Lead	No diversion or halting of work occured as the fossils were collected from the spoils pile.	Substation
	02/18/2011	Y						Remarks: No fossils found during site	IV
Mitigation Paleo Mo	on Measure in onitor	Complia	nce? Y					inspection.	Substation
	02/19/2011	Y P	aleontological					Remarks: No fossils found during excavation.	Encina
Mitigation Paleo mo	on Measure in nitor		· ·					, and the second	Substation

From: 02/13/2011

Page 61 of 61