

Representative Photographs of a topped pole with distribution underbuild



Representative Photographs of a topped pole with distribution underbuild



Note the structure shown is a cable pole