



Source: Geotechnical Consultants, 2007.

Sunrise Powerlink Project

Figure D.13-6 San Jacinto Fault Crossing

January 2008 Draft EIR/EIS