

Southern California Edison

# Tree Assessment Summary Report

**TLRR Control – Silver Peak Project**

Inyo County and Mono County, California

August 2022

Control – Silver Peak Project Tree Assessment Summary Report  
TLRR – Inyo County and Mono County, California

# Control – Silver Peak Project

## Tree Assessment Summary Report

**TLRR – Inyo County and Mono County, California**

August 2022

**Prepared By:**

Arcadis U.S., Inc.  
320 Commerce, Suite 200ite 200  
Irvine  
California 92602  
Phone: 714 730 9052  
Fax: 714 730 9345

**Prepared For:**

Southern California Edison

*This document is intended only for the use of the individual or entity for which it was prepared and may contain information that is privileged, confidential and exempt from disclosure under applicable law. Any dissemination, distribution or copying of this document is strictly prohibited.*

## Contents

<b>Acronyms and Abbreviations.....</b>	<b>iii</b>
<b>1    Introduction.....</b>	<b>1</b>
<b>1.1    Project Summary .....</b>	<b>1</b>
<b>1.2    Project Overview.....</b>	<b>2</b>
<b>1.2.1    Subtransmission.....</b>	<b>2</b>
<b>1.2.2    Distribution.....</b>	<b>2</b>
<b>1.2.3    Substations .....</b>	<b>2</b>
<b>2    Methods .....</b>	<b>3</b>
<b>2.1    Native Tree Assessments .....</b>	<b>3</b>
<b>2.2    Potential Tree Disturbance Types.....</b>	<b>4</b>
<b>3    Native Tree Survey Results .....</b>	<b>4</b>
<b>4    Conclusion .....</b>	<b>5</b>
<b>5    References .....</b>	<b>6</b>

## Tables

Table 1.       Summary of CSP 2022 Native Tree Assessment Survey Data

Table 2.       CSP 2022 Native Tree Survey Data

## Figures

Figure 1       Site Location

Figure 2       Native Tree Assessment Locations

## Acronyms and Abbreviations

CSP	Control – Silver Peak Project
kV	kilovolt(s)
LiDAR	Light Detection and Ranging
PEA	Proponents Environmental Assessment
SCE	Southern California Edison Company
TLRR	Transmission Line Rating Remediation
TSP	tubular steel poles

# 1 Introduction

This Southern California Edison Company (SCE) Tree Assessment Summary Report documents the native tree data collected within the proposed Control – Silver Peak Project (CSP Project) alignment in Inyo and Mono counties, California (Figure 1). The proposed CSP Project includes replacing existing facilities (generally wood poles) and installing new facilities along two existing subtransmission circuits.

Trees were mapped within a defined survey area along the CSP Project alignment. The defined survey area was based on a conservative estimate of the size, location, and alignment of proposed construction work areas. The size, location, and alignment of construction work areas is subject to revision; construction work areas will be reduced in size, and re-located and re-aligned, prior to construction to avoid resource impacts. The revised construction work areas will not exceed the defined survey area; therefore, this survey represents a conservative (worst-case) estimate of potential impacts to trees.

## 1.1 Project Summary

SCE is a public utility that provides electric service to a population of approximately 15 million people within a 50,000-square-mile service area that encompasses 180 cities throughout Southern California. SCE owns and operates approximately 5,000 miles of bulk power facilities (500 kilovolt [kV] and 220 kV transmission lines) and 1,500 miles of subtransmission (55 kV to 115 kV) lines. SCE also owns and operates 1,200 miles of radial 115 kV subtransmission lines.

The design of electric lines in California is governed by GO 95, Rules for Overhead Electric Line Construction. The purpose of the Rules contained within GO 95 is to "...formulate, for the State of California, requirements for overhead line design, construction, and maintenance, the application of which would ensure adequate service and secure safety to persons engaged in the construction, maintenance, operation or use of overhead lines and to the public in general."

GO 95 Rules 37 through 39 specify minimum vertical and horizontal clearances that must be maintained between an electric power line (referred to as a conductor) and other conductors, or between a conductor and the ground, buildings, and a variety of other objects. Conductor clearance in the field (e.g., between a conductor and the ground) is not a static value—it changes depending upon the operational characteristics of the line. As greater amounts of electricity are transmitted by a conductor, the conductor material heats up and expands, resulting in greater sag (and a lesser clearance) in a given span.

In 2006, SCE identified that the clearances along some of its circuits were not compliant with the clearances required by GO 95 due to the installation of additional infrastructure under SCE lines over time; survey, engineering, and construction inaccuracies; the growth of vegetation; and changes in topography. This information was communicated to both the CPUC and the California Independent System Operator. SCE then initiated a Light Detection and Ranging (LiDAR) study and engineering modeling work to confirm these discrepancies.

The collective effort to identify and remediate these discrepancies across SCE's system is referred to as the Transmission Line Rating Remediation (TLRR) Program. Based on the LiDAR and engineering modeling work, SCE's TLRR effort is developing a remediation plan for each discrepancy to ensure compliance with GO 95 standards.

The CSP Project is one activity within SCE's larger TLRR effort. The discrepancies identified on the subtransmission lines included under the CSP Project were identified through LiDAR and engineering modeling work performed under the TLRR effort.

## 1.2 Project Overview

Through the CSP Project, SCE proposes to rebuild some portions of two existing subtransmission lines and to replace or modify existing subtransmission structures along other portions of these existing subtransmission lines. The CSP Project includes the following components to remediate the identified discrepancies

### 1.2.1 Subtransmission

The CSP Project would rebuild infrastructure along 57.1 miles of existing 55 kV subtransmission circuits by:

- Removing existing subtransmission wood poles and wood pole H-frames, and replacing them with tubular steel poles (TSPs), TSP H-frames, and wood pole-equivalents.<sup>1</sup>
- Removing existing conductor and installing new Aluminum Conductor Composite Core or Aluminum Conductor Steel Reinforced subtransmission conductor on replacement structures.
- Installing optical ground wire, All-Dielectric Self-Supporting fiber optic cable, and overhead groundwire for system protection.

### 1.2.2 Distribution

Distribution circuits are installed on existing poles in Segments 3, 4, and 5. This infrastructure will be transferred from existing structures to replacement structures or the existing infrastructure will be left in-place and the poles on which the infrastructure is installed would be topped above the distribution circuit and appurtenances, or the poles will be left at their existing height

### 1.2.3 Substations

The CSP Project would include the following substation-related work:

- Disconnect existing conductor from existing positions at the White Mountain Substation and connect new conductor to existing positions.
- Install new optical groundwire and overhead groundwire and make minor modifications to the existing terminal racks at White Mountain substation to accommodate the new optical groundwire and overhead groundwire.
- Install telecommunication equipment on existing rack structures, install cable in new or existing underground cable raceways, and install new or replacement telecommunications infrastructure within existing cabinets, control buildings, or Mechanical and Electrical Equipment Rooms within the Control Substation and at the Fish Lake Valley Metering Station.
- Update relay settings at Control, Deep Springs, White Mountain, and Zack substations.
- Install a capacitor bank and circuit breaker at Fish Lake Valley Metering Station.

---

<sup>1</sup> 'Wood pole-equivalents' include wood poles, lightweight steel poles, ductile iron poles, and composite poles.

## 2 Methods

As outlined in the CSP Project Proponent's Environmental Assessment (PEA; Arcadis 2021), trees or portions of trees that occur within anticipated CSP Project work areas and/or encroach upon work areas, access roads, or laydown yards may be pruned and/or removed to facilitate the safe movement of construction equipment. Laydown yard sites have been preferentially placed to minimize the pruning or removal of trees.

Native trees were mapped within a defined survey area along the CSP Project alignment. The defined survey area was based on a conservative estimate of the size, location, and alignment of proposed construction work areas and associated laydown yards. The size, location, and alignment of construction work areas is subject to revision; construction work areas will be reduced in size, and re-located and re-aligned, prior to construction to avoid resource impacts. The revised construction work areas will not exceed the defined survey area; therefore, this survey represents a conservative estimate of potential impacts to trees.

Initial assessments of native trees in all potential CSP Project disturbance locations and associated access roads were conducted by Arcadis between July 7 and July 25, 2022. Additional surveys may be conducted on an as-needed basis.

This Tree Assessment Summary Report documents the native tree species, locations, quantities, size, and health that were observed within and near anticipated Project work areas and access roads, as described in the data collection methods summary below.

### 2.1 Native Tree Assessments

Trees were assessed during the surveys if trees or portions of trees occur within anticipated CSP Project work areas and/or encroach upon work areas, access roads, or laydown yards. All native trees with a single trunk at least 8 inches in diameter, or multiple trunks with a combined diameter of 8 inches, were documented. Trunk diameter at breast height (dbh) was measured four and one-half feet above mean natural grade for all tree species except for willows (members of the genus *Salix*). For willows, the total number of trunks were estimated. Non-native trees were not assessed at this time.

Tree assessment data includes tree species, location, number of trunks, dbh, approximate height, qualitative tree health (i.e., excellent, good, fair, poor, dead), and current conditions (e.g., fire scars, fungal infestation, tree previously subject to pruning). Coordinates of individual trees were collected using hand-held devices (i.e., phones and electronic tablets) using FieldMaps and Survey123 software; the devices were paired with Trimble global positioning system antennae (R1 units).

For trees hanging over anticipated Project work areas, potential pruning and/or root disturbance was assessed if anticipated disturbance was equal to or greater than 25% of the tree canopy or 25% of the root zone under the tree canopy. Potential pruning and/or limbing of an individual tree was evaluated if tree branches extended within 20 feet of the ground surface, based on the assumption that a 20-foot vertical clearance would be required to allow work equipment and vehicles unimpeded access to anticipated Project work areas. An extendable stadia rod was used to estimate the height of tree limbs from the ground surface.

Dead trees were mapped if they occurred within anticipated Project work areas to document trees that were already dead prior to Project activities.

Native tree assessments were performed by Arcadis Ecologists Cynthia Nicely, Khua Moua, Meghan McGill, and Todd White. Ms. Nicely is a Certified Arborist (International Society of Arboriculture WE-13216A), and Ms. McGill is training to become a Certified Arborist.

## 2.2 Potential Tree Disturbance Types

Data gathered during tree surveys were used to assess potential tree disturbance types as follows:

**Occurs within Anticipated Project Work Areas.** Native trees that are rooted within anticipated Project work areas may require removal (100% tree canopy pruning and 100% root disturbance) or may be flagged for avoidance, based on future work area refinements. Trees within anticipated Project work areas are treated in Tables 1 and 2 separately from trees that are rooted outside of anticipated Project work areas but that overhang work areas and/or overhang access roads.

**Percent of Canopy to be Potentially Pruned.** Trees that are rooted outside of anticipated Project work areas and that overhang anticipated Project work areas and/or access roads with branches that are less than 20 vertical feet above the ground surface were evaluated to determine if more than 25% of the tree canopy would require new pruning and/or limbing for horizontal and/or vertical clearance to facilitate equipment and vehicle access. This pruning is separate from any pruning recommended to promote the health of or safety of the tree.

**Percent Root Disturbance.** Trees that overhang anticipated Project work areas and/or access roads were also evaluated for estimated new root disturbance during work activities. Because the majority of observed native tree species produce roots within the top 12 inches of the soil surface, trees were evaluated to determine if more than 25% of subsurface roots would experience new root disturbance during work activities. A single tree overhanging work areas and/or access roads may be subject to both pruning and root disturbance.

Note: Root disturbance documentation during construction does not include native trees that occur along existing access roads that are not subject to road improvements, since there would be no new root disturbance.

## 3 Native Tree Survey Results

A total of 2,388 native trees were documented in potential CSP Project disturbance locations and associated access roads in July 2022 (Tables 1 and 2). Of these, 1,876 native living trees occurred within anticipated Project work areas, and 50 dead trees occurred within anticipated Project work areas.

An additional 454 living trees and 8 dead trees were documented outside anticipated Project work areas, mostly immediately adjacent to but rooted outside of Project work areas and/or associated access roads. Many of these trees outside of Project work areas overhang a work area and/or access road. Of these, 68 trees may be subject to pruning that removes 25% or more of the tree canopy for horizontal and vertical clearance and/or may be subject to root disturbance of 25% or more under the dripline of the tree canopy; many trees subject to root disturbance will also require pruning.

The actual number of trees subject to removal, pruning, and/or root disturbance will be quantified during construction and will depend on equipment size and height, as well as implementation of potential native tree avoidance and protection measures.

Table 1 summarizes the total numbers of trees documented during the 2022 CSP native tree surveys, with comprehensive tree data provided in Table 2. Figure 2 provides the locations of mapped native trees during the 2022 CSP tree assessment surveys.

## 4 Conclusion

Native tree surveys along the CSP Project alignment indicated that 2,388 trees with a diameter of 8 inches at breast height or greater occur within anticipated CSP Project work areas and associated access roads. Of these trees, 1,876 native living trees occur within the anticipated Project work areas, and 454 living trees occur outside of Project work areas, in many cases overhanging the anticipated Project work areas and / or access roads. Of these, 68 trees may be subject to pruning that removes 25% or more of the tree canopy for horizontal and vertical clearance and/or may be subject to root disturbance of 25% or more under the dripline of the tree canopy.

The actual number of trees subject to removal, pruning, and/or root disturbance will be quantified during construction and will depend on equipment size and height, as well as implementation of potential oak tree avoidance and protection measures.

## 5 References

Arcadis U.S., Inc. (Arcadis). 2021. Proponent's Environmental Assessment for Southern California Edison Company's TLRR Control-Silver Peak 55 kV Project. Prepared for Southern California Edison Company. December

# Tables

Table 1.  
 Summary of CSP 2022 Native Tree Assessment Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 kV Project  
 Inyo and Mono Counties  
 Southern California Edison



Scientific Name	Common Name	Total Native Trees Documented	Total Living Native Trees within Anticipated Project Work Areas <sup>1</sup>	Total Dead Native Trees within Anticipated Work Areas	Total Living Trees Outside of Work Area and Overhanging	Total Dead Native Trees Outside of Work Areas and Overhanging	Total Living Native Trees Rooted Outside of Anticipated Work Areas with > 25% Anticipated Pruning and/or > 25% Anticipated Root Disturbance	Total Living Native Trees Rooted Outside of Anticipated Work Areas with < 25% Anticipated Pruning and or < 25% Anticipated Root Disturbance
<i>Betula occidentalis</i>	water birch	111	94	0	17	0	4	13
<i>Juniperus osteosperma</i>	Utah juniper	98	80	3	15	0	2	13
<i>Pinus flexilis</i>	limber pine	58	48	3	6	1	0	6
<i>Pinus longaeva</i>	bristlecone pine	212	186	4	22	0	7	15
<i>Pinus monophylla</i>	singleleaf pinyon pine	711	536	19	150	6	20	130
<i>Populus fremontii</i>	Fremont cottonwood	65	52	2	11	0	4	7
<i>Populus tremuloides</i>	quaking aspen	160	136	3	21	0	1	20
<i>Populus trichocarpa</i>	black cottonwood	36	25	1	10	0	5	5
<i>Salix laevigata</i>	red willow	23	19	0	4	0	1	4
<i>Salix lasiandra</i> ( <i>Salix lucida</i> )	Pacific willow, shining willow	3	2	0	1	0	0	1
<i>Salix lasiolepis</i>	arroyo willow	883	687	11	185	0	24	161
<i>Salix lutea</i>	yellow willow	23	11	0	12	0	0	12
<hr/>								
<i>Pinus</i> species	unknown pine	2	0	2	0	0	0	0
<i>Salix</i> species	unknown willow	3	0	2	0	1	0	0
<b>Totals</b>		<b>2,388</b>	<b>1,876</b>	<b>50</b>	<b>454</b>	<b>8</b>	<b>68</b>	<b>387</b>

<sup>1</sup> Trees within work areas that also overhang an adjacent access road are categorized within the Project work area category.

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E05-073944D	<i>Betula occidentalis</i>	Water birch	10	20	12	-	#1-4", #2-7"	4	7	Good	Inside	100%	100%	-	Some dead on outside
1E05-074802B	<i>Betula occidentalis</i>	Water birch	10	20	10	-	#1-10"x10	10	10	Good	Inside	100%	100%	-	-
1E05-075340A	<i>Betula occidentalis</i>	Water birch	20	30	7	-	#1-10"x7	10	10	Good	Inside	100%	100%	-	-
1E05-075625B	<i>Betula occidentalis</i>	Water birch	10	20	5	-	#1-10"x5	10	10	Good	Inside	100%	100%	-	-
1E05-075700C	<i>Betula occidentalis</i>	Water birch	10	20	35	-	#1-4"x35	4	4	Excellent	Inside	100%	100%	-	-
1E05-080503D	<i>Betula occidentalis</i>	Water birch	10	20	9	-	#1-4"x9	4	4	Good	Inside	100%	100%	-	-
1E05-080745C	<i>Betula occidentalis</i>	Water birch	20	30	30	-	#1-4"x30	4	4	Good	Inside	100%	100%	-	-
1E05-081129C	<i>Betula occidentalis</i>	Water birch	10	20	30	-	#1-4"x30	4	4	Good	Inside	100%	100%	-	-
1E05-081355D	<i>Betula occidentalis</i>	Water birch	10	20	8	-	#1-4"x8	4	4	Excellent	Inside	100%	100%	-	-
1E05-081453C	<i>Betula occidentalis</i>	Water birch	20	30	30	-	#1-4"x30	4	4	Excellent	Inside	100%	100%	-	-
1E05-081539D	<i>Betula occidentalis</i>	Water birch	10	20	6	-	#1-4"x6	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-081649C	<i>Betula occidentalis</i>	Water birch	10	20	25	-	#1-1-4"x25			Good	Inside	100%	100%	Previously pruned	-
1E05-081852C	<i>Betula occidentalis</i>	Water birch	10	20	35	-	#1-1-4"x35			Good	Inside	100%	100%	Previously pruned	-
1E05-082029D	<i>Betula occidentalis</i>	Water birch	20	30	6	-	#1-4", #2-7"x2	4	7	Good	Inside	100%	100%	-	-
1E05-082254C	<i>Betula occidentalis</i>	Water birch	10	20	40	-	#1-1-4"x40			Good	Inside	100%	100%	Previously pruned	-
1E05-082525C	<i>Betula occidentalis</i>	Water birch	10	20	25	-	#1-4"x25	4	4	Fair	Inside	100%	100%	-	-
1E05-082713C	<i>Betula occidentalis</i>	Water birch	10	20	40	-	#1-1-4"x40			Good	Inside	100%	100%	-	-
1E05-082738D	<i>Betula occidentalis</i>	Water birch	10	20	10	-	#1-4"x10	4	4	Good	Inside	100%	100%	-	-
1E05-082905B	<i>Betula occidentalis</i>	Water birch	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E05-082913C	<i>Betula occidentalis</i>	Water birch	10	20	25	-	#1-1-4"x25			Good	Inside	100%	100%	Previously pruned	-
1E05-083141C	<i>Betula occidentalis</i>	Water birch	20	30	25	-	#1-4"x25	4	4	Good	Inside	100%	100%	-	-
1E05-083242D	<i>Betula occidentalis</i>	Water birch	20	30	6	-	#1-4"x5, #2-7"	4	7	Excellent	Inside	100%	100%	-	-
1E05-083634D	<i>Betula occidentalis</i>	Water birch	10	20	6	-	#1-7", #2-4"x4	4	7	Good	Inside	100%	100%	-	-
1E05-084306D	<i>Betula occidentalis</i>	Water birch	20	30	6	-	#1-4"x6	4	4	Good	Inside	100%	100%	-	-
1E05-084515D	<i>Betula occidentalis</i>	Water birch	10	20	8	-	#1-4"x8	4	4	Excellent	Inside	100%	100%	-	-
1E05-084700D	<i>Betula occidentalis</i>	Water birch	20	30	7	-	#1-7", #2-4"x5	4	7	Good	Inside	100%	100%	-	-
1E05-084826A	<i>Betula occidentalis</i>	Water birch	10	20	12	-	#2-7"x2, #3-4"x10	4	7	Good	Inside	100%	100%	Previously pruned	-
1E05-084947C	<i>Betula occidentalis</i>	Water birch	20	30	22	-	#1-4", #2-10"x2	10	4	Good	Inside	100%	100%	-	-
1E05-085233C	<i>Betula occidentalis</i>	Water birch	20	30	23	-	#1-4"x20, #2-7"x3	4	7	Good	Inside	100%	100%	Previously pruned	-
1E05-085234A	<i>Betula occidentalis</i>	Water birch	10	20	11	-	#1-7"x10, #2-7"	7	7	Good	Inside	100%	100%	Previously pruned	-
1E05-085501C	<i>Betula occidentalis</i>	Water birch	20	30	25	-	#1-1-2"x20, #2-7"x5		7	Good	Inside	100%	100%	Previously pruned	-
1E05-085609D	<i>Betula occidentalis</i>	Water birch	10	20	8	-	#1-4"x8	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-085654A	<i>Betula occidentalis</i>	Water birch	10	20	12	-	#1-7"x2, #2-4"x10	4	7	Good	Inside	100%	100%	Previously pruned	-
1E05-085746D	<i>Betula occidentalis</i>	Water birch	10	20	15	-	#1-4"x15	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-085915A	<i>Betula occidentalis</i>	Water birch	10	20	18	-	#1-7"x3, #2-4"x15	4	7	Good	Inside	100%	100%	Previously pruned	-
1E05-085943D	<i>Betula occidentalis</i>	Water birch	20	30	8	-	#1-7", #2-4"x6	4	7	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E05-090134A	<i>Betula occidentalis</i>	Water birch	10	20	18	-	#1-4", #2-7"x3	4	7	Good	Inside	100%	100%	Previously pruned	-
1E05-091215B	<i>Betula occidentalis</i>	Water birch	0	10	1	-	#1-4"	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-091607B	<i>Betula occidentalis</i>	Water birch	0	10	1	-	#1-4"	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-091816A	<i>Betula occidentalis</i>	Water birch	10	20	25	-	#1-4"x25	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-092009A	<i>Betula occidentalis</i>	Water birch	10	20	16	-	#1-4", #2-7"	4	7	Good	Inside	100%	100%	Previously pruned	-
1E05-092427D	<i>Betula occidentalis</i>	Water birch	10	20	12	-	#1-4"x12	4	4	Good	Inside	100%	100%	-	-
1E05-093301D	<i>Betula occidentalis</i>	Water birch	10	20	13	-	#1-4"x10, #2-7"	4	7	Excellent	Inside	100%	100%	-	-
1E05-093934D	<i>Betula occidentalis</i>	Water birch	10	20	5	-	#1-4"x5	4	4	Excellent	Inside	100%	100%	-	-
1E05-095048D	<i>Betula occidentalis</i>	Water birch	20	30	17	-	#1-7", #2-4"x5	4	7	Good	Inside	100%	100%	-	-
1E05-095138A	<i>Betula occidentalis</i>	Water birch	0	10	8	-	#1-4"x8	4	4	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E05-100355A	<i>Betula occidentalis</i>	Water birch	10	20	9	-	#1-4"x8, #2-7"	4	7	Good	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E05-100453D	<i>Betula occidentalis</i>	Water birch	20	30	20	-	#1-4", #2-7"x15	4	7	Good	Inside	100%	100%	-	-
1E05-100700B	<i>Betula occidentalis</i>	Water birch	0	10	4	-	#1-4"x4	4	4	Good	Overhanging	More than 25%	Less than 25%	-	-
1E05-100929A	<i>Betula occidentalis</i>	Water birch	10	20	15	-	#1-7"x15	7	7	Good	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E05-101010B	<i>Betula occidentalis</i>	Water birch	0	10	20	-	#1-4"x20	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-101128A	<i>Betula occidentalis</i>	Water birch	10	20	14	-	#1-7"x2, #2-4"x12	4	7	Good	Inside	100%	100%	Previously pruned	-
1E05-101342A	<i>Betula occidentalis</i>	Water birch	10	20	6	-	#1-4"x3, #2-7"x3	4	7	Good	Inside	100%	100%	Previously pruned	-
1E05-101402B	<i>Betula occidentalis</i>	Water birch	0	10	10	-	#1-4"x10	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-101403D	<i>Betula occidentalis</i>	Water birch	10	20	3	-	#1-3"x3	3	3	Excellent	Inside	100%	100%	-	-
1E05-101615B	<i>Betula occidentalis</i>	Water birch	10	20	10	-	#1-4"x10	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-102306B	<i>Betula occidentalis</i>	Water birch	10	20	15	-	#1-4"x15	4	4	Good	Inside	100%	100%	-	-
1E05-102522B	<i>Betula occidentalis</i>	Water birch	10	20	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E05-102750B	<i>Betula occidentalis</i>	Water birch	10	20	10	-	#1-4"x10	4	4	Good	Inside	100%	100%	-	-
1E05-103019B	<i>Betula occidentalis</i>	Water birch	10	20	20	-	#1-4"x20	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-103033D	<i>Betula occidentalis</i>	Water birch	20	30	12	-	#1-4"x12	4	4	Excellent	Inside	100%	100%	-	-
1E05-103636A	<i>Betula occidentalis</i>	Water birch	20	30	31	-	#1-7", #2-4"x24	4	7	Excellent	Inside	100%	100%	Previously pruned	-
1E05-104143B	<i>Betula occidentalis</i>	Water birch	10	20	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-104340B	<i>Betula occidentalis</i>	Water birch	10	20	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-104526A	<i>Betula occidentalis</i>	Water birch	10	20	40	-	#1-4"x40	4	4	Excellent	Inside	100%	100%	Previously pruned	-
1E05-104624B	<i>Betula occidentalis</i>	Water birch	10	20	10	-	#1-4"x10	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-104746A	<i>Betula occidentalis</i>	Water birch	10	20	40	-	#1-4"x40	4	4	Excellent	Inside	100%	100%	Previously pruned	-
1E05-105712B	<i>Betula occidentalis</i>	Water birch	10	20	10	-	#1-4"x10	4	4	Good	Inside	100%	100%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in Inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E05-105749A	<i>Betula occidentalis</i>	Water birch	20	30	45	-	#1-4"x45	4	4	Good	Overhanging	More than 25%	More than 25%	Previously pruned	-
1E05-105908B	<i>Betula occidentalis</i>	Water birch	10	20	15	-	#1-4"x15	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-110111A	<i>Betula occidentalis</i>	Water birch	20	30	30	-	#1-4"x13, #2-7"x17	4	7	Excellent	Inside	100%	100%	-	-
1E05-110556B	<i>Betula occidentalis</i>	Water birch	10	20	20	-	#1-4"x20	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-110805A	<i>Betula occidentalis</i>	Water birch	10	20	23	-	#1-4"x18, #2-7"x5	4	7	Good	Inside	100%	100%	-	-
1E05-112600A	<i>Betula occidentalis</i>	Water birch	20	30	24	-	#1-4"x12, #2-7"x12	4	7	Good	Inside	100%	100%	-	-
1E05-113311A	<i>Betula occidentalis</i>	Water birch	20	30	42	-	#1-4", #2-7"x12	4	7	Good	Inside	100%	100%	-	-
1E05-114218A	<i>Betula occidentalis</i>	Water birch	10	20	40	-	#1-4"x40	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-115126B	<i>Betula occidentalis</i>	Water birch	10	20	13	-	#1-7"x3, #2-4"x10	4	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E05-115306A	<i>Betula occidentalis</i>	Water birch	10	20	30	-	#1-4"x30	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-115629A	<i>Betula occidentalis</i>	Water birch	10	20	10	-	#1-4"x10	4	4	Good	Inside	100%	100%	-	-
1E05-115919B	<i>Betula occidentalis</i>	Water birch	10	20	20	-	#1-7"x5, #2-4"x15	4	7	Good	Inside	100%	100%	-	-
1E05-115955A	<i>Betula occidentalis</i>	Water birch	0	10	25	-	#1-4"x25	4	4	Good	Inside	100%	100%	Previously pruned	Very small, but many trunks
1E05-120207A	<i>Betula occidentalis</i>	Water birch	10	20	35	-	#1-4"x30, #2-7"x5	4	7	Good	Inside	100%	100%	Previously pruned	-
1E05-122304B	<i>Betula occidentalis</i>	Water birch	10	20	2	-	#1-4"x2	4	4	Excellent	Inside	100%	100%	-	-
1E05-123006B	<i>Betula occidentalis</i>	Water birch	10	20	10	-	#1-7", #2-4"x5	4	7	Good	Inside	100%	100%	Previously pruned	-
1E05-123409C	<i>Betula occidentalis</i>	Water birch	20	30	20	-	#1-7"x20	7	7	Excellent	Inside	100%	100%	-	-
1E05-124035C	<i>Betula occidentalis</i>	Water birch	20	30	20	-	#1-4"x15, #2-7"x5	4	7	Excellent	Inside	100%	100%	-	-
1E10-094202D	<i>Betula occidentalis</i>	Water birch	10	20	13	-	#1-4"x13	4	4	Good	Inside	100%	100%	-	-
1E10-130854D	<i>Betula occidentalis</i>	Water birch	0	10	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	-	-
1E10-133744C	<i>Betula occidentalis</i>	Water birch	20	30	20	-	#1-4"x20	4	4	Excellent	Inside	100%	100%	-	-
1E12-085145C	<i>Betula occidentalis</i>	Water birch	10	20	10	-	#1-4"x10	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-085405C	<i>Betula occidentalis</i>	Water birch	10	20	12	-	#1-4"x12	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-085707C	<i>Betula occidentalis</i>	Water birch	10	20	1	-	#8-4"	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-090625C	<i>Betula occidentalis</i>	Water birch	20	30	14	-	#1-4"x14	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-090916C	<i>Betula occidentalis</i>	Water birch	20	30	8	-	#1-4"x8	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-095557B	<i>Betula occidentalis</i>	Water birch	10	20	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E12-095740A	<i>Betula occidentalis</i>	Water birch	20	30	4	-	#1-7"x4	7	7	Excellent	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E12-095756B	<i>Betula occidentalis</i>	Water birch	10	20	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E12-101351C	<i>Betula occidentalis</i>	Water birch	10	20	6	-	#1-4"x6	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-102058C	<i>Betula occidentalis</i>	Water birch	20	30	2	-	#1-4"x2	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-104056B	<i>Betula occidentalis</i>	Water birch	10	20	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E15-095539D	<i>Betula occidentalis</i>	Water birch	20	30	20	-	#1-4"x20	4	4	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E15-095548C	<i>Betula occidentalis</i>	Water birch	10	20	11	-	#1-10"x3, #2-7"x8	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-100947C	<i>Betula occidentalis</i>	Water birch	10	20	20	-	#1-4"x20	4	4	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-101301D	<i>Betula occidentalis</i>	Water birch	10	20	20	-	#1-4"x20	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-091206A	<i>Betula occidentalis</i>	Water birch	20	30	7	-	#1-7"x7	7	7	Excellent	Inside	100%	100%	-	-
1E16-091956A	<i>Betula occidentalis</i>	Water birch	20	30	8	-	#1-7"x8	7	7	Excellent	Inside	100%	100%	-	-
1E16-092605A	<i>Betula occidentalis</i>	Water birch	20	30	9	-	#1-7"x5, #2-4"x4	4	7	Excellent	Inside	100%	100%	-	-
1E16-093006C	<i>Betula occidentalis</i>	Water birch	20	30	8	-	#1-4"x8	4	4	Excellent	Inside	100%	100%	-	-
1E16-095412A	<i>Betula occidentalis</i>	Water birch	10	20	3	-	#1-7"x3	7	7	Excellent	Inside	100%	100%	-	-
1E16-101548C	<i>Betula occidentalis</i>	Water birch	10	20	4	-	#1-4"x4	4	4	Excellent	Inside	100%	100%	-	-
ADD-163730A	<i>Betula occidentalis</i>	Water birch	10	20	3	-	#1-7"x3	7	7	Good	Inside	100%	100%	-	-
1E08-101914C	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E08-102159D	<i>Juniperus osteosperma</i>	Utah juniper	0	10	4	-	#1-10", #2-7", #3-4"x2	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E08-102620D	<i>Juniperus osteosperma</i>	Utah juniper	20	30	10	-	#1-7"x7, #2-10"x3	10	7	Good	Overhanging	More than 25%	Less than 25%	-	-
1E08-103221C	<i>Juniperus osteosperma</i>	Utah juniper	20	30	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	-
1E08-103442A	<i>Juniperus osteosperma</i>	Utah juniper	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E08-104231A	<i>Juniperus osteosperma</i>	Utah juniper	10	20	2	-	#1-7"x2	7	7	Excellent	Inside	100%	100%	-	-
1E08-110016C	<i>Juniperus osteosperma</i>	Utah juniper	20	30	5	-	#1-10", #2-10"x4	10	10	Good	Inside	100%	100%	-	-
1E08-110037B	<i>Juniperus osteosperma</i>	Utah juniper	20	30	6	-	#1-10"x4, #2-18"x2	10	18	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E08-110512B	<i>Juniperus osteosperma</i>	Utah juniper	0	10	4	-	#1-10"x4	10	10	Good	Inside	100%	100%	Previously pruned	Top of tree removed. Recently pruned.
1E08-110516D	<i>Juniperus osteosperma</i>	Utah juniper	10	20	3	-	#1-7", #2-4"x2	4	7	Good	Inside	100%	100%	-	-
1E08-110641A	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E08-110650B	<i>Juniperus osteosperma</i>	Utah juniper	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top of tree removed. Recently pruned
1E08-110839B	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E08-111204A	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E08-111315D	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-8"	8	8	Good	Inside	100%	100%	-	-
1E08-111502C	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E08-111505B	<i>Juniperus osteosperma</i>	Utah juniper	0	10	4	-	#1-7", #2-4"x3	4	7	Good	Inside	100%	100%	Previously pruned	Top removed, recently pruned
1E08-111553D	<i>Juniperus osteosperma</i>	Utah juniper	0	10	8	-	#1-4"x8	4	4	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sali)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E08-111649C	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E08-111711D	<i>Juniperus osteosperma</i>	Utah juniper	0	10	7	-	#1-4"x7	4	4	Good	Inside	100%	100%	-	-
1E08-112603C	<i>Juniperus osteosperma</i>	Utah juniper	20	30	8	-	#1-7", #2-7"x3	7	7	Good	Overhanging	More than 25%	More than 25%	-	-
1E08-114011D	<i>Juniperus osteosperma</i>	Utah juniper	0	10	3	-	#1-18", #2-4"x2	18	4	Fair	Inside	100%	100%	Previously pruned	Extensively pruned
1E08-114127C	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E08-114218D	<i>Juniperus osteosperma</i>	Utah juniper	0	10	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E08-114639C	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E08-114715D	<i>Juniperus osteosperma</i>	Utah juniper	0	10	1	-	#1-8"	8	8	Excellent	Inside	100%	100%	-	-
1E08-114837D	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E08-115427C	<i>Juniperus osteosperma</i>	Utah juniper	30	40	7	-	#1-18", #2-10"x5	10	18	Excellent	Inside	100%	100%	-	-
1E08-121602D	<i>Juniperus osteosperma</i>	Utah juniper	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E08-121712D	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-8"	8	8	Good	Inside	100%	100%	-	-
1E08-122002D	<i>Juniperus osteosperma</i>	Utah juniper	10	20	5	-	#1-18", #2-7"x4	18	7	Good	Inside	100%	100%	-	-
1E08-122109A	<i>Juniperus osteosperma</i>	Utah juniper	30	40	1	-	#1-54"	54	54	Excellent	Inside	100%	100%	-	-
1E08-122404D	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E08-122459A	<i>Juniperus osteosperma</i>	Utah juniper	20	30	1	-	#1-42"	42	42	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E08-122529D	<i>Juniperus osteosperma</i>	Utah juniper	10	20	5	-	#1-7", #2-4"x4	4	7	Good	Inside	100%	100%	-	-
1E08-122706D	<i>Juniperus osteosperma</i>	Utah juniper	10	20	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	-	-
1E08-122925D	<i>Juniperus osteosperma</i>	Utah juniper	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E08-122953B	<i>Juniperus osteosperma</i>	Utah juniper	10	20	2	-	#1-10", #2-7"	10	7	Good	Inside	100%	100%	-	-
1E08-123205B	<i>Juniperus osteosperma</i>	Utah juniper	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E08-123345B	<i>Juniperus osteosperma</i>	Utah juniper	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E08-123730C	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E08-123908C	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E08-124402A	<i>Juniperus osteosperma</i>	Utah juniper	10	20	3	-	#1-7"x3	7	7	Excellent	Inside	100%	100%	-	-
1E10-092828C	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Tree topped at 20' above the ground surface. Total of 5 main trunks branching out at 6' above the ground surface all topped. Directly under conductor.
1E10-095102B	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	
1E10-101542B	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	
1E10-104656C	<i>Juniperus osteosperma</i>	Utah juniper	20	30	5	-	#1-10", #2-7"x3	10	7	Fair	Overhanging	Less than 25%	Less than 25%	-	
1E10-105749C	<i>Juniperus osteosperma</i>	Utah juniper	10	20	3	-	#1-4"x3	4	4	Excellent	Inside	100%	100%	-	
1E10-110328C	<i>Juniperus osteosperma</i>	Utah juniper	20	30	5	-	#1-18", #2-10"x3	10	18	Good	Inside	100%	100%	Previously pruned	-
1E10-110657C	<i>Juniperus osteosperma</i>	Utah juniper	0	10	1	-	#1-10"	10	10	Dead	Inside	--	--	Previously pruned	Cut down at 3' above the ground surface.
1E10-124046D	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-124306D	<i>Juniperus osteosperma</i>	Utah juniper	0	10	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/x)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E10-124913D	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-125018C	<i>Juniperus osteosperma</i>	Utah juniper	20	30	3	-	#1-10"x3	10	10	Excellent	Inside	100%	100%	-	-
1E10-125108D	<i>Juniperus osteosperma</i>	Utah juniper	0	10	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E10-125533D	<i>Juniperus osteosperma</i>	Utah juniper	0	10	3	-	#1-7"x3	7	7	Good	Inside	100%	100%	-	-
1E10-125805D	<i>Juniperus osteosperma</i>	Utah juniper	0	10	7	-	#1-4"x6, #2-7"	4	7	Fair	Inside	100%	100%	-	-
1E10-131408D	<i>Juniperus osteosperma</i>	Utah juniper	0	10	1	-	#1-10"	10	10	Dead	Inside	--	--	-	-
1E10-132945C	<i>Juniperus osteosperma</i>	Utah juniper	20	30	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E10-133346A	<i>Juniperus osteosperma</i>	Utah juniper	10	20	3	-	#1-10"x3	10	10	Excellent	Inside	100%	100%	-	-
1E12-085730D	<i>Juniperus osteosperma</i>	Utah juniper	10	20	5	-	#1-18", #2-7"x3, #3-10"	10	7	Good	Inside	100%	100%	Previously pruned	-
1E12-090742B	<i>Juniperus osteosperma</i>	Utah juniper	0	10	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E12-091951D	<i>Juniperus osteosperma</i>	Utah juniper	0	10	3	-	#1-7"x3	7	7	Good	Inside	100%	100%	-	-
1E12-093348A	<i>Juniperus osteosperma</i>	Utah juniper	10	20	4	-	#1-10", #2-7"x3	10	7	Fair	Inside	100%	100%	Previously pruned	-
1E12-094336C	<i>Juniperus osteosperma</i>	Utah juniper	20	30	9	-	#1-18", #2-10", #3-7"x4	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-112720D	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E12-115039C	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-7"	7	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E13-094433B	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E13-095551A	<i>Juniperus osteosperma</i>	Utah juniper	20	30	2	-	#1-18"x2	18	18	Fair	Inside	100%	100%	-	-
1E13-102013B	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E13-103343B	<i>Juniperus osteosperma</i>	Utah juniper	10	20	2	-	#1-10", #2-7"	10	7	Good	Inside	100%	100%	-	-
1E13-121952B	<i>Juniperus osteosperma</i>	Utah juniper	10	20	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	-	-
1E13-123726A	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-10"	10	10	Dead	Inside	--	--	-	-
1E13-123944A	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	Severely topped
1E14-093647B	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E14-094009B	<i>Juniperus osteosperma</i>	Utah juniper	10	20	2	-	#1-10", #2-7"	10	7	Good	Inside	100%	100%	-	-
1E14-094145B	<i>Juniperus osteosperma</i>	Utah juniper	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-
1E14-094314A	<i>Juniperus osteosperma</i>	Utah juniper	10	20	10	-	#1-7"x8, #2-10"x2	10	7	Fair	Inside	100%	100%	Previously pruned	Topped
1E14-094436B	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-094821D	<i>Juniperus osteosperma</i>	Utah juniper	10	20	3	-	#1-7"x3	7	7	Good	Inside	100%	100%	-	-
1E14-095412C	<i>Juniperus osteosperma</i>	Utah juniper	10	20	2	-	#1-4", #2-10"	10	4	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	Tree topped at 11' above the ground surface.
1E14-100201D	<i>Juniperus osteosperma</i>	Utah juniper	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E14-100256D	<i>Juniperus osteosperma</i>	Utah juniper	0	10	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	Whole top cut off
1E14-100854B	<i>Juniperus osteosperma</i>	Utah juniper	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-101152D	<i>Juniperus osteosperma</i>	Utah juniper	10	20	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	-	-
1E14-101913C	<i>Juniperus osteosperma</i>	Utah juniper	20	30	1	-	#1-18"	18	18	Fair	Overhanging	Less than 25%	Less than 25%	-	-
1E14-102534D	<i>Juniperus osteosperma</i>	Utah juniper	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E14-103232A	<i>Juniperus osteosperma</i>	Utah juniper	20	30	12	-	#1-7"x12	7	7	Fair	Inside	100%	100%	-	-
1E14-103315D	<i>Juniperus osteosperma</i>	Utah juniper	0	10	6	-	#1-4"x6	4	4	Good	Overhanging	Less than 25%	Less than 25%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E14-111459C	<i>Juniperus osteosperma</i>	Utah juniper	20	30	2	-	#1-18", #2-10"	10	18	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E14-140811C	<i>Juniperus osteosperma</i>	Utah juniper	0	10	2	-	#1-10"x2	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E15-091422C	<i>Juniperus osteosperma</i>	Utah juniper	10	20	4	-	#1-10", #2-7"x3	10	7	Good	Inside	100%	100%	Previously pruned	-
1E16-112547C	<i>Juniperus osteosperma</i>	Utah juniper	0	10	4	-	#1-4"x4	4	4	Excellent	Inside	100%	100%	-	-
1E16-125158C	<i>Juniperus osteosperma</i>	Utah juniper	10	20	3	-	#1-7"x3	7	7	Good	Inside	100%	100%	-	-
1E16-125551C	<i>Juniperus osteosperma</i>	Utah juniper	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	Previously pruned	Topped.
1E16-131525C	<i>Juniperus osteosperma</i>	Utah juniper	10	20	5	-	#1-7"x5	7	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-131609A	<i>Juniperus osteosperma</i>	Utah juniper	10	20	5	-	#1-10"x3, #2-7"x2	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E17-121253A	<i>Juniperus osteosperma</i>	Utah juniper	0	10	1	-	#1-4"	4	4	Good	Inside	100%	100%	-	-
1E07-082819A	<i>Pinus flexilis</i>	Limber pine	20	30	2	-	#1-18", #2-18"	18	18	Good	Inside	100%	100%	-	-
1E07-083118D	<i>Pinus flexilis</i>	Limber pine	10	20	1	-	#1-42"	42	42	Good	Inside	100%	100%	-	-
1E07-083549A	<i>Pinus flexilis</i>	Limber pine	20	30	1	-	#1-30"	30	30	Good	Inside	100%	100%	-	-
1E07-084333D	<i>Pinus flexilis</i>	Limber pine	20	30	2	-	#1-18"x2	18	18	Good	Inside	100%	100%	-	-
1E07-085605B	<i>Pinus flexilis</i>	Limber pine	20	30	1	-	#1-7"	7	7	Good	Inside	100%	100%	Previously pruned	-
1E07-090537C	<i>Pinus flexilis</i>	Limber pine	30	40	2	-	#1-18"x2	18	18	Dead	Overhanging	Less than 25%	Less than 25%	Fire scars, previously pruned	-
1E07-090755A	<i>Pinus flexilis</i>	Limber pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E07-090920D	<i>Pinus flexilis</i>	Limber pine	10	20	6	-	#1-18", #2-7"x5	18	7	Fair	Inside	100%	100%	-	-
1E07-092219B	<i>Pinus flexilis</i>	Limber pine	30	40	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-092521A	<i>Pinus flexilis</i>	Limber pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E07-092835D	<i>Pinus flexilis</i>	Limber pine	30	40	1	-	#1-30"	30	30	Good	Inside	100%	100%	-	-
1E07-093147D	<i>Pinus flexilis</i>	Limber pine	0	10	1	-	#1-18"	18	18	Dead	Inside	--	--	-	-
1E07-094014D	<i>Pinus flexilis</i>	Limber pine	10	20	2	-	#1-4", #2-7"	4	7	Excellent	Inside	100%	100%	-	-
1E07-095052D	<i>Pinus flexilis</i>	Limber pine	20	30	1	-	#1-18"	18	18	Fair	Inside	100%	100%	-	Browning leaves
1E07-095548A	<i>Pinus flexilis</i>	Limber pine	20	30	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	-	-
1E07-100357B	<i>Pinus flexilis</i>	Limber pine	20	30	3	-	#1-7"x3	7	7	Good	Inside	100%	100%	-	-
1E07-100757B	<i>Pinus flexilis</i>	Limber pine	30	40	3	-	#1-10", #2-18"	10	18	Good	Inside	100%	100%	Fire scars, previously pruned	-
1E07-101933D	<i>Pinus flexilis</i>	Limber pine	30	40	1	-	#1-66"	66	66	Good	Inside	100%	100%	Previously pruned	-
1E07-102013C	<i>Pinus flexilis</i>	Limber pine	20	30	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E07-102850B	<i>Pinus flexilis</i>	Limber pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E07-105445A	<i>Pinus flexilis</i>	Limber pine	30	40	2	-	#1-30"x2	30	30	Good	Inside	100%	100%	-	-
1E07-110152C	<i>Pinus flexilis</i>	Limber pine	40	50	2	-	#1-18", #2-30"	18	30	Excellent	Inside	100%	100%	Previously pruned	-
1E07-110334A	<i>Pinus flexilis</i>	Limber pine	20	30	3	-	#1-4", #2-7"x2	4	7	Excellent	Inside	100%	100%	-	-
1E07-110447B	<i>Pinus flexilis</i>	Limber pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E07-110517C	<i>Pinus flexilis</i>	Limber pine	40	50	3	-	#1-18", #2-10"	10	18	Fair	Inside	100%	100%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E07-110651D	<i>Pinus flexilis</i>	Limber pine	20	30	1	-	#1-42"	42	42	Good	Overhanging	Less than 25%	Less than 25%	-	Fallen over
1E07-110754B	<i>Pinus flexilis</i>	Limber pine	30	40	2	-	#1-18"x2	18	18	Good	Inside	100%	100%	-	-
1E07-110800A	<i>Pinus flexilis</i>	Limber pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E07-110924D	<i>Pinus flexilis</i>	Limber pine	20	30	3	-	#1-18"x3	18	18	Good	Inside	100%	100%	-	-
															Downslope trunk cut at 15' above the ground surface. Trunks are splitting away from each other at base, metal eye inserted into up slope trunk.
1E07-110933C	<i>Pinus flexilis</i>	Limber pine	40	50	2	-	#1-30"x2	30	30	Poor	Inside	100%	100%	Previously pruned	
1E07-111044A	<i>Pinus flexilis</i>	Limber pine	30	40	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	-
1E07-111056B	<i>Pinus flexilis</i>	Limber pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E07-111319B	<i>Pinus flexilis</i>	Limber pine	30	40	1	-	#1-54"	54	54	Good	Inside	100%	100%	Fire scars, previously pruned	-
1E07-111325D	<i>Pinus flexilis</i>	Limber pine	10	20	3	-	#1-7", #2-10"x2	10	7	Excellent	Inside	100%	100%	-	-
1E07-111529C	<i>Pinus flexilis</i>	Limber pine	40	50	2	-	#1-30", #2-18"	18	30	Fair	Overhanging	Less than 25%	Less than 25%	Fire scars, previously pruned	-
1E07-111605D	<i>Pinus flexilis</i>	Limber pine	30	40	2	-	#1-30", #2-18"	18	30	Good	Inside	100%	100%	Previously pruned	-
1E07-111749D	<i>Pinus flexilis</i>	Limber pine	20	30	1	-	#1-8"	8	8	Excellent	Inside	100%	100%	-	-
1E07-111801A	<i>Pinus flexilis</i>	Limber pine	30	40	3	-	#1-7"x3	7	7	Good	Inside	100%	100%	-	-
1E07-111859C	<i>Pinus flexilis</i>	Limber pine	40	50	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E07-111913D	<i>Pinus flexilis</i>	Limber pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E07-112036D	<i>Pinus flexilis</i>	Limber pine	20	30	2	-	#1-10", #2-7"	10	7	Good	Inside	100%	100%	-	-
1E07-112211D	<i>Pinus flexilis</i>	Limber pine	30	40	2	-	#1-30", #2-10"	10	30	Good	Inside	100%	100%	Previously pruned	-
1E07-112215C	<i>Pinus flexilis</i>	Limber pine	40	50	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E07-112354C	<i>Pinus flexilis</i>	Limber pine	30	40	3	-	#1-10", #2-18"	10	18	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E07-112400D	<i>Pinus flexilis</i>	Limber pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E07-112643D	<i>Pinus flexilis</i>	Limber pine	30	40	3	-	#1-18"x2, #2-30"	18	30	Good	Inside	100%	100%	Previously pruned	-
1E07-112812B	<i>Pinus flexilis</i>	Limber pine	30	40	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	-	-
1E07-112900A	<i>Pinus flexilis</i>	Limber pine	30	40	2	-	#1-18", #2-30"	18	30	Good	Inside	100%	100%	-	-
1E07-113321B	<i>Pinus flexilis</i>	Limber pine	20	30	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E07-113510B	<i>Pinus flexilis</i>	Limber pine	20	30	3	-	#1-7"x3	7	7	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E09-085932A	<i>Pinus flexilis</i>	Limber pine	20	30	1	-	#1-30"	30	30	Dead	Inside	--	--	-	-
1E09-091229B	<i>Pinus flexilis</i>	Limber pine	20	30	1	-	#1-30"	30	30	Good	Inside	100%	100%	-	-
1E09-102242D	<i>Pinus flexilis</i>	Limber pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sali)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E09-102255C	<i>Pinus flexilis</i>	Limber pine	40	50	4	-	#1-18"x2, #2-10"x2	10	18	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	Pruning in upper canopy facing access road, top half of one trunk broken off. Appears to have been struck by lightning.
1E09-104955D	<i>Pinus flexilis</i>	Limber pine	10	20	1	-	#1-30"	30	30	Dead	Inside	--	--	-	-
1E09-112347A	<i>Pinus flexilis</i>	Limber pine	40	50	1	-	#1-10"	10	10	Fair	Inside	100%	100%	-	-
1E09-115035B	<i>Pinus flexilis</i>	Limber pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-104541D	<i>Pinus flexilis</i>	Limber pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E07-082739D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E07-083940B	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E07-090547D	<i>Pinus longaeva</i>	Bristlecone pine	40	50	4	-	#1-30", #2-18", #3-10", #4-7"	10	7	Good	Inside	100%	100%	-	-
1E07-091125B	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E07-091504B	<i>Pinus longaeva</i>	Bristlecone pine	0	10	2	-	#1-10", #2-7"	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-091956B	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E08-121816A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	-
1E08-131914A	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Fire scars	-
1E08-132219C	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Tree has been topped.
1E08-132416A	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Good	Special Case			Previously pruned	Tree has been topped
1E08-132731C	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E08-135954C	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E08-140410B	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E08-140550B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-30"	30	30	Fair	Inside	100%	100%	Fire scars	Top removed
1E09-084531D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E09-084644D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-18"x2	18	18	Good	Inside	100%	100%	Previously pruned	-
1E09-085117D	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top cut off
1E09-085243D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E09-085249B	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-42"	42	42	Good	Inside	100%	100%	Previously pruned	Tree top removed recently along with pruning
1E09-085617B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E09-085702D	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-30"	30	30	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E09-090009D	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-10"	10	10	Good	Overhanging	More than 25%	Less than 25%	-	-
1E09-090015B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E09-090210D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-090215C	<i>Pinus longaeva</i>	Bristlecone pine	40	50	3	-	#1-10", #2-7"	10	7	Excellent	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sali)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E09-090256A	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E09-090359D	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E09-090425B	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-30"	30	30	Good	Inside	100%	100%	-	-
1E09-090814D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	-	-
1E09-090821B	<i>Pinus longaeva</i>	Bristlecone pine	20	30	2	-	#1-10", #2-7"	10	7	Good	Inside	100%	100%	-	-
1E09-090828A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-30", #2-7"	30	7	Good	Inside	100%	100%	-	-
1E09-090956D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-091028A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-42"	42	42	Fair	Inside	100%	100%	Fire scars	-
1E09-091028A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-42"x2	42	42	Good	Inside	100%	100%	-	-
1E09-091651B	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-30"	30	30	Fair	Inside	100%	100%	Fire scars	-
1E09-091914B	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-54"	54	54	Fair	Inside	100%	100%	Fire scars	-
1E09-092213B	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-30"	30	30	Good	Inside	100%	100%	-	-
1E09-092311A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-54"	54	54	Excellent	Inside	100%	100%	-	-
1E09-092527B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-092600A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E09-092813B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-18"	18	18	Fair	Inside	100%	100%	-	-
1E09-092819A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-42"	42	42	Good	Inside	100%	100%	-	-
1E09-093130C	<i>Pinus longaeva</i>	Bristlecone pine	50	60	2	-	#1-18"x2	18	18	Excellent	Overhanging	More than 25%	More than 25%	Previously pruned	Pruning in upper canopy around 30-35' above the ground surface.
1E09-093138B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-18"	18	18	Fair	Inside	100%	100%	-	-
1E09-093358D	<i>Pinus longaeva</i>	Bristlecone pine	50	60	1	-	#1-30"	30	30	Good	Inside	100%	100%	-	-
1E09-093631D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-18"x2	18	18	Excellent	Inside	100%	100%	-	-
1E09-093738C	<i>Pinus longaeva</i>	Bristlecone pine	50	60	1	-	#1-30"	30	30	Good	Inside	100%	100%	Previously pruned	Pruning on uphill side facing existing pole.
1E09-093817B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-093828D	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-094022B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-30"	30	30	Poor	Inside	100%	100%	Fire scars	-
1E09-094146A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-30"x2	30	30	Excellent	Inside	100%	100%	-	-
1E09-094149D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-30"	30	30	Good	Inside	100%	100%	-	-
1E09-094251B	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-42"	42	42	Good	Inside	100%	100%	-	-
1E09-094324A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E09-094503A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Fair	Inside	100%	100%	-	-
1E09-094503A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-7"	7	7	Fair	Inside	100%	100%	-	-
1E09-094540B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E09-094727B	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-30"	30	30	Fair	Inside	100%	100%	Fire scars	-
1E09-094802C	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-10", #2-4"	10	4	Excellent	Inside	100%	100%	-	-
1E09-094824A	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-42"	42	42	Excellent	Inside	100%	100%	Previously pruned	-
1E09-094831D	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-094938A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E09-095025B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-095057D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-095209C	<i>Pinus longaeva</i>	Bristlecone pine	50	60	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	Previously pruned	Previous pruning along downslope side facing existing pole.
1E09-095215A	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E09-095238D	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-095423A	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E09-095700B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-18"	18	18	Fair	Inside	100%	100%	Fire scars	-
1E09-095752A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E09-095951D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-100246D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	3	-	#1-18"x3	18	18	Fair	Inside	100%	100%	-	-
1E09-100517D	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-100918B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Fire scars	-
1E09-101046D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-101252D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-101825D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-102420B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-18"	18	18	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	Recently pruned
1E09-102524D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-102749A	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-7"	7	7	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E09-102915D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	-	-
1E09-103216D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-103417D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-103514C	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Heavily prunes on downslope side facing wires.
1E09-103826D	<i>Pinus longaeva</i>	Bristlecone pine	10	20	2	-	#1-18", #2-4"	18	4	Excellent	Inside	100%	100%	-	-
1E09-104015D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	-
1E09-104136D	<i>Pinus longaeva</i>	Bristlecone pine	10	20	4	-	#1-4"x4	4	4	Excellent	Inside	100%	100%	-	-
1E09-104316D	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-30"	30	30	Excellent	Inside	100%	100%	Previously pruned	-
1E09-104419D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Fair	Inside	100%	100%	-	-
1E09-104654D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E09-104732C	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-30"	30	30	Good	Inside	100%	100%	Previously pruned	Heavily pruned on downslope side facing wires.
1E09-105105C	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Previous pruning on downslope side.
1E09-105148D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Dead	Inside	--	--	-	-
1E09-105501D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	3	-	#1-7"x3	7	7	Fair	Inside	100%	100%	-	-
1E09-105641B	<i>Pinus longaeva</i>	Bristlecone pine	20	30	2	-	#1-30", #2-18"	18	30	Fair	Inside	100%	100%	Previously pruned, Fire scars	Fallen over
1E09-105852A	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-7"	7	7	Fair	Inside	100%	100%	-	-
1E09-105906D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-110034A	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E09-110223B	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-30"	30	30	Good	Inside	100%	100%	-	-
1E09-110347B	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	-	-
1E09-110533D	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-110639B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E09-110708C	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Tre topped at ~30' above the ground surface.
1E09-110751D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-110815A	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-30"	30	30	Fair	Inside	100%	100%	Previously pruned	-
1E09-1111140A	<i>Pinus longaeva</i>	Bristlecone pine	40	50	2	-	#1-18"x2	18	18	Dead	Inside	--	--	Previously pruned	-
1E09-111150D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-111416C	<i>Pinus longaeva</i>	Bristlecone pine	50	60	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E09-111607A	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E09-111614C	<i>Pinus longaeva</i>	Bristlecone pine	50	60	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E09-111703B	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	Fire scars	-
1E09-111809A	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-18"	18	18	Fair	Inside	100%	100%	Previously pruned	-
1E09-111940C	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-7"	7	7	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E09-112010D	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-112146D	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-8"	8	8	Good	Inside	100%	100%	-	-
1E09-112416C	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-7"	7	7	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E09-112501D	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-112647B	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-54"	54	54	Good	Inside	100%	100%	Fire scars, previously pruned	-
1E09-112650A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-112802A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E09-112959B	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	Fire scars	-
1E09-113203C	<i>Pinus longaeva</i>	Bristlecone pine	60	70	1	-	#1-30"	30	30	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E09-113321B	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E09-113540D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	2	-	#1-10"x2	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E09-113617B	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E09-113711C	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-7"	7	7	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E09-113909B	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E09-114124C	<i>Pinus longaeva</i>	Bristlecone pine	50	60	1	-	#1-18"	18	18	Good	Overhanging	More than 25%	More than 25%	-	-
1E09-114134B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E09-114206D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	-	-
1E09-114350D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	-	-
1E09-114359B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E09-114519B	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-114528A	<i>Pinus longaeva</i>	Bristlecone pine	40	50	2	-	#1-18"x2	18	18	Good	Inside	100%	100%	-	-
1E09-114530C	<i>Pinus longaeva</i>	Bristlecone pine	50	60	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E09-114531D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-114651D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	2	-	#1-4", #2-7"	4	7	Good	Inside	100%	100%	-	-
1E09-114734B	<i>Pinus longaeva</i>	Bristlecone pine	30	40	3	-	#1-18", #2-7"x2	18	7	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E09-114745A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-114807D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Overhanging	More than 25%	Less than 25%	-	-
1E09-114917D	<i>Pinus longaeva</i>	Bristlecone pine	50	60	1	-	#1-18"	18	18	Fair	Inside	100%	100%	-	-
1E09-115019C	<i>Pinus longaeva</i>	Bristlecone pine	60	70	1	-	#1-30"	30	30	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E09-115044D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-115231D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-9"	9	9	Excellent	Inside	100%	100%	-	-
1E09-115345D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-115449D	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-30"	30	30	Good	Inside	100%	100%	Previously pruned	-
															Tree topped at 22' above the ground surface. Only one 8-12" trunk remains, other 5 cut off between 3-5' above the ground surface.
1E09-115455C	<i>Pinus longaeva</i>	Bristlecone pine	20	30	6	-	#1-10", #2-7"x4	10	7	Good	Inside	100%	100%	Previously pruned	
1E09-115620D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-8"	8	8	Good	Inside	100%	100%	-	-
1E09-115649A	<i>Pinus longaeva</i>	Bristlecone pine	40	50	2	-	#1-18"x2	18	18	Fair	Inside	100%	100%	Previously pruned	Topped
1E09-115736D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-115843D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E09-115906A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Fair	Inside	100%	100%	Previously pruned	Topped, possibly just broke off
1E09-115908B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	Previously pruned	Recently pruned
1E09-120011D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-120133D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-18"x2	18	18	Good	Inside	100%	100%	-	-
1E09-120220B	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E09-120336D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E09-120339B	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	Previously pruned	Recently pruned
1E09-120508D	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E09-120624D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E09-120706B	<i>Pinus longaeva</i>	Bristlecone pine	30	40	3	-	#1-18", #2-10"x2	10	18	Excellent	Inside	100%	100%	Previously pruned	Recently pruned branches
1E09-120718D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-120739A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E09-120857D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-18"	18	18	Fair	Inside	100%	100%	-	Broken at top
1E09-120953D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-121117A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	Topped
1E09-121117D	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-30"	30	30	Good	Inside	100%	100%	Previously pruned	-
1E09-121230B	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-30"	30	30	Good	Inside	100%	100%	-	Snapped trunk.
1E09-121243D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-121332C	<i>Pinus longaeva</i>	Bristlecone pine	50	60	1	-	#1-30"	30	30	Good	Overhanging	More than 25%	More than 25%	-	-
1E09-121358D	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sali)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E09-121406A	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	Topped
1E09-121504D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-121528A	<i>Pinus longaeva</i>	Bristlecone pine	40	50	3	-	#1-30"x3	30	30	Good	Overhanging	More than 25%	Less than 25%	Previously pruned	Has prune only tag
1E09-121542D	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-121657D	<i>Pinus longaeva</i>	Bristlecone pine	40	50	3	-	#1-18"x2, #2-10"	10	18	Good	Inside	100%	100%	-	-
1E09-121823D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	-	-
1E09-121910D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-121931C	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Tree topped at 35' above the ground surface.
1E09-122115B	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	
1E09-122355B	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	
1E09-122356D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-7"	7	7	Fair	Inside	100%	100%	-	
1E09-122632D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Fair	Inside	100%	100%	-	
1E09-122642C	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-42"	42	42	Excellent	Overhanging	More than 25%	More than 25%	-	-
1E09-122651B	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	-
1E09-122745A	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-30"	30	30	Excellent	Inside	100%	100%	-	-
1E09-122812D	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-122911D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-18"x2	18	18	Good	Inside	100%	100%	-	-
1E09-123013B	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E09-123051D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-18"x2	18	18	Good	Inside	100%	100%	-	-
1E09-123126A	<i>Pinus longaeva</i>	Bristlecone pine	50	60	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	-
1E09-123217D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Dead	Inside	--	--	-	-
1E09-123303D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-18"x2	18	18	Good	Inside	100%	100%	-	-
1E09-123312B	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	-
1E09-123359D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	Previously pruned	-
1E09-123519D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-123611C	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	Previously pruned	Tree topped at 20' above the ground surface. Pruning along down slope side.
1E09-123631D	<i>Pinus longaeva</i>	Bristlecone pine	40	50	3	-	#1-18"x3	18	18	Excellent	Inside	100%	100%	-	
1E09-123740D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	
1E09-123904D	<i>Pinus longaeva</i>	Bristlecone pine	10	20	1	-	#1-18"	18	18	Dead	Inside	--	--	-	
1E09-124015D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	
1E09-124156D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E09-124259D	<i>Pinus longaeva</i>	Bristlecone pine	10	20	4	-	#1-4"x4	4	4	Excellent	Inside	100%	100%	-	-
1E09-124430D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	Smallest trunk dead showing fire scarring.
1E09-124448C	<i>Pinus longaeva</i>	Bristlecone pine	40	50	3	-	#1-18"x2, #2-10"	10	18	Good	Inside	100%	100%	Fire scars	
1E09-124859D	<i>Pinus longaeva</i>	Bristlecone pine	40	50	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	
1E09-125043D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	2	-	#1-18", #2-10"	10	18	Good	Inside	100%	100%	-	
1E09-125201C	<i>Pinus longaeva</i>	Bristlecone pine	60	70	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	
1E09-125344D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	1	-	#1-10"	10	10	Fair	Inside	100%	100%	-	
1E09-125453D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	-	-
1E09-125549D	<i>Pinus longaeva</i>	Bristlecone pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E09-125650D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	3	-	#1-10"x3	10	10	Good	Inside	100%	100%	-	-
1E09-125814D	<i>Pinus longaeva</i>	Bristlecone pine	20	30	2	-	#1-18", #2-10"	10	18	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E15-093538A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	5	-	#1-4"x5	4	4	Poor	Inside	100%	100%	Previously pruned	-
1E05-073604B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	3	-	#1-18"x3	18	18	Good	Inside	100%	100%	-	-
1E05-075956D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	40	50	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E05-082111B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-4"	4	4	Good	Inside	100%	100%	-	-
1E05-082203D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E05-082510D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Overhanging	More than 25%	Less than 25%	-	-
1E05-093433C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-4"	4	4	Excellent	Inside	100%	100%	-	-
1E05-093512D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	6	-	#1-7", #2-10"x3	10	7	Good	Inside	100%	100%	-	-
1E05-094553C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-4"	4	4	Excellent	Inside	100%	100%	-	-
1E05-094757C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E05-095435D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-4", #2-7"	4	7	Dead	Inside	--	--	-	-
1E05-095904C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E05-100300B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E05-102324D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	4	-	#1-10"x3, #2-7"	10	7	Excellent	Inside	100%	100%	-	-
1E05-103614B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E05-103642C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	3	-	#1-18"x3	18	18	Good	Inside	100%	100%	-	-
1E05-103809B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E05-104108A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-7"	7	7	Good	Inside	100%	100%	Previously pruned	-
1E05-104324A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E05-105134A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	4	-	#1-10"x4	10	10	Good	Inside	100%	100%	Previously pruned	-
1E05-105444A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	3	-	#1-10"x3	10	10	Good	Overhanging	More than 25%	More than 25%	Previously pruned	-
1E05-110408A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-7", #2-4"	4	7	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E05-111156D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	5	-	#1-4"x5	4	4	Excellent	Inside	100%	100%	-	-
1E05-111348D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	4	-	#1-4"x4	4	4	Fair	Inside	100%	100%	-	-
1E05-111555A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E05-112243A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Fire scars	-
1E05-112415A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-30"	30	30	Good	Inside	100%	100%	Fire scars, previously pruned	-
1E05-113106A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-30"	30	30	Good	Inside	100%	100%	Fire scars	-
1E05-115411D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	5	-	#1-4", #2-7"x3	4	7	Poor	Inside	100%	100%	-	-
1E05-121214B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E05-135024D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	7	-	#1-4"x4, #2-7"x3	4	7	Dead	Inside	--	--	-	-
1E05-141441D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	6	-	#1-4"x6	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-160355A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	Fire scars	-
1E07-121042B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-
1E07-121409B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-
1E07-121415D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	10	-	#1-4"x10	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-121551A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	6	-	#1-4"x6	4	4	Excellent	Inside	100%	100%	-	-
1E07-123035B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	Appears to have been recently pruned

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/x)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in Inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E07-123057A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-7"x3	7	7	Excellent	Inside	100%	100%	-	-
1E07-123221A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E07-123345D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	7	-	#1-10"x2, #2-7"x3, #3-4"x2	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-123435C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	5	-	#1-4"x5	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-123439A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	10	-	#1-4"x10	4	4	Good	Inside	100%	100%	-	-
1E07-123640D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-4"x3	4	4	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-123758D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-10", #2-4"	10	4	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-123912C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7", #2-10"	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-124006A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	-	-
1E07-124114D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-4"x3	4	4	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-124131A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E07-124423C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-124447D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10", #2-4"	10	4	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	Very recently pruned
1E07-124646C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	5	-	#1-7", #2-4"x3	4	7	Good	Overhanging	Less than 25%	Less than 25%	Fire scars	-
1E07-124846B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E07-124848A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-7"x2, #2-4"x2	4	7	Good	Inside	100%	100%	Previously pruned	-
1E07-125027B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-125125A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-7"x4	7	7	Fair	Inside	100%	100%	-	-
1E07-125232D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	6	-	#1-4"x5, #2-7"	4	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-125330A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-4"x4	4	4	Poor	Inside	100%	100%	-	-
1E07-125535D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-10", #2-18"	10	18	Poor	Overhanging	Less than 25%	Less than 25%	-	-
1E07-125535D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	3	-	#1-10"x2, #2-7"	10	7	Fair	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E07-125537A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-7"x4	7	7	Good	Overhanging	Less than 25%	Less than 25%	Fire scars	-
1E07-125652C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E07-125938C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	8	-	#1-18", #2-10", #3-7"x4	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-130436D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	7	-	#1-10"x3, #2-7"x4	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-130644A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	10	-	#1-7"x2, #2-4"x8	4	7	Good	Inside	100%	100%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E07-130718C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-10", #2-4"x2	10	4	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	Damage to bark on road side.
1E07-130723B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-
1E07-130853D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-4", #2-10"	10	4	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-130857B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	-	Recently pruned on some branches
1E07-131207D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	3	-	#1-18", #2-4"x2	18	4	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-131339C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7", #2-4"	4	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-131606B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	-	-
1E07-131629A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-10", #2-7"	10	7	Good	Inside	100%	100%	-	-
1E07-131706C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-10", #2-7", #3-4"x2	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-131951B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	6	-	#1-4"x5, #2-7"	4	7	Good	Inside	100%	100%	-	Recently pruned
1E07-132443C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	5	-	#1-10", #2-4"x4	10	4	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-132458D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E07-132754D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E07-132915A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	3	-	#1-7"x3	7	7	Good	Inside	100%	100%	-	-
1E07-133005B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E07-133027D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-4", #2-7"	4	7	Good	Inside	100%	100%	-	-
1E07-133050A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	4	-	#1-7"x4	7	7	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E07-133127B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	Recently pruned
1E07-133217A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	3	-	#1-7", #2-4"x2	4	7	Good	Inside	100%	100%	-	Recently pruned
1E07-133326D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	5	-	#1-7", #2-4"x2	4	7	Good	Overhanging	Less than 25%	More than 25%	-	-
1E07-133610D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	6	-	#1-4", #2-10"x3	10	4	Good	Inside	100%	100%	Previously pruned	-
1E07-133800D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-133823C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	6	-	#1-18"x2, #2-10"	10	18	Good	Inside	100%	100%	-	-
1E07-134020D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	6	-	#1-4"x6	4	4	Good	Inside	100%	100%	-	-
1E07-134226B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-7"x4	7	7	Good	Inside	100%	100%	Previously pruned	-
1E07-134231D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	-	-
1E07-134233A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	13	-	#1-4"x13	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-134400A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	3	-	#1-10"x3	10	10	Good	Inside	100%	100%	-	-
1E07-134417B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	5	-	#1-7"x5	7	7	Good	Inside	100%	100%	Previously pruned	-
1E07-134428D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	4	-	#1-4", #2-7"	4	7	Good	Inside	100%	100%	-	-
1E07-134509C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	4	-	#1-4"x4	4	4	Excellent	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E07-134558B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-10", #2-7"x2	10	7	Good	Inside	100%	100%	Previously pruned	-
1E07-134608A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	4	-	#1-18"x4	18	18	Good	Inside	100%	100%	-	-
1E07-134626D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E07-134746D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	9	-	#1-7"x5, #2-18"x2, #3-10"	10	7	Good	Inside	100%	100%	Previously pruned	-
1E07-134754A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	4	-	#1-7"x3, #2-10"	10	7	Good	Inside	100%	100%	-	-
1E07-134754A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	6	-	#1-7"x3, #2-4"x3	4	7	Fair	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E07-134956B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E07-135034C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	13	-	#1-10", #2-7"x4, #3-4"x8	10	7	Good	Inside	100%	100%	-	-
1E07-135142D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E07-135159A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-7"x3	7	7	Fair	Inside	100%	100%	-	Recently pruned
1E07-135217B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	Recently pruned
1E07-135304D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7", #2-4"	4	7	Good	Inside	100%	100%	-	-
1E07-135353A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	5	-	#1-4"x3, #2-7"x2	4	7	Good	Inside	100%	100%	-	-
1E07-135432B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E07-135447D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E07-135512C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	5	-	#1-18", #2-10", #3-7"x3	10	7	Good	Inside	100%	100%	-	-
1E07-135554B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	Previously pruned	-
1E07-135604D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-7", #2-4"x3	4	7	Good	Overhanging	More than 25%	Less than 25%	-	-
1E07-135605A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E07-135721A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-7"x4	7	7	Fair	Inside	100%	100%	-	-
1E07-135822D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E07-135833B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10", #2-4"	10	4	Good	Inside	100%	100%	Previously pruned	-
1E07-135850A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Poor	Inside	100%	100%	-	-
1E07-135935D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	6	-	#1-10", #2-7"	10	7	Good	Inside	100%	100%	Previously pruned	-
1E07-140059A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-7"x4	7	7	Fair	Inside	100%	100%	-	-
1E07-140203D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	5	-	#1-7"x5	7	7	Good	Inside	100%	100%	-	-
1E07-140311C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	4	-	#1-10", #2-7"x3	10	7	Good	Inside	100%	100%	-	-
1E07-141321A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	4	-	#1-7"x2, #2-10"x2	10	7	Fair	Inside	100%	100%	-	Recently pruned
1E07-141358B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-
1E07-141511B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	One trunk was previously pruned
1E07-141519A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Recently pruned
1E07-141722B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-
1E07-141835A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-10", #2-4"	10	4	Good	Inside	100%	100%	Previously pruned	Recently pruned
1E07-142119C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-10", #2-4"	10	4	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	Recently pruned.

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E07-142349D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-10", #2-4"	10	4	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	Pruned very recently, sap fresh
1E07-142522D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	Pruned very recently
1E07-142725A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	Recently pruned-top
1E07-143145A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-4"x3	4	4	Fair	Inside	100%	100%	Previously pruned	Recently pruned
1E07-143250C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7", #2-4"	4	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-143420D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-143725B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	Recently pruned
1E07-143813A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	Recently pruned
1E07-144008C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	9	-	#1-18"x2, #2-10"x5, #3-7"x2	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-144040A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E07-144054D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-10", #2-18"	10	18	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-144225D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-18", #2-10"	10	18	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-144509D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	7	-	#1-18", #2-10"x2, #3-4"	10	4	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-145037D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-18", #2-30"	18	30	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-145209C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	3	-	#1-18", #2-10"	10	18	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-145302D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-42"	42	42	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-145558D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-18", #2-10"	10	18	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-150006D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	5	-	#1-18", #2-10", #3-4"x3	10	4	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-151138C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	9	-	#1-18", #2-10"x3, #3-7"x5	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-151426D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	Previously pruned	-
1E07-151718A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E07-151850A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E07-152124B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E07-152130A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-7"x3	7	7	Good	Inside	100%	100%	Previously pruned	-
1E07-152130A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	Previously pruned	-
1E07-152206C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	4	-	#1-18", #2-7"x3	18	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-152241B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	Recently pruned
1E07-152509B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	6	-	#1-10", #2-7"x5	10	7	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E07-152745A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Fair	Inside	100%	100%	-	Tree topped
1E07-153519D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-7", #2-4"	4	7	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-153637C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7", #2-4"	4	7	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E07-154003D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-154208D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-154539D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Dead	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-155429D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Fair	Overhanging	Less than 25%	Less than 25%	-	-
1E07-155627D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-30"	30	30	Dead	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-155639C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	9	-	#1-7", #2-4"x5	4	7	Excellent	Inside	100%	100%	-	-
1E07-155733D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-160023D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-160236D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Dead	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-160654C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-4", #2-7"	4	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-161258C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	3	-	#10", #2-7"x2	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E08-100703B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-18", #2-7"	18	7	Good	Inside	100%	100%	Previously pruned	Recently pruned
1E08-102958B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	10	-	#1-18"x3, #2-10"x7	10	18	Good	Inside	100%	100%	-	-
1E08-103044D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-18", #2-4"	18	4	Excellent	Overhanging	More than 25%	Less than 25%	-	-
1E08-103123A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E08-103420D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-10", #2-4"x2	10	4	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E08-103611B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E08-103909B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E08-104027A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E08-104047B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E08-104354A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Excellent	Inside	100%	100%	-	-
1E08-104358D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-7", #2-4"x2	4	7	Good	Inside	100%	100%	-	-
1E08-104614A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Excellent	Inside	100%	100%	-	-
1E08-111108B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top of tree removed. Recently pruned
1E08-111315B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top removed, recently pruned
1E08-112713D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	4	-	#1-7", #2-4"x3	4	7	Good	Inside	100%	100%	-	-
1E08-113443D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-7", #2-4"x2	4	7	Good	Inside	100%	100%	-	-
1E08-120015C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E08-121842B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	6	-	#1-18", #2-10"x2, #3-7"x3	10	7	Good	Inside	100%	100%	Previously pruned	-
1E08-122338C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	Previously pruned	Tree topped at 14' above the ground surface.
1E08-125335D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-10", #2-4"x2	10	4	Good	Inside	100%	100%	-	-
1E08-135405A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-4"x3	4	4	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E09-083737C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E09-084634C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E09-085809C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-7", #2-4"x3	4	7	Excellent	Inside	100%	100%	-	-
1E09-090602C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-10"x2	10	10	Excellent	Inside	100%	100%	Previously pruned	Tree topped when younger.
1E09-090940C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-7"x4	7	7	Excellent	Inside	100%	100%	-	-
1E09-113400D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	10	-	#1-4"x10	4	4	Good	Inside	100%	100%	-	-
1E10-092139D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Poor	Inside	100%	100%	-	Mistletoe infestation
1E10-092550C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E10-092615D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10", #2-18"	10	18	Excellent	Inside	100%	100%	Previously pruned	-
1E10-093110B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E10-093227D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-10", #2-4"x2	10	4	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E10-093401B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-7", #2-4"x2	4	7	Good	Inside	100%	100%	-	-
1E10-093429D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-18", #2-10"	10	18	Good	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E10-093454C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Dead	Inside	--	--	-	-
1E10-093728D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E10-093945C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Dead	Inside	--	--	-	-
1E10-095022C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E10-095336C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-095516C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E10-095552D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E10-095730D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E10-095835C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E10-100145C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E10-100417C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E10-101022C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E10-101157C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E10-101455C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E10-101519C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-101538A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-101543C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-101926A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-101958B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-30"	30	30	Good	Inside	100%	100%	-	-
1E10-102334A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-102352B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E10-102428A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-102530B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-102635A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-102712B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-102733A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-102836B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-102848A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-103006A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-103031B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-103104A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-103136B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-103228A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-103318B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-103402A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-103459B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-103523A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-103612B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-104111B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-7", #2-4"	4	7	Good	Inside	100%	100%	-	-
1E10-111813B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-10", #2-7"	10	7	Good	Inside	100%	100%	Previously pruned	Top of tree removed
1E10-111823C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E10-112039B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Top of tree removed
1E10-112141D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-112211B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-112330C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E10-112334B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-112557D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-4"x2	4	4	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E10-113925C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-113927D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	5	-	#1-4"x5	4	4	Good	Overhanging	More than 25%	Less than 25%	-	-
1E10-114144C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-114146D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E10-114652C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E10-114919D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	3	-	#1-18"x3	18	18	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E10-114919D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Fair	Overhanging	Less than 25%	Less than 25%	-	-
1E10-115309D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-4"x2	4	4	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E10-115447D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	5	-	#1-7"x2, #2-4"x3	4	7	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E10-122503B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E10-122746B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E10-122904B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-123027B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-123124B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-123220B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E10-123721A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	Topped
1E10-124238A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E10-124355B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top removed
1E10-124507D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-124521B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top removed
1E10-124555C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E10-124633A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E10-124716D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E10-124827C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E10-125314D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-125919C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E10-130138C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	Previously pruned	Pruned on E side facing tree.
1E10-130600D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-10", #2-7"x3	10	7	Poor	Inside	100%	100%	-	-
1E10-131312D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-131739C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-131754D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-132421D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-132434C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-132540A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-132557D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-132608B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E10-132742D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-132935B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Top removed
1E10-132943A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E10-133214A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Dead	Inside	--	--	-	-
1E10-133445C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E12-084934C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-085412D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E12-085452A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Topped
1E12-085514D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-7"x3	7	7	Good	Inside	100%	100%	Previously pruned	-
1E12-085633A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	Topped
1E12-085711B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	Previously pruned	-
1E12-085840A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-7"	7	7	Fair	Inside	100%	100%	Previously pruned	Topped
1E12-085846B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E12-090008D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-18", #2-10"x2	10	18	Good	Inside	100%	100%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E12-090011B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top removed
1E12-090020A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Topped
1E12-090745A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E12-090745D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Fair	Inside	100%	100%	-	-
1E12-090936A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E12-091032D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-8"	8	8	Excellent	Inside	100%	100%	-	-
1E12-092210B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E12-092233A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E12-092516D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E12-092646B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-30"	30	30	Good	Inside	100%	100%	Previously pruned	-
1E12-092656D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E12-092821B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E12-092924C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	Tree topped at 20' above the ground surface.
1E12-092950B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-10", #2-18"x2	10	18	Good	Inside	100%	100%	Previously pruned	-
1E12-093046A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-7", #2-4"	4	7	Good	Inside	100%	100%	-	-
1E12-093116B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Recently pruned
1E12-093219D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E12-093230B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E12-093248C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	Tree topped at 20' above the ground surface. 1
1E12-093458C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-093522B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E12-093631B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Recently pruned
1E12-093650A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Topped
1E12-093651C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	Tree topped at 11' above the ground surface.
1E12-093743B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E12-093747D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E12-093858B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E12-094117A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Overhanging	More than 25%	Less than 25%	-	-
1E12-094209B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E12-094433B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top removed

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E12-094440D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10"x2	10	10	Good	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E12-094538B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	Top removed
1E12-094651B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Top removed
1E12-094757B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-7", #2-4"	4	7	Good	Inside	100%	100%	Previously pruned	Top removed
1E12-094807D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E12-095233B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-10", #2-7"	10	7	Good	Inside	100%	100%	Previously pruned	Top removed
1E12-095236D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-8"	8	8	Good	Inside	100%	100%	-	-
1E12-095250A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	4	-	#1-10", #2-7", #3-4"x2	10	7	Excellent	Inside	100%	100%	-	-
1E12-095341D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E12-095451D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-18", #2-4"x2	18	4	Good	Inside	100%	100%	-	-
1E12-095543A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E12-101749D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E12-102041B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E12-102115A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E12-102203B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E12-102328B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-18"x2	18	18	Good	Inside	100%	100%	Previously pruned	-
1E12-102528A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E12-102539D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-8"	8	8	Excellent	Inside	100%	100%	-	-
1E12-102541B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E12-102652B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E12-102657A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E12-102820A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E12-102855B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E12-103033B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E12-103036D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-
1E12-103119A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E12-103131A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E12-103141A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E12-103142D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E12-103153A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E12-103212A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E12-103229B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	Previously pruned	-
1E12-103419B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E12-103425D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-
1E12-103643B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E12-103729D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E12-103743B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-
1E12-103849D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E12-104030D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E12-104223D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-4", #2-7"	4	7	Good	Inside	100%	100%	-	-
1E12-104308A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E12-104454D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-8"	8	8	Good	Inside	100%	100%	-	-
1E12-104511A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	3	-	#1-7"x3	7	7	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E12-104626D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-7", #2-4"x2	4	7	Good	Inside	100%	100%	-	-
1E12-104656A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E12-104734D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-18", #2-7"	18	7	Good	Inside	100%	100%	-	-
1E12-104848A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	-
1E12-104947A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E12-105204A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	Topped
1E12-105240D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-8"	8	8	Good	Inside	100%	100%	-	-
1E12-105347D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E12-105424A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-4"	4	4	Good	Inside	100%	100%	-	-
1E12-105452D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E12-105642D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E12-105809D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E12-110122C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-110458D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E12-110520C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Dead	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-110633D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-8"	8	8	Good	Inside	100%	100%	-	-
1E12-111109D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E12-112614A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E12-112851B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	Previously pruned	-
1E12-113156A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Topped
1E12-113256D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E12-113422A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E12-113835D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Dead	Inside	--	--	Previously pruned	-
1E12-120736A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	Previously pruned	Topped
1E12-120744D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E12-121030A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E12-121252D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E13-091453A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	Severely topped
1E13-092649B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E13-092809C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E13-092936D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E13-093017C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-18", #2-10"	10	18	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E13-094721C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E13-094947C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E13-095129A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10", #2-7"	10	7	Good	Inside	100%	100%	-	-
1E13-095702B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E13-100156D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10", #2-4"	10	4	Excellent	Inside	100%	100%	-	-
1E13-100310D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	Previously pruned	-
1E13-100400D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	Heavily pruned
1E13-100728A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10", #2-7"	10	7	Good	Inside	100%	100%	-	-
1E13-101132D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E13-101555B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E13-101743B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E13-101823D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E13-102010D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-18"	18	18	Fair	Inside	100%	100%	Previously pruned	-
1E13-102147B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E13-102328D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-8"	8	8	Good	Inside	100%	100%	-	-
1E13-102423D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E13-102429B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-18", #2-7"	18	7	Good	Inside	100%	100%	-	-
1E13-102631B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E13-102733B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E13-102852B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E13-102949B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E13-103153B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E13-103544B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E13-103700A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-7", #2-4"x3	4	7	Good	Inside	100%	100%	-	-
1E13-103906B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E13-103948A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-10", #2-7"x2	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E13-104141B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-7"x3	7	7	Excellent	Inside	100%	100%	-	-
1E13-104936B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E13-104949A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	Previously pruned	-
1E13-105210B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E13-114702A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	1	-	#1-18"	18	18	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E13-114725B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E13-114837B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top removed
1E13-114949B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Top removed
1E13-114955A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E13-115122A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10", #2-7"	10	7	Fair	Inside	100%	100%	Previously pruned	-
1E13-115149B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	Top removed
1E13-115710A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-30"	30	30	Fair	Inside	100%	100%	Previously pruned	Topped
1E13-115923B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Poor	Inside	100%	100%	-	-
1E13-115953A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-7"	7	7	Fair	Inside	100%	100%	Previously pruned	-
1E13-120046B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E13-120258B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10", #2-4"	10	4	Good	Inside	100%	100%	-	-
1E13-120508B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E13-120549A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-7"x3	7	7	Fair	Inside	100%	100%	Previously pruned	Severely pruned
1E13-120735B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E13-121009B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E13-121245B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E13-121559B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	Previously pruned	-
1E13-121809A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	1	-	#1-42"	42	42	Good	Inside	100%	100%	Previously pruned	-
1E13-122202A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-7"	7	7	Fair	Inside	100%	100%	-	-
1E13-122253B	<i>Pinus monophylla</i>	Other	0	10	1	-	#1-18"	18	18	Dead	Inside	--	--	Previously pruned	Dead
1E13-123428B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/x)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in Inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E13-123518A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-7"x2	7	7	Fair	Inside	100%	100%	Previously pruned	-
1E13-124254B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10", #2-7"	10	7	Good	Inside	100%	100%	-	-
1E13-124256A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	40	50	3	-	#1-30", #2-10"x2	10	30	Good	Inside	100%	100%	Previously pruned	-
1E13-124741B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top removed
1E13-124851A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-7"	7	7	Fair	Inside	100%	100%	Previously pruned	-
1E13-125038B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E13-125118A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	1	-	#1-18"	18	18	Good	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E14-093238D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E14-093431A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E14-093452D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top cut off
1E14-093522B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-093602D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top cut off
1E14-093608A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Fair	Inside	100%	100%	-	-
1E14-093706D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	Heavily pruned and topped
1E14-093832B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-093941D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Topped
1E14-094109D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-18"	18	18	Fair	Inside	100%	100%	Previously pruned	Top cut off
1E14-094306B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-094327C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-094400D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E14-094508D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E14-094558C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-094619B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-094648A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	Topped
1E14-094745B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-10", #2-7"x2	10	7	Good	Inside	100%	100%	-	-
1E14-094759C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-095050B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E14-095210D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E14-095233C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-095346D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E14-095346D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E14-095453D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E14-095745D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E14-095745D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E14-095745D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E14-095810A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Fair	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E14-095837D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E14-100101D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-8"	8	8	Poor	Inside	100%	100%	Previously pruned	Whole top cut off
1E14-100350D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7", #2-10"	10	7	Good	Inside	100%	100%	Previously pruned	-
1E14-100523B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-100722B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E14-100748A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	-
1E14-101034D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-101038B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-101052A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-101152A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E14-101217B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10", #2-7"	10	7	Good	Inside	100%	100%	-	-
1E14-101252D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-101333B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E14-101416C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	10	-	#1-18", #2-10", #3-7", #4-4"x3	10	7	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-101449B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-101534A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Fair	Inside	100%	100%	Previously pruned	-
1E14-102124C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-102311C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	4	-	#1-18"x2, #2-10", #3-7"	10	7	Excellent	Overhanging	More than 25%	More than 25%	Previously pruned	-
1E14-102443D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-18"	18	18	Dead	Inside	--	--	-	-
1E14-102553A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	5	-	#1-7"x5	7	7	Fair	Inside	100%	100%	-	-
1E14-102858C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E14-102946A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	-
1E14-102954B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E14-103052D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-103106C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E14-103155D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E14-103328B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	Recently pruned
1E14-103458A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Fair	Inside	100%	100%	-	-
1E14-103606B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-7"x3	7	7	Good	Inside	100%	100%	Previously pruned	Recently pruned
1E14-103713A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/x)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E14-103949B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-103955D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-8"	8	8	Fair	Inside	100%	100%	Previously pruned	Completely topped
1E14-104015A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	-
1E14-104128D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	-
1E14-104230D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-104236A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-104246C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E14-104400A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-104450C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-104558A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	-
1E14-104558A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	-
1E14-104646C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E14-104720A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-104850A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Dead	Inside	--	--	-	-
1E14-104859C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E14-105034C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-105428C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	8	-	#1-18", #2-7", #3-10"	10	7	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E14-105512D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Overhanging	More than 25%	Less than 25%	Previously pruned	Topped
1E14-105609B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	Top appears to have been removed
1E14-105645D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E14-105742C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-105937C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-110009D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E14-110107C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-110128D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-18", #2-7", #3-10"	10	7	Good	Inside	100%	100%	Previously pruned	-
1E14-110308C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	2	-	#1-18", #2-10"	10	18	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-110405D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Fair	Overhanging	Less than 25%	Less than 25%	-	-
1E14-110536C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-110545D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-8"	8	8	Dead	Inside	--	--	-	-
1E14-110657D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Overhanging	More than 25%	Less than 25%	-	-
1E14-111115A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	Severely topped

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E14-111121C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	30	40	1	-	#1-18"	18	18	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-111141B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E14-111240D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E14-111301A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E14-112943C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E14-113111C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E14-113400C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E14-135737B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10", #2-7"	10	7	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-135745D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-30"	30	30	Dead	Inside	--	--	Previously pruned	-
1E14-135822A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Fair	Inside	100%	100%	Previously pruned	-
1E14-135834C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E14-135901D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-
1E14-140008A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10"x2	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E14-140024B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	Previously pruned	-
1E14-140029D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-18"x2	18	18	Good	Inside	100%	100%	-	-
1E14-140128C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E14-140140A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-10"x2, #2-18"	10	18	Fair	Inside	100%	100%	Previously pruned	-
1E14-140218D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-30", #2-10"	10	30	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E14-140300B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	5	-	#1-7", #2-4"x4	4	7	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-140341A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-7"x2, #2-10"x2	10	7	Fair	Inside	100%	100%	Previously pruned	-
1E14-140355D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E14-140355D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E14-140404C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-140454B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-140527D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-140601B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-140627A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10"x2	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E14-140700B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-140713D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E14-140803B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-141016B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-141135C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	Tree topped at 10' above the ground surface.
1E14-141428A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLLR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E14-141456D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	-	-
1E14-141507B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-141521C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E14-141641B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-141725A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-141745A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E14-141805B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-141806A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E14-143300A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	7	-	#1-7"x4, #2-10"x3	10	7	Good	Inside	100%	100%	Previously pruned	-
1E14-143300A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	7	-	#1-7"x4, #2-10"x3	10	7	Good	Inside	100%	100%	Previously pruned	-
1E14-143613A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	Previously pruned	-
1E14-143647D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10", #2-7"	10	7	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E14-143801B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E14-143854D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-18", #2-7"	18	7	Good	Inside	100%	100%	-	-
1E14-143903A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-7"x3	7	7	Fair	Inside	100%	100%	Previously pruned	Topped
1E14-143932B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	-	-
1E14-144010C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E14-144022A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-7"	7	7	Fair	Inside	100%	100%	Previously pruned	-
1E14-144025D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E14-144131B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	4	-	#1-7"x4	7	7	Good	Inside	100%	100%	Previously pruned	Top removed
1E14-144139A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E14-144216D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E14-144312C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E14-144327D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E14-144332A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-10"x2	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E14-144358B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-144421D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E14-144528B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10", #2-7"	10	7	Good	Inside	100%	100%	-	-
1E15-084333A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E15-084407C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	Previously pruned	-
1E15-084430B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Dead	Inside	--	--	-	-
1E15-084456D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E15-084530A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-084548D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E15-084637B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Dead	Inside	--	--	Previously pruned	Top removed
1E15-084718A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Fair	Inside	100%	100%	-	-
1E15-084851B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top removed
1E15-084940A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Fair	Inside	100%	100%	-	-
1E15-085131B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E15-085318A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E15-085452D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E15-085554D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E15-085708D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	Previously pruned	-
1E15-085809D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-
1E15-085926C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-10", #2-4"x2	10	4	Good	Inside	100%	100%	Previously pruned	Tree topped at 7' above the ground surface.
1E15-090256C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-10", #2-7"x2	10	7	Good	Inside	100%	100%	Previously pruned	Tree topped at 9' above the ground surface.
1E15-090348D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-4"	4	4	Good	Inside	100%	100%	-	-
1E15-090618C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Dead	Inside	--	--	Previously pruned	Tree topped at 11' above the ground surface. Another directly adjacent to same height, DBH 3" also dead.
1E15-090927C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Dead	Inside	--	--	-	-
1E15-091053A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	3	-	#1-7"x3	7	7	Fair	Inside	100%	100%	Previously pruned	Topped
1E15-091348A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Fair	Inside	100%	100%	Previously pruned	-
1E15-091650B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Dead	Inside	--	--	-	-
1E15-091938B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10", #2-7"	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-092823D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Overhanging	More than 25%	Less than 25%	-	-
1E15-092842B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Recently pruned
1E15-092856C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-10"x3	10	10	Dead	Inside	--	--	Previously pruned	Tree topped at 12' above the ground surface.
1E15-092943A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Poor	Inside	100%	100%	Previously pruned	-
1E15-093056B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Overhanging	Less than 25%	Less than 25%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E15-093117D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-4", #2-7"	4	7	Good	Inside	100%	100%	-	-
1E15-093241D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-18"	18	18	Dead	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E15-093403B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	Top removed
1E15-093431D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-18"	18	18	Dead	Inside	--	--	Previously pruned	-
1E15-093619B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E15-093639C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-10"x3	10	10	Good	Inside	100%	100%	Previously pruned	Tree topped at 14' above the ground surface.
1E15-093725D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E15-093926C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E15-093928B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	Top removed
1E15-094036B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	3	-	#1-7", #2-4"x2	4	7	Good	Inside	100%	100%	Previously pruned	Top removed
1E15-094629B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	Previously pruned	-
1E15-094904A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-7"	7	7	Poor	Inside	100%	100%	Previously pruned	Topped
1E15-095023A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-7", #2-10"	10	7	Fair	Inside	100%	100%	Previously pruned	Topped
1E15-095158D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7", #2-10"	10	7	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E15-095351A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Poor	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E15-095426B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-30", #2-7"x2	30	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-100232D	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	3	-	#1-7", #2-10"	10	7	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E15-100313C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-100723A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-100938A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Dead	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-101110A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	5	-	#1-4"x5	4	4	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-101300A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-10"x2	10	10	Dead	Inside	--	--	Previously pruned	-
1E15-101607A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	6	-	#1-7"x6	7	7	Poor	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-101623B	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E15-101841A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	4	-	#1-4"x4	4	4	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-113159A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Poor	Inside	100%	100%	Previously pruned	-
1E16-113632A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Poor	Inside	100%	100%	Previously pruned	Topped
1E16-114007A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Poor	Inside	100%	100%	Previously pruned	Topped

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/k)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E16-114322C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Fair	Inside	100%	100%	Previously pruned	-
1E16-114546C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Fair	Inside	100%	100%	-	-
1E16-115504A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Fair	Inside	100%	100%	-	-
1E16-120940A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E16-121211C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Fair	Inside	100%	100%	-	-
1E16-121302A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E16-121505C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-4", #2-4"	4	4	Fair	Inside	100%	100%	-	-
1E16-121720C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Fair	Inside	100%	100%	-	-
1E16-124947A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Fair	Inside	100%	100%	-	-
1E16-125044A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E16-125255A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E16-130511C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-130658A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Fair	Overhanging	Less than 25%	Less than 25%	-	-
1E16-130955C	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	3	-	#1-10", #2-7"x2	10	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-131001A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-131514A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
ADD-105533A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
ADD-105944	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	-	-
ADD-110630	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	-	-
ADD-110755	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Overhanging	Less than 25%	Less than 25%	-	-
ADD-111533A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Overhanging	More than 25%	Less than 25%	-	-
ADD-111913A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
ADD-112442A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	-	-
ADD-113232A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	-	-
ADD-113424A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Overhanging	Less than 25%	Less than 25%	-	-
ADD-113950A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-7"	7	7	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
ADD-114432A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
ADD-115729A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	0	10	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	extensively pruned and topped
ADD-121239A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
ADD-121438A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
ADD-131943A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
ADD-132525A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
ADD-132815A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	20	30	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
ADD-145755A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#2-7"x2	7	7	Good	Overhanging	Less than 25%	Less than 25%	-	-
ADD-160920A	<i>Pinus monophylla</i>	Singleleaf pinyon pine	10	20	2	-	#1-7"x2	7	7	Good	Inside	100%	100%	-	-
1E09-111155B	<i>Pinus species</i>	Unknown pine	20	30	1	-	#1-18"	18	18	Dead	Inside	--	--	-	-
1E15-094844B	<i>Pinus species</i>	Unknown pine	10	20	2	-	#1-10", #2-7"	10	7	Dead	Inside	--	--	Previously pruned	-
1E01-122054A	<i>Populus fremontii</i>	Fremont cottonwood	10	20	1	-	#1-10"	10	10	Good	Overhanging	More than 25%	Less than 25%	-	-
1E01-143502A	<i>Populus fremontii</i>	Fremont cottonwood	20	30	4	-	#1-7", #2-4"x2	4	7	Excellent	Inside	100%	100%	-	-
1E01-145040A	<i>Populus fremontii</i>	Fremont cottonwood	40	50	2	-	#1-42"x2	42	42	Excellent	Inside	100%	100%	Previously pruned	-
1E01-145105D	<i>Populus fremontii</i>	Fremont cottonwood	40	50	2	-	#2-54"x2	54	54	Good	Inside	100%	100%	Previously pruned	-
1E01-145439A	<i>Populus fremontii</i>	Fremont cottonwood	20	30	1	-	#1-30"	30	30	Dead	Inside	--	--	Previously pruned	-
1E01-150927D	<i>Populus fremontii</i>	Fremont cottonwood	10	20	3	-	#1-7", #2-4"	4	7	Good	Inside	100%	100%	Previously pruned	-
1E01-150941A	<i>Populus fremontii</i>	Fremont cottonwood	30	40	4	-	#1-18"x3, #2-10"	10	18	Fair	Inside	100%	100%	Previously pruned	-
1E01-151204D	<i>Populus fremontii</i>	Fremont cottonwood	30	40	1	-	#1-30"	30	30	Good	Inside	100%	100%	-	Some dieback near bottom
1E01-151433D	<i>Populus fremontii</i>	Fremont cottonwood	40	50	1	-	#1-42"	42	42	Good	Inside	100%	100%	-	-
1E01-151827D	<i>Populus fremontii</i>	Fremont cottonwood	20	30	2	-	#1-7", #2-18"	18	7	Fair	Inside	100%	100%	-	-
1E01-151846A	<i>Populus fremontii</i>	Fremont cottonwood	30	40	1	-	#1-42"	42	42	Good	Inside	100%	100%	Previously pruned	-
1E01-152212D	<i>Populus fremontii</i>	Fremont cottonwood	30	40	1	-	#1-30"	30	30	Good	Inside	100%	100%	-	-
1E01-152234A	<i>Populus fremontii</i>	Fremont cottonwood	40	50	1	-	#1-30"	30	30	Good	Inside	100%	100%	-	-
1E01-152514D	<i>Populus fremontii</i>	Fremont cottonwood	30	40	2	-	#2-54", #2-18"	18	54	Good	Inside	100%	100%	-	-
1E02-080335D	<i>Populus fremontii</i>	Fremont cottonwood	10	20	1	-	#1-10"	10	10	Fair	Inside	100%	100%	-	-
1E02-080626D	<i>Populus fremontii</i>	Fremont cottonwood	20	30	3	-	#1-10"x2, #2-7"	10	7	Good	Inside	100%	100%	Previously pruned	-
1E02-080634B	<i>Populus fremontii</i>	Fremont cottonwood	20	30	7	-	#1-10"x4, #2-4"x3	10	4	Good	Inside	100%	100%	Previously pruned	Center of tree has been previously pruned
1E02-080910D	<i>Populus fremontii</i>	Fremont cottonwood	0	10	1	-	#1-30"	30	30	Poor	Inside	100%	100%	Previously pruned	Trunk hollow
1E02-081001C	<i>Populus fremontii</i>	Fremont cottonwood	20	30	5	-	#1-7"x2, #2-18", #3-18", #4-10"	10	7	Good	Inside	100%	100%	Previously pruned	-
1E02-081027D	<i>Populus fremontii</i>	Fremont cottonwood	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E02-081151D	<i>Populus fremontii</i>	Fremont cottonwood	10	20	1	-	#1-30"	30	30	Poor	Inside	100%	100%	Previously pruned	Hollow trunk
1E02-081343D	<i>Populus fremontii</i>	Fremont cottonwood	10	20	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E02-081527A	<i>Populus fremontii</i>	Fremont cottonwood	10	20	1	-	#1-10"	10	10	Fair	Inside	100%	100%	Previously pruned	-
1E02-081757D	<i>Populus fremontii</i>	Fremont cottonwood	20	30	2	-	#1-7", #2-10"	10	7	Fair	Inside	100%	100%	-	-
1E02-081955D	<i>Populus fremontii</i>	Fremont cottonwood	0	10	1	-	#1-30"	30	30	Dead	Inside	--	--	Previously pruned	Hollow stem

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in Inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E02-082125D	<i>Populus fremontii</i>	Fremont cottonwood	20	30	2	-	#1-7", #2-30"	30	7	Fair	Inside	100%	100%	Previously pruned	-
1E02-082229B	<i>Populus fremontii</i>	Fremont cottonwood	20	30	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E02-082307D	<i>Populus fremontii</i>	Fremont cottonwood	20	30	2	-	#1-10", #2-30"	10	30	Fair	Inside	100%	100%	Previously pruned	
1E02-082504D	<i>Populus fremontii</i>	Fremont cottonwood	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E02-082837C	<i>Populus fremontii</i>	Fremont cottonwood	20	30	6	-	#1-7", #2-10", #3-4", #4-18", #5-7"	10	7	Good	Inside	100%	100%	Previously pruned	Heavy pruning down to 5' above the ground surface, 3 of trunks measured pruned to 6' above the ground surface and are dead.
1E02-090242D	<i>Populus fremontii</i>	Fremont cottonwood	30	40	1	-	#1-30"	30	30	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E02-090855B	<i>Populus fremontii</i>	Fremont cottonwood	30	40	3	-	#1-54", #2-10"	10	54	Good	Inside	100%	100%	-	None
1E02-090920A	<i>Populus fremontii</i>	Fremont cottonwood	20	30	1	-	#1-66"	66	66	Good	Overhanging	More than 25%	Less than 25%	Previously pruned	Has 'prune only sign attached
1E02-091049C	<i>Populus fremontii</i>	Fremont cottonwood	30	40	3	-	#1-102", #2-18", #3-42"	102	42	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E02-095849C	<i>Populus fremontii</i>	Fremont cottonwood	40	50	4	-	#1-30"x2, #2-18", #3-10"	10	30	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E02-114329A	<i>Populus fremontii</i>	Fremont cottonwood	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	
1E02-114417B	<i>Populus fremontii</i>	Fremont cottonwood	40	50	1	-	#1-54"	54	54	Excellent	Inside	100%	100%	-	None
1E02-114719B	<i>Populus fremontii</i>	Fremont cottonwood	40	50	1	-	#1-66"	66	66	Good	Inside	100%	100%	-	One trunk broken off
1E02-114821A	<i>Populus fremontii</i>	Fremont cottonwood	10	20	3	-	#1-18"x3	18	18	Good	Inside	100%	100%	-	One trunk has broken off
1E02-121811D	<i>Populus fremontii</i>	Fremont cottonwood	40	50	1	-	#1-54"	54	54	Excellent	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E02-122129D	<i>Populus fremontii</i>	Fremont cottonwood	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E02-122306D	<i>Populus fremontii</i>	Fremont cottonwood	30	40	1	-	#1-42"	42	42	Good	Inside	100%	100%	Previously pruned	-
1E02-122848D	<i>Populus fremontii</i>	Fremont cottonwood	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E02-123137D	<i>Populus fremontii</i>	Fremont cottonwood	30	40	1	-	#1-66"	66	66	Excellent	Inside	100%	100%	-	-
1E02-123443D	<i>Populus fremontii</i>	Fremont cottonwood	20	30	5	-	#1-4", #2-7", #3-18", #4-30"	18	7	Excellent	Inside	100%	100%	Previously pruned	-
1E02-123758D	<i>Populus fremontii</i>	Fremont cottonwood	20	30	4	-	#1-18"x4	18	18	Good	Inside	100%	100%	Previously pruned	-
1E02-124025D	<i>Populus fremontii</i>	Fremont cottonwood	0	10	4	-	#1-4"x3, #2-7"	4	7	Good	Inside	100%	100%	Previously pruned	-
1E02-124212D	<i>Populus fremontii</i>	Fremont cottonwood	10	20	1	-	#1-18"	18	18	Good	Inside	100%	100%	-	-
1E02-125719C	<i>Populus fremontii</i>	Fremont cottonwood	40	50	2	-	#1-10", #2-4"	10	4	Excellent	Inside	100%	100%	Previously pruned	-
1E02-130323B	<i>Populus fremontii</i>	Fremont cottonwood	10	20	1	-	#1-10"	10	10	Excellent	Inside	100%	100%	-	None
1E02-133953A	<i>Populus fremontii</i>	Fremont cottonwood	10	20	1	-	#1-18"	18	18	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E02-134311B	<i>Populus fremontii</i>	Fremont cottonwood	30	40	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	None
1E03-080059A	<i>Populus fremontii</i>	Fremont cottonwood	10	20	3	-	#1-7"x3	7	7	Fair	Inside	100%	100%	Previously pruned	Fallen over
1E03-085545D	<i>Populus fremontii</i>	Fremont cottonwood	20	30	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E03-101940A	<i>Populus fremontii</i>	Fremont cottonwood	50	60	1	-	#1-42"	42	42	Excellent	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E07-085901C	<i>Populus fremontii</i>	Fremont cottonwood	10	20	5	-	#1-4"x5	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E10-104747B	<i>Populus fremontii</i>	Fremont cottonwood	20	30	1	-	#1-18"	18	18	Good	Inside	100%	100%	Previously pruned	-
1E10-105147A	<i>Populus fremontii</i>	Fremont cottonwood	20	30	2	-	#1-7"x2	7	7	Fair	Inside	100%	100%	-	-
1E10-122417D	<i>Populus fremontii</i>	Fremont cottonwood	30	40	2	-	#1-18"x2	18	18	Fair	Overhanging	More than 25%	Less than 25%	-	-
1E10-131115C	<i>Populus fremontii</i>	Fremont cottonwood	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	Estimation by proxy.
1E10-133005D	<i>Populus fremontii</i>	Fremont cottonwood	10	20	2	-	#1-7", #2-18"	18	7	Excellent	Inside	100%	100%	-	-
1E12-121420A	<i>Populus fremontii</i>	Fremont cottonwood	30	40	1	-	#1-18"	18	18	Excellent	Inside	100%	100%	-	-
1E15-094902C	<i>Populus fremontii</i>	Fremont cottonwood	20	30	1	-	#1-7"	7	7	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E16-093514C	<i>Populus fremontii</i>	Fremont cottonwood	20	30	1	-	#1-7"	7	7	Excellent	Inside	100%	100%	-	-
1E16-131258C	<i>Populus fremontii</i>	Fremont cottonwood	10	20	1	-	#1-7"	7	7	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-082607B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-083112C	<i>Populus tremuloides</i>	Quaking aspen	10	20	1	-	#1-7"	7	7	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E07-083214B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-083324B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-083539B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-083648C	<i>Populus tremuloides</i>	Quaking aspen	10	20	2	-	#1-7"x2	7	7	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E07-084000C	<i>Populus tremuloides</i>	Quaking aspen	10	20	3	-	#1-4", #2-7"x2	4	7	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E07-084225C	<i>Populus tremuloides</i>	Quaking aspen	10	20	3	-	#1-4", #2-7"x2	4	7	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-084533C	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E07-084743C	<i>Populus tremuloides</i>	Quaking aspen	10	20	4	-	#1-4"x4	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E07-084938B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-
1E07-085011C	<i>Populus tremuloides</i>	Quaking aspen	10	20	3	-	#1-4"x3	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E07-085258A	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E07-085316D	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E07-085328C	<i>Populus tremuloides</i>	Quaking aspen	10	20	4	-	#1-4", #2-7"x2	4	7	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E07-085359B	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E07-085448A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Good	Overhanging	Less than 25%	Less than 25%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E07-085512D	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	-	-
1E07-085639C	<i>Populus tremuloides</i>	Quaking aspen	10	20	2	-	#1-4"x2	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E07-085650A	<i>Populus tremuloides</i>	Quaking aspen	0	10	15	-	#1-4"x15	4	4	Good	Inside	100%	100%	Previously pruned	Very close multiple trunks
1E07-085850D	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E07-085910B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-085914A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-090022B	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-090028A	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-090138A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	-	-
1E07-090143C	<i>Populus tremuloides</i>	Quaking aspen	10	20	2	-	#1-4"x2	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-090255B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-090319D	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E07-090332A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-7"x4	7	7	Good	Inside	100%	100%	-	-
1E07-090451B	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-090551B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-090627A	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-
1E07-090730B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-090824B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-090948B	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-091007A	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Fair	Inside	100%	100%	-	-
1E07-091214A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	-	-
1E07-091255C	<i>Populus tremuloides</i>	Quaking aspen	10	20	2	-	#1-4", #2-7"	4	7	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-091318A	<i>Populus tremuloides</i>	Quaking aspen	10	20	4	-	#1-4"x4	4	4	Poor	Inside	100%	100%	-	-
1E07-091429A	<i>Populus tremuloides</i>	Quaking aspen	0	10	5	-	#1-4"x5	4	4	Fair	Inside	100%	100%	-	-
1E07-091510D	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-2", #2-4"	2	4	Fair	Inside	100%	100%	-	-
1E07-091605A	<i>Populus tremuloides</i>	Quaking aspen	0	10	8	-	#1-4"x8	4	4	Fair	Inside	100%	100%	-	-
1E07-091634C	<i>Populus tremuloides</i>	Quaking aspen	10	20	4	-	#1-4"x4	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	Smallest 2 trunks pruned off at 3' above the ground surface.
1E07-091722A	<i>Populus tremuloides</i>	Quaking aspen	0	10	6	-	#1-4"x6	4	4	Fair	Inside	100%	100%	-	-
1E07-091722B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-091813A	<i>Populus tremuloides</i>	Quaking aspen	0	10	8	-	#1-4"x8	4	4	Fair	Inside	100%	100%	-	-
1E07-091939A	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Fair	Inside	100%	100%	-	-
1E07-092012C	<i>Populus tremuloides</i>	Quaking aspen	10	20	3	-	#1-4"x3	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-092106A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Poor	Inside	100%	100%	-	-
1E07-092208D	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-2", #2-4"	2	4	Good	Inside	100%	100%	-	-
1E07-092214C	<i>Populus tremuloides</i>	Quaking aspen	10	20	6	-	#1-4"x6	4	4	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	2 trunks dead.
1E07-092243A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Fair	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E07-092349A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Poor	Inside	100%	100%	-	-
1E07-092402D	<i>Populus tremuloides</i>	Quaking aspen	0	10	5	-	#1-2"x5	2	2	Good	Inside	100%	100%	-	-
1E07-092619C	<i>Populus tremuloides</i>	Quaking aspen	10	20	8	-	#1-4", #2-1-3"x6	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-092632D	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-2"x4	2	2	Fair	Inside	100%	100%	-	-
1E07-092720A	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Poor	Inside	100%	100%	-	-
1E07-092909B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-093052B	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-093057A	<i>Populus tremuloides</i>	Quaking aspen	0	10	6	-	#1-4"x6	4	4	Fair	Inside	100%	100%	-	-
1E07-093222A	<i>Populus tremuloides</i>	Quaking aspen	0	10	6	-	#1-4"x6	4	4	Good	Inside	100%	100%	-	-
1E07-093416A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	-	-
1E07-093501B	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Fair	Inside	100%	100%	Previously pruned	-
1E07-093546C	<i>Populus tremuloides</i>	Quaking aspen	10	20	4	-	#1-4", #2-4"x3	4	4	Excellent	Inside	100%	100%	Previously pruned	-
1E07-093747B	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Fair	Inside	100%	100%	Previously pruned	-
1E07-093912A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Fair	Inside	100%	100%	-	-
1E07-094018C	<i>Populus tremuloides</i>	Quaking aspen	10	20	4	-	#1-4", #2-<1"	4		Excellent	Inside	100%	100%	Previously pruned	One trunk prunes off at 3' above the ground surface.
1E07-094019A	<i>Populus tremuloides</i>	Quaking aspen	0	10	5	-	#1-4"x5	4	4	Fair	Inside	100%	100%	-	-
1E07-094021B	<i>Populus tremuloides</i>	Quaking aspen	0	10	1	-	#1-4"	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-094129A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Fair	Inside	100%	100%	-	-
1E07-094140B	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Fair	Inside	100%	100%	Previously pruned	-
1E07-094228A	<i>Populus tremuloides</i>	Quaking aspen	0	10	6	-	#1-4"x6	4	4	Fair	Inside	100%	100%	-	-
1E07-094357A	<i>Populus tremuloides</i>	Quaking aspen	0	10	7	-	#1-4"x7	4	4	Good	Inside	100%	100%	-	-
1E07-094439C	<i>Populus tremuloides</i>	Quaking aspen	10	20	3	-	#1-4"x3	4	4	Excellent	Inside	100%	100%	Previously pruned	-
1E07-094525A	<i>Populus tremuloides</i>	Quaking aspen	0	10	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E07-094627B	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Fair	Inside	100%	100%	-	-
1E07-094648A	<i>Populus tremuloides</i>	Quaking aspen	0	10	6	-	#1-4"x6	4	4	Fair	Inside	100%	100%	-	-
1E07-094802C	<i>Populus tremuloides</i>	Quaking aspen	10	20	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-094826D	<i>Populus tremuloides</i>	Quaking aspen	0	10	6	-	#1-2"x4, #2-4"x2	2	4	Fair	Inside	100%	100%	-	-
1E07-094850B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Fair	Inside	100%	100%	Previously pruned	-
1E07-094944A	<i>Populus tremuloides</i>	Quaking aspen	0	10	8	-	#1-4"x8	4	4	Fair	Inside	100%	100%	-	-
1E07-095059A	<i>Populus tremuloides</i>	Quaking aspen	0	10	5	-	#1-4"x5	4	4	Fair	Inside	100%	100%	-	-
1E07-095122B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-095202A	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E07-095232B	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Fair	Inside	100%	100%	Previously pruned	-
1E07-095235D	<i>Populus tremuloides</i>	Quaking aspen	0	10	8	-	#1-2"x8	2	2	Fair	Inside	100%	100%	-	-
1E07-095324A	<i>Populus tremuloides</i>	Quaking aspen	0	10	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E07-095350B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Fair	Inside	100%	100%	Previously pruned	-
1E07-095522B	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-095548A	<i>Populus tremuloides</i>	Quaking aspen	0	10	8	-	#1-4"x8	4	4	Fair	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E07-095614D	<i>Populus tremuloides</i>	Quaking aspen	0	10	8	-	#1-4"x8	4	4	Fair	Inside	100%	100%	-	-
1E07-095630B	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Fair	Inside	100%	100%	Previously pruned	-
1E07-100127D	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Fair	Inside	100%	100%	-	-
1E07-100144A	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Dead	Inside	--	--	-	-
1E07-100228C	<i>Populus tremuloides</i>	Quaking aspen	10	20	3	-	#1-4"x3	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E07-100259D	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Fair	Inside	100%	100%	-	-
1E07-100421A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Fair	Inside	100%	100%	-	-
1E07-100424D	<i>Populus tremuloides</i>	Quaking aspen	0	10	7	-	#1-4"x7	4	4	Fair	Inside	100%	100%	-	Half dead
1E07-100545A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Fair	Inside	100%	100%	-	-
1E07-100623C	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Excellent	Inside	100%	100%	Previously pruned	-
1E07-100807A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	-	-
1E07-100833D	<i>Populus tremuloides</i>	Quaking aspen	0	10	8	-	#1-2"x8	2	2	Fair	Inside	100%	100%	-	Half dead
1E07-100925A	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E07-100947C	<i>Populus tremuloides</i>	Quaking aspen	10	20	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	Previously pruned	Smallest trunk dead.
1E07-101010D	<i>Populus tremuloides</i>	Quaking aspen	0	10	6	-	#1-2", #2-4"	2	4	Poor	Inside	100%	100%	-	-
1E07-101039A	<i>Populus tremuloides</i>	Quaking aspen	0	10	10	-	#1-4"x10	4	4	Good	Inside	100%	100%	-	-
1E07-101147D	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	-	-
1E07-101307A	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E07-101337D	<i>Populus tremuloides</i>	Quaking aspen	0	10	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E07-101411A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Fair	Inside	100%	100%	-	-
1E07-101552A	<i>Populus tremuloides</i>	Quaking aspen	10	20	2	-	#1-4"x2	4	4	Fair	Inside	100%	100%	Previously pruned	-
1E07-101556D	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Fair	Inside	100%	100%	-	-
1E07-101721A	<i>Populus tremuloides</i>	Quaking aspen	10	20	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-101734D	<i>Populus tremuloides</i>	Quaking aspen	0	10	5	-	#1-4"x5	4	4	Fair	Inside	100%	100%	-	-
1E07-101804B	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-
1E07-101840A	<i>Populus tremuloides</i>	Quaking aspen	10	20	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-102045B	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-102147D	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	-	-
1E07-102402C	<i>Populus tremuloides</i>	Quaking aspen	10	20	5	-	#1-4"x3, #2-1-2"x2	4	4	Good	Inside	100%	100%	Previously pruned	2 smallest trunks dead.
1E07-102406D	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-2"x4	2	2	Good	Inside	100%	100%	-	-
1E07-102444A	<i>Populus tremuloides</i>	Quaking aspen	10	20	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E07-102611A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	-	-
1E07-102734A	<i>Populus tremuloides</i>	Quaking aspen	10	20	6	-	#1-4"x6	4	4	Good	Inside	100%	100%	-	-
1E07-102858D	<i>Populus tremuloides</i>	Quaking aspen	0	10	6	-	#1-2"x6	2	2	Fair	Inside	100%	100%	-	-
1E07-102900A	<i>Populus tremuloides</i>	Quaking aspen	0	10	4	-	#1-4"x4	4	4	Fair	Inside	100%	100%	-	-
1E07-102908C	<i>Populus tremuloides</i>	Quaking aspen	10	20	3	-	#1-4"x3	4	4	Excellent	Inside	100%	100%	-	-
1E07-103055B	<i>Populus tremuloides</i>	Quaking aspen	10	20	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-103100D	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Fair	Inside	100%	100%	-	-
1E07-103107C	<i>Populus tremuloides</i>	Quaking aspen	10	20	5	-	#1-4"x5	4	4	Excellent	Inside	100%	100%	Previously pruned	-
1E07-103220A	<i>Populus tremuloides</i>	Quaking aspen	0	10	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E07-103227D	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x2, #2-7"	4	7	Dead	Inside	--	--	-	-
1E07-103355A	<i>Populus tremuloides</i>	Quaking aspen	10	20	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E07-103355C	<i>Populus tremuloides</i>	Quaking aspen	10	20	7	-	#1-4", #2-1"	1	4	Good	Inside	100%	100%	Previously pruned	2 smaller trunks dead.
1E07-103355C	<i>Populus tremuloides</i>	Quaking aspen	10	20	4	-	#1-4", #2-1"	1	4	Good	Inside	100%	100%	Previously pruned	2 smallest trunks dead.

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E07-103528D	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-7", #2-4"	4	7	Fair	Inside	100%	100%	-	-
1E07-103540A	<i>Populus tremuloides</i>	Quaking aspen	10	20	3	-	#1-4"x3	4	4	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E07-103734A	<i>Populus tremuloides</i>	Quaking aspen	10	20	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E07-103736D	<i>Populus tremuloides</i>	Quaking aspen	10	20	2	-	#1-7"x2	7	7	Dead	Inside	--	--	-	-
1E07-103758B	<i>Populus tremuloides</i>	Quaking aspen	10	20	1	-	#1-4"	4	4	Good	Inside	100%	100%	-	-
1E07-103909D	<i>Populus tremuloides</i>	Quaking aspen	0	10	2	-	#1-7", #2-4"	4	7	Poor	Inside	100%	100%	-	-
1E07-103912A	<i>Populus tremuloides</i>	Quaking aspen	10	20	10	-	#1-4"x10	4	4	Excellent	Overhanging	More than 25%	Less than 25%	-	-
1E07-103912A	<i>Populus tremuloides</i>	Quaking aspen	10	20	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E07-103920B	<i>Populus tremuloides</i>	Quaking aspen	10	20	2	-	#1-4", #2-7"	4	7	Good	Inside	100%	100%	-	-
1E07-104100B	<i>Populus tremuloides</i>	Quaking aspen	10	20	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-104138C	<i>Populus tremuloides</i>	Quaking aspen	10	20	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	1 trunk dead. 2 smallest trunks dead.
1E07-104138C	<i>Populus tremuloides</i>	Quaking aspen	10	20	4	-	#1-4"x4	4	4	Good	Inside	100%	100%	-	2 smallest trunks dead.
1E07-104150D	<i>Populus tremuloides</i>	Quaking aspen	0	10	5	-	#1-4"x5	4	4	Poor	Inside	100%	100%	-	-
1E07-104231A	<i>Populus tremuloides</i>	Quaking aspen	0	10	7	-	#1-4"x7	4	4	Fair	Inside	100%	100%	-	-
1E07-104306B	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-104335D	<i>Populus tremuloides</i>	Quaking aspen	0	10	8	-	#1-4"x3, #2-2"x5	2	4	Fair	Inside	100%	100%	-	-
1E07-104428A	<i>Populus tremuloides</i>	Quaking aspen	10	20	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E07-104506B	<i>Populus tremuloides</i>	Quaking aspen	10	20	2	-	#1-4"x2	4	4	Good	Inside	100%	100%	Previously pruned	-
1E07-104614A	<i>Populus tremuloides</i>	Quaking aspen	10	20	3	-	#1-7"x3	7	7	Good	Inside	100%	100%	-	-
1E07-104701B	<i>Populus tremuloides</i>	Quaking aspen	0	10	3	-	#1-4"x3	4	4	Good	Inside	100%	100%	-	-
1E07-105031C	<i>Populus tremuloides</i>	Quaking aspen	10	20	4	-	#1-4"x4	4	4	Excellent	Inside	100%	100%	-	2 smallest trunks dead.
1E07-105325C	<i>Populus tremuloides</i>	Quaking aspen	10	20	4	-	#4-4"x4	4	4	Good	Inside	100%	100%	-	1 trunk dead.
1E07-105614C	<i>Populus tremuloides</i>	Quaking aspen	10	20	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	-	-
1E07-105818C	<i>Populus tremuloides</i>	Quaking aspen	10	20	4	-	#1-4"x4	4	4	Excellent	Inside	100%	100%	-	-
1E17-082702A	<i>Populus tremuloides</i>	Quaking aspen	10	20	12	-	#1-4"x12	4	4	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E05-081332B	<i>Populus trichocarpa</i>	Black cottonwood	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	-	-
1E05-082320B	<i>Populus trichocarpa</i>	Black cottonwood	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E05-082648B	<i>Populus trichocarpa</i>	Black cottonwood	20	30	1	-	#1-18"	18	18	Poor	Inside	100%	100%	-	-
1E05-083231B	<i>Populus trichocarpa</i>	Black cottonwood	20	30	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
1E05-083539B	<i>Populus trichocarpa</i>	Black cottonwood	20	30	1	-	#1-10"	10	10	Fair	Inside	100%	100%	-	-
1E05-083841B	<i>Populus trichocarpa</i>	Black cottonwood	20	30	2	-	#1-10"x2	10	10	Good	Inside	100%	100%	Previously pruned	-
1E05-084609C	<i>Populus trichocarpa</i>	Black cottonwood	30	40	5	-	#1-7"x4, #2-10"	10	7	Good	Inside	100%	100%	Previously pruned	-
1E05-085016B	<i>Populus trichocarpa</i>	Black cottonwood	10	20	1	-	#1-10"	10	10	Dead	Inside	--	--	-	-
1E05-085410B	<i>Populus trichocarpa</i>	Black cottonwood	10	20	1	-	#1-18"	18	18	Fair	Inside	100%	100%	-	-
1E05-085419A	<i>Populus trichocarpa</i>	Black cottonwood	10	20	2	-	#1-7"x2	7	7	Fair	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E05-090541B	<i>Populus trichocarpa</i>	Black cottonwood	10	20	1	-	#1-7"	7	7	Fair	Inside	100%	100%	Previously pruned	-
1E05-090813B	<i>Populus trichocarpa</i>	Black cottonwood	20	30	1	-	#1-18"	18	18	Fair	Inside	100%	100%	-	-
1E05-091320A	<i>Populus trichocarpa</i>	Black cottonwood	10	20	8	-	#1-7", #2-4"x7	4	7	Fair	Inside	100%	100%	Previously pruned	-
1E05-091833B	<i>Populus trichocarpa</i>	Black cottonwood	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E05-092114B	<i>Populus trichocarpa</i>	Black cottonwood	0	10	2	-	#1-10", #2-4"	10	4	Fair	Inside	100%	100%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E05-092232A	<i>Populus trichocarpa</i>	Black cottonwood	20	30	1	-	#1-10"	10	10	Fair	Overhanging	Less than 25%	Less than 25%	-	-
1E05-092401B	<i>Populus trichocarpa</i>	Black cottonwood	0	10	1	-	#1-7"	7	7	Fair	Inside	100%	100%	Previously pruned	-
1E05-092521A	<i>Populus trichocarpa</i>	Black cottonwood	10	20	5	-	#1-4"x5	4	4	Good	Inside	100%	100%	Previously pruned	-
1E05-092605B	<i>Populus trichocarpa</i>	Black cottonwood	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E05-093221B	<i>Populus trichocarpa</i>	Black cottonwood	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	Previously pruned	-
1E05-093350A	<i>Populus trichocarpa</i>	Black cottonwood	20	30	2	-	#1-7", #2-4"	4	7	Fair	Inside	100%	100%	Previously pruned	-
1E05-093409B	<i>Populus trichocarpa</i>	Black cottonwood	10	20	1	-	#1-18"	18	18	Fair	Inside	100%	100%	-	-
1E05-093607A	<i>Populus trichocarpa</i>	Black cottonwood	20	30	2	-	#1-7", #2-4"	4	7	Fair	Inside	100%	100%	Previously pruned	-
1E05-093808A	<i>Populus trichocarpa</i>	Black cottonwood	10	20	1	-	#1-7"	7	7	Good	Inside	100%	100%	Previously pruned	-
1E05-093813B	<i>Populus trichocarpa</i>	Black cottonwood	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E05-093913A	<i>Populus trichocarpa</i>	Black cottonwood	10	20	3	-	#1-7", #2-4"	4	7	Good	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E05-094128A	<i>Populus trichocarpa</i>	Black cottonwood	0	10	3	-	#1-4"x3	4	4	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	Significant pruning
1E10-112928B	<i>Populus trichocarpa</i>	Black cottonwood	10	20	1	-	#1-10"	10	10	Good	Inside	100%	100%	Previously pruned	-
1E13-093658D	<i>Populus trichocarpa</i>	Black cottonwood	30	40	1	-	#1-10"	10	10	Good	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E13-093916D	<i>Populus trichocarpa</i>	Black cottonwood	20	30	1	-	#1-8"	8	8	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E13-094252D	<i>Populus trichocarpa</i>	Black cottonwood	20	30	2	-	#1-10", #2-7"	10	7	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E13-095427D	<i>Populus trichocarpa</i>	Black cottonwood	0	10	4	-	#1-4"x4	4	4	Good	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E13-095753D	<i>Populus trichocarpa</i>	Black cottonwood	0	10	3	-	#1-4"x3	4	4	Good	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E13-120900A	<i>Populus trichocarpa</i>	Black cottonwood	30	40	3	-	#1-10", #2-7"x2	10	7	Good	Inside	100%	100%	-	-
1E13-121251A	<i>Populus trichocarpa</i>	Black cottonwood	30	40	1	-	#1-10"	10	10	Good	Inside	100%	100%	-	-
ADD-110657	<i>Populus trichocarpa</i>	Black cottonwood	0	10	1	-	#1-7"	7	7	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	Extensively pruned
1E01-122500A	<i>Salix laevigata</i>	Red willow	0	10	-	1-10	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E02-081540D	<i>Salix laevigata</i>	Red willow	0	10	-	1-10	-	-	-	Poor	Inside	100%	100%	Previously pruned	-
1E02-105425B	<i>Salix laevigata</i>	Red willow	10	20	-	1-10	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E02-120755B	<i>Salix laevigata</i>	Red willow	20	30	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-131732A	<i>Salix laevigata</i>	Red willow	20	30	-	1-10	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E05-143850A	<i>Salix laevigata</i>	Red willow	20	30	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-144258A	<i>Salix laevigata</i>	Red willow	20	30	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E05-144403A	<i>Salix laevigata</i>	Red willow	20	30	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-144954A	<i>Salix laevigata</i>	Red willow	30	40	-	1-10	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-150709A	<i>Salix laevigata</i>	Red willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-153219A	<i>Salix laevigata</i>	Red willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-153358A	<i>Salix laevigata</i>	Red willow	20	30	-	1-10	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E05-153635A	<i>Salix laevigata</i>	Red willow	20	30	-	11-50	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E05-153955A	<i>Salix laevigata</i>	Red willow	10	20	-	1-10	-	-	-	Fair	Inside	100%	100%	Previously pruned	-
1E05-154128A	<i>Salix laevigata</i>	Red willow	20	30	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-154320A	<i>Salix laevigata</i>	Red willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-155613A	<i>Salix laevigata</i>	Red willow	20	30	-	1-10	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E15-102932D	<i>Salix laevigata</i>	Red willow	20	30	-	1-10	-	-	-	Excellent	Overhanging	More than 25%	Less than 25%	-	-
1E15-111535D	<i>Salix laevigata</i>	Red willow	30	40	-	1-10	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E15-112742D	<i>Salix laevigata</i>	Red willow	20	30	-	1-10	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E15-112957D	<i>Salix laevigata</i>	Red willow	20	30	-	1-10	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E19-083137A	<i>Salix laevigata</i>	Red willow	10	20	-	1-10	-	-	-	Excellent	Inside	100%	100%	-	-
1E19-083531A	<i>Salix laevigata</i>	Red willow	20	30	-	1-10	-	-	-	Good	Inside	100%	100%	-	-
1E02-100938B	<i>Salix lasiandra</i> ( <i>Salix lucida</i> )	Pacific willow, shining willow	20	30	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E02-110839B	<i>Salix lasiandra</i> ( <i>Salix lucida</i> )	Pacific willow, shining willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-123048A	<i>Salix lasiandra</i> ( <i>Salix lucida</i> )	Pacific willow, shining willow	20	30	-	1-10	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E01-112030B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E01-114235D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E01-122024D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E01-153755A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	1-10	-	-	-	Fair	Inside	100%	100%	-	-
1E02-144620D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E02-144806D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E02-144919D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E02-145047D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E02-145602C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-074525D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-074749D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-074928D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-075135D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E03-075612D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Inside	100%	100%	-	Lots of dead branches
1E03-075816D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-075930D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-080012B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-080050D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E03-080247D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Overhanging	More than 25%	More than 25%	-	-
1E03-080428A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E03-080613A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-080744A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-080858B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/x)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E03-080945A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-081248A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-081321B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-081421A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-081501B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-082137D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	More than 25%	More than 25%	-	Galls on tree
1E03-082144A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-082259A	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	1-10	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E03-082308C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-082320D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-082440D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-082548D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-082740D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-082903D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-083008D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E03-083330C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-083338D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E03-083544A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E03-083552D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Fair	Inside	100%	100%	-	Galls and outer branches dying
1E03-083712D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-083844D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-083957D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-084106D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-084232D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-084350D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-084353C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-084500D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	-	Half dead
1E03-084700C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-084821D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-084943D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-084952C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-085217C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-085358D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-085434C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-085716D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-085724C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-085733B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-085846D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E03-085936D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-090053D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-090126B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E03-090230A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-090238D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-090318C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E03-090401B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-090403D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Inside	100%	100%	-	Half dead
1E03-090531C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-090539D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E03-090914A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-091806B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-091857D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-092016D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-092312D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	Some dead branches
1E03-092338B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-092436C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-092442D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-092639D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Fair	Inside	100%	100%	-	Lots of dead branches
1E03-092711C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-092853D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	Lots of dead but also new growth
1E03-092909B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-093011C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Dead	Inside	--	--	-	-
1E03-093035D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E03-093042B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-093450D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E03-093503C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-093609D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E03-093618A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-093622B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-093637C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Dead	Inside	--	--	-	-
1E03-093755B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E03-093824D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	Some dead
1E03-093923D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-093929B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-093940A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-093954C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	South side trunk bases dead, north side growing back.
1E03-094041A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-094153B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E03-094219D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-094321D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/x)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E03-094441A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-094620C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	Many lower trunks and branches dead.
1E03-094638D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	1-10	-	-	-	Good	Inside	100%	100%	-	-
1E03-094649B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-094657A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-094832D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-094939B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-095040D	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E03-095129C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-095224D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E03-095337D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	-	Lots of dead
1E03-095430C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-095509D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Overhanging	More than 25%	Less than 25%	-	Lots of dead
1E03-095637D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-095752D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E03-095845D	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-100010D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	Some dead branches
1E03-100114D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E03-100329D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-100511D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-100622D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-100757D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-100957D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E03-101122D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Fair	Inside	100%	100%	-	Partially dead
1E03-101242D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
															Leaves nearest road appear to have some type of infection similar to powdery mildew.
1E03-101302C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Fungal infestation	
1E03-101359D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	More than 25%	More than 25%	-	-
1E03-101747C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Overhanging	More than 25%	Less than 25%	Fungal infestation	-
1E03-102211C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E03-102624C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	Large specimen cut back to base, originally with 3-12" trunks. Re-emergent new growth appearing.
1E03-102718B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-102721A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-103446A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-103647B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-103823A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-104312A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-104318B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-104958B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-105144B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-105324B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-105513A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-105637B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-105753A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	1-10	-	-	-	Good	Inside	100%	100%	-	Resprout
1E03-105843B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-105924A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E03-110017B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-110136A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-110202B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-110457B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-110511A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-110640A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-110817B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-111101A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-111309D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-111440B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-111536A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Fair	Inside	100%	100%	-	Being over run by vine (see photos)
1E03-111601D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	Some dead in dry areas
1E03-111832D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-112100D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-112232D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-112357D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-112528D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-112733D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Fair	Inside	100%	100%	Previously pruned	Some dead
1E03-112951D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Dead	Inside	--	--	Previously pruned	Dead and pruned
1E03-113249D	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-113415D	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-113525D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-113622D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E03-113732D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Inside	100%	100%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E03-120424D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Inside	100%	100%	Previously pruned	Half dead
1E03-120550D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Fair	Inside	100%	100%	Previously pruned	Some dead
1E03-120744D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E03-121014D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-121131D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-121230D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E03-121307A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-121418D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E03-121537A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-121608D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-121629B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-121855D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-121903B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-122008D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	Some dead on outside
1E03-122203A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	Gigantic multi-trunked
1E03-122208D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-122228C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	-	Directly adjacent to south side of water crossing. Impacts from vehicle travel.
1E03-122340B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-122350D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E03-122425A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	Gigantic willow, looks like one plant
1E03-122523D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E03-122804C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-122908B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-122949A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-123014B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-123102A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E03-123130B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-123225C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-123546C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E03-123551C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E03-123849C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-124147C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-125005C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E03-125229C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-074732A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-074940C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-074940C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-075049D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-075117A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-080608D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	1-10	-	-	-	Good	Inside	100%	100%	-	-
1E05-081002D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	Dead near bottom
1E05-081142D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	1-10	-	-	-	Excellent	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E05-081314C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-081748D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-082050C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-083005D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	Previously pruned	-
1E05-083336C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-083646C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-083839C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-084037C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-084051D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	1-10	-	-	-	Good	Inside	100%	100%	-	-
1E05-084610B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-084920D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-085814C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-085955B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-090335A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-091613A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	1-10	-	-	-	Fair	Inside	100%	100%	Previously pruned	-
1E05-092700D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	-	Half dead
1E05-092826D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Poor	Inside	100%	100%	-	-
1E05-092907C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	Approximately 40% of uphill side dead.	-
1E05-093138D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Poor	Inside	100%	100%	-	Half dead
1E05-093239C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-093643C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-093803D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-093916C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-094147D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Poor	Inside	100%	100%	-	-
1E05-094338C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-094342C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-094546C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-094720A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E05-094752C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-094757C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Dead	Inside	--	--	-	-
1E05-094851D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-094951A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E05-094953D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-095402C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-095707C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-095712C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-100202A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E05-100202C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Fair	Inside	100%	100%	-	-
1E05-100346C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-100525C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-100707D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-100752A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/x)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E05-100944D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	-	-
1E05-101030C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Fair	Inside	100%	100%	-	-
1E05-101039C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E05-101056D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Fair	Inside	100%	100%	-	-
1E05-101250B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-101332C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E05-101338C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E05-101456C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-101654C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-101701C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-101715D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-101823C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-101841D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	-	Half dead
1E05-102120C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Dead	Inside	-	--	-	-
1E05-102315C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-102324C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-102530D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Fair	Inside	100%	100%	-	-
1E05-102602A	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Poor	Inside	100%	100%	Previously pruned	-
1E05-102623D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Dead	Inside	--	--	-	-
1E05-102728D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	Very wide canopy
1E05-102917D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-102936A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	Previously pruned	-
1E05-103046C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-103201D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-103328D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-103354C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-103410B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-103647D	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-103830D	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-103937C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-104013D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Overhanging	More than 25%	Less than 25%	-	-
1E05-1041118C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-104235C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-104420C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-104849B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	Main plant has three large offshoots, center of old plant is dead
1E05-104928A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	
1E05-104959C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-105054B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-105136C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-105204B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-105255C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-105515C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-105640C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Fair	Inside	100%	100%	-	-
1E05-105650C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-105710D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/x)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E05-105832D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-105918D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Poor	Inside	100%	100%	-	-
1E05-105920C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Fair	Inside	100%	100%	-	-
1E05-110008D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Poor	Inside	100%	100%	-	-
1E05-110044C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-110122D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E05-110159C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Dead	Inside	--	--	-	-
1E05-110220B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-110258D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Poor	Inside	100%	100%	-	-
1E05-110328C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Fair	Inside	100%	100%	-	-
1E05-110403B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-110517D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Fair	Inside	100%	100%	-	-
1E05-110529C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-110627D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-110652C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-110700C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-110906D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-111007D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Poor	Inside	100%	100%	-	Mostly dead along road
1E05-111109A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	Birch branches fell on half of tree
1E05-111307A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-111403C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Dead	Inside	--	--	-	-
1E05-112828C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-112832A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-112948A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-113206C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Dead	Inside	--	--	-	-
1E05-113532A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-114346A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-114725A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-114914A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-114958A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-115138A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E05-115454A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-115636B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E05-115738A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-115839A	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-115935D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-120207D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Fair	Inside	100%	100%	-	-
1E05-120258B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-120311D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	1-10	-	-	-	Good	Inside	100%	100%	-	-
1E05-120501D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-120502A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E05-120504B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-120555D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	-	Many dead branches with a couple small live ones
1E05-120742D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	Some dead on road side
1E05-120819B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-120849D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-120849D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E05-120959B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	-	Presence of vine growing on willow
1E05-121034D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Inside	100%	100%	-	Lots of dead at base
1E05-121401D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-121417C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E05-121453B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-121525D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-121629B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	-	Presence of vine on willow
1E05-121726D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-121802C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-122120D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Dead	Inside	--	--	-	-
1E05-122232D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-122307C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-122453B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	Presence of vine on willow
1E05-122456D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E05-122605D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-122657C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-122709B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-122743D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Poor	Inside	100%	100%	-	-
1E05-122856B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-122911C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-123045C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-123226B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-123231C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-123459D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Fair	Inside	100%	100%	-	-
1E05-123844D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-123918C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-124019D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-124132D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-124256C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-124625D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E05-131012C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-131049D	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Overhanging	More than 25%	Less than 25%	-	-
1E05-131215C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-131356D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E05-131357C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-131506C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-131621D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E05-131740D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-131910D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-132235A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E05-132255D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-134431D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E05-134600D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/x)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E05-134756D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-135016C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-135357D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	More than 25%	Less than 25%	-	-
1E05-135541D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	1-10	-	-	-	Good	Inside	100%	100%	-	-
1E05-135659D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-135914D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E05-140131D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E05-140223C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	Road side overhang mostly dead.
1E05-141843A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	-	-
1E05-142042D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Fair	Inside	100%	100%	-	-
1E05-142117B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	Vine presence on willow
1E05-142119A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-142253B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Fair	Inside	100%	100%	-	Vine presence on willow
1E05-142318A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E05-142438B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-143344B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	Presence of vine on willow
1E05-143622B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-143842B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-144103B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-144112A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-144241B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-144405B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-144547A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-144703B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	Presence of vine on willow as well
1E05-144718A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-144828B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	Presence of vine on willow
1E05-145153A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-145302C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-145327B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-145339A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-145505A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-145541D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-145608C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-145636A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E05-145711B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-145712D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E05-145735A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E05-145843C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-145910D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E05-145912A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E05-145926B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	Presence of vine on willow	-
1E05-150002C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-150014D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-150029A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Fair	Inside	100%	100%	Main trunks are dead lots of offshoots growing	-
1E05-150141C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-150143D	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-150307D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E05-150509D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-150709D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-150952A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-151042D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-151155A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-151233C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-151236D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-151316A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Fair	Inside	100%	100%	-	-
1E05-151347D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-151435C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-151530A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-151537D	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-151549C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-151737B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-151744C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-151840A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-151916C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-152005A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-152007C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-152007C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-152025B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-152052C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-152136A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-152232C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-152409A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-152527C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Poor	Inside	100%	100%	-	-
1E05-152531A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-152705C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-152727A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-152740D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-152838A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-152838C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-152932D	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-152951A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-153012C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-153104A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E05-153224D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-153339C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-153618C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-153733D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E05-154841A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-155235A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-155325B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	Presence of vine on willow
1E05-155344A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-155734B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	Vine presence on willow
1E05-155859A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E05-155926B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	Vine presence on willow
1E05-160050A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E05-160117B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	Vine presence on willow
1E05-160246B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	Vine presence on willow
1E05-160423B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	Vine presence on willow
1E05-160538A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	Previously pruned	-
1E05-160801B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	Vine presence on willow
1E05-160807A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-160914A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-160922C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-161017B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	Vine presence on willow
1E05-161037A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-161211B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	Vine presence on willow
1E05-161225A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-161403B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	Vine presence on willow
1E05-161412A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E05-161804C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-161819D	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-162010D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E05-162035C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-162138D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-162241D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E05-162251C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-162349D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E05-162423C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-162516D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E05-162608D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-		-	-	-	Excellent	Inside	100%	100%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E05-162633C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E05-162716D	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-162801C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-162812D	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-162904D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-162927C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E05-163036D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E05-163123C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-163237D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E05-163404D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-163511C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-163515C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E05-163544D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E05-163813C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E10-093152A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E10-093156A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	Previously pruned	-
1E10-093547A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	Previously pruned	-
1E10-093951D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E10-094340D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E10-094517D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E10-094644D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E10-094826D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E10-094852A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E10-095048A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	Previously pruned	-
1E10-095344A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E10-095425B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E10-095747A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E10-095807B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E10-095904A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E10-095940B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E10-100057A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E10-101800D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E10-102009D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E10-102515D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E10-102609D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E10-102928D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E10-103412D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E10-103619D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E10-104017D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E10-104200A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E10-104554A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E10-104826A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E10-104943A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E10-110631A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	-	-
1E10-110843A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E10-111045A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E10-111358A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E10-111514B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E10-111702A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E10-111733A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E10-111755A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E10-124755A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E10-124928A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Fair	Inside	100%	100%	Previously pruned	-
1E10-125058A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E10-125632A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E12-085852C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E12-090042C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E12-090232C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	More than 25%	More than 25%	Previously pruned	-
1E12-090409C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-091134C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E12-091410C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-091544C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E12-091752C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-091928C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E12-092115C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-092520C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E12-092725C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-095105C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Excellent	Overhanging	More than 25%	More than 25%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Salix)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E12-095253C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Overhanging	More than 25%	More than 25%	Previously pruned	-
1E12-095434C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-095623C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-095647D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E12-095739D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E12-095805C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-095931C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-100143C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-100306C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-100605C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-100933C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-101111C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-101527C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-101709C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	More than 25%	More than 25%	-	-
1E12-101905C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E12-102218C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	More than 25%	More than 25%	-	-
1E12-102350C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-102518C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-102644C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-102756C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-102910C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-103050C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-103211C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-103330C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-103449C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sali)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E12-103631C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-103751C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-103936C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-104056C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-104337C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	Mixed in with <i>S. exigua</i> .
1E12-104434B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E12-104547B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E12-104649C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-104659B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E12-104809B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E12-104910C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-104931B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E12-105051C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-105231C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	More than 25%	More than 25%	-	-
1E12-105352C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-105512C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E12-105705C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-105742B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E12-105822C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-111618C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-112152C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-112351C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-112519C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-112708C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	More than 25%	More than 25%	Previously pruned	-
1E12-112850C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-113518C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Salix)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E12-113835C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-114004C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-114130C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-114336C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-114457C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-114652C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-114812C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-115303A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-115425C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-115648A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-115650C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-115715D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E12-115724B	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E12-115816C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E12-120613D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E13-092431C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E13-092553D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E13-092813D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E13-093127D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E13-093349C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	Down in creek.
1E13-093406D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E13-094603D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E13-094654D	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E13-094737D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E13-094823D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E13-094919D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E13-095252D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E13-095259C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Overhanging	More than 25%	Less than 25%	-	-
1E13-095335D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E13-095541D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E13-095611C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E13-095701D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Overhanging	More than 25%	More than 25%	-	-
1E13-095742C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	More than 25%	More than 25%	Previously pruned	-
1E13-095906D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E13-095927C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E13-100651D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E13-100805D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	More than 25%	Less than 25%	-	-
1E13-100904D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E13-100957C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E13-101224C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E13-101328D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Overhanging	More than 25%	Less than 25%	-	-
1E13-101412C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E13-101518D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	More than 25%	Less than 25%	Previously pruned	-
1E13-101745C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E13-101954C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E13-102531D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E13-102611D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E13-102611D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E13-121059A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E13-121640A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E13-122108A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E13-122343A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E13-122445A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	Previously pruned	-
1E13-122448B	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E14-112240A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E14-112905A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E15-100856D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-101521C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/x)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E15-102957C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-105258C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-105403D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E15-105509D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E15-105541C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-105607D	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E15-105718D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-105834D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-105853C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-110433D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E15-110622D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E15-110643C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E15-110750D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E15-110903D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E15-111212D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E15-111334D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E15-111434D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E15-111708D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	More than 25%	More than 25%	Previously pruned	-
1E15-111851D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E15-111950D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E15-112053D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E15-113540D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E15-113643D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E15-113804D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	1-10	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E15-113912D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E15-113956D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/x)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E15-114142D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E15-114238C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E15-114310D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E15-114416D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E15-114431C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-115216D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-115257C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E15-115343D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E15-115512D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E15-120315D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-120336C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-120518D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E15-120732D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E15-120735C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Overhanging	Less than 25%	Less than 25%	-	-
1E15-121112C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Overhanging	Less than 25%	Less than 25%	-	-
1E15-121302D	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Overhanging	Less than 25%	Less than 25%	-	-
1E15-121307C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Overhanging	Less than 25%	Less than 25%	-	-
1E15-121556C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E15-121608D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E15-121936D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Fair	Overhanging	Less than 25%	Less than 25%	-	Half dead
1E15-122017C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Overhanging	Less than 25%	Less than 25%	-	-
1E15-122059D	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Overhanging	Less than 25%	Less than 25%	-	Lots of dead
1E15-122326C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E15-122441C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Overhanging	Less than 25%	Less than 25%	-	-
1E16-085721A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-085721A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-085731C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Salix)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E16-085856A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-085916C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-091120A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-091240C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-091326A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-091412A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-091434C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-091501A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-091734C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-091736A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-091832A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-091911C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-092103C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-092105A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-092200A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-092208C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-092253A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-092351C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-092452A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-092455C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-092600C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-092717C	<i>Salix lasiolepis</i>	Arroyo willow	20	30	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-092808A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E16-092818A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-092830A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-092834C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-093150C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-093304A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E16-093304C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-093351A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-093422C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-093451A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	-	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-093635A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-093639C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-093737A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-093744C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-093836A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-093936C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-093953A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	-	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-094106C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-094723C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E16-095612A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E16-095754A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E16-095914A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-100029A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Overhanging	More than 25%	Less than 25%	-	-
1E16-100251A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-100338A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/s)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E16-100421A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-100737A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E16-100737A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E16-100826C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E16-100918A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-101010C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E16-101016A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-101159A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-101210C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-101325A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-101332C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-101418A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E16-101515A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E16-101749C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E16-101826A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-101911C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E16-101945A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-102119C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E16-102120A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-102251C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E16-102305A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-102412C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E16-102416A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-102457A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-102534C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E16-102558A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-102652A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E16-102729C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E16-102847A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E16-103000A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E16-103206C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E16-103415C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E16-103444A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E16-103656C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E16-103705A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Fair	Inside	100%	100%	-	-
1E16-103838C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	Heavily grazed.
1E16-103921A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E16-104019C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	-	Heavily grazed.
1E16-104144C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	Heavily grazed.
1E16-104146A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E16-104308C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	Heavily grazed.
1E16-104446C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	-	Heavily grazed.
1E16-104743C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E16-104854C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	Heavily grazed.
1E16-105035C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Inside	100%	100%	-	Heavily grazed.
1E16-105305C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Dead	Inside	--	--	-	Heavily grazed.

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/x)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E16-105411C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E16-105528C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E16-105653C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E16-105818C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	-	-
1E16-110121C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Fair	Inside	100%	100%	-	Heavily grazed.
1E16-110301C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	-	-
1E16-121953A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-122918A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-123121C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-125907A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	11-50	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-125942C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-133544A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-133816A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-133847C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E16-133908A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E17-082424C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E17-082537A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E17-082637C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E17-082702A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E17-082820C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	Cattle damage.
1E17-083218A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E17-083251C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Overhanging	More than 25%	More than 25%	-	-
1E17-083412A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E17-085452C	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Fair	Inside	100%	100%	-	Heavily grazed.
1E17-100757C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E19-075038C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E19-082650C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E19-082653A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E19-083116C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Fair	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E19-084523A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E19-085114A	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Inside	100%	100%	Previously pruned	-
1E19-085436A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E19-085516A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison



Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Sa/x)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Roots Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E19-085722A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E19-085802A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E19-085903A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E19-085940C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E19-085947A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E19-090855C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	-	-
1E19-091012C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	-	-
1E19-091326A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E19-091616A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E19-092436A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E19-092453C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E19-092529A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E19-092623C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E19-092711A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	101+	-	-	-	Good	Inside	100%	100%	-	-
1E19-092733C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Fair	Inside	100%	100%	-	-
1E19-092848C	<i>Salix lasiolepis</i>	Arroyo willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	-	-
1E19-092857A	<i>Salix lasiolepis</i>	Arroyo willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E08-102230A	<i>Salix lutea</i>	Yellow willow	20	30	-	11-50	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E08-102521A	<i>Salix lutea</i>	Yellow willow	20	30	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E08-102822A	<i>Salix lutea</i>	Yellow willow	20	30	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E13-090126A	<i>Salix lutea</i>	Yellow willow	10	20	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E13-090310B	<i>Salix lutea</i>	Yellow willow	10	20	-	101+	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E13-090533B	<i>Salix lutea</i>	Yellow willow	10	20	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E13-090651A	<i>Salix lutea</i>	Yellow willow	20	30	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E13-090701B	<i>Salix lutea</i>	Yellow willow	10	20	-	11-50	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E13-090748B	<i>Salix lutea</i>	Yellow willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E13-091416B	<i>Salix lutea</i>	Yellow willow	10	20	-	101+	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E13-103018A	<i>Salix lutea</i>	Yellow willow	10	20	-	11-50	-	-	-	Excellent	Inside	100%	100%	-	-
1E13-121534A	<i>Salix lutea</i>	Yellow willow	0	10	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	-	-
1E14-095208B	<i>Salix lutea</i>	Yellow willow	0	10	-	11-50	-	-	-	Good	Inside	100%	100%	Cattle grazing	-
1E14-110820C	<i>Salix lutea</i>	Yellow willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-111737C	<i>Salix lutea</i>	Yellow willow	10	20	-	51-100	-	-	-	Good	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-112115C	<i>Salix lutea</i>	Yellow willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-112318C	<i>Salix lutea</i>	Yellow willow	20	30	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-

Table 2. CSP 2022 Native Tree Survey Data  
 Tree Assessment Summary Report  
 TLRR Control - Silver Peak 55 KV Project  
 Inyo and Mono Counties  
 Southern California Edison




Tree Name	Species Name	Common Name	Tree Height Min	Tree Height Max	Number of Trunks (excluding Salix)	Number of Willow Trunks	Trunk DBH (# trunks - given DBH in inches)	Smallest DBH (inches)	Largest DBH (inches)	Qualitative Health of Tree	Inside Project Work Area or Rooted Outside but Overhanging	Canopy Disturbance Anticipated	Root Disturbance Anticipated	Notes	Additional Notes
1E14-112452D	<i>Salix lutea</i>	Yellow willow	10	20	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E14-112510C	<i>Salix lutea</i>	Yellow willow	20	30	-	51-100	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-112517B	<i>Salix lutea</i>	Yellow willow	0	10	-	51-100	-	-	-	Good	Inside	100%	100%	Previously pruned	-
1E14-112534A	<i>Salix lutea</i>	Yellow willow	20	30	-	101+	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	-	-
1E14-112625D	<i>Salix lutea</i>	Yellow willow	20	30	-	11-50	-	-	-	Excellent	Overhanging	Less than 25%	Less than 25%	Previously pruned	-
1E14-112750B	<i>Salix lutea</i>	Yellow willow	10	20	-	51-100	-	-	-	Excellent	Inside	100%	100%	Previously pruned	-
1E02-151725D	<i>Salix</i> species	Unknown willow	0	10	-	11-50	-	-	-	Dead	Inside	--	--	-	-
1E03-084638D	<i>Salix</i> species	Unknown willow	0	10	-	11-50	-	-	-	Dead	Inside	--	--	-	-
1E03-080247D	<i>Salix</i> species	Unknown willow	10	20	-	51-100	-	-	-	Dead	Overhanging	--	--	-	-

Note: The number of stems for *Salix* individuals were estimated but diameter at breast height was not measured.

# Figures







## Legend

- Arroyo willow
- Access Road
- Proposed Alignment
- Work Areas
- Material Yards

### Note:


Trees were mapped within a defined survey area along the CSP Project alignment. The defined survey area was based on a conservative estimate of the size, location, and alignment of proposed construction work areas. The size, location, and alignment of construction work areas is subject to revision; construction work areas will be reduced in size, and re-located and re-aligned, prior to construction to avoid resource impacts. The revised construction work areas will not exceed the defined survey area; therefore, this survey represents a conservative (worst-case) estimate of potential impacts to trees.



0 200 400 800  
Feet

## Control-Silver Peak Project

### Native Tree Assessment Locations



## Legend

- Arroyo willow
- Fremont cottonwood
- Red willow
- Access Road
- Proposed Alignment
- Work Areas
- Material Yards

### Note:

Trees were mapped within a defined survey area along the CSP Project alignment. The defined survey area was based on a conservative estimate of the size, location, and alignment of proposed construction work areas. The size, location, and alignment of construction work areas is subject to revision; construction work areas will be reduced in size, and re-located and re-aligned, prior to construction to avoid resource impacts. The revised construction work areas will not exceed the defined survey area; therefore, this survey represents a conservative (worst-case) estimate of potential impacts to trees.



0 200 400 800  
Feet

**Control-Silver Peak Project**

**Native Tree Assessment Locations**







### Legend

- Arroyo willow
- Fremont cottonwood
- Red willow
- ▲ Fremont cottonwood, Dead
- Access Road
- Proposed Alignment
- Work Areas


**Note:**  
Trees were mapped within a defined survey area along the CSP Project alignment. The defined survey area was based on a conservative estimate of the size, location, and alignment of proposed construction work areas. The size, location, and alignment of construction work areas is subject to revision; construction work areas will be reduced in size, and re-located and re-aligned, prior to construction to avoid resource impacts. The revised construction work areas will not exceed the defined survey area; therefore, this survey represents a conservative (worst-case) estimate of potential impacts to trees.



0 200 400 800  
Feet


### Control-Silver Peak Project

### Native Tree Assessment Locations









## Legend

- Arroyo willow
- Access Road
- Proposed Alignment
- Work Areas
- Material Yards


Note:  
Trees were mapped within a defined survey area along the CSP Project alignment. The defined survey area was based on a conservative estimate of the size, location, and alignment of proposed construction work areas. The size, location, and alignment of construction work areas is subject to revision; construction work areas will be reduced in size, and re-located and re-aligned, prior to construction to avoid resource impacts. The revised construction work areas will not exceed the defined survey area; therefore, this survey represents a conservative (worst-case) estimate of potential impacts to trees.




0 200 400 800  
Feet

## Control-Silver Peak Project

## Native Tree Assessment Locations









### Legend

- Arroyo willow
- Red willow
- ▲ Singleleaf pinyon pine,  
Dead
- Access Road
- Proposed Alignment
- Work Areas
- Material Yards

**Note:**  
Trees were mapped within a defined survey area along the CSP Project alignment. The defined survey area was based on a conservative estimate of the size, location, and alignment of proposed construction work areas. The size, location, and alignment of construction work areas is subject to revision; construction work areas will be reduced in size, and re-located and re-aligned, prior to construction to avoid resource impacts. The revised construction work areas will not exceed the defined survey area; therefore, this survey represents a conservative (worst-case) estimate of potential impacts to trees.



0 200 400 800  
Feet

**Control-Silver Peak  
Project**

**Native Tree Assessment Locations**



## Legend

- Arroyo willow
- Black cottonwood
- Singleleaf pinyon pine
- Water birch
- △ Arroyo willow, Dead
- △ Black cottonwood, Dead
- ▲ Singleleaf pinyon pine, Dead
- Access Road
- Proposed Alignment
- Work Areas
- Material Yards

### Note:


Trees were mapped within a defined survey area along the CSP Project alignment. The defined survey area was based on a conservative estimate of the size, location, and alignment of proposed construction work areas. The size, location, and alignment of construction work areas is subject to revision; construction work areas will be reduced in size, and re-located and re-aligned, prior to construction to avoid resource impacts. The revised construction work areas will not exceed the defined survey area; therefore, this survey represents a conservative (worst-case) estimate of potential impacts to trees.




0 200 400 800  
Feet

**Control-Silver Peak Project**

**Native Tree Assessment Locations**







## Legend

- Bristlecone pine
- Fremont cottonwood
- Limber pine
- Quaking aspen
- Singleleaf pinyon pine
- Limber pine, Dead
- Quaking aspen, Dead
- Access Road
- Proposed Alignment
- Work Areas
- Material Yards
- Substations

### Note:


Trees were mapped within a defined survey area along the CSP Project alignment. The defined survey area was based on a conservative estimate of the size, location, and alignment of proposed construction work areas. The size, location, and alignment of construction work areas is subject to revision; construction work areas will be reduced in size, and re-located and re-aligned, prior to construction to avoid resource impacts. The revised construction work areas will not exceed the defined survey area; therefore, this survey represents a conservative (worst-case) estimate of potential impacts to trees.



0 200 400 800  
Feet

## Control-Silver Peak Project

### Native Tree Assessment Locations







### Legend

- Bristlecone pine
- Access Road
- Proposed Alignment
- Work Areas
- Material Yards


Note:  
Trees were mapped within a defined survey area along the CSP Project alignment. The defined survey area was based on a conservative estimate of the size, location, and alignment of proposed construction work areas. The size, location, and alignment of construction work areas is subject to revision; construction work areas will be reduced in size, and re-located and re-aligned, prior to construction to avoid resource impacts. The revised construction work areas will not exceed the defined survey area; therefore, this survey represents a conservative (worst-case) estimate of potential impacts to trees.




0 200 400 800  
Feet

**Control-Silver Peak Project**

**Native Tree Assessment Locations**







## Legend

- Arroyo willow
- Limber pine
- Singleleaf pinyon pine
- Utah juniper
- Yellow willow
- △ Singleleaf pinyon pine, Dead
- ▲ Utah juniper, Dead
- Access Road
- Proposed Alignment
- Work Areas
- Material Yards


**Note:**  
Trees were mapped within a defined survey area along the CSP Project alignment. The defined survey area was based on a conservative estimate of the size, location, and alignment of proposed construction work areas. The size, location, and alignment of construction work areas is subject to revision; construction work areas will be reduced in size, and re-located and re-aligned, prior to construction to avoid resource impacts. The revised construction work areas will not exceed the defined survey area; therefore, this survey represents a conservative (worst-case) estimate of potential impacts to trees.





0 200 400 800  
Feet

**Control-Silver Peak Project**

**Native Tree Assessment Locations**







## Legend

- Arroyo willow
- Fremont cottonwood
- Pacific willow, shining willow
- Singleleaf pinyon pine
- Utah juniper
- Water birch
- △ Arroyo willow, Dead
- ▲ Utah juniper, Dead
- Access Road
- Proposed Alignment
- Work Areas
- Material Yards

**Note:**  
Trees were mapped within a defined survey area along the CSP Project alignment. The defined survey area was based on a conservative estimate of the size, location, and alignment of proposed construction work areas. The size, location, and alignment of construction work areas is subject to revision; construction work areas will be reduced in size, and re-located and re-aligned, prior to construction to avoid resource impacts. The revised construction work areas will not exceed the defined survey area; therefore, this survey represents a conservative (worst-case) estimate of potential impacts to trees.



0 200 400 800

Feet

## Control-Silver Peak Project

## Native Tree Assessment Locations



### Legend

- Arroyo willow
- Singleleaf pinyon pine
- Utah juniper
- Proposed Alignment
- Work Areas

#### Note:

Trees were mapped within a defined survey area along the CSP Project alignment. The defined survey area was based on a conservative estimate of the size, location, and alignment of proposed construction work areas. The size, location, and alignment of construction work areas is subject to revision; construction work areas will be reduced in size, and re-located and re-aligned, prior to construction to avoid resource impacts. The revised construction work areas will not exceed the defined survey area; therefore, this survey represents a conservative (worst-case) estimate of potential impacts to trees.



0 200 400 800  
Feet

### Control-Silver Peak Project

### Native Tree Assessment Locations



- Legend**
- Arroyo willow
  - Quaking aspen
  - Access Road
  - Proposed Alignment
  - Work Areas Material
  - Yards

**Note:**  
Trees were mapped within a defined survey area along the CSP Project alignment. The defined survey area was based on a conservative estimate of the size, location, and alignment of proposed construction work areas. The size, location, and alignment of construction work areas is subject to revision; construction work areas will be reduced in size, and re-located and re-aligned, prior to construction to avoid resource impacts. The revised construction work areas will not exceed the defined survey area; therefore, this survey represents a conservative (worst-case) estimate of potential impacts to trees.



0 200 400 800  
Feet

### Control-Silver Peak Project

### Native Tree Assessment Locations

Arcadis U.S., Inc.  
320 Commerce, Suite 200  
Irvine  
California 92602  
Phone: 714 730 9052  
Fax: 714 730 9345  
[www.arcadis.com](http://www.arcadis.com)