

PROJECT MEMORANDUM SYCAMORE-PEÑASQUITOS 230-KV TRANSMISSION LINE PROJECT

Date:	April 24, 2017
To:	Billie Blanchard, CPUC Project Manager
From:	Sheila Hoyer, CPUC Monitoring Supervisor
Subject:	Weekly Report #15 – April 10 to April 15, 2017

INTRODUCTION

This report provides a summary of the construction and compliance activities associated with the SDG&E Sycamore-Peñasquitos 230-kV Transmission Line Project for the week of April 10 to April 15, 2017.

A summary of the Notices to Proceed, and Minor Project Refinement, and Temporary Extra Workspace Requests are provided in Tables 1, 2, and 3, respectively. A summary of Noncompliance, Project Memoranda and Incidents is provided in Table 4. Daily Inspection Reports are provided in Appendix A.

CPUC/Panorama Environmental Monitors (EMs): Dave Flietner, Jerry Scott, and Korey Klutz

STAGING YARDS

Summary of Activity:

Stonebridge Staging Yard:

1. Delivering materials and equipment, BMP maintenance and excavating a receiving pit for vacuum truck spoils.

Driving Range Staging Yard:

1. Maintaining BMPs, delivering materials and equipment, working on the recycled water system (equipment maintenance), and stockpiling truck spoils from underground excavations.

Underground Transmission Line:

1. Construction occurred in Segment 5 along sections 4-6, 11 and 12 (approximately between stations 66+00 to 101+00, 174+00, 189+15, and 227+50). Saw cutting for trench and

vaults, vault installation, potholing to locate existing utilities, and installing storm drain inlet protection.

Environmental Compliance:

- 1. During this reporting period, all pavement was kept clean. No winds occurred that were higher than 20 mph. All off-road diesel-powered construction equipment used on the Project met a minimum of EPA Tier 3 standards.
- 2. Monitoring for special-status species and inspections for wildlife was implemented to avoid and minimize impacts to biological resources. Construction activities, including vegetation removal, within the Stonebridge Staging Yard and Driving Range Staging Yard were initiated outside of the nesting season and construction activities remain ongoing. Nest surveys were conducted on April 10, 11, 12 and 13, 2017. Nest Bird Survey Reports were submitted to the CPUC on April 11 and 14, 2017. Daily nest monitoring occurred on April 10, 11, 12, 13 and 14, 2017 in areas of active construction where nest buffer reduction requests had been approved and active construction was occurring. All project equipment arrived clean and free of mud and/or vegetation.
- 3. During this reporting period, cultural, paleontological, and Native American monitors were on site for ground-disturbing activities in areas with moderate to high potential to encounter resources. Cultural, Native American and paleontological monitoring of potholing activities conducted with a vacuum truck was reduced during this reporting period as recommended by the CPUCapproved Qualified Paleontologist and CPUC-approved cultural resources specialist/archaeologist since the work was being performed in previously disturbed fill materials, and the potential to encounter paleontologically-sensitive deposits or archaeological resources during potholing was determined to be low. No cultural, Native American, or paleontological resources were identified during this reporting period.
- 4. All trash and debris was properly contained and removed. All vehicles and equipment were checked for leaks. No reportable releases and/or spills occurred during this reporting period.
- 5. Daytime construction activities during this reporting period were confined to Monday through Friday and occurred between 7:00 a.m. and 5:30 p.m. A noise permit was obtained from the City of San Diego for nighttime construction activities. Nighttime construction activities were confined to Sunday through Thursday and occurred between 9:00 p.m. and 5:00 a.m.
- 6. Project personnel parked their personal vehicles within a designated personal vehicle parking area within the project limits within the Stonebridge Staging Yard. Workers parked within the work limits of the Driving Range Staging Yard or parked on the adjacent public street.
- 7. No precipitation was recorded in the on-site rain gauges at Driving Range or Stonebridge Staging Yards. The Qualified Storm Water Pollution Prevention Plan Practitioner (QSP) conducted visual inspections at the Stonebridge and Driving Range Staging Yards, and along the underground transmission line section on April 10-14. During this reporting period, the QSP observed that the inlet

protections BMPs (gravel bags) were frequently being damaged by vehicles running over the gravel bags. As a result, damaged gravel bags were being frequently replaced. The QSP suggested more durable BMP (Durabags) to mitigate repetitive gravel bag breakage in high traffic areas. On April 11 and April 12, 2017, the contractor installed Durabags in high traffic areas. Additionally, the contractor installed and maintained BMPs along the right-of-way (ROW) in Segment 5. The installed BMPs consist of gravel bags and filter fabric protection used for storm drain inlet protection during vault excavation, potholing, and sawcutting activities. During saw-cutting activities, a vacuum is used to collect water runoff, and a street cleaner is used during and at the end of the work day to mitigate excess sediment accumulation on the ROW.

- 8. All construction and compliance personnel on site during this reporting period completed the Project Safety and Environmental Awareness Program (SEAP). To date, approximately 500 Project personnel have received the required SEAP training, and 386 Project personnel have received the UXO training.
- 9. No Compliance Level Incidents or Project Memoranda were issued during the subject period.

10. No public complaints were received during this reporting period.

Agency Representatives during Construction (other than CPUC EMs): None

CPUC NOTICES TO PROCEED (NTPs)

Table 1 summarizes the CPUC NTP activity for the SDG&E Sycamore-Peñasquitos 230-kV Transmission Line Project to date.

Date	Date		
Submitted	Issued	Segment #	Description
12/05/16	12/29/16	N/A	Mobilize and begin operations at the construction staging yards.
01/23/17	02/07/17	Segment B	Construct the underground portion of the Project from Sycamore Substation to Structure P03, and from Structure P05 to Structure CC MM CP.
02/03/17	02/27/17	Segment A	 Overhead construction from Sycamore Substation to Structure P06
		Segment C	2. Overhead construction from Structure CC MM CP to the Peñasquitos Substation
			3. Deepwell AC mitigation installation
			 Construction activities at Sycamore Canyon and Peñasquitos Substations
	01/23/17	01/23/17 02/07/17	01/23/17 02/07/17 Segment 02/03/17 02/27/17 Segment A Segment

Table 1 CPUC NTPs

MINOR PROJECT REFINEMENT & TEMPORARY EXTRA WORKSPACE REQUESTS

Tables 2 and 3 summarize the Minor Project Refinements (MPRs) and Temporary Extra Workspace (TEWS) Requests have been submitted to date.

MPR Request	Date Submitted	Date Issued	Segment #	Description
#1	12/06/16	1/11/17	Segment A	Underground 230-kV getaway from Sycamore Substation to Structure P03.
#2	01/17/17	01/24/17	Segment B	Realignment of the 230-kV underground transmission line from Miramar Road north on Black Mountain Road and west on Activity Road.
#3	03/06/17	03/08/17	Segment A	Provides temporary power to the SDG&E trailer at the Stonebridge Staging Yard through the existing power box located outside of the existing Project boundary.

Table 2 Minor Project Refinement (MPR) Requests

Table 3	Temporary	Extra Workspace	(TFWS) Request	2
Tuble 3	remporary	EXILU WORKSPUCE	(IEWS) Kequesi	2

TEWS	Date	Date	Segment	Description
Request	Submitted	Issued	#	
None to date				

NON-COMPLIANCES, PROJECT MEMORANDA & INCIDENTS

No Compliance Level Incidents or Project Memoranda were issued during the subject period.

Table 4 Non-Compliances, Project Memoranda, and Other Incidents

Туре	Date	Location	Description
Level 1	04/12/2017	Segment B	Potable water was used in a street sweeper.

ATTACHMENT A INSPECTION REPORTS

Sycamore-Peñasquitos 230-kV Transmission Line Project Weekly Report #15 5

2017-04-09 Sycamore-Peñasquitos Inspection Report

SDG&E Sycamore-Peñasquitos 230-kV Transmission Line Project: Daily Inspection Report

Inspection Date	2017-04-09
Start Time	19:45:00
End Time	23:30:00
Monitor Name	Dave Flietner
Organization	The Sanberg Group (Sanberg)
Summary of Construction Activities	Excavation for vault and potholing are scheduled. (Not observed before 11:30).
Summary of Compliance Activities	LEI, cultural, Native, and paleontological monitors were or hand to monitor soil disturbing activity.
Were any issues encountered?	No

Photo Log

Photo



Caption

Preparing shield for vault excavation.

Photo Attributes

Capture Date/Time: Sun Apr 09 2017 23:19:14 GMT-0700 (PDT) Coordinates: 32.889272, -117.159022 View Direction: Southeast

Photo



Caption

Crew installing inlet protection on Carroll Rd.

Photo Attributes Capture Date/Time: Sun Apr 09 2017 21:50:31 GMT-0700 (PDT) Coordinates: 32.884991, -117.172359 View Direction: East



n Flaggers at west end of Trade St.

Photo Attributes Capture Date/Time: Sun Apr 09 2017 21:33:48 GMT-0700 (PDT) Coordinates: 32.88863, -117.160888 View Direction: West

Photo



Caption

Three flaggers at east end of work zone (Carroll & Trade St.).

Photo Attributes Capture Date/Time: Sun Apr 09 2017 21:09:39 GMT-0700 (PDT) Coordinates: 32.88927, -117.158309 View Direction: West

Daily Checklist

Q1 – General Avoidance and Minimization: (a) Were the limits of work areas and access roads clearly marked? (b) Were construction activities limited to CPUC-approved work areas?

Q2 – Air Quality/GHG: (a) Were dust avoidance and minimization requirements implemented and monitored adequately? (b) Was dust generation below required thresholds? (c) Were equipment and vehicles maintained and operated in a manner to limit emissions? (d) Was organic waste collected and separated from non-organic waste for appropriate composting or recycling, as appropriate?

Q2 Notes

Q3 – Special-Status Plants: Were impact avoidance and minimization requirements for special-status plants implemented adequately (e.g., avoiding sensitive areas)?

Q4 – Wildlife (Non-Avian): Were impact avoidance and minimization requirements for wildlife implemented adequately (e.g., avoiding sensitive areas, covering excavations, and inspecting equipment/trenches)?

Q5 – Nesting and Burrowing Birds: (a) Were active nests and occupied burrows identified and monitored during applicable

Met Requirements

Met Requirements

I didn't observe trash cans or other waste collection, but didn't see any litter either. It's likely that individuals are placing waste in their vehicles.

N/A

Met Requirements

seasons, as required? (b) Were impact avoidance and minimization requirements for any active nests or occupied burrows implemented adequately?	
$\ensuremath{Q6}$ – Water Features and Aquatic Habitat: Were water features avoided?	N/A
Q7 – Stormwater, Erosion, and Sediment Control: (a) Were erosion and sediment control BMPs in place and functioning properly? (b) Were inactive or completed work areas stabilized and/or restored adequately?	Met Requirements
Q7 Notes	Inlet protection installed throughout work zone and was being placed in nearby areas.
Q8 – Invasive Weed Control: Were procedures to prevent the spread of invasive weeds implemented adequately?	Met Requirements
Q9 – Hazardous Materials and Waste Management: (a) Were hazardous materials stored and labeled properly? (b) Was hazardous material waste disposed of appropriately? (c) Were any spills or leaks addressed adequately? (d) Was solid waste collected and disposed of adequately?	Met Requirements
Q9 Notes	
Q10 – Fire Management: (a) Were fire prevention procedures in place? (b) Was firefighting equipment available on site?	Met Requirements
Q11 – Cultural, Paleontological, and Tribal Resources: (a) Were cultural, paleontological, and tribal resources monitoring and impact avoidance occurring as required? (b) If potential resources or human remains were inadvertently discovered, were response procedures and protocols implemented as required?	Met Requirements
Q11 Notes	Two crews of cultural, Native, and paleontological monitors working: one set to monitor excavation of vault, the other to spot check between two sites for potholing.
Q12 – Construction Noise: (a) Were noise minimization measures in place, as required? (b) If noise complaints were received, were they documented and addressed, as required?	Met Requirements
Q13 – Maintain Access: (a) Was access to driveways (e.g., businesses, schools, residences) maintained as required? (b) Was access to recreational areas maintained and appropriate signage installed? (c) Was pedestrian and bicycle access maintained, or were detours clearly defined?	Met Requirements
Q13 Notes	
Q14 – Traffic Control (a) Were flaggers present at all times? (b) Were barriers, cones, and signs in place? (c) Were detours clearly marked?	Met Requirements
Q14 Notes	Flaggers present at both ends of work and cones and signs placed properly. Traffic was light and was mostly construction vehicles.
Q15 – Helicopter Use (a) Were helicopter use restrictions implemented adequately? (b) Were helicopter take-off and landing sites within prescribed limits?	N/A
Q16 – Worker Training and Communication: Have all workers on site received the required environmental trainings for the project?	Met Requirements
Q17 – MMCRP Implementation: (a) Were project activities consistent with the approved project as defined in the EIR and subsequent CPUC authorizations? (b) Were MMCRP procedures implemented adequately?	

2017-40-10 AM Inspection Report

SDG&E Sycamore-Peñasquitos 230-kV Transmission Line Project: Daily Inspection Report	
Inspection Date	2017-04-10
Start Time	09:31:00
End Time	10:26:00
Monitor Name	Dave Flietner
Organization	The Sanberg Group (Sanberg)
Summary of Construction Activities	No activity. Daylight inspection.
Summary of Compliance Activities	No monitors. Daylight inspection.
Were any issues encountered?	No

Photo Log

Photo



Caption

Filter functioning but gravel bags damaged (right turn lane, Camino Santa Fe at Trade S

Photo Attributes Capture Date/Time: Mon Apr 10 2017 10:06:26 GMT-0700 (PDT) Coordinates: 32.888471, -117.16756 View Direction: North

Photo



Caption

Trash and organic waste. (I don't recall seeing this last night).

Photo Attributes Capture Date/Time: Mon Apr 10 2017 09:54:48 GMT-0700 (PDT) Coordinates: 32.888872, -117.159788 View Direction: West



Photo Attributes Capture Date/Time: Mon Apr 10 2017 09:50:01 GMT-0700 (PDT) Coordinates: 32.889158, -117.157205

Photo



Caption

Photo Attributes Capture Date/Time: Mon Apr 10 2017 09:47:49 GMT-0700 (PDT) Coordinates: 32.88915, -117.156286 View Direction: East

Photo



CaptionStorage for vault shoring and equipment (Trade St. East of Carroll).Photo AttributesCapture Date/Time: Mon Apr 10 2017 09:45:08 GMT-0700 (PDT)

Coordinates: 32.889277, -117.156162 View Direction: South

Photo



Caption Vault cover does not impede traffic.

Photo Attributes Capture Date/Time: Mon Apr 10 2017 09:39:17 GMT-0700 (PDT) Coordinates: 32.889029, -117.159637 View Direction: Southwest

Photo



Caption

Inlet protection.



Photo



Caption	Saw cut area.	
	Capture Date/Time: Mon Apr 10 2017 09:35	:21 GMT-0700 (PDT)
	Coordinates: 32.88876, -117.161193 View Direction: Southwest	
	Daily Checklist	
Q1 – General Avoidance and Minimization: (a) Were the limits of work areas and access roads clearly marked? (b) Were construction activities limited to CPUC-approved work areas?		Met Requirements
minimization requ adequately? (b) V thresholds? (c) V and operated in a organic waste co	GHG: (a) Were dust avoidance and uirements implemented and monitored Was dust generation below required Vere equipment and vehicles maintained a manner to limit emissions? (d) Was llected and separated from non-organic riate composting or recycling, as	Met Requirements
Q2 Notes		I observed pizza box, orange peels and napkin near job site. I don't recall seeing this when I walked the area (twice) last night.
minimization requ	tus Plants: Were impact avoidance and uirements for special-status plants equately (e.g., avoiding sensitive areas)?	Met Requirements
minimization requadequately (e.g.,	n-Avian): Were impact avoidance and uirements for wildlife implemented avoiding sensitive areas, covering inspecting equipment/trenches)?	Met Requirements
occupied burrows seasons, as requ minimization requ	d Burrowing Birds: (a) Were active nests and s identified and monitored during applicable hired? (b) Were impact avoidance and uirements for any active nests or occupied ented adequately?	Met Requirements
Q6 – Water Feat features avoided	ures and Aquatic Habitat: Were water ?	Met Requirements
erosion and sedi properly? (b) We	, Erosion, and Sediment Control: (a) Were ment control BMPs in place and functioning re inactive or completed work areas restored adequately?	Met Requirements
Q7 Notes		Filter fabrics at inlets functioning. Gravel bags at corner of Camino Santa Fe and Trade St. have been damaged. LEI informed.
	eed Control: Were procedures to prevent the eweeds implemented adequately?	Met Requirements
Were hazardous Was hazardous r Were any spills c	Materials and Waste Management: (a) materials stored and labeled properly? (b) material waste disposed of appropriately? (c) or leaks addressed adequately? (d) Was cted and disposed of adequately?	Met Requirements
	gement: (a) Were fire prevention ace? (b) Was firefighting equipment available	Met Requirements
Were cultural, pa monitoring and ir If potential resou	Paleontological, and Tribal Resources: (a) leontological, and tribal resources npact avoidance occurring as required? (b) rces or human remains were inadvertently response procedures and protocols required?	Met Requirements
measures in plac	on Noise: (a) Were noise minimization e, as required? (b) If noise complaints were ey documented and addressed, as	Met Requirements
businesses, scho (b) Was access t appropriate signa	Access: (a) Was access to driveways (e.g., ools, residences) maintained as required? o recreational areas maintained and age installed? (c) Was pedestrian and aintained, or were detours clearly defined?	Met Requirements
	ntrol (a) Were flaggers present at all times? , cones, and signs in place? (c) Were arked?	Met Requirements
implemented ade	Use (a) Were helicopter use restrictions equately? (b) Were helicopter take-off and in prescribed limits?	Met Requirements
	aining and Communication: Have all eceived the required environmental trainings	Met Requirements

for the project?

Q17 – MMCRP Implementation: (a) Were project activities consistent with the approved project as defined in the EIR and subsequent CPUC authorizations? (b) Were MMCRP procedures implemented adequately?

Met Requirements

2017-04-10 PM Inspection Report

SDG&E Sycamore-Peñasquitos 230-kV Transmission Line Project: Daily Inspection Report	
Inspection Date	2017-04-10
Start Time	20:00:00
End Time	00:00:00
Monitor Name	Jerry Scott
Organization	The Sanberg Group (Sanberg)
Summary of Construction Activities	Crews are cutting asphalt, excavating, installing, shoring, and installing steel plates.
Summary of Compliance Activities	All monitors were present. All BMP's were in place and in good working order. Fire prevention measures were in practice with barriers and extinguishers. Cones, markers, signage, and flaggers were in place. Dust was at a minimum and no vehicles were observed idling over 5 minutes
Were any issues encountered?	No

Photo Log

Photo



Caption

Lighting and flaggers in place.

Photo Attributes Capture Date/Time: Mon Apr 10 2017 22:46:39 GMT-0700 (PDT) Coordinates: 32.888972, -117.159225 View Direction: North



n Little to no dust being created.


Photo Attributes Capture Date/Time: Mon Apr 10 2017 22:44:18 GMT-0700 (PDT) Coordinates: 32.888957, -117.159336 View Direction: West

Photo



Caption BMP's in place for SWPPP

Photo Attributes Capture Date/Time: Mon Apr 10 2017 21:25:40 GMT-0700 (PDT) Coordinates: 32.888995, -117.159151 View Direction: West



Cutting asphalt with fire barrier in place. Capture Date/Time: Mon Apr 10 2017 21:19:54 GMT-0700 (PDT) Coordinates: 32.889067, -117.159520 Photo Attributes

View Direction: Southwest

Photo



Caption

Cones, lighting, and flaggers in place.

Capture Date/Time: Mon Apr 10 2017 21:16:14 GMT-0700 (PDT) Coordinates: 32.888985, -117.159149 Photo Attributes View Direction: Northeast

Daily Checklist

Q1 - General Avoidance and Minimization: (a) Were the limits of work areas and access roads clearly marked? (b) Were construction activities limited to CPUC-approved work areas?

Q1 Notes

Met Requirements

Work was performed within approved work limits. Work areas were clearly marked. Met Requirements

Q2 - Air Quality/GHG: (a) Were dust avoidance and minimization requirements implemented and monitored adequately? (b) Was dust generation below required thresholds? (c) Were equipment and vehicles maintained and operated in a manner to limit emissions? (d) Was organic waste collected and separated from non-organic waste for appropriate composting or recycling, as appropriate? Q2 Notes Dust was kept to a minimum and no vehicles were observed idling over 5 minutes Q3 - Special-Status Plants: Were impact avoidance and Met Requirements minimization requirements for special-status plants implemented adequately (e.g., avoiding sensitive areas)? Q3 Notes No sensitive species within the work area. Q4 - Wildlife (Non-Avian): Were impact avoidance and Met Requirements minimization requirements for wildlife implemented adequately (e.g., avoiding sensitive areas, covering excavations, and inspecting equipment/trenches)? Q4 Notes No sensitive areas within this section of work. Q5 - Nesting and Burrowing Birds: (a) Were active nests and Met Requirements occupied burrows identified and monitored during applicable seasons, as required? (b) Were impact avoidance and minimization requirements for any active nests or occupied burrows implemented adequately? Q5 Notes No nests observed within this section. Q6 - Water Features and Aquatic Habitat: Were water Met Requirements features avoided? Q6 Notes No water features within this section of work. Q7 - Stormwater, Erosion, and Sediment Control: (a) Were Met Requirements erosion and sediment control BMPs in place and functioning properly? (b) Were inactive or completed work areas stabilized and/or restored adequately? Q7 Notes All SWPPP BMP's were in place and in good working order Q8 - Invasive Weed Control: Were procedures to prevent the Met Requirements spread of invasive weeds implemented adequately? Q8 Notes None in this section of work. Q9 - Hazardous Materials and Waste Management: (a) Were Met Requirements hazardous materials stored and labeled properly? (b) Was hazardous material waste disposed of appropriately? (c) Were any spills or leaks addressed adequately? (d) Was solid waste collected and disposed of adequately? **Q9** Notes No spills or hazardous materials observed. Q10 - Fire Management: (a) Were fire prevention procedures Met Requirements in place? (b) Was firefighting equipment available on site? Q10 Notes Fire protection prevention practices were in place. Q11 - Cultural, Paleontological, and Tribal Resources: (a) Met Requirements Were cultural, paleontological, and tribal resources monitoring and impact avoidance occurring as required? (b) If potential resources or human remains were inadvertently discovered, were response procedures and protocols implemented as required? Q11 Notes All monitors were on site Q12 - Construction Noise: (a) Were noise minimization Met Requirements measures in place, as required? (b) If noise complaints were received, were they documented and addressed, as required? Q12 Notes Noise minimization was in place and no complaints were reported regarding noise Q13 - Maintain Access: (a) Was access to driveways (e.g. Met Requirements businesses, schools, residences) maintained as required? (b) Was access to recreational areas maintained and appropriate signage installed? (c) Was pedestrian and bicycle access maintained, or were detours clearly defined? Q13 Notes Access to local business was maintained throughout the evening. Q14 - Traffic Control (a) Were flaggers present at all times? Met Requirements (b) Were barriers, cones, and signs in place? (c) Were detours clearly marked? Q14 Notes Cones, flaggers, and signage were in place at all times. Q15 - Helicopter Use (a) Were helicopter use restrictions N/A implemented adequately? (b) Were helicopter take-off and landing sites within prescribed limits? Q15 Notes None in use

Q16 – Worker Training and Communication: Have all workers on site received the required environmental trainings for the project?

Q16 Notes

Q17 – MMCRP Implementation: (a) Were project activities consistent with the approved project as defined in the EIR and subsequent CPUC authorizations? (b) Were MMCRP procedures implemented adequately?

Q17 Notes

Met Requirements

All workers on site were properly trained and displayed the required stickers on their hard hats.

Met Requirements

All mitigation measures were observed and in place

2017-04-11 AM Inspection Report

SDG&E Sycamora Beñesquitas 220 kV	
SDG&E Sycamore-Peñasquitos 230-kV Transmission Line Project: Daily	
Inspection Report	
Inspection Date	2017-04-11
Start Time	04:00:00
End Time	06:00:00
Monitor Name	Jerry Scott
Organization	The Sanberg Group (Sanberg)
Summary of Construction Activities	Crews cut asphalt, excavated, installed shoring, as well as steel plates
Summary of Compliance Activities	All monitors were present. All barriers, cones, flaggers, and signage were in place. Adequate lighting was in place. Dust was at a minimum and no vehicles were observed idling over 5 minutes.
Were any issues encountered?	No
Photo Log	

Caption

Dumpsters were covered.

Photo Attributes Capture Date/Time: Tue Apr 11 2017 05:31:30 GMT-0700 (PDT) Coordinates: 32.891137, -117.191623 View Direction: Southwest



Photo

Shaker plates in place at material yard.

Photo Attributes Capture Date/Time: Tue Apr 11 2017 05:27:21 GMT-0700 (PDT) Coordinates: 32.891194, -117.191673 View Direction: East



Caption

Signage in place for idling as well as rattlesnake warning.

Photo Attributes

Capture Date/Time: Tue Apr 11 2017 05:25:39 GMT-0700 (PDT) Coordinates: 32.891241, -117.191847 View Direction: Northeast



Flaggers in place directing traffic Photo Attributes Capture Date/Time: Tue Apr 11 2017 04:49:01 GMT-0700 (PDT) Coordinates: 32.889136, -117.159190

View Direction: East

Photo



Caption

Steel plates installed to cover trenches.

Capture Date/Time: Tue Apr 11 2017 04:46:05 GMT-0700 (PDT) Coordinates: 32.889020, -117.159640 Photo Attributes View Direction: South

Daily Checklist

Q1 – General Avoidance and Minimization: (a) Were the limits of work areas and access roads clearly marked? (b) Were construction activities limited to CPUC-approved work areas?

Q1 Notes

Limits of work areas and access roads were clearly marked.

Q2 - Air Quality/GHG: (a) Were dust avoidance and

Met Requirements

Met Requirements

minimization requirements implemented and monitored adequately? (b) Was dust generation below required thresholds? (c) Were equipment and vehicles maintained and operated in a manner to limit emissions? (d) Was organic waste collected and separated from non-organic waste for appropriate composting or recycling, as appropriate? Q2 Notes No random dust nor idling vehicles were observed. Q3 - Special-Status Plants: Were impact avoidance and N/A minimization requirements for special-status plants implemented adequately (e.g., avoiding sensitive areas)? Q3 Notes No sensitive species in this section were observed. Q4 - Wildlife (Non-Avian): Were impact avoidance and Met Requirements minimization requirements for wildlife implemented adequately (e.g., avoiding sensitive areas, covering excavations, and inspecting equipment/trenches)? All excavations were covered with steel plates and sealed with asphalt. Q4 Notes Q5 – Nesting and Burrowing Birds: (a) Were active nests and $\,$ N/A occupied burrows identified and monitored during applicable seasons, as required? (b) Were impact avoidance and minimization requirements for any active nests or occupied burrows implemented adequately? Q5 Notes No nesting birds observed in this section. Q6 - Water Features and Aquatic Habitat: Were water N/A features avoided? Q6 Notes No water features in this section. Q7 - Stormwater, Erosion, and Sediment Control: (a) Were Met Requirements erosion and sediment control BMPs in place and functioning properly? (b) Were inactive or completed work areas stabilized and/or restored adequately? Q7 Notes All BMP's were in place and in good working order. Q8 – Invasive Weed Control: Were procedures to prevent the N/A spread of invasive weeds implemented adequately? No off road work in this section. Q8 Notes Q9 - Hazardous Materials and Waste Management: (a) Met Requirements Were hazardous materials stored and labeled properly? (b) Was hazardous material waste disposed of appropriately? (c) Were any spills or leaks addressed adequately? (d) Was solid waste collected and disposed of adequately? Q9 Notes Hazardous materials were properly labeled and stored at the Driving Range storage yard. Q10 - Fire Management: (a) Were fire prevention Met Requirements procedures in place? (b) Was firefighting equipment available on site? Q10 Notes Fire prevention practices were in place. Q11 - Cultural, Paleontological, and Tribal Resources: (a) Met Requirements Were cultural, paleontological, and tribal resources monitoring and impact avoidance occurring as required? (b) If potential resources or human remains were inadvertently discovered, were response procedures and protocols implemented as required? Q11 Notes All monitors were on site. Q12 - Construction Noise: (a) Were noise minimization Met Requirements measures in place, as required? (b) If noise complaints were received, were they documented and addressed, as required? Q12 Notes No noise complaints were reported. Q13 - Maintain Access: (a) Was access to driveways (e.g., Met Requirements businesses, schools, residences) maintained as required? (b) Was access to recreational areas maintained and appropriate signage installed? (c) Was pedestrian and bicycle access maintained, or were detours clearly defined? Q13 Notes Access to local business and driveways were maintained. Q14 - Traffic Control (a) Were flaggers present at all times? Met Requirements (b) Were barriers, cones, and signs in place? (c) Were detours clearly marked? Q14 Notes Flaggers, cones, and signage were all in place. Q15 - Helicopter Use (a) Were helicopter use restrictions N/A implemented adequately? (b) Were helicopter take-off and landing sites within prescribed limits?

Q15 Notes

Q16 – Worker Training and Communication: Have all workers on site received the required environmental trainings for the project?

Q16 Notes

Q17 – MMCRP Implementation: (a) Were project activities consistent with the approved project as defined in the EIR and subsequent CPUC authorizations? (b) Were MMCRP procedures implemented adequately?

Q17 Notes

No helicopters in use.

Met Requirements

All employees were properly trained and displayed stickers on their hard hats.

Met Requirements

Project activities were consistent with regulations and mitigation measures were implemented.

2017-04-11 PM Inspection Report

No

SDG&E Sycamore-Peñasquitos 230-kV Transmission Line Project: Daily Inspection Report Inspection Date 2017-04-11 Start Time 20:00:00 End Time 00:26:00 Monitor Name Jerry Scott Organization The Sanberg Group (Sanberg) Summary of Construction Activities Crews will be cutting asphalt, potholing, and welding. Summary of Compliance Activities All BMP's were in place and in good working order. All monitors were on site. All fire preventive measures were in place and ingood working order. All monitors were on site. All ne All signage, lighting, barriers, cones, and flaggers were in place.

Were any issues encountered?


Photo



Caption

Digital signage in place at entrances to work areas.

Photo Attributes Capture Date/Time: Tue Apr 11 2017 23:05:55 GMT-0700 (PDT) Coordinates: 32.885436, -117.168272 View Direction: West



Excavation of trench with shoring in place. Photo Attributes Capture Date/Time: Tue Apr 11 2017 22:48:42 GMT-0700 (PDT) Coordinates: 32.889152, -117.159430 View Direction: Southwest

Photo



Caption BMP's in place for SWPPP.

Photo Attributes Capture Date/Time: Tue Apr 11 2017 22:33:03 GMT-0700 (PDT) Coordinates: 32.889186, -117.153233 View Direction: South



Photo Attributes Capture Date/Time: Tue Apr 11 2017 21:57:30 GMT-0700 (PDT) Coordinates: 32.892188, -117.185660 View Direction: Northwest

Photo



Caption

Lighting, cones, and flaggers in place for traffic safety.

Photo Attributes Capture Date/Time: Tue Apr 11 2017 21:04:56 GMT-0700 (PDT) Coordinates: 32.888933, -117.158923 View Direction: North

Daily Checklist

Q1 – General Avoidance and Minimization: (a) Were the limits of work areas and access roads clearly marked? (b) Were construction activities limited to CPUC-approved work areas?

Q1 Notes

Met Requirements

Work area limits and access roads were clearly marked and limited to CPUC-approved areas.

Q2 – Air Quality/GHG: (a) Were dust avoidance and minimization requirements implemented and monitored

Met Requirements

adequately? (b) Was dust generation below required thresholds? (c) Were equipment and vehicles maintained and operated in a manner to limit emissions? (d) Was organic waste collected and separated from non-organic waste for appropriate composting or recycling, as appropriate? Q2 Notes All air quality preventive measures were practiced and in place. No vehicles were observed idling over the 5 minute limit. Q3 - Special-Status Plants: Were impact avoidance and N/A minimization requirements for special-status plants implemented adequately (e.g., avoiding sensitive areas)? Q3 Notes No sensitive species in the work areas. Q4 - Wildlife (Non-Avian): Were impact avoidance and Met Requirements minimization requirements for wildlife implemented adequately (e.g., avoiding sensitive areas, covering excavations, and inspecting equipment/trenches)? Q4 Notes No sensitive species or wildlife was observed in the area. Q5 - Nesting and Burrowing Birds: (a) Were active nests and N/A occupied burrows identified and monitored during applicable seasons, as required? (b) Were impact avoidance and minimization requirements for any active nests or occupied burrows implemented adequately? Q5 Notes No nesting or burrowing birds were within the work areas. Q6 - Water Features and Aquatic Habitat: Were water features N/A avoided? Q6 Notes No water features were within the work areas. Q7 - Stormwater, Erosion, and Sediment Control: (a) Were Met Requirements erosion and sediment control BMPs in place and functioning properly? (b) Were inactive or completed work areas stabilized and/or restored adequately? Q7 Notes All BMP's were in place and in good working order. Q8 - Invasive Weed Control: Were procedures to prevent the Met Requirements spread of invasive weeds implemented adequately? Q8 Notes N/A Q9 - Hazardous Materials and Waste Management: (a) Were Met Requirements hazardous materials stored and labeled properly? (b) Was hazardous material waste disposed of appropriately? (c) Were any spills or leaks addressed adequately? (d) Was solid waste collected and disposed of adequately? Q9 Notes All hazardous waste measures and waste management practices were in compliance. Q10 – Fire Management: (a) Were fire prevention procedures in Met Requirements place? (b) Was firefighting equipment available on site? All rite prevention measures were in use and in place. Q10 Notes Q11 - Cultural, Paleontological, and Tribal Resources: (a) Were Met Requirements cultural, paleontological, and tribal resources monitoring and impact avoidance occurring as required? (b) If potential resources or human remains were inadvertently discovered, were response procedures and protocols implemented as required? All monitors were on site. Q11 Notes Q12 - Construction Noise: (a) Were noise minimization Met Requirements measures in place, as required? (b) If noise complaints were received, were they documented and addressed, as required? All noise levels were kept within compliance levels. Q12 Notes Q13 - Maintain Access: (a) Was access to driveways (e.g. Met Requirements businesses, schools, residences) maintained as required? (b) Was access to recreational areas maintained and appropriate signage installed? (c) Was pedestrian and bicycle access maintained, or were detours clearly defined? Q13 Notes All access to local business and driveways were maintained. Q14 - Traffic Control (a) Were flaggers present at all times? (b) Met Requirements Were barriers, cones, and signs in place? (c) Were detours clearly marked? Q14 Notes All traffic safety measures were in place and in use. Q15 - Helicopter Use (a) Were helicopter use restrictions N/A implemented adequately? (b) Were helicopter take-off and landing sites within prescribed limits?

Q15 Notes

Q16 – Worker Training and Communication: Have all workers on site received the required environmental trainings for the project?

Q16 Notes

Q17 – MMCRP Implementation: (a) Were project activities consistent with the approved project as defined in the EIR and subsequent CPUC authorizations? (b) Were MMCRP procedures implemented adequately?

Q17 Notes

No helicopters were used.

Met Requirements

All personnel had training stickers on their hard hats.

Met Requirements

All activities were within compliance measures and mitigation.

2017-04-14 AM Inspection Report

SDG&E Sycamore-Peñasquitos 230-kV Transmission Line Project: Daily Inspection Report	
Inspection Date	2017-04-12
Start Time	04:00:00
End Time	06:00:00
Monitor Name	Jerry Scott
Organization	The Sanberg Group (Sanberg)
Summary of Construction Activities	Crews cut asphalt, excavated, potholed, did welding, and street sweeping for clean-up.
Summary of Compliance Activities	All BMP's were in place. Fire and dust prevention practices were in place, as well as noise reduction. All cones, markers, barriers, signage as well as flaggers were in place for traffic safety.
Were any issues encountered?	No

Were any issues encountered?

Photo

Photo Log	
Photo Log	3
	1 3

Caption

Digital construction signage in place.

Photo Attributes Capture Date/Time: Wed Apr 12 2017 05:17:06 GMT-0700 (PDT) Coordinates: 32.888580, -117.167159 View Direction: Southeast



Shaker plates in place to prevent track out.

Photo Attributes Capture Date/Time: Wed Apr 12 2017 05:15:17 GMT-0700 (PDT) Coordinates: 32.891168, -117.191703 View Direction: North

Photo



Caption

Dumpsters were covered to contain debris.

Photo Attributes Capture Date/Time: Wed Apr 12 2017 05:13:35 GMT-0700 (PDT) Coordinates: 32.891096, -117.191588 View Direction: West



Photo

Bird netting in place to prevent nesting in equipment. Capture Date/Time: Wed Apr 12 2017 05:12:16 GMT-0700 (PDT) Photo Attributes Coordinates: 32.891106, -117.191351

View Direction: East

Caption

Hazardous material containment practices were in place.

Capture Date/Time: Wed Apr 12 2017 05:07:10 GMT-0700 (PDT) Coordinates: 32.891188, -117.191537 Photo Attributes View Direction: South

Daily Checklist

Q1 – General Avoidance and Minimization: (a) Were the limits Met Requirements of work areas and access roads clearly marked? (b) Were construction activities limited to CPUC-approved work areas?

Q1 Notes

Area work limits were clearly marked and limited to CPUC-approved areas.

Q2 - Air Quality/GHG: (a) Were dust avoidance and minimization requirements implemented and monitored Met Requirements

adequately? (b) Was dust generation below required thresholds? (c) Were equipment and vehicles maintained and operated in a manner to limit emissions? (d) Was organic waste collected and separated from non-organic waste for appropriate composting or recycling, as appropriate? Q2 Notes Dust was at a minimum and no vehicles were observed idling over the 5minute limit. Q3 - Special-Status Plants: Were impact avoidance and N/A minimization requirements for special-status plants implemented adequately (e.g., avoiding sensitive areas)? Q3 Notes No sensitive specie were in thus section of work. Q4 - Wildlife (Non-Avian): Were impact avoidance and Met Requirements minimization requirements for wildlife implemented adequately (e.g., avoiding sensitive areas, covering excavations, and inspecting equipment/trenches)? Q4 Notes Little to no wildlife in this section. Steel plates were put in place. Q5 - Nesting and Burrowing Birds: (a) Were active nests and N/A occupied burrows identified and monitored during applicable seasons, as required? (b) Were impact avoidance and minimization requirements for any active nests or occupied burrows implemented adequately? Q5 Notes No nesting or burrowing birds within the work area limits of this section of work. N/A Q6 - Water Features and Aquatic Habitat: Were water features avoided? Q6 Notes No water features in this section of work. Q7 - Stormwater, Erosion, and Sediment Control: (a) Were Met Requirements erosion and sediment control BMPs in place and functioning properly? (b) Were inactive or completed work areas stabilized and/or restored adequately? Q7 Notes All BMP's were in place to be in compliance with SWPPP. Q8 - Invasive Weed Control: Were procedures to prevent the N/A spread of invasive weeds implemented adequately? Q8 Notes No off road work in this area of construction. Q9 - Hazardous Materials and Waste Management: (a) Were Met Requirements hazardous materials stored and labeled properly? (b) Was hazardous material waste disposed of appropriately? (c) Were any spills or leaks addressed adequately? (d) Was solid waste collected and disposed of adequately? Q9 Notes Hazardous materials were clearly labeled and stored with secondary containment measures in place. Q10 - Fire Management: (a) Were fire prevention procedures Met Requirements in place? (b) Was firefighting equipment available on site? Q10 Notes Fire barriers were used and extinguishers present to be in compliance with fire safety measures. Q11 - Cultural, Paleontological, and Tribal Resources: (a) Met Requirements Were cultural, paleontological, and tribal resources monitoring and impact avoidance occurring as required? (b) If potential resources or human remains were inadvertently discovered, were response procedures and protocols implemented as required? All monitors were on site to protect and document any discoveries or Q11 Notes concerns. Q12 - Construction Noise: (a) Were noise minimization Met Requirements measures in place, as required? (b) If noise complaints were received, were they documented and addressed, as required? Q12 Notes Construction noise levels were kept to a minimum. Q13 - Maintain Access: (a) Was access to driveways (e.g. Met Requirements businesses, schools, residences) maintained as required? (b) Was access to recreational areas maintained and appropriate signage installed? (c) Was pedestrian and bicycle access maintained, or were detours clearly defined? Q13 Notes Access to local business as well as driveways were maintained throughout the work Q14 – Traffic Control (a) Were flaggers present at all times? Met Requirements (b) Were barriers, cones, and signs in place? (c) Were detours clearly marked? Q14 Notes Cones, barriers, signage, and flaggers were in place to safely control traffic. Q15 - Helicopter Use (a) Were helicopter use restrictions N/A

implemented adequately? (b) Were helicopter take-off and landing sites within prescribed limits?

Q15 Notes

Q16 – Worker Training and Communication: Have all workers on site received the required environmental trainings for the project?

Q16 Notes

Q17 – MMCRP Implementation: (a) Were project activities consistent with the approved project as defined in the EIR and subsequent CPUC authorizations? (b) Were MMCRP procedures implemented adequately?

Q17 Notes

No helicopters in use.

Met Requirements

All personnel on site had training stickers displayed on their hard hats.

Met Requirements

All mitigation measures were observed and in place for fire prevention, noise reduction, dust control, traffic control, and access.

2017-04-13 PM Inspection Report

SDG&E Sycamore-Peñasquitos 230-kV Transmission Line Project: Daily Inspection Report	
Inspection Date	2017-04-13
Start Time	19:45:00
End Time	00:00:00
Monitor Name	Korey Klutz
Organization	The Sanberg Group (Sanberg)
Summary of Construction Activities	Vault construction along Trade St, just west of Carroll Way intersection. Asphalt cutting along Trade Place south of Arjons Dr. Excavation occurring along Carrol Road.
Summary of Compliance Activities	All required monitors were on site at each job site. Monitors observed included Paleo., Arch., and Native American. Safety/Traffic control was also implemented at each site. LEI was onsite and made sure monitors were available for all required work sites.
Were any issues encountered?	No



Caption

Photo

Digital traffic control sign.

Photo Attributes Capture Date/Time: Thu Apr 13 2017 23:38:31 GMT-0700 (PDT) Coordinates: 32.889059, -117.155962 View Direction: West



Truck delivering beams to next vault site.

Photo Attributes Capture Date/Time: Thu Apr 13 2017 23:37:15 GMT-0700 (PDT) Coordinates: 32.889045, -117.155763

Photo



Caption

BMPs

Photo Attributes Capture Date/Time: Thu Apr 13 2017 23:36:20 GMT-0700 (PDT) Coordinates: 32.889078, -117.155259 View Direction: West



Vault Site on Trade St.

Photo Attributes Capture Date/Time: Thu Apr 13 2017 23:34:53 GMT-0700 (PDT) Coordinates: 32.889044, -117.155215 View Direction: West


Photo



Caption

Asphalt cutting site along Trade Place.

Capture Date/Time: Thu Apr 13 2017 23:34:09 GMT-0700 (PDT) Coordinates: 32.889035, -117.155208 View Direction: North Photo Attributes



Pot hole vacuum truck along Trade Place.

Photo Attributes Capture Date/Time: Thu Apr 13 2017 23:33:00 GMT-0700 (PDT) Coordinates: 32.889088, -117.155231 View Direction: North

Daily Checklist

Q1 – General Avoidance and Minimization: (a) Were the limits of work areas and access roads clearly marked? (b) Were construction activities limited to CPUC-approved work areas?

Q1 Notes

Q2 – Air Quality/GHG: (a) Were dust avoidance and minimization requirements implemented and monitored adequately? (b) Was dust generation below required thresholds? (c) Were equipment and vehicles maintained and operated in a manner to limit emissions? (d) Was organic waste collected and separated from non-organic waste for appropriate composting or recycling, as appropriate?

Q2 Notes

Q3 – Special-Status Plants: Were impact avoidance and minimization requirements for special-status plants implemented adequately (e.g., avoiding sensitive areas)?

Q3 Notes

Q4 – Wildlife (Non-Avian): Were impact avoidance and minimization requirements for wildlife implemented adequately (e.g., avoiding sensitive areas, covering excavations, and inspecting equipment/trenches)?

Q4 Notes

Q5 – Nesting and Burrowing Birds: (a) Were active nests and occupied burrows identified and monitored during applicable seasons, as required? (b) Were impact avoidance and minimization requirements for any active nests or occupied burrows implemented adequately?

Q5 Notes

Q6 – Water Features and Aquatic Habitat: Were water features N/A avoided?

Q6 Notes

Q7 – Stormwater, Erosion, and Sediment Control: (a) Were erosion and sediment control BMPs in place and functioning properly? (b) Were inactive or completed work areas stabilized

Met Requirements

Work was conducted within approved CPUC limits.

Met Requirements

Compliance measure were implemented at each site. Note was made at the tailboard regarding 5 minute maximum idle time.

N/A

Work not conducted within the vicinity of any special status plants.

N/A

No wildlife were encountered during site construction.

N/A

Burrowing owl nest or birds not encountered or known to be around vicinity of job site.

No water feature within or adjacent to job sites

Met Requirements

Sycamore-Penasquitos Page 4

and/or restored adequately? Q7 Notes BMPS installed as needed throughout work areas Q8 - Invasive Weed Control: Were procedures to prevent the N/A spread of invasive weeds implemented adequately? Q8 Notes Q9 - Hazardous Materials and Waste Management: (a) Were Met Requirements hazardous materials stored and labeled properly? (b) Was hazardous material waste disposed of appropriately? (c) Were any spills or leaks addressed adequately? (d) Was solid waste collected and disposed of adequately? Q9 Notes No hazardous material spills occurred. Q10 - Fire Management: (a) Were fire prevention procedures Met Requirements in place? (b) Was firefighting equipment available on site? Q11 - Cultural, Paleontological, and Tribal Resources: (a) Met Requirements Were cultural, paleontological, and tribal resources monitoring and impact avoidance occurring as required? (b) If potential resources or human remains were inadvertently discovered, were response procedures and protocols implemented as required? Q11 Notes Monitors present at required job sites. Q12 - Construction Noise: (a) Were noise minimization Met Requirements measures in place, as required? (b) If noise complaints were received, were they documented and addressed, as required? Q12 Notes No complaints reported. Q13 - Maintain Access: (a) Was access to driveways (e.g., Met Requirements businesses, schools, residences) maintained as required? (b) Was access to recreational areas maintained and appropriate signage installed? (c) Was pedestrian and bicycle access maintained, or were detours clearly defined? Q13 Notes Access was maintained throughout construction. Traffic control on site to ensure safety Q14 - Traffic Control (a) Were flaggers present at all times? Met Requirements (b) Were barriers, cones, and signs in place? (c) Were detours clearly marked? Q14 Notes Traffic plan implemented as approved. Q15 - Helicopter Use (a) Were helicopter use restrictions N/A implemented adequately? (b) Were helicopter take-off and landing sites within prescribed limits? Q16 - Worker Training and Communication: Have all workers Met Requirements on site received the required environmental trainings for the project? Q16 Notes No, 4 traffic control personnel were observed without their required SEAP stickers. LEI notified and discussion was had with traffic control representative. It is understood that all personnel onsite attended training but stickers were not available Q17 - MMCRP Implementation: (a) Were project activities Met Requirements consistent with the approved project as defined in the EIR and subsequent CPUC authorizations? (b) Were MMCRP procedures implemented adequately?

Q17 Notes

Conditions were implemented as approved. LEI will follow up with training list to ensure all traffic personnel have stickers that attended the class.

2017-04-14 AM Inspection Report

No

SDG&E Sycamore-Peñasquitos 230-kV Transmission Line Project: **Daily Inspection Report** 2017-04-14 Inspection Date Start Time 05:00:00 07:06:00 End Time Monitor Name Korey Klutz Organization The Sanberg Group (Sanberg) Summary of Construction Activities Monitor drove active project sites from the previous night's work. All work had ended. Traffic control signs and measures were actively being removed. Nighttime lighting and construction equipment were properly stored. Utiliquest contractor was observed marking project sites with spray paint on concrete/asphalt presumably for upcoming work. Summary of Compliance Activities LEI and monitors were onsite during active work. Traffic control measures implemented as permitted. All work was completed during the appropriate timelines

Were any issues encountered?

Photo Log

Photo



Caption


Rare plant population along Carrol Road near NBBR #3. Species = Atemisia palmeri.

Photo Attributes

Capture Date/Time: Fri Apr 14 2017 06:58:28 GMT-0700 (PDT) Coordinates: 32.893853, -117.151510

View Direction: West

Photo




Caption

Asphalt cut work site on Trade Place, work completed.

Photo Attributes

Capture Date/Time: Fri Apr 14 2017 06:57:19 GMT-0700 (PDT) Coordinates: 32.893853, -117.151464

Photo



Caption

Potholing and asphalt cut site along Arjons.


Photo Attributes Capture Date/Time: Fri Apr 14 2017 06:56:38 GMT-0700 (PDT) Coordinates: 32.893853, -117.151450 View Direction: North



Driving range yard.

Photo Attributes Capture Date/Time: Fri Apr 14 2017 06:42:23 GMT-0700 (PDT) Coordinates: 32.892985, -117.202877 View Direction: East

Photo





Excavation site along Carrol Road. Note construction not occurring. Capture Date/Time: Fri Apr 14 2017 06:41:33 GMT-0700 (PDT) Coordinates: 32.892986, -117.202854 View Direction: West



Hazardous material sign at driving range yard.

Photo Attributes

Thazardous material sign at unving range yard

Capture Date/Time: Fri Apr 14 2017 06:39:35 GMT-0700 (PDT) Coordinates: 32.893002, -117.202851 View Direction: North

Daily Checklist

Q1 – General Avoidance and Minimization: (a) Were the limits of work areas and access roads clearly marked? (b) Were construction activities limited to CPUC-approved work areas?

Q1 Notes

Q2 – Air Quality/GHG: (a) Were dust avoidance and minimization requirements implemented and monitored adequately? (b) Was dust generation below required thresholds? (c) Were equipment and vehicles maintained and operated in a manner to limit emissions? (d) Was organic waste collected and separated from non-organic waste for appropriate composting or recycling, as appropriate?

Q2 Notes

Q3 – Special-Status Plants: Were impact avoidance and minimization requirements for special-status plants implemented adequately (e.g., avoiding sensitive areas)?

Q3 Notes

Q4 – Wildlife (Non-Avian): Were impact avoidance and minimization requirements for wildlife implemented adequately (e.g., avoiding sensitive areas, covering excavations, and inspecting equipment/trenches)?

Q4 Notes

Q5 – Nesting and Burrowing Birds: (a) Were active nests and occupied burrows identified and monitored during applicable seasons, as required? (b) Were impact avoidance and minimization requirements for any active nests or occupied burrows implemented adequately?

Q5 Notes

Q6 – Water Features and Aquatic Habitat: Were water features avoided?

Q6 Notes

Q7 – Stormwater, Erosion, and Sediment Control: (a) Were erosion and sediment control BMPs in place and functioning properly? (b) Were inactive or completed work areas stabilized and/or restored adequately?

Q7 Notes

Met Requirements

Work conducted during permitted sites and during appropriate time limits.

Met Requirements

Measures implemented as needed.

Met Requirements

Rare plant population observed adjacent to work site on Carrol Road. No impacts observed.

N/A

No constraints known or identified during construction activities.

Met Requirements

Nesting bird buffers implemented per approvals.

Met Requirements

No water features within or adjacent to work sites.

Met Requirements

BMPS implemented per conditions of approval.

Q8 – Invasive Weed Control: Were procedures to prevent the spread of invasive weeds implemented adequately?	N/A
Q8 Notes	Invasive weeds not observed
Q9 – Hazardous Materials and Waste Management: (a) Were hazardous materials stored and labeled properly? (b) Was hazardous material waste disposed of appropriately? (c) Were any spills or leaks addressed adequately? (d) Was solid waste collected and disposed of adequately?	Met Requirements
Q9 Notes	Hazardous spill precautions and signage measures implemented per conditions of approval
Q10 – Fire Management: (a) Were fire prevention procedures in place? (b) Was firefighting equipment available on site?	Met Requirements
Q11 – Cultural, Paleontological, and Tribal Resources: (a) Were cultural, paleontological, and tribal resources monitoring and impact avoidance occurring as required? (b) If potential resources or human remains were inadvertently discovered, were response procedures and protocols implemented as required?	Met Requirements
Q11 Notes	Required monitors were on site during construction
Q12 – Construction Noise: (a) Were noise minimization measures in place, as required? (b) If noise complaints were received, were they documented and addressed, as required?	Met Requirements
Q13 – Maintain Access: (a) Was access to driveways (e.g., businesses, schools, residences) maintained as required? (b) Was access to recreational areas maintained and appropriate signage installed? (c) Was pedestrian and bicycle access maintained, or were detours clearly defined?	Met Requirements
Q13 Notes	
Q14 – Traffic Control (a) Were flaggers present at all times? (b) Were barriers, cones, and signs in place? (c) Were detours clearly marked?	Met Requirements
Q14 Notes	Traffic measures implemented per plan and permits
Q15 – Helicopter Use (a) Were helicopter use restrictions implemented adequately? (b) Were helicopter take-off and landing sites within prescribed limits?	N/A
Q16 – Worker Training and Communication: Have all workers on site received the required environmental trainings for the project?	Met Requirements
Q17 – MMCRP Implementation: (a) Were project activities consistent with the approved project as defined in the EIR and subsequent CPUC authorizations? (b) Were MMCRP procedures implemented adequately?	Met Requirements
Q17 Notes	Project requirements were observed to be in compliance with conditions of approval and MMCRP.