

Source: DOC, 2004c.

Aspen Environmental Group

Important Farmland

DCPP Steam Generator Replacement

Figure D.8-5