

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

### INTRODUCTION

During the week of 12/05/2010 through 12/11/2010, construction continued at the Alpine RFO, Alpine Construction Yards, San Luis Rey Substation, the Rough Acres Construction Yard, the Thomas Yard and Link 4 Underground.

Pre-Construction Activity with appropriate monitors:

Crews worked 12/06/2010 through 12/10/2010

Link 1: one crew each day staking towers; seed collection 1 day, habitat/cultural/PBHS assessments two days.

Link 2: one or two crews each day, staking towers.

Link 3: Suncrest Substation, spiny red berry transplanting was been completed. Plants placed on the mitigation parcel. Erosion control in place for areas where plants were removed, as needed.

Link 4: one crew conducting habitat assessment including tree height surveying. Bauer Bridge area included in tree survey.

Link 5: one to six crews conducted tower staking.

### ALL LINKS

The following is a summary of construction activity where monitors were on site:

Alpine RFO: Minimal contractor activity on site primarily for the PAR office modular office. No ground disturbing activity.

Alpine Construction Yard: Equipment and reel deliveries continued.

San Luis Rey Substation: Installation of capacitor banks and other equipment continued. Soil stockpiles removed except for small amount to be used as backfill. Work on 12/11/2010 by SDG&E crews.

Rough Acres Construction Yard: Conducted construction activity in preparation of the Groundbreaking Ceremony on 12/9/2010: leveling and placement of Class II roadbase; installation of ceremony tents and other equipment; installation of soil-stabilizer for the air crane, refreshed staking for Phase I limits. All ceremony equipment was removed by 12/10/2010 and an extra sweep of the area conducted.

A minimal number of reels were delivered during the week. Construction deliveries discontinued on 12/8/2010 and 12/9/2010.

Biological clearances began by the on-site monitor in preparation of Phase 2 Use of the site.

Encina Switchyard: No ground disturbing work being conducted. Only SDG&E on site to build and test disconnects. The next contractor to conduct Sunrise work will be Roel and they are not expected to begin set-up and construction until possibly January 3, 2011.

Thomas Yard: Deliveries of material continued, including Saturday 12/11/2010. An additional burrowing owl was observed and a buffer zone established.

Link 4 Underground: Daily three and four crews were working Link 4, on Alpine Blvd. during the week.

Crews performed potholing between Station No. 224 and 279. Saw cutting was performed for excavation for Vault No. 18. Excavation was performed for Vault No. 18.

Exploration drilling was performed for Vault No. 18 and between Vault No. 18 and No. 19.

SWEAP and Wildland Fire Prevention Training continues to be facilitated at the Ayres Inn in Alpine every Tuesday and Thursday at 7:30 a.m.

No rain event occurred during the reporting period of 12/05/2010 to 12/12/2010. No precipitation recorded.

### ENVIRONMENTAL MONITORS

#### LINK: 1

Burns & McDonnell

Kelly Goocher

---

# Sunrise Powerlink Transmission Project

Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

---

ENVIRONMENTAL MONITORS

# Sunrise Powerlink Transmission Project

Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

## ENVIRONMENTAL MONITORS

### LINK: 1

Chambers Group	Erik Strods
Chambers Group	John Kanlund
Pangea Biological	Don Spires

### LINK: 4

ASM Affiliates, Inc.	Jessica Hennessey
ASM Affiliates, Inc.	Rebekah Loveless
ASM Affiliates, Inc.	Stephen Rochester
ASM Affiliates, Inc.	Thomas Taylor
Burns & McDonnell	Ken Katsuda
Chambers Group	Seth Reimers
TRC Solutions, Inc.	Katherine Vittum
TRC Solutions, Inc.	Michael Scaffidi
TRC Solutions, Inc.	Randy Blake
TRC Solutions, Inc.	Ryan Villanueva

### LINK: NA

Burns & McDonnell	Jim Gibson
Chambers Group	Ivy Watson
TRC Solutions, Inc.	Lauralyn Jensen

## ENVIRONMENTAL COMPLIANCE

Mitigation Measure	A	B	C	D	E	F	G	H
Date	(Y/N)	Species	Loc UTM Lat-Long	Cause	Issue	Action	Comments	Tower

### LINK: 1

B-1c	12/06/2010	Y						Rough Acres
Mitigation Measure in Compliance?		Y						
bio-monitoring								
	12/06/2010	Y					Remarks: All work activity in compliance	Thomas Yard
Mitigation Measure in Compliance?		Y						
Compliance								

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

### ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: 1</b>								
B-1c								
12/06/2010	Y						area in compliance	Rough Acres
<b>Mitigation Measure in Compliance?</b>							Remarks: none	
12/06/2010	Y				1	Notified Link Lead	Crews were in compliance	Thomas Yard
<b>Mitigation Measure in Compliance?</b>							Remarks: Crews were in compliance	
12/07/2010	Y						area in compliance	Rough Acres
<b>Mitigation Measure in Compliance?</b>							Remarks: none	
12/07/2010	Y							Rough Acres
<b>Mitigation Measure in Compliance?</b>								
12/07/2010	Y						Remarks: All work activity in compliance	Thomas Yard
<b>Mitigation Measure in Compliance?</b>								
12/08/2010	Y						Crews in compliance	Thomas Yard
<b>Mitigation Measure in Compliance?</b>							Remarks: Crews remained in compliance.	
12/08/2010	Y						Remarks: All work activity in compliance	Thomas Yard
<b>Mitigation Measure in Compliance?</b>								
12/08/2010	Y							Rough Acres
<b>Mitigation Measure in Compliance?</b>								
12/08/2010	Y						area in compliance	Rough Acres
<b>Mitigation Measure in Compliance?</b>							Remarks: none	

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

### ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: 1</b>								
B-1c								
12/09/2010	Y							Rough Acres Phase 1
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
oversight								
12/09/2010	Y				1		Remarks: Crews working in compliance.	Thomas Yard
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Compliance met								
12/09/2010	Y						Remarks: All work activity in compliance	Thomas Yard
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Compliance								
12/10/2010	Y						area in compliance	Rough Acres
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>						Remarks: none	
compliance								
12/10/2010	Y				1		Crews in compliance on site	Thomas Yard
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>						Remarks: Crews working in compliance	
Compliance met								
12/10/2010	Y							Thomas Yard
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Bio-Monitoring								
12/10/2010	Y							Rough Acres Phase 1
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
oversight								
12/11/2010	Y				1		Compliance met	Thomas Yard
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>						Remarks: Compliance met, crews working in compliance with biomonitor on site	
Compliance met								
12/11/2010	Y							Thomas Yard
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Bio-Monitoring								

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

### ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: 1</b>								
B-7d								
12/06/2010	Y	Burrowing Owl					Remarks: BUOW observed late in the afternoon, Thomas remained >500 ft from construction activities	yard
<b>Mitigation Measure in Compliance? Y</b>								
BUOW obser								
12/06/2010	Y	Burrowing Owl	11s 0634155, 3637860			Notified Link Lead	Species noted by link lead on previous reports Remarks: Species observed using 'burrow' (hole) east of previous 'burrow' (drain) site. Species > 500 ft from construction zone. No impact to species.	Thomas Yard
<b>Mitigation Measure in Compliance? Y</b>								
Species BUOW								
12/08/2010	Y	Burrowing Owl	11s 0634179, 3637858			Notified Link Lead	Species not in construction activity zone. Species not impacted by construction activities. Remarks: <input type="checkbox"/> Second burrowing owl observed possible pair.	South end of Thomas Yard
<b>Mitigation Measure in Compliance? Y</b>								
Second BUOW								
12/08/2010	Y	Burrowing Owl					Remarks: A second BUOW was observed in the SE part of the yard (Not within the construction area). The 2 BUOWs were occupying different 'burrows'; one at the drain and one at the 'hole'. Late afternoon observations indicate this is a pair (m/f); both BUOWs observed at the 'hole'. Will continue to monitor activity and use.	Thomas yard
<b>Mitigation Measure in Compliance? Y</b>								
BUOW observed								
12/09/2010	Y	Burrowing Owl	11s 0634104, 3638225			Notified Link Lead	Species noted in area previously by other biomonitors and remained well outside active work area and not affected by construction. Remarks: Sensitive species noted	East end of Thomas Yard
<b>Mitigation Measure in Compliance? Y</b>								
compliance met								
12/09/2010	Y	Burrowing Owl					Remarks: A BUOW was observed down an aisle between stacked boxcars on the east side of the active yard. Pellets were also observed. An owl was observed in this area on Nov 19 (chris bugbee). Unknown if this is a third owl on the site. Area of use is >160 ft from active construction activities. See report from John Kanlund (chambers) for coordinates. Will continue to monitor activity and use.	Thomas yard
<b>Mitigation Measure in Compliance? Y</b>								
BUOW observed								

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

### ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: 1</b>								
B-7d								
12/10/2010	Y	Burrowing Owl	11s 0634274, 3637845			Notified Link Lead	Compliance met no impact to species Remarks: Three burrowing owls noted on-site	South Thomas Yard
No impact								
12/10/2010	Y							Thomas Yard
<b>Mitigation Measure in Compliance? Y</b>								
Burrowing Owls								
12/11/2010	Y							Thomas Yard
<b>Mitigation Measure in Compliance? Y</b>								
Burrowing Owls								
BIO-APM-3								
12/06/2010	Y						Water truck on site controlled dust	ROUGH ACRES
<b>Mitigation Measure in Compliance? Y</b>								
dust control								
12/07/2010	Y						Water truck on site controlled dust	ROUGH ACRES
<b>Mitigation Measure in Compliance? Y</b>								
dust control								
12/08/2010	Y						Water truck on site controlled dust	ROUGH ACRES
<b>Mitigation Measure in Compliance? Y</b>								
dust control								
12/10/2010	Y						Water truck on site controlled dust	ROUGH ACRES
<b>Mitigation Measure in Compliance? Y</b>								
dust control								
N-1a								
12/08/2010	N						Remarks: All delivery trucks in compliance	Thomas yard
<b>Mitigation Measure in Compliance? Y</b>								
Compliance								
12/09/2010	N						Remarks: All delivery trucks in compliance	Thomas yard
<b>Mitigation Measure in Compliance? Y</b>								
Compliance								

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

### ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: 1</b>								
N-1a								
12/11/2010	N						Vehicle idle time below five minutes when not in use	Thomas Yard
<b>Mitigation Measure in Compliance?</b>							Remarks: Crews working in compliance	
Compliance met								
<b>LINK: 4</b>								
B-1c								
12/06/2010	Y						all delivery, unloading, and construction operations throughout the yards was within compliance with the APMs and all mitigation measures were met	lower/upper Alpine constructor yard
<b>Mitigation Measure in Compliance?</b>								
compliance								
12/06/2010	Y						Conducted biological monitoring. No biological issues were observed throughout the day.	Vault 18
<b>Mitigation Measure in Compliance?</b>							Remarks: Compliance Met	
Underground								
12/06/2010	Y						All required monitors were onsite during potholing activities	267+74-264 257+50
<b>Mitigation Measure in Compliance?</b>								
compliance								
12/06/2010	Y						Conducted biological monitoring. No environmental issues were observed throughout the day.	Vault 19
<b>Mitigation Measure in Compliance?</b>								
Compliance								
12/07/2010	Y						All required monitors were onsite during potholing activities	257+96 - 253+50
<b>Mitigation Measure in Compliance?</b>								
compliance								
12/07/2010	Y						all delivery and unloading operations were in compliance with the APMs and the mitigation measures were met	lower/upper Alpine constructor yard
<b>Mitigation Measure in Compliance?</b>								
compliance								
12/07/2010	Y						Conducted biological monitoring. No environmental issues were observed throughout the day.	Vault 18
<b>Mitigation Measure in Compliance?</b>							Remarks: Compliance met	
Underground								

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

### ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: 4</b>								
B-1c								
12/07/2010	Y						Conducted biological monitoring. No environmental issues were observed throughout the day.	Vault 19
<b>Mitigation Measure in Compliance? Y</b>								
Compliance								
12/07/2010	Y						All MMs and APMs were complied with throughout the day.	Link 4
<b>Mitigation Measure in Compliance? Y</b>								
compliance								
12/08/2010	Y						All required monitors were onsite during potholing activities. No environmental issues were observed throughout the day.	249+44 - 241+00
<b>Mitigation Measure in Compliance? Y</b>								
compliance								
12/08/2010	Y						The unloading of the wire reels was done in compliance with the APMs and the mitigation measures were met	upper Alpine construction yard
<b>Mitigation Measure in Compliance? Y</b>								
compliance								
12/08/2010	Y						Conducted biological monitoring. No environmental issues were observed during the day. Remarks: Compliance met.	Vault 19
<b>Mitigation Measure in Compliance? Y</b>								
Underground								
12/08/2010	Y						Conducted biological monitoring. No environmental issues were observed throughout the day. Remarks: Compliance met	Vault 18
<b>Mitigation Measure in Compliance? Y</b>								
Underground								
12/08/2010	Y							Vaults 14-17
<b>Mitigation Measure in Compliance? Y</b>								
Veg Survey								
12/08/2010	Y						All MMs and APMs were complied with throughout the day.	Link 4
<b>Mitigation Measure in Compliance? Y</b>								
compliance								
12/09/2010	Y						No environmental issues were observed throughout the day.	Vault 19
<b>Mitigation Measure in Compliance? Y</b>								
Monitoring								

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

### ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: 4</b>								
B-1c								
12/09/2010	Y						all construction activity, delivery and unloading, and routine daily activities was in compliance with the APMs and the mitigation measures were met	lower/upper Alpine constructor yards
<b>Mitigation Measure in Compliance? Y</b>								
compliance								
12/09/2010	Y						Conducted biological monitoring. Remarks: Compliance met.	Vault 14 and 16.
<b>Mitigation Measure in Compliance? Y</b>								
Underground								
12/09/2010	Y						All required monitors were onsite during potholing activities. No environmental issues were observed throughout the day.	231+05 - 227+00
<b>Mitigation Measure in Compliance? Y</b>								
compliance								
12/09/2010	Y						Conducted biological monitoring Remarks: Compliance met	Vault 18
<b>Mitigation Measure in Compliance? Y</b>								
Underground								
12/09/2010	Y						All MMs and APMs were complied with throughout the day.	Link 4
<b>Mitigation Measure in Compliance? Y</b>								
compliance								
12/10/2010	Y						all construction and distribution activities were in compliance with the APMs and the mitigation measures were met	lower/upper Alpine constructor yards
<b>Mitigation Measure in Compliance? Y</b>								
compliance								
12/10/2010	Y						No environmental issues were observed throughout the day.	Vault 19
<b>Mitigation Measure in Compliance? Y</b>								
Monitoring								
12/10/2010	Y						Conducted biological monitoring. Remarks: Compliance met.	Vault 15 and 16.
<b>Mitigation Measure in Compliance? Y</b>								
underground								
12/10/2010	Y						Conducted biological monitoring Remarks: Compliance met	Vault 18
<b>Mitigation Measure in Compliance? Y</b>								
Underground								

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

### ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: 4</b>								
B-1c								
12/10/2010	Y						All required monitors were onsite during potholing activities. No biological issues were observed.	226+50 - 226+23
<b>Mitigation Measure in Compliance? Y</b>								
compliance								
12/10/2010	Y						All MMs and APMs were complied with throughout the day. A bobcat was found dead along our ROW. The bobcat appeared to have been hit by a vehicle. Cassandra Garza from ASPEN, was notified.	Link 4
<b>Mitigation Measure in Compliance? Y</b>								
compliance								
B-7a								
12/06/2010	Y						Equipment was checked before moving to confirm no wildlife present	267+74-264 257+50
<b>Mitigation Measure in Compliance? Y</b>								
check vehicles								
12/07/2010	Y						Equipment was checked before moving to confirm no wildlife present	257+96 - 253+50
<b>Mitigation Measure in Compliance? Y</b>								
check vehicles								
12/08/2010	Y						Crews properly covered the excavation of vault 18 with steel plates Remarks: Compliance met	Vault 18
<b>Mitigation Measure in Compliance? Y</b>								
Excavation								
12/08/2010	Y						Equipment was checked before moving to confirm no wildlife present	249+44 - 241+00
<b>Mitigation Measure in Compliance? Y</b>								
check vehicles								
12/09/2010	Y						Crews properly covered the excavation of vault 18 with steel plates Remarks: Excavation was properly covered	Vault 18
<b>Mitigation Measure in Compliance? Y</b>								
Underground								
12/09/2010	Y						Equipment was checked before moving to confirm no wildlife present	231+05 - 227+00
<b>Mitigation Measure in Compliance? Y</b>								
check vehicles								

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

### ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: 4</b>								
B-7a								
12/10/2010	Y						Crews properly covered the excavation of vault 18 with steel plates	Vault 18
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>						Remarks: Compliance met	
Underground								
BIO-APM-3								
12/06/2010	Y						the use of a water truck and all vehicle operators obeying the 5 mph speed limit eliminated fugitive dust in the construction yard	upper Alpine constructor yard
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
dust								
12/06/2010	Y						Vehicles were restricted to existing access roads. Vehicles remained on Alpine Blvd.	267+74-264 257+50
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
ROW								
12/07/2010	Y						Vehicles were restricted to existing access roads. Vehicles remained on Alpine Blvd.	257+96 - 253+50
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
ROW								
12/07/2010	Y						fugitive dust was eliminated by applying water to the yard's surface with a water truck during work hours and all vehicle operators obeyed the 5 mph speed limit	upper Alpine constructor yard
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
dust								
12/08/2010	Y						a water truck was used to moisten the surface of the yard in order to eliminate fugitive dust; in addition, all vehicle operators obeyed the 5 mph speed limit	upper Alpine constructor yard
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
dust								
12/08/2010	Y						Vehicles were restricted to existing access roads. Vehicles remained on Alpine Blvd.	249+44 - 241+00
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
ROW								
12/09/2010	Y						a water truck applied water to the surface of the construction yard to eliminate fugitive dust created by construction activities	upper Alpine constructor yard
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
dust								

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

### ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: 4</b>								
BIO-APM-3								
12/09/2010	Y						Vehicles were restricted to existing access roads. Vehicles remained on Alpine Blvd.	231+05 - 227+00
<b>Mitigation Measure in Compliance? Y</b>								
ROW								
12/10/2010	Y						Vehicles remained on Alpine Blvd, but permits to work within the ROW were given.	226+50 - 226+23
<b>Mitigation Measure in Compliance? Y</b>								
ROW								
12/10/2010	Y						a water truck was used to apply water to the surface of the construction yard in order to eliminate fugitive dust. In addition, all vehicle operators obeyed the 5 mph speed limit while in the construction yard	upper Alpine construction yard
<b>Mitigation Measure in Compliance? Y</b>								
dust								
BIO-APM-4								
12/06/2010	Y						All vehicles at job site stayed on existing roads	267+74-264 257+50
<b>Mitigation Measure in Compliance? Y</b>								
ROW								
12/07/2010	Y						All vehicles at job site stayed on existing roads	257+96 - 253+50
<b>Mitigation Measure in Compliance? Y</b>								
ROW								
12/08/2010	Y						All vehicles at job site stayed on existing roads and ROW.	249+44 - 241+00
<b>Mitigation Measure in Compliance? Y</b>								
ROW								
12/09/2010	Y						All vehicles at job site stayed on existing roads and ROW.	231+05 - 227+00
<b>Mitigation Measure in Compliance? Y</b>								
ROW								
12/10/2010	Y						Vehicles followed mitigations and remained on pavement within the ROW.	226+50 - 226+23
<b>Mitigation Measure in Compliance? Y</b>								
ROW								

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

### ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: 4</b>								
C-1e								
12/06/2010	Y						No cultural issues were observed throughout the day.	Vault 18
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Cultural								
12/06/2010	Y						While monitoring, No cultural issues were observed throughout the day.	Alpine Blvd vault 19L
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Cultural								
12/07/2010	Y						Cultural monitoring was performed throughout the day. No cultural issues were observed.	Alpine Blvd vault 16L
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Cultural								
12/07/2010	Y						No cultural issues were observed today.	Vault 19
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Cultural								
12/07/2010	Y						No Cultural issues were observed today.	Vault 18
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Cultural								
12/08/2010	Y						No cultural issues were observed throughout the day.	Location 18, Alpine Boulevard
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Cultural								
12/08/2010	Y							Vaults 14,15,16,17
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Cultural								
12/08/2010	Y						Remarks: No cultural resources expected, impacted or discovered.	249+44
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Pot Hole diggin								
12/09/2010	Y						No cultural issues were observed throughout the day as I monitored the crew.	Alpine Blvd vault 19L
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Cultural								

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

### ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: 4</b>								
C-1e								
12/09/2010	Y						No cultural issues were observed as I monitored throughout the day.	Location 18 Alpine Boulevard
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
12/10/2010	Y							VLT 14L
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Pot hole monito								
12/10/2010	Y			No cultural material was observed at the excavation area.				Section 18, Alpine Boulevard
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
12/10/2010	Y						No cultural issues were observed while monitoring today.	Alpine Blvd vault 19L
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Cultural								
N-1a								
12/08/2010	N						semi truck drivers hauling the wire reels were asked to shut off their engines while waiting to be unloaded; all drivers eagerly complied with the request	upper Alpine constructor yard
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
idling								
<b>LINK: NA</b>								
B-1c								
12/06/2010	Y						Conducted biological monitoring	Encina Substation
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>						Remarks: Conducted biological monitoring	
BIO monitoring								
12/06/2010	Y						in compliance	Oceanside substation
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>						Remarks: Everything in compliance	

# Sunrise Powerlink Transmission Project

## Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

### ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: NA</b>								
B-1c								
12/07/2010	Y						in compliance	San Luis Rey
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>						Remarks: Everything in compliance	substation
12/07/2010	Y						Remarks: Work was in Compliance	Encina
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Mitigation met								
12/07/2010	Y						Remarks: Work was in Compliance	San Luis Rey
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Mitigation met								
12/08/2010	Y						Remarks: Work was in Compliance	Encina
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Mitigation met								
12/08/2010	Y						Remarks: Work was in Compliance	San Luis Rey
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Mitigation met								
12/09/2010	Y						Remarks: Work was in Compliance	Encina
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Mitigation met								
12/09/2010	Y						Remarks: Work was in Compliance	San Luis Rey
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Mitigation met								
12/09/2010	Y						in compliance	San Luis Rey
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>						Remarks: Everything in compliance	substation
12/10/2010	Y						Remarks: Work was in Compliance	Encina
<b>Mitigation Measure in Compliance?</b>	<b>Y</b>							
Mitigation met								

# Sunrise Powerlink Transmission Project

Weekly Monitoring Report No. 00012

From: 12/05/2010 Through: 12/11/2010

## ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
<b>LINK: NA</b>								
B-1c								
12/10/2010	Y						Remarks: Work was in Compliance	San Luis Rey
<b>Mitigation Measure in Compliance? Y</b>								
Mitigation met								
12/11/2010	Y						Remarks: Work was in Compliance	Encina
<b>Mitigation Measure in Compliance? Y</b>								
Mitigation met								
12/11/2010	Y						Remarks: Work was in Compliance	San Luis Rey
<b>Mitigation Measure in Compliance? Y</b>								
Mitigation met								