#### **Sunrise Powerlink Transmission Project** Weekly Monitoring Report No. 00008

**From:** 11/07/2010 **Through:** 11/13/2010

#### INTRODUCTION

During the week of 11/07/2010 through 11/13/2010, construction continued at the Alpine RFO, Alpine Construction Yards, San Luis Rey Substation, Encina Switchyard, the Rough Acres Construction Yard.

Pre-Construction Activity with appropriate monitors:

Link 4, sign posting along Alpine Boulevard for traffic control and construction dates. Two PAR crews placed signage, 11/9 and 11/10 only.

Link 1, three crews marked ESA¿s, access roads and work areas, 11/10 and 11/11 only.

Link 5, two crews marked towers areas, 11/10 and 11/11 only.

#### ALL LINKS

The following is a summary of construction activity where monitors were on site.

Alpine RFO: Crews continued clearing of brush and fence installation commenced in areas where clearing was conducted. Crews stayed within flagged areas. Improvements continued on the main driveway, concrete poured in parking near office buildings and driveway, SDG&E temporary construction trailer removed.

Alpine Construction Yard: Equipment and reels deliveries continued on a limited basis.

San Luis Rey Substation: Underground foundation work and installation of capacitor banks being conducted.

Rough Acres Construction Yard: There was limited delivery of equipment during this period.

Encina Switchyard: Repair of existing footings continues. On 11/10/2010, rock was placed in the area just outside of the Switchyard to prevent track-out from occurring in the future. On 11/11/2010, an additional rumble plate was placed between the Switchyard parking area and the paved drive.

White Star Communication Facility: All work completed except for removal of one wood pole. Waiting for the tenant to remove hardware. Pole removal scheduled for 11/15/2010.

A rain event occurred on 11/8/2010. Precipitation amounts are as follows: .1 of an inch at Alpine and .2 of an inch at Rough Acres. Inspection of BMP¿s were made with no deficiencies.

#### ENVIRONMENTAL MONITORS

LINK: 1	
Burns & McDonnell	Janice Rodgers
Burns & McDonnell	Rebecca Carson
Chambers Group	Chris Bugbee
Chambers Group	Erik Strods
Pangea Biological	Don Spires
LINK: 4	
Burns & McDonnell	Ken Katsuda
Chambers Group	Seth Reimers
TRC Solutions, Inc.	Britta Dahlke
TRC Solutions, Inc.	Michael Scaffidi

Weekly Monitoring Report No. 00008

**From:** 11/07/2010 **Through:** 11/13/2010

ENVIR	ONMENTAL	MONITORS						
LINK:	NA							
Chambe	ers Group		Chris Bugbee					
Chambe	ers Group		John Kanlund					
Chambe	rs Group		Kris Alberts					
Pangea	Biological		Don Spires					
Pangea	Biological		Mark Meriditl	1				
TRC So	lutions, Inc.		Alicia Hill					
TRC So	lutions, Inc.		Lauralyn Jens	en				
ENVIR	ONMENTAL	COMPLIANCE						
Mitigat	ion Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK:	1							
B-1c								
<b>Mitigat</b> complia		Y 1 Compliance? Y					area in compliance Remarks: none	Rough Acres
-	11/09/2010	Y						Rough
Mitigati oversigh		a Compliance? Y						Acres Phase 1
	11/09/2010	Y					area in compliance	Rough
Mitigati complia		Compliance? Y					Remarks: none	Acres
	11/10/2010	Y					area in compliance	Rough
Mitigati complia		Compliance? Y					Remarks: none	Acres
	11/11/2010	Y					No issues noted.	White Star
Mitigat	ion Measure in	Compliance? Y						Communic Facility
	11/11/2010	Y					all work compliant	White Star
<b>Mitigat</b> i Bio	ion Measure in	Compliance? Y						

Weekly Monitoring Report No. 00008

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1							
B-1c							
11/11/2010						area in compliance	Rough Acres
Mitigation Measure in compliance	i Compliance? Y					Remarks: none	Acres
11/12/2010	Y						Rough
<b>Mitigation Measure in</b> Bio-Monitoring	a Compliance? Y						Acres
11/12/2010	Y					area in compliance	Rough
Mitigation Measure in compliance	Compliance? Y					Remarks: none	Acres
11/13/2010	Y						Rough
<b>Mitigation Measure in</b> Bio-Monitoring	a Compliance? Y						Acres
B-2a							
11/11/2010	Y					The work area was adequately marked.	White Star
Mitigation Measure in	a Compliance? Y						Communica Facility
BIO-APM-3							
11/10/2010						Water truck on site controlled dust	ROUGH
Mitigation Measure in dust control	a Compliance? Y						ACRES
11/11/2010	Y					Water truck on site controlled dust	ROUGH
Mitigation Measure in dust control	Compliance? Y						ACRES
11/12/2010	Y					Water truck on site controlled dust	ROUGH
Mitigation Measure in dust control	a Compliance? Y						ACRES

### Weekly Monitoring Report No. 00008

ENVIRONMENT	AL COMPLIANCE						
Mitigation Measur Date	re A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1							
N-1a						NT	
11/11/20 Mitigation Measur	non N re in Compliance? Y					No unnecessary idling occurred.	White Star Communica Facility
WQ-APM-13							
11/11/20						Equipment was checked and no spills or leaks	White Star
Mitigation Measur	re in Compliance? Y					noted.	Communica Facility
LINK: 4							
11/10/20	)10 Y					All work activities complied with project	Alpine
Mitigation Measur Compliance Met	re in Compliance? Y					mitigation measures and APMs	Creek, Alpine/Tav Alpine/Star Valley, Alpine/Arn
B-1c							·
11/08/20						the construction yard is in compliance with all	lower
Mitigation Measur compliance	re in Compliance? Y					APMs and the mitigation measures were met	Alpine construction yard
11/09/20	)10 Y					All mitigation measures and APMs were	Alpine
Mitigation Measur compliance	re in Compliance? Y					complied with throughout the day. All required monitors were onsite.	Yards
11/09/20	)10 Y					the construction yard was in compliance with all	
Mitigation Measur compliance	re in Compliance? Y					APMs and the mitigation measures were met	Alpine construction yard
11/09/20	)10 Y					All required monitors were onsite during ground	Alpine
Mitigation Measur compliance met	re in Compliance? Y					disturbance.	Staging Yard

### Weekly Monitoring Report No. 00008

	COMBLIANCE						
ENVIRONMENTAL Mitigation Measure	A B	С	D	Е	F	G	н
Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	Issue	r Action	Comments	n Tower
LINK: 4							
B-1c							
11/10/2010	Y					the construction yard is in compliance with all	lower/uppe
Mitigation Measure in compliance	a Compliance? Y					APMs and the mitigation measures were met	Alpine construction yard
11/10/2010	Y					All mitigation measures and APMs were	Alpine
Mitigation Measure in compliance	a Compliance? Y					complied with throughout the day. All required monitors were onsite.	Yards
11/11/2010	Y					the construction yard is in compliance with all	upper
Mitigation Measure in compliance	1 Compliance? Y					APMs and the mitigation measures were met	Alpine construction yard
11/11/2010	Y					All mitigation measures and APMs were	Alpine
Mitigation Measure in compliance	a Compliance? Y					complied with throughout the day. All required monitors were onsite.	Yards
11/12/2010	Y					the construction yard is in compliance with all	upper
Mitigation Measure in compliance	a Compliance? Y					APMs and the mitigation measures were met	Alpine constructio yard
11/12/2010	Y					All mitigation measures and APMs were	Alpine
Mitigation Measure in compliance	a Compliance? Y					complied with throughout the day. All required monitors were onsite.	Yards
11/13/2010	Y					All mitigation measures and APMs were	Alpine
Mitigation Measure in compliance	a Compliance? Y					complied with throughout the day.	Yards
BIO-APM-3							
11/09/2010	Y					fugitive dust was controlled with the use of 2	lower
Mitigation Measure in	Compliance? Y					water trucks applying water and all vehicle	Alpine
dust						operators obeying the 5 mpg speed limit within the yard	constructio yard

Weekly Monitoring Report No. 00008

ENVIRONME	ENTAL C	OMPLIANCE						
Mitigation Me Dat		A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 4								
BIO-APM-3								
11/1	10/2010	Y					fugitive dust was controlled by the use of a	lower
Mitigation Me dust	easure in (	Compliance? Y					water truck applying water to disturbed surfaces and all vehicle operators obeying a 5 mph speed limit within the yard	Alpine construction yard
11/1	1/2010	Y					fugitive dust was contolled by the use of a water	
Mitigation Me dust	easure in (	Compliance? Y					truck applying water to the soil surface and all vehicle operators obeying the 5 mph speed limit	Alpine construction yard
	12/2010 easure in (	Y Compliance? Y					fugitive dust was contolled by the use of a water truck applying water to the soil surface and all vehicle operators obeying the 5 mph speed limit	Alpine
	12/2010 easure in (	Y Compliance? Y					trucks waiting to be offloaded of steel were turned off to avoid excess idling	upper Alpine constructic yard
LINK: NA								
		Y Compliance? Y					Remarks: Alligator Lizard removed from area.	San Luis Rey
11/0	08/2010	Y Compliance? Y					all trenchlines examined periodically through the day; no wildlife observed in any. One alligator lizard (Elgaria multicarinata) was captured and removed from a debris pile before pile was partially relocated, the rest of which was disposed of.	San Luis Rey substation, Oceanside
	)8/2010 easure in (	Y Compliance? Y					Conducted biological monitoring Remarks: Conducted biological monitoring	Encina Substation

### Weekly Monitoring Report No. 00008

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: NA							
B-1c							
11/09/2010							San Luis
<b>Mitigation Measure in</b> Bio-monitoring	1 Compliance? Y						Rey
11/09/2010	Y					Conducted biological monitoring	Encina
<b>Mitigation Measure in</b> Bio monitor	n Compliance? Y					Remarks: Conducted biological monitoring	Substation
11/09/2010	Y					All required monitors were present and on site	Encina
Mitigation Measure in	n Compliance? Y					Remarks: No problem areas observed	Switchyar
11/09/2010						all work compliant	SLR
<b>Mitigation Measure in</b> Bio	1 Compliance? Y						Substation
11/10/2010	Y					Biological monitor on site	Encina
Mitigation Measure in	1 Compliance? Y					Remarks: Area in compliance with all mitigation measures and applicant proposed measures	Switchyar
11/10/2010	Y					all work compliant	SLR
<b>Mitigation Measure in</b> Bio	1 Compliance? Y						Substation
11/10/2010	Y						San Luis
<b>Mitigation Measure in</b> Bio-monitoring	1 Compliance? Y						Rey
11/10/2010	Y					Conducted biological monitoring	Encina
<b>Mitigation Measure in</b> BIO monitoring	n Compliance? Y					Remarks: Conducted biological monitoring	Substation
11/11/2010	Y					All work activities were kept within approved	Encina
Mitigation Measure in	n Compliance? Y					work limits Remarks: All required monitors on site	Switchyar

Weekly Monitoring Report No. 00008

ENVIRONMENTAL	COMPLIANCE						
Mitigation Measure Date	A B (Y/N) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: NA							
B-1c							
11/11/2010	Y					Crews in compliance	San Luis
Mitigation Measure in Compliance met	1 Compliance? Y						Rey Sub
11/11/2010	Y					Conducted biological monitoring	Encina
Mitigation Measure in BIO monitoring	n Compliance? Y					Remarks: Conducted biological monitoring	Substation
11/11/2010	Y						San Luis
<b>Mitigation Measure in</b> Bio-monitoring	a Compliance? Y						Rey
11/12/2010	Y					Conducted biological monitoring	Encina
Mitigation Measure in BIO monitoring	n Compliance? Y					Remarks: Conducted biological monitoring	Substation
11/13/2010	Y					All necessary monitors on site	Encina
Mitigation Measure in	Compliance? Y					Remarks: All areas in compliance	Switchyard
B-3a							
11/08/2010	-					Equipment and vehicles were free of mud and debris	Encina Switchyard
Mitigation Measure in	i Compliance? Y					Remarks: Equipment and vehicles were cleaned prior to arrival at the switchyard	Switchyard
BIO-APM-1							
11/08/2010	Y	33°			Notified Link	Two peregrine falcons were in the area and were	Encina
Mitigation Measure in	Compliance? Y	8'10.65"N,			Lead	not impacted by any work activities.	Substation
Peregrine Falco		117°20'9.62				Remarks: Two peregrine falcons were in the area and were not impacted by any work activities.	
11/09/2010	Y	33°			Notified Link	Two peregrine falcons were in the area and were	
Mitigation Measure in	Compliance? Y	8'10.65"N,	1		Lead	not impacted by any work activities.	Substation
Peregrine Falco		117°20'9.62				Remarks: Two peregrine falcons were in the area and were not impacted by any work activities.	

#### Weekly Monitoring Report No. 00008

**From:** 11/07/2010 **Through:** 11/13/2010

ENVIRONMENTAL	COMP	LIANCE						
Mitigation Measure Date	A (Y/N	B ) Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: NA								
BIO-APM-3								
11/12/2010 Mitigation Measure in		liance? Y					Vehicles obeyed the 10 mph speed lin fugitive dust was observed	mit and no Encina Switchya

**Mitigation Measure in Compliance?** Y Dust Control