



550 Kearny Street  
Suite 800  
San Francisco, CA 94108  
415.896.5900 [phone](tel:415.896.5900)  
415.896.0332 [fax](tel:415.896.0332)

[esassoc.com](http://esassoc.com)

# memorandum

date August 3, 2020

to John Forsythe, AICP

cc Cory Barringhaus (ESA), Eric Zigas (ESA)

from Sharon Dulava (ESA)

subject MPWSP – Ryan Ranch – Bishop Interconnection Project Weekly Report (07/27/2020 – 07/31/2020)

## ***Construction Activities***

No construction activities occurred on site during the week of 7/27/2020 – 7/31/2020.

## ***Compliance Activities***

ESA did not conduct site inspections during the week of 7/27/2020 – 7/31/2020. Denise Duffy & Associates (CalAm monitors) conducted a weekly spot check on 7/28/2020.

## ***Compliance Issues and Resolutions***

In the CalAm weekly compliance report dated 7/24/2020, CalAm monitors reported that the silt fencing installed around the staging area had been damaged. In addition, stock piles within the staging area were not covered, as required by MMRP Measures 4.6-1p and 4.10-1c. On 7/28/2020, CalAm monitors discussed repairing silt fence and covering of stockpiles with the contractor, Monterey Peninsula Engineering (MPE). MPE agreed to repair the silt fence and cover the stockpiles.