

memorandum

date August 10, 2020

to John Forsythe, AICP

cc Cory Barringhaus (ESA), Eric Zigas (ESA)

from Sharon Dulava (ESA)

subject MPWSP – Ryan Ranch – Bishop Interconnection Project Weekly Report (08/03/2020 – 08/07/2020)

Construction Activities

No construction activities occurred on site during the week of 8/03/2020 – 8/07/2020.

Compliance Activities

ESA did not conduct site inspections during the week of 8/03/2020 – 8/07/2020. Denise Duffy & Associates (CalAm monitors) conducted a weekly spot check on 8/05/2020.

Compliance Issues and Resolutions

In the CalAm weekly compliance report dated 7/24/2020, CalAm monitors reported that the silt fencing installed around the staging area had been damaged. In addition, stock piles within the staging area were not covered, as required by MMRP Measures 4.6-1p and 4.10-1c. During their 8/05/2020 site visit, CalAm monitors confirmed that damaged silt fence had been repaired and again discussed covering of stockpiles with the contractor, Monterey Peninsula Engineering (MPE). MPE agreed to either cover or remove the stockpiles.