5. VISUAL SIMULATIONS

3.14-1 (Revised) Key Observation Points	3.14-26a Existing Conditions for KOP-Center-11 Silver Moccasin Trailhead (Alternative 2, Segment 6)
3.14-2 Angeles National Forest Landscape Places and Scenic Integrity Objectives Segment 6 and 11	3.14-26b Visual Simulation for KOP-Center-11 Silver Moccasin Trailhead (Alternative 2, Segment 6)
3.14-3a (Revised) Existing Conditions for KOP-North-1 Oak Creek Canyon Road, Kern County. (Alternative 2, Segment 10)	3.14-27a (Revised) Existing Conditions for KOP-Center-12 Cogswell Reservoir & National Scenic Bikeway (Alternative 2, Segment 6)
3.14-3b (Revised) Visual Simulation for KOP-North-1 Oak Creek Canyon Road, Kern County. (Alternative 2, Segment 10)	3.14-27b (Revised) Visual Simulation for KOP-Center-12 Cogswell Reservoir & National Scenic Bikeway (Alternative 2, Segment 6)
3.14-4a (Revised) Existing Conditions for KOP-North-2 Tehachapi-Willow Springs Road, Kern County. (Alternative 2, Segment 10)	3.14-28a (Revised) Existing Conditions for KOP-Center-13 Mount Zion (Alternative 2, Segment 6)
3.14-4b (Revised) Visual Simulation for KOP-North-2 Tehachapi-Willow Springs Road, Kern County. (Alternative 2, Segment 10)	3.14-28b Visual Simulation for KOP-Center-13 Mount Zion (Alternative 2, Segment 6)
3.14-5a (Revised) Existing Conditions for KOP-North-3 170th Street West (Alternative 2, Segments 4, 9, 10)	3.14-29a Existing Conditions for KOP-Center-14 Pacific Crest Trail (Alternative 2, Segment 11)
3.14-5a (Revised) Visual Simulation for KOP-North-3 170th Street West (Alternative 2, Segments 4, 9, 10)	
	3.14-29b Visual Simulation for KOP-Center-14 Pacific Crest Trail (Alternative 2, Segment 11)
3.14-6a (Revised) Existing Conditions for KOP-North-4 California Poppy Reserve (Alternative 2, Segment 4)	3.14-30a (Revised) Existing Conditions for KOP-Center-15 Eastbound Mount Gleason Road (Alternative 2, Segment 11)
3.14-6b (Revised) Visual Simulation for KOP-North-4 California Poppy Reserve (Alternative 2, Segment 4)	3-14-30b (Revised) Visual Simulation for KOP-Center-15 Eastbound Mount Gleason Road (Alternative 2, Segment 11)
3.14-7a (Revised) Existing Conditions for KOP-North-5 110th Street at Silverwind Way (Alternative 2, Segment 4)	3.14-31a (Revised) Existing Conditions for KOP-Center-16 Southbound Angeles Forest Highway (Alternative 2, Segment 11)
3.14-7b (Revised) Visual Simulation for KOP-North-5 110th Street at Silverwind Way (Alternative 2, Segment 4)	3.14-31b (Revised) Visual Simulation for KOP-Center-16 Southbound Angeles Forest Highway (Alternative 2, Segment 11)
3.14-8a (Revised) Existing Conditions for KOP-North-6 Avenue J at Antelope Substation (Alternative 2, Segment 9)	3.14-32a Existing Conditions for KOP-Center-17 Northbound Angeles Forest Highway (Alternative 2, Segment 11)
3.14-8b (Revised) Visual Simulation for KOP-North-6 Avenue J at Antelope Substation (Alternative 2, Segment 9)	3.14-32b Visual Simulation for KOP-Center-17 Northbound Angeles Forest Highway (Alternative 2, Segment 11)
3.14-9a (Revised) Existing Conditions for KOP-North-7 Avenue L Near Olive Grove (Alternative 2, Segment 5)	3.14-33a (Revised) Existing Conditions for KOP-Center-18 Clear Creek Outdoor Education Camp (Alternative 2, Segment 11)
3.14-9b (Revised) Visual Simulation for KOP-North-7 Avenue L Near Olive Grove (Alternative 2, Segment 5)	3.14-33b Visual Simulation for KOP-Center-18 Clear Creek Outdoor Education Camp (Alternative 2, Segment 11)
3.14-10a (Revised) Existing Conditions for KOP-North-8 Avenue N at Agena Road (Alternative 2, Segment 5)	3.14-34a (Revised) Existing Conditions for KOP-Center-19 Gould Substation from Angeles Crest Scenic Byway (Alternative 2,
3.14-10b (Revised) Visual Simulation for KOP-North-8 Avenue N at Agena Road (Alternative 2, Segment 5)	Segment 11)
3.14-11a (Revised) Existing Conditions for KOP-North-9 Godde Hill Road (Alternative 2, Segment 5)	3.14-34b (Revised) Visual Simulation for KOP-Center-19 Gould Substation from Angeles Crest Scenic Byway (Alternative 2,
3.14-11b (Revised) Visual Simulation for KOP-North-9 Godde Hill Road (Alternative 2, Segment 5)	Segment 11)
3.14-12a (Revised) Existing Conditions for KOP-North-10 Elizabeth Lake Road (Alternative 2, Segment 5)	3.14-35a Existing Conditions for KOP-Center-20 Forest Road to Millard Campground (Alternative 2, Segment 11)
3.14-12b (Revised) Visual Simulation for KOP-North-10 Elizabeth Lake Road (Alternative 2, Segment 5)	3.14-35b Visual Simulation for KOP-Center-20 Forest Road to Millard Campground (Alternative 2, Segment 11)
3.14-13a (Revised) Existing Conditions for KOP-North-11 Sierra Pelona Ridge from Avenue S (Alternative 2, Segment 5)	3.14-36a (Revised) Existing Conditions for KOP-South-1Royal Oaks/Tocino Intersection, Duarte (Alternative 2, Segment 7)
3.14-13b (Revised) Visual Simulation for KOP-North-11 Sierra Pelona Ridge from Avenue S (Alternative 2, Segment 5)	3.14-36b (Revised) Visual Simulation for KOP- South-1Royal Oaks/Tocino Intersection, Duarte (Alternative 2, Segment 7)
3.14-14a (Revised) Existing Conditions for KOP-North-12 Sierra Highway and Antelope Valley Freeway (Alternative 2, Segment 5)	3.14-37a (Revised) Existing Conditions for KOP-South-2 I-605 Corridor Between I-210 & Arrow Hwy, Irwindale (Alternative 2,
3.14-14b (Revised) Visual Simulation for KOP-North-12 Sierra Highway and Antelope Valley Freeway (Alternative 2, Segment 5)	Segment 7)
3.14-15a (Revised) Existing Conditions for KOP-North-13 Acton/Vincent Grade Metrolink Park and Ride (Alternative 2, Segment 5)	3.14-37b (Revised) Visual Simulation for KOP- South-2 I-605 Corridor Between I-210 & Arrow Hwy, Irwindale (Alternative 2,
3.14-15b (Revised) Visual Simulation for KOP-North-13 Acton/Vincent Grade Metrolink Park and Ride (Alternative 2, Segment 5)	Segment 7)
3.14-16a (Revised) Existing Conditions for KOP-Center-1 Southbound Angeles Forest Highway (Alternative 2, Segment 6)	3.14-38a (Revised) Existing Conditions for KOP-South-3 Linard Street/Kayann Place Intersection, South El Monte (Alternative 2,
3.14-16b (Revised) Visual Simulation for KOP-Center-1 Southbound Angeles Forest Highway (Alternative 2, Segment 6)	Segment 7)
3.14-17a (Revised) Existing Conditions for KOP-Center-2 Northbound Angeles Forest Highway (Alternative 2, Segment 6)	3.14-38b (Revised) Visual Simulation for KOP- South-3 Linard Street/Kayann Place Intersection, South El Monte (Alternative 2,
3.14-17b Visual Simulation for KOP-Center-2 Northbound Angeles Forest Highway (Alternative 2, Segment 6)	Segment 7)
3.14-18a Existing Conditions for KOP-Center-3 Mount Gleason Road (Alternative 2, Segment 6)	3.14-39a (Revised) Existing Conditions for KOP-South-4 Paramount Boulevard, Montebello Hills (Alternative 2, Segment 7)
3.14-18b Visual Simulation for KOP-Center-3 Mount Gleason Road (Alternative 2, Segment 6)	3.14-39b (Revised) Visual Simulation for KOP- South-4 Paramount Boulevard, Montebello Hills (Alternative 2, Segment 7)
3.14-19a Existing Conditions for KOP-Center-4 Southbound Angeles Forest Highway (Alternative 2, Segment 6)	3.14-40a (Revised) Existing Conditions for KOP-South-5 Montebello Town Center, Montebello Hills (Alternative 2, Segment 7)
3.14-19b Visual Simulation for KOP-Center-4 Southbound Angeles Forest Highway (Alternative 2, Segment 6)	3.14-40b (Revised) Visual Simulation for KOP- South-5 Paramount Boulevard, Montebello Hills (Alternative 2, Segment 7)
3.14-20a Existing Conditions for KOP-Center-5 Northbound Angeles Forest Highway (Alternative 2, Segment 6)	3.14-41a (Revised) Existing Conditions for KOP-South-6 Legg Lake, Whittier Narrows, L.A. County (Alternative 2, Segment 7)
3.14-20b (Revised) Visual Simulation for KOP-Center-5 Northbound Angeles Forest Highway (Alternative 2, Segment 6)	3.14-41b (Revised) Visual Simulation for KOP- South-6 Legg Lake, Whittier Narrows, L.A. County (Alternative 2, Segment 7)
3.14-21a (Revised) Existing Conditions for KOP-Center-6 Southbound Upper Big Tujunga Canyon Road (Alternative 2, Segment 6)	3.14-42a (Revised) Existing Conditions for KOP-South-7 Buddhist Columbarium at Rose Hills Memorial Park (Alternative 2,
3.14-21b Visual Simulation for KOP-Center-6 Southbound Upper Big Tujunga Canyon Road (Alternative 2, Segment 6)	Segment 8)
3.14-22a Existing Conditions for KOP-Center-7 Northbound Upper Big Tujunga Canyon Road (Alternative 2, Segment 6)	3.14-42b (Revised) Visual Simulation for KOP- South-7 Buddhist Columbarium at Rose Hills Memorial Park (Alternative 2,
3.14-22b Visual Simulation for KOP-Center-7 Northbound Upper Big Tujunga Canyon Road (Alternative 2, Segment 6)	Segment 8)
3.14-23a (Revised) Existing Conditions for KOP-Center-8 Vetter Mountain Lookout (Alternative 2, Segment 6)	3.14-43a (Revised) Existing Conditions for KOP-South-8 Colima Road, Hacienda Heights (Alternative 2, Segment 8)
3.14-23b Visual Simulation for KOP-Center-8 Vetter Mountain Lookout (Alternative 2, Segment 6)	3.14-43b (Revised) Visual Simulation for KOP- South-8 Colima Road, Hacienda Heights (Alternative 2, Segment 8)
3.14-24a (Revised) Existing Conditions for KOP-Center-9 Angeles Crest Scenic Byway & Rincon-Shortcut Trailhead (Alternative 2,	3.14-44a (Revised) Existing Conditions for KOP-South-9 Hsi Lai Buddhist Temple (Alternative 2, Segment 8)
Segment 6)	3.14-44b (Revised) Visual Simulation for KOP- South-9 Hsi Lai Buddhist Temple (Alternative 2, Segment 8)
3.14-24b Visual Simulation for KOP-Center-9 Angeles Crest Scenic Byway & Rincon-Shortcut Trailhead (Alternative 2, Segment 6)	3.14-45a (Revised) Existing Conditions for KOP-South-10 Pathfinder Park, Rowland Heights (Alternative 2, Segment 8)
3.14-25a (Revised) Existing Conditions for KOP-Center-10 Eastbound Angeles Crest Scenic Byway (Alternative 2, Segment 6)	3.14-45b (Revised) Visual Simulation for KOP- South-10 Pathfinder Park, Rowland Heights (Alternative 2, Segment 8)
3.14-25b Visual Simulation for KOP-Center-10 Eastbound Angeles Crest Scenic Byway (Alternative 2, Segment 6)	3.14-46a (Revised) Existing Conditions for KOP-South-11 Orange Freeway (Highway 57), Diamond Bar (Alternative 2, Segment 8)

```
3.14-46b (Revised) Visual Simulation for KOP- South-11 Orange Freeway (Highway 57), Diamond Bar (Alternative 2, Segment 8)
3.14-47a (Revised) Existing Conditions for KOP-South-12 Crooked Creek Drive, Diamond Bar (Alternative 2, Segment 8)
3.14-47b (Revised) Visual Simulation for KOP- South-12 Crooked Creek Drive, Diamond Bar (Alternative 2, Segment 8)
3.14-48a (Revised) Existing Conditions for KOP-South-13 Intersection of Avenida Anita/Avenida Compadres, Chino Hills
(Alternative 2, Segment 8)
```

- 3.14-48b (Revised) Visual Simulation for KOP- South-13 Intersection of Avenida Anita/Avenida Compadres, Chino Hills (Alternative 2, Segment 8)
- 3.14-49a (Revised) Existing Conditions for KOP-South-14Coral Ridge Park, Chino Hills (Alternative 2, Segment 8)
- 3.14-49b (Revised) Visual Simulation for KOP- South-14 Coral Ridge Park, Chino Hills (Alternative 2, Segment 8)
- 3.14-50a (Revised) Existing Conditions for KOP-South-15 Cork Drive, Chino Hills (Alternative 2, Segment 8)
- 3.14-50b (Revised) Visual Simulation for KOP- South-15 Cork Drive, Chino Hills (Alternative 2, Segment 8)
- 3.14-51a (Revised) Existing Conditions for KOP-South-16 Yellowstone Circle, Chino(Alternative 2, Segment 8)
- 3.14-51b (Revised) Visual Simulation for KOP- South-16 Yellowstone Circle, Chino (Alternative 2, Segment 8)
- 3.14-52a (Revised) Existing Conditions for KOP-South-17 Edison Avenue at Reuben S. Ayala Community Park, Chino (Alternative 2, Segment 8)
- 3.14-52b (Revised) Visual Simulation for KOP- South-17 Edison Avenue at Reuben S. Ayala Community Park, Chino (Alternative 2, Segment 8)
- 3.14-53a (Revised) Existing Conditions for KOP-South-18 Chipola Court, Chino (Alternatives 2 and 4, Segment 8)
- 3.14-53b (Revised) Visual Simulation for KOP- South-18 Chipola Court, Chino (Alternative 2, Segment 8)
- 3.14-53c (New) Visual Simulation for KOP-South-18 Chipola Court, Chino (Alternative 4, Segment 8)
- 3.14-54a (Revised) Existing Conditions for KOP-South-19Tumbleweed Street, Ontario (Alternative 2, Segment 8)
- 3.14-54b (Revised) Visual Simulation for KOP- South-19 Tumbleweed Street, Ontario (Alternative 2, Segment 8)
- 3.14-55a (Revised) Existing Conditions for KOP-South-20 Chaparral Street and Clover Way, Ontario (Alternative 2, Segment 8)
- 3.14-55b (Revised) Visual Simulation for KOP- South-20 Chaparral Street and Clover Way, Ontario (Alternative 2, Segment 8)
- 3.14-56a (Revised) Existing Conditions for KOP-North-5 110th Street at Silverwind Way (Alternative 3, Segment 4)
- 3.14-56b (Revised) Visual Simulation for Alternative 3 at KOP-North-5 110th Street at Silverwind Way (Alternative 3, Segment 4)
- 3.14-57a (Revised) Existing Conditions for KOP-South-21 Carbon Canyon Road (Highway 142), Orange County (Alternative 4, Segment 8A)
- 3.14-57b (Revised) Visual Simulation for KOP- South-21 Carbon Canyon Road (Highway 142), Orange County. (Alternative 4, Routes A, C, and C Modified, Segment 8A)
- 3.14-57c (Revised) Visual Simulation for KOP- South-21 Carbon Canyon Road (Highway 142), Orange County. (Alternative 4, Routes B and D, Segment 8A)
- 3.14-58a (Revised) Existing Conditions for KOP-South-22 Vellano Planned Development, Chino Hills (Alternative 4, Routes A, B, C, C Modified, and D, Segment 8A)
- 3.14-58b (Revised) Visual Simulation for KOP-South-22 Vellano Planned Development, Chino Hills (Alternative 4, Routes A and B, Segment 8A)
- 3.14-58c (Revised) Visual Simulation for KOP-South-22 Vellano Planned Development, Chino Hills (Alternative 4, Route C and C Modified, Segment 8A)
- 3.14-58d (New) Visual Simulation for KOP-South-22 Vellano Planned Development, Chino Hills (Alternative 4, Route C Modified, Segment 8A)
- 3.14-58e (Revised) Visual Simulation for KOP-South-22 Vellano Planned Development, Chino Hills (Alternative 4, Route D, Segment 8A)
- 3.14-59a (Revised) Existing Conditions for KOP-South-23Chino Hills State Park Trail, CHSP (Alternative 4, Route A, Segment 8A)
- 3.14-59b (Revised) Visual Simulation for KOP-South-23Chino Hills State Park Trail, CHSP (Alternative 4, Route A, Segment 8A)
- 3.14-60a (Revised) Existing Conditions for KOP-South-24 Horse Camp in Chino Hills State Park, CHSP (Alternative 4, Routes A, B, C, C Modified, and D, Segment 8A)
- 3.14-60b (Revised) Visual Simulation for KOP-South-24 Horse Camp in Chino Hills State Park, CHSP (Alternative 4, Route A, Segment 8A)
- 3.14-60c (Revised) Visual Simulation for KOP-South-24 Horse Camp in Chino Hills State Park, CHSP (Alternative 4, Route B, Segment 8A)
- 3.14-60d (Revised) Visual Simulation for KOP-South-24 Horse Camp in Chino Hills State Park, CHSP (Alternative 4, Route C and C Modified, Segment 8A)

- 3.14-60e (Revised) Visual Simulation for KOP-South-24 Horse Camp in Chino Hills State Park, CHSP (Alternative 4, Route D, Segment 8A)
- 3.14-61a (Revised) Existing Conditions for KOP-South-25Butterfield Ranch Road, Chino Hills (Alternative 4, Routes A, B, C, & D, Segment 8A)
- 3.14-61b (Revised) Visual Simulation for KOP-South-25 Butterfield Ranch Road, Chino Hills (Alternative 4, Route B and D, Segment 8A)
- 3.14-62a (Revised) Existing Conditions for KOP-South-26 Intersection of Gold Shadow Lane/Avenida Compadres, Chino Hills (Alternative 5, Segment 8A)
- 3.14-62b (Revised) Visual Simulation for KOP-South-26 Intersection of Gold Shadow Lane/Avenida Compadres, Chino Hills (Alternative 5, Segment 8A)
- 3.14-63a (Revised) Existing Conditions for KOP-South-27 Pipeline Avenue, Chino Hills (Alternative 5, Segment 8A)
- 3.14-63b (Revised) Visual Simulation for KOP-South-27 Pipeline Avenue, Chino Hills (Alternative 5, Segment 8A)
- 3.14-64a Existing Conditions for KOP-Center-1 Southbound Angeles Forest Highway (Alternative 6, Segment 6)
- 3.14-64b (Revised) Visual Simulation for KOP-Center-1 Southbound Angeles Forest Highway (Alternative 6, Segment 6)
- 3.14-65a Existing Conditions for KOP-Center-2 Northbound Angeles Forest Highway (Alternative 6, Segment 6)
- 3.14-65b Visual Simulation for KOP-Center-2 Northbound Angeles Forest Highway (Alternative 6, Segment 6)
- 3.14-66a Existing Conditions for KOP-Center-3 Mount Gleason Road (Alternative 6, Segment 6)
- 3.14-66b (Revised) Visual Simulation for KOP-Center-3 Mount Gleason Road (Alternative 6, Segment 6)
- 3.14-67a Existing Conditions for KOP-Center-4 Southbound Angeles Forest Highway (Alternative 6, Segment 6)
- 3.14-67b (Revised) Visual Simulation for KOP-Center-4 Southbound Angeles Forest Highway (Alternative 6, Segment 6)
- 3.14-68a Existing Conditions for KOP-Center-5 Northbound Angeles Forest Highway (Alternative 6, Segment 6)
- 3.14-68b (Revised) Visual Simulation for KOP-Center-5 Northbound Angeles Forest Highway (Alternative 6, Segment 6)
- 3.14-69a (Revised) Existing Conditions for KOP-Center-6 Southbound Upper Big Tujunga Canyon Road (Alternative 6, Segment 6)
- 3.14-69b (Revised) Visual Simulation for KOP-Center-6 Southbound Upper Big Tujunga Canyon Road (Alternative 6, Segment 6)
- 3.14-70a Existing Conditions for KOP-Center-7 Northbound Upper Big Tujunga Canyon Road (Alternative 6, Segment 6)
- 3.14-70b (Revised) Visual Simulation for KOP-Center-7 Northbound Upper Big Tujunga Canyon Road (Alternative 6, Segment 6)
- 3.14-71a Existing Conditions for KOP-Center-8 Vetter Mountain Lookout (Alternative 6, Segment 6)
- 3.14-71b (Revised) Visual Simulation for KOP-Center-8 Vetter Mountain Lookout (Alternative 6, Segment 6)
- 3.14-72a Existing Conditions for KOP-Center-9 Angeles Crest Scenic Byway & Rincon-Shortcut Trailhead (Alternative 6, Segment 6)
- 3.14-72b Visual Simulation for KOP-Center-9 Angeles Crest Scenic Byway & Rincon-Shortcut Trailhead (Alternative 6, Segment 6)
- 3.14-73a Existing Conditions for KOP-Center-10 Eastbound Angeles Crest Scenic Byway (Alternative 6, Segment 6)
- 3.14-73b (Revised) Visual Simulation for KOP-Center-10 Eastbound Angeles Crest Scenic Byway (Alternative 6, Segment 6)
- 3.14-74a Existing Conditions for KOP-Center-11 Silver Moccasin Trailhead (Alternative 6, Segment 6)
- 3.14-74b (Revised) Visual Simulation for KOP-Center-11 Silver Moccasin Trailhead (Alternative 6, Segment 6)
- 3.14-75a (Revised) Existing Conditions for KOP-Center-12 Cogswell Reservoir & National Scenic Bikeway (Alternative 6, Segment 6)
- 3.14-75b (Revised) Visual Simulation for KOP-Center-12 Cogswell Reservoir & National Scenic Bikeway (Alternative 6, Segment 6)
- 3.14-76a Existing Conditions for KOP-Center-13 Mount Zion (Alternative 6, Segment 6)
- 3.14-76b Visual Simulation for KOP-Center-13 Mount Zion (Alternative 6, Segment 6)
- 3.14-77a (Revised) Existing Conditions for KOP-Center-14 Pacific Crest Trail (Alternative 6, Segment 11)
- 3.14-77b Visual Simulation for KOP-Center-14 Pacific Crest Trail (Alternative 6, Segment 11)
- 3.14-78a (Revised) Existing Conditions for KOP-Center-15 Eastbound Mount Gleason Road (Alternative 6, Segment 11)
- 3.14-78b (Revised) Visual Simulation for KOP-Center-15 Eastbound Mount Gleason Road (Alternative 6, Segment 11)
- 3.14-79a (Revised) Existing Conditions for KOP-Center-16 Southbound Angeles Forest Highway (Alternative 6, Segment 11)
- 3.14-79b (Revised) Visual Simulation for KOP-Center-16 Southbound Angeles Forest Highway (Alternative 6, Segment 11)
- 3.14-80a Existing Conditions for KOP-Center-17 Northbound Angeles Forest Highway (Alternative 6, Segment 11)
- 3.14-80b Visual Simulation for KOP-Center-17 Northbound Angeles Forest Highway (Alternative 6, Segment 11)
- 3.14-81a Existing Conditions for KOP-Center-18 Clear Creek Outdoor Education Camp (Alternative 6, Segment 11)
- 3.14-81b Visual Simulation for KOP-Center-18 Clear Creek Outdoor Education Camp (Alternative 6, Segment 11)
- 3.14-82a Existing Conditions for KOP-Center-19 Gould Substation from Angeles Crest Scenic Byway (Alternative 6, Segment 11)
- 3.14-82b Visual Simulation for KOP-Center-19 Gould Substation from Angeles Crest Scenic Byway (Alternative 6, Segment 11)
- 3.14-83a Existing Conditions for KOP-Center-20 Forest Road to Millard Campground (Alternative 6, Segment 11)
- 3.14-83b Visual Simulation for KOP-Center-20 Forest Road to Millard Campground (Alternative 6, Segment 11)