

**Sunrise Powerlink- 230kV Overhead Grounding Summary Report
Mitigation Measure PS-2a**

Number	Location	Object to be grounded	Date Completed
1	CP8	Woven wire fence and gate at entry to base	June 1, 2012
2	CP14/CP15-2	Woven wire fence	May 17, 2012
3	CP24-1/CP25-2	3FT Tall, 3 wire (barb)/Metal gate Station 214+79, crosses line	May 4, 2012
4	CP25-2/CP26	3 wire (barb) Station 224+38, left of line	May 4, 2012
5	CP28-1/CP29-1	4FT Tall, 3 wire (Barb) w/ T-bars	May 8, 2012
6	CP36-1/CP37-2	Barb wire fence/Guard rail	April 30, 2012
7	CP42-1/43-1	Ground each end and center	May 8, 2012
8	CP43-1/CP44-1	Large Gazebo, Metal Roof, Two chain link fences	May 17, 2012
9	CP53-1/CP54-1	Fences, house, water tank	May 19, 2012
10	CP69-2/CP70-3	Horse gate and Pipe rail fence, left of line	May 19, 2012
11	CP70-3/CP71	Gate/Pipe rail fencing/4ft Tall chainlink	May 24, 2012
12	CP95-1/CP99-2	Ground fences on edge of ROW at 500' intervals.	May 18, 2012
13	CP99-2/CP100-1	Gate and pipe rail fence	May 18, 2012