



This report provides a summary of environmental monitoring and compliance activities conducted by Burns and McDonnell (BMcD) staff and BMcD subconsultants for the San Diego Gas & Electric (SDG&E) Sunrise Powerlink Project during the above weekly time period.

Training

- SWEAP training continued for new Project personnel every Tuesday and Thursday. Additional trainings were provided as requested.
- Flat-tailed horned lizard (FTHL) trainings were provided to any new crew members or monitors prior to construction per mitigation measure B-7b and in accordance with the FTHL Rangewide Management Strategy. During morning tailboard meetings, guidelines were provided about recognizing, protecting, and notification requirements for FTHL. FTHL information cards were made available to any crew members or monitors as needed.
- Barefoot banded gecko trainings were provided to crews prior to pre-construction activities pursuant to the California Department of Fish and Game (CDFG) 2081 Incidental Take Permit requirements.
- Emergency Action/Fire Prevention training occurred on October 31, 2011.
- Environmental Inspections training occurred on November 2, 2011.
- Wildland Fire Refresher, Environmental Inspections/Warrants, Emergency Action/Fire Prevention, Heat Illness Prevention, and Smith Driving Refresher trainings occurred on November 4, 2011.
- Environmental PBS re-training was held October 31, 2011 through November 4, 2011 for all crew members and project personnel.

Pre/Post Construction

- Staked, flagged, and refreshed work areas at CP55, CP70 to CP71, EP9-1 to EP11-3, EP27-1 to EP28-1, EP32, EP42 to EP43-1, EP69-2, EP70-3, EP75-1, EP116-1 to EP117-2, EP119-2 to EP120-4, EP190-2 to EP191-2, EP238-1 to EP239-1, EP243 to EP244, EP247 to EP248-1, EP253-2 to EP254-3, EP259B to EP261-2, EP301, EP322-1 to EP323-1, and EP330-1 to EP331.
- Guard structure post construction impact survey from EP295 to EP296, EP299 to EP300-1, and EP341 to EP342.
- Post construction impact survey at EP324 access road.
- The ESA Team conducted the following activities during this reporting period:
 - Installed project signs and ESAs at CP70-3 and CP71.
 - Repaired, refreshed, and maintained the previously installed project signs and ESAs at Dunaway Yard, EP187-PS-N, EP220-1-PS-N, EP255-2-PS-S, EP345 to EP346, and EP346-E and EP346-N access roads.

Construction

- Monitors were present during construction activities to ensure compliance with mitigation measures as identified in the Final EIR/EIS Mitigation Monitoring, Compliance, and Reporting Program. Archaeologists, Paleontologists, and Native American Monitors were present at sites



Sunrise Powerlink Project
Weekly Report 59 – October 30, 2011 through November 05, 2011



where required as identified prior to construction activity and as approved in the NTPs. On average, the following number of monitors were on the Project throughout the week:

- 8 Archaeological Monitors.
- 128 Biological Monitors.
- 8 Native American Monitors.
- 8 SWPPP Monitors.
- Project staff carpooled to site reviews, kick-off tailgates, and off-site meetings. Construction and traffic control crews were observed carpooling from yards to work areas.
- Deterrents were utilized to discourage bird nest building activities throughout the Project. Deterrents are determined depending upon the location and type of possible nesting areas and may include metallic flagging, compact discs, plastic owls, and the presence of biological monitors. The table below demonstrates the construction progress to date:

OVERHEAD			
Agency	Foundations Completed	Towers Erected	Wire Installed
Non-Federal	85 of 169	42 of 169	11 of 169 EP215 to EP219
Bureau of Land Management	115 of 179	80 of 179	45 of 179 EP314 to EP322
Miramar	3 of 12	3 of 12	0 of 12
US Forest Service	14 of 76	0 of 76	0 of 76
UNDERGROUND			
Agency	Vaults Installed	Trenches Excavated & Backfilled	
Non-Federal	40 of 40	38 of 42	
SUBSTATION UPGRADES			
	2 of 7 Completed		
SUNCREST SUBSTATION			
	71 Percent Complete		



Overhead Construction

- Link 1
 - Vegetation clearing at EP170, EP170 pull sites, and Suckle mitigation property.
 - Boulder removal at EP170 and EP254-3.
 - Access road construction at EP227-E-A.
 - Grading at EP170 and EP170 pull sites.
 - Gate installation at EP191-2-N and EP220-1-N.
 - Gate adjustments and removal at EP206-1, EP207, and EP208.
 - Driveway installation at EP226-1-PS-E, EP227-E-A, and EP232-1-E-B at Desert Ranch Road.
 - Micropile drill setup at EP254-3.
 - Micropile drilling at EP252A-1 and EP261A.
 - Grouting at EP261A.
 - Micropile trimming at EP259-3, EP259B, EP261A, EP262-4, EP263A-2, EP263B-2, EP264-4, EP265-2, EP266-2, EP267-2, EP271-2, EP272-3, EP276-1, EP277-1, EP278-1, and EP281.
 - Proof testing at EP261-2, EP261A, EP263A-2, EP263B-2, EP265-2, EP266-2, and EP281.
 - Micropile cap work at EP269-1, EP270-2, EP271-2, EP272-3, EP273-1, EP274-1, EP275-1, EP276-1, EP277-1, EP278-1, and EP281.
 - Conventional drilling at EP174, EP175, EP176, EP199-3, and EP202-3.
 - Various foundation work (capping, cage installation, grounding, etc.) at EP176, EP182, EP199-3, and EP202-3.
 - Concrete pouring at EP176, EP199-3, and EP202-3.
 - Form removal and cleanup at EP176, EP180, EP182, EP199-3, and EP202-3.
 - Tower assembly at EP200-3, EP200A-1, EP203-3, EP204-3, EP207, EP247, EP255-2, EP257, EP271-2, EP274-1, EP278-1, EP279-1, EP280-2, EP290, EP304-2, EP305-3, EP310, EP311-1, and EP312.
 - Miscellaneous assembly work (perch deterrents, anti-climb guards) at EP357, EP359, EP360, EP361, and EP362-1.
 - QA/QC at EP305, EP310, EP311-1, and EP312.
 - Ground fence installation along I-8 at EP341 and EP342.
 - Ground rod installation at EP203-3.
 - Haul back of A, B, and C phase hard line, all phases of conductor, pulled from EP215 to EP219-1.
 - Pulled sock line for optical ground wire (OPGW) and conductor, haul back on hard line for conductor, and pulled OPGW & conductor for all three phases between EP301 and EP313.
 - Traveler work from EP301 to EP313 and EP319.
 - Splicing at EP322-1.
 - Sleeving at EP313/EP314 pull site.
 - Anchors installed at EP280-2.
 - Insulator work at/between EP301, EP302-1, EP303-2, EP304-2, EP306-1, EP307-1, EP308, and EP311-1.
 - Spacers installed between EP215 to EP219, EP315-1, and EP324.
 - Clipping and sagging from EP313 to EP322-1.
 - Clipping in from EP215 to EP219.
 - Guard structure removal at EP215.
 - Dead-end work at EP215 and EP219.



Sunrise Powerlink Project
Weekly Report 59 – October 30, 2011 through November 05, 2011



- BMPs installed from:
 - EP170-N to EP171-N, EP170, EP170 pull sites, EP171, EP220-1-N, and EP220-1 pull site.
- BMPs maintained from:
 - EP170 to Rough Acres Yard, EP280-2, and Plaster City Yard to IV Substation.
- Hydromulching at EP215, EP219-S pull site, EP220-1-N, and EP220-1 pull sites.
- Trained FTHL monitors, BBG monitors, BHS monitors, and Visible Emission Evaluators (VEEs) were onsite as required.
- BBG sweeps were conducted each day in BBG habitat.

•

Link 2

- During this reporting period, the PAL Levels were as follows: Monday-Ev, Tuesday-Ev, Wednesday-E, Thursday-Ev, Friday-A, and Saturday-B. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

USFS Land

- Access road construction at:
 - EP105-E-A, EP105-E-B, EP125-N, EP126-1-N, EP127-N, EP130-1-N, EP131-N, EP140-N, EP141-N, and La Posta Road from pavement to EP141.
- Vegetation clearing at EP2-3 TSAP, EP3-3 TSAP, EP4-3 TSAP, EP5-2 TSAP, EP6-1 TSAP, EP7-1 TSAP, EP105-E-A, and EP105-E-B.
- Conventional drilling at EP126-1 and EP127.
- Micropile drilling at EP140.
- Various micropile work (capping, pile surveys, site benching, etc.) at EP140.
- Grouting at EP134-1, EP138-2, and EP139-1.
- Micropile test pull at EP132-2, EP134-1, EP135, EP136, EP137, EP139, and EP140.
- Micropile trimming at EP132-2, EP136, EP137, and EP140.
- Concrete poured at EP141.
- Set rebar cages and installed forms at EP130-1 and EP141.
- Form removal and cleanup at EP131.
- Tower assembly at EP131.
- Gate/Fence installation at EP129-E-A.
- BMP installation at:
 - EP105-E-A, EP105-E-B, EP125-N, EP126-1, EP126-1-N, EP127-N, EP130-1-N, EP131-N, EP140-N, EP141-N, and La Posta Road from pavement to EP141.

BLM Land

- Access road construction at:
 - EP39-1-N-B and EP42-N.
- Vegetation clearing at EP69, EP71, EP72, EP73, and EP74-1.
- Grading at EP42 pull site, EP47-2 pull site, EP49, and EP51-1.
- Conventional drilling at EP42.
- Various micropile work (capping, pile surveys, site benching, etc.) at EP43-1, EP44, and EP45-1.
- Micropile trimming at EP47-2.
- Drilled pilot holes for blasting at EP47-2 pull site.
- Grouting at EP47-2.
- BMP installation at:
 - EP47-2 pull site, EP51-1, EP69, EP71, EP72, EP73, and EP74-1.



Non-Federal Land

- Vegetation clearing at EP85-2-E, EP89 pull sites, EP91 pull site, EP105-E-A, and EP105-E-B.
- Grading at EP89 pull sites, EP91 pull site, EP105-E-A, and EP105-E-B.
- Tree trimming at EP77 and EP78.
- QA/QC at EP89-1 and EP90-1.
- BMP
installation at:
 - EP85-2-E,
EP89 pull sites, EP91 pull site, EP105-E-A, and EP105-E-B.

•

Link 5

- During this reporting period, the PAL Levels were as follows: Monday-Ev, Tuesday-Ev, Wednesday-E, Thursday-Ev, Friday-A, and Saturday-B. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

USFS Land

- Vegetation removal at CP99-2 and CP100-1.
- Tree trimming at CP105-1.
- Access road construction at:
 - CP100-1-N.
- Dexpan boulder breaking at CP99-2.
- Conventional drilling at CP69-2 and CP100-1.
- Various micropile work (capping, pile surveys, site benching, etc.) at CP104-1.
- Micropile trimming at CP104-1.
- Micropile test pull at CP105-1.
- Grouting at CP105-1.
- Install temporary bridge at CP70-3-E-A for water line crossing.
- Gate installation at CP69-2.
- QA/QC at CP101-1, CP103-3, CP104-1, and CP105-1.
- BMP installation at:
 - CP100-1-N.
- Hydromulching at CP100-1-N.

BLM Land

- Tree trimming at CP67-3 and CP68-1.
- Various micropile work (capping, pile surveys, site benching, etc.) at CP65-1 and CP67-3.
- Micropile drilling at CP62A.
- Site cleanup at CP66-2 and CP68-1.
- BMP installation at:
 - CP65-1, CP66-2, CP67-3, and CP68-1.

Non-Federal Land

- Vegetation removal at CP31-2 pull site, CP31-2-E, CP31-2-N, CP31-2-PS-E, CP55/CP56-1 pull site, and CP56-1-E-A.
- Grading at CP31-2 pull site, CP31-2-E, CP31-2-N, CP31-2-PS-E, CP48-2/CP49-1 pull site, CP55/CP56-1 pull site, CP98-N-B, and CP99-N.



Sunrise Powerlink Project
Weekly Report 59 – October 30, 2011 through November 05, 2011



- Access road construction at:
 - CP49-1-PS-E, CP49-1-PS-N, CP56-1-E-A, CP64-2-E, and CP65-1-PS-N.
 - Dexpan boulder breaking at CP55/CP56-1 pull site, CP56-1-E-A, CP80-2, CP106-1, and CP107-1.
 - Drilled for blasting at CP49-1-PS-E and CP49-1-PS-N.
 - Airtrack drilling at CP98.
 - Micropile trimming at CP107.
 - Various micropile work (capping, pile surveys, site benching, etc.) at CP71, CP74-2, and CP107.
 - Grouting at CP70-3 and CP109-1.
 - Conventional drilling at CP70-3.
 - Micropile drilling at CP56-1, CP62-2, CP62A, and CP78-2.
 - Install ground rods at CP19, CP20, CP22, and CP75-1.
 - Tower assembly at CP41-2.
 - Site cleanup at CP75-1.
 - BMP installation at:
 - CP18-1, CP19-1, CP20, CP31-2 pull site, CP31-2-E, CP31-2-N, and CP31-2-PS-E, CP49-1-PS-E, CP49-1-PS-N, CP48-2/CP49-1 pull site, CP55/CP56-1 pull site, CP56-1, CP56-1-E-A, CP70-3, CP71, CP72-2, CP73-2, CP98-1-N-A, CP98-N-B, and CP99-N.
 - Hydromulching at CP98-1-N-A, CP98-N-B, and CP99-N.
-
- No work occurred during this reporting period.

69kV

Underground Construction (Link 4)

- Revitalization near South Grade Road.
- Trenching at Viejas Creek Bridge, V1L to riser pole, and V1R to riser pole.
- Pre-drilling/Drilling at Viejas Creek Bridge.
- Pre-racking/Racking and cleaning manholes for ABB (and jointing/splicing) at V3L, V4L, V10L, V11L, V20L, V1R, V7R, V10R, V12R, and V13R.
- Proofing from V1L to Riser Pole, V1L to V2L, Viejas Creek Bridge (south side), and V18L to V19L.
- Cable pulling from V9R to V10R and V18L to V19L.
- Erecting scaffolding at EP95 and Loritz Property.
- Terminating at Loritz riser pole.
- Forming at Slay Property (riser pole) and Viejas Creek Bridge.
- Road work at Slay/Bauer Property.
- Grading at Slay Property.
- Cooling line installation at Bore CalTrans Highway 8.

Suncrest Substation Construction (Link 3)

- Rough grading on the substation pad and along Bell Bluff Truck Trail.
- Crushing rock for select fill material.
- Steel erection in the northwest and southwest quadrants of the pad.
- Culvert installation east of the guard shack.
- Forming pads for foundations and pouring concrete.
- Trenching for conduit and ground grid in the southwest quadrant.
- Grading Class 2 base on the access roads leading to the northern and southern detention basins.
- Transformer assembly.



- BMP maintenance and installation ahead of predicted rain event and following rain event.
- Placing blocks and grouting for control shelter.
- Finish grading access road to the northern and southern basins.

Substation Upgrades

- Encina Switchyard
 - SDG&E crews were onsite working on scheduled outage preparation and wiring.
 - Marco Crane was onsite setting two transformers in Bay 10.
 - Roel Construction Superintendent Dave Goodwin was onsite revising engineering drawing for new 230 kV transformer containment pit.
 - Roel Construction continued forming frame for new 230 kV transformer containment pit until engineering drawing needed to be revised.
- Imperial Valley (IV)
 - PRAVA Construction built out the new maintenance/storage building.
 - SDG&E ETRAM crew was staging equipment in the northwest corner of the substation.
 - SDG&E worked in Bay 4 as well as erecting steel frames and bus supports.
 - Roel Construction continued forming pads in northeastern portion of substation in Bay 4.
- San Luis Rey
 - Wiring on new TBEA bank 70, 230 kV transformer.
- Sycamore Canyon
 - SDG&E Kearny Mesa crews worked on substation upgrades in Bay 26 and wiring gas circuit breakers. Crew is building disconnect stands and bus supports.
- Scripps
 - No Sunrise-related work

Construction Yards

- AER Yard – Helicopter operations, flying equipment, materials staging, and dust suppression.
- Alpine Yard – Materials staging and weed wash station.
- Bartlett-Hauser Yard – Water staging, helicopter operations, material delivery, and weed wash station.
- Barrett Canyon Yard – Grading access road, blasting, drilling, grading tower pull sites between EP39 and EP42, and hydromulch.
- Dunaway Yard – Awaiting seeding and fence removal in preparation for reclamation.
- Fromm Yard – Tower assembly, water staging, dust suppression, steel erection, dumpster delivery, and steel plates picked up.
- El Monte Yard – Crew staging, equipment and materials staging, helicopter operations, and dust suppression.
- Helix Yard – Helicopter operations, equipment and materials staging, concrete and crew staging, weed wash station, water staging, and dust suppression.
- Imperial Valley Yard – Awaiting seeding and removal of gravel water tank pad and fence in preparation for site reclamation.
- Jacumba Valley Ranch (JVR) Yard – Helicopter operations, weed wash station, water and equipment staging, materials and concrete staging, crew staging, dust suppression, and tower assembly.
- Kreutzkamp Yard – Tower assembly, helicopter operations, weed wash station, water staging, and



Sunrise Powerlink Project
Weekly Report 59 – October 30, 2011 through November 05, 2011



dust suppression.

- McCain Valley Yard – Tower assembly, equipment delivery, helicopter operations, water staging, and dust suppression.
- Plaster City Yard – Helicopter operations, concrete operations, staging for wire/line stringing, water staging, and dust suppression.
- Rough Acres Yard – Helicopter operations, materials staging, tower assembly, water staging, dust suppression, and weed wash station.
- S2 Yard – Tower assembly, equipment and materials staging, crew staging, helicopter operations, wire stringing staging, water staging, dust suppression, and helicopter activity.
- SWAT Yard – Tower assembly, concrete staging, water staging, helicopter operations, dust suppression, and weed wash station.
- Sycamore Yard – Tower assembly, weed wash station, dust suppression, helicopter operations, water staging (from hydrant), and steel assembly.
- Thing Valley Yard – Staging for La Posta Road work and rebar delivery.
- Wilson Yard – Staging materials for Suncrest Substation, helicopter operations, dust suppression, water staging, and tower assembly.

Wildlife Reporting

The following listed or Species of Special Concern were found dead in Project construction limits during this reporting period:

- Silvery Legless Lizard (*Anniella pulchra pulchra*) – Five (5) silvery legless lizards were found dead; one (1) at EP200A-1 and four (4) at EP105-2-N.
- Coastal Rosy Boa (*Lichanura trivirgata*) – One (1) coastal rosy boa was found dead north of CP95/CP96.

The following listed or Species of Special Concern were relocated during construction activities this reporting period:

- Flat-Tailed Horned Lizard (*Phrynosoma mcallii*) – One (1) flat-tailed horned lizard was relocated from Dunaway Yard.
- Coronado Skink (*Eumeces skiltonianus interparietalis*) – One (1) Coronado skink was relocated from CP31-2.
- Silvery Legless Lizard (*Anniella pulchra pulchra*) – Three (3) silvery legless lizards were relocated; one (1) from EP134-2 and two (2) from EP105-2 access road.
- Western Spadefoot Toad (*Spea hammondii*) – One (1) western spadefoot toad was relocated from CP31-2.

The following non-listed (not Species of Special Concern) were relocated during construction activities this reporting period:

- SWAT – One (1) deer mouse was relocated.

Spills/Hazardous Waste

- spills occurred during this reporting period No reportable



Customer Complaints

- No customer complaints were received during this reporting period.

Non-Compliances

- Non Compliance #2 from the USFS was issued on November 3, 2011, due to issues recorded during site visits.

Variances and TEWS

- Variance #29 for priority guard structures was approved on November 1, 2011.

Weather

- Rain events occurred on November 4-6, 2011.
 - November 4, 2011
 - EP25 to EP72 – Trace
 - EP73 to EP93 – 0.50 inches
 - SWAT Yard and Kreutzkamp Yard – Trace
 - Bartlett-Hauser Yard – 0.50 inches
 - EP105, EP125 to EP127, EP130 to EP131, EP138, EP140 to EP141, La Posta Road, and Thing Valley Yard – 0.20 inches
 - Suncrest Substation – 0.80 inches
 - Wilson Yard – 0.80 inches
 - Alpine HQ – 0.80 inches
 - Alpine Storage Yard – 0.50 inches
 - Hartung Yard – 0.80 inches
 - Helix Yard – 0.50 inches
 - Sycamore Yard – 0.75 inches
 - Sycamore Substation – 0.10 inches
 - CP44 – 0.45 inches
 - CP98 to CP100 – 0.10 inches
 - Encina Substation – 0.25 inches
 - November 5, 2011
 - McCain Valley Yard – 0.90 inches
 - Jacumba Valley Ranch Yard – 0.60 inches
 - AER Yard and Fromm Yard – 0.50 inches
 - Rough Acres Yard – 1 inch
 - EP107 to EP201 – 0.90 inches
 - EP208 to EP219 and EP220 – 1 inch
 - EP221-2 to EP238 – 0.60 inches
 - EP239 to EP254 – 0.60 inches
 - EP255 to EP281 – 0.50 inches
 - EP25 to EP72 – 1.60 inches
 - EP73 to EP93 – 1.90 inches
 - SWAT Yard – 1.70 inches
 - Kreutzkamp Yard – 1.40 inches
 - Bartlett-Hauser Yard – 1.90 inches



Sunrise Powerlink Project
Weekly Report 59 – October 30, 2011 through November 05, 2011



- EP101 to EP119, EP125 to EP141, La Posta Road, and Thing Valley Yard – 1.45 inches
- Suncrest Substation – 1.50 inches
- Wilson Yard – 1.50 inches
- Alpine HQ – 1.80 inches
- Alpine Storage Yard – 1.80 inches
- CP98 to CP100 Access Road – 1.50 inches
- CP101, CP103, CP104, CP105, CP106, CP107, CP108, and CP109 – 1.50 inches
- Hartung Yard – 1.80 inches
- Helix Yard – 1.40 inches
- Sycamore Yard – 1.15 inches
- Sycamore Substation – 1.20 inches
- CP29 to CP31 – 1.20 inches
- CP44 – 1.15 inches
- 69kV – 0.90 inches
- November 6, 2011
 - EP255 to EP281 – 1.60 inches
 - SWAT Yard – 1.70 inches
- BMPs were installed or maintained as needed throughout Project areas. In accordance with the Construction General Permit, daily site BMP inspections, photos, and appropriate BMPs for stormwater and non-stormwater were implemented. In accordance with the CGP, a post storm inspection was performed as a result of the qualifying rain event (QRE November 4, 2011 through November 6, 2011). Failures and shortcomings that were identified in the post storm inspection have been assessed and repairs/design changes to the BMPs will begin within 72 hours of identification.



Sunrise Powerlink Project
Weekly Report 59 – October 30, 2011 through November 05, 2011



Setting of the layback at EP279-1. *Photo courtesy of Rebecca Carson.*

Appendices

Peninsular Big Horn Sheep Monitoring Report

Flat-Tailed Horned Lizard Monitoring Report

Raven Control monitoring Report

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
11/5/2011	EP300-EP312	0	Site clearance survey
11/5/2011	EP300-EP312	0	Monitoring construction activities
11/5/2011	EP271-2, EP272-3, EP276-1 & EP281	0	Monitoring construction activities
11/5/2011	EP269-EP273	0	Site clearance survey
11/5/2011	EP265-2	0	Monitoring construction activities
11/5/2011	EP256-EP263A	0	Site clearance survey
11/5/2011	EP279-EP294	0	Site clearance survey
11/5/2011	EP279-EP294	0	Monitoring construction activities
11/5/2011	EP277-1	0	Monitoring construction activities
11/5/2011	EP263B-EP267	0	Site clearance survey
11/5/2011	EP263B-EP267	0	Monitoring construction activities
11/4/2011	S2 CY	0	Monitoring construction activities
11/4/2011	EP311, EP310	0	Monitoring construction activities
11/4/2011	EP307	0	Monitoring construction activities
11/4/2011	EP306/EP307 Pullsite	0	Monitoring construction activities
11/4/2011	EP300-EP312	0	Site clearance survey
11/4/2011	EP300-EP312	0	Monitoring construction activities
11/4/2011	EP269-EP273	0	Site clearance survey
11/4/2011	EP269-EP271	0	Site clearance survey
11/4/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/4/2011	EP279-EP294	0	Site clearance survey
11/4/2011	EP279-EP294	0	Monitoring construction activities
11/4/2011	EP274-EP278	0	Site clearance survey
11/4/2011	EP274-EP278	0	Monitoring construction activities
11/4/2011	EP263B-EP267	0	Site clearance survey
11/4/2011	EP263B-EP267	0	Monitoring construction activities
11/3/2011	EP311	0	Monitoring construction activities
11/3/2011	EP307	0	Monitoring construction activities
11/3/2011	EP280	0	Monitoring construction activities
11/3/2011	EP279-1	0	Monitoring construction activities
11/3/2011	EP278-1, EP279-1, EP280-1	0	Monitoring construction activities
11/3/2011	EP271-2	0	Monitoring construction activities
11/3/2011	EP269-EP273	0	Site clearance survey
11/3/2011	EP265-2	0	Monitoring construction activities
11/3/2011	EP263B-EP267; EP279-EP312	0	Site clearance survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
11/3/2011	EP261A, EP259-3	0	Monitoring construction activities
11/3/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/3/2011	EP279-EP294	0	Site clearance survey
11/3/2011	EP279-EP294	0	Monitoring construction activities
11/3/2011	EP274-EP278	0	Site clearance survey
11/3/2011	EP274-EP278	0	Monitoring construction activities
11/2/2011	EP269-EP273	0	Site clearance survey
11/2/2011	EP269-EP281	0	Site clearance survey
11/2/2011	EP269-EP281	0	Monitoring construction activities
11/2/2011	EP263B-EP267; EP279-EP312	0	Site clearance survey
11/2/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/2/2011	EP300-EP312; EP274-EP278	0	Site clearance survey
11/2/2011	EP300-EP312; EP274-EP278	0	Monitoring construction activities
11/1/2011	Suckle Property	0	Monitoring construction activities
11/1/2011	EP310 & EP311	0	Monitoring construction activities
11/1/2011	EP300-EP312	0	Site clearance survey
11/1/2011	EP300-EP312	0	Monitoring construction activities
11/1/2011	EP279-EP312	0	Site clearance survey
11/1/2011	EP277-1, EP276-1, EP261A, EP259B	0	Monitoring construction activities
11/1/2011	EP275-1	0	Monitoring construction activities
11/1/2011	EP269-EP273	0	Site clearance survey
11/1/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/1/2011	EP274-EP278	0	Site clearance survey
11/1/2011	EP274-EP278	0	Monitoring construction activities
11/1/2011	EP263B, EP267	0	Site clearance survey
11/1/2011	Devil's Canyon Bridge	0	Site clearance survey
11/1/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/31/2011	EP279-EP294	0	Site clearance survey
10/31/2011	EP279-EP294	0	Monitoring construction activities
10/31/2011	EP269-EP281	0	Site clearance survey
10/31/2011	EP269-EP281	0	Monitoring construction activities
10/31/2011	EP269-EP273	0	Site clearance survey
10/31/2011	EP269-EP281	0	Site clearance survey
10/31/2011	EP263A-2, EP266-2	0	Monitoring construction activities
10/31/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
10/31/2011	EP254-3	0	Monitoring construction activities
10/31/2011	EP305, EP310-1	0	Monitoring construction activities
10/31/2011	EP300-EP312	0	Site clearance survey
10/31/2011	EP300-EP312	0	Monitoring construction activities
10/31/2011	EP274-EP278	0	Site clearance survey
10/31/2011	EP263B-EP267	0	Site clearance survey
10/31/2011	Devil's Canyon Bridge	0	Site clearance survey
10/31/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/31/2011	EP262-4, EP263B-2, EP265-2, EP266-2, EP267-1	0	Monitoring construction activities
10/30/2011	EP300-EP306	0	Site clearance survey
10/30/2011	EP300-EP306	0	Monitoring construction activities
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Monitoring construction activities
10/30/2011	EP269-EP273	0	Site clearance survey
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Monitoring construction activities
10/30/2011	EP269-EP270	0	Site clearance survey
10/30/2011	EP267-2 & EP266-2	0	Monitoring construction activities
10/30/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/30/2011	EP279-EP294	0	Site clearance survey
10/30/2011	EP279-EP294	0	Monitoring construction activities
10/30/2011	EP274-EP278	0	Site clearance survey
10/30/2011	EP274-EP278	0	Monitoring construction activities
10/30/2011	EP263B-EP267	0	Site clearance survey
10/30/2011	Devil's Canyon Bridge	0	Site clearance survey
10/30/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/29/2011	EP300-EP306	0	Site clearance survey
10/29/2011	EP300-EP306	0	Monitoring construction activities
10/29/2011	EP274-EP278	0	Site clearance survey
10/29/2011	EP274-EP278	0	Monitoring construction activities
10/29/2011	EP269-EP273	0	Site clearance survey
10/29/2011	EP269-1	0	Monitoring construction activities
10/29/2011	EP269-EP281	0	Site clearance survey
10/29/2011	EP269-EP281	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
10/29/2011	EP269-EP281	0	Site clearance survey
10/29/2011	EP269-EP281	0	Monitoring construction activities
10/29/2011	EP269-EP270	0	Site clearance survey
10/29/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/29/2011	EP279-EP294	0	Site clearance survey
10/29/2011	EP279-EP294	0	Monitoring construction activities
10/29/2011	EP263B-EP267	0	Site clearance survey
10/29/2011	Devil's Cyn Bridge (w/in I-8 Island)	1	Morning perimeter survey 7:37 am
10/28/2011	EP300-EP306	0	Site clearance survey
10/28/2011	EP300-EP306	0	Monitoring construction activities
10/28/2011	EP269-EP281	0	Site clearance survey
10/28/2011	EP269-EP281	0	Monitoring construction activities
10/28/2011	EP269-EP273	0	Site clearance survey
10/28/2011	EP269-1	0	Monitoring construction activities
10/28/2011	EP269-EP281	0	Site clearance survey
10/28/2011	EP269-EP281	0	Monitoring construction activities
10/28/2011	EP269-EP270	0	Site clearance survey
10/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/28/2011	EP310	0	Monitoring construction activities
10/28/2011	EP279-EP294	0	Site clearance survey
10/28/2011	EP279-EP294	0	Monitoring construction activities
10/28/2011	EP274-EP278	0	Site clearance survey
10/28/2011	EP274-EP278	0	Monitoring construction activities
10/28/2011	EP263B-EP267	0	Site clearance survey
10/28/2011	AER and FROMM CY	0	Monitoring construction activities
10/27/2011	EP273-1 & EP276-1	0	Monitoring construction activities
10/27/2011	EP271-EP272	2	Site clearance survey 7:40 am
10/27/2011	EP271-EP272	0	Monitoring construction activities
10/27/2011	EP269-EP281: EP300-EP306	0	Site clearance survey
10/27/2011	EP269-EP281: EP300-EP306	0	Monitoring construction activities
10/27/2011	EP256-EP263A-2, AER CY	0	Site clearance survey
10/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/27/2011	EP279-EP294	0	Site clearance survey
10/27/2011	EP279-EP294	0	Monitoring construction activities
10/27/2011	EP274-EP278	0	Site clearance survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
10/27/2011	EP274-EP278	0	Monitoring construction activities
10/27/2011	EP269-EP271	0	Monitoring construction activities
10/27/2011	EP263B-EP267	0	Site clearance survey
10/27/2011	AER and FROMM CY	0	Monitoring construction activities
10/26/2011	EP311-1, EP312, EP310	0	Monitoring construction activities
10/26/2011	EP300-EP312	0	Site clearance survey
10/26/2011	EP300-EP312	0	Monitoring construction activities
10/26/2011	EP272-EP273	2	Site clearance survey 10:00 am
10/26/2011	EP272-EP273	0	Monitoring construction activities
10/26/2011	EP269-EP281; EP300-EP306	0	Site clearance survey
10/26/2011	EP269-EP281; EP300-EP306	0	Monitoring construction activities
10/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/26/2011	EP279-EP294	0	Site clearance survey
10/26/2011	EP279-EP294	0	Monitoring construction activities
10/26/2011	EP274-EP278	0	Site clearance survey
10/26/2011	EP274-EP278	0	Monitoring construction activities
10/26/2011	EP263B-EP267	0	Site clearance survey
10/25/2011	EP363-EP341, EP299 & EP300	0	Monitoring construction activities
10/25/2011	EP313-EP324	0	Monitoring construction activities
10/25/2011	EP310	0	Monitoring construction activities
10/25/2011	EP300-EP312	0	Site clearance survey
10/25/2011	EP300-EP312	0	Monitoring construction activities
10/25/2011	EP290	0	Monitoring construction activities
10/25/2011	EP269-EP273	0	Site clearance survey
10/25/2011	EP269-EP281; EP300-EP306	0	Site clearance survey
10/25/2011	EP269-EP281; EP300-EP306	0	Monitoring construction activities
10/25/2011	EP311	0	Monitoring construction activities
10/25/2011	EP279-EP294	0	Site clearance survey
10/25/2011	EP263B-EP267	0	Site clearance survey
10/24/2011	EP313-EP322	0	Monitoring construction activities
10/24/2011	EP305, EP306, EP312	0	Monitoring construction activities
10/24/2011	EP300-EP306	0	Site clearance survey
10/24/2011	EP300-EP306	0	Monitoring construction activities
10/24/2011	EP297-EP319	0	Monitoring construction activities
10/24/2011	EP269-EP273	0	Site clearance survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
10/24/2011	EP269-EP273	0	Monitoring construction activities
10/24/2011	EP269-EP281	0	Site clearance survey
10/24/2011	EP269-EP281	0	Monitoring construction activities
10/24/2011	EP279-EP294	0	Site clearance survey
10/24/2011	EP279-EP294	0	Monitoring construction activities
10/24/2011	EP274-EP278	0	Site clearance survey
10/24/2011	EP274-EP278	0	Monitoring construction activities
10/24/2011	EP263B-EP267	0	Site clearance survey
10/23/2011	EP300-EP312	0	Site clearance survey
10/23/2011	EP300-EP312	0	Monitoring construction activities
10/23/2011	EP269-EP273	0	Site clearance survey
10/23/2011	EP269-EP273	0	Monitoring construction activities
10/23/2011	EP269-EP281	0	Site clearance survey
10/23/2011	EP269-EP281	0	Monitoring construction activities
10/23/2011	EP269-EP270	0	Site clearance survey
10/23/2011	EP263B-EP267	0	Site clearance survey
10/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/23/2011	EP300-EP312	0	Site clearance survey
10/23/2011	EP300-EP312	0	Monitoring construction activities
10/23/2011	EP274-EP278	0	Site clearance survey
10/23/2011	EP274-EP278	0	Monitoring construction activities
10/23/2011	EP269-EP273	0	Site clearance survey
10/23/2011	EP269-EP273	0	Monitoring construction activities
10/22/2011	EP300-EP306	0	Site clearance survey
10/22/2011	EP300-EP306	0	Monitoring construction activity
10/22/2011	EP269-EP281	0	Site clearance survey
10/22/2011	EP269-EP281	0	Monitoring construction activity
10/22/2011	EP269-EP281	0	Site clearance survey
10/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/22/2011	EP274-EP278	0	Site clearance survey
10/22/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP306-EP312	0	Site clearance survey
10/21/2011	EP306-EP312	0	Monitoring construction activity
10/21/2011	EP274-EP278	0	Site clearance survey
10/21/2011	EP274-EP278	0	Monitoring construction activity

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
10/21/2011	EP269-EP281	0	Site clearance survey
10/21/2011	EP269-EP281	0	Site clearance survey
10/21/2011	EP269-EP281	0	Monitoring construction activity
10/21/2011	EP269-EP270	0	Site clearance survey
10/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/21/2011	EP274-EP278	0	Site clearance survey
10/21/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP269-EP273	0	Site clearance survey
10/21/2011	EP269-EP273	0	Monitoring construction activity
10/20/2011	EP269-EP281	0	Site clearance survey
10/20/2011	EP269	0	Site clearance survey
10/20/2011	EP269	0	Monitoring construction activity
10/20/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/20/2011	EP274-EP278	0	Site clearance survey
10/20/2011	EP274-EP278	0	Monitoring construction activity
10/20/2011	EP269-EP273	0	Site clearance survey
10/20/2011	EP269-EP273	0	Monitoring construction activity
10/20/2011	EP263B-EP267	0	Site clearance survey
10/20/2011	EP300-EP312	0	Site clearance survey
10/20/2011	EP300-EP312	0	Monitoring construction activity
10/19/2011	EP290-EP312	0	Site clearance survey
10/19/2011	EP290-EP312	0	Monitoring construction activity
10/19/2011	EP269-EP281	0	Site clearance survey
10/19/2011	EP300-EP312	0	Site clearance survey
10/19/2011	EP300-EP312	0	Monitoring construction activity
10/19/2011	EP274-EP278	0	Site clearance survey
10/19/2011	EP274-EP278	0	Monitoring construction activity
10/19/2011	EP269-EP273	0	Site clearance survey
10/19/2011	EP269-EP273	0	Monitoring construction activity
10/19/2011	EP263B-EP267	0	Site clearance survey
10/18/2011	Slay Property	0	Monitoring construction activity
10/18/2011	EP269-EP270	0	Site clearance survey
10/18/2011	EP269-EP270	0	Monitoring construction activity
10/18/2011	EP269-EP281	0	Site clearance survey
10/18/2011	EP269-EP270	0	Site clearance survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
10/18/2011	EP274-EP278	0	Site clearance survey
10/18/2011	EP274-EP278	0	Monitoring construction activity
10/18/2011	EP269-EP273	0	Site clearance survey
10/18/2011	EP269-EP273	0	Monitoring construction activity
10/18/2011	EP263B-EP267	0	Site clearance survey
10/17/2011	Slay Property	0	Site clearance survey
10/17/2011	EP312 & EP314	0	Monitoring construction activity
10/17/2011	EP306-EP312	0	Site clearance survey
10/17/2011	EP306-EP312	0	Afternoon perimeter survey
10/17/2011	EP305	0	Monitoring construction activity
10/17/2011	EP300-EP363	0	Monitoring construction activity
10/17/2011	EP300-EP306	0	Site clearance survey
10/17/2011	EP300-EP306	0	Monitoring construction activity
10/17/2011	EP270-2	0	Monitoring construction activity
10/17/2011	EP269-EP270	0	Site clearance survey
10/17/2011	EP269-EP270	0	Monitoring construction activity
10/17/2011	EP269-EP281	0	Site clearance survey
10/17/2011	EP269-EP270	0	Site clearance survey
10/17/2011	EP267-2	0	Monitoring construction activity
10/17/2011	EP261-2	0	Monitoring construction activity
10/17/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/17/2011	EP274-EP278	0	Site clearance survey
10/17/2011	EP274-EP278	0	Monitoring construction activity
10/17/2011	EP269-EP273	0	Site clearance survey
10/17/2011	EP269-EP273	0	Monitoring construction activity
10/17/2011	EP263B-EP267	0	Site clearance survey
10/16/2011	EP306-EP312	0	Site clearance survey
10/16/2011	EP306-EP312	0	Afternoon perimeter survey
10/16/2011	EP300-EP306	0	Site clearance survey
10/16/2011	EP300-EP306	0	Monitoring construction activity
10/16/2011	EP271-2	0	Monitoring construction activity
10/16/2011	EP270-2	0	Monitoring construction activity
10/16/2011	EP269-EP270	0	Site clearance survey
10/16/2011	EP256-EP281	0	Site clearance survey
10/16/2011	EP305	0	Monitoring construction activity

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
10/16/2011	EP274-EP278	0	Site clearance survey
10/16/2011	EP274-EP278	0	Monitoring construction activity
10/16/2011	EP269-EP273	0	Site clearance survey
10/16/2011	EP269-EP273	0	Monitoring construction activity
10/16/2011	EP263B-EP267	0	Site clearance survey
10/16/2011	EP256-EP263A-2, AER & FROMM CY	0	Site clearance survey
10/16/2011	EP256-EP263A-2, AER & FROMM CY	0	Monitoring construction activity
10/15/2011	Slay Property	0	Site clearance survey
10/15/2011	Slay Property	0	Monitoring construction activities
10/15/2011	EP306-EP312	0	Site clearance survey
10/15/2011	EP306-EP312	0	Afternoon perimeter survey
10/15/2011	EP305	0	Monitoring construction activities
10/15/2011	EP300-EP306	0	Site clearance survey
10/15/2011	EP300-EP306	0	Monitoring construction activities
10/15/2011	EP269-1 AND EP273-1	0	Monitoring construction activities
10/15/2011	EP269-EP281	0	Morning perimeter survey
10/15/2011	EP261-2	0	Monitoring construction activities
10/15/2011	EP274-EP278	0	Site clearance survey
10/15/2011	EP274-EP278	0	Monitoring construction activities
10/15/2011	EP263B-EP267	0	Site clearance survey
10/14/2011	Slay Property	0	Site clearance survey
10/14/2011	Slay Property	0	Monitoring construction activities
10/14/2011	EP310	0	Monitoring construction activities
10/14/2011	EP305	0	Monitoring construction activities
10/14/2011	EP300-EP306	0	Site clearance survey
10/14/2011	EP300-EP306	0	Monitoring construction activities
10/14/2011	EP291-EP301	0	Monitoring construction activities
10/14/2011	EP269 through EP281	0	Site clearance survey
10/14/2011	EP269-EP270	0	Site clearance survey
10/14/2011	EP263B-2	0	Monitoring construction activities
10/14/2011	EP256-EP263A	0	Site clearance survey
10/14/2011	EP256-EP263A	0	Monitoring construction activities
10/14/2011	EP274-EP278	0	Site clearance survey
10/14/2011	EP274-EP278	0	Monitoring construction activities
10/14/2011	EP269-EP273	0	Site clearance survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
10/14/2011	EP269-EP273	0	Monitoring construction activities
10/14/2011	EP263B-EP267	0	Site clearance survey
10/14/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/14/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/13/2011	Slay Property	0	Site clearance survey
10/13/2011	Slay Property	0	Monitoring construction activities
10/13/2011	EP310	0	Monitoring construction activities
10/13/2011	EP306-EP312	0	Site clearance survey
10/13/2011	EP306-EP312	0	Afternoon perimeter survey
10/13/2011	EP293	0	Monitoring construction activities
10/13/2011	EP291-EP301	0	Monitoring construction activities
10/13/2011	EP275-1	0	Monitoring construction activities
10/13/2011	EP269-EP270	0	Site clearance survey
10/13/2011	EP269-EP281	0	Site clearance survey
10/13/2011	EP269-EP270	0	Site clearance survey
10/13/2011	EP266-2	0	Monitoring construction activities
10/13/2011	EP274-EP278	0	Site clearance survey
10/13/2011	EP274-EP278	0	Monitoring construction activities
10/13/2011	EP269-EP273	0	Site clearance survey
10/13/2011	EP269-EP273	0	Monitoring construction activities
10/13/2011	EP263B-EP267	0	Site clearance survey
10/13/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/13/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/12/2011	Slay Property	0	Site clearance survey
10/12/2011	Slay Property	0	Monitoring construction activities
10/12/2011	EP306-EP312	0	Site clearance survey
10/12/2011	EP291-EP301	0	Monitoring construction activities
10/12/2011	EP269-EP270	0	Site clearance survey
10/12/2011	EP269-EP281	0	Site clearance survey
10/12/2011	EP269-EP281	0	Monitoring construction activities
10/12/2011	EP269-EP270	0	Site clearance survey
10/12/2011	EP311	0	Monitoring construction activities
10/12/2011	EP274-EP278	0	Site clearance survey
10/12/2011	EP274-EP278	0	Monitoring construction activities
10/12/2011	EP269-EP273	0	Site clearance survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
10/12/2011	EP269-EP273	0	Monitoring construction activities
10/12/2011	EP263B-EP267	0	Site clearance survey
10/12/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/12/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/11/2011	Slay Property	0	Site clearance survey
10/11/2011	Slay Property	0	Monitoring construction activities
10/11/2011	EP311	0	Monitoring construction activities
10/11/2011	EP306-EP312	0	Site clearance survey
10/11/2011	EP306-EP312	0	Afternoon perimeter survey
10/11/2011	EP300-EP306	0	Site clearance survey
10/11/2011	EP291-EP301	0	Monitoring construction activities
10/11/2011	EP269-EP273	0	Site clearance survey
10/11/2011	EP269-EP273	0	Monitoring construction activities
10/11/2011	EP269-EP270	0	Site clearance survey
10/11/2011	EP269-EP270	0	Monitoring construction activities
10/11/2011	EP274-EP278	0	Site clearance survey
10/11/2011	EP274-EP278	0	Monitoring construction activities
10/11/2011	EP263B-EP267	0	Site clearance survey
10/11/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/11/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/10/2011	Slay Property	0	Site clearance survey
10/10/2011	Slay Property	0	Monitoring construction activities
10/10/2011	EP306-EP312	0	Site clearance survey
10/10/2011	EP306-EP312	0	Afternoon perimeter survey
10/10/2011	EP305	0	Monitoring construction activities
10/10/2011	EP300-EP306	0	Site clearance survey
10/10/2011	EP300-EP306	0	Monitoring construction activities
10/10/2011	EP300-EP306	0	Site clearance survey
10/10/2011	EP291-EP301	0	Monitoring construction activities
10/10/2011	EP269-EP281	9	Sheep were seen entering I-8 Island during Site Clearance survey
10/10/2011	EP269-EP273	0	Site clearance survey
10/10/2011	EP269-EP273	0	Monitoring construction activities
10/10/2011	EP259-3	0	Monitoring construction activities
10/10/2011	EP274-EP278	0	Site clearance survey
10/10/2011	EP274-EP278	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
10/10/2011	EP263B-EP267	0	Site clearance survey
10/10/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/10/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/9/2011	EP306-EP312	0	Site clearance survey
10/9/2011	EP306-EP312	0	Monitoring construction activities
10/9/2011	EP300-EP306	0	Site clearance survey
10/9/2011	EP300-EP306	0	Monitoring construction activities
10/9/2011	EP300-EP306	0	Site clearance survey
10/9/2011	EP300-EP306	0	Monitoring construction activities
10/9/2011	EP269-EP273	0	Site clearance survey
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP269-EP270	0	Monitoring construction activities
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP256-3	0	Monitoring construction activities
10/9/2011	EP274-EP278	0	Site clearance survey
10/9/2011	EP274-EP278	0	Monitoring construction activities
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP269-EP270	0	Monitoring construction activities
10/9/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/9/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/8/2011	EP300-EP306	0	Site clearance survey
10/8/2011	EP300-EP306	0	Monitoring construction activity
10/8/2011	EP300-EP306	0	Site clearance survey
10/8/2011	EP300-EP306	0	Morning perimeter survey
10/8/2011	EP291-EP301	0	Monitoring construction activity
10/8/2011	EP278-1	0	Monitoring construction activity
10/8/2011	EP269-EP273	0	Site clearance survey
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP269-EP270	0	Monitoring construction activity
10/8/2011	EP269/EP270 Pullsite	0	Monitoring construction activity
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP259-3	0	Monitoring construction activity
10/8/2011	EP274-EP278	0	Site clearance survey
10/8/2011	EP274-EP278	0	Monitoring construction activity
10/8/2011	EP269-EP270	0	Site clearance survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
10/8/2011	EP269-EP270	0	Monitoring construction activity
10/8/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/8/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/7/2011	Slay Property	0	Site clearance survey
10/7/2011	EP306-EP312	0	Site clearance survey
10/7/2011	EP306-EP312	0	Morning perimeter survey
10/7/2011	EP300-EP306	0	Site clearance survey
10/7/2011	EP300-EP306	0	Monitoring construction activity
10/7/2011	EP300-EP306	0	Site clearance survey
10/7/2011	EP300-EP306	0	Morning perimeter survey
10/7/2011	EP291-EP301	0	Site clearance survey
10/7/2011	EP269-EP273	0	Site clearance survey
10/7/2011	EP269-EP270	0	Site clearance survey
10/7/2011	EP269-EP270	0	Monitoring construction activity
10/7/2011	EP269-EP270	0	Site clearance survey
10/7/2011	EP259-3	0	Monitoring construction activity
10/7/2011	EP274-EP278	0	Site clearance survey
10/7/2011	EP274-EP278	0	Monitoring construction activity
10/7/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/7/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/6/2011	Slay Property	0	Site clearance survey
10/6/2011	Slay Property	0	Monitoring construction activity
10/6/2011	EP306-EP312	0	Site clearance survey
10/6/2011	EP306-EP312	0	Monitoring construction activity
10/6/2011	EP291-EP301	0	Site clearance survey
10/6/2011	EP269-EP273	0	Site clearance survey
10/6/2011	EP269-EP270	0	Site clearance survey
10/6/2011	EP269-EP270	0	Monitoring construction activity
10/6/2011	EP269-EP281	0	Site clearance survey
10/6/2011	EP269-EP270	0	Site clearance survey
10/6/2011	EP263B-EP267	0	Site clearance survey
10/6/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/6/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/5/2011	Slay Property	0	Site clearance survey
10/5/2011	Slay Property	0	Monitoring construction activity

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
10/5/2011	EP303-2	0	Monitoring construction activity
10/5/2011	EP291-EP301	0	Site clearance survey
10/5/2011	EP269-EP273	0	Site clearance survey
10/5/2011	EP269-EP270	0	Site clearance survey
10/5/2011	EP269-EP270	0	Monitoring construction activity
10/5/2011	EP274-EP278	0	Site clearance survey
10/5/2011	EP274-EP278	0	Monitoring construction activity
10/5/2011	EP269-EP281	0	Site clearance survey
10/5/2011	EP269-EP270	0	Site clearance survey
10/5/2011	EP263B-EP267	0	Site clearance survey
10/5/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/5/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/4/2011	Slay Property	0	Site clearance survey
10/4/2011	Slay Property	0	Monitoring construction activity
10/4/2011	EP300-EP306	0	Site clearance survey
10/4/2011	EP300-EP306	0	Monitoring construction activity
10/4/2011	EP269-EP273	0	Site clearance survey
10/4/2011	EP269-EP270	0	Site clearance survey
10/4/2011	EP269-EP270	0	Monitoring construction activity
10/4/2011	EP256-EP263A	0	Site clearance survey
10/4/2011	EP274-EP278	0	Site clearance survey
10/4/2011	EP274-EP278	0	Monitoring construction activity
10/4/2011	EP263B-EP267	0	Site clearance survey
10/3/2011	Slay Property	0	Site clearance survey
10/3/2011	Slay Property	0	Monitoring construction activity
10/3/2011	EP300-EP306	0	Site clearance survey
10/3/2011	EP300-EP306	0	Monitoring construction activity
10/3/2011	EP300-EP306	0	Site clearance survey
10/3/2011	EP300-EP306	0	Morning perimeter survey
10/3/2011	EP291-EP341	0	Site clearance survey
10/3/2011	EP279-EP294	0	Site clearance survey
10/3/2011	EP269-EP273	0	Site clearance survey
10/3/2011	EP269-EP273	0	Monitoring construction activity
10/3/2011	EP263B-EP267	0	Site clearance survey
10/3/2011	EP263B-EP267	0	Monitoring construction activity

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
10/3/2011	EP256-EP263A	0	Site clearance survey
10/3/2011	EP274-EP278	0	Site clearance survey
10/3/2011	EP274-EP278	0	Monitoring construction activity
10/3/2011	EP263B-EP267	0	Site clearance survey
10/2/2011	EP300-EP306	0	Site clearance survey
10/2/2011	EP300-EP306	0	Monitoring construction activity
10/2/2011	EP269-EP281	0	Afternoon perimeter survey
10/2/2011	EP269-EP273	0	Afternoon perimeter survey
10/1/2011	EP300-EP306	0	Site clearance survey
10/1/2011	EP300-EP306	0	Monitoring construction activities
10/1/2011	EP300-EP306	0	Site clearance survey
10/1/2011	EP300-EP306	0	Morning perimeter survey
10/1/2011	EP269-EP273 and EP256-EP261	0	Site clearance survey
10/1/2011	EP269-EP273	0	Site clearance survey
10/1/2011	EP269-EP270	0	Site clearance survey
10/1/2011	EP274-EP278	0	Site clearance survey
10/1/2011	EP274-EP278	0	Monitoring construction activities
9/30/2011	Slay Property	0	Site clearance survey
9/30/2011	Slay Property	0	Monitoring construction activities
9/30/2011	EP300-EP312	0	Site clearance survey
9/30/2011	EP300-EP312	0	Monitoring construction activities
9/30/2011	EP300-EP306	0	Site clearance survey
9/30/2011	EP300-EP306	0	Monitoring construction activities
9/30/2011	EP291-EP348	0	Monitoring construction activities
9/30/2011	EP290-EP294, EP300-EP312	0	Site clearance survey
9/30/2011	EP290-EP294, EP300-EP312	0	Monitoring construction activities
9/30/2011	EP269-EP273	0	Site clearance survey
9/30/2011	EP269-EP273	0	Monitoring construction activities
9/30/2011	EP269-EP281	0	Site clearance survey
9/30/2011	EP279-EP294	0	Site clearance survey
9/30/2011	EP274-EP278	0	Site clearance survey
9/30/2011	EP274-EP278	0	Monitoring construction activities
9/30/2011	EP263-B-EP267	0	Site clearance survey
9/30/2011	EP256-EP263A, AER, Fromm CY	0	Site clearance survey
9/30/2011	EP256-EP263A, AER, Fromm CY	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
9/29/2011	Slay Property	0	Site clearance survey
9/29/2011	Slay Property	0	Monitoring construction activities
9/29/2011	EP300-EP312	0	Site clearance survey
9/29/2011	EP300-EP306	0	Site clearance survey
9/29/2011	EP300-EP306	0	Monitoring construction activities
9/29/2011	EP290-EP294, EP300-EP312	0	Site clearance survey
9/29/2011	EP290-EP294, EP300-EP312	0	Monitoring construction activities
9/29/2011	EP269-EP273	0	Site clearance survey
9/29/2011	EP269-EP273	0	Monitoring construction activities
9/29/2011	EP279-EP294	0	Site clearance survey
9/29/2011	EP274-EP278	0	Site clearance survey
9/29/2011	EP274-EP278	0	Monitoring construction activities
9/29/2011	EP263B-EP267	0	Site clearance survey
9/28/2011	Slay Property	0	Site clearance survey
9/28/2011	Slay Property	0	Monitoring construction activities
9/28/2011	EP330-EP291	0	Site clearance survey
9/28/2011	EP300-EP306	0	Site clearance survey
9/28/2011	EP300-EP306	0	Monitoring construction activities
9/28/2011	EP290-EP294	0	Site clearance survey
9/28/2011	EP290-EP294	0	Monitoring construction activities
9/28/2011	EP269-EP273	0	Site clearance survey
9/28/2011	EP269-EP273	0	Monitoring construction activities
9/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/28/2011	EP279-EP294	0	Site clearance survey
9/28/2011	EP279-EP294	0	Monitoring construction activities
9/28/2011	EP274-EP278	0	Site clearance survey
9/28/2011	EP274-EP278	0	Monitoring construction activities
9/28/2011	EP263B-EP267	0	Site clearance survey
9/27/2011	Slay Property	0	Site clearance survey
9/27/2011	Slay Property	0	Monitoring construction activities
9/27/2011	EP339-EP291	0	Site clearance survey
9/27/2011	EP309	0	Monitoring construction activities
9/27/2011	EP300-EP312	0	Site clearance survey
9/27/2011	EP300-EP312	0	Monitoring construction activities
9/27/2011	EP300-EP306	0	Site clearance survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
9/27/2011	EP278-1	0	Monitoring construction activities
9/27/2011	EP269-EP273	0	Site clearance survey
9/27/2011	EP269-EP273	0	Monitoring construction activities
9/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/27/2011	EP279-EP294	0	Site clearance survey
9/27/2011	EP279-EP294	0	Monitoring construction activities
9/27/2011	EP274-EP278	0	Site clearance survey
9/27/2011	EP274-EP278	0	Monitoring construction activities
9/27/2011	EP263B-EP267	0	Site clearance survey
9/27/2011	AER CY	0	Monitoring construction activities
9/26/2011	EP300-EP306	0	Site clearance survey
9/26/2011	EP300-EP306	0	Monitoring construction activities
9/26/2011	EP300-EP306	0	Site clearance survey
9/26/2011	EP300-EP312	0	Site clearance survey
9/26/2011	EP300-EP312	0	Monitoring construction activities
9/26/2011	EP291-EP301	0	Monitoring construction activities
9/26/2011	EP278-1, EP270-2	0	Monitoring construction activities
9/26/2011	EP274-EP278	0	Site clearance survey
9/26/2011	EP274-EP278	0	Monitoring construction activities
9/26/2011	EP269-EP273	0	Site clearance survey
9/26/2011	EP269-EP273	0	Monitoring construction activities
9/26/2011	EP269-EP270	0	Morning perimeter survey
9/26/2011	EP269-EP270	0	Monitoring construction activities
9/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/26/2011	EP279-EP294	0	Site clearance survey
9/26/2011	EP279-EP294	0	Monitoring construction activities
9/26/2011	EP269-EP271, EP256-EP263, AER & Fromm CY	0	Site clearance survey
9/26/2011	EP269-EP271, EP256-EP263, AER & Fromm CY	0	Monitoring construction activities
9/26/2011	EP263B-EP267	0	Site clearance survey
9/26/2011	CP88	0	Site clearance survey
9/26/2011	CP88	0	Monitoring construction activities
9/25/2011	EP300-EP306	0	Site clearance survey
9/25/2011	EP300-EP306	0	Monitoring construction activities
9/25/2011	EP300-EP306	0	Morning perimeter survey
9/25/2011	EP278	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
9/25/2011	EP274-EP278	0	Site clearance survey
9/25/2011	EP274-EP278	0	Monitoring construction activities
9/25/2011	EP271-2	0	Monitoring construction activities
9/25/2011	EP269-EP270	0	Morning perimeter survey
9/25/2011	EP269-EP270	0	Monitoring construction activities
9/25/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/25/2011	EP279-EP294	0	Site clearance survey
9/25/2011	EP279-EP294	0	Monitoring construction activities
9/25/2011	EP269-EP273	0	Site clearance survey
9/25/2011	EP269-EP273	0	Monitoring construction activities
9/25/2011	EP263B-EP267	0	Site clearance survey
9/24/2011	EP300-EP306	0	Site clearance survey
9/24/2011	EP300-EP306	0	Monitoring construction activities
9/24/2011	EP300-EP306	0	Site clearance survey
9/24/2011	EP300-EP306	0	Monitoring construction activities
9/24/2011	EP291/EP292 Pullsite	0	Monitoring construction activities
9/24/2011	EP274-EP278	0	Site clearance survey
9/24/2011	EP274-EP278	0	Monitoring construction activities
9/24/2011	EP274	0	Monitoring construction activities
9/24/2011	EP269-EP270	0	Site clearance survey
9/24/2011	EP269-EP270	0	Monitoring construction activities
9/24/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/24/2011	EP279-EP294	0	Site clearance survey
9/24/2011	EP279-EP294	0	Monitoring construction activities
9/24/2011	EP263B-EP267	0	Site clearance survey
9/23/2011	EP300-EP306	0	Site clearance survey
9/23/2011	EP300-EP306	0	Monitoring construction activities
9/23/2011	EP300-EP312	0	Site clearance survey
9/23/2011	EP300-EP312	0	Monitoring construction activities
9/23/2011	EP274-1	0	Monitoring construction activities
9/23/2011	EP269-EP271	0	Site clearance survey
9/23/2011	EP269-EP271	0	Monitoring construction activities
9/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/23/2011	EP279-EP294	0	Site clearance survey
9/23/2011	EP279-EP294	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
9/23/2011	EP278-1	0	Monitoring construction activities
9/23/2011	EP263B-EP267	0	Site clearance survey
9/22/2011	EP300-EP312	0	Site clearance survey
9/22/2011	EP300-EP312	0	Monitoring construction activities
9/22/2011	EP300-EP306	0	Site clearance survey
9/22/2011	EP300-EP306	0	Monitoring construction activities
9/22/2011	EP274-1	0	Monitoring construction activities
9/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/22/2011	EP279-EP294	0	Site clearance survey
9/22/2011	EP278-1	0	Monitoring construction activities
9/22/2011	EP274-EP278	0	Site clearance survey
9/22/2011	EP274-EP278	0	Monitoring construction activities
9/22/2011	EP263B-EP267	0	Site clearance survey
9/21/2011	EP300-EP306	0	Site clearance survey
9/21/2011	EP278-1	0	Monitoring construction activities
9/21/2011	EP274-1	0	Monitoring construction activities
9/21/2011	EP269-EP271, EP300-EP312	0	Site clearance survey
9/21/2011	EP269-EP271, EP300-EP312	0	Monitoring construction activities
9/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/21/2011	EP279-EP294	0	Site clearance survey
9/21/2011	EP279-EP294	0	Monitoring construction activities
9/21/2011	EP274-EP278	0	Site clearance survey
9/21/2011	EP274-EP278	0	Monitoring construction activities
9/21/2011	EP269-EP281	0	Site clearance survey
9/21/2011	EP269-EP281	0	Monitoring construction activities
9/21/2011	EP263B-EP267	0	Site clearance survey
9/20/2011	EP300-EP306	0	Site clearance survey
9/20/2011	EP278-1	0	Monitoring construction activities
9/20/2011	EP269-EP273	0	Site clearance survey
9/20/2011	EP269-EP273	0	Monitoring construction activities
9/20/2011	EP269-EP271	0	Site clearance survey
9/20/2011	EP269-EP271	0	Monitoring construction activities
9/20/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/20/2011	EP279-EP294	0	Site clearance survey
9/20/2011	EP279-EP294	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
9/20/2011	EP274-EP278	0	Site clearance survey
9/20/2011	EP274-EP278	0	Monitoring construction activities
9/20/2011	EP269-EP281	0	Site clearance survey
9/20/2011	EP269-EP281	0	Monitoring construction activities
9/20/2011	EP263B-EP267	0	Site clearance survey
9/19/2011	EP269-EP273	0	Site clearance survey
9/19/2011	EP269-EP273	0	Monitoring construction activities
9/19/2011	EP269-EP271	0	Site clearance survey
9/19/2011	EP269-EP271	0	Monitoring construction activities
9/19/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/19/2011	EP279-EP294	0	Site clearance survey
9/19/2011	EP279-EP294	0	Monitoring construction activities
9/19/2011	EP274-EP278	0	Site clearance survey
9/19/2011	EP274-EP278	0	Monitoring construction activities
9/19/2011	EP269-EP281	0	Site clearance survey
9/19/2011	EP269-EP281	0	Monitoring construction activities
9/19/2011	EP263B-EP267	0	Site clearance survey
9/18/2011	EP300-EP306	0	Site clearance survey
9/18/2011	EP300-EP312	0	Site clearance survey
9/18/2011	EP300-EP312	0	Monitoring construction activities
9/18/2011	EP269-EP273	0	Site clearance survey
9/18/2011	EP269-EP273	0	Monitoring construction activities
9/18/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/18/2011	EP279-EP294	0	Site clearance survey
9/18/2011	EP279-EP294	0	Monitoring construction activities
9/18/2011	EP274-EP278	0	Site clearance survey
9/18/2011	EP274-EP278	0	Monitoring construction activities
9/18/2011	EP269-EP281	0	Site clearance survey
9/18/2011	I8 Island	9	Afternoon perimeter survey
9/17/2011	EP300-EP306	0	Site clearance survey
9/17/2011	EP300-EP312	0	Site clearance survey
9/17/2011	EP300-EP312	0	Monitoring construction activities
9/17/2011	EP269-EP273	0	Site clearance survey
9/17/2011	EP269-EP273	0	Monitoring construction activities
9/17/2011	EP274-EP278	0	Site clearance survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
9/17/2011	EP274-EP278	0	Monitoring construction activities
9/17/2011	EP269-EP281	0	Site clearance survey
9/17/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/17/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/16/2011	EP300-EP312	0	Site clearance survey
9/16/2011	EP300-EP312	0	Monitoring construction activities
9/16/2011	EP300-EP306	0	Site clearance survey
9/16/2011	EP269-EP273	0	Site clearance survey
9/16/2011	EP269-EP273	0	Monitoring construction activities
9/16/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/16/2011	EP274-EP278	0	Site clearance survey
9/16/2011	EP274-EP278	0	Monitoring construction activities
9/16/2011	EP269-EP281	0	Site clearance survey
9/16/2011	EP263B-EP267	0	Site clearance survey
9/16/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/16/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/15/2011	EP300-EP312	0	Site clearance survey
9/15/2011	EP300-EP312	0	Monitoring construction activities
9/15/2011	EP300-EP306	0	Site clearance survey
9/15/2011	EP300-EP306	0	Monitoring construction activities
9/15/2011	EP269-EP273	0	Site clearance survey
9/15/2011	EP269-EP273	0	Monitoring construction activities
9/15/2011	EP256-EP263A, AER	0	Monitoring construction activities
9/15/2011	EP274-EP278	0	Site clearance survey
9/15/2011	EP274-EP278	0	Monitoring construction activities
9/15/2011	EP269-EP281	0	Site clearance survey
9/15/2011	EP269-EP281	0	Monitoring construction activities
9/15/2011	EP263B-EP267	0	Site clearance survey
9/14/2011	EP310-3	0	Monitoring construction activities
9/14/2011	EP300-EP312	0	Site clearance survey
9/14/2011	EP300-EP312	0	Monitoring construction activities
9/14/2011	EP300-EP306	0	Morning perimeter survey
9/14/2011	EP274-1	0	Monitoring construction activities
9/14/2011	EP269-EP273	0	Site clearance survey
9/14/2011	EP269-EP273	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
9/14/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/14/2011	EP274-EP278	0	Site clearance survey
9/14/2011	EP274-EP278	0	Monitoring construction activities
9/14/2011	EP269-EP281	0	Site clearance survey
9/14/2011	EP269-EP281	0	Monitoring construction activities
9/14/2011	EP263B-EP267	0	Site clearance survey
9/13/2011	EP300-EP312	0	Site clearance survey
9/13/2011	EP300-EP312	0	Monitoring construction activities
9/13/2011	EP300-EP306	0	Morning perimeter survey
9/13/2011	EP269-EP273	0	Site clearance survey
9/13/2011	EP269-EP273	0	Monitoring construction activities
9/13/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/13/2011	EP274-EP278	0	Site clearance survey
9/13/2011	EP274-EP278	0	Monitoring construction activities
9/13/2011	EP274-EP278	0	Monitoring construction activities
9/13/2011	EP274	0	Monitoring construction activities
9/13/2011	EP269-EP281	0	Site clearance survey
9/13/2011	EP263B-EP267	0	Site clearance survey
9/12/2011	Mountain Springs Grade Road	15	Morning perimeter survey
9/12/2011	EP305-3, EP310	0	Monitoring construction activities
9/12/2011	EP300-EP312	0	Site clearance survey
9/12/2011	EP300-EP312	0	Monitoring construction activities
9/12/2011	EP300-EP306	0	Site clearance survey
9/12/2011	EP300-EP306	0	Monitoring construction activities
9/12/2011	EP269-EP273	0	Site clearance survey
9/12/2011	EP269-EP273	0	Monitoring construction activities
9/12/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/12/2011	EP274-EP278	0	Site clearance survey
9/12/2011	EP274-EP278	0	Monitoring construction activities
9/12/2011	EP274-EP278	0	Monitoring construction activities
9/12/2011	EP274	0	Monitoring construction activities
9/12/2011	EP269-EP281	0	Monitoring construction activities
9/12/2011	EP263B-EP267	0	Site clearance survey
9/11/2011	EP300-EP312	0	Site clearance survey
9/11/2011	EP300-EP312	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
9/11/2011	EP300-EP306	0	Site clearance survey
9/11/2011	EP300-EP306	0	Monitoring construction activities
9/11/2011	EP271-2	0	Monitoring construction activities
9/11/2011	EP269-EP271	0	Site clearance survey
9/11/2011	EP269-EP271	0	Monitoring construction activities
9/11/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/11/2011	EP274-EP278	0	Site clearance survey
9/11/2011	EP274-EP278	0	Monitoring construction activities
9/11/2011	EP269-EP273	0	Site clearance survey
9/11/2011	EP269-EP273	0	Monitoring construction activities
9/11/2011	EP263B-EP267	0	Site clearance survey
9/11/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/11/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/10/2011	EP300-EP312	0	Site clearance survey
9/10/2011	EP300-EP312	0	Monitoring construction activities
9/10/2011	EP300-EP306	0	Site clearance survey
9/10/2011	EP300-EP306	0	Monitoring construction activities
9/10/2011	EP269-EP271	0	Site clearance survey
9/10/2011	EP269-EP271	0	Monitoring construction activities
9/10/2011	EP274-EP278	0	Site clearance survey
9/10/2011	EP274-EP278	0	Monitoring construction activities
9/10/2011	EP269-EP273	0	Morning perimeter survey
9/10/2011	EP269-EP273	0	Monitoring construction activities
9/10/2011	EP269-EP273	0	Evening perimeter survey
9/9/2011	EP300-EP312	0	Site clearance survey
9/9/2011	EP300-EP312	0	Monitoring construction activities
9/9/2011	EP300-EP306	0	Site clearance survey
9/9/2011	EP300-EP306	0	Monitoring construction activities
9/9/2011	EP271-2	0	Monitoring construction activities
9/9/2011	EP269-EP271	0	Site clearance survey
9/9/2011	EP269-EP271	0	Monitoring construction activities
9/9/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/9/2011	EP256-EP263A, AER and Fromm yards	0	Site clearance survey
9/9/2011	EP256-EP263A, AER and Fromm yards	0	Monitoring construction activities
9/9/2011	EP274-EP278	0	Site clearance survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
9/9/2011	EP274-EP278	0	Monitoring construction activities
9/9/2011	EP269-EP273	0	Morning perimeter survey
9/9/2011	EP269-EP273	0	Monitoring construction activities
9/9/2011	EP269-EP273	0	Evening perimeter survey
9/8/2011	EP300-EP312	0	Site clearance survey
9/8/2011	EP300-EP312	0	Monitoring construction activities
9/8/2011	EP271-2	0	Monitoring construction activities
9/8/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/8/2011	EP279-EP294	0	Site clearance survey
9/8/2011	EP279-EP294	0	Monitoring construction activities
9/8/2011	EP274-EP278	0	Site clearance survey
9/8/2011	EP274-EP278	0	Monitoring construction activities
9/8/2011	EP263B-EP267	0	Site clearance survey
9/7/2011	EP306-1	0	Monitoring construction activities
9/7/2011	EP300-EP312	0	Site clearance survey
9/7/2011	EP300-EP312	0	Monitoring construction activities
9/7/2011	EP300-EP306	0	Site clearance survey
9/7/2011	EP300-EP306	0	Monitoring construction activities
9/7/2011	EP273	0	Monitoring construction activities
9/7/2011	EP269-EP273	0	Site clearance survey
9/7/2011	EP269-EP273	0	Monitoring construction activities
9/7/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/7/2011	EP278-EP294	0	Morning perimeter survey
9/7/2011	EP278-EP294	0	Monitoring construction activities
9/7/2011	EP278-EP294	0	Evening perimeter survey
9/7/2011	EP274-EP278	0	Site clearance survey
9/7/2011	EP274-EP278	0	Monitoring construction activities
9/7/2011	EP263B-EP267	0	Site clearance survey
9/6/2011	EP300-EP312	0	Site clearance survey
9/6/2011	EP300-EP312	0	Monitoring construction activities
9/6/2011	EP273	0	Monitoring construction activities
9/6/2011	EP269-EP273	0	Site clearance survey
9/6/2011	EP269-EP273	0	Monitoring construction activities
9/6/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/6/2011	EP278-EP294	0	Morning perimeter survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
9/6/2011	EP278-EP294	0	Monitoring construction activities
9/6/2011	EP278-EP294	0	Evening perimeter survey
9/6/2011	EP274-EP278	0	Site clearance survey
9/6/2011	EP274-EP278	0	Monitoring construction activities
9/6/2011	EP263B-EP267	0	Site clearance survey
9/5/2011	EP300-EP312	0	Site clearance survey
9/5/2011	EP269-EP273	0	Site clearance survey
9/5/2011	EP269-EP273	0	Monitoring construction activities
9/5/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/5/2011	EP274-EP294	0	Site clearance survey
9/5/2011	EP263B-EP267	0	Site clearance survey
9/4/2011	EP300-EP312	0	Site clearance survey
9/4/2011	EP300-EP312	0	Monitoring construction activities
9/4/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
9/4/2011	EP269-EP281	0	Site clearance survey
9/4/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/4/2011	EP256-EP263A, AER and Fromm yards	0	Site clearance survey
9/4/2011	EP256-EP263A, AER and Fromm yards	0	Monitoring construction activities
9/4/2011	EP279-EP294	0	Site clearance survey
9/4/2011	EP279-EP294	0	Monitoring construction activities
9/4/2011	EP274-EP278	0	Site clearance survey
9/4/2011	EP274-EP278	0	Monitoring construction activities
9/4/2011	EP270	0	Site clearance survey
9/4/2011	EP270	0	Monitoring construction activities
9/3/2011	EP300-EP312	0	Monitoring Construction Activities
9/3/2011	EP300-EP312	0	Site clearance survey
9/3/2011	EP300-EP306	0	Monitoring Construction Activities
9/3/2011	EP300-EP306	0	Site clearance survey
9/3/2011	EP271	0	Monitoring Construction Activities
9/3/2011	EP269-EP273	0	Monitoring Construction Activities
9/3/2011	EP269-EP273	0	Site clearance survey
9/3/2011	EP269-EP281	0	Monitoring Construction Activities
9/3/2011	EP256-EP263A, AER and Fromm Yards	0	Monitoring Construction Activities
9/3/2011	EP256-EP263A, AER and Fromm Yards	0	Site clearance survey
9/3/2011	EP278-EP294	0	Evening perimeter survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
9/3/2011	EP278-EP294	0	Monitoring Construction Activities
9/3/2011	EP278-EP294	0	Morning perimeter survey
9/3/2011	EP269-1 & EP269/EP270 Pull site	0	Monitoring Construction Activities
9/2/2011	I-8 Island	9	Evening perimeter survey 4:45pm - 5:08pm
9/2/2011	I-8 Island	12	Morning perimeter survey 8:35am
9/2/2011	EP300-EP312	0	Monitoring Construction Activities
9/2/2011	EP300-EP312	0	Site clearance survey
9/2/2011	EP272 & EP276	0	Monitoring Construction Activities
9/2/2011	EP269-EP273	0	Monitoring Construction Activities
9/2/2011	EP269-EP273	0	Site clearance survey
9/2/2011	EP256-EP263A, AER and Fromm Yards	0	Monitoring Construction Activities
9/2/2011	EP256-EP263A, AER and Fromm Yards	0	Site clearance survey
9/2/2011	EP278-EP294	0	Evening perimeter survey
9/2/2011	EP278-EP294	0	Monitoring Construction Activities
9/2/2011	EP278-EP294	0	Morning perimeter survey
9/2/2011	EP269-EP272	0	Monitoring Construction Activities
9/2/2011	EP269-EP272	0	Site clearance survey
9/2/2011	EP263B-EP267	0	Site clearance survey
9/1/2011	I-8 Island	12	Evening perimeter survey 4:45pm - 5:40pm
9/1/2011	I-8 Island	12	Morning perimeter survey 8:35am
9/1/2011	EP300-EP312	0	Monitoring Construction Activities
9/1/2011	EP300-EP312	0	Site clearance survey
9/1/2011	EP269-EP273	0	Monitoring Construction Activities
9/1/2011	EP269-EP273	0	Site clearance survey
9/1/2011	EP256-EP263A-2	0	Site clearance survey
9/1/2011	EP255	0	Monitoring Construction Activities
9/1/2011	EP300-EP306	0	Site clearance survey
9/1/2011	EP278-EP294	0	Evening perimeter survey
9/1/2011	EP278-EP294	0	Monitoring Construction Activities
9/1/2011	EP278-EP294	0	Morning perimeter survey
9/1/2011	EP269-EP272	0	Monitoring Construction Activities
9/1/2011	EP269-EP272	0	Site clearance survey
9/1/2011	EP263B-EP267	0	Site clearance survey
8/31/2011	I-8 Island	0	Site clearance survey
8/31/2011	EP308	0	Monitoring Construction Activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
8/31/2011	EP300-EP312	0	Monitoring Construction Activities
8/31/2011	EP300-EP312	0	Site clearance survey
8/31/2011	EP269-EP273	0	Monitoring Construction Activities
8/31/2011	EP269-EP273	0	Site clearance survey
8/31/2011	EP300-EP306	0	Site clearance survey
8/31/2011	EP278-EP294	0	Evening perimeter survey
8/31/2011	EP278-EP294	0	Monitoring Construction Activities
8/31/2011	EP278-EP294	0	Morning perimeter survey
8/31/2011	EP269-EP272	0	Monitoring Construction Activities
8/31/2011	EP263B-EP267	0	Site clearance survey
8/30/2011	I-8 Island	16	Evening perimeter survey 4:30pm
8/30/2011	I-8 Island	9	Morning perimeter survey 9:10am - 9:30am
8/30/2011	EP300-EP312	0	Monitoring Construction Activities
8/30/2011	EP300-EP312	0	Site clearance survey
8/30/2011	EP269-EP273	0	Monitoring Construction Activities
8/30/2011	EP269-EP273	0	Site clearance survey
8/30/2011	EP300-EP306	0	Site clearance survey
8/30/2011	EP278-EP294	0	Evening perimeter survey
8/30/2011	EP278-EP294	0	Monitoring Construction Activities
8/30/2011	EP278-EP294	0	Morning perimeter survey
8/30/2011	EP274-EP278	0	Monitoring Construction Activities
8/30/2011	EP274-EP278	0	Site clearance survey
8/30/2011	EP269-EP272	0	Monitoring Construction Activities
8/30/2011	EP269-EP272	0	Site clearance survey
8/30/2011	EP263B-EP267	0	Site clearance survey
8/29/2011	I-8 Island	4	Morning perimeter survey 8:55am
8/29/2011	I-8 Island	12	Evening perimeter survey 4:35pm to 5:00pm
8/29/2011	EP300-EP312	0	Monitoring Construction Activities
8/29/2011	EP300-EP312	0	Site clearance survey
8/29/2011	EP278-2	0	Monitoring Construction Activities
8/29/2011	EP269-EP273	0	Monitoring Construction Activities
8/29/2011	EP269-EP273	0	Site clearance survey
8/29/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/29/2011	EP300-EP306	0	Site clearance survey
8/29/2011	EP274-EP278	0	Monitoring Construction Activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
8/29/2011	EP274-EP278	0	Site clearance survey
8/29/2011	EP269-EP272	0	Monitoring Construction Activities
8/29/2011	EP269-EP272	0	Site clearance survey
8/29/2011	EP263B-EP267	0	Site clearance survey
8/28/2011	I-8 Island	15	Morning perimeter survey @9:22am
8/28/2011	EP305	0	Monitoring Construction Activities
8/28/2011	EP281	0	Monitoring Construction Activities
8/28/2011	EP273	0	Monitoring Construction Activities
8/28/2011	EP269-EP273	0	Monitoring Construction Activities
8/28/2011	EP269-EP273	0	Site clearance survey
8/28/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/28/2011	EP300-EP306	0	Morning perimeter survey
8/28/2011	EP278-EP294	0	Evening perimeter survey
8/28/2011	EP278-EP294	0	Monitoring Construction Activities
8/28/2011	EP278-EP294	0	Morning perimeter survey
8/28/2011	EP274-EP278	0	Monitoring Construction Activities
8/28/2011	EP274-EP278	0	Site clearance survey
8/28/2011	EP269-EP272	0	Monitoring Construction Activities
8/28/2011	EP269-EP272	0	Site clearance survey
8/28/2011	EP263-B, EP267	0	Site clearance survey
8/27/2011	I-8 Island	0	Site clearance survey
8/27/2011	EP305	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Site clearance survey
8/27/2011	I-8 Island	0	Morning perimeter survey
8/27/2011	EP305	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Site clearance survey
8/27/2011	EP300-EP306, EP269-EP273	0	Monitoring Construction Activities
8/27/2011	EP272-3	0	Monitoring Construction Activities
8/27/2011	EP261	0	Monitoring Construction Activities
8/27/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/27/2011	EP278-EP294	0	Site clearance survey
8/27/2011	EP278-EP294	0	Monitoring Construction Activities
8/27/2011	EP274-EP278	0	Site clearance survey
8/27/2011	EP274-EP278	0	Monitoring Construction Activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
8/27/2011	EP269-EP272	0	Monitoring Construction Activities
8/27/2011	EP269-EP272	0	Site clearance survey
8/27/2011	EP263B-EP267	0	Site clearance survey
8/26/2011	I-8 Island	0	Morning perimeter survey
8/26/2011	EP269-EP273	0	Monitoring Construction Activities
8/26/2011	EP269-EP273	0	Morning perimeter survey
8/26/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/26/2011	EP300-EP306	0	Monitoring Construction Activities
8/26/2011	EP278-EP294	0	Evening perimeter survey
8/26/2011	EP278-EP294	0	Monitoring Construction Activities
8/26/2011	EP278-EP294	0	Morning perimeter survey
8/26/2011	EP274-EP278	0	Monitoring Construction Activities
8/26/2011	EP274-EP278	0	Site clearance survey
8/26/2011	EP269-EP272	0	Monitoring Construction Activities
8/26/2011	EP269-EP272	0	Morning perimeter survey
8/25/2011	I-8 Island	0	Morning perimeter survey
8/25/2011	EP269-EP273	0	Monitoring Construction Activities
8/25/2011	EP269-EP273	0	Morning perimeter survey
8/25/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/25/2011	EP278-EP294	0	Evening perimeter survey
8/25/2011	EP278-EP294	0	Monitoring Construction Activities
8/25/2011	EP278-EP294	0	Morning perimeter survey
8/25/2011	EP274-EP278	0	Monitoring Construction Activities
8/25/2011	EP274-EP278	0	Site clearance survey
8/25/2011	EP270-EP272	0	Site clearance survey
8/25/2011	EP269-EP272	0	Monitoring Construction Activities
8/25/2011	EP269-EP272	0	Morning perimeter survey
8/24/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/24/2011	EP300-EP312, EP263B-EP267	0	Site clearance survey
8/24/2011	EP269-EP273	0	Monitoring Construction Activities
8/24/2011	EP269-EP273	0	Site clearance survey
8/24/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/24/2011	EP278-EP294	0	Evening perimeter survey
8/24/2011	EP278-EP294	0	Monitoring Construction Activities
8/24/2011	EP278-EP294	0	Morning perimeter survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
8/24/2011	EP274-EP278	0	Monitoring Construction Activities
8/24/2011	EP274-EP278	0	Site clearance survey
8/23/2011	I-8 Island	0	Morning perimeter survey
8/23/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/23/2011	EP300-EP312, EP263B-EP267	0	Site clearance survey
8/23/2011	EP269-EP273	0	Monitoring Construction Activities
8/23/2011	EP269-EP273	0	Site clearance survey
8/23/2011	EP278-EP294	0	Evening perimeter survey
8/23/2011	EP278-EP294	0	Monitoring Construction Activities
8/23/2011	EP278-EP294	0	Morning perimeter survey
8/23/2011	EP274-EP278	0	Monitoring Construction Activities
8/23/2011	EP274-EP278	0	Morning perimeter survey
8/23/2011	EP270-EP272	0	Morning perimeter survey
8/23/2011	EP269-EP272	0	Morning perimeter survey
8/22/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/22/2011	EP300-EP312, EP263B-EP267	0	Morning perimeter survey
8/22/2011	EP269-EP273	0	Monitoring Construction Activities
8/22/2011	EP269-EP273	0	Monitoring Construction Activities
8/22/2011	EP269-EP273	0	Morning perimeter survey
8/22/2011	EP263B	0	Monitoring Construction Activities
8/22/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/22/2011	EP291	0	Monitoring Construction Activities
8/22/2011	EP278-EP294	0	Evening perimeter survey
8/22/2011	EP278-EP294	0	Monitoring Construction Activities
8/22/2011	EP278-EP294	0	Morning perimeter survey
8/21/2011	I-8 Island	11	Evening perimeter survey - 6:00pm
8/21/2011	EP269-EP273	0	Site clearance survey
8/21/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/21/2011	EP256-EP263	0	Monitoring Construction Activities
8/21/2011	EP256-EP263	0	Site clearance survey
8/21/2011	EP279-EP294	0	Afternoon clearance survey
8/21/2011	EP274-EP278	0	Evening perimeter survey
8/21/2011	EP269-EP272	0	Evening perimeter survey
8/21/2011	EP263B-EP267	0	Site clearance survey
8/20/2011	I8 and Mountain Spring Rd	3	Morning perimeter survey 9:20am

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
8/20/2011	I8 and Mountain Spring Rd	4	Evening perimeter survey 6:40pm
8/20/2011	EP300-EP312	0	Monitoring construction activities
8/20/2011	EP300-EP312	0	Site clearance survey
8/20/2011	EP269-EP273	0	Monitoring construction activities
8/20/2011	EP269-EP273	0	Site clearance survey
8/20/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/20/2011	EP300-EP306	0	Morning perimeter survey
8/20/2011	EP274-EP294	0	Monitoring construction activities
8/20/2011	EP274-EP294	0	Site clearance survey
8/20/2011	EP270-EP271	0	Morning perimeter survey
8/20/2011	EP269-EP271	0	Monitoring construction activities
8/20/2011	EP263B-EP267	0	Site clearance survey
8/19/2011	Radiator Water Tower 17	7	Site clearance survey
8/19/2011	EP298, EP300 & EP307	0	Site clearance survey
8/19/2011	EP296, EP300	0	Monitoring construction activities
8/19/2011	EP296, EP300	0	Site clearance survey
8/19/2011	EP269-EP273	0	Monitoring construction activities
8/19/2011	EP269-EP273	0	Site clearance survey
8/19/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/19/2011	EP291-EP293	0	Monitoring construction activities
8/19/2011	EP279-EP294	0	Monitoring construction activities
8/19/2011	EP274-EP278	0	Monitoring construction activities
8/19/2011	EP274-EP278	0	Site clearance survey
8/19/2011	EP263B-EP267	0	Site clearance survey
8/18/2011	EP269-EP273	0	Monitoring construction activities
8/18/2011	EP269-EP273	0	Site clearance survey
8/18/2011	EP349, EP293	0	Monitoring construction activities
8/18/2011	EP279-EP312	0	Monitoring construction activities
8/18/2011	EP274-EP278	0	Monitoring construction activities
8/18/2011	EP274-EP278	0	Site clearance survey
8/18/2011	EP263B-EP267	0	Site clearance survey
8/17/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/17/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/17/2011	EP269-EP273	0	Monitoring construction activities
8/17/2011	EP269-EP273	0	Site clearance survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
8/17/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/17/2011	EP279-EP294	0	Monitoring construction activities
8/17/2011	EP279-EP294	0	Site clearance survey
8/17/2011	EP274-EP278	0	Monitoring construction activities
8/17/2011	EP274-EP278	0	Site clearance survey
8/17/2011	EP263B-EP267	0	Site clearance survey
8/16/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/16/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/16/2011	EP269-EP273	0	Monitoring construction activities
8/16/2011	EP269-EP273	0	Site clearance survey
8/16/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/16/2011	EP279-EP294	0	Monitoring construction activities
8/16/2011	EP279-EP294	0	Site clearance survey
8/16/2011	EP274-EP278	0	Monitoring construction activities
8/16/2011	EP274-EP278	0	Site clearance survey
8/16/2011	EP265	0	Monitoring construction activities
8/16/2011	EP263B-EP267	0	Site clearance survey
8/15/2011	Fromm and AER Construction Yard	0	Monitoring construction activities
8/15/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/15/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/15/2011	EP294	0	Monitoring construction activities
8/15/2011	EP269-EP273	0	Site clearance survey
8/15/2011	EP269-EP273	0	Monitoring construction activities
8/15/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/15/2011	EP279-EP294	0	Monitoring construction activities
8/15/2011	EP279-EP294	0	Site clearance survey
8/15/2011	EP274-EP278	0	Monitoring construction activities
8/15/2011	EP274-EP278	0	Site clearance survey
8/15/2011	EP263B-EP267	0	Site clearance survey
8/14/2011	EP274-EP278	0	Monitoring construction activities
8/14/2011	EP263B-EP267	0	Site clearance survey
8/14/2011	EP274-EP278	0	Evening perimeter survey
8/14/2011	EP279-294	0	Monitoring construction activities
8/14/2011	EP269-EP273	0	Evening perimeter survey
8/14/2011	EP300-EP312	0	Site clearance survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
8/14/2011	EP300-EP312	0	Monitoring construction activities
8/13/2011	Fromm Construction Yard	0	Site clearance survey
8/13/2011	I-8 Island	19	Morning perimeter survey at 9:54am - 10:45am
8/13/2011	I-8 Island	6	Evening perimeter survey at 4:35pm
8/13/2011	EP263B-EP267	0	Site clearance survey
8/13/2011	EP269-EP271	0	Monitoring construction activities
8/13/2011	EP270-EP271	0	Monitoring construction activities
8/13/2011	EP274-EP278	0	Monitoring construction activities
8/13/2011	EP279-294	0	Monitoring construction activities
8/13/2011	EP300-EP306	0	Monitoring construction activities
8/13/2011	EP259B	0	Site clearance survey
8/13/2011	EP269-EP273	0	Monitoring construction activities
8/13/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/13/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/12/2011	I-8 Island	26	Evening perimeter survey at 4:25pm - 5:45
8/12/2011	EP263B-EP267	0	Site clearance survey
8/12/2011	EP269-EP271	0	Monitoring construction activities
8/12/2011	EP270-EP271	0	Monitoring construction activities
8/12/2011	EP279-294	0	Monitoring construction activities
8/12/2011	EP300-EP306	0	Monitoring construction activities
8/12/2011	EP300-EP312	0	Monitoring construction activities
8/12/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/12/2011	EP259B	0	Site clearance survey
8/12/2011	EP269-EP273	0	Monitoring construction activities
8/12/2011	EP274-EP278, EP290-EP294	0	Site clearance survey
8/12/2011	EP274-EP278, EP290-EP294	0	Monitoring construction activities
8/12/2011	EP294	0	Monitoring construction activities
8/11/2011	I-8 Island	12	Morning perimeter survey at 10:50am
8/11/2011	I-8 Island	28	Evening perimeter survey at 6:19pm
8/11/2011	EP263B-EP267	0	Site clearance survey
8/11/2011	EP269-EP271	0	Monitoring construction activities
8/11/2011	EP270-EP271	0	Monitoring construction activities
8/11/2011	EP279-294	0	Monitoring construction activities
8/11/2011	EP300-EP306	0	Monitoring construction activities
8/11/2011	EP300-EP312	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
8/11/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/11/2011	EP259B	0	Site clearance survey
8/11/2011	EP269-EP273	0	Monitoring construction activities
8/11/2011	EP274-EP278	0	Site clearance survey
8/11/2011	EP274-EP278	0	Monitoring construction activities
8/11/2011	EP292-EP356	0	Monitoring construction activities
8/11/2011	EP294	0	Monitoring construction activities
8/10/2011	I-8 Island	16	Evening perimeter survey at 4:55pm - 5:08
8/10/2011	EP263B-EP267	0	Site clearance survey
8/10/2011	EP269-EP271	0	Monitoring construction activities
8/10/2011	EP270-EP271	0	Monitoring construction activities
8/10/2011	EP273	0	Monitoring construction activities
8/10/2011	EP300-EP306	0	Monitoring construction activities
8/10/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/10/2011	EP259B	0	Site clearance survey
8/10/2011	EP269-EP273	0	Monitoring construction activities
8/10/2011	EP294	0	Monitoring construction activities
8/10/2011	EP300-EP312	0	Morning perimeter survey
8/10/2011	EP300-EP312	0	Monitoring construction activities
8/10/2011	EP300-EP312	0	Evening perimeter survey
8/10/2011	EP227, EP232, EP258, EP314, EP317, EP348, EP349	0	Site clearance survey
8/9/2011	I-8 Island	3	Morning perimeter survey at 10:30am
8/9/2011	I-8 Island	18	Evening perimeter survey at 4:30pm - 5:06pm
8/9/2011	EP263B-EP267	0	Site clearance survey
8/9/2011	EP269-EP271	0	Monitoring construction activities
8/9/2011	EP270-EP271	0	Monitoring construction activities
8/9/2011	EP270-EP273	0	Monitoring construction activities
8/9/2011	EP274-EP278	0	Monitoring construction activities
8/9/2011	EP279-294	0	Monitoring construction activities
8/9/2011	EP300-EP306	0	Monitoring construction activities
8/9/2011	EP305	0	Monitoring construction activities
8/9/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/9/2011	EP269-EP273	0	Site clearance survey
8/9/2011	EP294	0	Monitoring construction activities
8/9/2011	EP300-EP312	0	Morning perimeter survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
8/9/2011	EP300-EP312	0	Monitoring construction activities
8/9/2011	EP300-EP312	0	Evening perimeter survey
8/8/2011	I-8 Island	4	Morning perimeter survey at 9:45am - 9:55am
8/8/2011	I-8 Island	22	Evening perimeter survey at 4:24pm - 5:14pm
8/8/2011	EP279-294	3	Monitoring construction activities
8/8/2011	EP263B-EP267	0	Site clearance survey
8/8/2011	EP269-EP271	0	Monitoring construction activities
8/8/2011	EP270-EP271	0	Monitoring construction activities
8/8/2011	EP273	0	Monitoring construction activities
8/8/2011	EP274-EP278	0	Monitoring construction activities
8/8/2011	EP300-EP306	0	Monitoring construction activities
8/8/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/8/2011	EP269-EP273	0	Site clearance survey
8/8/2011	EP294	0	Monitoring construction activities
8/8/2011	EP300-EP312	0	Morning perimeter survey
8/8/2011	EP300-EP312	0	Monitoring construction activities
8/8/2011	EP300-EP312	0	Evening perimeter survey
8/8/2011	EP301-EP324, EP259-3, EP259B	0	Monitoring construction activities
8/8/2011	EP290-EP300	0	Site clearance survey
8/7/2011	I-8 Island	27	Evening perimeter survey at 6:00pm - 6:45
8/7/2011	EP263B-EP267	0	Site clearance survey
8/7/2011	EP270-EP271	0	Monitoring construction activities
8/7/2011	EP274-EP278	0	Monitoring construction activities
8/7/2011	EP279-294	0	Monitoring construction activities
8/7/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/7/2011	EP269-EP273	0	Evening perimeter survey
8/7/2011	EP300-EP312	0	Evening perimeter survey
8/6/2011	EP278 & EP277	0	Monitoring construction activities
8/6/2011	I-8 Island	12	Afternoon perimeter survey at 1:20pm
8/6/2011	EP263B-EP267	0	Site clearance survey
8/6/2011	EP269-EP271	0	Monitoring construction activities
8/6/2011	EP270-EP271	0	Monitoring construction activities
8/6/2011	EP274-EP278	0	Monitoring construction activities
8/6/2011	EP279-294	0	Monitoring construction activities
8/6/2011	EP300-EP306	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
8/6/2011	EP262, EP266, EP267	0	Site clearance survey
8/6/2011	EP269-EP273	0	Monitoring construction activities
8/6/2011	EP307-EP315	0	Morning perimeter survey
8/6/2011	EP307-EP316	0	Monitoring construction activities
8/6/2011	EP307-EP317	0	Evening perimeter survey
8/5/2011	EP263B-EP267	0	Site clearance survey
8/5/2011	EP271, EP273, EP274, EP277 and EP278	0	Monitoring construction activities
8/5/2011	EP274-EP278	0	Monitoring construction activities
8/5/2011	EP279-294	0	Monitoring construction activities
8/5/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/5/2011	EP269-EP273	0	Monitoring construction activities
8/5/2011	EP294	0	Monitoring construction activities
8/5/2011	EP307-EP312	0	Morning perimeter survey
8/5/2011	EP307-EP313	0	Monitoring construction activities
8/5/2011	EP307-EP314	0	Evening perimeter survey
8/4/2011	I-8 Island	23	Evening perimeter survey at 4:00pm - 4:33pm
8/4/2011	EP263B-EP267	0	Site clearance survey
8/4/2011	EP269-EP271	0	Monitoring construction activities
8/4/2011	EP270-EP271	0	Monitoring construction activities
8/4/2011	EP274-EP278	0	Monitoring construction activities
8/4/2011	EP279-294	0	Monitoring construction activities
8/4/2011	EP300-EP306	0	Monitoring construction activities
8/4/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/4/2011	EP269-EP273	0	Monitoring construction activities
8/4/2011	EP294	0	Monitoring construction activities
8/3/2011	I-8 Island	17	Evening perimeter survey at 5:45pm - 6:05pm
8/3/2011	EP256-EP263	0	Monitoring construction activities
8/3/2011	EP263B-EP267	0	Site clearance survey
8/3/2011	EP269-EP271	0	Monitoring construction activities
8/3/2011	EP270-EP271	0	Monitoring construction activities
8/3/2011	EP274-EP278	0	Monitoring construction activities
8/3/2011	EP279-294	0	Monitoring construction activities
8/3/2011	EP290-EP312	0	Monitoring construction activities
8/3/2011	EP300-EP306	0	Monitoring construction activities
8/3/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
8/3/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
8/3/2011	EP269-EP273	0	Monitoring construction activities
8/3/2011	EP271	0	Monitoring construction activities
8/3/2011	EP294	0	Monitoring construction activities
8/3/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/3/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/3/2011	I-8 Island	0	Monitoring construction activities
8/2/2011	I-8 Island	12	Morning perimeter survey at 9:50am
8/2/2011	I-8 Island	23	Evening perimeter survey at 4:30pm
8/2/2011	EP263B-EP267	0	Site clearance survey
8/2/2011	EP269-EP271	0	Monitoring construction activities
8/2/2011	EP270-EP271	0	Monitoring construction activities
8/2/2011	EP279-294	0	Monitoring construction activities
8/2/2011	EP300-EP306	0	Monitoring construction activities
8/2/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
8/2/2011	EP269-EP273	0	Monitoring construction activities
8/2/2011	EP271 and EP273	0	Monitoring construction activities
8/2/2011	EP273	0	Monitoring construction activities
8/2/2011	EP274-EP278	0	Monitoring construction activities
8/2/2011	EP294	0	Monitoring construction activities
8/1/2011	I-8 Island	19	Morning perimeter survey at 10:00 - 10:20am
8/1/2011	I-8 Island	1	Evening perimeter survey at 4:30pm
8/1/2011	EP263B-EP267	0	Site clearance survey
8/1/2011	EP269-EP271	0	Monitoring construction activities
8/1/2011	EP270-EP271	0	Monitoring construction activities
8/1/2011	EP274-EP278	0	Monitoring construction activities
8/1/2011	EP279-294	0	Monitoring construction activities
8/1/2011	EP290-EP312	0	Monitoring construction activities
8/1/2011	EP300-EP306	0	Monitoring construction activities
8/1/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/1/2011	EP269	0	Monitoring construction activities
8/1/2011	EP269-EP273	0	Monitoring construction activities
8/1/2011	EP272	0	Monitoring construction activities
8/1/2011	EP291 & EP301-EP304	0	Monitoring construction activities
8/1/2011	EP300-EP312, EP290-EP294	0	Site clearance survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
8/1/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
7/31/2011	I-8 Island	24	Evening perimeter survey at 5:55pm
7/31/2011	EP263B-EP267	0	Site clearance survey
7/31/2011	EP270-EP271	0	Monitoring construction activities
7/31/2011	EP274-EP278	0	Monitoring construction activities
7/31/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/31/2011	EP269-EP273	0	Evening perimeter survey
7/31/2011	EP279-EP294	0	Site clearance survey
7/31/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
7/30/2011	EP271	1	Morning perimeter survey at 7:00am
7/30/2011	EP256-EP263A-2, AER Yard	6	Monitoring during construction activities. These sheep were outside of all work areas and associated buffers and did not impact work.
7/30/2011	I-8 Island	11	Morning perimeter survey at 10:15am - 11:07
7/30/2011	I-8 Island	7	Evening perimeter survey at 4:12pm
7/30/2011	EP263B-EP267	0	Site clearance survey
7/30/2011	EP269	0	Site clearance survey
7/30/2011	EP269-EP272	0	Monitoring construction activities
7/30/2011	EP270-EP271	0	Monitoring construction activities
7/30/2011	EP274-EP278	0	Monitoring construction activities
7/30/2011	EP279-294	0	Monitoring construction activities
7/30/2011	EP300-EP306	0	Monitoring construction activities
7/30/2011	EP269	0	Monitoring construction activities
7/30/2011	EP269-EP273	0	Site clearance survey
7/30/2011	EP270-EP271	0	Monitoring construction activities
7/30/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
7/30/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
7/29/2011	I-8 Island	14	Morning perimeter survey at 8:55am
7/29/2011	I-8 Island	2	Evening perimeter survey at 4:00pm
7/29/2011	EP263B-EP267	0	Site clearance survey
7/29/2011	EP269	0	Site clearance survey
7/29/2011	EP269-EP272	0	Monitoring construction activities
7/29/2011	EP270-EP271	0	Monitoring construction activities
7/29/2011	EP274-EP278	0	Monitoring construction activities
7/29/2011	EP279-294	0	Monitoring construction activities
7/29/2011	EP300-EP306	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
7/29/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/29/2011	EP269	0	Monitoring construction activities
7/29/2011	EP269-EP273	0	Site clearance survey
7/29/2011	EP270	0	Monitoring construction activities
7/29/2011	EP300-EP312	0	Morning perimeter survey
7/29/2011	EP300-EP312	0	Monitoring construction activities
7/29/2011	EP300-EP312	0	Evening perimeter survey
7/29/2011	EP303	0	Monitoring construction activities
7/28/2011	EP269	4	Monitoring during construction activities
7/28/2011	I-8 Island	11	Morning perimeter survey at 9:19am
7/28/2011	I-8 Island	8	Evening perimeter survey at 4:00pm - 4:50pm
7/28/2011	EP279-294	0	Monitoring construction activities
7/28/2011	EP263B-EP267	0	Site clearance survey
7/28/2011	EP269	0	Site clearance survey
7/28/2011	EP270-EP271	0	Monitoring construction activities
7/28/2011	EP274-EP278	0	Monitoring construction activities
7/28/2011	EP300-EP306	0	Monitoring construction activities
7/28/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/28/2011	EP269	0	Monitoring construction activities
7/28/2011	EP270	0	Monitoring construction activities
7/28/2011	EP300-EP312	0	Morning perimeter survey
7/28/2011	EP300-EP312	0	Monitoring construction activities
7/28/2011	EP300-EP312	0	Evening perimeter survey
7/28/2011	AER CY	0	Site clearance survey
7/27/2011	I-8 Island	13	Evening perimeter survey at 6:30pm - 7:00pm
7/27/2011	EP279-294	0	Monitoring construction activities
7/27/2011	EP263B-EP267	0	Site clearance survey
7/27/2011	EP268 - EP263	0	Monitoring construction activities
7/27/2011	EP269	0	Site clearance survey
7/27/2011	EP270-EP271	0	Monitoring construction activities
7/27/2011	EP274-EP278	0	Monitoring construction activities
7/27/2011	EP300-EP306	0	Monitoring construction activities
7/27/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/27/2011	EP269-EP273	0	Morning perimeter survey
7/27/2011	EP269-EP273	0	Evening perimeter survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
7/27/2011	EP300-EP312	0	Morning perimeter survey
7/27/2011	EP300-EP312	0	Monitoring construction activities
7/27/2011	EP300-EP312	0	Evening perimeter survey
7/26/2011	Devils Canyon Bridge1, Hwy 8	1	Monitoring during construction activities
7/26/2011	I-8 Island	24	Morning perimeter survey at 9:46am - 10:45am
7/26/2011	I-8 Island	7	Evening perimeter survey at 6:17pm - 6:50pm
7/26/2011	EP263B-EP267	0	Site clearance survey
7/26/2011	EP269	0	Site clearance survey
7/26/2011	EP270	0	Monitoring construction activities
7/26/2011	EP274-EP278	0	Monitoring construction activities
7/26/2011	EP279-294	0	Monitoring construction activities
7/26/2011	EP300-EP306	0	Monitoring construction activities
7/26/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/26/2011	EP269-EP273	0	Morning perimeter survey
7/26/2011	EP269-EP273	0	Evening perimeter survey
7/26/2011	EP300-EP312	0	Monitoring construction activities
7/26/2011	EP300-EP312	0	Morning perimeter survey
7/26/2011	EP300-EP312	0	Monitoring construction activities
7/26/2011	EP300-EP312	0	Evening perimeter survey
7/25/2011	I-8 Island	21	Morning perimeter survey at 8:47am
7/25/2011	I-8 Island	20	Evening perimeter survey at 6:37am
7/25/2011	EP263B-EP267	0	Site clearance survey
7/25/2011	EP269	0	Site clearance survey
7/25/2011	EP270	0	Monitoring construction activities
7/25/2011	EP274-EP278	0	Monitoring construction activities
7/25/2011	EP279-294	0	Monitoring construction activities
7/25/2011	EP300-EP306	0	Monitoring construction activities
7/25/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/25/2011	EP269-EP273	0	Morning perimeter survey
7/25/2011	EP269-EP273	0	Evening perimeter survey
7/25/2011	EP300 & EP302	0	Monitoring construction activities
7/25/2011	EP300-EP312	0	Morning perimeter survey
7/25/2011	EP300-EP312	0	Monitoring construction activities
7/25/2011	EP300-EP312	0	Evening perimeter survey
7/25/2011	EP276	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
7/24/2011	I-8 Island	13	Evening perimeter survey at 6:25pm
7/24/2011	EP263B-EP267	0	Site clearance survey
7/24/2011	EP269	0	Site clearance survey
7/24/2011	EP270	0	Monitoring construction activities
7/24/2011	EP279-294	0	Monitoring construction activities
7/24/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/24/2011	EP269-EP273	0	Evening perimeter survey
7/24/2011	EP274-EP278	0	Evening perimeter survey
7/24/2011	EP300-EP312	0	Evening perimeter survey
7/23/2011	EP263B-EP267	0	Site clearance survey
7/23/2011	EP269	0	Site clearance survey
7/23/2011	EP270	0	Monitoring construction activities
7/23/2011	EP279-294	0	Monitoring construction activities
7/23/2011	EP300-EP312	0	Monitoring construction activities
7/23/2011	EP300-EP312	0	Site clearance survey
7/23/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/23/2011	EP269-EP276	0	Morning perimeter survey
7/23/2011	EP274-EP278	0	Morning perimeter survey
7/23/2011	EP274-EP278	0	Evening perimeter survey
7/23/2011	I-8 Island	0	Morning perimeter survey
7/22/2011	I-8 Island	18	Evening perimeter survey at 6:35pm
7/22/2011	EP263B-EP267	0	Site clearance survey
7/22/2011	EP269	0	Site clearance survey
7/22/2011	EP269-EP270	0	Monitoring construction activities
7/22/2011	EP270	0	Monitoring construction activities
7/22/2011	EP300-EP312	0	Monitoring construction activities
7/22/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/22/2011	EP269-EP273	0	Morning perimeter survey
7/22/2011	EP269-EP273	0	Evening perimeter survey
7/22/2011	EP274-EP278	0	Site clearance survey
7/22/2011	EP274-EP278	0	Monitoring construction activities
7/21/2011	I-8 Island	18	Evening perimeter survey at 6:35pm
7/21/2011	EP263B-EP267	0	Site clearance survey
7/21/2011	EP269	0	Site clearance survey
7/21/2011	EP269-EP270	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
7/21/2011	EP270	0	Monitoring construction activities
7/21/2011	EP279-294	0	Monitoring construction activities
7/21/2011	EP300-EP312	0	Monitoring construction activities
7/21/2011	EP300-EP306	0	Site clearance survey
7/21/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/21/2011	EP269-EP273	0	Morning perimeter survey
7/21/2011	EP269-EP273	0	Evening perimeter survey
7/21/2011	EP274-EP278	0	Morning perimeter survey
7/21/2011	EP274-EP278	0	Evening perimeter survey
7/20/2011	I-8 Island	4	Evening perimeter survey at 6:50pm
7/20/2011	EP269-EP273	0	Morning perimeter survey
7/20/2011	EP269-EP273	0	Evening perimeter survey
7/20/2011	EP263B-EP267	0	Site clearance survey
7/20/2011	EP269	0	Site clearance survey
7/20/2011	EP270	0	Monitoring construction activities
7/20/2011	EP279-294	0	Monitoring construction activities
7/20/2011	EP300-EP312	0	Monitoring construction activities
7/20/2011	EP300-EP306	0	Site clearance survey
7/20/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/20/2011	EP274-EP278	0	Morning perimeter survey
7/20/2011	EP274-EP278	0	Evening perimeter survey
7/19/2011	I-8 Island	10	Morning perimeter survey at 9:10am
7/19/2011	I-8 Island	17	Evening perimeter survey at 4:00pm - 6:40pm
7/19/2011	EP269-EP273	0	Morning perimeter survey
7/19/2011	EP269-EP273	0	Evening perimeter survey
7/19/2011	EP269	0	Site clearance survey
7/19/2011	EP270	0	Monitoring construction activities
7/19/2011	EP279-294	0	Monitoring construction activities
7/19/2011	EP300-EP312	0	Monitoring construction activities
7/19/2011	EP300-EP306	0	Site clearance survey
7/19/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/19/2011	EP274-EP278	0	Morning perimeter survey
7/19/2011	EP274-EP278	0	Evening perimeter survey
7/19/2011	EP263B-EP267	0	Site clearance survey
7/18/2011	I-8 Island	21	Evening perimeter survey at 7:10pm

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
7/18/2011	EP263B-EP267	0	Site clearance survey
7/18/2011	EP269	0	Site clearance survey
7/18/2011	EP270	0	Monitoring construction activities
7/18/2011	EP279-294	0	Monitoring construction activities
7/18/2011	EP300-EP312	0	Monitoring construction activities
7/18/2011	EP300-EP306	0	Site clearance survey
7/18/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/18/2011	EP274-EP278	0	Morning perimeter survey
7/18/2011	EP274-EP278	0	Evening perimeter survey
7/18/2011	EP269-EP273	0	Site clearance survey
7/17/2011	I-8 Island	17	Evening perimeter survey at 5:55pm - 6:25
7/17/2011	EP263B-EP267	0	Site clearance survey
7/17/2011	EP269	0	Site clearance survey
7/17/2011	EP270	0	Monitoring construction activities
7/17/2011	EP300-EP312	0	Monitoring construction activities
7/17/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/17/2011	EP274-EP278	0	Evening perimeter survey
7/17/2011	EP279-EP294	0	Site clearance survey
7/17/2011	EP269-EP273	0	Site clearance survey
7/16/2011	I-8 Island	1	Morning perimeter survey at 8:35am
7/16/2011	EP263B-EP267	0	Site clearance survey
7/16/2011	EP269	0	Site clearance survey
7/16/2011	EP270	0	Monitoring construction activities
7/16/2011	EP300-EP306	0	Monitoring construction activities
7/16/2011	EP300-EP312	0	Monitoring construction activities
7/16/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/16/2011	EP274-EP278	0	Morning perimeter survey
7/16/2011	EP279-EP294	0	Morning perimeter survey
7/16/2011	EP279-EP294	0	Site clearance survey
7/16/2011	EP279-EP294	0	Monitoring construction activities
7/16/2011	EP269-EP273	0	Site clearance survey
7/15/2011	EP273-1	1	Evening perimeter survey at 4:30pm
7/15/2011	I-8 Island	12	Evening perimeter survey at 6:35pm - 7:00pm
7/15/2011	EP263B-EP267	0	Site clearance survey
7/15/2011	EP269	0	Site clearance survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
7/15/2011	EP270	0	Monitoring construction activities
7/15/2011	EP279-294	0	Monitoring construction activities
7/15/2011	EP300-EP306	0	Monitoring construction activities
7/15/2011	EP300-EP312	0	Monitoring construction activities
7/15/2011	EP256-EP263A-2, AER Yard	0	Site clearance survey
7/15/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/15/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/15/2011	EP269-EP273	0	Site clearance survey
7/15/2011	EP274-EP278	0	Morning perimeter survey
7/15/2011	EP274-EP278	0	Evening perimeter survey
7/14/2011	I-8 Island	3	Evening perimeter survey at 4:10pm
7/14/2011	I-8 Island		7:15am - 9:30am PBHS were at above point
7/14/2011	EP263B-EP267	0	Site clearance survey
7/14/2011	EP269	0	Site clearance survey
7/14/2011	EP270	0	Monitoring construction activities
7/14/2011	EP279-294	0	Monitoring construction activities
7/14/2011	EP300-EP306	0	Monitoring construction activities
7/14/2011	EP300-EP312	0	Monitoring construction activities
7/14/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/14/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/14/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/14/2011	EP274-EP278	0	Morning perimeter survey
7/14/2011	EP274-EP278	0	Evening perimeter survey
7/14/2011	EP269-EP273	0	Site clearance survey
7/13/2011	I-8 Island	21	Evening perimeter survey at 4:40pm
7/13/2011	EP263B-EP267	0	Site clearance survey
7/13/2011	EP269	0	Site clearance survey
7/13/2011	EP270	0	Monitoring construction activities
7/13/2011	EP279-294	0	Monitoring construction activities
7/13/2011	EP300-EP306	0	Monitoring construction activities
7/13/2011	EP300-EP312	0	Monitoring construction activities
7/13/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/13/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/13/2011	EP269-EP273	0	Site clearance survey
7/12/2011	EP256-EP263A-2, AER Yard	15	Monitoring during construction activities @ 7:40am - 11:00am

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
7/12/2011	I-8 Island	17	Evening perimeter survey at 4:00pm
7/12/2011	EP263B-EP267	0	Site clearance survey
7/12/2011	EP269	0	Site clearance survey
7/12/2011	EP270	0	Monitoring construction activities
7/12/2011	EP279-294	0	Monitoring construction activities
7/12/2011	EP300-EP306	0	Monitoring construction activities
7/12/2011	EP300-EP312	0	Monitoring construction activities
7/12/2011	EP274-EP278	0	Morning perimeter survey
7/12/2011	EP274-EP278	0	Evening perimeter survey
7/12/2011	EP269-EP273	0	Site clearance survey
7/11/2011	I-8 Island	29	Evening perimeter survey at 4:40pm
7/11/2011	EP263B-EP267	0	Site clearance survey
7/11/2011	EP269	0	Site clearance survey
7/11/2011	EP270	0	Monitoring construction activities
7/11/2011	EP279-294	0	Monitoring construction activities
7/11/2011	EP300-EP306	0	Monitoring construction activities
7/11/2011	EP300-EP312	0	Monitoring construction activities
7/11/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/11/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/11/2011	EP269-EP273	0	Site clearance survey
7/11/2011	EP274-EP278	0	Morning perimeter survey
7/11/2011	EP274-EP278	0	Evening perimeter survey
7/10/2011	I-8 Island	8	Perimeter survey
7/10/2011	I-8 Island	20	Monitoring construction activities
7/10/2011	EP269	0	Site clearance survey
7/10/2011	EP270	0	Monitoring construction activities
7/10/2011	EP279-294	0	Monitoring construction activities
7/10/2011	EP300-EP312	0	Monitoring construction activities
7/10/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/10/2011	EP274-EP278, EP265-EP267	0	Site clearance survey
7/9/2011	EP263A-2	11	Evening perimeter survey
7/9/2011	EP263B-EP267	0	Site clearance survey
7/9/2011	EP269-EP274	0	Monitoring construction activities
7/9/2011	EP279-294	0	Monitoring construction activities
7/9/2011	EP300-EP307	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
7/9/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/9/2011	EP269-EP273	0	Site clearance survey
7/9/2011	EP274-EP278	0	Morning perimeter survey
7/9/2011	EP310	0	Monitoring construction activities
7/8/2011	EP263B-EP267	0	Site clearance survey
7/8/2011	EP300-EP312	0	Monitoring construction activities
7/8/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/8/2011	EP269-EP273	0	Site clearance survey
7/8/2011	EP274-EP278	0	Morning perimeter survey
7/8/2011	EP274-EP278	0	Evening perimeter survey
7/8/2011	EP303	0	Monitoring construction activities
7/8/2011	EP279-EP294	0	Monitoring construction activities
7/7/2011	I-8 Island	8	Evening perimeter survey at 7:00pm
7/7/2011	EP263B-EP267	0	Site clearance survey
7/7/2011	EP269-EP273	0	Monitoring construction activities
7/7/2011	EP300-EP312	0	Monitoring construction activities
7/7/2011	EP300-EP307	0	Monitoring construction activities
7/7/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/7/2011	EP269-EP273	0	Site clearance survey
7/7/2011	EP274-EP278	0	Morning perimeter survey
7/7/2011	EP274-EP278	0	Evening perimeter survey
7/7/2011	EP303 & EP304	0	Monitoring construction activities
7/7/2011	EP306-EP312	0	Site clearance survey
7/6/2011	EP263A-2	2	Evening perimeter survey
7/6/2011	EP263B-EP267	0	Site clearance survey
7/6/2011	EP269-EP272	0	Monitoring construction activities
7/6/2011	EP300-EP312	0	Monitoring construction activities
7/6/2011	EP300-EP307	0	Monitoring construction activities
7/6/2011	EP303	0	Site clearance survey
7/6/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/6/2011	EP274-EP278	0	Morning perimeter survey
7/6/2011	EP274-EP278	0	Evening perimeter survey
7/6/2011	EP305 to EP304	0	Monitoring construction activities
7/6/2011	I-8 Island	0	Monitoring construction activities
7/6/2011	EP269-EP273	0	Site clearance survey

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
7/5/2011	EP270	14	Morning perimeter survey at 6:30am - 10:00am
7/5/2011	EP270	9	Evening perimeter survey at 5:00pm
7/5/2011	I-8 Island	7	Evening perimeter survey at 6:20pm
7/5/2011	EP269-EP273	0	Morning perimeter survey
7/5/2011	EP269-EP273	0	Evening perimeter survey
7/5/2011	EP263B-EP267	0	Site clearance survey
7/5/2011	EP269-EP271	0	Monitoring construction activities
7/5/2011	EP300-EP312	0	Monitoring construction activities
7/5/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/5/2011	EP274-EP278	0	Morning perimeter survey
7/5/2011	EP274-EP278	0	Evening perimeter survey
7/5/2011	EP307 to EP305	0	Monitoring construction activities
7/5/2011	I-8 Island	0	Site clearance survey
7/4/2011	EP270	9	Perimeter survey
7/4/2011	EP263B-EP267	0	Site clearance survey
7/4/2011	EP300-EP312	0	Monitoring construction activities
7/4/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/4/2011	EP269-EP273	0	Site clearance survey
7/4/2011	EP274-EP278	0	Evening perimeter survey
7/4/2011	I-8 Island	0	Site clearance survey
7/2/2011	EP263B-EP267	0	Site clearance survey
7/2/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/2/2011	EP269-EP273	0	Site clearance survey
7/2/2011	EP274-EP278	0	Morning perimeter survey
7/2/2011	I-8 Island	0	Site clearance survey
7/1/2011	EP263B-EP267	0	Site clearance survey
7/1/2011	EP300-EP312	0	Monitoring construction activities
7/1/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/1/2011	EP269-EP273	0	Site clearance survey
7/1/2011	EP274-EP278	0	Morning perimeter survey
7/1/2011	EP274-EP278	0	Evening perimeter survey
7/1/2011	I-8 Island	0	Site clearance survey
6/30/2011	EP300-EP312	0	Monitoring construction activities
6/29/2011	EP310-EP312	0	Monitoring construction activities
4/15/2011	EP210, EP211, EP213-EP215, EP217-EP219	0	Monitoring construction activities

PBS Monitoring Report - Week Ending 11/05/2011

Date	Location	Number observed	Comments
3/26/2011	EP105	0	Site clearance survey

Flat Tailed Horned Lizard Counts - Week Ending 11/05/2011									
Date	Location	Observed		Injured		Relocated		Dead	
	Post RCLMP*	Day	Night	Day	Night	Day	Night	Day	Night
11/1/2011	Dunaway CY					1			
10/13/2011	AR to EP354							1	
9/20/2011	AR btwn EP357 and EP358							1	
9/19/2011	AR btwn EP352 and EP353	1							
9/12/2011	EP325					1			
9/9/2011	AR to EP363	1							
9/6/2011	AR to EP360/361					1			
9/6/2011	EP360					2			
9/6/2011	EP359					1			
9/3/2011	SWPL AR to EP324					1			
9/3/2011	SWPL AR to EP342					1			
9/3/2011	SWPL AR to EP345							1	
9/3/2011	SWPL AR to EP344 and EP345					1			
8/31/2011	EP324					1			
8/31/2011	SWPL AR to EP325-2					1			
8/30/2011	SWPL AR to EP346 and EP347					1			
8/29/2011	SWPL AR to EP353 and EP354							1	
8/29/2011	SWPL AR to EP324							1	
8/27/2011	EP349					1			
8/25/2011	EP360							1	
8/25/2011	Btwn EP320/321					1			
8/24/2011	SWPL AR near EP346					1			
8/23/2011	EP349					1			
8/21/2011	SWPL AR btwn EP344/345					1			
8/21/2011	SWPL AR to EP345							1	
8/19/2011	SWPL AR to EP339					1			
8/20/2011	SWPL AR to IV Sub							1	
8/20/2011	SWPL AR btwn EP346/347					1			
8/19/2011	EP338/339 Pullsite					1			
8/19/2011	EP355/356 Pullsite					1			
8/18/2011	EP347					1			
8/18/2011	SWPL AR to EP353							1	
8/11/2011	SWPL AR by EP348					1			
8/11/2011	EP348/EP349 Pullsite					1			
8/10/2011	EP347					1			
8/8/2011	SWPL AR to EP351					2			
8/6/2011	BLM AR near EP327							1	
8/1/2011	IV Substation Yard	1							
8/1/2011	EP325					1			
8/1/2011	AR to EP345					1			
7/30/2011	EP322					1			
7/28/2011	EP355/EP356 Pullsite					1			
7/27/2011	Near EP316-2	1							

Flat Tailed Horned Lizard Counts - Week Ending 11/05/2011									
Date	Location	Observed		Injured		Relocated		Dead	
7/26/2011	SWPL AR to EP344	1							
	Post RCLMP*	Day	Night	Day	Night	Day	Night	Day	Night
7/26/2011	EP347					1			
7/26/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/22/2011	AR to IV Sub					1			
7/21/2011	EP360					1			
7/21/2011	AR to EP326					1			
7/19/2011	SWPL AR to IV Sub	1							
7/19/2011	EP353					1			
7/19/2011	AR to Dunaway CY					1			
7/18/2011	EP318					1			
7/17/2011	EP355					1			
7/15/2011	EP359	1							
7/15/2011	EP352	1							
7/15/2011	EP350	1							
7/14/2011	Spur Rd to EP355							1	
7/14/2011	EP322	1							
7/13/2011	EP357	1							
7/12/2011	EP344	1							
7/12/2011	SWPL AR btwn EP348/345							1	
TOTAL POST RCLMP		12	0	0	0	43	0	12	
Prior to RCLMP		Day		Day		Day		Day	
7/11/2011	AR to EP352					2			
7/11/2011	AR to EP345					2			
7/10/2011	EP358					1			
7/10/2011	SWPL AR to EP354					2			
7/9/2011	AR to EP330	1							
7/8/2011	Spur Rd. to EP352	1							
7/7/2011	EP324					1			
7/7/2011	EP355					1			
7/6/2011	SWPL AR btwn EP362/363							1	
7/5/2011	EP354					1			
7/1/2011	AR to EP353	1							
6/30/2011	AR between EP310/311							1	
6/30/2011	EP358	1							
6/30/2011	EP360	1							
6/30/2011	AR to EP312							1	
6/30/2011	EP360							1	
6/27/2011	EP350					1			
6/27/2011	SWPL AR to IV Substation	2							
6/26/2011	IV Substation					1			

Flat Tailed Horned Lizard Counts - Week Ending 11/05/2011					
Date	Location	Observed	Injured	Relocated	Dead
6/25/2011	SWPL AR to EP361	1			
6/24/2011	EP359			1	
6/23/2011	SWPL AR to EP360			2	
6/22/2011	SWPL AR to EP355			1	
6/20/2011	EP356	2			
6/20/2011	SWPL AR to EP359	1			
6/20/2011	Near EP356	2			
6/20/2011	AR between EP358/357				1
6/18/2011	AR to Dunaway CY				1
6/17/2011	Near EP322	1			
6/7/2011	Near EP355	1			
6/7/2011	EP361			1	
6/7/2011	AR btwn EP343/EP344				1
6/7/2011	AR between EP324/325				1
6/6/2011	SWPL AR btwn EP344/EP345			1	
6/3/2011	EP359			1	
6/3/2011	SWPL AR EP362			1	
6/2/2011	AR to EP358			1	
6/2/2011	SWPL AR to EP316-2				1
6/2/2011	AR east of EP325				1
6/1/2011	SWPL AR btwn EP319/EP320			1	
6/1/2011	SWPL AR to EP318			1	
5/31/2011	SWPL AR btwn EP359/EP360			1	
5/31/2011	SWPL AR to EP320			1	
5/31/2011	EP360				1
5/27/2011	EP357			1	
5/26/2011	SWPL AR to EP359			1	
5/25/2011	Spur Rd to EP321			1	
5/23/2011	EP323			1	
5/21/2011	EP324			1	
5/20/2011	IV CY			1	
5/20/2011	AR to EP362			1	
5/20/2011	AR btwn EP324/EP325			1	
5/20/2011	SWPL AR btwn EP326/EP327			1	
5/20/2011	IV Substation			3	
5/19/2011	IV Substation			5	
5/19/2011	EP324			1	
5/18/2011	IV Substation Yard			1	
5/18/2011	IV Substation Yard				1
5/17/2011	AR to IV Substation				1
5/16/2011	IV Substation Yard			1	
5/13/2011	SWPL AR Near EP362-1	1			
5/12/2011	AR to EP355			1	
5/11/2011	EP360	1			

Flat Tailed Horned Lizard Counts - Week Ending 11/05/2011					
Date	Location	Observed	Injured	Relocated	Dead
5/11/2011	Dunaway CY	3			
5/11/2011	Dunaway Yard			4	
5/10/2011	EP322	1			
5/10/2011	AR to Dunaway CY	1			
5/9/2011	Dunaway Yard			4	
5/7/2011	EP322	1			
5/7/2011	Spur Road to EP344	1			
5/7/2011	Dunaway Yard			1	
5/6/2011	AR to EP321-1	1			
5/5/2011	AR to EP321-1	1			
5/5/2011	AR to Dunaway CY	2			
5/5/2011	Dunaway Yard			2	
5/4/2011	AR btwn EP343/EP344			1	
5/3/2011	SWPL AR btwn EP320/EP321	1			
4/27/2011	AR to EP322	2			
4/26/2011	EP322	1			
4/25/2011	Plaster City CY	1			
4/20/2011	Plaster City			1	
4/18/2011	Plaster City			1	
4/14/2011	AR to IV Substation	1			
4/2/2011	Dunaway CY	1			
TOTAL PRIOR TO RCLMP		35	0	60	13
YTD		47	0	103	25

*RCLMP refers to the Revised Construction Lighting Mitigation Plan

Raven Control Monitoring Report - Week Ending 11/05/2011							
Date	Location	Number of Ravens observed	Raven Activity				
			Nesting	Flying	Perching	Roosting	Scavaging
11/5/2011	S2 Yard	7			7		no
11/5/2011	IV Substation	1			1		no
11/4/2011	S2 Yard	5			5		no
11/3/2011	S2 Yard	5			3		2 no
11/3/2011	IV Substation	1			1		no
11/3/2011	Fromm CY	1				1	no
11/3/2011	EP303 and EP302	2			2		no
11/3/2011	EP281	2			2		no
11/2/2011	S2 Yard	4			4		no
11/2/2011	IV Substation	1		1			no
11/2/2011	EP305, EP310, EP311	1		1			no
11/1/2011	S2 Yard	2			2		no
11/1/2011	IV Substation	1		1			no
11/1/2011	EP305 and EP312	1			1		no
10/31/2011	S2 Yard	5			5		no
10/31/2011	AER and Fromm CY	1				1	no
10/30/2011	No ravens observed						
10/29/2011	IV Substation	3		3			no
10/28/2011	IV Substation	1		1			no
10/28/2011	EP256, EP357 & EP358	5		5			no
10/27/2011	EP356, EP358 & EP362	2		2			no
10/27/2011	EP305, EP307, EP310-EP312	1		1			no
10/26/2011	EP306, EP307 & EP310	2		2			no
10/25/2011	IV Substation	1		1			no
10/25/2011	EP310	1		1			no
10/24/2011	S2 Yard	3				3	no
10/24/2011	EP305	1			1		no
10/23/2011	S2 Yard	3			3		no
10/22/2011	No ravens observed						
10/21/2011	Dunaway CY	1			1		no
10/20/2011	S2 Yard	2				2	no
10/20/2011	Dunaway CY	5				5	no
10/19/2011	EP314	1		1			no
10/19/2011	EP290	5		5			no
10/18/2011	No ravens observed						
10/17/2011	EP301	3		3			no
10/16/2011	No ravens observed						
10/15/2011	S2 Yard	2				2	no
10/15/2011	Dunaway CY	1				1	no
10/15/2011	EP315	2				2	no
10/15/2011	EP301	3			3		no
10/14/2011	Fromm CY	3				3	no
10/14/2011	EP305	2		2			no
10/14/2011	EP301	3			3		no
10/13/2011	S2 Yard	2				2	no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
10/13/2011	Dunaway CY	5					5	no
10/13/2011	Fromm CY	1					1	no
10/13/2011	EP354-EP363	2			2			no
10/13/2011	EP301	4		4				no
10/12/2011	EP300-EP301	2		2				no
10/11/2011	Plaster City Yard	2			2			no
10/11/2011	IV Substation	2					2	no
10/10/2011	Fromm CY	2				2		no
10/10/2011	EP359-EP360	2		2				no
10/10/2011	EP355-EP363	2		2				no
10/10/2011	EP301	3		3				no
10/9/2011	S2 Yard	3					3	no
10/9/2011	EP300	6		6				no
10/8/2011	EP357	2			2			no
10/8/2011	EP306	3					3	no
10/7/2011	Dunaway CY	1		1				no
10/7/2011	EP291-EP301	3		3				no
10/6/2011	Fromm CY	2					2	no
10/5/2011	Dunaway CY	2		2				no
10/5/2011	EP303-2	2		2				no
10/4/2011	EP310 & EP311	2		2				no
10/4/2011	EP301	3					3	no
10/4/2011	EP293	2		2				no
10/3/2011	S2 Yard	2					2	no
10/3/2011	Dunaway CY	2			2			no
10/2/2011	EP356-EP363	2		1	1			no
10/1/2011	Plaster City Yard	2					2	no
10/1/2011	EP360	2			2			no
9/30/2011	S2 Yard	2					2	no
9/30/2011	EP355	1		1				no
9/30/2011	EP314	2		2				no
9/30/2011	EP301	2		1	1			no
9/29/2011	EP291/EP292 Pullsite	1				1		no
9/28/2011	EP361	1			1			no
9/27/2011	EP315	2		1	1			no
9/27/2011	EP309	1		1				no
9/27/2011	EP301 & EP304	4		3	1			no
9/27/2011	EP290	1			1			no
9/26/2011	EP362	2			2			no
9/26/2011	Fromm CY	1				1		no
9/25/2011	No ravens observed							
9/24/2011	Plaster City Yard	2					2	no
9/24/2011	EP317	1		1				no
9/24/2011	EP309	1		1				no
9/23/2011	EP362	4			4			no
9/23/2011	EP303	2		2				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
9/22/2011	Fromm CY	1				1		no
9/22/2011	EP303	2		2				no
9/22/2011	EP301	2		2				no
9/22/2011	EP295-EP322	3		3				no
9/21/2011	S2 Yard	3			3			no
9/21/2011	Fromm CY	1					1	no
9/21/2011	EP303	1		1				no
9/20/2011	S2 Yard	2			2			no
9/20/2011	Fromm CY	1				1		no
9/19/2011	S2 Yard	3			3			no
9/19/2011	EP304, EP307, EP309	1		1				no
9/18/2011	S2 Yard	3				3		no
9/18/2011	EP281	1		1				no
9/17/2011	S2 Yard	3					3	no
9/17/2011	EP362	1			1			no
9/17/2011	Fromm CY	3				3		no
9/16/2011	EP363	2			2			no
9/16/2011	Fromm CY	1					1	no
9/16/2011	EP304	2		2				no
9/16/2011	EP290	1		1				no
9/15/2011	S2 Yard	4			4			no
9/15/2011	Fromm CY	3					3	no
9/15/2011	EP296	1		1				no
9/15/2011	EP306	2					2	no
9/15/2011	EP304	1		1				no
9/15/2011	EP301	2		2				no
9/14/2011	Plaster City Yard	1			1			no
9/14/2011	EP361	2			2			no
9/14/2011	Fromm CY	1				1		no
9/14/2011	EP308	1					1	no
9/14/2011	EP301	5		4	1			no
9/14/2011	EP292	3		3				no
9/13/2011	S2 Yard	10			10			no
9/13/2011	EP348	3		3				no
9/13/2011	EP345	2		2				no
9/13/2011	EP326	1					1	no
9/13/2011	EP325	2		2				no
9/13/2011	EP326	1		1				no
9/13/2011	EP304	7		7				no
9/13/2011	EP291	7		7				no
9/12/2011	S2 Yard	3			3			no
9/12/2011	EP350	1		1				no
9/12/2011	EP304	1		1				no
9/12/2011	EP301	1		1				no
9/11/2011	S2 Yard	2				2		no
9/10/2011	S2 Yard	2					2	no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
9/9/2011	EP304	1			1			no
9/8/2011	S2 Yard	3					3	no
9/7/2011	S2 Yard	3					3	no
9/6/2011	No ravens observed							
9/5/2011	No ravens observed							
9/4/2011	No ravens observed							
9/3/2011	No ravens observed							
9/2/2011	EP348	1		1				no
9/2/2011	S2 Yard	1		1				no
9/2/2011	EP303	1		1				no
9/2/2011	EP363	2		2				1 at IV Sub
9/1/2011	EP303	2					2	no
9/1/2011	EP293	1					1	no
9/1/2011	EP304	2					2	no
8/31/2011	S2 Yard	1		1				no
8/31/2011	EP308	1		1				no
8/31/2011	EP305-3	2					2	no
8/31/2011	EP303	2		2				no
8/30/2011	EP303	1		1				no
8/29/2011	S2 Yard	1		1				no
8/29/2011	EP303	1		1				no
8/28/2011	No ravens observed							
8/27/2011	EP305	3			3			no
8/26/2011	EP301	2		2				no
8/25/2011	S2 Yard	2					2	no
8/25/2011	EP301	2		2				no
8/24/2011	S2 Yard	3				3		no
8/23/2011	EP292-1	3		3				no
8/22/2011	No ravens observed							
8/21/2011	No ravens observed							
8/20/2011	S2 Yard	2				2		no
8/20/2011	EP312	2		2				no
8/20/2011	S2 Yard	2					2	no
8/20/2011	EP312	2		2				no
8/19/2011	EP307	2			2			no
8/19/2011	EP296	1		1				no
8/18/2011	S2 Yard	2				1	1	no
8/18/2011	EP301	Flock	x					no
8/17/2011	S2 Yard	2				1	1	no
8/17/2011	EP301	3			3			no
8/16/2011	S2 Yard	1					1	no
8/16/2011	EP301	1		1				no
8/15/2011	No ravens observed							
8/14/2011	No ravens observed							
8/13/2011	S2 Yard	2					2	no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
8/12/2011	IV Substation	2				2		no
8/12/2011	S2 Yard	3				3	3	no
8/11/2011	EP294	4			4			no
8/11/2011	S2 Yard	3				3	3	no
8/10/2011	S2 Yard	3				2	1	no
8/9/2011	S2 Yard	not specified						no
8/8/2011	EP294	2			2			no
8/8/2011	S2 Yard	1						no
8/7/2011	No ravens observed							
8/6/2011	S2 Yard	1						no
8/5/2011	EP301	3		3				no
8/4/2011	S2 Yard	not specified						no
8/3/2011	S2 Yard	2		2				no
8/3/2011	S2 Yard	1						no
8/2/2011	S2 Yard	3					3	no
8/1/2011	EP314	not specified		x				no
7/31/2011	No ravens observed							
7/30/2011	EP314	3		2			1	no
7/30/2011	S2 Yard	1					1	no
7/29/2011	S2 Yard	1						no
7/28/2011	EP319	4	1	2	1			no
7/28/2011	S2 Yard	not specified						no
7/27/2011	S2 Yard	not specified						no
7/26/2011	No ravens observed							
7/25/2011	EP290	1			1			no
7/24/2011	No ravens observed							
7/23/2011	No ravens observed							
7/22/2011	EP290	2		1	1			no
7/21/2011	S2 Yard	1		1				no
7/20/2011	Ocotillo, CA	5						no
7/19/2011	Ocotillo, CA	1						no
7/18/2011	CP40-2	not specified						no
7/18/2011	CP41-2	not specified						no
7/18/2011	CP42-1	not specified						no
7/17/2011	No ravens observed							
7/16/2011	CP42-1	not specified						no
7/15/2011	No ravens observed							
7/14/2011	EP357	not specified						no
7/14/2011	EP358	not specified						no
7/14/2011	EP359	not specified						no
7/14/2011	Plaster City Yard	2		2				no
7/13/2011	EP313-EP314 PS	not specified						no
7/13/2011	S2 Yard	3					3	no
7/12/2011	CP18-1	not specified						no
7/12/2011	CP19-1	not specified						no
7/12/2011	CP22-1	not specified						no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
7/11/2011	EP304-EP314	not specified						no
7/10/2011			No ravens observed					
7/9/2011	EP351	not specified						no
7/9/2011	EP353	not specified						no
7/9/2011	EP354	not specified						no
7/9/2011	EP355	not specified						no
7/9/2011	not specified	not specified						no
7/9/2011	S2 Yard	3					3	no
7/8/2011	EP303	2			1		1	no
7/8/2011	EP303	1		1				no
7/8/2011	S2 Yard	3					3	no
7/1/11 - 7/7/11			No ravens observed					
6/30/2011	EP300	3		3				no
6/21/11 - 6/29/11			No ravens observed					
6/20/2011	S2 Yard	2					2	no
6/1/11 - 6/19/11			No ravens observed					
5/1/11 - 5/31/11			No ravens observed					
4/22/11 - 4/30/11			No ravens observed					
4/21/2011	EP341	1	1					no
4/1/11 - 4/20/11			No ravens observed					
3/1/11 - 3/31/11			No ravens observed					
2/1/11 - 2/28/11			No ravens observed					
1/21/11 - 1/31/11			No ravens observed					
1/21/2011	Rough Acres Yard	not specified						no