



This report provides a summary of environmental monitoring and compliance activities conducted by Burns and McDonnell (BMcD) staff and BMcD subconsultants for the San Diego Gas & Electric (SDG&E) Sunrise Powerlink Project during the above weekly time period.

### **Training**

- SWEAP training continued for new Project personnel every Tuesday and Thursday. Additional trainings were provided as requested.
- Flat-tailed horned lizard (FTHL) trainings were provided to any new crew members or monitors prior to construction per mitigation measure B-7b and in accordance with the FTHL Rangewide Management Strategy. During morning tailboard meetings, guidelines were provided about recognizing, protecting, and notification requirements for FTHL. FTHL information cards were made available to any crew members or monitors as needed.
- Barefoot banded gecko (BBG) trainings were provided to crews prior to pre-construction activities pursuant to the California Department of Fish and Game (CDFG) 2081 Incidental Take Permit requirements.
- Emergency Action/Fire Prevention training occurred on November 10, 2011.
- Environmental Peninsular bighorn sheep (PBS) re-training was held on November 9, 2011, for all crew members and project personnel. PBS training will continue to be given every Tuesday and Thursday as part of the SWEAP Training.

### **Pre/Post Construction**

- Staked, flagged, and refreshed work areas from CP53-1 to CP54-1, access road to pull site near CP55, EP23-2 to E25-2, EP42 to EP43-1, EP50 to EP51-1, EP54-1 to EP56-4, EP58-2 to EP62A-1, EP79, EP84 to EP85-2, EP197-3 to EP198-3, EP259B to EP261-2, Fromm Property, and Gorka Property.
- Post construction impact survey at EP206-1, EP290, EP291-1, EP307-1, EP310, EP312, EP314, EP316-2, EP318-1, EP319, EP320-1, and EP321-1.
- The ESA Team conducted the following activities during this reporting period:
  - Installed project signs and ESAs at JVR Yard, AER Yard, El Monte Yard, Sycamore Canyon Yard, CP71, CP106-1-E between CP107 to CP106-1, EP31-2 pull site, EP170 pull site, and EP187-1.
  - Repaired, refreshed, and maintained the previously installed project signs and ESAs at/from EP172 to EP205 along McCain Valley Road, EP324, EP326, and EP327-N.

### **Construction**

- Monitors were present during construction activities to ensure compliance with mitigation measures as identified in the Final EIR/EIS Mitigation Monitoring, Compliance, and Reporting Program. Archaeologists, Paleontologists, and Native American Monitors were present at sites where required as identified prior to construction activity and as approved in the NTPs. On average, the following number of monitors were on the Project throughout the week:
  - 9 Archaeological Monitors.
  - 128 Biological Monitors.
  - 10 Native American Monitors.



**Sunrise Powerlink Project**  
**Weekly Report 60 – November 06, 2011 through November 12, 2011**



- 1 Paleontological monitors.
- 8 SWPPP Monitors.
- Project staff carpooled to site reviews, kick-off tailgates, and off-site meetings. Construction and traffic control crews were observed carpooling from yards to work areas.
- Deterrents were utilized to discourage bird nest building activities throughout the Project. Deterrents are determined depending upon the location and type of possible nesting areas and may include metallic flagging, compact discs, plastic owls, and the presence of biological monitors.

The table below demonstrates the construction progress to date:

OVERHEAD					
Agency	Foundations Completed	Towers Erected	Wire Installed		
Non-Federal	102 of 169	47 of 169	14 of 169 EP89-1 to EP91		
Bureau of Land Management	116 of 179	83 of 179	58 of 179 EP301 to EP313		
Miramar	3 of 12	3 of 12	0 of 12		
US Forest Service	17 of 76	0 of 76	0 of 76		
UNDERGROUND					
Agency	Vaults Installed	Trenches Excavated & Backfilled			
Non-Federal	40 of 40	38 of 42			
SUBSTATION UPGRADES					
2 of 7 Completed					
SUNCREST SUBSTATION					
72 Percent Complete					



### Overhead Construction

- Link 1

- Vegetation clearing at EP170, EP170 pull site, EP174, EP175, EP176, EP177, EP219-GS-NS-32, and EP243/EP244 pull site.
- Boulder removal at EP254-3.
- Topsoil salvage at EP243/EP244 pull site.
- Access road maintenance at EP173-1-N.
- Grading at EP170, EP170 pull site, EP177, EP177-N, and EP243/EP244 pull site.
- Driveway installation at EP206-1, EP207, EP208, and EP227-E-A.
- Micropile drilling at EP252A-1.
- Micropile trimming at EP261A, EP261-2, EP262-4, and EP263B-2.
- Proof testing at EP262-4 and EP263B-2.
- Micropile cap work at EP254-3, EP259B-2, EP259-3, EP262-4, EP264-4, EP265-2, EP266, EP267-2, EP271-2, EP276-1, EP277-1, and EP281.
- Soil boring at EP170.
- Conventional drilling at EP170, EP173-1, EP174, EP175, EP192, and EP199-3.
- Various foundation work (capping, cage installation, grounding, etc.) at EP173-1, EP174, EP175, and EP199-3.
- Concrete pouring at EP175 and EP199-3.
- Ground compaction testing at EP215.
- Tower assembly at EP178, EP198-3, EP200-3, EP202-3, EP240, EP242, EP279-1, EP280-2, and EP290.
- Miscellaneous assembly work (perch deterrents, anti-climb guards) at EP357 and from EP359 to EP363.
- QA/QC at EP200-3, EP255, EP274, EP279, and EP290.
- Pulled sock line for optical ground wire (OPGW), sagged, and clipped in from EP301 to EP313/EP314 pull site.
- Sagging and clipping in from EP301 to EP313.
- Splicing at EP355.
- Sleeving at EP306, EP307, and EP313/EP314 pull site.
- Insulator work at/between EP301, EP303-2 and EP304-2.
- Jumpers installed at EP304.
- Spacers installed from EP301 to EP314.
- Guard structure installation prep at EP219-1, EP219/220 pull site, EP220-1, and EP243/EP244 pull site.
- Guard structure installation at EP219-1 and EP219/220 pull site.
- Guard structure removal at EP215.
- Dead-end work at EP215, EP219, EP301, EP303-2, and EP304-2.
- BMPs installed at:
  - EP170-N, EP170 pull site, EP177, EP219-1, EP219-GS-NS-32, and EP243/EP244 pull site.
- BMPs maintained at/from:
  - EP170, EP170-N, EP175 to EP203, and EP255.
- Hydromulching at EP215 and EP219-1.
- Trained FTHL monitors, BBG monitors, BHS monitors, and Visible Emission Evaluators (VEEs) were onsite as required.



- Link 2
  - During this reporting period, the PAL Levels were as follows: Monday-B, Tuesday-C, Wednesday-D, Thursday-D, Friday-C, and Saturday-B. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

#### USFS Land

- Access road construction at:
  - EP105-2-E-A, EP105-2-E-B, EP125-N, EP126-1-N, EP127-N, EP130-1-N, EP131-N, EP140-1-N, EP141-N, and La Posta Road from pavement to EP141.
- Vegetation clearing at EP105-2-E-A, EP105-2-E-B, EP2-3 TSAP, EP3-3 TSAP, EP4-3 TSAP, EP5-2 TSAP, EP6-1 TSAP, EP7-1 TSAP, EP8-2 TSAP, EP10-2, EP13-3 TSAP, EP24-1, EP24-1 TSAP, EP57-2, EP57-2 TSAP, EP58-2, EP58-2 TSAP, EP111-4, EP112A, EP114, EP115, EP117-2, and EP118-2.
- Grading at EP2-3, EP2-3 TSAP, EP3-3, EP3-3 TSAP, EP4-3, EP4-3 TSAP, EP5-2, EP5-2 TSAP, EP6-1, EP6-1 TSAP, EP7-1, EP7-1 TSAP, EP8-2, EP8-2 TSAP, EP10-2, EP10-2 TSAP, EP13-3, and EP13-3 TSAP.
- Tree trimming at EP10-2, EP11-3, EP13-3, EP14-1, and EP130-1.
- Micropile drilling at EP2-3 and EP4-3.
- Various micropile work (capping, pile surveys, site benching, etc.) at EP2-3, EP3-3, EP4-3, EP6-1, EP132-2, EP135, and EP140-1.
- Micropile test pull at EP132-2, EP134-1, EP135, EP136, EP137, EP138-2, EP139, and EP140-1.
- Micropile trimming at EP132-2, EP134-1, EP135, EP136, EP137, EP138-2, EP139, and EP140-1.
- Concrete poured at EP126-1 and EP130-1.
- Set rebar cages and installed forms at EP126-1.
- Demobilized equipment at EP134-1, EP135, EP136, and EP137.
- Form removal and cleanup at EP126-1 and EP130-1.
- Tower assembly at EP131 and EP141.
- Gate/Fence installation at EP129-E-A, EP131, and EP141.
- BMP installation at:
  - EP34-1, EP105-2-E-A, EP105-2-E-B, EP125-N, EP126-1, EP126-1-N, EP127-N, EP130-1-N, EP131-N, EP140-1-N, EP141-N, and La Posta Road from pavement to EP141.

#### BLM Land

- Access road construction at:
  - EP39-1-N-B and EP42-N.
- Grading at EP47-2 pull site.
- Conventional drilling at EP39-1.
- Various micropile work (capping, pile surveys, site benching, etc.) at EP43-1, EP44, EP45-1, and EP47-2.
- Micropile trimming at EP47-2.
- Concrete poured at EP42.
- Grouting at EP47-2.
- Tower assembly at EP42, EP43-1, and EP44.
- Arroyo toad fencing installed along EP67-E and EP67-N.
- BMP installation at:



- EP47-2 pull site, EP47-2-PS-N, EP47-2-PS-E, EP49-E, EP50-E, EP51-1-E, EP52-1-E, EP53-3-E-A, EP53-3-E-B, EP51-1, EP69, EP71, EP72, EP73, and EP74-1.
- Hydromulching at EP47 pull site.

#### Non-Federal Land

- Access road construction at:
  - EP103-2-N, EP105-2-E-A, and EP105-2-E-B.
- Vegetation clearing at EP85-2-E, EP89 pull sites, EP91 pull site, EP92, EP93, EP104-2, EP105-2, EP105-2-E-A, and EP105-2-E-B.
- Grading at EP89 pull sites EP91 pull site.
- Guard structure installation at EP89.
- BMP  
installation at:
  - EP84, EP85-2-E, EP89, EP89 pull sites, EP91, EP91 pull site, EP103-2-N, EP105-2-E-A, and EP105-2-E-B.

#### Link 5

- During this reporting period, the PAL Levels were as follows: Monday-B, Tuesday-C, Wednesday-D, Thursday-D, Friday-C, and Saturday-B. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

#### USFS Land

- Vegetation removal at CP99-2 and CP100-1.
- Tree trimming at CP104-1 and CP105-1.
- Access road construction at:
  - CP100-1-N.
- Conventional drilling at CP69-2.
- Various micropile work (capping, pile surveys, site benching, etc.) at CP101-1, CP103-3, CP104-1, and CP105-1.
- Concrete poured at CP100-1.
- Form clean up at CP100-1.
- Tower assembly at CP101-1.
- QA/QC at CP101-1, CP103-3, CP104-1, and CP105-1.
- BMP installation at:
  - CP69-2 and CP100-1-N.
- Hydromulching at CP100-1-N.

#### BLM Land

- Various micropile work (capping, pile surveys, site benching, etc.) at CP65-1 and CP67-3.
- Micropile drilling at CP58-1 and CP62A.
- Ground resistance testing at CP66-2 and CP68-1.
- Tower assembly at CP65-1 and CP67-3.

#### Non-Federal Land



**Sunrise Powerlink Project**  
**Weekly Report 60 – November 06, 2011 through November 12, 2011**



- Vegetation removal at CP31-2 pull site, CP31-2-E, CP31-2-N, CP31-2-PS-E, CP55/CP56-1 pull site, and CP56-1-E-A.
  - Grading at CP31-2 pull site, CP48-2/CP49-1 pull site, and CP55/CP56-1 pull site.
  - Access road construction at:
    - CP31-2-E, CP31-2-N, CP31-2-PS-E, CP49-1-PS-E, CP49-1-PS-N, CP56-1-E-A, CP64-2-E, and CP65-1-PS-N, CP98-N-B, and CP99-N.
  - Dexpan boulder breaking at CP55/CP56-1 pull site, CP56-1-E-A, CP80-2, and CP81-1.
  - Blasting at CP98.
  - Various micropile work (capping, pile surveys, site benching, etc.) at CP71, CP106-1, CP107, and CP109-1.
  - Grouting at CP75-1.
  - Conventional drilling at CP70-3.
  - Micropile drilling at CP56-1, CP62A, CP78-2, and CP79-1.
  - Install ground rods at CP24-1, CP25-2, and CP26.
  - Ground resistance testing at CP73-2 and CP75-1.
  - Tower assembly at CP71, CP72-2, CP74-2, CP87-1, CP88-1, CP108, and CP109-1.
  - BMP installation at:
    - CP31-2 pull site, CP31-2-E, CP31-2-N, CP31-2-PS-E, CP49-1-PS-E, CP49-1-PS-N, CP48-2/CP49-1 pull site, CP55/CP56-1 pull site, CP56-1, CP56-1-E-A, CP98-1-N-A, CP98-N-B, and CP99-N.
  - Hydromulching at CP98-1-N-A, CP98-N-B and CP99-N.
- 
- TL6920 Sycamore Substation removed old wire and installed new wire.

69kV

#### Underground Construction (Link 4)

- Revitalization near South Grade Road.
- Trenching at Viejas Creek Bridge.
- Pre-drilling/Drilling at Alpine Creek Bore.
- Pre-racking/Racking and cleaning manholes for ABB (and jointing/splicing) at V1L, V3L, V10L, V20L, V7R, V12R, and V18R.
- Proofing from V1L to riser pole, V1R to riser pole, Viejas Creek Bridge (south side), and V18R to V19R.
- Cable pulling from V1R to V2R, V18L to V19L, and V20.
- Erecting scaffolding at EP95 and Loritz Property.
- Terminating riser pole at Loritz.
- Forming at Viejas Creek Bridge and riser pole at Slay Property.

#### Suncrest Substation Construction (Link 3)

- Crushing rock for select fill material.
- Steel erection in the northwest and southwest quadrants of the pad.
- Culvert installation east of the guard shack.
- Forming pads for foundations and pouring concrete.
- Trenching for conduit and ground grid in the southwest quadrant.
- Grading Class 2 base on the access roads leading to the northern and southern detention basins.
- Transformer assembly.
- BMP maintenance and installation along Bell Bluff Truck Trail and on the substation pad.
- Installation of gravel/geotextile filter in southern sediment basin.
- Paving access roads to northern and southern detention basins.
- Placing blocks and grouting for control shelter.



- Finish grading access road to the northern and southern basins.

#### Substation Upgrades

- Encina Switchyard
  - SDG&E Kearny Mesa crews worked on disconnects in Bays 2 through 5.
  - Roel excavated new containment basin around transformer installed on east side of control house.
  - Chula Vista Electric installed conduit in and around control house.
- Imperial Valley (IV)
  - SDG&E ETRAM crew staged equipment in the northwest corner of the substation.
  - SDG&E worked in Bay 4 and erected steel frames and bus supports.
  - Roel finished pads in Bay 4.
  - PRAVA worked inside new storage warehouse.
- San Luis Rey
  - Wiring on new TBEA bank 70, 230 kV transformer.
- Sycamore Canyon
  - SDG&E crews worked on wiring inside the control house.
- Scripps
  - No Sunrise-related work.

#### Construction Yards

- AER Yard – Materials staging.
- Alpine Yard – Materials staging and weed wash station.
- Bartlett-Hauser Yard – Water staging, helicopter operations, material delivery, and weed wash station.
- Barrett Canyon Yard – Grading access road, drilling, and grading tower pull site.
- Dunaway Yard – No activity.
- Fromm Yard – Tower assembly, water staging, dust suppression, and helicopter operations.
- El Monte Yard – Crew staging, equipment and materials staging, and helicopter operations.
- Helix Yard – Helicopter operations, equipment and materials staging, concrete and crew staging, weed wash station, and water staging.
- Imperial Valley Yard – No activity.
- Jacumba Valley Ranch (JVR) Yard – Helicopter operations, weed wash station, water and equipment staging, materials and concrete staging, crew staging, dust suppression, tower assembly, and hub for coordination of activities within PBHS areas.
- Kreutzkamp Yard – Tower assembly, weed wash station, water staging, and dust suppression.
- McCain Valley Yard – Tower assembly, helicopter operations, water staging, dust suppression, and collecting woody debris and chipping.
- Plaster City Yard – Helicopter operations, staging for wire/line stringing, water staging, and dust suppression.
- Rough Acres Yard – Helicopter operations, materials staging, tower assembly, water staging, dust suppression, and weed wash station.
- S2 Yard – Equipment and materials staging, crew staging, helicopter operations, water staging, dust suppression, and hub for coordination of activities within PBHS areas.
- SWAT Yard – Tower assembly, concrete staging, water staging, helicopter operations, dust



**Sunrise Powerlink Project**  
**Weekly Report 60 – November 06, 2011 through November 12, 2011**



suppression, and weed wash station.

- Sycamore Yard – Tower assembly, weed wash station, dust suppression, helicopter operations, and water staging.
- Thing Valley Yard – Staging for La Posta Road work and steel delivery.
- Wilson Yard – Staging materials for Suncrest Substation, helicopter operations, dust suppression, water staging, and tower assembly.

### **Wildlife Reporting**

- Peninsular bighorn sheep (PBS) were reported in Mountain Springs Grade on November 7 & 8, 2011.

The following listed or Species of Special Concern were found dead in Project construction limits during this reporting period:

- Silvery Legless Lizard (*Anniella pulchra pulchra*) – Twelve (12) silvery legless lizards were found dead; two (2) at EP105-2, one (1) at EP177, one (1) at EP103-2, five (5) at EP104, one (1) at EP141 pull site, one (1) at EP206, and one (1) at EP243/EP244 pull site.
- Coronado Skink (*Eumeces skiltonianus interparietalis*) – One (1) Coronado skink was found dead at EP6.

The following listed or Species of Special Concern were relocated during construction activities this reporting period:

- Coronado Skink (*Eumeces skiltonianus interparietalis*) – One (1) Coronado skink was relocated from EP104.
- Silvery Legless Lizard (*Anniella pulchra pulchra*) – Thirteen (13) silvery legless lizards were relocated; seven (7) from EP105-2, three (3) from EP104, one (1) from EP177, one (1) from EP3, and one (1) from Thing Valley Yard.
- San Diego Ring-necked Snake (*Diadophis punctatus similis*) – One (1) San Diego ring-necked snake was relocated from EP104.
- Rosy Boa (*Lichanura trivirgata*) – Two (2) rosy boas were relocated from EP3.

### **Spills/Hazardous Waste**

- No reportable spills occurred during this reporting period.

### **Customer Complaints**

- No customer complaints were received during this reporting period.

### **Non-Compliances**

- No non-compliances were received during this reporting period.

### **Variances and TEWS**

- TEWS #31 was approved for parking and turnaround at EP252A-1 and EP254-3-E.

### **Weather**

- Rain events occurred on November 7, 2011, and November 12, 2011.
  - Post-storm totals for November 7, 2011:



**Sunrise Powerlink Project**  
**Weekly Report 60 – November 06, 2011 through November 12, 2011**



- EP170 to EP207 – 1.00 inches
  - EP208 to EP220 – 1.15 inches
  - EP221-2 to EP238 – 0.65 inches
  - EP239 to EP254 – 0.65 inches
  - EP255 to EP281 – 0.50 inches
  - EP101 to EP119, EP125 to EP141, La Posta Road and Thing Valley Yard – 1.45 inches
  - EP2 to EP72 – 2.10 inches
  - EP73 to EP93 – 2.3 inches
  - SWAT Yard – 2.10 inches
  - Kreutzkamp Yard – 1.80 inches
  - Bartlett Yard – 2.30 inches
  - Suncrest and Wilson Yard – 2.15 inches
  - Alpine Office, Alpine Yard, and Link 4 – 2.20 inches
  - CP101 to CP109 – 2.10 inches
  - CP98 to EP100 – 2.10 inches
- 
- BMPs were installed or maintained as needed throughout Project areas. In accordance with the Construction General Permit (CGP), daily site BMP inspections, photos, and appropriate BMPs for stormwater and non-stormwater were implemented. In accordance with the CGP, a post-storm inspection was performed as a result of the qualifying rain events. Failures and shortcomings that were identified in the post-storm inspection have been assessed and repairs/design changes to the BMPs will begin within 72 hours of identification.



**Sunrise Powerlink Project**  
**Weekly Report 60 – November 06, 2011 through November 12, 2011**



S2 Yard. *Photo courtesy of Kham Slater.*

# **Appendices**

Peninsular Big Horn Sheep Monitoring Report

Flat-Tailed Horned Lizard Monitoring Report

Raven Control monitoring Report

Flat Tailed Horned Lizard Counts - Week Ending 11/12/2011									
Date	Location	Observed		Injured		Relocated		Dead	
	Post RCLMP*	Day	Night	Day	Night	Day	Night	Day	Night
11/1/2011	Dunaway CY					1			
10/13/2011	AR to EP354							1	
9/20/2011	AR btwn EP357 and EP358							1	
9/19/2011	AR btwn EP352 and EP353	1							
9/12/2011	EP325					1			
9/9/2011	AR to EP363	1							
9/6/2011	AR to EP360/361					1			
9/6/2011	EP360					2			
9/6/2011	EP359					1			
9/3/2011	SWPL AR to EP324					1			
9/3/2011	SWPL AR to EP342					1			
9/3/2011	SWPL AR to EP345							1	
9/3/2011	SWPL AR to EP344 and EP345					1			
8/31/2011	EP324					1			
8/31/2011	SWPL AR to EP325-2					1			
8/30/2011	SWPL AR to EP346 and EP347					1			
8/29/2011	SWPL AR to EP353 and EP354							1	
8/29/2011	SWPL AR to EP324							1	
8/27/2011	EP349					1			
8/25/2011	EP360							1	
8/25/2011	Btwn EP320/321					1			
8/24/2011	SWPL AR near EP346					1			
8/23/2011	EP349					1			
8/21/2011	SWPL AR btwn EP344/345					1			
8/21/2011	SWPL AR to EP345							1	
8/19/2011	SWPL AR to EP339					1			
8/20/2011	SWPL AR to IV Sub							1	
8/20/2011	SWPL AR btwn EP346/347					1			
8/19/2011	EP338/339 Pullsite					1			
8/19/2011	EP355/356 Pullsite					1			
8/18/2011	EP347					1			
8/18/2011	SWPL AR to EP353							1	
8/11/2011	SWPL AR by EP348					1			
8/11/2011	EP348/EP349 Pullsite					1			
8/10/2011	EP347					1			
8/8/2011	SWPL AR to EP351					2			
8/6/2011	BLM AR near EP327							1	
8/1/2011	IV Substation Yard	1							
8/1/2011	EP325					1			
8/1/2011	AR to EP345					1			
7/30/2011	EP322					1			
7/28/2011	EP355/EP356 Pullsite					1			
7/27/2011	Near EP316-2	1							

Flat Tailed Horned Lizard Counts - Week Ending 11/12/2011									
Date	Location	Observed		Injured		Relocated		Dead	
7/26/2011	SWPL AR to EP344	1							
	Post RCLMP*	Day	Night	Day	Night	Day	Night	Day	Night
7/26/2011	EP347					1			
7/26/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/22/2011	AR to IV Sub					1			
7/21/2011	EP360					1			
7/21/2011	AR to EP326					1			
7/19/2011	SWPL AR to IV Sub	1							
7/19/2011	EP353					1			
7/19/2011	AR to Dunaway CY					1			
7/18/2011	EP318					1			
7/17/2011	EP355					1			
7/15/2011	EP359	1							
7/15/2011	EP352	1							
7/15/2011	EP350	1							
7/14/2011	Spur Rd to EP355							1	
7/14/2011	EP322	1							
7/13/2011	EP357	1							
7/12/2011	EP344	1							
7/12/2011	SWPL AR btwn EP348/345							1	
TOTAL POST RCLMP		12	0	0	0	43	0	12	
Prior to RCLMP		Day		Day		Day		Day	
7/11/2011	AR to EP352					2			
7/11/2011	AR to EP345					2			
7/10/2011	EP358					1			
7/10/2011	SWPL AR to EP354					2			
7/9/2011	AR to EP330	1							
7/8/2011	Spur Rd. to EP352	1							
7/7/2011	EP324					1			
7/7/2011	EP355					1			
7/6/2011	SWPL AR btwn EP362/363							1	
7/5/2011	EP354					1			
7/1/2011	AR to EP353	1							
6/30/2011	AR between EP310/311							1	
6/30/2011	EP358	1							
6/30/2011	EP360	1							
6/30/2011	AR to EP312							1	
6/30/2011	EP360							1	
6/27/2011	EP350					1			
6/27/2011	SWPL AR to IV Substation	2							
6/26/2011	IV Substation					1			

Flat Tailed Horned Lizard Counts - Week Ending 11/12/2011					
Date	Location	Observed	Injured	Relocated	Dead
6/25/2011	SWPL AR to EP361	1			
6/24/2011	EP359			1	
6/23/2011	SWPL AR to EP360			2	
6/22/2011	SWPL AR to EP355			1	
6/20/2011	EP356	2			
6/20/2011	SWPL AR to EP359	1			
6/20/2011	Near EP356	2			
6/20/2011	AR between EP358/357				1
6/18/2011	AR to Dunaway CY				1
6/17/2011	Near EP322	1			
6/7/2011	Near EP355	1			
6/7/2011	EP361			1	
6/7/2011	AR btwn EP343/EP344				1
6/7/2011	AR between EP324/325				1
6/6/2011	SWPL AR btwn EP344/EP345			1	
6/3/2011	EP359			1	
6/3/2011	SWPL AR EP362			1	
6/2/2011	AR to EP358			1	
6/2/2011	SWPL AR to EP316-2				1
6/2/2011	AR east of EP325				1
6/1/2011	SWPL AR btwn EP319/EP320			1	
6/1/2011	SWPL AR to EP318			1	
5/31/2011	SWPL AR btwn EP359/EP360			1	
5/31/2011	SWPL AR to EP320			1	
5/31/2011	EP360				1
5/27/2011	EP357			1	
5/26/2011	SWPL AR to EP359			1	
5/25/2011	Spur Rd to EP321			1	
5/23/2011	EP323			1	
5/21/2011	EP324			1	
5/20/2011	IV CY			1	
5/20/2011	AR to EP362			1	
5/20/2011	AR btwn EP324/EP325			1	
5/20/2011	SWPL AR btwn EP326/EP327			1	
5/20/2011	IV Substation			3	
5/19/2011	IV Substation			5	
5/19/2011	EP324			1	
5/18/2011	IV Substation Yard			1	
5/18/2011	IV Substation Yard				1
5/17/2011	AR to IV Substation				1
5/16/2011	IV Substation Yard			1	
5/13/2011	SWPL AR Near EP362-1	1			
5/12/2011	AR to EP355			1	
5/11/2011	EP360	1			

Flat Tailed Horned Lizard Counts - Week Ending 11/12/2011					
Date	Location	Observed	Injured	Relocated	Dead
5/11/2011	Dunaway CY	3			
5/11/2011	Dunaway Yard			4	
5/10/2011	EP322	1			
5/10/2011	AR to Dunaway CY	1			
5/9/2011	Dunaway Yard			4	
5/7/2011	EP322	1			
5/7/2011	Spur Road to EP344	1			
5/7/2011	Dunaway Yard			1	
5/6/2011	AR to EP321-1	1			
5/5/2011	AR to EP321-1	1			
5/5/2011	AR to Dunaway CY	2			
5/5/2011	Dunaway Yard			2	
5/4/2011	AR btwn EP343/EP344			1	
5/3/2011	SWPL AR btwn EP320/EP321	1			
4/27/2011	AR to EP322	2			
4/26/2011	EP322	1			
4/25/2011	Plaster City CY	1			
4/20/2011	Plaster City			1	
4/18/2011	Plaster City			1	
4/14/2011	AR to IV Substation	1			
4/2/2011	Dunaway CY	1			
<b>TOTAL PRIOR TO RCLMP</b>		<b>35</b>	<b>0</b>	<b>60</b>	<b>13</b>
<b>YTD</b>		<b>47</b>	<b>0</b>	<b>103</b>	<b>25</b>

\*RCLMP refers to the Revised Construction Lighting Mitigation Plan

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
11/12/2011	EP300-EP312	0	Site clearance survey
11/12/2011	EP300-EP312	0	Monitoring construction activities
11/12/2011	EP269-EP281	0	Site clearance survey
11/12/2011	EP269-EP281	0	Monitoring construction activities
11/12/2011	EP263B-2	0	Monitoring construction activities
11/12/2011	EP274-EP278	0	Site clearance survey
11/12/2011	EP274-EP278	0	Monitoring construction activities
11/12/2011	EP269-EP281	0	Site clearance survey
11/12/2011	EP269-EP281	0	Monitoring construction activities
11/11/2011	EP306-EP312	0	Site clearance survey
11/11/2011	EP300-EP312	0	Monitoring construction activities
11/11/2011	EP269-EP281	0	Site clearance survey
11/11/2011	EP269-EP281	0	Monitoring construction activities
11/11/2011	EP269-EP273	0	Site clearance survey
11/11/2011	EP269-EP270	0	Site clearance survey
11/11/2011	EP269-EP270	0	Monitoring construction activities
11/11/2011	EP263B-EP267	0	Site clearance survey
11/11/2011	EP263B-EP267	0	Monitoring construction activities
11/11/2011	EP274-EP278	0	Site clearance survey
11/11/2011	EP274-EP278	0	Monitoring construction activities
11/11/2011	EP269-EP281	0	Site clearance survey
11/11/2011	EP269-EP281	0	Monitoring construction activities
11/10/2011	EP306-EP312	0	Site clearance survey
11/10/2011	EP269-EP273	0	Site clearance survey
11/10/2011	EP269-EP281	0	Site clearance survey
11/10/2011	EP269-EP281	0	Monitoring construction activities
11/10/2011	EP269-EP270	0	Site clearance survey
11/10/2011	EP269-EP270	0	Monitoring construction activities
11/10/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/10/2011	EP274-EP278	0	Site clearance survey
11/10/2011	EP274-EP278	0	Monitoring construction activities
11/9/2011	Fromm CY	0	Monitoring construction activities
11/9/2011	EP313/EP314 Pullsite	0	Monitoring construction activities
11/9/2011	EP306-EP312	0	Site clearance survey
11/9/2011	EP306	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
11/9/2011	EP269-EP273	0	Site clearance survey
11/9/2011	EP269-EP281	0	Site clearance survey
11/9/2011	EP269-EP281	0	Monitoring construction activities
11/9/2011	EP265-2	0	Site clearance survey
11/9/2011	EP265-2	0	Monitoring construction activities
11/9/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/9/2011	EP274-EP278	0	Site clearance survey
11/9/2011	EP274-EP278	0	Monitoring construction activities
11/9/2011	EP263B-EP267, EP269-EP281	0	Site clearance survey
11/9/2011	EP263B-EP267, EP269-EP281	0	Monitoring construction activities
11/8/2011	EP306-EP312	0	Site clearance survey
11/8/2011	EP300-EP312	0	Site clearance survey
11/8/2011	EP300-EP312	0	Monitoring construction activities
11/8/2011	EP280	0	Monitoring construction activities
11/8/2011	EP272-EP275	0	Site clearance survey
11/8/2011	EP272-EP275	5	Monitoring construction activities
11/8/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/8/2011	EP279-EP294	0	Site clearance survey
11/8/2011	EP279-EP294	0	Monitoring construction activities
11/8/2011	EP274-EP278	0	Site clearance survey
11/8/2011	EP274-EP278	0	Monitoring construction activities
11/8/2011	EP269-EP281	0	Site clearance survey
11/8/2011	EP269-EP281	0	Monitoring construction activities
11/8/2011	EP263B-EP267, EP269-EP281	0	Site clearance survey
11/8/2011	EP263B-EP267, EP269-EP281	0	Monitoring construction activities
11/8/2011	Devils Cyn Bridge	5	Monitoring construction activities
11/7/2011	EP307-EP308	0	Monitoring construction activities
11/7/2011	EP300-EP312	0	Site clearance survey
11/7/2011	EP300-EP312	0	Monitoring construction activities
11/7/2011	EP280	0	Monitoring construction activities
11/7/2011	EP271-EP274	3	Site clearance survey
11/7/2011	EP271-EP274	0	Site clearance survey
11/7/2011	EP271-EP274	5	Site clearance survey
11/7/2011	EP271-EP274	0	Monitoring construction activities
11/7/2011	EP269-EP271	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
11/7/2011	EP269-EP271	0	Monitoring construction activities
11/7/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/7/2011	EP278-EP281	0	Site clearance survey
11/7/2011	EP274-EP278	0	Site clearance survey
11/7/2011	EP274-EP278	0	Monitoring construction activities
11/7/2011	EP269-EP281	0	Site clearance survey
11/7/2011	EP269-EP281	0	Monitoring construction activities
11/7/2011	EP263B-EP267	0	Site clearance survey
11/7/2011	EP263B-EP267	0	Monitoring construction activities
11/6/2011	EP308-EP310	0	Monitoring construction activities
11/6/2011	EP303-2, EP302-1	0	Monitoring construction activities
11/6/2011	EP300-EP312	0	Site clearance survey
11/6/2011	EP300-EP312	0	Monitoring construction activities
11/6/2011	EP300-EP312	0	Site clearance survey
11/6/2011	EP300-EP312	0	Monitoring construction activities
11/6/2011	EP290-EP312, EP269-EP281	0	Site clearance survey
11/6/2011	EP290-EP312, EP269-EP281	0	Monitoring construction activities
11/6/2011	EP279-1	0	Monitoring construction activities
11/6/2011	EP269-EP281	0	Site clearance survey
11/6/2011	EP269-EP281	0	Monitoring construction activities
11/6/2011	EP274-EP278	0	Monitoring construction activities
11/6/2011	EP274-EP278	0	Site clearance survey
11/6/2011	EP269-EP281	0	Monitoring construction activities
11/6/2011	EP269-EP281	0	site clearance survey
11/5/2011	EP300-EP312	0	Site clearance survey
11/5/2011	EP300-EP312	0	Monitoring construction activities
11/5/2011	EP271-2, EP272-3, EP276-1 & EP281	0	Monitoring construction activities
11/5/2011	EP269-EP273	0	Site clearance survey
11/5/2011	EP265-2	0	Monitoring construction activities
11/5/2011	EP256-EP263A	0	Site clearance survey
11/5/2011	EP279-EP294	0	Site clearance survey
11/5/2011	EP279-EP294	0	Monitoring construction activities
11/5/2011	EP277-1	0	Monitoring construction activities
11/5/2011	EP263B-EP267	0	Site clearance survey
11/5/2011	EP263B-EP267	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
11/4/2011	S2 CY	0	Monitoring construction activities
11/4/2011	EP311, EP310	0	Monitoring construction activities
11/4/2011	EP307	0	Monitoring construction activities
11/4/2011	EP306/EP307 Pullsite	0	Monitoring construction activities
11/4/2011	EP300-EP312	0	Site clearance survey
11/4/2011	EP300-EP312	0	Monitoring construction activities
11/4/2011	EP269-EP273	0	Site clearance survey
11/4/2011	EP269-EP271	0	Site clearance survey
11/4/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/4/2011	EP279-EP294	0	Site clearance survey
11/4/2011	EP279-EP294	0	Monitoring construction activities
11/4/2011	EP274-EP278	0	Site clearance survey
11/4/2011	EP274-EP278	0	Monitoring construction activities
11/4/2011	EP263B-EP267	0	Site clearance survey
11/4/2011	EP263B-EP267	0	Monitoring construction activities
11/3/2011	EP311	0	Monitoring construction activities
11/3/2011	EP307	0	Monitoring construction activities
11/3/2011	EP280	0	Monitoring construction activities
11/3/2011	EP279-1	0	Monitoring construction activities
11/3/2011	EP278-1, EP279-1, EP280-1	0	Monitoring construction activities
11/3/2011	EP271-2	0	Monitoring construction activities
11/3/2011	EP269-EP273	0	Site clearance survey
11/3/2011	EP265-2	0	Monitoring construction activities
11/3/2011	EP263B-EP267; EP279-EP312	0	Site clearance survey
11/3/2011	EP261A, EP259-3	0	Monitoring construction activities
11/3/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/3/2011	EP279-EP294	0	Site clearance survey
11/3/2011	EP279-EP294	0	Monitoring construction activities
11/3/2011	EP274-EP278	0	Site clearance survey
11/3/2011	EP274-EP278	0	Monitoring construction activities
11/2/2011	EP269-EP273	0	Site clearance survey
11/2/2011	EP269-EP281	0	Site clearance survey
11/2/2011	EP269-EP281	0	Monitoring construction activities
11/2/2011	EP263B-EP267; EP279-EP312	0	Site clearance survey
11/2/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
11/2/2011	EP300-EP312; EP274-EP278	0	Site clearance survey
11/2/2011	EP300-EP312; EP274-EP278	0	Monitoring construction activities
11/1/2011	Suckle Property	0	Monitoring construction activities
11/1/2011	EP310 & EP311	0	Monitoring construction activities
11/1/2011	EP300-EP312	0	Site clearance survey
11/1/2011	EP300-EP312	0	Monitoring construction activities
11/1/2011	EP279-EP312	0	Site clearance survey
11/1/2011	EP277-1, EP276-1, EP261A, EP259B	0	Monitoring construction activities
11/1/2011	EP275-1	0	Monitoring construction activities
11/1/2011	EP269-EP273	0	Site clearance survey
11/1/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/1/2011	EP274-EP278	0	Site clearance survey
11/1/2011	EP274-EP278	0	Monitoring construction activities
11/1/2011	EP263B, EP267	0	Site clearance survey
11/1/2011	Devil's Canyon Bridge	0	Site clearance survey
11/1/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/31/2011	EP279-EP294	0	Site clearance survey
10/31/2011	EP279-EP294	0	Monitoring construction activities
10/31/2011	EP269-EP281	0	Site clearance survey
10/31/2011	EP269-EP281	0	Monitoring construction activities
10/31/2011	EP269-EP273	0	Site clearance survey
10/31/2011	EP269-EP281	0	Site clearance survey
10/31/2011	EP263A-2, EP266-2	0	Monitoring construction activities
10/31/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/31/2011	EP254-3	0	Monitoring construction activities
10/31/2011	EP305, EP310-1	0	Monitoring construction activities
10/31/2011	EP300-EP312	0	Site clearance survey
10/31/2011	EP300-EP312	0	Monitoring construction activities
10/31/2011	EP274-EP278	0	Site clearance survey
10/31/2011	EP263B-EP267	0	Site clearance survey
10/31/2011	Devil's Canyon Bridge	0	Site clearance survey
10/31/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/31/2011	EP262-4, EP263B-2, EP265-2, EP266-2, EP267-1	0	Monitoring construction activities
10/30/2011	EP300-EP306	0	Site clearance survey
10/30/2011	EP300-EP306	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Monitoring construction activities
10/30/2011	EP269-EP273	0	Site clearance survey
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Monitoring construction activities
10/30/2011	EP269-EP270	0	Site clearance survey
10/30/2011	EP267-2 & EP266-2	0	Monitoring construction activities
10/30/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/30/2011	EP279-EP294	0	Site clearance survey
10/30/2011	EP279-EP294	0	Monitoring construction activities
10/30/2011	EP274-EP278	0	Site clearance survey
10/30/2011	EP274-EP278	0	Monitoring construction activities
10/30/2011	EP263B-EP267	0	Site clearance survey
10/30/2011	Devil's Canyon Bridge	0	Site clearance survey
10/30/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/29/2011	EP300-EP306	0	Site clearance survey
10/29/2011	EP300-EP306	0	Monitoring construction activities
10/29/2011	EP274-EP278	0	Site clearance survey
10/29/2011	EP274-EP278	0	Monitoring construction activities
10/29/2011	EP269-EP273	0	Site clearance survey
10/29/2011	EP269-1	0	Monitoring construction activities
10/29/2011	EP269-EP281	0	Site clearance survey
10/29/2011	EP269-EP281	0	Monitoring construction activities
10/29/2011	EP269-EP281	0	Site clearance survey
10/29/2011	EP269-EP281	0	Monitoring construction activities
10/29/2011	EP269-EP270	0	Site clearance survey
10/29/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/29/2011	EP279-EP294	0	Site clearance survey
10/29/2011	EP279-EP294	0	Monitoring construction activities
10/29/2011	EP263B-EP267	0	Site clearance survey
10/29/2011	Devil's Cyn Bridge (w/in I-8 Island)	1	Morning perimeter survey 7:37 am
10/28/2011	EP300-EP306	0	Site clearance survey
10/28/2011	EP300-EP306	0	Monitoring construction activities
10/28/2011	EP269-EP281	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
10/28/2011	EP269-EP281	0	Monitoring construction activities
10/28/2011	EP269-EP273	0	Site clearance survey
10/28/2011	EP269-1	0	Monitoring construction activities
10/28/2011	EP269-EP281	0	Site clearance survey
10/28/2011	EP269-EP281	0	Monitoring construction activities
10/28/2011	EP269-EP270	0	Site clearance survey
10/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/28/2011	EP310	0	Monitoring construction activities
10/28/2011	EP279-EP294	0	Site clearance survey
10/28/2011	EP279-EP294	0	Monitoring construction activities
10/28/2011	EP274-EP278	0	Site clearance survey
10/28/2011	EP274-EP278	0	Monitoring construction activities
10/28/2011	EP263B-EP267	0	Site clearance survey
10/28/2011	AER and FROMM CY	0	Monitoring construction activities
10/27/2011	EP273-1 & EP276-1	0	Monitoring construction activities
10/27/2011	EP271-EP272	2	Site clearance survey 7:40 am
10/27/2011	EP271-EP272	0	Monitoring construction activities
10/27/2011	EP269-EP281: EP300-EP306	0	Site clearance survey
10/27/2011	EP269-EP281: EP300-EP306	0	Monitoring construction activities
10/27/2011	EP256-EP263A-2, AER CY	0	Site clearance survey
10/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/27/2011	EP279-EP294	0	Site clearance survey
10/27/2011	EP279-EP294	0	Monitoring construction activities
10/27/2011	EP274-EP278	0	Site clearance survey
10/27/2011	EP274-EP278	0	Monitoring construction activities
10/27/2011	EP269-EP271	0	Monitoring construction activities
10/27/2011	EP263B-EP267	0	Site clearance survey
10/27/2011	AER and FROMM CY	0	Monitoring construction activities
10/26/2011	EP311-1, EP312, EP310	0	Monitoring construction activities
10/26/2011	EP300-EP312	0	Site clearance survey
10/26/2011	EP300-EP312	0	Monitoring construction activities
10/26/2011	EP272-EP273	2	Site clearance survey 10:00 am
10/26/2011	EP272-EP273	0	Monitoring construction activities
10/26/2011	EP269-EP281; EP300-EP306	0	Site clearance survey
10/26/2011	EP269-EP281; EP300-EP306	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
10/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/26/2011	EP279-EP294	0	Site clearance survey
10/26/2011	EP279-EP294	0	Monitoring construction activities
10/26/2011	EP274-EP278	0	Site clearance survey
10/26/2011	EP274-EP278	0	Monitoring construction activities
10/26/2011	EP263B-EP267	0	Site clearance survey
10/25/2011	EP363-EP341, EP299 & EP300	0	Monitoring construction activities
10/25/2011	EP313-EP324	0	Monitoring construction activities
10/25/2011	EP310	0	Monitoring construction activities
10/25/2011	EP300-EP312	0	Site clearance survey
10/25/2011	EP300-EP312	0	Monitoring construction activities
10/25/2011	EP290	0	Monitoring construction activities
10/25/2011	EP269-EP273	0	Site clearance survey
10/25/2011	EP269-EP281; EP300-EP306	0	Site clearance survey
10/25/2011	EP269-EP281; EP300-EP306	0	Monitoring construction activities
10/25/2011	EP311	0	Monitoring construction activities
10/25/2011	EP279-EP294	0	Site clearance survey
10/25/2011	EP263B-EP267	0	Site clearance survey
10/24/2011	EP313-EP322	0	Monitoring construction activities
10/24/2011	EP305, EP306, EP312	0	Monitoring construction activities
10/24/2011	EP300-EP306	0	Site clearance survey
10/24/2011	EP300-EP306	0	Monitoring construction activities
10/24/2011	EP297-EP319	0	Monitoring construction activities
10/24/2011	EP269-EP273	0	Site clearance survey
10/24/2011	EP269-EP273	0	Monitoring construction activities
10/24/2011	EP269-EP281	0	Site clearance survey
10/24/2011	EP269-EP281	0	Monitoring construction activities
10/24/2011	EP279-EP294	0	Site clearance survey
10/24/2011	EP279-EP294	0	Monitoring construction activities
10/24/2011	EP274-EP278	0	Site clearance survey
10/24/2011	EP274-EP278	0	Monitoring construction activities
10/24/2011	EP263B-EP267	0	Site clearance survey
10/23/2011	EP300-EP312	0	Site clearance survey
10/23/2011	EP300-EP312	0	Monitoring construction activities
10/23/2011	EP269-EP273	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
10/23/2011	EP269-EP273	0	Monitoring construction activities
10/23/2011	EP269-EP281	0	Site clearance survey
10/23/2011	EP269-EP281	0	Monitoring construction activities
10/23/2011	EP269-EP270	0	Site clearance survey
10/23/2011	EP263B-EP267	0	Site clearance survey
10/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/23/2011	EP300-EP312	0	Site clearance survey
10/23/2011	EP300-EP312	0	Monitoring construction activities
10/23/2011	EP274-EP278	0	Site clearance survey
10/23/2011	EP274-EP278	0	Monitoring construction activities
10/23/2011	EP269-EP273	0	Site clearance survey
10/23/2011	EP269-EP273	0	Monitoring construction activities
10/22/2011	EP300-EP306	0	Site clearance survey
10/22/2011	EP300-EP306	0	Monitoring construction activity
10/22/2011	EP269-EP281	0	Site clearance survey
10/22/2011	EP269-EP281	0	Monitoring construction activity
10/22/2011	EP269-EP281	0	Site clearance survey
10/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/22/2011	EP274-EP278	0	Site clearance survey
10/22/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP306-EP312	0	Site clearance survey
10/21/2011	EP306-EP312	0	Monitoring construction activity
10/21/2011	EP274-EP278	0	Site clearance survey
10/21/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP269-EP281	0	Site clearance survey
10/21/2011	EP269-EP281	0	Site clearance survey
10/21/2011	EP269-EP281	0	Monitoring construction activity
10/21/2011	EP269-EP270	0	Site clearance survey
10/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/21/2011	EP274-EP278	0	Site clearance survey
10/21/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP269-EP273	0	Site clearance survey
10/21/2011	EP269-EP273	0	Monitoring construction activity
10/20/2011	EP269-EP281	0	Site clearance survey
10/20/2011	EP269	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
10/20/2011	EP269	0	Monitoring construction activity
10/20/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/20/2011	EP274-EP278	0	Site clearance survey
10/20/2011	EP274-EP278	0	Monitoring construction activity
10/20/2011	EP269-EP273	0	Site clearance survey
10/20/2011	EP269-EP273	0	Monitoring construction activity
10/20/2011	EP263B-EP267	0	Site clearance survey
10/20/2011	EP300-EP312	0	Site clearance survey
10/20/2011	EP300-EP312	0	Monitoring construction activity
10/19/2011	EP290-EP312	0	Site clearance survey
10/19/2011	EP290-EP312	0	Monitoring construction activity
10/19/2011	EP269-EP281	0	Site clearance survey
10/19/2011	EP300-EP312	0	Site clearance survey
10/19/2011	EP300-EP312	0	Monitoring construction activity
10/19/2011	EP274-EP278	0	Site clearance survey
10/19/2011	EP274-EP278	0	Monitoring construction activity
10/19/2011	EP269-EP273	0	Site clearance survey
10/19/2011	EP269-EP273	0	Monitoring construction activity
10/19/2011	EP263B-EP267	0	Site clearance survey
10/18/2011	Slay Property	0	Monitoring construction activity
10/18/2011	EP269-EP270	0	Site clearance survey
10/18/2011	EP269-EP270	0	Monitoring construction activity
10/18/2011	EP269-EP281	0	Site clearance survey
10/18/2011	EP269-EP270	0	Site clearance survey
10/18/2011	EP274-EP278	0	Site clearance survey
10/18/2011	EP274-EP278	0	Monitoring construction activity
10/18/2011	EP269-EP273	0	Site clearance survey
10/18/2011	EP269-EP273	0	Monitoring construction activity
10/18/2011	EP263B-EP267	0	Site clearance survey
10/17/2011	Slay Property	0	Site clearance survey
10/17/2011	EP312 & EP314	0	Monitoring construction activity
10/17/2011	EP306-EP312	0	Site clearance survey
10/17/2011	EP306-EP312	0	Afternoon perimeter survey
10/17/2011	EP305	0	Monitoring construction activity
10/17/2011	EP300-EP363	0	Monitoring construction activity

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
10/17/2011	EP300-EP306	0	Site clearance survey
10/17/2011	EP300-EP306	0	Monitoring construction activity
10/17/2011	EP270-2	0	Monitoring construction activity
10/17/2011	EP269-EP270	0	Site clearance survey
10/17/2011	EP269-EP270	0	Monitoring construction activity
10/17/2011	EP269-EP281	0	Site clearance survey
10/17/2011	EP269-EP270	0	Site clearance survey
10/17/2011	EP267-2	0	Monitoring construction activity
10/17/2011	EP261-2	0	Monitoring construction activity
10/17/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/17/2011	EP274-EP278	0	Site clearance survey
10/17/2011	EP274-EP278	0	Monitoring construction activity
10/17/2011	EP269-EP273	0	Site clearance survey
10/17/2011	EP269-EP273	0	Monitoring construction activity
10/17/2011	EP263B-EP267	0	Site clearance survey
10/16/2011	EP306-EP312	0	Site clearance survey
10/16/2011	EP306-EP312	0	Afternoon perimeter survey
10/16/2011	EP300-EP306	0	Site clearance survey
10/16/2011	EP300-EP306	0	Monitoring construction activity
10/16/2011	EP271-2	0	Monitoring construction activity
10/16/2011	EP270-2	0	Monitoring construction activity
10/16/2011	EP269-EP270	0	Site clearance survey
10/16/2011	EP256-EP281	0	Site clearance survey
10/16/2011	EP305	0	Monitoring construction activity
10/16/2011	EP274-EP278	0	Site clearance survey
10/16/2011	EP274-EP278	0	Monitoring construction activity
10/16/2011	EP269-EP273	0	Site clearance survey
10/16/2011	EP269-EP273	0	Monitoring construction activity
10/16/2011	EP263B-EP267	0	Site clearance survey
10/16/2011	EP256-EP263A-2, AER & FROMM CY	0	Site clearance survey
10/16/2011	EP256-EP263A-2, AER & FROMM CY	0	Monitoring construction activity
10/15/2011	Slay Property	0	Site clearance survey
10/15/2011	Slay Property	0	Monitoring construction activities
10/15/2011	EP306-EP312	0	Site clearance survey
10/15/2011	EP306-EP312	0	Afternoon perimeter survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
10/15/2011	EP305	0	Monitoring construction activities
10/15/2011	EP300-EP306	0	Site clearance survey
10/15/2011	EP300-EP306	0	Monitoring construction activities
10/15/2011	EP269-1 AND EP273-1	0	Monitoring construction activities
10/15/2011	EP269-EP281	0	Morning perimeter survey
10/15/2011	EP261-2	0	Monitoring construction activities
10/15/2011	EP274-EP278	0	Site clearance survey
10/15/2011	EP274-EP278	0	Monitoring construction activities
10/15/2011	EP263B-EP267	0	Site clearance survey
10/14/2011	Slay Property	0	Site clearance survey
10/14/2011	Slay Property	0	Monitoring construction activities
10/14/2011	EP310	0	Monitoring construction activities
10/14/2011	EP305	0	Monitoring construction activities
10/14/2011	EP300-EP306	0	Site clearance survey
10/14/2011	EP300-EP306	0	Monitoring construction activities
10/14/2011	EP291-EP301	0	Monitoring construction activities
10/14/2011	EP269 through EP281	0	Site clearance survey
10/14/2011	EP269-EP270	0	Site clearance survey
10/14/2011	EP263B-2	0	Monitoring construction activities
10/14/2011	EP256-EP263A	0	Site clearance survey
10/14/2011	EP256-EP263A	0	Monitoring construction activities
10/14/2011	EP274-EP278	0	Site clearance survey
10/14/2011	EP274-EP278	0	Monitoring construction activities
10/14/2011	EP269-EP273	0	Site clearance survey
10/14/2011	EP269-EP273	0	Monitoring construction activities
10/14/2011	EP263B-EP267	0	Site clearance survey
10/14/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/14/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/13/2011	Slay Property	0	Site clearance survey
10/13/2011	Slay Property	0	Monitoring construction activities
10/13/2011	EP310	0	Monitoring construction activities
10/13/2011	EP306-EP312	0	Site clearance survey
10/13/2011	EP306-EP312	0	Afternoon perimeter survey
10/13/2011	EP293	0	Monitoring construction activities
10/13/2011	EP291-EP301	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
10/13/2011	EP275-1	0	Monitoring construction activities
10/13/2011	EP269-EP270	0	Site clearance survey
10/13/2011	EP269-EP281	0	Site clearance survey
10/13/2011	EP269-EP270	0	Site clearance survey
10/13/2011	EP266-2	0	Monitoring construction activities
10/13/2011	EP274-EP278	0	Site clearance survey
10/13/2011	EP274-EP278	0	Monitoring construction activities
10/13/2011	EP269-EP273	0	Site clearance survey
10/13/2011	EP269-EP273	0	Monitoring construction activities
10/13/2011	EP263B-EP267	0	Site clearance survey
10/13/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/13/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/12/2011	Slay Property	0	Site clearance survey
10/12/2011	Slay Property	0	Monitoring construction activities
10/12/2011	EP306-EP312	0	Site clearance survey
10/12/2011	EP291-EP301	0	Monitoring construction activities
10/12/2011	EP269-EP270	0	Site clearance survey
10/12/2011	EP269-EP281	0	Site clearance survey
10/12/2011	EP269-EP281	0	Monitoring construction activities
10/12/2011	EP269-EP270	0	Site clearance survey
10/12/2011	EP311	0	Monitoring construction activities
10/12/2011	EP274-EP278	0	Site clearance survey
10/12/2011	EP274-EP278	0	Monitoring construction activities
10/12/2011	EP269-EP273	0	Site clearance survey
10/12/2011	EP269-EP273	0	Monitoring construction activities
10/12/2011	EP263B-EP267	0	Site clearance survey
10/12/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/12/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/11/2011	Slay Property	0	Site clearance survey
10/11/2011	Slay Property	0	Monitoring construction activities
10/11/2011	EP311	0	Monitoring construction activities
10/11/2011	EP306-EP312	0	Site clearance survey
10/11/2011	EP306-EP312	0	Afternoon perimeter survey
10/11/2011	EP300-EP306	0	Site clearance survey
10/11/2011	EP291-EP301	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
10/11/2011	EP269-EP273	0	Site clearance survey
10/11/2011	EP269-EP273	0	Monitoring construction activities
10/11/2011	EP269-EP270	0	Site clearance survey
10/11/2011	EP269-EP270	0	Monitoring construction activities
10/11/2011	EP274-EP278	0	Site clearance survey
10/11/2011	EP274-EP278	0	Monitoring construction activities
10/11/2011	EP263B-EP267	0	Site clearance survey
10/11/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/11/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/10/2011	Slay Property	0	Site clearance survey
10/10/2011	Slay Property	0	Monitoring construction activities
10/10/2011	EP306-EP312	0	Site clearance survey
10/10/2011	EP306-EP312	0	Afternoon perimeter survey
10/10/2011	EP305	0	Monitoring construction activities
10/10/2011	EP300-EP306	0	Site clearance survey
10/10/2011	EP300-EP306	0	Monitoring construction activities
10/10/2011	EP300-EP306	0	Site clearance survey
10/10/2011	EP291-EP301	0	Monitoring construction activities
10/10/2011	EP269-EP281	9	Sheep were seen entering I-8 Island during Site Clearance survey
10/10/2011	EP269-EP273	0	Site clearance survey
10/10/2011	EP269-EP273	0	Monitoring construction activities
10/10/2011	EP259-3	0	Monitoring construction activities
10/10/2011	EP274-EP278	0	Site clearance survey
10/10/2011	EP274-EP278	0	Monitoring construction activities
10/10/2011	EP263B-EP267	0	Site clearance survey
10/10/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/10/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/9/2011	EP306-EP312	0	Site clearance survey
10/9/2011	EP306-EP312	0	Monitoring construction activities
10/9/2011	EP300-EP306	0	Site clearance survey
10/9/2011	EP300-EP306	0	Monitoring construction activities
10/9/2011	EP300-EP306	0	Site clearance survey
10/9/2011	EP300-EP306	0	Monitoring construction activities
10/9/2011	EP269-EP273	0	Site clearance survey
10/9/2011	EP269-EP270	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
10/9/2011	EP269-EP270	0	Monitoring construction activities
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP256-3	0	Monitoring construction activities
10/9/2011	EP274-EP278	0	Site clearance survey
10/9/2011	EP274-EP278	0	Monitoring construction activities
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP269-EP270	0	Monitoring construction activities
10/9/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/9/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/8/2011	EP300-EP306	0	Site clearance survey
10/8/2011	EP300-EP306	0	Monitoring construction activity
10/8/2011	EP300-EP306	0	Site clearance survey
10/8/2011	EP300-EP306	0	Morning perimeter survey
10/8/2011	EP291-EP301	0	Monitoring construction activity
10/8/2011	EP278-1	0	Monitoring construction activity
10/8/2011	EP269-EP273	0	Site clearance survey
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP269-EP270	0	Monitoring construction activity
10/8/2011	EP269/EP270 Pullsite	0	Monitoring construction activity
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP259-3	0	Monitoring construction activity
10/8/2011	EP274-EP278	0	Site clearance survey
10/8/2011	EP274-EP278	0	Monitoring construction activity
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP269-EP270	0	Monitoring construction activity
10/8/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/8/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/7/2011	Slay Property	0	Site clearance survey
10/7/2011	EP306-EP312	0	Site clearance survey
10/7/2011	EP306-EP312	0	Morning perimeter survey
10/7/2011	EP300-EP306	0	Site clearance survey
10/7/2011	EP300-EP306	0	Monitoring construction activity
10/7/2011	EP300-EP306	0	Site clearance survey
10/7/2011	EP300-EP306	0	Morning perimeter survey
10/7/2011	EP291-EP301	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
10/7/2011	EP269-EP273	0	Site clearance survey
10/7/2011	EP269-EP270	0	Site clearance survey
10/7/2011	EP269-EP270	0	Monitoring construction activity
10/7/2011	EP269-EP270	0	Site clearance survey
10/7/2011	EP259-3	0	Monitoring construction activity
10/7/2011	EP274-EP278	0	Site clearance survey
10/7/2011	EP274-EP278	0	Monitoring construction activity
10/7/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/7/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/6/2011	Slay Property	0	Site clearance survey
10/6/2011	Slay Property	0	Monitoring construction activity
10/6/2011	EP306-EP312	0	Site clearance survey
10/6/2011	EP306-EP312	0	Monitoring construction activity
10/6/2011	EP291-EP301	0	Site clearance survey
10/6/2011	EP269-EP273	0	Site clearance survey
10/6/2011	EP269-EP270	0	Site clearance survey
10/6/2011	EP269-EP270	0	Monitoring construction activity
10/6/2011	EP269-EP281	0	Site clearance survey
10/6/2011	EP269-EP270	0	Site clearance survey
10/6/2011	EP263B-EP267	0	Site clearance survey
10/6/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/6/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/5/2011	Slay Property	0	Site clearance survey
10/5/2011	Slay Property	0	Monitoring construction activity
10/5/2011	EP303-2	0	Monitoring construction activity
10/5/2011	EP291-EP301	0	Site clearance survey
10/5/2011	EP269-EP273	0	Site clearance survey
10/5/2011	EP269-EP270	0	Site clearance survey
10/5/2011	EP269-EP270	0	Monitoring construction activity
10/5/2011	EP274-EP278	0	Site clearance survey
10/5/2011	EP274-EP278	0	Monitoring construction activity
10/5/2011	EP269-EP281	0	Site clearance survey
10/5/2011	EP269-EP270	0	Site clearance survey
10/5/2011	EP263B-EP267	0	Site clearance survey
10/5/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
10/5/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/4/2011	Slay Property	0	Site clearance survey
10/4/2011	Slay Property	0	Monitoring construction activity
10/4/2011	EP300-EP306	0	Site clearance survey
10/4/2011	EP300-EP306	0	Monitoring construction activity
10/4/2011	EP269-EP273	0	Site clearance survey
10/4/2011	EP269-EP270	0	Site clearance survey
10/4/2011	EP269-EP270	0	Monitoring construction activity
10/4/2011	EP256-EP263A	0	Site clearance survey
10/4/2011	EP274-EP278	0	Site clearance survey
10/4/2011	EP274-EP278	0	Monitoring construction activity
10/4/2011	EP263B-EP267	0	Site clearance survey
10/3/2011	Slay Property	0	Site clearance survey
10/3/2011	Slay Property	0	Monitoring construction activity
10/3/2011	EP300-EP306	0	Site clearance survey
10/3/2011	EP300-EP306	0	Monitoring construction activity
10/3/2011	EP300-EP306	0	Site clearance survey
10/3/2011	EP300-EP306	0	Morning perimeter survey
10/3/2011	EP291-EP341	0	Site clearance survey
10/3/2011	EP279-EP294	0	Site clearance survey
10/3/2011	EP269-EP273	0	Site clearance survey
10/3/2011	EP269-EP273	0	Monitoring construction activity
10/3/2011	EP263B-EP267	0	Site clearance survey
10/3/2011	EP263B-EP267	0	Monitoring construction activity
10/3/2011	EP256-EP263A	0	Site clearance survey
10/3/2011	EP274-EP278	0	Site clearance survey
10/3/2011	EP274-EP278	0	Monitoring construction activity
10/3/2011	EP263B-EP267	0	Site clearance survey
10/2/2011	EP300-EP306	0	Site clearance survey
10/2/2011	EP300-EP306	0	Monitoring construction activity
10/2/2011	EP269-EP281	0	Afternoon perimeter survey
10/2/2011	EP269-EP273	0	Afternoon perimeter survey
10/1/2011	EP300-EP306	0	Site clearance survey
10/1/2011	EP300-EP306	0	Monitoring construction activities
10/1/2011	EP300-EP306	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
10/1/2011	EP300-EP306	0	Morning perimeter survey
10/1/2011	EP269-EP273 and EP256-EP261	0	Site clearance survey
10/1/2011	EP269-EP273	0	Site clearance survey
10/1/2011	EP269-EP270	0	Site clearance survey
10/1/2011	EP274-EP278	0	Site clearance survey
10/1/2011	EP274-EP278	0	Monitoring construction activities
9/30/2011	Slay Property	0	Site clearance survey
9/30/2011	Slay Property	0	Monitoring construction activities
9/30/2011	EP300-EP312	0	Site clearance survey
9/30/2011	EP300-EP312	0	Monitoring construction activities
9/30/2011	EP300-EP306	0	Site clearance survey
9/30/2011	EP300-EP306	0	Monitoring construction activities
9/30/2011	EP291-EP348	0	Monitoring construction activities
9/30/2011	EP290-EP294, EP300-EP312	0	Site clearance survey
9/30/2011	EP290-EP294, EP300-EP312	0	Monitoring construction activities
9/30/2011	EP269-EP273	0	Site clearance survey
9/30/2011	EP269-EP273	0	Monitoring construction activities
9/30/2011	EP269-EP281	0	Site clearance survey
9/30/2011	EP279-EP294	0	Site clearance survey
9/30/2011	EP274-EP278	0	Site clearance survey
9/30/2011	EP274-EP278	0	Monitoring construction activities
9/30/2011	EP263-B-EP267	0	Site clearance survey
9/30/2011	EP256-EP263A, AER, Fromm CY	0	Site clearance survey
9/30/2011	EP256-EP263A, AER, Fromm CY	0	Monitoring construction activities
9/29/2011	Slay Property	0	Site clearance survey
9/29/2011	Slay Property	0	Monitoring construction activities
9/29/2011	EP300-EP312	0	Site clearance survey
9/29/2011	EP300-EP306	0	Site clearance survey
9/29/2011	EP300-EP306	0	Monitoring construction activities
9/29/2011	EP290-EP294, EP300-EP312	0	Site clearance survey
9/29/2011	EP290-EP294, EP300-EP312	0	Monitoring construction activities
9/29/2011	EP269-EP273	0	Site clearance survey
9/29/2011	EP269-EP273	0	Monitoring construction activities
9/29/2011	EP279-EP294	0	Site clearance survey
9/29/2011	EP274-EP278	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
9/29/2011	EP274-EP278	0	Monitoring construction activities
9/29/2011	EP263B-EP267	0	Site clearance survey
9/28/2011	Slay Property	0	Site clearance survey
9/28/2011	Slay Property	0	Monitoring construction activities
9/28/2011	EP330-EP291	0	Site clearance survey
9/28/2011	EP300-EP306	0	Site clearance survey
9/28/2011	EP300-EP306	0	Monitoring construction activities
9/28/2011	EP290-EP294	0	Site clearance survey
9/28/2011	EP290-EP294	0	Monitoring construction activities
9/28/2011	EP269-EP273	0	Site clearance survey
9/28/2011	EP269-EP273	0	Monitoring construction activities
9/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/28/2011	EP279-EP294	0	Site clearance survey
9/28/2011	EP279-EP294	0	Monitoring construction activities
9/28/2011	EP274-EP278	0	Site clearance survey
9/28/2011	EP274-EP278	0	Monitoring construction activities
9/28/2011	EP263B-EP267	0	Site clearance survey
9/27/2011	Slay Property	0	Site clearance survey
9/27/2011	Slay Property	0	Monitoring construction activities
9/27/2011	EP339-EP291	0	Site clearance survey
9/27/2011	EP309	0	Monitoring construction activities
9/27/2011	EP300-EP312	0	Site clearance survey
9/27/2011	EP300-EP312	0	Monitoring construction activities
9/27/2011	EP300-EP306	0	Site clearance survey
9/27/2011	EP278-1	0	Monitoring construction activities
9/27/2011	EP269-EP273	0	Site clearance survey
9/27/2011	EP269-EP273	0	Monitoring construction activities
9/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/27/2011	EP279-EP294	0	Site clearance survey
9/27/2011	EP279-EP294	0	Monitoring construction activities
9/27/2011	EP274-EP278	0	Site clearance survey
9/27/2011	EP274-EP278	0	Monitoring construction activities
9/27/2011	EP263B-EP267	0	Site clearance survey
9/27/2011	AER CY	0	Monitoring construction activities
9/26/2011	EP300-EP306	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
9/26/2011	EP300-EP306	0	Monitoring construction activities
9/26/2011	EP300-EP306	0	Site clearance survey
9/26/2011	EP300-EP312	0	Site clearance survey
9/26/2011	EP300-EP312	0	Monitoring construction activities
9/26/2011	EP291-EP301	0	Monitoring construction activities
9/26/2011	EP278-1, EP270-2	0	Monitoring construction activities
9/26/2011	EP274-EP278	0	Site clearance survey
9/26/2011	EP274-EP278	0	Monitoring construction activities
9/26/2011	EP269-EP273	0	Site clearance survey
9/26/2011	EP269-EP273	0	Monitoring construction activities
9/26/2011	EP269-EP270	0	Morning perimeter survey
9/26/2011	EP269-EP270	0	Monitoring construction activities
9/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/26/2011	EP279-EP294	0	Site clearance survey
9/26/2011	EP279-EP294	0	Monitoring construction activities
9/26/2011	EP269-EP271, EP256-EP263, AER & Fromm CY	0	Site clearance survey
9/26/2011	EP269-EP271, EP256-EP263, AER & Fromm CY	0	Monitoring construction activities
9/26/2011	EP263B-EP267	0	Site clearance survey
9/26/2011	CP88	0	Site clearance survey
9/26/2011	CP88	0	Monitoring construction activities
9/25/2011	EP300-EP306	0	Site clearance survey
9/25/2011	EP300-EP306	0	Monitoring construction activities
9/25/2011	EP300-EP306	0	Morning perimeter survey
9/25/2011	EP278	0	Monitoring construction activities
9/25/2011	EP274-EP278	0	Site clearance survey
9/25/2011	EP274-EP278	0	Monitoring construction activities
9/25/2011	EP271-2	0	Monitoring construction activities
9/25/2011	EP269-EP270	0	Morning perimeter survey
9/25/2011	EP269-EP270	0	Monitoring construction activities
9/25/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/25/2011	EP279-EP294	0	Site clearance survey
9/25/2011	EP279-EP294	0	Monitoring construction activities
9/25/2011	EP269-EP273	0	Site clearance survey
9/25/2011	EP269-EP273	0	Monitoring construction activities
9/25/2011	EP263B-EP267	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
9/24/2011	EP300-EP306	0	Site clearance survey
9/24/2011	EP300-EP306	0	Monitoring construction activities
9/24/2011	EP300-EP306	0	Site clearance survey
9/24/2011	EP300-EP306	0	Monitoring construction activities
9/24/2011	EP291/EP292 Pullsite	0	Monitoring construction activities
9/24/2011	EP274-EP278	0	Site clearance survey
9/24/2011	EP274-EP278	0	Monitoring construction activities
9/24/2011	EP274	0	Monitoring construction activities
9/24/2011	EP269-EP270	0	Site clearance survey
9/24/2011	EP269-EP270	0	Monitoring construction activities
9/24/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/24/2011	EP279-EP294	0	Site clearance survey
9/24/2011	EP279-EP294	0	Monitoring construction activities
9/24/2011	EP263B-EP267	0	Site clearance survey
9/23/2011	EP300-EP306	0	Site clearance survey
9/23/2011	EP300-EP306	0	Monitoring construction activities
9/23/2011	EP300-EP312	0	Site clearance survey
9/23/2011	EP300-EP312	0	Monitoring construction activities
9/23/2011	EP274-1	0	Monitoring construction activities
9/23/2011	EP269-EP271	0	Site clearance survey
9/23/2011	EP269-EP271	0	Monitoring construction activities
9/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/23/2011	EP279-EP294	0	Site clearance survey
9/23/2011	EP279-EP294	0	Monitoring construction activities
9/23/2011	EP278-1	0	Monitoring construction activities
9/23/2011	EP263B-EP267	0	Site clearance survey
9/22/2011	EP300-EP312	0	Site clearance survey
9/22/2011	EP300-EP312	0	Monitoring construction activities
9/22/2011	EP300-EP306	0	Site clearance survey
9/22/2011	EP300-EP306	0	Monitoring construction activities
9/22/2011	EP274-1	0	Monitoring construction activities
9/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/22/2011	EP279-EP294	0	Site clearance survey
9/22/2011	EP278-1	0	Monitoring construction activities
9/22/2011	EP274-EP278	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
9/22/2011	EP274-EP278	0	Monitoring construction activities
9/22/2011	EP263B-EP267	0	Site clearance survey
9/21/2011	EP300-EP306	0	Site clearance survey
9/21/2011	EP278-1	0	Monitoring construction activities
9/21/2011	EP274-1	0	Monitoring construction activities
9/21/2011	EP269-EP271, EP300-EP312	0	Site clearance survey
9/21/2011	EP269-EP271, EP300-EP312	0	Monitoring construction activities
9/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/21/2011	EP279-EP294	0	Site clearance survey
9/21/2011	EP279-EP294	0	Monitoring construction activities
9/21/2011	EP274-EP278	0	Site clearance survey
9/21/2011	EP274-EP278	0	Monitoring construction activities
9/21/2011	EP269-EP281	0	Site clearance survey
9/21/2011	EP269-EP281	0	Monitoring construction activities
9/21/2011	EP263B-EP267	0	Site clearance survey
9/20/2011	EP300-EP306	0	Site clearance survey
9/20/2011	EP278-1	0	Monitoring construction activities
9/20/2011	EP269-EP273	0	Site clearance survey
9/20/2011	EP269-EP273	0	Monitoring construction activities
9/20/2011	EP269-EP271	0	Site clearance survey
9/20/2011	EP269-EP271	0	Monitoring construction activities
9/20/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/20/2011	EP279-EP294	0	Site clearance survey
9/20/2011	EP279-EP294	0	Monitoring construction activities
9/20/2011	EP274-EP278	0	Site clearance survey
9/20/2011	EP274-EP278	0	Monitoring construction activities
9/20/2011	EP269-EP281	0	Site clearance survey
9/20/2011	EP269-EP281	0	Monitoring construction activities
9/20/2011	EP263B-EP267	0	Site clearance survey
9/19/2011	EP269-EP273	0	Site clearance survey
9/19/2011	EP269-EP273	0	Monitoring construction activities
9/19/2011	EP269-EP271	0	Site clearance survey
9/19/2011	EP269-EP271	0	Monitoring construction activities
9/19/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/19/2011	EP279-EP294	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
9/19/2011	EP279-EP294	0	Monitoring construction activities
9/19/2011	EP274-EP278	0	Site clearance survey
9/19/2011	EP274-EP278	0	Monitoring construction activities
9/19/2011	EP269-EP281	0	Site clearance survey
9/19/2011	EP269-EP281	0	Monitoring construction activities
9/19/2011	EP263B-EP267	0	Site clearance survey
9/18/2011	EP300-EP306	0	Site clearance survey
9/18/2011	EP300-EP312	0	Site clearance survey
9/18/2011	EP300-EP312	0	Monitoring construction activities
9/18/2011	EP269-EP273	0	Site clearance survey
9/18/2011	EP269-EP273	0	Monitoring construction activities
9/18/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/18/2011	EP279-EP294	0	Site clearance survey
9/18/2011	EP279-EP294	0	Monitoring construction activities
9/18/2011	EP274-EP278	0	Site clearance survey
9/18/2011	EP274-EP278	0	Monitoring construction activities
9/18/2011	EP269-EP281	0	Site clearance survey
9/18/2011	I8 Island	9	Afternoon perimeter survey
9/17/2011	EP300-EP306	0	Site clearance survey
9/17/2011	EP300-EP312	0	Site clearance survey
9/17/2011	EP300-EP312	0	Monitoring construction activities
9/17/2011	EP269-EP273	0	Site clearance survey
9/17/2011	EP269-EP273	0	Monitoring construction activities
9/17/2011	EP274-EP278	0	Site clearance survey
9/17/2011	EP274-EP278	0	Monitoring construction activities
9/17/2011	EP269-EP281	0	Site clearance survey
9/17/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/17/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/16/2011	EP300-EP312	0	Site clearance survey
9/16/2011	EP300-EP312	0	Monitoring construction activities
9/16/2011	EP300-EP306	0	Site clearance survey
9/16/2011	EP269-EP273	0	Site clearance survey
9/16/2011	EP269-EP273	0	Monitoring construction activities
9/16/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/16/2011	EP274-EP278	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
9/16/2011	EP274-EP278	0	Monitoring construction activities
9/16/2011	EP269-EP281	0	Site clearance survey
9/16/2011	EP263B-EP267	0	Site clearance survey
9/16/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/16/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/15/2011	EP300-EP312	0	Site clearance survey
9/15/2011	EP300-EP312	0	Monitoring construction activities
9/15/2011	EP300-EP306	0	Site clearance survey
9/15/2011	EP300-EP306	0	Monitoring construction activities
9/15/2011	EP269-EP273	0	Site clearance survey
9/15/2011	EP269-EP273	0	Monitoring construction activities
9/15/2011	EP256-EP263A, AER	0	Monitoring construction activities
9/15/2011	EP274-EP278	0	Site clearance survey
9/15/2011	EP274-EP278	0	Monitoring construction activities
9/15/2011	EP269-EP281	0	Site clearance survey
9/15/2011	EP269-EP281	0	Monitoring construction activities
9/15/2011	EP263B-EP267	0	Site clearance survey
9/14/2011	EP310-3	0	Monitoring construction activities
9/14/2011	EP300-EP312	0	Site clearance survey
9/14/2011	EP300-EP312	0	Monitoring construction activities
9/14/2011	EP300-EP306	0	Morning perimeter survey
9/14/2011	EP274-1	0	Monitoring construction activities
9/14/2011	EP269-EP273	0	Site clearance survey
9/14/2011	EP269-EP273	0	Monitoring construction activities
9/14/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/14/2011	EP274-EP278	0	Site clearance survey
9/14/2011	EP274-EP278	0	Monitoring construction activities
9/14/2011	EP269-EP281	0	Site clearance survey
9/14/2011	EP269-EP281	0	Monitoring construction activities
9/14/2011	EP263B-EP267	0	Site clearance survey
9/13/2011	EP300-EP312	0	Site clearance survey
9/13/2011	EP300-EP312	0	Monitoring construction activities
9/13/2011	EP300-EP306	0	Morning perimeter survey
9/13/2011	EP269-EP273	0	Site clearance survey
9/13/2011	EP269-EP273	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
9/13/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/13/2011	EP274-EP278	0	Site clearance survey
9/13/2011	EP274-EP278	0	Monitoring construction activities
9/13/2011	EP274-EP278	0	Monitoring construction activities
9/13/2011	EP274	0	Monitoring construction activities
9/13/2011	EP269-EP281	0	Site clearance survey
9/13/2011	EP263B-EP267	0	Site clearance survey
9/12/2011	Mountain Springs Grade Road	15	Morning perimeter survey
9/12/2011	EP305-3, EP310	0	Monitoring construction activities
9/12/2011	EP300-EP312	0	Site clearance survey
9/12/2011	EP300-EP312	0	Monitoring construction activities
9/12/2011	EP300-EP306	0	Site clearance survey
9/12/2011	EP300-EP306	0	Monitoring construction activities
9/12/2011	EP269-EP273	0	Site clearance survey
9/12/2011	EP269-EP273	0	Monitoring construction activities
9/12/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/12/2011	EP274-EP278	0	Site clearance survey
9/12/2011	EP274-EP278	0	Monitoring construction activities
9/12/2011	EP274-EP278	0	Monitoring construction activities
9/12/2011	EP274	0	Monitoring construction activities
9/12/2011	EP269-EP281	0	Monitoring construction activities
9/12/2011	EP263B-EP267	0	Site clearance survey
9/11/2011	EP300-EP312	0	Site clearance survey
9/11/2011	EP300-EP312	0	Monitoring construction activities
9/11/2011	EP300-EP306	0	Site clearance survey
9/11/2011	EP300-EP306	0	Monitoring construction activities
9/11/2011	EP271-2	0	Monitoring construction activities
9/11/2011	EP269-EP271	0	Site clearance survey
9/11/2011	EP269-EP271	0	Monitoring construction activities
9/11/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/11/2011	EP274-EP278	0	Site clearance survey
9/11/2011	EP274-EP278	0	Monitoring construction activities
9/11/2011	EP269-EP273	0	Site clearance survey
9/11/2011	EP269-EP273	0	Monitoring construction activities
9/11/2011	EP263B-EP267	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
9/11/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/11/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/10/2011	EP300-EP312	0	Site clearance survey
9/10/2011	EP300-EP312	0	Monitoring construction activities
9/10/2011	EP300-EP306	0	Site clearance survey
9/10/2011	EP300-EP306	0	Monitoring construction activities
9/10/2011	EP269-EP271	0	Site clearance survey
9/10/2011	EP269-EP271	0	Monitoring construction activities
9/10/2011	EP274-EP278	0	Site clearance survey
9/10/2011	EP274-EP278	0	Monitoring construction activities
9/10/2011	EP269-EP273	0	Morning perimeter survey
9/10/2011	EP269-EP273	0	Monitoring construction activities
9/10/2011	EP269-EP273	0	Evening perimeter survey
9/9/2011	EP300-EP312	0	Site clearance survey
9/9/2011	EP300-EP312	0	Monitoring construction activities
9/9/2011	EP300-EP306	0	Site clearance survey
9/9/2011	EP300-EP306	0	Monitoring construction activities
9/9/2011	EP271-2	0	Monitoring construction activities
9/9/2011	EP269-EP271	0	Site clearance survey
9/9/2011	EP269-EP271	0	Monitoring construction activities
9/9/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/9/2011	EP256-EP263A, AER and Fromm yards	0	Site clearance survey
9/9/2011	EP256-EP263A, AER and Fromm yards	0	Monitoring construction activities
9/9/2011	EP274-EP278	0	Site clearance survey
9/9/2011	EP274-EP278	0	Monitoring construction activities
9/9/2011	EP269-EP273	0	Morning perimeter survey
9/9/2011	EP269-EP273	0	Monitoring construction activities
9/9/2011	EP269-EP273	0	Evening perimeter survey
9/8/2011	EP300-EP312	0	Site clearance survey
9/8/2011	EP300-EP312	0	Monitoring construction activities
9/8/2011	EP271-2	0	Monitoring construction activities
9/8/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/8/2011	EP279-EP294	0	Site clearance survey
9/8/2011	EP279-EP294	0	Monitoring construction activities
9/8/2011	EP274-EP278	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
9/8/2011	EP274-EP278	0	Monitoring construction activities
9/8/2011	EP263B-EP267	0	Site clearance survey
9/7/2011	EP306-1	0	Monitoring construction activities
9/7/2011	EP300-EP312	0	Site clearance survey
9/7/2011	EP300-EP312	0	Monitoring construction activities
9/7/2011	EP300-EP306	0	Site clearance survey
9/7/2011	EP300-EP306	0	Monitoring construction activities
9/7/2011	EP273	0	Monitoring construction activities
9/7/2011	EP269-EP273	0	Site clearance survey
9/7/2011	EP269-EP273	0	Monitoring construction activities
9/7/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/7/2011	EP278-EP294	0	Morning perimeter survey
9/7/2011	EP278-EP294	0	Monitoring construction activities
9/7/2011	EP278-EP294	0	Evening perimeter survey
9/7/2011	EP274-EP278	0	Site clearance survey
9/7/2011	EP274-EP278	0	Monitoring construction activities
9/7/2011	EP263B-EP267	0	Site clearance survey
9/6/2011	EP300-EP312	0	Site clearance survey
9/6/2011	EP300-EP312	0	Monitoring construction activities
9/6/2011	EP273	0	Monitoring construction activities
9/6/2011	EP269-EP273	0	Site clearance survey
9/6/2011	EP269-EP273	0	Monitoring construction activities
9/6/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/6/2011	EP278-EP294	0	Morning perimeter survey
9/6/2011	EP278-EP294	0	Monitoring construction activities
9/6/2011	EP278-EP294	0	Evening perimeter survey
9/6/2011	EP274-EP278	0	Site clearance survey
9/6/2011	EP274-EP278	0	Monitoring construction activities
9/6/2011	EP263B-EP267	0	Site clearance survey
9/5/2011	EP300-EP312	0	Site clearance survey
9/5/2011	EP269-EP273	0	Site clearance survey
9/5/2011	EP269-EP273	0	Monitoring construction activities
9/5/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/5/2011	EP274-EP294	0	Site clearance survey
9/5/2011	EP263B-EP267	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
9/4/2011	EP300-EP312	0	Site clearance survey
9/4/2011	EP300-EP312	0	Monitoring construction activities
9/4/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
9/4/2011	EP269-EP281	0	Site clearance survey
9/4/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/4/2011	EP256-EP263A, AER and Fromm yards	0	Site clearance survey
9/4/2011	EP256-EP263A, AER and Fromm yards	0	Monitoring construction activities
9/4/2011	EP279-EP294	0	Site clearance survey
9/4/2011	EP279-EP294	0	Monitoring construction activities
9/4/2011	EP274-EP278	0	Site clearance survey
9/4/2011	EP274-EP278	0	Monitoring construction activities
9/4/2011	EP270	0	Site clearance survey
9/4/2011	EP270	0	Monitoring construction activities
9/3/2011	EP300-EP312	0	Monitoring Construction Activities
9/3/2011	EP300-EP312	0	Site clearance survey
9/3/2011	EP300-EP306	0	Monitoring Construction Activities
9/3/2011	EP300-EP306	0	Site clearance survey
9/3/2011	EP271	0	Monitoring Construction Activities
9/3/2011	EP269-EP273	0	Monitoring Construction Activities
9/3/2011	EP269-EP273	0	Site clearance survey
9/3/2011	EP269-EP281	0	Monitoring Construction Activities
9/3/2011	EP256-EP263A, AER and Fromm Yards	0	Monitoring Construction Activities
9/3/2011	EP256-EP263A, AER and Fromm Yards	0	Site clearance survey
9/3/2011	EP278-EP294	0	Evening perimeter survey
9/3/2011	EP278-EP294	0	Monitoring Construction Activities
9/3/2011	EP278-EP294	0	Morning perimeter survey
9/3/2011	EP269-1 & EP269/EP270 Pull site	0	Monitoring Construction Activities
9/2/2011	I-8 Island	9	Evening perimeter survey 4:45pm - 5:08pm
9/2/2011	I-8 Island	12	Morning perimeter survey 8:35am
9/2/2011	EP300-EP312	0	Monitoring Construction Activities
9/2/2011	EP300-EP312	0	Site clearance survey
9/2/2011	EP272 & EP276	0	Monitoring Construction Activities
9/2/2011	EP269-EP273	0	Monitoring Construction Activities
9/2/2011	EP269-EP273	0	Site clearance survey
9/2/2011	EP256-EP263A, AER and Fromm Yards	0	Monitoring Construction Activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
9/2/2011	EP256-EP263A, AER and Fromm Yards	0	Site clearance survey
9/2/2011	EP278-EP294	0	Evening perimeter survey
9/2/2011	EP278-EP294	0	Monitoring Construction Activities
9/2/2011	EP278-EP294	0	Morning perimeter survey
9/2/2011	EP269-EP272	0	Monitoring Construction Activities
9/2/2011	EP269-EP272	0	Site clearance survey
9/2/2011	EP263B-EP267	0	Site clearance survey
9/1/2011	I-8 Island	12	Evening perimeter survey 4:45pm - 5:40pm
9/1/2011	I-8 Island	12	Morning perimeter survey 8:35am
9/1/2011	EP300-EP312	0	Monitoring Construction Activities
9/1/2011	EP300-EP312	0	Site clearance survey
9/1/2011	EP269-EP273	0	Monitoring Construction Activities
9/1/2011	EP269-EP273	0	Site clearance survey
9/1/2011	EP256-EP263A-2	0	Site clearance survey
9/1/2011	EP255	0	Monitoring Construction Activities
9/1/2011	EP300-EP306	0	Site clearance survey
9/1/2011	EP278-EP294	0	Evening perimeter survey
9/1/2011	EP278-EP294	0	Monitoring Construction Activities
9/1/2011	EP278-EP294	0	Morning perimeter survey
9/1/2011	EP269-EP272	0	Monitoring Construction Activities
9/1/2011	EP269-EP272	0	Site clearance survey
9/1/2011	EP263B-EP267	0	Site clearance survey
8/31/2011	I-8 Island	0	Site clearance survey
8/31/2011	EP308	0	Monitoring Construction Activities
8/31/2011	EP300-EP312	0	Monitoring Construction Activities
8/31/2011	EP300-EP312	0	Site clearance survey
8/31/2011	EP269-EP273	0	Monitoring Construction Activities
8/31/2011	EP269-EP273	0	Site clearance survey
8/31/2011	EP300-EP306	0	Site clearance survey
8/31/2011	EP278-EP294	0	Evening perimeter survey
8/31/2011	EP278-EP294	0	Monitoring Construction Activities
8/31/2011	EP278-EP294	0	Morning perimeter survey
8/31/2011	EP269-EP272	0	Monitoring Construction Activities
8/31/2011	EP263B-EP267	0	Site clearance survey
8/30/2011	I-8 Island	16	Evening perimeter survey 4:30pm

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
8/30/2011	I-8 Island	9	Morning perimeter survey 9:10am - 9:30am
8/30/2011	EP300-EP312	0	Monitoring Construction Activities
8/30/2011	EP300-EP312	0	Site clearance survey
8/30/2011	EP269-EP273	0	Monitoring Construction Activities
8/30/2011	EP269-EP273	0	Site clearance survey
8/30/2011	EP300-EP306	0	Site clearance survey
8/30/2011	EP278-EP294	0	Evening perimeter survey
8/30/2011	EP278-EP294	0	Monitoring Construction Activities
8/30/2011	EP278-EP294	0	Morning perimeter survey
8/30/2011	EP274-EP278	0	Monitoring Construction Activities
8/30/2011	EP274-EP278	0	Site clearance survey
8/30/2011	EP269-EP272	0	Monitoring Construction Activities
8/30/2011	EP269-EP272	0	Site clearance survey
8/30/2011	EP263B-EP267	0	Site clearance survey
8/29/2011	I-8 Island	4	Morning perimeter survey 8:55am
8/29/2011	I-8 Island	12	Evening perimeter survey 4:35pm to 5:00pm
8/29/2011	EP300-EP312	0	Monitoring Construction Activities
8/29/2011	EP300-EP312	0	Site clearance survey
8/29/2011	EP278-2	0	Monitoring Construction Activities
8/29/2011	EP269-EP273	0	Monitoring Construction Activities
8/29/2011	EP269-EP273	0	Site clearance survey
8/29/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/29/2011	EP300-EP306	0	Site clearance survey
8/29/2011	EP274-EP278	0	Monitoring Construction Activities
8/29/2011	EP274-EP278	0	Site clearance survey
8/29/2011	EP269-EP272	0	Monitoring Construction Activities
8/29/2011	EP269-EP272	0	Site clearance survey
8/29/2011	EP263B-EP267	0	Site clearance survey
8/28/2011	I-8 Island	15	Morning perimeter survey @9:22am
8/28/2011	EP305	0	Monitoring Construction Activities
8/28/2011	EP281	0	Monitoring Construction Activities
8/28/2011	EP273	0	Monitoring Construction Activities
8/28/2011	EP269-EP273	0	Monitoring Construction Activities
8/28/2011	EP269-EP273	0	Site clearance survey
8/28/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
8/28/2011	EP300-EP306	0	Morning perimeter survey
8/28/2011	EP278-EP294	0	Evening perimeter survey
8/28/2011	EP278-EP294	0	Monitoring Construction Activities
8/28/2011	EP278-EP294	0	Morning perimeter survey
8/28/2011	EP274-EP278	0	Monitoring Construction Activities
8/28/2011	EP274-EP278	0	Site clearance survey
8/28/2011	EP269-EP272	0	Monitoring Construction Activities
8/28/2011	EP269-EP272	0	Site clearance survey
8/28/2011	EP263-B, EP267	0	Site clearance survey
8/27/2011	I-8 Island	0	Site clearance survey
8/27/2011	EP305	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Site clearance survey
8/27/2011	I-8 Island	0	Morning perimeter survey
8/27/2011	EP305	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Site clearance survey
8/27/2011	EP300-EP306, EP269-EP273	0	Monitoring Construction Activities
8/27/2011	EP272-3	0	Monitoring Construction Activities
8/27/2011	EP261	0	Monitoring Construction Activities
8/27/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/27/2011	EP278-EP294	0	Site clearance survey
8/27/2011	EP278-EP294	0	Monitoring Construction Activities
8/27/2011	EP274-EP278	0	Site clearance survey
8/27/2011	EP274-EP278	0	Monitoring Construction Activities
8/27/2011	EP269-EP272	0	Monitoring Construction Activities
8/27/2011	EP269-EP272	0	Site clearance survey
8/27/2011	EP263B-EP267	0	Site clearance survey
8/26/2011	I-8 Island	0	Morning perimeter survey
8/26/2011	EP269-EP273	0	Monitoring Construction Activities
8/26/2011	EP269-EP273	0	Morning perimeter survey
8/26/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/26/2011	EP300-EP306	0	Monitoring Construction Activities
8/26/2011	EP278-EP294	0	Evening perimeter survey
8/26/2011	EP278-EP294	0	Monitoring Construction Activities
8/26/2011	EP278-EP294	0	Morning perimeter survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
8/26/2011	EP274-EP278	0	Monitoring Construction Activities
8/26/2011	EP274-EP278	0	Site clearance survey
8/26/2011	EP269-EP272	0	Monitoring Construction Activities
8/26/2011	EP269-EP272	0	Morning perimeter survey
8/25/2011	I-8 Island	0	Morning perimeter survey
8/25/2011	EP269-EP273	0	Monitoring Construction Activities
8/25/2011	EP269-EP273	0	Morning perimeter survey
8/25/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/25/2011	EP278-EP294	0	Evening perimeter survey
8/25/2011	EP278-EP294	0	Monitoring Construction Activities
8/25/2011	EP278-EP294	0	Morning perimeter survey
8/25/2011	EP274-EP278	0	Monitoring Construction Activities
8/25/2011	EP274-EP278	0	Site clearance survey
8/25/2011	EP270-EP272	0	Site clearance survey
8/25/2011	EP269-EP272	0	Monitoring Construction Activities
8/25/2011	EP269-EP272	0	Morning perimeter survey
8/24/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/24/2011	EP300-EP312, EP263B-EP267	0	Site clearance survey
8/24/2011	EP269-EP273	0	Monitoring Construction Activities
8/24/2011	EP269-EP273	0	Site clearance survey
8/24/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/24/2011	EP278-EP294	0	Evening perimeter survey
8/24/2011	EP278-EP294	0	Monitoring Construction Activities
8/24/2011	EP278-EP294	0	Morning perimeter survey
8/24/2011	EP274-EP278	0	Monitoring Construction Activities
8/24/2011	EP274-EP278	0	Site clearance survey
8/23/2011	I-8 Island	0	Morning perimeter survey
8/23/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/23/2011	EP300-EP312, EP263B-EP267	0	Site clearance survey
8/23/2011	EP269-EP273	0	Monitoring Construction Activities
8/23/2011	EP269-EP273	0	Site clearance survey
8/23/2011	EP278-EP294	0	Evening perimeter survey
8/23/2011	EP278-EP294	0	Monitoring Construction Activities
8/23/2011	EP278-EP294	0	Morning perimeter survey
8/23/2011	EP274-EP278	0	Monitoring Construction Activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
8/23/2011	EP274-EP278	0	Morning perimeter survey
8/23/2011	EP270-EP272	0	Morning perimeter survey
8/23/2011	EP269-EP272	0	Morning perimeter survey
8/22/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/22/2011	EP300-EP312, EP263B-EP267	0	Morning perimeter survey
8/22/2011	EP269-EP273	0	Monitoring Construction Activities
8/22/2011	EP269-EP273	0	Monitoring Construction Activities
8/22/2011	EP269-EP273	0	Morning perimeter survey
8/22/2011	EP263B	0	Monitoring Construction Activities
8/22/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/22/2011	EP291	0	Monitoring Construction Activities
8/22/2011	EP278-EP294	0	Evening perimeter survey
8/22/2011	EP278-EP294	0	Monitoring Construction Activities
8/22/2011	EP278-EP294	0	Morning perimeter survey
8/21/2011	I-8 Island	11	Evening perimeter survey - 6:00pm
8/21/2011	EP269-EP273	0	Site clearance survey
8/21/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/21/2011	EP256-EP263	0	Monitoring Construction Activities
8/21/2011	EP256-EP263	0	Site clearance survey
8/21/2011	EP279-EP294	0	Afternoon clearance survey
8/21/2011	EP274-EP278	0	Evening perimeter survey
8/21/2011	EP269-EP272	0	Evening perimeter survey
8/21/2011	EP263B-EP267	0	Site clearance survey
8/20/2011	I8 and Moutain Spring Rd	3	Morning perimeter survey 9:20am
8/20/2011	I8 and Moutain Spring Rd	4	Evening perimeter survey 6:40pm
8/20/2011	EP300-EP312	0	Monitoring construction activities
8/20/2011	EP300-EP312	0	Site clearance survey
8/20/2011	EP269-EP273	0	Monitoring construction activities
8/20/2011	EP269-EP273	0	Site clearance survey
8/20/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/20/2011	EP300-EP306	0	Morning perimeter survey
8/20/2011	EP274-EP294	0	Monitoring construction activities
8/20/2011	EP274-EP294	0	Site clearance survey
8/20/2011	EP270-EP271	0	Morning perimeter survey
8/20/2011	EP269-EP271	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
8/20/2011	EP263B-EP267	0	Site clearance survey
8/19/2011	Radiator Water Tower 17	7	Site clearance survey
8/19/2011	EP298, EP300 & EP307	0	Site clearance survey
8/19/2011	EP296, EP300	0	Monitoring construction activities
8/19/2011	EP296, EP300	0	Site clearance survey
8/19/2011	EP269-EP273	0	Monitoring construction activities
8/19/2011	EP269-EP273	0	Site clearance survey
8/19/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/19/2011	EP291-EP293	0	Monitoring construction activities
8/19/2011	EP279-EP294	0	Monitoring construction activities
8/19/2011	EP274-EP278	0	Monitoring construction activities
8/19/2011	EP274-EP278	0	Site clearance survey
8/19/2011	EP263B-EP267	0	Site clearance survey
8/18/2011	EP269-EP273	0	Monitoring construction activities
8/18/2011	EP269-EP273	0	Site clearance survey
8/18/2011	EP349, EP293	0	Monitoring construction activities
8/18/2011	EP279-EP312	0	Monitoring construction activities
8/18/2011	EP274-EP278	0	Monitoring construction activities
8/18/2011	EP274-EP278	0	Site clearance survey
8/18/2011	EP263B-EP267	0	Site clearance survey
8/17/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/17/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/17/2011	EP269-EP273	0	Monitoring construction activities
8/17/2011	EP269-EP273	0	Site clearance survey
8/17/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/17/2011	EP279-EP294	0	Monitoring construction activities
8/17/2011	EP279-EP294	0	Site clearance survey
8/17/2011	EP274-EP278	0	Monitoring construction activities
8/17/2011	EP274-EP278	0	Site clearance survey
8/17/2011	EP263B-EP267	0	Site clearance survey
8/16/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/16/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/16/2011	EP269-EP273	0	Monitoring construction activities
8/16/2011	EP269-EP273	0	Site clearance survey
8/16/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
8/16/2011	EP279-EP294	0	Monitoring construction activities
8/16/2011	EP279-EP294	0	Site clearance survey
8/16/2011	EP274-EP278	0	Monitoring construction activities
8/16/2011	EP274-EP278	0	Site clearance survey
8/16/2011	EP265	0	Monitoring construction activities
8/16/2011	EP263B-EP267	0	Site clearance survey
8/15/2011	Fromm and AER Construction Yard	0	Monitoring construction activities
8/15/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/15/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/15/2011	EP294	0	Monitoring construction activities
8/15/2011	EP269-EP273	0	Site clearance survey
8/15/2011	EP269-EP273	0	Monitoring construction activities
8/15/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/15/2011	EP279-EP294	0	Monitoring construction activities
8/15/2011	EP279-EP294	0	Site clearance survey
8/15/2011	EP274-EP278	0	Monitoring construction activities
8/15/2011	EP274-EP278	0	Site clearance survey
8/15/2011	EP263B-EP267	0	Site clearance survey
8/14/2011	EP274-EP278	0	Monitoring construction activities
8/14/2011	EP263B-EP267	0	Site clearance survey
8/14/2011	EP274-EP278	0	Evening perimeter survey
8/14/2011	EP279-294	0	Monitoring construction activities
8/14/2011	EP269-EP273	0	Evening perimeter survey
8/14/2011	EP300-EP312	0	Site clearance survey
8/14/2011	EP300-EP312	0	Monitoring construction activities
8/13/2011	Fromm Construction Yard	0	Site clearance survey
8/13/2011	I-8 Island	19	Morning perimeter survey at 9:54am - 10:45am
8/13/2011	I-8 Island	6	Evening perimeter survey at 4:35pm
8/13/2011	EP263B-EP267	0	Site clearance survey
8/13/2011	EP269-EP271	0	Monitoring construction activities
8/13/2011	EP270-EP271	0	Monitoring construction activities
8/13/2011	EP274-EP278	0	Monitoring construction activities
8/13/2011	EP279-294	0	Monitoring construction activities
8/13/2011	EP300-EP306	0	Monitoring construction activities
8/13/2011	EP259B	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
8/13/2011	EP269-EP273	0	Monitoring construction activities
8/13/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/13/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/12/2011	I-8 Island	26	Evening perimeter survey at 4:25pm - 5:45
8/12/2011	EP263B-EP267	0	Site clearance survey
8/12/2011	EP269-EP271	0	Monitoring construction activities
8/12/2011	EP270-EP271	0	Monitoring construction activities
8/12/2011	EP279-294	0	Monitoring construction activities
8/12/2011	EP300-EP306	0	Monitoring construction activities
8/12/2011	EP300-EP312	0	Monitoring construction activities
8/12/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/12/2011	EP259B	0	Site clearance survey
8/12/2011	EP269-EP273	0	Monitoring construction activities
8/12/2011	EP274-EP278, EP290-EP294	0	Site clearance survey
8/12/2011	EP274-EP278, EP290-EP294	0	Monitoring construction activities
8/12/2011	EP294	0	Monitoring construction activities
8/11/2011	I-8 Island	12	Morning perimeter survey at 10:50am
8/11/2011	I-8 Island	28	Evening perimeter survey at 6:19pm
8/11/2011	EP263B-EP267	0	Site clearance survey
8/11/2011	EP269-EP271	0	Monitoring construction activities
8/11/2011	EP270-EP271	0	Monitoring construction activities
8/11/2011	EP279-294	0	Monitoring construction activities
8/11/2011	EP300-EP306	0	Monitoring construction activities
8/11/2011	EP300-EP312	0	Monitoring construction activities
8/11/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/11/2011	EP259B	0	Site clearance survey
8/11/2011	EP269-EP273	0	Monitoring construction activities
8/11/2011	EP274-EP278	0	Site clearance survey
8/11/2011	EP274-EP278	0	Monitoring construction activities
8/11/2011	EP292-EP356	0	Monitoring construction activities
8/11/2011	EP294	0	Monitoring construction activities
8/10/2011	I-8 Island	16	Evening perimeter survey at 4:55pm - 5:08
8/10/2011	EP263B-EP267	0	Site clearance survey
8/10/2011	EP269-EP271	0	Monitoring construction activities
8/10/2011	EP270-EP271	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
8/10/2011	EP273	0	Monitoring construction activities
8/10/2011	EP300-EP306	0	Monitoring construction activities
8/10/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/10/2011	EP259B	0	Site clearance survey
8/10/2011	EP269-EP273	0	Monitoring construction activities
8/10/2011	EP294	0	Monitoring construction activities
8/10/2011	EP300-EP312	0	Morning perimeter survey
8/10/2011	EP300-EP312	0	Monitoring construction activities
8/10/2011	EP300-EP312	0	Evening perimeter survey
8/10/2011	EP227, EP232, EP258, EP314, EP317, EP348, EP349	0	Site clearance survey
8/9/2011	I-8 Island	3	Morning perimeter survey at 10:30am
8/9/2011	I-8 Island	18	Evening perimeter survey at 4:30pm - 5:06pm
8/9/2011	EP263B-EP267	0	Site clearance survey
8/9/2011	EP269-EP271	0	Monitoring construction activities
8/9/2011	EP270-EP271	0	Monitoring construction activities
8/9/2011	EP270-EP273	0	Monitoring construction activities
8/9/2011	EP274-EP278	0	Monitoring construction activities
8/9/2011	EP279-294	0	Monitoring construction activities
8/9/2011	EP300-EP306	0	Monitoring construction activities
8/9/2011	EP305	0	Monitoring construction activities
8/9/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/9/2011	EP269-EP273	0	Site clearance survey
8/9/2011	EP294	0	Monitoring construction activities
8/9/2011	EP300-EP312	0	Morning perimeter survey
8/9/2011	EP300-EP312	0	Monitoring construction activities
8/9/2011	EP300-EP312	0	Evening perimeter survey
8/8/2011	I-8 Island	4	Morning perimeter survey at 9:45am - 9:55am
8/8/2011	I-8 Island	22	Evening perimeter survey at 4:24pm - 5:14pm
8/8/2011	EP279-294	3	Monitoring construction activities
8/8/2011	EP263B-EP267	0	Site clearance survey
8/8/2011	EP269-EP271	0	Monitoring construction activities
8/8/2011	EP270-EP271	0	Monitoring construction activities
8/8/2011	EP273	0	Monitoring construction activities
8/8/2011	EP274-EP278	0	Monitoring construction activities
8/8/2011	EP300-EP306	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
8/8/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/8/2011	EP269-EP273	0	Site clearance survey
8/8/2011	EP294	0	Monitoring construction activities
8/8/2011	EP300-EP312	0	Morning perimeter survey
8/8/2011	EP300-EP312	0	Monitoring construction activities
8/8/2011	EP300-EP312	0	Evening perimeter survey
8/8/2011	EP301-EP324, EP259-3, EP259B	0	Monitoring construction activities
8/8/2011	EP290-EP300	0	Site clearance survey
8/7/2011	I-8 Island	27	Evening perimeter survey at 6:00pm - 6:45
8/7/2011	EP263B-EP267	0	Site clearance survey
8/7/2011	EP270-EP271	0	Monitoring construction activities
8/7/2011	EP274-EP278	0	Monitoring construction activities
8/7/2011	EP279-294	0	Monitoring construction activities
8/7/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/7/2011	EP269-EP273	0	Evening perimeter survey
8/7/2011	EP300-EP312	0	Evening perimeter survey
8/6/2011	EP278 & EP277	0	Monitoring construction activities
8/6/2011	I-8 Island	12	Afternoon perimeter survey at 1:20pm
8/6/2011	EP263B-EP267	0	Site clearance survey
8/6/2011	EP269-EP271	0	Monitoring construction activities
8/6/2011	EP270-EP271	0	Monitoring construction activities
8/6/2011	EP274-EP278	0	Monitoring construction activities
8/6/2011	EP279-294	0	Monitoring construction activities
8/6/2011	EP300-EP306	0	Monitoring construction activities
8/6/2011	EP262, EP266, EP267	0	Site clearance survey
8/6/2011	EP269-EP273	0	Monitoring construction activities
8/6/2011	EP307-EP315	0	Morning perimeter survey
8/6/2011	EP307-EP316	0	Monitoring construction activities
8/6/2011	EP307-EP317	0	Evening perimeter survey
8/5/2011	EP263B-EP267	0	Site clearance survey
8/5/2011	EP271, EP273, EP274, EP277 and EP278	0	Monitoring construction activities
8/5/2011	EP274-EP278	0	Monitoring construction activities
8/5/2011	EP279-294	0	Monitoring construction activities
8/5/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/5/2011	EP269-EP273	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
8/5/2011	EP294	0	Monitoring construction activities
8/5/2011	EP307-EP312	0	Morning perimeter survey
8/5/2011	EP307-EP313	0	Monitoring construction activities
8/5/2011	EP307-EP314	0	Evening perimeter survey
8/4/2011	I-8 Island	23	Evening perimeter survey at 4:00pm - 4:33pm
8/4/2011	EP263B-EP267	0	Site clearance survey
8/4/2011	EP269-EP271	0	Monitoring construction activities
8/4/2011	EP270-EP271	0	Monitoring construction activities
8/4/2011	EP274-EP278	0	Monitoring construction activities
8/4/2011	EP279-294	0	Monitoring construction activities
8/4/2011	EP300-EP306	0	Monitoring construction activities
8/4/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/4/2011	EP269-EP273	0	Monitoring construction activities
8/4/2011	EP294	0	Monitoring construction activities
8/3/2011	I-8 Island	17	Evening perimeter survey at 5:45pm - 6:05pm
8/3/2011	EP256-EP263	0	Monitoring construction activities
8/3/2011	EP263B-EP267	0	Site clearance survey
8/3/2011	EP269-EP271	0	Monitoring construction activities
8/3/2011	EP270-EP271	0	Monitoring construction activities
8/3/2011	EP274-EP278	0	Monitoring construction activities
8/3/2011	EP279-294	0	Monitoring construction activities
8/3/2011	EP290-EP312	0	Monitoring construction activities
8/3/2011	EP300-EP306	0	Monitoring construction activities
8/3/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/3/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
8/3/2011	EP269-EP273	0	Monitoring construction activities
8/3/2011	EP271	0	Monitoring construction activities
8/3/2011	EP294	0	Monitoring construction activities
8/3/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/3/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/3/2011	I-8 Island	0	Monitoring construction activities
8/2/2011	I-8 Island	12	Morning perimeter survey at 9:50am
8/2/2011	I-8 Island	23	Evening perimeter survey at 4:30pm
8/2/2011	EP263B-EP267	0	Site clearance survey
8/2/2011	EP269-EP271	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
8/2/2011	EP270-EP271	0	Monitoring construction activities
8/2/2011	EP279-294	0	Monitoring construction activities
8/2/2011	EP300-EP306	0	Monitoring construction activities
8/2/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
8/2/2011	EP269-EP273	0	Monitoring construction activities
8/2/2011	EP271 and EP273	0	Monitoring construction activities
8/2/2011	EP273	0	Monitoring construction activities
8/2/2011	EP274-EP278	0	Monitoring construction activities
8/2/2011	EP294	0	Monitoring construction activities
8/1/2011	I-8 Island	19	Morning perimeter survey at 10:00 - 10:20am
8/1/2011	I-8 Island	1	Evening perimeter survey at 4:30pm
8/1/2011	EP263B-EP267	0	Site clearance survey
8/1/2011	EP269-EP271	0	Monitoring construction activities
8/1/2011	EP270-EP271	0	Monitoring construction activities
8/1/2011	EP274-EP278	0	Monitoring construction activities
8/1/2011	EP279-294	0	Monitoring construction activities
8/1/2011	EP290-EP312	0	Monitoring construction activities
8/1/2011	EP300-EP306	0	Monitoring construction activities
8/1/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/1/2011	EP269	0	Monitoring construction activities
8/1/2011	EP269-EP273	0	Monitoring construction activities
8/1/2011	EP272	0	Monitoring construction activities
8/1/2011	EP291 & EP301-EP304	0	Monitoring construction activities
8/1/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/1/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
7/31/2011	I-8 Island	24	Evening perimeter survey at 5:55pm
7/31/2011	EP263B-EP267	0	Site clearance survey
7/31/2011	EP270-EP271	0	Monitoring construction activities
7/31/2011	EP274-EP278	0	Monitoring construction activities
7/31/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/31/2011	EP269-EP273	0	Evening perimeter survey
7/31/2011	EP279-EP294	0	Site clearance survey
7/31/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
7/30/2011	EP271	1	Morning perimeter survey at 7:00am

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
7/30/2011	EP256-EP263A-2, AER Yard	6	Monitoring during construction activities. These sheep were outside of all work areas and associated buffers and did not impact work.
7/30/2011	I-8 Island	11	Morning perimeter survey at 10:15am - 11:07
7/30/2011	I-8 Island	7	Evening perimeter survey at 4:12pm
7/30/2011	EP263B-EP267	0	Site clearance survey
7/30/2011	EP269	0	Site clearance survey
7/30/2011	EP269-EP272	0	Monitoring construction activities
7/30/2011	EP270-EP271	0	Monitoring construction activities
7/30/2011	EP274-EP278	0	Monitoring construction activities
7/30/2011	EP279-294	0	Monitoring construction activities
7/30/2011	EP300-EP306	0	Monitoring construction activities
7/30/2011	EP269	0	Monitoring construction activities
7/30/2011	EP269-EP273	0	Site clearance survey
7/30/2011	EP270-EP271	0	Monitoring construction activities
7/30/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
7/30/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
7/29/2011	I-8 Island	14	Morning perimeter survey at 8:55am
7/29/2011	I-8 Island	2	Evening perimeter survey at 4:00pm
7/29/2011	EP263B-EP267	0	Site clearance survey
7/29/2011	EP269	0	Site clearance survey
7/29/2011	EP269-EP272	0	Monitoring construction activities
7/29/2011	EP270-EP271	0	Monitoring construction activities
7/29/2011	EP274-EP278	0	Monitoring construction activities
7/29/2011	EP279-294	0	Monitoring construction activities
7/29/2011	EP300-EP306	0	Monitoring construction activities
7/29/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/29/2011	EP269	0	Monitoring construction activities
7/29/2011	EP269-EP273	0	Site clearance survey
7/29/2011	EP270	0	Monitoring construction activities
7/29/2011	EP300-EP312	0	Morning perimeter survey
7/29/2011	EP300-EP312	0	Monitoring construction activities
7/29/2011	EP300-EP312	0	Evening perimeter survey
7/29/2011	EP303	0	Monitoring construction activities
7/28/2011	EP269	4	Monitoring during construction activities
7/28/2011	I-8 Island	11	Morning perimeter survey at 9:19am

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
7/28/2011	I-8 Island	8	Evening perimeter survey at 4:00pm - 4:50pm
7/28/2011	EP279-294	0	Monitoring construction activities
7/28/2011	EP263B-EP267	0	Site clearance survey
7/28/2011	EP269	0	Site clearance survey
7/28/2011	EP270-EP271	0	Monitoring construction activities
7/28/2011	EP274-EP278	0	Monitoring construction activities
7/28/2011	EP300-EP306	0	Monitoring construction activities
7/28/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/28/2011	EP269	0	Monitoring construction activities
7/28/2011	EP270	0	Monitoring construction activities
7/28/2011	EP300-EP312	0	Morning perimeter survey
7/28/2011	EP300-EP312	0	Monitoring construction activities
7/28/2011	EP300-EP312	0	Evening perimeter survey
7/28/2011	AER CY	0	Site clearance survey
7/27/2011	I-8 Island	13	Evening perimeter survey at 6:30pm - 7:00pm
7/27/2011	EP279-294	0	Monitoring construction activities
7/27/2011	EP263B-EP267	0	Site clearance survey
7/27/2011	EP268 - EP263	0	Monitoring construction activities
7/27/2011	EP269	0	Site clearance survey
7/27/2011	EP270-EP271	0	Monitoring construction activities
7/27/2011	EP274-EP278	0	Monitoring construction activities
7/27/2011	EP300-EP306	0	Monitoring construction activities
7/27/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/27/2011	EP269-EP273	0	Morning perimeter survey
7/27/2011	EP269-EP273	0	Evening perimeter survey
7/27/2011	EP300-EP312	0	Morning perimeter survey
7/27/2011	EP300-EP312	0	Monitoring construction activities
7/27/2011	EP300-EP312	0	Evening perimeter survey
7/26/2011	Devils Canyon Bridge1, Hwy 8	1	Monitoring during construction activities
7/26/2011	I-8 Island	24	Morning perimeter survey at 9:46am - 10:45am
7/26/2011	I-8 Island	7	Evening perimeter survey at 6:17pm - 6:50pm
7/26/2011	EP263B-EP267	0	Site clearance survey
7/26/2011	EP269	0	Site clearance survey
7/26/2011	EP270	0	Monitoring construction activities
7/26/2011	EP274-EP278	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
7/26/2011	EP279-294	0	Monitoring construction activities
7/26/2011	EP300-EP306	0	Monitoring construction activities
7/26/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/26/2011	EP269-EP273	0	Morning perimeter survey
7/26/2011	EP269-EP273	0	Evening perimeter survey
7/26/2011	EP300-EP312	0	Monitoring construction activities
7/26/2011	EP300-EP312	0	Morning perimeter survey
7/26/2011	EP300-EP312	0	Monitoring construction activities
7/26/2011	EP300-EP312	0	Evening perimeter survey
7/25/2011	I-8 Island	21	Morning perimeter survey at 8:47am
7/25/2011	I-8 Island	20	Evening perimeter survey at 6:37am
7/25/2011	EP263B-EP267	0	Site clearance survey
7/25/2011	EP269	0	Site clearance survey
7/25/2011	EP270	0	Monitoring construction activities
7/25/2011	EP274-EP278	0	Monitoring construction activities
7/25/2011	EP279-294	0	Monitoring construction activities
7/25/2011	EP300-EP306	0	Monitoring construction activities
7/25/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/25/2011	EP269-EP273	0	Morning perimeter survey
7/25/2011	EP269-EP273	0	Evening perimeter survey
7/25/2011	EP300 & EP302	0	Monitoring construction activities
7/25/2011	EP300-EP312	0	Morning perimeter survey
7/25/2011	EP300-EP312	0	Monitoring construction activities
7/25/2011	EP300-EP312	0	Evening perimeter survey
7/25/2011	EP276	0	Monitoring construction activities
7/24/2011	I-8 Island	13	Evening perimeter survey at 6:25pm
7/24/2011	EP263B-EP267	0	Site clearance survey
7/24/2011	EP269	0	Site clearance survey
7/24/2011	EP270	0	Monitoring construction activities
7/24/2011	EP279-294	0	Monitoring construction activities
7/24/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/24/2011	EP269-EP273	0	Evening perimeter survey
7/24/2011	EP274-EP278	0	Evening perimeter survey
7/24/2011	EP300-EP312	0	Evening perimeter survey
7/23/2011	EP263B-EP267	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
7/23/2011	EP269	0	Site clearance survey
7/23/2011	EP270	0	Monitoring construction activities
7/23/2011	EP279-294	0	Monitoring construction activities
7/23/2011	EP300-EP312	0	Monitoring construction activities
7/23/2011	EP300-EP312	0	Site clearance survey
7/23/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/23/2011	EP269-EP276	0	Morning perimeter survey
7/23/2011	EP274-EP278	0	Morning perimeter survey
7/23/2011	EP274-EP278	0	Evening perimeter survey
7/23/2011	I-8 Island	0	Morning perimeter survey
7/22/2011	I-8 Island	18	Evening perimeter survey at 6:35pm
7/22/2011	EP263B-EP267	0	Site clearance survey
7/22/2011	EP269	0	Site clearance survey
7/22/2011	EP269-EP270	0	Monitoring construction activities
7/22/2011	EP270	0	Monitoring construction activities
7/22/2011	EP300-EP312	0	Monitoring construction activities
7/22/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/22/2011	EP269-EP273	0	Morning perimeter survey
7/22/2011	EP269-EP273	0	Evening perimeter survey
7/22/2011	EP274-EP278	0	Site clearance survey
7/22/2011	EP274-EP278	0	Monitoring construction activities
7/21/2011	I-8 Island	18	Evening perimeter survey at 6:35pm
7/21/2011	EP263B-EP267	0	Site clearance survey
7/21/2011	EP269	0	Site clearance survey
7/21/2011	EP269-EP270	0	Monitoring construction activities
7/21/2011	EP270	0	Monitoring construction activities
7/21/2011	EP279-294	0	Monitoring construction activities
7/21/2011	EP300-EP312	0	Monitoring construction activities
7/21/2011	EP300-EP306	0	Site clearance survey
7/21/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/21/2011	EP269-EP273	0	Morning perimeter survey
7/21/2011	EP269-EP273	0	Evening perimeter survey
7/21/2011	EP274-EP278	0	Morning perimeter survey
7/21/2011	EP274-EP278	0	Evening perimeter survey
7/20/2011	I-8 Island	4	Evening perimeter survey at 6:50pm

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
7/20/2011	EP269-EP273	0	Morning perimeter survey
7/20/2011	EP269-EP273	0	Evening perimeter survey
7/20/2011	EP263B-EP267	0	Site clearance survey
7/20/2011	EP269	0	Site clearance survey
7/20/2011	EP270	0	Monitoring construction activities
7/20/2011	EP279-294	0	Monitoring construction activities
7/20/2011	EP300-EP312	0	Monitoring construction activities
7/20/2011	EP300-EP306	0	Site clearance survey
7/20/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/20/2011	EP274-EP278	0	Morning perimeter survey
7/20/2011	EP274-EP278	0	Evening perimeter survey
7/19/2011	I-8 Island	10	Morning perimeter survey at 9:10am
7/19/2011	I-8 Island	17	Evening perimeter survey at 4:00pm - 6:40pm
7/19/2011	EP269-EP273	0	Morning perimeter survey
7/19/2011	EP269-EP273	0	Evening perimeter survey
7/19/2011	EP269	0	Site clearance survey
7/19/2011	EP270	0	Monitoring construction activities
7/19/2011	EP279-294	0	Monitoring construction activities
7/19/2011	EP300-EP312	0	Monitoring construction activities
7/19/2011	EP300-EP306	0	Site clearance survey
7/19/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/19/2011	EP274-EP278	0	Morning perimeter survey
7/19/2011	EP274-EP278	0	Evening perimeter survey
7/19/2011	EP263B-EP267	0	Site clearance survey
7/18/2011	I-8 Island	21	Evening perimeter survey at 7:10pm
7/18/2011	EP263B-EP267	0	Site clearance survey
7/18/2011	EP269	0	Site clearance survey
7/18/2011	EP270	0	Monitoring construction activities
7/18/2011	EP279-294	0	Monitoring construction activities
7/18/2011	EP300-EP312	0	Monitoring construction activities
7/18/2011	EP300-EP306	0	Site clearance survey
7/18/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/18/2011	EP274-EP278	0	Morning perimeter survey
7/18/2011	EP274-EP278	0	Evening perimeter survey
7/18/2011	EP269-EP273	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
7/17/2011	I-8 Island	17	Evening perimeter survey at 5:55pm - 6:25
7/17/2011	EP263B-EP267	0	Site clearance survey
7/17/2011	EP269	0	Site clearance survey
7/17/2011	EP270	0	Monitoring construction activities
7/17/2011	EP300-EP312	0	Monitoring construction activities
7/17/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/17/2011	EP274-EP278	0	Evening perimeter survey
7/17/2011	EP279-EP294	0	Site clearance survey
7/17/2011	EP269-EP273	0	Site clearance survey
7/16/2011	I-8 Island	1	Morning perimeter survey at 8:35am
7/16/2011	EP263B-EP267	0	Site clearance survey
7/16/2011	EP269	0	Site clearance survey
7/16/2011	EP270	0	Monitoring construction activities
7/16/2011	EP300-EP306	0	Monitoring construction activities
7/16/2011	EP300-EP312	0	Monitoring construction activities
7/16/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/16/2011	EP274-EP278	0	Morning perimeter survey
7/16/2011	EP279-EP294	0	Morning perimeter survey
7/16/2011	EP279-EP294	0	Site clearance survey
7/16/2011	EP279-EP294	0	Monitoring construction activities
7/16/2011	EP269-EP273	0	Site clearance survey
7/15/2011	EP273-1	1	Evening perimeter survey at 4:30pm
7/15/2011	I-8 Island	12	Evening perimeter survey at 6:35pm - 7:00pm
7/15/2011	EP263B-EP267	0	Site clearance survey
7/15/2011	EP269	0	Site clearance survey
7/15/2011	EP270	0	Monitoring construction activities
7/15/2011	EP279-294	0	Monitoring construction activities
7/15/2011	EP300-EP306	0	Monitoring construction activities
7/15/2011	EP300-EP312	0	Monitoring construction activities
7/15/2011	EP256-EP263A-2, AER Yard	0	Site clearance survey
7/15/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/15/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/15/2011	EP269-EP273	0	Site clearance survey
7/15/2011	EP274-EP278	0	Morning perimeter survey
7/15/2011	EP274-EP278	0	Evening perimeter survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
7/14/2011	I-8 Island	3	Evening perimeter survey at 4:10pm
7/14/2011	I-8 Island		7:15am - 9:30am PBHS were at above point
7/14/2011	EP263B-EP267	0	Site clearance survey
7/14/2011	EP269	0	Site clearance survey
7/14/2011	EP270	0	Monitoring construction activities
7/14/2011	EP279-294	0	Monitoring construction activities
7/14/2011	EP300-EP306	0	Monitoring construction activities
7/14/2011	EP300-EP312	0	Monitoring construction activities
7/14/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/14/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/14/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/14/2011	EP274-EP278	0	Morning perimeter survey
7/14/2011	EP274-EP278	0	Evening perimeter survey
7/14/2011	EP269-EP273	0	Site clearance survey
7/13/2011	I-8 Island	21	Evening perimeter survey at 4:40pm
7/13/2011	EP263B-EP267	0	Site clearance survey
7/13/2011	EP269	0	Site clearance survey
7/13/2011	EP270	0	Monitoring construction activities
7/13/2011	EP279-294	0	Monitoring construction activities
7/13/2011	EP300-EP306	0	Monitoring construction activities
7/13/2011	EP300-EP312	0	Monitoring construction activities
7/13/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/13/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/13/2011	EP269-EP273	0	Site clearance survey
7/12/2011	EP256-EP263A-2, AER Yard	15	Monitoring during construction activities @ 7:40am - 11:00am
7/12/2011	I-8 Island	17	Evening perimeter survey at 4:00pm
7/12/2011	EP263B-EP267	0	Site clearance survey
7/12/2011	EP269	0	Site clearance survey
7/12/2011	EP270	0	Monitoring construction activities
7/12/2011	EP279-294	0	Monitoring construction activities
7/12/2011	EP300-EP306	0	Monitoring construction activities
7/12/2011	EP300-EP312	0	Monitoring construction activities
7/12/2011	EP274-EP278	0	Morning perimeter survey
7/12/2011	EP274-EP278	0	Evening perimeter survey
7/12/2011	EP269-EP273	0	Site clearance survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
7/11/2011	I-8 Island	29	Evening perimeter survey at 4:40pm
7/11/2011	EP263B-EP267	0	Site clearance survey
7/11/2011	EP269	0	Site clearance survey
7/11/2011	EP270	0	Monitoring construction activities
7/11/2011	EP279-294	0	Monitoring construction activities
7/11/2011	EP300-EP306	0	Monitoring construction activities
7/11/2011	EP300-EP312	0	Monitoring construction activities
7/11/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/11/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/11/2011	EP269-EP273	0	Site clearance survey
7/11/2011	EP274-EP278	0	Morning perimeter survey
7/11/2011	EP274-EP278	0	Evening perimeter survey
7/10/2011	I-8 Island	8	Perimeter survey
7/10/2011	I-8 Island	20	Monitoring construction activities
7/10/2011	EP269	0	Site clearance survey
7/10/2011	EP270	0	Monitoring construction activities
7/10/2011	EP279-294	0	Monitoring construction activities
7/10/2011	EP300-EP312	0	Monitoring construction activities
7/10/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/10/2011	EP274-EP278, EP265-EP267	0	Site clearance survey
7/9/2011	EP263A-2	11	Evening perimeter survey
7/9/2011	EP263B-EP267	0	Site clearance survey
7/9/2011	EP269-EP274	0	Monitoring construction activities
7/9/2011	EP279-294	0	Monitoring construction activities
7/9/2011	EP300-EP307	0	Monitoring construction activities
7/9/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/9/2011	EP269-EP273	0	Site clearance survey
7/9/2011	EP274-EP278	0	Morning perimeter survey
7/9/2011	EP310	0	Monitoring construction activities
7/8/2011	EP263B-EP267	0	Site clearance survey
7/8/2011	EP300-EP312	0	Monitoring construction activities
7/8/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/8/2011	EP269-EP273	0	Site clearance survey
7/8/2011	EP274-EP278	0	Morning perimeter survey
7/8/2011	EP274-EP278	0	Evening perimeter survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
7/8/2011	EP303	0	Monitoring construction activities
7/8/2011	EP279-EP294	0	Monitoring construction activities
7/7/2011	I-8 Island	8	Evening perimeter survey at 7:00pm
7/7/2011	EP263B-EP267	0	Site clearance survey
7/7/2011	EP269-EP273	0	Monitoring construction activities
7/7/2011	EP300-EP312	0	Monitoring construction activities
7/7/2011	EP300-EP307	0	Monitoring construction activities
7/7/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/7/2011	EP269-EP273	0	Site clearance survey
7/7/2011	EP274-EP278	0	Morning perimeter survey
7/7/2011	EP274-EP278	0	Evening perimeter survey
7/7/2011	EP303 & EP304	0	Monitoring construction activities
7/7/2011	EP306-EP312	0	Site clearance survey
7/6/2011	EP263A-2	2	Evening perimeter survey
7/6/2011	EP263B-EP267	0	Site clearance survey
7/6/2011	EP269-EP272	0	Monitoring construction activities
7/6/2011	EP300-EP312	0	Monitoring construction activities
7/6/2011	EP300-EP307	0	Monitoring construction activities
7/6/2011	EP303	0	Site clearance survey
7/6/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/6/2011	EP274-EP278	0	Morning perimeter survey
7/6/2011	EP274-EP278	0	Evening perimeter survey
7/6/2011	EP305 to EP304	0	Monitoring construction activities
7/6/2011	I-8 Island	0	Monitoring construction activities
7/6/2011	EP269-EP273	0	Site clearance survey
7/5/2011	EP270	14	Morning perimeter survey at 6:30am - 10:00am
7/5/2011	EP270	9	Evening perimeter survey at 5:00pm
7/5/2011	I-8 Island	7	Evening perimeter survey at 6:20pm
7/5/2011	EP269-EP273	0	Morning perimeter survey
7/5/2011	EP269-EP273	0	Evening perimeter survey
7/5/2011	EP263B-EP267	0	Site clearance survey
7/5/2011	EP269-EP271	0	Monitoring construction activities
7/5/2011	EP300-EP312	0	Monitoring construction activities
7/5/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/5/2011	EP274-EP278	0	Morning perimeter survey

**PBS Monitoring Report - Week Ending 11/12/2011**

Date	Location	Number observed	Comments
7/5/2011	EP274-EP278	0	Evening perimeter survey
7/5/2011	EP307 to EP305	0	Monitoring construction activities
7/5/2011	I-8 Island	0	Site clearance survey
7/4/2011	EP270	9	Perimeter survey
7/4/2011	EP263B-EP267	0	Site clearance survey
7/4/2011	EP300-EP312	0	Monitoring construction activities
7/4/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/4/2011	EP269-EP273	0	Site clearance survey
7/4/2011	EP274-EP278	0	Evening perimeter survey
7/4/2011	I-8 Island	0	Site clearance survey
7/2/2011	EP263B-EP267	0	Site clearance survey
7/2/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/2/2011	EP269-EP273	0	Site clearance survey
7/2/2011	EP274-EP278	0	Morning perimeter survey
7/2/2011	I-8 Island	0	Site clearance survey
7/1/2011	EP263B-EP267	0	Site clearance survey
7/1/2011	EP300-EP312	0	Monitoring construction activities
7/1/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/1/2011	EP269-EP273	0	Site clearance survey
7/1/2011	EP274-EP278	0	Morning perimeter survey
7/1/2011	EP274-EP278	0	Evening perimeter survey
7/1/2011	I-8 Island	0	Site clearance survey
6/30/2011	EP300-EP312	0	Monitoring construction activities
6/29/2011	EP310-EP312	0	Monitoring construction activities
4/15/2011	EP210, EP211, EP213-EP215, EP217-EP219	0	Monitoring construction activities
3/26/2011	EP105	0	Site clearance survey

Raven Control Monitoring Report - Week Ending 11/12/2011							
Date	Location	Number of Ravens observed	Raven Activity				
			Nesting	Flying	Perching	Roosting	Scavaging
11/12/2011	Dunaway CY	1			1		
11/11/2011	Dunaway CY	4					4
11/11/2011	S2 Yard	5					5
11/10/2011	Fromm CY	2					2
11/10/2011	EP355	1		1			
11/9/2011	Dunaway CY	1			1		
11/8/2011	S2 Yard	5			5		
11/8/2011	Dunaway CY	2			2		
11/7/2011	S2 Yard	3					3
11/7/2011	EP308-EP310	1					1
11/7/2011	EP301 Pullsite	7		6	1		
11/6/2011	No ravens observed						
11/5/2011	S2 Yard	7			7		
11/5/2011	IV Substation	1			1		
11/4/2011	S2 Yard	5			5		
11/3/2011	S2 Yard	5			3		2
11/3/2011	IV Substation	1			1		
11/3/2011	Fromm CY	1				1	
11/3/2011	EP303 and EP302	2			2		
11/3/2011	EP281	2			2		
11/2/2011	S2 Yard	4			4		
11/2/2011	IV Substation	1		1			
11/2/2011	EP305, EP310, EP311	1		1			
11/1/2011	S2 Yard	2			2		
11/1/2011	IV Substation	1		1			
11/1/2011	EP305 and EP312	1			1		
10/31/2011	S2 Yard	5			5		
10/31/2011	AER and Fromm CY	1				1	
10/30/2011	No ravens observed						
10/29/2011	IV Substation	3		3			
10/28/2011	IV Substation	1		1			
10/28/2011	EP256, EP357 & EP358	5		5			
10/27/2011	EP356, EP358 & EP362	2		2			
10/27/2011	EP305, EP307, EP310-	1		1			
10/26/2011	EP306, EP307 & EP310	2		2			
10/25/2011	IV Substation	1		1			
10/25/2011	EP310	1		1			
10/24/2011	S2 Yard	3					3
10/24/2011	EP305	1			1		
10/23/2011	S2 Yard	3			3		
10/22/2011	No ravens observed						
10/21/2011	Dunaway CY	1			1		
10/20/2011	S2 Yard	2					2
10/20/2011	Dunaway CY	5					5
10/19/2011	EP314	1		1			

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
10/19/2011	EP290	5		5				no
10/18/2011			No ravens observed					
10/17/2011	EP301	3		3				no
10/16/2011			No ravens observed					
10/15/2011	S2 Yard	2					2	no
10/15/2011	Dunaway CY	1				1		no
10/15/2011	EP315	2					2	no
10/15/2011	EP301	3			3			no
10/14/2011	Fromm CY	3				3		no
10/14/2011	EP305	2		2				no
10/14/2011	EP301	3			3			no
10/13/2011	S2 Yard	2					2	no
10/13/2011	Dunaway CY	5					5	no
10/13/2011	Fromm CY	1					1	no
10/13/2011	EP354-EP363	2			2			no
10/13/2011	EP301	4		4				no
10/12/2011	EP300-EP301	2		2				no
10/11/2011	Plaster City Yard	2			2			no
10/11/2011	IV Substation	2					2	no
10/10/2011	Fromm CY	2				2		no
10/10/2011	EP359-EP360	2		2				no
10/10/2011	EP355-EP363	2		2				no
10/10/2011	EP301	3		3				no
10/9/2011	S2 Yard	3					3	no
10/9/2011	EP300	6		6				no
10/8/2011	EP357	2			2			no
10/8/2011	EP306	3					3	no
10/7/2011	Dunaway CY	1		1				no
10/7/2011	EP291-EP301	3		3				no
10/6/2011	Fromm CY	2					2	no
10/5/2011	Dunaway CY	2		2				no
10/5/2011	EP303-2	2		2				no
10/4/2011	EP310 & EP311	2		2				no
10/4/2011	EP301	3					3	no
10/4/2011	EP293	2		2				no
10/3/2011	S2 Yard	2					2	no
10/3/2011	Dunaway CY	2			2			no
10/2/2011	EP356-EP363	2		1	1			no
10/1/2011	Plaster City Yard	2					2	no
10/1/2011	EP360	2			2			no
9/30/2011	S2 Yard	2					2	no
9/30/2011	EP355	1		1				no
9/30/2011	EP314	2		2				no
9/30/2011	EP301	2		1	1			no
9/29/2011	EP291/EP292 Pullsite	1			1			no
9/28/2011	EP361	1			1			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
9/27/2011	EP315	2		1	1			no
9/27/2011	EP309	1		1				no
9/27/2011	EP301 & EP304	4		3	1			no
9/27/2011	EP290	1			1			no
9/26/2011	EP362	2			2			no
9/26/2011	Fromm CY	1				1		no
9/25/2011	No ravens observed							
9/24/2011	Plaster City Yard	2					2	no
9/24/2011	EP317	1		1				no
9/24/2011	EP309	1		1				no
9/23/2011	EP362	4			4			no
9/23/2011	EP303	2		2				no
9/22/2011	Fromm CY	1				1		no
9/22/2011	EP303	2		2				no
9/22/2011	EP301	2		2				no
9/22/2011	EP295-EP322	3		3				no
9/21/2011	S2 Yard	3			3			no
9/21/2011	Fromm CY	1					1	no
9/21/2011	EP303	1		1				no
9/20/2011	S2 Yard	2			2			no
9/20/2011	Fromm CY	1				1		no
9/19/2011	S2 Yard	3			3			no
9/19/2011	EP304, EP307, EP309	1		1				no
9/18/2011	S2 Yard	3				3		no
9/18/2011	EP281	1		1				no
9/17/2011	S2 Yard	3					3	no
9/17/2011	EP362	1			1			no
9/17/2011	Fromm CY	3				3		no
9/16/2011	EP363	2			2			no
9/16/2011	Fromm CY	1					1	no
9/16/2011	EP304	2		2				no
9/16/2011	EP290	1		1				no
9/15/2011	S2 Yard	4			4			no
9/15/2011	Fromm CY	3					3	no
9/15/2011	EP296	1		1				no
9/15/2011	EP306	2					2	no
9/15/2011	EP304	1		1				no
9/15/2011	EP301	2		2				no
9/14/2011	Plaster City Yard	1			1			no
9/14/2011	EP361	2			2			no
9/14/2011	Fromm CY	1				1		no
9/14/2011	EP308	1					1	no
9/14/2011	EP301	5		4	1			no
9/14/2011	EP292	3		3				no
9/13/2011	S2 Yard	10			10			no
9/13/2011	EP348	3		3				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
9/13/2011	EP345	2		2				no
9/13/2011	EP326	1					1	no
9/13/2011	EP325	2		2				no
9/13/2011	EP326	1		1				no
9/13/2011	EP304	7		7				no
9/13/2011	EP291	7		7				no
9/12/2011	S2 Yard	3			3			no
9/12/2011	EP350	1		1				no
9/12/2011	EP304	1		1				no
9/12/2011	EP301	1		1				no
9/11/2011	S2 Yard	2				2		no
9/10/2011	S2 Yard	2					2	no
9/9/2011	EP304	1			1			no
9/8/2011	S2 Yard	3					3	no
9/7/2011	S2 Yard	3					3	no
9/6/2011	No ravens observed							
9/5/2011	No ravens observed							
9/4/2011	No ravens observed							
9/3/2011	No ravens observed							
9/2/2011	EP348	1		1				no
9/2/2011	S2 Yard	1		1				no
9/2/2011	EP303	1		1				no
9/2/2011	EP363	2		2				1 at IV Sub
9/1/2011	EP303	2					2	no
9/1/2011	EP293	1					1	no
9/1/2011	EP304	2					2	no
8/31/2011	S2 Yard	1		1				no
8/31/2011	EP308	1		1				no
8/31/2011	EP305-3	2					2	no
8/31/2011	EP303	2		2				no
8/30/2011	EP303	1		1				no
8/29/2011	S2 Yard	1		1				no
8/29/2011	EP303	1		1				no
8/28/2011	No ravens observed							
8/27/2011	EP305	3			3			no
8/26/2011	EP301	2		2				no
8/25/2011	S2 Yard	2					2	no
8/25/2011	EP301	2		2				no
8/24/2011	S2 Yard	3				3		no
8/23/2011	EP292-1	3		3				no
8/22/2011	No ravens observed							
8/21/2011	No ravens observed							
8/20/2011	S2 Yard	2				2		no
8/20/2011	EP312	2		2				no
8/20/2011	S2 Yard	2					2	no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
8/20/2011	EP312	2		2				no
8/19/2011	EP307	2			2			no
8/19/2011	EP296	1		1				no
8/18/2011	S2 Yard	2				1	1	no
8/18/2011	EP301	Flock		x				no
8/17/2011	S2 Yard	2				1	1	no
8/17/2011	EP301	3			3			no
8/16/2011	S2 Yard	1					1	no
8/16/2011	EP301	1		1				no
8/15/2011	No ravens observed							
8/14/2011	No ravens observed							
8/13/2011	S2 Yard	2					2	no
8/12/2011	IV Substation	2				2		no
8/12/2011	S2 Yard	3				3	3	no
8/11/2011	EP294	4			4			no
8/11/2011	S2 Yard	3				3	3	no
8/10/2011	S2 Yard	3				2	1	no
8/9/2011	S2 Yard	not specified						no
8/8/2011	EP294	2			2			no
8/8/2011	S2 Yard	1						no
8/7/2011	No ravens observed							
8/6/2011	S2 Yard	1						no
8/5/2011	EP301	3		3				no
8/4/2011	S2 Yard	not specified						no
8/3/2011	S2 Yard	2		2				no
8/3/2011	S2 Yard	1						no
8/2/2011	S2 Yard	3					3	no
8/1/2011	EP314	not specified		x				no
7/31/2011	No ravens observed							
7/30/2011	EP314	3		2			1	no
7/30/2011	S2 Yard	1					1	no
7/29/2011	S2 Yard	1						no
7/28/2011	EP319	4	1	2	1			no
7/28/2011	S2 Yard	not specified						no
7/27/2011	S2 Yard	not specified						no
7/26/2011	No ravens observed							
7/25/2011	EP290	1				1		no
7/24/2011	No ravens observed							
7/23/2011	No ravens observed							
7/22/2011	EP290	2		1	1			no
7/21/2011	S2 Yard	1		1				no
7/20/2011	Ocotillo, CA	5						no
7/19/2011	Ocotillo, CA	1						no
7/18/2011	CP40-2	not specified						no
7/18/2011	CP41-2	not specified						no
7/18/2011	CP42-1	not specified						no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed	
			Nesting	Flying	Perching	Roosting	Scavaging		
7/17/2011			No ravens observed						
7/16/2011	CP42-1	not specified						no	
7/15/2011			No ravens observed						
7/14/2011	EP357	not specified						no	
7/14/2011	EP358	not specified						no	
7/14/2011	EP359	not specified						no	
7/14/2011	Plaster City Yard	2		2				no	
7/13/2011	EP313-EP314 PS	not specified						no	
7/13/2011	S2 Yard	3					3	no	
7/12/2011	CP18-1	not specified						no	
7/12/2011	CP19-1	not specified						no	
7/12/2011	CP22-1	not specified						no	
7/11/2011	EP304-EP314	not specified						no	
7/10/2011			No ravens observed						
7/9/2011	EP351	not specified						no	
7/9/2011	EP353	not specified						no	
7/9/2011	EP354	not specified						no	
7/9/2011	EP355	not specified						no	
7/9/2011	not specified	not specified						no	
7/9/2011	S2 Yard	3					3	no	
7/8/2011	EP303	2			1		1	no	
7/8/2011	EP303	1		1				no	
7/8/2011	S2 Yard	3					3	no	
7/1/11 - 7/7/11			No ravens observed						
6/30/2011	EP300	3		3				no	
6/21/11 - 6/29/11			No ravens observed						
6/20/2011	S2 Yard	2					2	no	
6/1/11 - 6/19/11			No ravens observed						
5/1/11 - 5/31/11			No ravens observed						
4/22/11 - 4/30/11			No ravens observed						
4/21/2011	EP341	1	1					no	
4/1/11 - 4/20/11			No ravens observed						
3/1/11 - 3/31/11			No ravens observed						
2/1/11 - 2/28/11			No ravens observed						
1/21/11 - 1/31/11			No ravens observed						
1/21/2011	Rough Acres Yard	not specified						no	