

November 8, 2011

## **I. REPRESENTATIVES, LOCATIONS AND DATES**

### **LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region**

- Mr. Dan Mason, Campo, served as monitor on November 5. His report has yet to be received.
- Mr. Ed Mercado, Campo, served as monitor on October 31 and November 1, 3 and 4.
- Mr. Daniel Padilla, Cocopah, served as monitor on October 31 through November 3.
- Mr. Bert Quihuis, Campo, served as monitor on November 1.
- David Thompson on Manzanita served as monitor on November 4.
- Mr. Daniel Tsosie, Campo, served as monitor on November 5.
- Mr. Frank Salazar, Campo, served as monitor on November 3.
- Ms. Veronica Santos, Manzanita, served as monitor on October 31 and November 4 and 5.
- Mr. Santiago Santos, Manzanita, served as monitor on October 31 and November 1, 3, and 5.

### **LINK 2: Bartlett-Hauser Yard, Kreutzkamp Yard, Thing Valley Yard**

- Mr. Jonathan Jones served as monitor on October 31 and November 1.
- Ms. Andrea Najera of Campo served as monitor on November 3, 4, and 5.
- Mr. Jesse Pinto, Jamul, served as monitor on October 31, November 1 and November 4. His reports have yet to be received.

### **LINK 3: Suncrest Substation**

- No monitors required at this location for this week.

### **LINK 4: Alpine Underground**

- Mr. Clarence Brown, Viejas, served as monitor on October 31 and November 1 and 3.
- Mr. Joshua Craddock of Viejas served as monitor on November 1.

### **LINK 5: Various Locations**

- Mr. Frank Brown, Viejas, served as monitor on November 3 to 5. His reports have yet to be received.
- Mr. Boe Willey of Manzanita served as monitor on November 3.
- Mr. Larry Sutton of Viejas served as monitor on November 1 and 4.
- Mr. Joshua Craddock of Viejas served as monitor on November 3, 5.

---

## **II. CONSTRUCTION ACTIVITIES**

### **LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region**

Activities along this Link this week consisted of reconstruction of tower legs, drilling, vegetation clearing, BMP installation, landscape restoration, road maintenance and fence repair.

### **LINK 2: Bartlett-Hauser Yard, Kreutzkamp Yard, Thing Valley Yard**

Activities reported this week included clearing vegetation and grading.

### **LINK 3: Suncrest Substation**

No monitors required at this location for this week.

**LINK 4: Alpine Underground**

Activities along this Link for this week included excavating.

**LINK 5: Various Locations**

Activities reported this week included tree trimming, grading, and watering.

---

**III. OBSERVATIONS**

**LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region**

On November 4, Mr. Thompson noted chipping debris and cores.

**LINK 2: Bartlett-Hauser Yard, Kreutzkamp Yard, Thing Valley Yard**

No cultural materials reported this week.

**LINK 3: Suncrest Substation**

No monitors required at this location for this week.

**LINK 4: Alpine Underground**

No cultural materials observed this week.

**LINK 5: Various Locations**

No cultural materials observed this week.

---

**IV. CONCERNS EXPRESSED**

**LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region**

Mr. Thompson is concerned that due to the broken leg of the tower, work to repair it will go beyond the current limit of work and into a site. He notes that he accompanied SDGE personnel to go take a look at that area.

**LINK 2: Bartlett-Hauser Yard, Kreutzkamp Yard, Thing Valley Yard**

No concerns expressed this week.

**LINK 3: Suncrest Substation**

No concerns expressed this week.

**LINK 4: Alpine Underground**

No concerns expressed this week.

**LINK 5: Various Locations**

No concerns expressed this week.

---

**V. SUMMARY**

Few artifacts were observed this week and only one concern was expressed in result to a fallen tower leg. The concern was to make sure that any work going beyond the original work boundaries to retrieve the leg would not impact any resources.

---

## **VI. SUMMARY PREPARER**

Hillary Murphy, Project Archaeologist, Tierra Environmental Services, Inc.

Joseph M. Nixon, Senior Anthropologist, Tierra Environmental Services, Inc.

Kyle Stankowski, Associate Archaeologist, Tierra Environmental Services, Inc.