



This report provides a summary of environmental monitoring and compliance activities conducted by Burns and McDonnell (BMcD) staff and BMcD subconsultants for the San Diego Gas & Electric (SDG&E) Sunrise Powerlink Project during the above weekly time period.

### **Training**

- SWEAP and PBS training continued for new Project personnel every Tuesday and Thursday. Additional trainings were provided as requested.
- Flat-tailed horned lizard (FTHL) trainings were provided to any new crew members or monitors prior to construction per mitigation measure B-7b and in accordance with the FTHL Rangewide Management Strategy. During morning tailboard meetings, guidelines were provided about recognizing, protecting, and notification requirements for FTHL. FTHL information cards were made available to any crew members or monitors as needed.
- Barefoot banded gecko (BBG) trainings were provided to crews prior to pre-construction activities pursuant to the California Department of Fish and Game (CDFG) 2081 Incidental Take Permit requirements.

### **Pre/Post Construction**

- Staked, flagged, and refreshed work areas near SPL-69-6, SPL-69-8, SPL-69-11, Sycamore Substation, CP59, EP54-1/EP56-4 pull site, EP58-2, EP117-2, EP118-2, EP200A-1, EP201-3, EP202-3, EP204-3, EP205-2, EP206-1, EP207, EP208, EP209-1, EP210, EP211, EP213, EP214, EP215, EP217-1, EP218-1, EP219-1, EP220-1, EP255-2, EP256, and EP257.
- Topographic survey of existing access road near CP59.
- The ESA Team conducted the following activities during this reporting period:
  - Repaired, refreshed, and maintained the previously installed project signs and ESAs at/from CP19 to CP26, CP28 access road, CP50, CP65, CP69 to CP70 access road, CP71 to CP87, McCain Valley Road, EP9, EP11, EP12, EP39 to EP42, EP47 to EP53, EP71 to EP79 access road, EP89-1, EP90-1, EP91, EP90 to EP99 access road, EP170 to EP215, EP206 to McCain Yard access road, EP239 to EP245 access road, EP245 to EP256, EP250 access road, EP254 to EP257 access road, EP254 to EP259, EP258 to EP261, EP351-N access road, EP351, EP352 access road, EP352 to EP361 access road, EP361-N access road, EP361 to EP362, and EP363-1-B-E access road.
  - Installed ESAs at/from CP28, EP27, EP269-1-E access road, EP294 to EP313, and Sycamore Yard.
  - Inspected ESA barrier around spayfoot toad habitat.

### **Construction**

- Monitors were present during construction activities to ensure compliance with mitigation measures as identified in the Final EIR/EIS Mitigation Monitoring, Compliance, and Reporting Program. Archaeologists, Paleontologists, and Native American Monitors were present at sites where required as identified prior to construction activity and as approved in the NTPs. On average, the following number of monitors were on the Project throughout the week:



**Sunrise Powerlink Project**  
**Weekly Report 64 – December 04, 2011 through December 10, 2011**



- 8 Archaeological Monitors.
- 132 Biological Monitors.
- 9 Native American Monitors.
- 1 Paleontological Monitor.
- 8 SWPPP Monitors.
- Project staff carpooled to site reviews, kick-off tailgates, and off-site meetings. Construction and traffic control crews were observed carpooling from yards to work areas.
- Deterrents were utilized to discourage bird nest building activities throughout the Project. Deterrents are determined depending upon the location and type of possible nesting areas and may include metallic flagging, compact discs, plastic owls, and the presence of biological monitors.

The table below demonstrates the construction progress to date:

OVERHEAD					
Agency	Foundations Completed	Towers Erected	Wire Installed		
Non-Federal	99 of 169	57 of 169	23 of 169		
Bureau of Land Management	132 of 179	102 of 179	67 of 179		
Miramar	6 of 14	3 of 14	0 of 14		
US Forest Service	20 of 76	16 of 76	17 of 76		
UNDERGROUND					
Agency	Vaults Installed	Trenches Excavated & Backfilled			
Non-Federal	40 of 40	41 of 42			
SUBSTATION UPGRADES					
2 of 7 Completed					
SUNCREST SUBSTATION					
77 Percent Complete					



### Overhead Construction

- Link 1
  - Boulder removal at EP146, EP147, EP148-1, EP185-1, and EP189-3.
  - Access road construction at EP170-N and EP171-N.
  - Stream rock crossing installed at EP170, EP171, and EP176.
  - Grading at EP185-1 and EP258-3.
  - Grading occurred in preparation for the regen site at EP215.
  - Final grading at EP258 and from EP290 to EP294.
  - Final grading at tower sites and along access roads from EP300-1 to EP312.
  - Site prep for micropile drilling at EP145, EP148, EP149, EP189-3, and EP237-1.
  - Micropile drilling at EP193-2, EP194-3, EP195-2, EP196-2, EP228, EP236-1, EP237-1, and EP254-3.
  - Micropile trimming and cleanup at EP274-1, EP278-1, and EP279-1.
  - Micropile cap work at EP145, EP146, EP147, EP221A, EP223-1, EP226-1, EP227, EP229-1, EP254-3, EP271-2, EP276-1, EP277-1, and EP280-2.
  - Conventional drilling at EP177, EP185-1, and EP193-2.
  - Rebar installation at EP193-2.
  - Concrete pouring at EP193-2.
  - Form removal and cleanup at EP184-1.
  - Equipment demobilized from EP184-1.
  - Tower assembly at EP259-3, EP259B, EP261-2, EP261A, EP262-4, EP263A-2, EP265-2, EP266-2, EP267-2, EP269-1, EP270-2, EP271-2, EP272-3, EP273-1, EP274-1, EP275-1, EP276-1, EP277-1, EP279-1, EP280-2, and EP281.
  - Miscellaneous tower work (anti-climbing guards and bird deterrents) at EP292-1, EP293, EP294, EP300-1, EP302-1, EP303-2, EP304-2, and EP306-1.
  - QA/QC at EP224-1, EP269-1, EP271-2, EP272-3, EP273-1, EP276-1, EP278-1, EP279-1, and EP280-2.
  - Concrete block anchors installed at EP259B, EP261-2, EP261A, EP262-4, EP263-2, EP264-4, EP265-2, and EP270-2.
  - Concrete block anchors removed at EP221-2, EP221A, EP223-1, EP224-1, EP225-1, EP226-1, EP229-1, EP230-1, EP231-1, EP231A, EP232-1, EP235-1, EP238-1, EP261A, EP262-4, EP263A-2, and 263B-2.
  - Ground resistance testing at EP258-3, EP259-3, EP259B, EP266-2, EP267-2, EP269-1, EP270-2, EP271-2, EP272-3, EP273-1, and EP274-1.
  - Ground rod installation at EP171, EP172, EP173-1, EP174, EP191-2, EP192-2, EP245-1, EP247, and EP305-3.
  - Mobilization of equipment and snub installation at EP292-1 pull site.
  - Travelers installed from EP269-1 to EP290.
  - Insulator work from EP269-1 to EP290 and at EP363-1.
  - Snubs backfilled and equipment staging at EP292-1 pull site.
  - Guard structure EP267-2-GS-NF-38 installed on the north and south sides of I-8.
  - Guard structure netting installed at EP267-2-GS-NF-38 and EP281.
  - Two phases of conductor pulled from EP363-1 to Imperial Valley Substation.
  - Splicing at EP301.
  - Fiber testing from EP291 through EP363-1.
  - BMPs maintained ay/from:
    - EP170-N to EP210, EP185-1, and EP303-2.
  - BMPs removed from:
    - EP300-1 to EP312.
    - Trained FTHL monitors, BBG monitors, BHS monitors, and Visible Emission Evaluators (VEEs) were onsite as required.



- Link 2
  - During this reporting period, the PAL Levels were as follows: Monday-E, Tuesday-E, Wednesday-Ev, Thursday-D, Friday-C, and Saturday-D. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

#### USFS Land

- Access road construction at:
  - EP11-3-N, EP12-3-N, EP22-1-PS-N, EP35-1-N, EP58-2-N, EP112-3-E, EP113-5-PS-N-A, EP113-5-PS-N-B, and EP138-2-E-A.
- Vegetation clearing at EP11-3, EP22-1 pull site, EP112-3, EP113-5 pull sites, EP120-4 TSAP, EP120A TSAP, EP121A TSAP, EP121-3 TSAP, EP122-1 TSAP, EP123-1 TSAP.
- Gate installation at EP11-3, EP121-3 to EP128, EP121-3-E to EP141-N, and EP142-1.
- Micropile drilling at EP3-3, EP5-2, and EP7-1.
- Micropile capping at EP2-3.
- Equipment mobilized to EP112A-1.
- Soil boring at 112-3.
- Conventional drilling at EP113-5.
- Dead-end and traveler work, sagging, and clipping in from EP131 to EP141.
- Hydromulching at EP135, EP136, and EP138-2.
- BMP installation at/from:
  - EP11-3-N, EP12-3-N, EP22-1-PS-N, EP35-1-E, EP58-2-N, EP112-3-E, EP112-3, EP113-5 pull site, EP121-3 to EP128, EP121-3-E to EP141-N, and EP142-1.

#### BLM Land

- Access road construction at:
  - EP47-2-PS-N, EP49-E to EP51-1-E, and EP63-E to EP65-1-E.
- Dexpan boulder removal at EP49 and EP74-1.
- Gate installation at EP39-1 and EP96.
- Micropile site preparation at EP50, EP56-4, EP102A-1, EP106-3, and EP107-3.
- Micropile cleanup at EP47-2.
- Conventional drilling at EP39-1, EP94, EP95, EP96, EP97, EP98-1, EP99-2, EP103-2, and EP104-2.
- Various foundation work (curing, cage installation, etc.) at EP96,
- Concrete pouring at EP96 and EP103-2.
- Form removal at EP94 and EP95.
- Sagging of conductor and fiber, dead-end work, marker ball installation, and equipment mobilization from EP42 to EP47-2.
- Spacing from EP42 to EP45.
- Arroyo toad fencing was installed between EP76-2-E and EP79-E-C.
- BMP installation at:
  - EP42-N, EP75-2, EP76-2, EP94 to EP99-2, and EP94-N to EP99-2-N-B.
- Hydromulching at EP94 to EP99-2 and EP94-N to EP99-2-N-B.

#### Non-Federal Land

- Vegetation clearing at EP26-1, EP27-1, EP30-2, EP30-2 pull site, EP83 pull site north, and EP32-1.



**Sunrise Powerlink Project**  
**Weekly Report 64 – December 04, 2011 through December 10, 2011**



- Tree trimming along EP105-2-E-B.
  - Access road construction at:
    - EP58-2-N, EP63-E to EP65-1-E, EP83-N, EP83-PS-N-B, and EP84-E-D.
  - Grading along EP93-N.
  - Driveway construction at EP89-1-E and EP93.
  - Micropile setup at EP106-3.
  - Micropile cap work at EP79, EP81, EP85-2, and EP86-1.
  - Conventional drilling at EP26-1 and EP27-1.
  - Various foundation work (curing, cage installation, etc.) at EP26-1 and EP27-1.
  - Concrete pouring at EP26-1.
  - Arroyo toad fencing was installed at the EP66-E, EP67 pull sites, and EP76-2-E.
  - BMP installation at:
    - EP26-1, EP27-1, EP30-2-N, EP58-2-N, EP77, EP78A, EP79, EP82 pull site north, EP83-PS-N-B, EP93, and EP93-N.
  - Hydromulching at EP93 and EP93-N.
- Link 5
    - During this reporting period, the PAL Levels were as follows: Monday-E, Tuesday-E, Wednesday-Ev, Thursday-D, Friday-C, and Saturday-D. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

#### USFS Land

- Conventional drilling at CP99-2.
- Dead-end work, sagging, and clipping from CP65-1 to CP75-1.
- Sagging and clipping OPGW and conductor from CP100-1 to CP109-1.
- Dead-end work and marker ball installation from CP100-1 to CP109-1.
- Ground rod installation and testing at CP100-1.
- BMP maintenance at CP69-2 and CP100-1-N
- Hydromulching at CP104-1 and CP105-1.

#### BLM Land

- Micropile drilling at CP59.
- Micropile trimming at CP58-1 and CP62A.
- Dead-end work, sagging, and clipping from CP65-1 to CP75-1.
- BMPs maintained at CP61-1.
- Hydroseeding at CP68-1.

#### Non-Federal Land

- Vegetation clearing at CP33-2, CP34-2, CP35-2, CP37-2, CP46 TSAP, CP47 TSAP, and CP55.
- Access road construction at CP49-1-PS-N.
- Dexpan boulder breaking at CP29-1, CP31-2, CP48-2, CP49-1, CP76-1, CP77, and CP83.
- Micropile drilling at CP51-2, CP53-1, CP55, CP76-1, and CP84.
- Grouting at CP21, CP23, CP57, CP79-1, CP80-2, and CP81-1.
- Micropile trimming at CP56-1.
- Micropile capping work at CP21.
- Tower assembly at CP16-1.
- Spacers, marker balls, and jumpers were installed from CP65-1 to CP75-1.



**Sunrise Powerlink Project**  
**Weekly Report 64 – December 04, 2011 through December 10, 2011**



- Dead-end work, sagging, and clipping from CP65-1 to CP75-1.
- Sagging and clipping OPGW and conductor from CP100-1 to CP109-1.
- Dead-end work and marker ball installation from CP100-1 to CP109-1.
- Ground resistance testing at CP56-1, CP87-1, CP88-1, and CP95-1.
- BMP installation at:
  - CP16-1, CP23, CP31-2, CP48-2, CP49-1, and CP71.
- BMP maintenance at:
  - CP55, CP70-3, CP98-N-A, CP98-N-B, and CP99-N.
- Hydromulching around and disassembling of the radio tower site near CP108.

Miramar

- Vegetation clearing at CP3.
  - Access road construction at:
    - CP6-1-N, CP7-N, CP8-2-N, CP9-E, CP9-N, CP10-E, CP10-N, CP11-E, CP11-1-N, CP12-E, CP13-2-E-C, and CP14-N.
  - Conventional drilling at CP8-2.
  - Concrete pouring at CP9-1 and CP12-1.
  - Tower assembly at CP15-1.
  - Ground rod installation at CP15.
  - BMP installation at CP7, CP8-2, CP10, CP11-1, and CP15-1.
  - Hydroseeding at CP106-1.
- 69kV
    - Vegetation clearing occurred between Beeler Canyon Road and Sycamore Substation.

Underground Construction (Link 4)

- Revitalization near Bay Meadows and Louise Drive.
- Pre-racking/Racking and cleaning manholes for ABB (and jointing/splicing) at V5L, V19L, V20L, V8R, and V9R.
- Fiber pulling from V12R to V17R and V13L to V17L.
- Paving (including paving prep) near V5R to V6R.
- Proofing from V18R to V19R.
- Cable pulling from V1R to riser and V1R to V2R.
- Erecting scaffolding at EP95 and Loritz Property and Slay riser poles.
- Terminating at Loritz riser pole.
- Grading at Bauer/Slay property and Caltrans bore location.
- Raise manhole necking to grade (also adjusting necking at V12R, V12L, and V19R).
- Finish jack and bore at Alpine Creek.
- Bauer Bridge removal preparation.

Suncrest Substation Construction (Link 3)

- Steel erection in the southwest quadrant of the pad.
- Removing forms and scaffolding from the water tank and pouring second layer of shotcrete.
- PAR wire pulling activities continued in the northwest quadrant of the pad.
- Class 2 base placement along Bell Bluff Truck Trail east of the guard shack.
- Soil removal and re-compaction as well as class 2 base placement along Bell Bluff Truck Trail east of the guard shack.
- Wrapping tension band around the water tank.



- Finish grading and class 2 base placement in the 230kV yard and the northwest quadrant of the pad.
- Crushing class 2 base and select fill material.
- Forming pads for foundations and pouring concrete.
- Trenching for conduit and ground grid in the southwest quadrant.
- BMP maintenance and installation along Bell Bluff Truck Trail and on the substation pad by both detention basins.

### Substation Upgrades

- Encina Switchyard
  - Roel worked on forming and backfilling around the newly poured containment pit for the new 230kV transformer, forming and installing rebar to pour additional concrete for containment pit at the new 230kV transformer pad, pouring additional concrete for containment pit at the new 230kV transformer pad, forming concrete for containment pit for the transformer pad, and working on backfilling open trenches.
- Imperial Valley (IV)
  - SDG&E ETRAM crew staged equipment in the northwest corner of the substation.
  - SDG&E worked in Bay 4 and erected steel frames and bus supports.
  - The current outage is in effect for the rest of the week to complete the final work.
  - PRAVA worked inside new storage warehouse and electricians worked on wiring.
- San Luis Rey
  - No Sunrise-related work.
- Sycamore Canyon
  - SDG&E Kearny Mesa Construction crews worked on building disconnects for 230kV upgrades.
- Scripps
  - No Sunrise-related work.

### Construction Yards

- Sycamore Yard – Weed wash station, helicopter operations, dust suppression, water staging, tower assembly, and staging for BMP, road, micropile, erection, brush clearing, and conventional foundation crews.
- Helix Yard – Helicopter operations; weed wash station; dust suppression; staging for micropile, TSAP, assembly, tree trimming, and wire crews; water staging; and weed maintenance.
- El Monte Yard – Staging for wire crews, helicopter operations, water staging, and dust suppression.
- Alpine Yard – Materials staging and weed wash station.
- Wilson Yard – Staging materials for Suncrest Substation; helicopter operations; staging for micropile, BMP, and wire crews; dust suppression; water staging; and tower assembly.
- SWAT Yard – Concrete staging; water staging; helicopter operations; staging for road, conventional foundation, BMP, and wire crews; dust suppression; and weed wash station.
- Barrett Canyon Yard – Helicopter operations, dust suppression, and staging for road, BMP, and wire crews.
- Kreutzkamp Yard – Helicopter operations; staging for road, conventional foundation, and BMP crews; weed wash station; weed clearing; water staging; and dust suppression.
- Bartlett-Hauser Yard – Water staging; weed maintenance; dust suppression; BMP drainage maintenance; staging for road, conventional foundation, and BMP crews; staging for gate, driveway, and micropile crews; and weed wash station.



- Thing Valley Yard – Helicopter operations, water staging, dust suppression, and staging for road, gate installation, wire, TSAP, and BMP crews.
- McCain Valley Yard – Tower assembly, helicopter operations, staging for micropile and conventional foundation crews, water staging, and dust suppression.
- Rough Acres Yard – Helicopter operations, staging for foundation and BMP crews, materials staging, water staging, dust suppression, and weed wash station.
- Jacumba Valley Ranch (JVR) Yard – Helicopter operations; weed wash station; water staging; staging for micropile, QC, erection, and wire stringing crews; dust suppression; and hub for coordination of activities within PBS areas.
- AER Yard – Helicopter operations, tower assembly, staging for wire stringing materials, grouting operations and crews, dust control, and BMP maintenance.
- Fromm Yard – Tower assembly, helicopter activity, staging for tower erection and wire stringing crews, water staging, dust suppression, and removal of slats from yard fence to avoid blow over.
- S2 Yard – Water staging, helicopter activity, tower assembly, staging for erection and wire stringing crews, dust suppression, and staging for survey, road, QC, and assembly crews.
- Plaster City Yard – Demobilizing office trailers.
- Dunaway Yard – No activity.
- Imperial Valley Yard – No activity.

### **Wildlife Reporting**

- Peninsular bighorn sheep (PBS) were reported in Mountain Springs Grade on December 4, 5, 6, and 7, 2011.

The following listed or Species of Special Concern were found dead in Project construction limits during this reporting period:

- Silvery Legless Lizard (*Anniella pulchra pulchra*) – Three (3) silvery legless lizards were found dead; two (2) at EP11-3 and one (1) at EP35.
- Coronado Skink (*Plestidon skiltonianus interparietalis*) – Four (4) Coronado skinks were found dead at EP30 Pullsite.
- American Badger (*Taxidea taxus*) – One (1) American badger was found dead near EP259-3.

The following listed or Species of Special Concern were relocated during construction activities this reporting period:

- Silvery Legless Lizard (*Anniella pulchra pulchra*) – Ten (10) silvery legless lizards were relocated; six (6) from EP11-3, one (1) from EP104-2, one (1) from EP106-3, one (1) from Thing Valley Yard, and one (1) from EP196.
- Coronado Skink (*Plestidon skiltonianus interparietalis*) – Six (6) Coronado skinks were relocated; one (1) from EP83 North pull site, three (3) from EP11-3, and two (2) from CP77.
- Coast Horned Lizard (*Phrynosoma blainvillii*) – One (1) coast horned lizard was relocated from EP11-3.
- Pacific Chorus Frog (*Pseudacris regilla*) – two Pacific chorus frogs were relocated from Kreutzcamp Yard

### **Spills/Hazardous Waste**

- spills occurred outside of the USFS during this reporting period. No reportable



**Sunrise Powerlink Project**  
**Weekly Report 64 – December 04, 2011 through December 10, 2011**



- Minor leaks, drips, and releases on USFS lands were submitted to the USFS in a weekly HazMat log.

### **Customer Complaints**

- No customer complaints were received during this reporting period.

### **Non-Compliances**

- Non non-compliances were issued during this reporting period.

### **Variances and TEWS**

- Variance #32 for guard structures and pull site modifications for wire stringing was approved on December 9, 2011.

### **Weather**

- No rain events occurred during this reporting period.
- BMPs were installed or maintained as needed throughout Project areas. In accordance with the Construction General Permit (CGP), daily site BMP inspections, photos, and appropriate BMPs for stormwater and non-stormwater were implemented. In accordance with the CGP, a post-storm inspection was performed as a result of the qualifying rain events. Failures and shortcomings that were identified in the post-storm inspection have been assessed and repairs/design changes to the BMPs will begin within 72 hours of identification.



**Sunrise Powerlink Project**  
**Weekly Report 64 – December 04, 2011 through December 10, 2011**

**Burns & McDonnell**  
SINCE 1898



Air crane tower pick at S-2 Construction Yard. *Photo courtesy of Kham Slater.*



Setting split bridge at EP269. *Photo courtesy of Rebecca Carson.*



Female pocket mouse feeding her young in the vicinity of EP12. *Photo courtesy of John Dicus.*

# **Appendices**

Peninsular Big Horn Sheep Monitoring Report

Flat-Tailed Horned Lizard Monitoring Report

Raven Control Monitoring Report

Flat Tailed Horned Lizard Counts - Week Ending 12/10/2011									
Date	Location	Observed		Injured		Relocated		Dead	
	Post RCLMP*	Day	Night	Day	Night	Day	Night	Day	Night
11/1/2011	Dunaway CY					1			
10/13/2011	AR to EP354							1	
9/20/2011	AR btwn EP357 and EP358							1	
9/19/2011	AR btwn EP352 and EP353	1							
9/12/2011	EP325					1			
9/9/2011	AR to EP363	1							
9/6/2011	AR to EP360/361					1			
9/6/2011	EP360					2			
9/6/2011	EP359					1			
9/3/2011	SWPL AR to EP324					1			
9/3/2011	SWPL AR to EP342					1			
9/3/2011	SWPL AR to EP345							1	
9/3/2011	SWPL AR to EP344 and EP345					1			
8/31/2011	EP324					1			
8/31/2011	SWPL AR to EP325-2					1			
8/30/2011	SWPL AR to EP346 and EP347					1			
8/29/2011	SWPL AR to EP353 and EP354							1	
8/29/2011	SWPL AR to EP324							1	
8/27/2011	EP349					1			
8/25/2011	EP360							1	
8/25/2011	Btwn EP320/321					1			
8/24/2011	SWPL AR near EP346					1			
8/23/2011	EP349					1			
8/21/2011	SWPL AR btwn EP344/345					1			
8/21/2011	SWPL AR to EP345							1	
8/19/2011	SWPL AR to EP339					1			
8/20/2011	SWPL AR to IV Sub							1	
8/20/2011	SWPL AR btwn EP346/347					1			
8/19/2011	EP338/339 Pullsite					1			
8/19/2011	EP355/356 Pullsite					1			
8/18/2011	EP347					1			
8/18/2011	SWPL AR to EP353							1	
8/11/2011	SWPL AR by EP348					1			
8/11/2011	EP348/EP349 Pullsite					1			
8/10/2011	EP347					1			
8/8/2011	SWPL AR to EP351					2			
8/6/2011	BLM AR near EP327							1	
8/1/2011	IV Substation Yard	1							
8/1/2011	EP325					1			
8/1/2011	AR to EP345					1			
7/30/2011	EP322					1			
7/28/2011	EP355/EP356 Pullsite					1			
7/27/2011	Near EP316-2	1							

Flat Tailed Horned Lizard Counts - Week Ending 12/10/2011									
Date	Location	Observed		Injured		Relocated		Dead	
7/26/2011	SWPL AR to EP344	1							
	Post RCLMP*	Day	Night	Day	Night	Day	Night	Day	Night
7/26/2011	EP347					1			
7/26/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/22/2011	AR to IV Sub					1			
7/21/2011	EP360					1			
7/21/2011	AR to EP326					1			
7/19/2011	SWPL AR to IV Sub	1							
7/19/2011	EP353					1			
7/19/2011	AR to Dunaway CY					1			
7/18/2011	EP318					1			
7/17/2011	EP355					1			
7/15/2011	EP359	1							
7/15/2011	EP352	1							
7/15/2011	EP350	1							
7/14/2011	Spur Rd to EP355							1	
7/14/2011	EP322	1							
7/13/2011	EP357	1							
7/12/2011	EP344	1							
7/12/2011	SWPL AR btwn EP348/345							1	
TOTAL POST RCLMP		12	0	0	0	43	0	12	
Prior to RCLMP		Day		Day		Day		Day	
7/11/2011	AR to EP352					2			
7/11/2011	AR to EP345					2			
7/10/2011	EP358					1			
7/10/2011	SWPL AR to EP354					2			
7/9/2011	AR to EP330	1							
7/8/2011	Spur Rd. to EP352	1							
7/7/2011	EP324					1			
7/7/2011	EP355					1			
7/6/2011	SWPL AR btwn EP362/363							1	
7/5/2011	EP354					1			
7/1/2011	AR to EP353	1							
6/30/2011	AR between EP310/311							1	
6/30/2011	EP358	1							
6/30/2011	EP360	1							
6/30/2011	AR to EP312							1	
6/30/2011	EP360							1	
6/27/2011	EP350					1			
6/27/2011	SWPL AR to IV Substation	2							
6/26/2011	IV Substation					1			

Flat Tailed Horned Lizard Counts - Week Ending 12/10/2011					
Date	Location	Observed	Injured	Relocated	Dead
6/25/2011	SWPL AR to EP361	1			
6/24/2011	EP359			1	
6/23/2011	SWPL AR to EP360			2	
6/22/2011	SWPL AR to EP355			1	
6/20/2011	EP356	2			
6/20/2011	SWPL AR to EP359	1			
6/20/2011	Near EP356	2			
6/20/2011	AR between EP358/357				1
6/18/2011	AR to Dunaway CY				1
6/17/2011	Near EP322	1			
6/7/2011	Near EP355	1			
6/7/2011	EP361			1	
6/7/2011	AR btwn EP343/EP344				1
6/7/2011	AR between EP324/325				1
6/6/2011	SWPL AR btwn EP344/EP345			1	
6/3/2011	EP359			1	
6/3/2011	SWPL AR EP362			1	
6/2/2011	AR to EP358			1	
6/2/2011	SWPL AR to EP316-2				1
6/2/2011	AR east of EP325				1
6/1/2011	SWPL AR btwn EP319/EP320			1	
6/1/2011	SWPL AR to EP318			1	
5/31/2011	SWPL AR btwn EP359/EP360			1	
5/31/2011	SWPL AR to EP320			1	
5/31/2011	EP360				1
5/27/2011	EP357			1	
5/26/2011	SWPL AR to EP359			1	
5/25/2011	Spur Rd to EP321			1	
5/23/2011	EP323			1	
5/21/2011	EP324			1	
5/20/2011	IV CY			1	
5/20/2011	AR to EP362			1	
5/20/2011	AR btwn EP324/EP325			1	
5/20/2011	SWPL AR btwn EP326/EP327			1	
5/20/2011	IV Substation			3	
5/19/2011	IV Substation			5	
5/19/2011	EP324			1	
5/18/2011	IV Substation Yard			1	
5/18/2011	IV Substation Yard				1
5/17/2011	AR to IV Substation				1
5/16/2011	IV Substation Yard			1	
5/13/2011	SWPL AR Near EP362-1	1			
5/12/2011	AR to EP355			1	
5/11/2011	EP360	1			

Flat Tailed Horned Lizard Counts - Week Ending 12/10/2011					
Date	Location	Observed	Injured	Relocated	Dead
5/11/2011	Dunaway CY	3			
5/11/2011	Dunaway Yard			4	
5/10/2011	EP322	1			
5/10/2011	AR to Dunaway CY	1			
5/9/2011	Dunaway Yard			4	
5/7/2011	EP322	1			
5/7/2011	Spur Road to EP344	1			
5/7/2011	Dunaway Yard			1	
5/6/2011	AR to EP321-1	1			
5/5/2011	AR to EP321-1	1			
5/5/2011	AR to Dunaway CY	2			
5/5/2011	Dunaway Yard			2	
5/4/2011	AR btwn EP343/EP344			1	
5/3/2011	SWPL AR btwn EP320/EP321	1			
4/27/2011	AR to EP322	2			
4/26/2011	EP322	1			
4/25/2011	Plaster City CY	1			
4/20/2011	Plaster City			1	
4/18/2011	Plaster City			1	
4/14/2011	AR to IV Substation	1			
4/2/2011	Dunaway CY	1			
<b>TOTAL PRIOR TO RCLMP</b>		<b>35</b>	<b>0</b>	<b>60</b>	<b>13</b>
<b>YTD</b>		<b>47</b>	<b>0</b>	<b>103</b>	<b>25</b>

\*RCLMP refers to the Revised Construction Lighting Mitigation Plan

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
12/10/2011	EP300-EP312	0	Site clearance survey
12/10/2011	EP300-EP312	0	Monitoring construction activities
12/10/2011	EP291, EP313, EP330-1, EP339 & EP363	0	Monitoring construction activities
12/10/2011	EP274-EP278	0	Site clearance survey
12/10/2011	EP274-EP278	0	Monitoring construction activities
12/10/2011	EP269-EP270	0	Site clearance survey
12/10/2011	EP269-EP270	0	Monitoring construction activities
12/10/2011	EP269-1, EP271-2, EP282-3 & EP273-1	0	Monitoring construction activities
12/10/2011	EP269-EP281	0	Site clearance survey
12/10/2011	EP269-EP281	0	Monitoring construction activities
12/10/2011	EP269-EP273	0	Site clearance survey
12/10/2011	EP269-EP273	0	Monitoring construction activities
12/10/2011	EP267-2	0	Monitoring construction activities
12/10/2011	EP263B-EP269	0	Site clearance survey
12/10/2011	EP262-4	0	Monitoring construction activities
12/9/2011	EP300-EP312	0	Site clearance survey
12/9/2011	EP300-EP312	0	Monitoring construction activities
12/9/2011	EP274-EP278	0	Site clearance survey
12/9/2011	EP274-EP278	0	Monitoring construction activities
12/9/2011	EP272-3	0	Monitoring construction activities
12/9/2011	EP269-EP281	0	Site clearance survey
12/9/2011	EP269-EP281	0	Monitoring construction activities
12/9/2011	EP269-EP273	0	Site clearance survey
12/9/2011	EP269-EP273	0	Monitoring construction activities
12/9/2011	EP267-2	0	Monitoring construction activities
12/9/2011	EP263B-EP269	0	Site clearance survey
12/9/2011	EP262-4	0	Monitoring construction activities
12/8/2011	EP301	0	Monitoring construction activities
12/8/2011	EP281	0	Monitoring construction activities
12/8/2011	EP272-3	0	Monitoring construction activities
12/8/2011	EP269-EP312	0	Site clearance survey
12/8/2011	EP269-EP273	0	Site clearance survey
12/8/2011	EP267-2	0	Monitoring construction activities
12/8/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/8/2011	EP274-EP278	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
12/8/2011	EP274-EP278	0	Monitoring construction activities
12/7/2011	EP301	0	Monitoring construction activities
12/7/2011	EP300-EP312	5	Site clearance survey-Observed outside project area
12/7/2011	EP300-EP312	0	Site clearance survey
12/7/2011	EP300-EP312	0	Monitoring construction activities
12/7/2011	EP274-EP278	0	Site clearance survey
12/7/2011	EP274-EP278	0	Monitoring construction activities
12/7/2011	EP269-EP273	0	Site clearance survey
12/7/2011	EP269-EP272	0	Site clearance survey
12/7/2011	EP269-EP281	0	Site clearance survey
12/7/2011	EP269-EP281	0	Monitoring construction activities
12/7/2011	EP259B and EP259-3	0	Monitoring construction activities
12/7/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/6/2011	EP301	0	Monitoring construction activities
12/6/2011	EP300-EP308	0	Monitoring construction activities
12/6/2011	EP300-EP312	0	Site clearance survey
12/6/2011	EP300-EP312	0	Monitoring construction activities
12/6/2011	EP271-2	0	Monitoring construction activities
12/6/2011	EP271-2	0	Monitoring construction activities
12/6/2011	EP269-EP273	0	Site clearance survey
12/6/2011	EP269-EP272	1	Site clearance survey
12/6/2011	EP269-1 to EP255	0	Monitoring construction activities
12/6/2011	EP269-1	0	Monitoring construction activities
12/6/2011	EP269-EP281	0	Site clearance survey
12/6/2011	EP269-EP281	0	Monitoring construction activities
12/6/2011	EP267-2-GS-NF-38	0	Monitoring construction activities
12/6/2011	EP267-2-GS-NF-38	0	Monitoring construction activities
12/6/2011	EP259B	0	Monitoring construction activities
12/6/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/6/2011	EP279-EP294	0	Site clearance survey
12/6/2011	EP279-EP294	0	Monitoring construction activities
12/6/2011	EP274-EP278	1	Site clearance survey-Area remained open to ground crews
12/6/2011	EP274-EP278	Same 1 as noted above	Monitoring construction activities
12/5/2011	EP300-EP312	1	Site clearance survey-Area remained open to ground crews

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
12/5/2011	EP300-EP312	Same 1 as noted above	Monitoring construction activities
12/5/2011	EP300-EP312	0	Site clearance survey
12/5/2011	EP300-EP312	0	Monitoring construction activities
12/5/2011	EP275-1, EP276-1	0	Monitoring construction activities
12/5/2011	EP274-EP278	0	Site clearance survey
12/5/2011	EP274-EP278	0	Monitoring construction activities
12/5/2011	EP272	1	Site clearance survey-Ram detected in boudary of low-elevation flight boundary
12/5/2011	EP269-EP272	Same 1 as noted above	Site clearance survey
12/5/2011	EP269-1	0	Monitoring construction activities
12/5/2011	EP269-EP281	0	Site clearance survey
12/5/2011	EP269-EP281	0	Monitoring construction activities
12/5/2011	EP267-2-GS-NF-38	0	Monitoring construction activities
12/5/2011	EP263B-2, EP263A-2, EP262-4 and EP261A	0	Monitoring construction activities
12/5/2011	EP259B	0	Monitoring construction activities
12/5/2011	EP258-3	0	Monitoring construction activities
12/5/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/5/2011	EP279-EP294	0	Site clearance survey
12/5/2011	EP279-EP294	0	Monitoring construction activities
12/4/2011	EP300-EP312	0	Site clearance survey
12/4/2011	EP300-EP312	0	Monitoring construction activities
12/4/2011	EP294	0	Monitoring construction activities
12/4/2011	EP280, EP275-1	0	Monitoring construction activities
12/4/2011	EP274-EP278	0	Site clearance survey
12/4/2011	EP274-EP278	0	Monitoring construction activities
12/4/2011	EP273-1, EP278-1, EP279-1 and EP280	0	Monitoring construction activities
12/4/2011	EP269-1-E	0	Monitoring construction activities
12/4/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
12/4/2011	EP269-EP281	0	Monitoring construction activities
12/4/2011	EP269-EP281	0	Site clearance survey
12/4/2011	EP256-EP263A	1	Site clearance survey-Area remained open to ground crews
12/4/2011	EP279-EP294	0	Monitoring construction activities
12/4/2011	EP279-EP294	0	Site clearance survey
12/4/2011	EP267-2-GS-NF-38	0	Monitoring construction activities
12/3/2011	EP300-EP312	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
12/3/2011	EP300-EP312	0	Monitoring construction activities
12/3/2011	EP278-1, EP279-1 & EP280-2	0	Monitoring construction activities
12/3/2011	EP274-EP278	0	Site clearance survey
12/3/2011	EP274-EP278	0	Monitoring construction activities
12/3/2011	EP269-EP270	0	Site clearance survey
12/3/2011	EP269-EP270	0	Monitoring construction activities
12/3/2011	EP269-EP281	0	Site clearance survey
12/3/2011	EP269-EP281	0	Monitoring construction activities
12/3/2011	EP263B-EP269	0	Site clearance survey
12/3/2011	EP263B-EP269	0	Monitoring construction activities
12/3/2011	EP257	0	Monitoring construction activities
12/3/2011	EP256-EP263A	2	Site clearance survey
12/3/2011	EP256-EP263A	Same 2 listed above	Monitoring construction activities
12/3/2011	EP279-EP294	0	Site clearance survey
12/3/2011	EP279-EP294	0	Monitoring construction activities
12/2/2011	EP300-EP312	0	Site clearance survey
12/2/2011	EP300-EP312	0	Monitoring construction activities
12/2/2011	EP300-EP312	0	Site clearance survey
12/2/2011	EP300-EP312	0	Monitoring construction activities
12/2/2011	EP281-GS-BLM-3	0	Monitoring construction activities
12/2/2011	EP280-EP281	0	Monitoring construction activities
12/2/2011	EP274-EP278	0	Site clearance survey
12/2/2011	EP274-EP278	0	Monitoring construction activities
12/2/2011	EP269-EP273	0	Site clearance survey
12/2/2011	EP269-EP281	0	Site clearance survey
12/2/2011	EP269-EP281	0	Monitoring construction activities
12/2/2011	EP263B-EP269	0	Site clearance survey
12/2/2011	EP263B-EP269	0	Monitoring construction activities
12/2/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
12/2/2011	EP279-EP294	0	Site clearance survey
12/2/2011	EP279-EP294	0	Monitoring construction activities
12/1/2011	EP300-EP312	0	Site clearance survey
12/1/2011	EP279-EP294; EP273-EP276	0	Site clearance survey
12/1/2011	EP279-EP294; EP273-EP276	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
12/1/2011	EP274-1, EP275-1	0	Monitoring construction activities
12/1/2011	EP274-EP278	0	Site clearance survey
12/1/2011	EP274-EP278	0	Monitoring construction activities
12/1/2011	EP269-EP273	0	Site clearance survey
12/1/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/30/2011	EP300-EP312	0	Site clearance survey
11/30/2011	EP300-EP312	0	Monitoring construction activities
11/30/2011	EP300-EP312	0	Site clearance survey
11/30/2011	EP274-EP278	0	Site clearance survey
11/30/2011	EP274-EP278	0	Monitoring construction activities
11/30/2011	EP273-1	0	Monitoring construction activities
11/30/2011	EP269-EP281	0	Site clearance survey
11/30/2011	EP269-EP281	0	Monitoring construction activities
11/30/2011	EP269-EP281	0	Site clearance survey
11/30/2011	EP269-EP281	0	Monitoring construction activities
11/30/2011	EP269-EP273	0	Site clearance survey
11/30/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/30/2011	EP279-EP294	0	Site clearance survey
11/30/2011	EP279-EP294	0	Monitoring construction activities
11/29/2011	EP300-EP312	0	Site clearance survey
11/29/2011	EP300-EP312	0	Monitoring construction activities
11/29/2011	EP300-EP312	0	Site clearance survey
11/29/2011	EP300-EP312	0	Monitoring construction activities
11/29/2011	EP274-EP278	0	Site clearance survey
11/29/2011	EP274-EP278	0	Monitoring construction activities
11/29/2011	EP273-1	0	Monitoring construction activities
11/29/2011	EP269-EP281	0	Site clearance survey
11/29/2011	EP269-EP281	0	Monitoring construction activities
11/29/2011	EP269-EP281	0	Site clearance survey
11/29/2011	EP269-EP281	0	Monitoring construction activities
11/29/2011	EP269-EP273	0	Site clearance survey
11/29/2011	EP269-EP281	0	Site clearance survey
11/29/2011	EP269-EP281	0	Monitoring construction activities
11/29/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/29/2011	EP279-EP294	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
11/29/2011	EP279-EP294	0	Monitoring construction activities
11/28/2011	EP300-EP312	0	Site clearance survey
11/28/2011	EP300-EP312	0	Monitoring construction activities
11/28/2011	EP274-EP278	0	Site clearance survey
11/28/2011	EP274-EP278	0	Monitoring construction activities
11/28/2011	EP273-1	0	Monitoring construction activities
11/28/2011	EP269-EP281	0	Site clearance survey
11/28/2011	EP269-EP281	0	Monitoring construction activities
11/28/2011	EP269-EP273	0	Site clearance survey
11/28/2011	EP269-EP273	0	Monitoring construction activities
11/28/2011	EP269-EP270	0	Site clearance survey
11/28/2011	EP269-EP281	0	Site clearance survey
11/28/2011	EP269-EP281	0	Monitoring construction activities
11/28/2011	EP263B-EP267	0	Site clearance survey
11/28/2011	EP263B-EP267	0	Monitoring construction activities
11/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/28/2011	EP279-EP294	0	Site clearance survey
11/28/2011	EP279-EP294	0	Monitoring construction activities
11/27/2011	EP300-EP312	0	Site clearance survey
11/27/2011	EP300-EP312	0	Monitoring construction activities
11/27/2011	EP279-1 & EP280-2	0	Monitoring construction activities
11/27/2011	EP274-EP278	0	Site clearance survey
11/27/2011	EP274-EP278	0	Monitoring construction activities
11/27/2011	EP269-EP281	0	Site clearance survey
11/27/2011	EP269-EP281	0	Monitoring construction activities
11/27/2011	EP269-EP281	0	Site clearance survey
11/27/2011	EP269-EP281	0	Monitoring construction activities
11/27/2011	EP269-EP274	3	Site clearance survey
11/27/2011	EP269-EP274	Same 3 as noted above	Monitoring construction activities
11/27/2011	EP269-EP270	0	Site clearance survey
11/27/2011	EP269-EP281	0	Site clearance survey
11/27/2011	EP269-EP281	0	Monitoring construction activities
11/27/2011	EP263B-EP269	0	Site clearance survey
11/27/2011	EP263B-EP269	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
11/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/27/2011	EP279-EP294	0	Site clearance survey
11/27/2011	EP279-EP294	0	Monitoring construction activities
11/26/2011	EP300-EP312	0	Site clearance survey
11/26/2011	EP300-EP312	0	Monitoring construction activities
11/26/2011	EP274-EP278	0	Site clearance survey
11/26/2011	EP274-EP278	0	Monitoring construction activities
11/26/2011	EP269-EP271	11	Site clearance survey - Six PBS sited approaching EP270 @ 11:30am. At 5:00pm 5 PBS were sited near EP270
11/26/2011	EP269-EP271	Same 11 as noted above	Monitoring construction activities
11/26/2011	EP269-EP273	Same 11 as noted above	Site clearance survey
11/26/2011	EP269-EP273	Same 11 as noted above	Monitoring construction activities
11/26/2011	EP270	Same 11 as noted above	Site clearance survey
11/26/2011	EP269-EP281	0	Site clearance survey
11/26/2011	EP269-EP281	0	Monitoring construction activities
11/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/26/2011	EP279-EP294	0	Site clearance survey
11/25/2011	EP274-EP278	0	Site clearance survey
11/25/2011	EP274-EP278	0	Monitoring construction activities
11/25/2011	EP272	0	Site clearance survey
11/25/2011	EP269-EP273	1	Site clearance survey - 1 Ram was sighted near EP272 in am
11/25/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/25/2011	EP279-EP294	0	Monitoring construction activities
11/24/2011	EP269-EP273	0	Site clearance survey
11/24/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/24/2011	EP279-EP294	0	Site clearance survey
11/23/2011	EP300-EP312, EP269-EP281	0	Site clearance survey
11/23/2011	EP300-EP312, EP269-EP281	0	Monitoring construction activities
11/23/2011	EP274-EP278	0	Site clearance survey
11/23/2011	EP274-EP278	0	Monitoring construction activities
11/23/2011	EP270-2	0	Monitoring construction activities
11/23/2011	EP269-EP273	0	Site clearance survey
11/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/22/2011	EP277-1	0	Monitoring construction activities
11/22/2011	EP274-EP278	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
11/22/2011	EP269-EP281	0	Site clearance survey
11/22/2011	EP269-EP273	0	Site clearance survey
11/22/2011	EP269-EP270	0	Site clearance survey
11/22/2011	EP269-EP270	0	Monitoring construction activities
11/22/2011	EP269-EP281	0	Site clearance survey
11/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/22/2011	EP279-EP294	0	Site clearance survey
11/22/2011	EP279-EP294	0	Monitoring construction activities
11/21/2011	EP269-EP281	1	Site clearance survey
11/21/2011	EP300-EP312	0	Site clearance survey
11/21/2011	EP300-EP312	0	Monitoring construction activities
11/21/2011	EP300-EP312	0	Site clearance survey
11/21/2011	EP300-EP312	0	Monitoring construction activities
11/21/2011	EP281	0	Monitoring construction activities
11/21/2011	EP276-1-EP270-2	0	Monitoring construction activities
11/21/2011	EP274-EP278	0	Site clearance survey
11/21/2011	EP274-EP278	0	Monitoring construction activities
11/21/2011	EP272	1	Site clearacne surve - 6:45am 1 ram sighted near EP272
11/21/2011	EP269-EP281	0	Site clearance survey
11/21/2011	EP269-EP281	0	Monitoring construction activities
11/21/2011	EP265-2-EP281	0	Monitoring construction activities
11/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/21/2011	EP279-EP294	0	Site clearance survey
11/21/2011	EP279-EP294	0	Monitoring construction activities
11/20/2011	EP300-EP312	0	Site clearance survey
11/20/2011	EP300-EP312	0	Site clearance survey
11/20/2011	EP300-EP312	0	Monitoring construction activities
11/20/2011	EP277-1 and EP272-3	0	Monitoring construction activities
11/20/2011	EP274-EP278	0	Site clearance survey
11/20/2011	EP274-EP278	0	Monitoring construction activities
11/20/2011	EP271	0	Site clearance survey
11/20/2011	EP271	0	Monitoring construction activities
11/20/2011	EP269-EP281	0	Site clearance survey
11/20/2011	EP269-EP281	0	Monitoring construction activities
11/20/2011	EP256-EP263A	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
11/20/2011	EP256-EP263A	0	Monitoring construction activities
11/19/2011	EP300-EP312	0	Site clearance survey
11/19/2011	EP300-EP312	0	Monitoring construction activities
11/19/2011	EP300-EP312	0	Site clearance survey
11/19/2011	EP300-EP312	0	Monitoring construction activities
11/19/2011	EP281	0	Monitoring construction activities
11/19/2011	EP277-1	0	Monitoring construction activities
11/19/2011	EP274-EP278	0	Site clearance survey
11/19/2011	EP274-EP278	0	Monitoring construction activities
11/19/2011	EP269-EP281	0	Site clearance survey
11/19/2011	EP269-EP281	0	Monitoring construction activities
11/19/2011	EP256-EP263A	0	Site clearance survey
11/19/2011	EP256-EP263A	0	Monitoring construction activities
11/18/2011	EP300-EP312	0	Site clearance survey
11/18/2011	EP300-EP312	0	Monitoring construction activities
11/18/2011	EP281-GS-BLM-3	0	Monitoring construction activities
11/18/2011	EP276-1	0	Monitoring construction activities
11/18/2011	EP274-EP278	0	Site clearance survey
11/18/2011	EP274-EP278	0	Monitoring construction activities
11/18/2011	EP272	16	Site clearance survey-PBS were observed within Devil's Cyn 2 west of EP272 @ ~8:00am. At that time the flight corridor was closed to low-elevation flights from EP271-EP273
11/18/2011	EP272	Same 16 PBS as noted above	Monitoring construction activities
11/18/2011	EP269-EP281	0	Site clearance survey
11/18/2011	EP269-EP281	0	Monitoring construction activities
11/18/2011	EP256-EP263A	0	Site clearance survey
11/18/2011	EP256-EP263A	0	Monitoring construction activities
11/17/2011	EP281-GS-BLM-3 & EP290-GS-NF-40	0	Monitoring construction activities
11/17/2011	EP277-1	0	Monitoring construction activities
11/17/2011	EP271-EP274	0	Site clearance survey
11/17/2011	EP300-EP312	0	Site clearance survey
11/17/2011	EP300-EP312	0	Monitoring construction activities
11/16/2011	EP300-EP312	0	Site clearance survey
11/16/2011	EP300-EP312	0	Monitoring construction activities
11/16/2011	EP276-1	0	Monitoring construction activities
11/16/2011	EP272	13	Site clearance survey-PBS were observed ~300 feet west of EP272 at ~7:00am. At that time, low-elevation flights were closed from EP271-EP274

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
11/16/2011	EP272	Same 13 PBS as noted above	Monitoring construction activities
11/16/2011	EP269-EP281	0	Site clearance survey
11/16/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/16/2011	EP274-EP278	0	Site clearance survey
11/16/2011	EP274-EP278	0	Monitoring construction activities
11/16/2011	EP269-EP281	0	Site clearance survey
11/16/2011	EP269-EP281	0	Monitoring construction activities
11/15/2011	EP269-EP273	0	Site clearance survey
11/15/2011	EP269-EP281	0	Site clearance survey
11/15/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/15/2011	EP274-EP278	0	Site clearance survey
11/15/2011	EP274-EP278	0	Monitoring construction activities
11/15/2011	AER and Fromm CY's	0	Monitoring construction activities
11/14/2011	EP306-EP312	0	Site clearance survey
11/14/2011	EP269-EP273	0	Site clearance survey
11/14/2011	EP263A-2, EP263B-2	0	Monitoring construction activities
11/14/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/14/2011	EP274-EP278	0	Site clearance survey
11/14/2011	EP274-EP278	0	Monitoring construction activities
11/13/2011	EP306-EP312	0	Site clearance survey
11/13/2011	EP300-EP312	0	Site clearance survey
11/13/2011	EP300-EP312	0	Monitoring construction activities
11/13/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/13/2011	EP274-EP278	0	Site clearance survey
11/13/2011	EP274-EP278	0	Monitoring construction activities
11/13/2011	EP269-EP281	0	Site clearance survey
11/13/2011	EP269-EP281	0	Monitoring construction activities
11/12/2011	EP300-EP312	0	Site clearance survey
11/12/2011	EP300-EP312	0	Monitoring construction activities
11/12/2011	EP269-EP281	0	Site clearance survey
11/12/2011	EP269-EP281	0	Monitoring construction activities
11/12/2011	EP263B-2	0	Monitoring construction activities
11/12/2011	EP274-EP278	0	Site clearance survey
11/12/2011	EP274-EP278	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
11/12/2011	EP269-EP281	0	Site clearance survey
11/12/2011	EP269-EP281	0	Monitoring construction activities
11/11/2011	EP306-EP312	0	Site clearance survey
11/11/2011	EP300-EP312	0	Monitoring construction activities
11/11/2011	EP269-EP281	0	Site clearance survey
11/11/2011	EP269-EP281	0	Monitoring construction activities
11/11/2011	EP269-EP273	0	Site clearance survey
11/11/2011	EP269-EP270	0	Site clearance survey
11/11/2011	EP269-EP270	0	Monitoring construction activities
11/11/2011	EP263B-EP267	0	Site clearance survey
11/11/2011	EP263B-EP267	0	Monitoring construction activities
11/11/2011	EP274-EP278	0	Site clearance survey
11/11/2011	EP274-EP278	0	Monitoring construction activities
11/11/2011	EP269-EP281	0	Site clearance survey
11/11/2011	EP269-EP281	0	Monitoring construction activities
11/10/2011	EP306-EP312	0	Site clearance survey
11/10/2011	EP269-EP273	0	Site clearance survey
11/10/2011	EP269-EP281	0	Site clearance survey
11/10/2011	EP269-EP281	0	Monitoring construction activities
11/10/2011	EP269-EP270	0	Site clearance survey
11/10/2011	EP269-EP270	0	Monitoring construction activities
11/10/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/10/2011	EP274-EP278	0	Site clearance survey
11/10/2011	EP274-EP278	0	Monitoring construction activities
11/9/2011	Fromm CY	0	Monitoring construction activities
11/9/2011	EP313/EP314 Pullsite	0	Monitoring construction activities
11/9/2011	EP306-EP312	0	Site clearance survey
11/9/2011	EP306	0	Monitoring construction activities
11/9/2011	EP269-EP273	0	Site clearance survey
11/9/2011	EP269-EP281	0	Site clearance survey
11/9/2011	EP269-EP281	0	Monitoring construction activities
11/9/2011	EP265-2	0	Site clearance survey
11/9/2011	EP265-2	0	Monitoring construction activities
11/9/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/9/2011	EP274-EP278	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
11/9/2011	EP274-EP278	0	Monitoring construction activities
11/9/2011	EP263B-EP267, EP269-EP281	0	Site clearance survey
11/9/2011	EP263B-EP267, EP269-EP281	0	Monitoring construction activities
11/8/2011	EP306-EP312	0	Site clearance survey
11/8/2011	EP300-EP312	0	Site clearance survey
11/8/2011	EP300-EP312	0	Monitoring construction activities
11/8/2011	EP280	0	Monitoring construction activities
11/8/2011	EP272-EP275	0	Site clearance survey
11/8/2011	EP272-EP275	5	Monitoring construction activities
11/8/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/8/2011	EP279-EP294	0	Site clearance survey
11/8/2011	EP279-EP294	0	Monitoring construction activities
11/8/2011	EP274-EP278	0	Site clearance survey
11/8/2011	EP274-EP278	0	Monitoring construction activities
11/8/2011	EP269-EP281	0	Site clearance survey
11/8/2011	EP269-EP281	0	Monitoring construction activities
11/8/2011	EP263B-EP267, EP269-EP281	0	Site clearance survey
11/8/2011	EP263B-EP267, EP269-EP281	0	Monitoring construction activities
11/8/2011	Devils Cyn Bridge	5	Monitoring construction activities
11/7/2011	EP307-EP308	0	Monitoring construction activities
11/7/2011	EP300-EP312	0	Site clearance survey
11/7/2011	EP300-EP312	0	Monitoring construction activities
11/7/2011	EP280	0	Monitoring construction activities
11/7/2011	EP271-EP274	3	Site clearance survey
11/7/2011	EP271-EP274	0	Site clearance survey
11/7/2011	EP271-EP274	5	Site clearance survey
11/7/2011	EP271-EP274	0	Monitoring construction activities
11/7/2011	EP269-EP271	0	Site clearance survey
11/7/2011	EP269-EP271	0	Monitoring construction activities
11/7/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/7/2011	EP278-EP281	0	Site clearance survey
11/7/2011	EP274-EP278	0	Site clearance survey
11/7/2011	EP274-EP278	0	Monitoring construction activities
11/7/2011	EP269-EP281	0	Site clearance survey
11/7/2011	EP269-EP281	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
11/7/2011	EP263B-EP267	0	Site clearance survey
11/7/2011	EP263B-EP267	0	Monitoring construction activities
11/6/2011	EP308-EP310	0	Monitoring construction activities
11/6/2011	EP303-2, EP302-1	0	Monitoring construction activities
11/6/2011	EP300-EP312	0	Site clearance survey
11/6/2011	EP300-EP312	0	Monitoring construction activities
11/6/2011	EP300-EP312	0	Site clearance survey
11/6/2011	EP300-EP312	0	Monitoring construction activities
11/6/2011	EP290-EP312, EP269-EP281	0	Site clearance survey
11/6/2011	EP290-EP312, EP269-EP281	0	Monitoring construction activities
11/6/2011	EP279-1	0	Monitoring construction activities
11/6/2011	EP269-EP281	0	Site clearance survey
11/6/2011	EP269-EP281	0	Monitoring construction activities
11/6/2011	EP274-EP278	0	Monitoring construction activities
11/6/2011	EP274-EP278	0	Site clearance survey
11/6/2011	EP269-EP281	0	Monitoring construction activities
11/6/2011	EP269-EP281	0	site clearance survey
11/5/2011	EP300-EP312	0	Site clearance survey
11/5/2011	EP300-EP312	0	Monitoring construction activities
11/5/2011	EP271-2, EP272-3, EP276-1 & EP281	0	Monitoring construction activities
11/5/2011	EP269-EP273	0	Site clearance survey
11/5/2011	EP265-2	0	Monitoring construction activities
11/5/2011	EP256-EP263A	0	Site clearance survey
11/5/2011	EP279-EP294	0	Site clearance survey
11/5/2011	EP279-EP294	0	Monitoring construction activities
11/5/2011	EP277-1	0	Monitoring construction activities
11/5/2011	EP263B-EP267	0	Site clearance survey
11/5/2011	EP263B-EP267	0	Monitoring construction activities
11/4/2011	S2 CY	0	Monitoring construction activities
11/4/2011	EP311, EP310	0	Monitoring construction activities
11/4/2011	EP307	0	Monitoring construction activities
11/4/2011	EP306/EP307 Pullsite	0	Monitoring construction activities
11/4/2011	EP300-EP312	0	Site clearance survey
11/4/2011	EP300-EP312	0	Monitoring construction activities
11/4/2011	EP269-EP273	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
11/4/2011	EP269-EP271	0	Site clearance survey
11/4/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/4/2011	EP279-EP294	0	Site clearance survey
11/4/2011	EP279-EP294	0	Monitoring construction activities
11/4/2011	EP274-EP278	0	Site clearance survey
11/4/2011	EP274-EP278	0	Monitoring construction activities
11/4/2011	EP263B-EP267	0	Site clearance survey
11/4/2011	EP263B-EP267	0	Monitoring construction activities
11/3/2011	EP311	0	Monitoring construction activities
11/3/2011	EP307	0	Monitoring construction activities
11/3/2011	EP280	0	Monitoring construction activities
11/3/2011	EP279-1	0	Monitoring construction activities
11/3/2011	EP278-1, EP279-1, EP280-1	0	Monitoring construction activities
11/3/2011	EP271-2	0	Monitoring construction activities
11/3/2011	EP269-EP273	0	Site clearance survey
11/3/2011	EP265-2	0	Monitoring construction activities
11/3/2011	EP263B-EP267; EP279-EP312	0	Site clearance survey
11/3/2011	EP261A, EP259-3	0	Monitoring construction activities
11/3/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/3/2011	EP279-EP294	0	Site clearance survey
11/3/2011	EP279-EP294	0	Monitoring construction activities
11/3/2011	EP274-EP278	0	Site clearance survey
11/3/2011	EP274-EP278	0	Monitoring construction activities
11/2/2011	EP269-EP273	0	Site clearance survey
11/2/2011	EP269-EP281	0	Site clearance survey
11/2/2011	EP269-EP281	0	Monitoring construction activities
11/2/2011	EP263B-EP267; EP279-EP312	0	Site clearance survey
11/2/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/2/2011	EP300-EP312; EP274-EP278	0	Site clearance survey
11/2/2011	EP300-EP312; EP274-EP278	0	Monitoring construction activities
11/1/2011	Suckle Property	0	Monitoring construction activities
11/1/2011	EP310 & EP311	0	Monitoring construction activities
11/1/2011	EP300-EP312	0	Site clearance survey
11/1/2011	EP300-EP312	0	Monitoring construction activities
11/1/2011	EP279-EP312	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
11/1/2011	EP277-1, EP276-1, EP261A, EP259B	0	Monitoring construction activities
11/1/2011	EP275-1	0	Monitoring construction activities
11/1/2011	EP269-EP273	0	Site clearance survey
11/1/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
11/1/2011	EP274-EP278	0	Site clearance survey
11/1/2011	EP274-EP278	0	Monitoring construction activities
11/1/2011	EP263B, EP267	0	Site clearance survey
11/1/2011	Devil's Canyon Bridge	0	Site clearance survey
11/1/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/31/2011	EP279-EP294	0	Site clearance survey
10/31/2011	EP279-EP294	0	Monitoring construction activities
10/31/2011	EP269-EP281	0	Site clearance survey
10/31/2011	EP269-EP281	0	Monitoring construction activities
10/31/2011	EP269-EP273	0	Site clearance survey
10/31/2011	EP269-EP281	0	Site clearance survey
10/31/2011	EP263A-2, EP266-2	0	Monitoring construction activities
10/31/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/31/2011	EP254-3	0	Monitoring construction activities
10/31/2011	EP305, EP310-1	0	Monitoring construction activities
10/31/2011	EP300-EP312	0	Site clearance survey
10/31/2011	EP300-EP312	0	Monitoring construction activities
10/31/2011	EP274-EP278	0	Site clearance survey
10/31/2011	EP263B-EP267	0	Site clearance survey
10/31/2011	Devil's Canyon Bridge	0	Site clearance survey
10/31/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/31/2011	EP262-4, EP263B-2, EP265-2, EP266-2, EP267-1	0	Monitoring construction activities
10/30/2011	EP300-EP306	0	Site clearance survey
10/30/2011	EP300-EP306	0	Monitoring construction activities
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Monitoring construction activities
10/30/2011	EP269-EP273	0	Site clearance survey
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Site clearance survey
10/30/2011	EP269-EP281	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
10/30/2011	EP269-EP270	0	Site clearance survey
10/30/2011	EP267-2 & EP266-2	0	Monitoring construction activities
10/30/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/30/2011	EP279-EP294	0	Site clearance survey
10/30/2011	EP279-EP294	0	Monitoring construction activities
10/30/2011	EP274-EP278	0	Site clearance survey
10/30/2011	EP274-EP278	0	Monitoring construction activities
10/30/2011	EP263B-EP267	0	Site clearance survey
10/30/2011	Devil's Canyon Bridge	0	Site clearance survey
10/30/2011	Devil's Canyon Bridge	0	Monitoring construction activities
10/29/2011	EP300-EP306	0	Site clearance survey
10/29/2011	EP300-EP306	0	Monitoring construction activities
10/29/2011	EP274-EP278	0	Site clearance survey
10/29/2011	EP274-EP278	0	Monitoring construction activities
10/29/2011	EP269-EP273	0	Site clearance survey
10/29/2011	EP269-1	0	Monitoring construction activities
10/29/2011	EP269-EP281	0	Site clearance survey
10/29/2011	EP269-EP281	0	Monitoring construction activities
10/29/2011	EP269-EP281	0	Site clearance survey
10/29/2011	EP269-EP281	0	Monitoring construction activities
10/29/2011	EP269-EP270	0	Site clearance survey
10/29/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/29/2011	EP279-EP294	0	Site clearance survey
10/29/2011	EP279-EP294	0	Monitoring construction activities
10/29/2011	EP263B-EP267	0	Site clearance survey
10/29/2011	Devil's Cyn Bridge (w/in I-8 Island)	1	Morning perimeter survey 7:37 am
10/28/2011	EP300-EP306	0	Site clearance survey
10/28/2011	EP300-EP306	0	Monitoring construction activities
10/28/2011	EP269-EP281	0	Site clearance survey
10/28/2011	EP269-EP281	0	Monitoring construction activities
10/28/2011	EP269-EP273	0	Site clearance survey
10/28/2011	EP269-1	0	Monitoring construction activities
10/28/2011	EP269-EP281	0	Site clearance survey
10/28/2011	EP269-EP281	0	Monitoring construction activities
10/28/2011	EP269-EP270	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
10/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/28/2011	EP310	0	Monitoring construction activities
10/28/2011	EP279-EP294	0	Site clearance survey
10/28/2011	EP279-EP294	0	Monitoring construction activities
10/28/2011	EP274-EP278	0	Site clearance survey
10/28/2011	EP274-EP278	0	Monitoring construction activities
10/28/2011	EP263B-EP267	0	Site clearance survey
10/28/2011	AER and FROMM CY	0	Monitoring construction activities
10/27/2011	EP273-1 & EP276-1	0	Monitoring construction activities
10/27/2011	EP271-EP272	2	Site clearance survey 7:40 am
10/27/2011	EP271-EP272	0	Monitoring construction activities
10/27/2011	EP269-EP281: EP300-EP306	0	Site clearance survey
10/27/2011	EP269-EP281: EP300-EP306	0	Monitoring construction activities
10/27/2011	EP256-EP263A-2, AER CY	0	Site clearance survey
10/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/27/2011	EP279-EP294	0	Site clearance survey
10/27/2011	EP279-EP294	0	Monitoring construction activities
10/27/2011	EP274-EP278	0	Site clearance survey
10/27/2011	EP274-EP278	0	Monitoring construction activities
10/27/2011	EP269-EP271	0	Monitoring construction activities
10/27/2011	EP263B-EP267	0	Site clearance survey
10/27/2011	AER and FROMM CY	0	Monitoring construction activities
10/26/2011	EP311-1, EP312, EP310	0	Monitoring construction activities
10/26/2011	EP300-EP312	0	Site clearance survey
10/26/2011	EP300-EP312	0	Monitoring construction activities
10/26/2011	EP272-EP273	2	Site clearance survey 10:00 am
10/26/2011	EP272-EP273	0	Monitoring construction activities
10/26/2011	EP269-EP281; EP300-EP306	0	Site clearance survey
10/26/2011	EP269-EP281; EP300-EP306	0	Monitoring construction activities
10/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
10/26/2011	EP279-EP294	0	Site clearance survey
10/26/2011	EP279-EP294	0	Monitoring construction activities
10/26/2011	EP274-EP278	0	Site clearance survey
10/26/2011	EP274-EP278	0	Monitoring construction activities
10/26/2011	EP263B-EP267	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
10/25/2011	EP363-EP341, EP299 & EP300	0	Monitoring construction activities
10/25/2011	EP313-EP324	0	Monitoring construction activities
10/25/2011	EP310	0	Monitoring construction activities
10/25/2011	EP300-EP312	0	Site clearance survey
10/25/2011	EP300-EP312	0	Monitoring construction activities
10/25/2011	EP290	0	Monitoring construction activities
10/25/2011	EP269-EP273	0	Site clearance survey
10/25/2011	EP269-EP281; EP300-EP306	0	Site clearance survey
10/25/2011	EP269-EP281; EP300-EP306	0	Monitoring construction activities
10/25/2011	EP311	0	Monitoring construction activities
10/25/2011	EP279-EP294	0	Site clearance survey
10/25/2011	EP263B-EP267	0	Site clearance survey
10/24/2011	EP313-EP322	0	Monitoring construction activities
10/24/2011	EP305, EP306, EP312	0	Monitoring construction activities
10/24/2011	EP300-EP306	0	Site clearance survey
10/24/2011	EP300-EP306	0	Monitoring construction activities
10/24/2011	EP297-EP319	0	Monitoring construction activities
10/24/2011	EP269-EP273	0	Site clearance survey
10/24/2011	EP269-EP273	0	Monitoring construction activities
10/24/2011	EP269-EP281	0	Site clearance survey
10/24/2011	EP269-EP281	0	Monitoring construction activities
10/24/2011	EP279-EP294	0	Site clearance survey
10/24/2011	EP279-EP294	0	Monitoring construction activities
10/24/2011	EP274-EP278	0	Site clearance survey
10/24/2011	EP274-EP278	0	Monitoring construction activities
10/24/2011	EP263B-EP267	0	Site clearance survey
10/23/2011	EP300-EP312	0	Site clearance survey
10/23/2011	EP300-EP312	0	Monitoring construction activities
10/23/2011	EP269-EP273	0	Site clearance survey
10/23/2011	EP269-EP273	0	Monitoring construction activities
10/23/2011	EP269-EP281	0	Site clearance survey
10/23/2011	EP269-EP281	0	Monitoring construction activities
10/23/2011	EP269-EP270	0	Site clearance survey
10/23/2011	EP263B-EP267	0	Site clearance survey
10/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
10/23/2011	EP300-EP312	0	Site clearance survey
10/23/2011	EP300-EP312	0	Monitoring construction activities
10/23/2011	EP274-EP278	0	Site clearance survey
10/23/2011	EP274-EP278	0	Monitoring construction activities
10/23/2011	EP269-EP273	0	Site clearance survey
10/23/2011	EP269-EP273	0	Monitoring construction activities
10/22/2011	EP300-EP306	0	Site clearance survey
10/22/2011	EP300-EP306	0	Monitoring construction activity
10/22/2011	EP269-EP281	0	Site clearance survey
10/22/2011	EP269-EP281	0	Monitoring construction activity
10/22/2011	EP269-EP281	0	Site clearance survey
10/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/22/2011	EP274-EP278	0	Site clearance survey
10/22/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP306-EP312	0	Site clearance survey
10/21/2011	EP306-EP312	0	Monitoring construction activity
10/21/2011	EP274-EP278	0	Site clearance survey
10/21/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP269-EP281	0	Site clearance survey
10/21/2011	EP269-EP281	0	Site clearance survey
10/21/2011	EP269-EP281	0	Monitoring construction activity
10/21/2011	EP269-EP270	0	Site clearance survey
10/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/21/2011	EP274-EP278	0	Site clearance survey
10/21/2011	EP274-EP278	0	Monitoring construction activity
10/21/2011	EP269-EP273	0	Site clearance survey
10/21/2011	EP269-EP273	0	Monitoring construction activity
10/20/2011	EP269-EP281	0	Site clearance survey
10/20/2011	EP269	0	Site clearance survey
10/20/2011	EP269	0	Monitoring construction activity
10/20/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/20/2011	EP274-EP278	0	Site clearance survey
10/20/2011	EP274-EP278	0	Monitoring construction activity
10/20/2011	EP269-EP273	0	Site clearance survey
10/20/2011	EP269-EP273	0	Monitoring construction activity

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
10/20/2011	EP263B-EP267	0	Site clearance survey
10/20/2011	EP300-EP312	0	Site clearance survey
10/20/2011	EP300-EP312	0	Monitoring construction activity
10/19/2011	EP290-EP312	0	Site clearance survey
10/19/2011	EP290-EP312	0	Monitoring construction activity
10/19/2011	EP269-EP281	0	Site clearance survey
10/19/2011	EP300-EP312	0	Site clearance survey
10/19/2011	EP300-EP312	0	Monitoring construction activity
10/19/2011	EP274-EP278	0	Site clearance survey
10/19/2011	EP274-EP278	0	Monitoring construction activity
10/19/2011	EP269-EP273	0	Site clearance survey
10/19/2011	EP269-EP273	0	Monitoring construction activity
10/19/2011	EP263B-EP267	0	Site clearance survey
10/18/2011	Slay Property	0	Monitoring construction activity
10/18/2011	EP269-EP270	0	Site clearance survey
10/18/2011	EP269-EP270	0	Monitoring construction activity
10/18/2011	EP269-EP281	0	Site clearance survey
10/18/2011	EP269-EP270	0	Site clearance survey
10/18/2011	EP274-EP278	0	Site clearance survey
10/18/2011	EP274-EP278	0	Monitoring construction activity
10/18/2011	EP269-EP273	0	Site clearance survey
10/18/2011	EP269-EP273	0	Monitoring construction activity
10/18/2011	EP263B-EP267	0	Site clearance survey
10/17/2011	Slay Property	0	Site clearance survey
10/17/2011	EP312 & EP314	0	Monitoring construction activity
10/17/2011	EP306-EP312	0	Site clearance survey
10/17/2011	EP306-EP312	0	Afternoon perimeter survey
10/17/2011	EP305	0	Monitoring construction activity
10/17/2011	EP300-EP363	0	Monitoring construction activity
10/17/2011	EP300-EP306	0	Site clearance survey
10/17/2011	EP300-EP306	0	Monitoring construction activity
10/17/2011	EP270-2	0	Monitoring construction activity
10/17/2011	EP269-EP270	0	Site clearance survey
10/17/2011	EP269-EP270	0	Monitoring construction activity
10/17/2011	EP269-EP281	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
10/17/2011	EP269-EP270	0	Site clearance survey
10/17/2011	EP267-2	0	Monitoring construction activity
10/17/2011	EP261-2	0	Monitoring construction activity
10/17/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activity
10/17/2011	EP274-EP278	0	Site clearance survey
10/17/2011	EP274-EP278	0	Monitoring construction activity
10/17/2011	EP269-EP273	0	Site clearance survey
10/17/2011	EP269-EP273	0	Monitoring construction activity
10/17/2011	EP263B-EP267	0	Site clearance survey
10/16/2011	EP306-EP312	0	Site clearance survey
10/16/2011	EP306-EP312	0	Afternoon perimeter survey
10/16/2011	EP300-EP306	0	Site clearance survey
10/16/2011	EP300-EP306	0	Monitoring construction activity
10/16/2011	EP271-2	0	Monitoring construction activity
10/16/2011	EP270-2	0	Monitoring construction activity
10/16/2011	EP269-EP270	0	Site clearance survey
10/16/2011	EP256-EP281	0	Site clearance survey
10/16/2011	EP305	0	Monitoring construction activity
10/16/2011	EP274-EP278	0	Site clearance survey
10/16/2011	EP274-EP278	0	Monitoring construction activity
10/16/2011	EP269-EP273	0	Site clearance survey
10/16/2011	EP269-EP273	0	Monitoring construction activity
10/16/2011	EP263B-EP267	0	Site clearance survey
10/16/2011	EP256-EP263A-2, AER & FROMM CY	0	Site clearance survey
10/16/2011	EP256-EP263A-2, AER & FROMM CY	0	Monitoring construction activity
10/15/2011	Slay Property	0	Site clearance survey
10/15/2011	Slay Property	0	Monitoring construction activities
10/15/2011	EP306-EP312	0	Site clearance survey
10/15/2011	EP306-EP312	0	Afternoon perimeter survey
10/15/2011	EP305	0	Monitoring construction activities
10/15/2011	EP300-EP306	0	Site clearance survey
10/15/2011	EP300-EP306	0	Monitoring construction activities
10/15/2011	EP269-1 AND EP273-1	0	Monitoring construction activities
10/15/2011	EP269-EP281	0	Morning perimeter survey
10/15/2011	EP261-2	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
10/15/2011	EP274-EP278	0	Site clearance survey
10/15/2011	EP274-EP278	0	Monitoring construction activities
10/15/2011	EP263B-EP267	0	Site clearance survey
10/14/2011	Slay Property	0	Site clearance survey
10/14/2011	Slay Property	0	Monitoring construction activities
10/14/2011	EP310	0	Monitoring construction activities
10/14/2011	EP305	0	Monitoring construction activities
10/14/2011	EP300-EP306	0	Site clearance survey
10/14/2011	EP300-EP306	0	Monitoring construction activities
10/14/2011	EP291-EP301	0	Monitoring construction activities
10/14/2011	EP269 through EP281	0	Site clearance survey
10/14/2011	EP269-EP270	0	Site clearance survey
10/14/2011	EP263B-2	0	Monitoring construction activities
10/14/2011	EP256-EP263A	0	Site clearance survey
10/14/2011	EP256-EP263A	0	Monitoring construction activities
10/14/2011	EP274-EP278	0	Site clearance survey
10/14/2011	EP274-EP278	0	Monitoring construction activities
10/14/2011	EP269-EP273	0	Site clearance survey
10/14/2011	EP269-EP273	0	Monitoring construction activities
10/14/2011	EP263B-EP267	0	Site clearance survey
10/14/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/14/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/13/2011	Slay Property	0	Site clearance survey
10/13/2011	Slay Property	0	Monitoring construction activities
10/13/2011	EP310	0	Monitoring construction activities
10/13/2011	EP306-EP312	0	Site clearance survey
10/13/2011	EP306-EP312	0	Afternoon perimeter survey
10/13/2011	EP293	0	Monitoring construction activities
10/13/2011	EP291-EP301	0	Monitoring construction activities
10/13/2011	EP275-1	0	Monitoring construction activities
10/13/2011	EP269-EP270	0	Site clearance survey
10/13/2011	EP269-EP281	0	Site clearance survey
10/13/2011	EP269-EP270	0	Site clearance survey
10/13/2011	EP266-2	0	Monitoring construction activities
10/13/2011	EP274-EP278	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
10/13/2011	EP274-EP278	0	Monitoring construction activities
10/13/2011	EP269-EP273	0	Site clearance survey
10/13/2011	EP269-EP273	0	Monitoring construction activities
10/13/2011	EP263B-EP267	0	Site clearance survey
10/13/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/13/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/12/2011	Slay Property	0	Site clearance survey
10/12/2011	Slay Property	0	Monitoring construction activities
10/12/2011	EP306-EP312	0	Site clearance survey
10/12/2011	EP291-EP301	0	Monitoring construction activities
10/12/2011	EP269-EP270	0	Site clearance survey
10/12/2011	EP269-EP281	0	Site clearance survey
10/12/2011	EP269-EP281	0	Monitoring construction activities
10/12/2011	EP269-EP270	0	Site clearance survey
10/12/2011	EP311	0	Monitoring construction activities
10/12/2011	EP274-EP278	0	Site clearance survey
10/12/2011	EP274-EP278	0	Monitoring construction activities
10/12/2011	EP269-EP273	0	Site clearance survey
10/12/2011	EP269-EP273	0	Monitoring construction activities
10/12/2011	EP263B-EP267	0	Site clearance survey
10/12/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/12/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/11/2011	Slay Property	0	Site clearance survey
10/11/2011	Slay Property	0	Monitoring construction activities
10/11/2011	EP311	0	Monitoring construction activities
10/11/2011	EP306-EP312	0	Site clearance survey
10/11/2011	EP306-EP312	0	Afternoon perimeter survey
10/11/2011	EP300-EP306	0	Site clearance survey
10/11/2011	EP291-EP301	0	Monitoring construction activities
10/11/2011	EP269-EP273	0	Site clearance survey
10/11/2011	EP269-EP273	0	Monitoring construction activities
10/11/2011	EP269-EP270	0	Site clearance survey
10/11/2011	EP269-EP270	0	Monitoring construction activities
10/11/2011	EP274-EP278	0	Site clearance survey
10/11/2011	EP274-EP278	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
10/11/2011	EP263B-EP267	0	Site clearance survey
10/11/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/11/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/10/2011	Slay Property	0	Site clearance survey
10/10/2011	Slay Property	0	Monitoring construction activities
10/10/2011	EP306-EP312	0	Site clearance survey
10/10/2011	EP306-EP312	0	Afternoon perimeter survey
10/10/2011	EP305	0	Monitoring construction activities
10/10/2011	EP300-EP306	0	Site clearance survey
10/10/2011	EP300-EP306	0	Monitoring construction activities
10/10/2011	EP300-EP306	0	Site clearance survey
10/10/2011	EP291-EP301	0	Monitoring construction activities
10/10/2011	EP269-EP281	9	Sheep were seen entering I-8 Island during Site Clearance survey
10/10/2011	EP269-EP273	0	Site clearance survey
10/10/2011	EP269-EP273	0	Monitoring construction activities
10/10/2011	EP259-3	0	Monitoring construction activities
10/10/2011	EP274-EP278	0	Site clearance survey
10/10/2011	EP274-EP278	0	Monitoring construction activities
10/10/2011	EP263B-EP267	0	Site clearance survey
10/10/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/10/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/9/2011	EP306-EP312	0	Site clearance survey
10/9/2011	EP306-EP312	0	Monitoring construction activities
10/9/2011	EP300-EP306	0	Site clearance survey
10/9/2011	EP300-EP306	0	Monitoring construction activities
10/9/2011	EP300-EP306	0	Site clearance survey
10/9/2011	EP300-EP306	0	Monitoring construction activities
10/9/2011	EP269-EP273	0	Site clearance survey
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP269-EP270	0	Monitoring construction activities
10/9/2011	EP269-EP270	0	Site clearance survey
10/9/2011	EP256-3	0	Monitoring construction activities
10/9/2011	EP274-EP278	0	Site clearance survey
10/9/2011	EP274-EP278	0	Monitoring construction activities
10/9/2011	EP269-EP270	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
10/9/2011	EP269-EP270	0	Monitoring construction activities
10/9/2011	EP256-EP263A, AER and FROMM CYs	0	Site clearance survey
10/9/2011	EP256-EP263A, AER and FROMM CYs	0	Monitoring construction activities
10/8/2011	EP300-EP306	0	Site clearance survey
10/8/2011	EP300-EP306	0	Monitoring construction activity
10/8/2011	EP300-EP306	0	Site clearance survey
10/8/2011	EP300-EP306	0	Morning perimeter survey
10/8/2011	EP291-EP301	0	Monitoring construction activity
10/8/2011	EP278-1	0	Monitoring construction activity
10/8/2011	EP269-EP273	0	Site clearance survey
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP269-EP270	0	Monitoring construction activity
10/8/2011	EP269/EP270 Pullsite	0	Monitoring construction activity
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP259-3	0	Monitoring construction activity
10/8/2011	EP274-EP278	0	Site clearance survey
10/8/2011	EP274-EP278	0	Monitoring construction activity
10/8/2011	EP269-EP270	0	Site clearance survey
10/8/2011	EP269-EP270	0	Monitoring construction activity
10/8/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/8/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/7/2011	Slay Property	0	Site clearance survey
10/7/2011	EP306-EP312	0	Site clearance survey
10/7/2011	EP306-EP312	0	Morning perimeter survey
10/7/2011	EP300-EP306	0	Site clearance survey
10/7/2011	EP300-EP306	0	Monitoring construction activity
10/7/2011	EP300-EP306	0	Site clearance survey
10/7/2011	EP300-EP306	0	Morning perimeter survey
10/7/2011	EP291-EP301	0	Site clearance survey
10/7/2011	EP269-EP273	0	Site clearance survey
10/7/2011	EP269-EP270	0	Site clearance survey
10/7/2011	EP269-EP270	0	Monitoring construction activity
10/7/2011	EP269-EP270	0	Site clearance survey
10/7/2011	EP259-3	0	Monitoring construction activity
10/7/2011	EP274-EP278	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
10/7/2011	EP274-EP278	0	Monitoring construction activity
10/7/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/7/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/6/2011	Slay Property	0	Site clearance survey
10/6/2011	Slay Property	0	Monitoring construction activity
10/6/2011	EP306-EP312	0	Site clearance survey
10/6/2011	EP306-EP312	0	Monitoring construction activity
10/6/2011	EP291-EP301	0	Site clearance survey
10/6/2011	EP269-EP273	0	Site clearance survey
10/6/2011	EP269-EP270	0	Site clearance survey
10/6/2011	EP269-EP270	0	Monitoring construction activity
10/6/2011	EP269-EP281	0	Site clearance survey
10/6/2011	EP269-EP270	0	Site clearance survey
10/6/2011	EP263B-EP267	0	Site clearance survey
10/6/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/6/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/5/2011	Slay Property	0	Site clearance survey
10/5/2011	Slay Property	0	Monitoring construction activity
10/5/2011	EP303-2	0	Monitoring construction activity
10/5/2011	EP291-EP301	0	Site clearance survey
10/5/2011	EP269-EP273	0	Site clearance survey
10/5/2011	EP269-EP270	0	Site clearance survey
10/5/2011	EP269-EP270	0	Monitoring construction activity
10/5/2011	EP274-EP278	0	Site clearance survey
10/5/2011	EP274-EP278	0	Monitoring construction activity
10/5/2011	EP269-EP281	0	Site clearance survey
10/5/2011	EP269-EP270	0	Site clearance survey
10/5/2011	EP263B-EP267	0	Site clearance survey
10/5/2011	EP256-EP263A, AER & FROMM CY's	0	Site clearance survey
10/5/2011	EP256-EP263A, AER & FROMM CY's	0	Monitoring construction activity
10/4/2011	Slay Property	0	Site clearance survey
10/4/2011	Slay Property	0	Monitoring construction activity
10/4/2011	EP300-EP306	0	Site clearance survey
10/4/2011	EP300-EP306	0	Monitoring construction activity
10/4/2011	EP269-EP273	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
10/4/2011	EP269-EP270	0	Site clearance survey
10/4/2011	EP269-EP270	0	Monitoring construction activity
10/4/2011	EP256-EP263A	0	Site clearance survey
10/4/2011	EP274-EP278	0	Site clearance survey
10/4/2011	EP274-EP278	0	Monitoring construction activity
10/4/2011	EP263B-EP267	0	Site clearance survey
10/3/2011	Slay Property	0	Site clearance survey
10/3/2011	Slay Property	0	Monitoring construction activity
10/3/2011	EP300-EP306	0	Site clearance survey
10/3/2011	EP300-EP306	0	Monitoring construction activity
10/3/2011	EP300-EP306	0	Site clearance survey
10/3/2011	EP300-EP306	0	Morning perimeter survey
10/3/2011	EP291-EP341	0	Site clearance survey
10/3/2011	EP279-EP294	0	Site clearance survey
10/3/2011	EP269-EP273	0	Site clearance survey
10/3/2011	EP269-EP273	0	Monitoring construction activity
10/3/2011	EP263B-EP267	0	Site clearance survey
10/3/2011	EP263B-EP267	0	Monitoring construction activity
10/3/2011	EP256-EP263A	0	Site clearance survey
10/3/2011	EP274-EP278	0	Site clearance survey
10/3/2011	EP274-EP278	0	Monitoring construction activity
10/3/2011	EP263B-EP267	0	Site clearance survey
10/2/2011	EP300-EP306	0	Site clearance survey
10/2/2011	EP300-EP306	0	Monitoring construction activity
10/2/2011	EP269-EP281	0	Afternoon perimeter survey
10/2/2011	EP269-EP273	0	Afternoon perimeter survey
10/1/2011	EP300-EP306	0	Site clearance survey
10/1/2011	EP300-EP306	0	Monitoring construction activities
10/1/2011	EP300-EP306	0	Site clearance survey
10/1/2011	EP300-EP306	0	Morning perimeter survey
10/1/2011	EP269-EP273 and EP256-EP261	0	Site clearance survey
10/1/2011	EP269-EP273	0	Site clearance survey
10/1/2011	EP269-EP270	0	Site clearance survey
10/1/2011	EP274-EP278	0	Site clearance survey
10/1/2011	EP274-EP278	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
9/30/2011	Slay Property	0	Site clearance survey
9/30/2011	Slay Property	0	Monitoring construction activities
9/30/2011	EP300-EP312	0	Site clearance survey
9/30/2011	EP300-EP312	0	Monitoring construction activities
9/30/2011	EP300-EP306	0	Site clearance survey
9/30/2011	EP300-EP306	0	Monitoring construction activities
9/30/2011	EP291-EP348	0	Monitoring construction activities
9/30/2011	EP290-EP294, EP300-EP312	0	Site clearance survey
9/30/2011	EP290-EP294, EP300-EP312	0	Monitoring construction activities
9/30/2011	EP269-EP273	0	Site clearance survey
9/30/2011	EP269-EP273	0	Monitoring construction activities
9/30/2011	EP269-EP281	0	Site clearance survey
9/30/2011	EP279-EP294	0	Site clearance survey
9/30/2011	EP274-EP278	0	Site clearance survey
9/30/2011	EP274-EP278	0	Monitoring construction activities
9/30/2011	EP263-B-EP267	0	Site clearance survey
9/30/2011	EP256-EP263A, AER, Fromm CY	0	Site clearance survey
9/30/2011	EP256-EP263A, AER, Fromm CY	0	Monitoring construction activities
9/29/2011	Slay Property	0	Site clearance survey
9/29/2011	Slay Property	0	Monitoring construction activities
9/29/2011	EP300-EP312	0	Site clearance survey
9/29/2011	EP300-EP306	0	Site clearance survey
9/29/2011	EP300-EP306	0	Monitoring construction activities
9/29/2011	EP290-EP294, EP300-EP312	0	Site clearance survey
9/29/2011	EP290-EP294, EP300-EP312	0	Monitoring construction activities
9/29/2011	EP269-EP273	0	Site clearance survey
9/29/2011	EP269-EP273	0	Monitoring construction activities
9/29/2011	EP279-EP294	0	Site clearance survey
9/29/2011	EP274-EP278	0	Site clearance survey
9/29/2011	EP274-EP278	0	Monitoring construction activities
9/29/2011	EP263B-EP267	0	Site clearance survey
9/28/2011	Slay Property	0	Site clearance survey
9/28/2011	Slay Property	0	Monitoring construction activities
9/28/2011	EP330-EP291	0	Site clearance survey
9/28/2011	EP300-EP306	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
9/28/2011	EP300-EP306	0	Monitoring construction activities
9/28/2011	EP290-EP294	0	Site clearance survey
9/28/2011	EP290-EP294	0	Monitoring construction activities
9/28/2011	EP269-EP273	0	Site clearance survey
9/28/2011	EP269-EP273	0	Monitoring construction activities
9/28/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/28/2011	EP279-EP294	0	Site clearance survey
9/28/2011	EP279-EP294	0	Monitoring construction activities
9/28/2011	EP274-EP278	0	Site clearance survey
9/28/2011	EP274-EP278	0	Monitoring construction activities
9/28/2011	EP263B-EP267	0	Site clearance survey
9/27/2011	Slay Property	0	Site clearance survey
9/27/2011	Slay Property	0	Monitoring construction activities
9/27/2011	EP339-EP291	0	Site clearance survey
9/27/2011	EP309	0	Monitoring construction activities
9/27/2011	EP300-EP312	0	Site clearance survey
9/27/2011	EP300-EP312	0	Monitoring construction activities
9/27/2011	EP300-EP306	0	Site clearance survey
9/27/2011	EP278-1	0	Monitoring construction activities
9/27/2011	EP269-EP273	0	Site clearance survey
9/27/2011	EP269-EP273	0	Monitoring construction activities
9/27/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/27/2011	EP279-EP294	0	Site clearance survey
9/27/2011	EP279-EP294	0	Monitoring construction activities
9/27/2011	EP274-EP278	0	Site clearance survey
9/27/2011	EP274-EP278	0	Monitoring construction activities
9/27/2011	EP263B-EP267	0	Site clearance survey
9/27/2011	AER CY	0	Monitoring construction activities
9/26/2011	EP300-EP306	0	Site clearance survey
9/26/2011	EP300-EP306	0	Monitoring construction activities
9/26/2011	EP300-EP306	0	Site clearance survey
9/26/2011	EP300-EP312	0	Site clearance survey
9/26/2011	EP300-EP312	0	Monitoring construction activities
9/26/2011	EP291-EP301	0	Monitoring construction activities
9/26/2011	EP278-1, EP270-2	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
9/26/2011	EP274-EP278	0	Site clearance survey
9/26/2011	EP274-EP278	0	Monitoring construction activities
9/26/2011	EP269-EP273	0	Site clearance survey
9/26/2011	EP269-EP273	0	Monitoring construction activities
9/26/2011	EP269-EP270	0	Morning perimeter survey
9/26/2011	EP269-EP270	0	Monitoring construction activities
9/26/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/26/2011	EP279-EP294	0	Site clearance survey
9/26/2011	EP279-EP294	0	Monitoring construction activities
9/26/2011	EP269-EP271, EP256-EP263, AER & Fromm CY	0	Site clearance survey
9/26/2011	EP269-EP271, EP256-EP263, AER & Fromm CY	0	Monitoring construction activities
9/26/2011	EP263B-EP267	0	Site clearance survey
9/26/2011	CP88	0	Site clearance survey
9/26/2011	CP88	0	Monitoring construction activities
9/25/2011	EP300-EP306	0	Site clearance survey
9/25/2011	EP300-EP306	0	Monitoring construction activities
9/25/2011	EP300-EP306	0	Morning perimeter survey
9/25/2011	EP278	0	Monitoring construction activities
9/25/2011	EP274-EP278	0	Site clearance survey
9/25/2011	EP274-EP278	0	Monitoring construction activities
9/25/2011	EP271-2	0	Monitoring construction activities
9/25/2011	EP269-EP270	0	Morning perimeter survey
9/25/2011	EP269-EP270	0	Monitoring construction activities
9/25/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/25/2011	EP279-EP294	0	Site clearance survey
9/25/2011	EP279-EP294	0	Monitoring construction activities
9/25/2011	EP269-EP273	0	Site clearance survey
9/25/2011	EP269-EP273	0	Monitoring construction activities
9/25/2011	EP263B-EP267	0	Site clearance survey
9/24/2011	EP300-EP306	0	Site clearance survey
9/24/2011	EP300-EP306	0	Monitoring construction activities
9/24/2011	EP300-EP306	0	Site clearance survey
9/24/2011	EP300-EP306	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
9/24/2011	EP291/EP292 Pullsite	0	Monitoring construction activities
9/24/2011	EP274-EP278	0	Site clearance survey
9/24/2011	EP274-EP278	0	Monitoring construction activities
9/24/2011	EP274	0	Monitoring construction activities
9/24/2011	EP269-EP270	0	Site clearance survey
9/24/2011	EP269-EP270	0	Monitoring construction activities
9/24/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/24/2011	EP279-EP294	0	Site clearance survey
9/24/2011	EP279-EP294	0	Monitoring construction activities
9/24/2011	EP263B-EP267	0	Site clearance survey
9/23/2011	EP300-EP306	0	Site clearance survey
9/23/2011	EP300-EP306	0	Monitoring construction activities
9/23/2011	EP300-EP312	0	Site clearance survey
9/23/2011	EP300-EP312	0	Monitoring construction activities
9/23/2011	EP274-1	0	Monitoring construction activities
9/23/2011	EP269-EP271	0	Site clearance survey
9/23/2011	EP269-EP271	0	Monitoring construction activities
9/23/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/23/2011	EP279-EP294	0	Site clearance survey
9/23/2011	EP279-EP294	0	Monitoring construction activities
9/23/2011	EP278-1	0	Monitoring construction activities
9/23/2011	EP263B-EP267	0	Site clearance survey
9/22/2011	EP300-EP312	0	Site clearance survey
9/22/2011	EP300-EP312	0	Monitoring construction activities
9/22/2011	EP300-EP306	0	Site clearance survey
9/22/2011	EP300-EP306	0	Monitoring construction activities
9/22/2011	EP274-1	0	Monitoring construction activities
9/22/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/22/2011	EP279-EP294	0	Site clearance survey
9/22/2011	EP278-1	0	Monitoring construction activities
9/22/2011	EP274-EP278	0	Site clearance survey
9/22/2011	EP274-EP278	0	Monitoring construction activities
9/22/2011	EP263B-EP267	0	Site clearance survey
9/21/2011	EP300-EP306	0	Site clearance survey
9/21/2011	EP278-1	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
9/21/2011	EP274-1	0	Monitoring construction activities
9/21/2011	EP269-EP271, EP300-EP312	0	Site clearance survey
9/21/2011	EP269-EP271, EP300-EP312	0	Monitoring construction activities
9/21/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/21/2011	EP279-EP294	0	Site clearance survey
9/21/2011	EP279-EP294	0	Monitoring construction activities
9/21/2011	EP274-EP278	0	Site clearance survey
9/21/2011	EP274-EP278	0	Monitoring construction activities
9/21/2011	EP269-EP281	0	Site clearance survey
9/21/2011	EP269-EP281	0	Monitoring construction activities
9/21/2011	EP263B-EP267	0	Site clearance survey
9/20/2011	EP300-EP306	0	Site clearance survey
9/20/2011	EP278-1	0	Monitoring construction activities
9/20/2011	EP269-EP273	0	Site clearance survey
9/20/2011	EP269-EP273	0	Monitoring construction activities
9/20/2011	EP269-EP271	0	Site clearance survey
9/20/2011	EP269-EP271	0	Monitoring construction activities
9/20/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/20/2011	EP279-EP294	0	Site clearance survey
9/20/2011	EP279-EP294	0	Monitoring construction activities
9/20/2011	EP274-EP278	0	Site clearance survey
9/20/2011	EP274-EP278	0	Monitoring construction activities
9/20/2011	EP269-EP281	0	Site clearance survey
9/20/2011	EP269-EP281	0	Monitoring construction activities
9/20/2011	EP263B-EP267	0	Site clearance survey
9/19/2011	EP269-EP273	0	Site clearance survey
9/19/2011	EP269-EP273	0	Monitoring construction activities
9/19/2011	EP269-EP271	0	Site clearance survey
9/19/2011	EP269-EP271	0	Monitoring construction activities
9/19/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/19/2011	EP279-EP294	0	Site clearance survey
9/19/2011	EP279-EP294	0	Monitoring construction activities
9/19/2011	EP274-EP278	0	Site clearance survey
9/19/2011	EP274-EP278	0	Monitoring construction activities
9/19/2011	EP269-EP281	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
9/19/2011	EP269-EP281	0	Monitoring construction activities
9/19/2011	EP263B-EP267	0	Site clearance survey
9/18/2011	EP300-EP306	0	Site clearance survey
9/18/2011	EP300-EP312	0	Site clearance survey
9/18/2011	EP300-EP312	0	Monitoring construction activities
9/18/2011	EP269-EP273	0	Site clearance survey
9/18/2011	EP269-EP273	0	Monitoring construction activities
9/18/2011	EP256-EP263A-2, AER CY	0	Monitoring construction activities
9/18/2011	EP279-EP294	0	Site clearance survey
9/18/2011	EP279-EP294	0	Monitoring construction activities
9/18/2011	EP274-EP278	0	Site clearance survey
9/18/2011	EP274-EP278	0	Monitoring construction activities
9/18/2011	EP269-EP281	0	Site clearance survey
9/18/2011	I8 Island	9	Afternoon perimeter survey
9/17/2011	EP300-EP306	0	Site clearance survey
9/17/2011	EP300-EP312	0	Site clearance survey
9/17/2011	EP300-EP312	0	Monitoring construction activities
9/17/2011	EP269-EP273	0	Site clearance survey
9/17/2011	EP269-EP273	0	Monitoring construction activities
9/17/2011	EP274-EP278	0	Site clearance survey
9/17/2011	EP274-EP278	0	Monitoring construction activities
9/17/2011	EP269-EP281	0	Site clearance survey
9/17/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/17/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/16/2011	EP300-EP312	0	Site clearance survey
9/16/2011	EP300-EP312	0	Monitoring construction activities
9/16/2011	EP300-EP306	0	Site clearance survey
9/16/2011	EP269-EP273	0	Site clearance survey
9/16/2011	EP269-EP273	0	Monitoring construction activities
9/16/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/16/2011	EP274-EP278	0	Site clearance survey
9/16/2011	EP274-EP278	0	Monitoring construction activities
9/16/2011	EP269-EP281	0	Site clearance survey
9/16/2011	EP263B-EP267	0	Site clearance survey
9/16/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
9/16/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/15/2011	EP300-EP312	0	Site clearance survey
9/15/2011	EP300-EP312	0	Monitoring construction activities
9/15/2011	EP300-EP306	0	Site clearance survey
9/15/2011	EP300-EP306	0	Monitoring construction activities
9/15/2011	EP269-EP273	0	Site clearance survey
9/15/2011	EP269-EP273	0	Monitoring construction activities
9/15/2011	EP256-EP263A, AER	0	Monitoring construction activities
9/15/2011	EP274-EP278	0	Site clearance survey
9/15/2011	EP274-EP278	0	Monitoring construction activities
9/15/2011	EP269-EP281	0	Site clearance survey
9/15/2011	EP269-EP281	0	Monitoring construction activities
9/15/2011	EP263B-EP267	0	Site clearance survey
9/14/2011	EP310-3	0	Monitoring construction activities
9/14/2011	EP300-EP312	0	Site clearance survey
9/14/2011	EP300-EP312	0	Monitoring construction activities
9/14/2011	EP300-EP306	0	Morning perimeter survey
9/14/2011	EP274-1	0	Monitoring construction activities
9/14/2011	EP269-EP273	0	Site clearance survey
9/14/2011	EP269-EP273	0	Monitoring construction activities
9/14/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/14/2011	EP274-EP278	0	Site clearance survey
9/14/2011	EP274-EP278	0	Monitoring construction activities
9/14/2011	EP269-EP281	0	Site clearance survey
9/14/2011	EP269-EP281	0	Monitoring construction activities
9/14/2011	EP263B-EP267	0	Site clearance survey
9/13/2011	EP300-EP312	0	Site clearance survey
9/13/2011	EP300-EP312	0	Monitoring construction activities
9/13/2011	EP300-EP306	0	Morning perimeter survey
9/13/2011	EP269-EP273	0	Site clearance survey
9/13/2011	EP269-EP273	0	Monitoring construction activities
9/13/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/13/2011	EP274-EP278	0	Site clearance survey
9/13/2011	EP274-EP278	0	Monitoring construction activities
9/13/2011	EP274-EP278	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
9/13/2011	EP274	0	Monitoring construction activities
9/13/2011	EP269-EP281	0	Site clearance survey
9/13/2011	EP263B-EP267	0	Site clearance survey
9/12/2011	Mountain Springs Grade Road	15	Morning perimeter survey
9/12/2011	EP305-3, EP310	0	Monitoring construction activities
9/12/2011	EP300-EP312	0	Site clearance survey
9/12/2011	EP300-EP312	0	Monitoring construction activities
9/12/2011	EP300-EP306	0	Site clearance survey
9/12/2011	EP300-EP306	0	Monitoring construction activities
9/12/2011	EP269-EP273	0	Site clearance survey
9/12/2011	EP269-EP273	0	Monitoring construction activities
9/12/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/12/2011	EP274-EP278	0	Site clearance survey
9/12/2011	EP274-EP278	0	Monitoring construction activities
9/12/2011	EP274-EP278	0	Monitoring construction activities
9/12/2011	EP274	0	Monitoring construction activities
9/12/2011	EP269-EP281	0	Monitoring construction activities
9/12/2011	EP263B-EP267	0	Site clearance survey
9/11/2011	EP300-EP312	0	Site clearance survey
9/11/2011	EP300-EP312	0	Monitoring construction activities
9/11/2011	EP300-EP306	0	Site clearance survey
9/11/2011	EP300-EP306	0	Monitoring construction activities
9/11/2011	EP271-2	0	Monitoring construction activities
9/11/2011	EP269-EP271	0	Site clearance survey
9/11/2011	EP269-EP271	0	Monitoring construction activities
9/11/2011	EP256-EP263A-2, AER	0	Monitoring construction activities
9/11/2011	EP274-EP278	0	Site clearance survey
9/11/2011	EP274-EP278	0	Monitoring construction activities
9/11/2011	EP269-EP273	0	Site clearance survey
9/11/2011	EP269-EP273	0	Monitoring construction activities
9/11/2011	EP263B-EP267	0	Site clearance survey
9/11/2011	EP256-EP263A, AER, Fromm	0	Site clearance survey
9/11/2011	EP256-EP263A, AER, Fromm	0	Monitoring construction activities
9/10/2011	EP300-EP312	0	Site clearance survey
9/10/2011	EP300-EP312	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
9/10/2011	EP300-EP306	0	Site clearance survey
9/10/2011	EP300-EP306	0	Monitoring construction activities
9/10/2011	EP269-EP271	0	Site clearance survey
9/10/2011	EP269-EP271	0	Monitoring construction activities
9/10/2011	EP274-EP278	0	Site clearance survey
9/10/2011	EP274-EP278	0	Monitoring construction activities
9/10/2011	EP269-EP273	0	Morning perimeter survey
9/10/2011	EP269-EP273	0	Monitoring construction activities
9/10/2011	EP269-EP273	0	Evening perimeter survey
9/9/2011	EP300-EP312	0	Site clearance survey
9/9/2011	EP300-EP312	0	Monitoring construction activities
9/9/2011	EP300-EP306	0	Site clearance survey
9/9/2011	EP300-EP306	0	Monitoring construction activities
9/9/2011	EP271-2	0	Monitoring construction activities
9/9/2011	EP269-EP271	0	Site clearance survey
9/9/2011	EP269-EP271	0	Monitoring construction activities
9/9/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/9/2011	EP256-EP263A, AER and Fromm yards	0	Site clearance survey
9/9/2011	EP256-EP263A, AER and Fromm yards	0	Monitoring construction activities
9/9/2011	EP274-EP278	0	Site clearance survey
9/9/2011	EP274-EP278	0	Monitoring construction activities
9/9/2011	EP269-EP273	0	Morning perimeter survey
9/9/2011	EP269-EP273	0	Monitoring construction activities
9/9/2011	EP269-EP273	0	Evening perimeter survey
9/8/2011	EP300-EP312	0	Site clearance survey
9/8/2011	EP300-EP312	0	Monitoring construction activities
9/8/2011	EP271-2	0	Monitoring construction activities
9/8/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/8/2011	EP279-EP294	0	Site clearance survey
9/8/2011	EP279-EP294	0	Monitoring construction activities
9/8/2011	EP274-EP278	0	Site clearance survey
9/8/2011	EP274-EP278	0	Monitoring construction activities
9/8/2011	EP263B-EP267	0	Site clearance survey
9/7/2011	EP306-1	0	Monitoring construction activities
9/7/2011	EP300-EP312	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
9/7/2011	EP300-EP312	0	Monitoring construction activities
9/7/2011	EP300-EP306	0	Site clearance survey
9/7/2011	EP300-EP306	0	Monitoring construction activities
9/7/2011	EP273	0	Monitoring construction activities
9/7/2011	EP269-EP273	0	Site clearance survey
9/7/2011	EP269-EP273	0	Monitoring construction activities
9/7/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/7/2011	EP278-EP294	0	Morning perimeter survey
9/7/2011	EP278-EP294	0	Monitoring construction activities
9/7/2011	EP278-EP294	0	Evening perimeter survey
9/7/2011	EP274-EP278	0	Site clearance survey
9/7/2011	EP274-EP278	0	Monitoring construction activities
9/7/2011	EP263B-EP267	0	Site clearance survey
9/6/2011	EP300-EP312	0	Site clearance survey
9/6/2011	EP300-EP312	0	Monitoring construction activities
9/6/2011	EP273	0	Monitoring construction activities
9/6/2011	EP269-EP273	0	Site clearance survey
9/6/2011	EP269-EP273	0	Monitoring construction activities
9/6/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/6/2011	EP278-EP294	0	Morning perimeter survey
9/6/2011	EP278-EP294	0	Monitoring construction activities
9/6/2011	EP278-EP294	0	Evening perimeter survey
9/6/2011	EP274-EP278	0	Site clearance survey
9/6/2011	EP274-EP278	0	Monitoring construction activities
9/6/2011	EP263B-EP267	0	Site clearance survey
9/5/2011	EP300-EP312	0	Site clearance survey
9/5/2011	EP269-EP273	0	Site clearance survey
9/5/2011	EP269-EP273	0	Monitoring construction activities
9/5/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/5/2011	EP274-EP294	0	Site clearance survey
9/5/2011	EP263B-EP267	0	Site clearance survey
9/4/2011	EP300-EP312	0	Site clearance survey
9/4/2011	EP300-EP312	0	Monitoring construction activities
9/4/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
9/4/2011	EP269-EP281	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
9/4/2011	EP256-EP263A-2, AER yard	0	Monitoring construction activities
9/4/2011	EP256-EP263A, AER and Fromm yards	0	Site clearance survey
9/4/2011	EP256-EP263A, AER and Fromm yards	0	Monitoring construction activities
9/4/2011	EP279-EP294	0	Site clearance survey
9/4/2011	EP279-EP294	0	Monitoring construction activities
9/4/2011	EP274-EP278	0	Site clearance survey
9/4/2011	EP274-EP278	0	Monitoring construction activities
9/4/2011	EP270	0	Site clearance survey
9/4/2011	EP270	0	Monitoring construction activities
9/3/2011	EP300-EP312	0	Monitoring Construction Activities
9/3/2011	EP300-EP312	0	Site clearance survey
9/3/2011	EP300-EP306	0	Monitoring Construction Activities
9/3/2011	EP300-EP306	0	Site clearance survey
9/3/2011	EP271	0	Monitoring Construction Activities
9/3/2011	EP269-EP273	0	Monitoring Construction Activities
9/3/2011	EP269-EP273	0	Site clearance survey
9/3/2011	EP269-EP281	0	Monitoring Construction Activities
9/3/2011	EP256-EP263A, AER and Fromm Yards	0	Monitoring Construction Activities
9/3/2011	EP256-EP263A, AER and Fromm Yards	0	Site clearance survey
9/3/2011	EP278-EP294	0	Evening perimeter survey
9/3/2011	EP278-EP294	0	Monitoring Construction Activities
9/3/2011	EP278-EP294	0	Morning perimeter survey
9/3/2011	EP269-1 & EP269/EP270 Pull site	0	Monitoring Construction Activities
9/2/2011	I-8 Island	9	Evening perimeter survey 4:45pm - 5:08pm
9/2/2011	I-8 Island	12	Morning perimeter survey 8:35am
9/2/2011	EP300-EP312	0	Monitoring Construction Activities
9/2/2011	EP300-EP312	0	Site clearance survey
9/2/2011	EP272 & EP276	0	Monitoring Construction Activities
9/2/2011	EP269-EP273	0	Monitoring Construction Activities
9/2/2011	EP269-EP273	0	Site clearance survey
9/2/2011	EP256-EP263A, AER and Fromm Yards	0	Monitoring Construction Activities
9/2/2011	EP256-EP263A, AER and Fromm Yards	0	Site clearance survey
9/2/2011	EP278-EP294	0	Evening perimeter survey
9/2/2011	EP278-EP294	0	Monitoring Construction Activities
9/2/2011	EP278-EP294	0	Morning perimeter survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
9/2/2011	EP269-EP272	0	Monitoring Construction Activities
9/2/2011	EP269-EP272	0	Site clearance survey
9/2/2011	EP263B-EP267	0	Site clearance survey
9/1/2011	I-8 Island	12	Evening perimeter survey 4:45pm - 5:40pm
9/1/2011	I-8 Island	12	Morning perimeter survey 8:35am
9/1/2011	EP300-EP312	0	Monitoring Construction Activities
9/1/2011	EP300-EP312	0	Site clearance survey
9/1/2011	EP269-EP273	0	Monitoring Construction Activities
9/1/2011	EP269-EP273	0	Site clearance survey
9/1/2011	EP256-EP263A-2	0	Site clearance survey
9/1/2011	EP255	0	Monitoring Construction Activities
9/1/2011	EP300-EP306	0	Site clearance survey
9/1/2011	EP278-EP294	0	Evening perimeter survey
9/1/2011	EP278-EP294	0	Monitoring Construction Activities
9/1/2011	EP278-EP294	0	Morning perimeter survey
9/1/2011	EP269-EP272	0	Monitoring Construction Activities
9/1/2011	EP269-EP272	0	Site clearance survey
9/1/2011	EP263B-EP267	0	Site clearance survey
8/31/2011	I-8 Island	0	Site clearance survey
8/31/2011	EP308	0	Monitoring Construction Activities
8/31/2011	EP300-EP312	0	Monitoring Construction Activities
8/31/2011	EP300-EP312	0	Site clearance survey
8/31/2011	EP269-EP273	0	Monitoring Construction Activities
8/31/2011	EP269-EP273	0	Site clearance survey
8/31/2011	EP300-EP306	0	Site clearance survey
8/31/2011	EP278-EP294	0	Evening perimeter survey
8/31/2011	EP278-EP294	0	Monitoring Construction Activities
8/31/2011	EP278-EP294	0	Morning perimeter survey
8/31/2011	EP269-EP272	0	Monitoring Construction Activities
8/31/2011	EP263B-EP267	0	Site clearance survey
8/30/2011	I-8 Island	16	Evening perimeter survey 4:30pm
8/30/2011	I-8 Island	9	Morning perimeter survey 9:10am - 9:30am
8/30/2011	EP300-EP312	0	Monitoring Construction Activities
8/30/2011	EP300-EP312	0	Site clearance survey
8/30/2011	EP269-EP273	0	Monitoring Construction Activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
8/30/2011	EP269-EP273	0	Site clearance survey
8/30/2011	EP300-EP306	0	Site clearance survey
8/30/2011	EP278-EP294	0	Evening perimeter survey
8/30/2011	EP278-EP294	0	Monitoring Construction Activities
8/30/2011	EP278-EP294	0	Morning perimeter survey
8/30/2011	EP274-EP278	0	Monitoring Construction Activities
8/30/2011	EP274-EP278	0	Site clearance survey
8/30/2011	EP269-EP272	0	Monitoring Construction Activities
8/30/2011	EP269-EP272	0	Site clearance survey
8/30/2011	EP263B-EP267	0	Site clearance survey
8/29/2011	I-8 Island	4	Morning perimeter survey 8:55am
8/29/2011	I-8 Island	12	Evening perimeter survey 4:35pm to 5:00pm
8/29/2011	EP300-EP312	0	Monitoring Construction Activities
8/29/2011	EP300-EP312	0	Site clearance survey
8/29/2011	EP278-2	0	Monitoring Construction Activities
8/29/2011	EP269-EP273	0	Monitoring Construction Activities
8/29/2011	EP269-EP273	0	Site clearance survey
8/29/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/29/2011	EP300-EP306	0	Site clearance survey
8/29/2011	EP274-EP278	0	Monitoring Construction Activities
8/29/2011	EP274-EP278	0	Site clearance survey
8/29/2011	EP269-EP272	0	Monitoring Construction Activities
8/29/2011	EP269-EP272	0	Site clearance survey
8/29/2011	EP263B-EP267	0	Site clearance survey
8/28/2011	I-8 Island	15	Morning perimeter survey @9:22am
8/28/2011	EP305	0	Monitoring Construction Activities
8/28/2011	EP281	0	Monitoring Construction Activities
8/28/2011	EP273	0	Monitoring Construction Activities
8/28/2011	EP269-EP273	0	Monitoring Construction Activities
8/28/2011	EP269-EP273	0	Site clearance survey
8/28/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/28/2011	EP300-EP306	0	Morning perimeter survey
8/28/2011	EP278-EP294	0	Evening perimeter survey
8/28/2011	EP278-EP294	0	Monitoring Construction Activities
8/28/2011	EP278-EP294	0	Morning perimeter survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
8/28/2011	EP274-EP278	0	Monitoring Construction Activities
8/28/2011	EP274-EP278	0	Site clearance survey
8/28/2011	EP269-EP272	0	Monitoring Construction Activities
8/28/2011	EP269-EP272	0	Site clearance survey
8/28/2011	EP263-B, EP267	0	Site clearance survey
8/27/2011	I-8 Island	0	Site clearance survey
8/27/2011	EP305	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Site clearance survey
8/27/2011	I-8 Island	0	Morning perimeter survey
8/27/2011	EP305	0	Monitoring Construction Activities
8/27/2011	EP300-EP306, EP269-EP273	0	Site clearance survey
8/27/2011	EP300-EP306, EP269-EP273	0	Monitoring Construction Activities
8/27/2011	EP272-3	0	Monitoring Construction Activities
8/27/2011	EP261	0	Monitoring Construction Activities
8/27/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/27/2011	EP278-EP294	0	Site clearance survey
8/27/2011	EP278-EP294	0	Monitoring Construction Activities
8/27/2011	EP274-EP278	0	Site clearance survey
8/27/2011	EP274-EP278	0	Monitoring Construction Activities
8/27/2011	EP269-EP272	0	Monitoring Construction Activities
8/27/2011	EP269-EP272	0	Site clearance survey
8/27/2011	EP263B-EP267	0	Site clearance survey
8/26/2011	I-8 Island	0	Morning perimeter survey
8/26/2011	EP269-EP273	0	Monitoring Construction Activities
8/26/2011	EP269-EP273	0	Morning perimeter survey
8/26/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/26/2011	EP300-EP306	0	Monitoring Construction Activities
8/26/2011	EP278-EP294	0	Evening perimeter survey
8/26/2011	EP278-EP294	0	Monitoring Construction Activities
8/26/2011	EP278-EP294	0	Morning perimeter survey
8/26/2011	EP274-EP278	0	Monitoring Construction Activities
8/26/2011	EP274-EP278	0	Site clearance survey
8/26/2011	EP269-EP272	0	Monitoring Construction Activities
8/26/2011	EP269-EP272	0	Morning perimeter survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
8/25/2011	I-8 Island	0	Morning perimeter survey
8/25/2011	EP269-EP273	0	Monitoring Construction Activities
8/25/2011	EP269-EP273	0	Morning perimeter survey
8/25/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/25/2011	EP278-EP294	0	Evening perimeter survey
8/25/2011	EP278-EP294	0	Monitoring Construction Activities
8/25/2011	EP278-EP294	0	Morning perimeter survey
8/25/2011	EP274-EP278	0	Monitoring Construction Activities
8/25/2011	EP274-EP278	0	Site clearance survey
8/25/2011	EP270-EP272	0	Site clearance survey
8/25/2011	EP269-EP272	0	Monitoring Construction Activities
8/25/2011	EP269-EP272	0	Morning perimeter survey
8/24/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/24/2011	EP300-EP312, EP263B-EP267	0	Site clearance survey
8/24/2011	EP269-EP273	0	Monitoring Construction Activities
8/24/2011	EP269-EP273	0	Site clearance survey
8/24/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/24/2011	EP278-EP294	0	Evening perimeter survey
8/24/2011	EP278-EP294	0	Monitoring Construction Activities
8/24/2011	EP278-EP294	0	Morning perimeter survey
8/24/2011	EP274-EP278	0	Monitoring Construction Activities
8/24/2011	EP274-EP278	0	Site clearance survey
8/23/2011	I-8 Island	0	Morning perimeter survey
8/23/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities
8/23/2011	EP300-EP312, EP263B-EP267	0	Site clearance survey
8/23/2011	EP269-EP273	0	Monitoring Construction Activities
8/23/2011	EP269-EP273	0	Site clearance survey
8/23/2011	EP278-EP294	0	Evening perimeter survey
8/23/2011	EP278-EP294	0	Monitoring Construction Activities
8/23/2011	EP278-EP294	0	Morning perimeter survey
8/23/2011	EP274-EP278	0	Monitoring Construction Activities
8/23/2011	EP274-EP278	0	Morning perimeter survey
8/23/2011	EP270-EP272	0	Morning perimeter survey
8/23/2011	EP269-EP272	0	Morning perimeter survey
8/22/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
8/22/2011	EP300-EP312, EP263B-EP267	0	Morning perimeter survey
8/22/2011	EP269-EP273	0	Monitoring Construction Activities
8/22/2011	EP269-EP273	0	Monitoring Construction Activities
8/22/2011	EP269-EP273	0	Morning perimeter survey
8/22/2011	EP263B	0	Monitoring Construction Activities
8/22/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/22/2011	EP291	0	Monitoring Construction Activities
8/22/2011	EP278-EP294	0	Evening perimeter survey
8/22/2011	EP278-EP294	0	Monitoring Construction Activities
8/22/2011	EP278-EP294	0	Morning perimeter survey
8/21/2011	I-8 Island	11	Evening perimeter survey - 6:00pm
8/21/2011	EP269-EP273	0	Site clearance survey
8/21/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities
8/21/2011	EP256-EP263	0	Monitoring Construction Activities
8/21/2011	EP256-EP263	0	Site clearance survey
8/21/2011	EP279-EP294	0	Afternoon clearance survey
8/21/2011	EP274-EP278	0	Evening perimeter survey
8/21/2011	EP269-EP272	0	Evening perimeter survey
8/21/2011	EP263B-EP267	0	Site clearance survey
8/20/2011	I8 and Moutain Spring Rd	3	Morning perimeter survey 9:20am
8/20/2011	I8 and Moutain Spring Rd	4	Evening perimeter survey 6:40pm
8/20/2011	EP300-EP312	0	Monitoring construction activities
8/20/2011	EP300-EP312	0	Site clearance survey
8/20/2011	EP269-EP273	0	Monitoring construction activities
8/20/2011	EP269-EP273	0	Site clearance survey
8/20/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/20/2011	EP300-EP306	0	Morning perimeter survey
8/20/2011	EP274-EP294	0	Monitoring construction activities
8/20/2011	EP274-EP294	0	Site clearance survey
8/20/2011	EP270-EP271	0	Morning perimeter survey
8/20/2011	EP269-EP271	0	Monitoring construction activities
8/20/2011	EP263B-EP267	0	Site clearance survey
8/19/2011	Radiator Water Tower 17	7	Site clearance survey
8/19/2011	EP298, EP300 & EP307	0	Site clearance survey
8/19/2011	EP296, EP300	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
8/19/2011	EP296, EP300	0	Site clearance survey
8/19/2011	EP269-EP273	0	Monitoring construction activities
8/19/2011	EP269-EP273	0	Site clearance survey
8/19/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/19/2011	EP291-EP293	0	Monitoring construction activities
8/19/2011	EP279-EP294	0	Monitoring construction activities
8/19/2011	EP274-EP278	0	Monitoring construction activities
8/19/2011	EP274-EP278	0	Site clearance survey
8/19/2011	EP263B-EP267	0	Site clearance survey
8/18/2011	EP269-EP273	0	Monitoring construction activities
8/18/2011	EP269-EP273	0	Site clearance survey
8/18/2011	EP349, EP293	0	Monitoring construction activities
8/18/2011	EP279-EP312	0	Monitoring construction activities
8/18/2011	EP274-EP278	0	Monitoring construction activities
8/18/2011	EP274-EP278	0	Site clearance survey
8/18/2011	EP263B-EP267	0	Site clearance survey
8/17/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/17/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/17/2011	EP269-EP273	0	Monitoring construction activities
8/17/2011	EP269-EP273	0	Site clearance survey
8/17/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/17/2011	EP279-EP294	0	Monitoring construction activities
8/17/2011	EP279-EP294	0	Site clearance survey
8/17/2011	EP274-EP278	0	Monitoring construction activities
8/17/2011	EP274-EP278	0	Site clearance survey
8/17/2011	EP263B-EP267	0	Site clearance survey
8/16/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/16/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/16/2011	EP269-EP273	0	Monitoring construction activities
8/16/2011	EP269-EP273	0	Site clearance survey
8/16/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/16/2011	EP279-EP294	0	Monitoring construction activities
8/16/2011	EP279-EP294	0	Site clearance survey
8/16/2011	EP274-EP278	0	Monitoring construction activities
8/16/2011	EP274-EP278	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
8/16/2011	EP265	0	Monitoring construction activities
8/16/2011	EP263B-EP267	0	Site clearance survey
8/15/2011	Fromm and AER Construction Yard	0	Monitoring construction activities
8/15/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/15/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/15/2011	EP294	0	Monitoring construction activities
8/15/2011	EP269-EP273	0	Site clearance survey
8/15/2011	EP269-EP273	0	Monitoring construction activities
8/15/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/15/2011	EP279-EP294	0	Monitoring construction activities
8/15/2011	EP279-EP294	0	Site clearance survey
8/15/2011	EP274-EP278	0	Monitoring construction activities
8/15/2011	EP274-EP278	0	Site clearance survey
8/15/2011	EP263B-EP267	0	Site clearance survey
8/14/2011	EP274-EP278	0	Monitoring construction activities
8/14/2011	EP263B-EP267	0	Site clearance survey
8/14/2011	EP274-EP278	0	Evening perimeter survey
8/14/2011	EP279-294	0	Monitoring construction activities
8/14/2011	EP269-EP273	0	Evening perimeter survey
8/14/2011	EP300-EP312	0	Site clearance survey
8/14/2011	EP300-EP312	0	Monitoring construction activities
8/13/2011	Fromm Construction Yard	0	Site clearance survey
8/13/2011	I-8 Island	19	Morning perimeter survey at 9:54am - 10:45am
8/13/2011	I-8 Island	6	Evening perimeter survey at 4:35pm
8/13/2011	EP263B-EP267	0	Site clearance survey
8/13/2011	EP269-EP271	0	Monitoring construction activities
8/13/2011	EP270-EP271	0	Monitoring construction activities
8/13/2011	EP274-EP278	0	Monitoring construction activities
8/13/2011	EP279-294	0	Monitoring construction activities
8/13/2011	EP300-EP306	0	Monitoring construction activities
8/13/2011	EP259B	0	Site clearance survey
8/13/2011	EP269-EP273	0	Monitoring construction activities
8/13/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/13/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/12/2011	I-8 Island	26	Evening perimeter survey at 4:25pm - 5:45

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
8/12/2011	EP263B-EP267	0	Site clearance survey
8/12/2011	EP269-EP271	0	Monitoring construction activities
8/12/2011	EP270-EP271	0	Monitoring construction activities
8/12/2011	EP279-294	0	Monitoring construction activities
8/12/2011	EP300-EP306	0	Monitoring construction activities
8/12/2011	EP300-EP312	0	Monitoring construction activities
8/12/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/12/2011	EP259B	0	Site clearance survey
8/12/2011	EP269-EP273	0	Monitoring construction activities
8/12/2011	EP274-EP278, EP290-EP294	0	Site clearance survey
8/12/2011	EP274-EP278, EP290-EP294	0	Monitoring construction activities
8/12/2011	EP294	0	Monitoring construction activities
8/11/2011	I-8 Island	12	Morning perimeter survey at 10:50am
8/11/2011	I-8 Island	28	Evening perimeter survey at 6:19pm
8/11/2011	EP263B-EP267	0	Site clearance survey
8/11/2011	EP269-EP271	0	Monitoring construction activities
8/11/2011	EP270-EP271	0	Monitoring construction activities
8/11/2011	EP279-294	0	Monitoring construction activities
8/11/2011	EP300-EP306	0	Monitoring construction activities
8/11/2011	EP300-EP312	0	Monitoring construction activities
8/11/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/11/2011	EP259B	0	Site clearance survey
8/11/2011	EP269-EP273	0	Monitoring construction activities
8/11/2011	EP274-EP278	0	Site clearance survey
8/11/2011	EP274-EP278	0	Monitoring construction activities
8/11/2011	EP292-EP356	0	Monitoring construction activities
8/11/2011	EP294	0	Monitoring construction activities
8/10/2011	I-8 Island	16	Evening perimeter survey at 4:55pm - 5:08
8/10/2011	EP263B-EP267	0	Site clearance survey
8/10/2011	EP269-EP271	0	Monitoring construction activities
8/10/2011	EP270-EP271	0	Monitoring construction activities
8/10/2011	EP273	0	Monitoring construction activities
8/10/2011	EP300-EP306	0	Monitoring construction activities
8/10/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/10/2011	EP259B	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
8/10/2011	EP269-EP273	0	Monitoring construction activities
8/10/2011	EP294	0	Monitoring construction activities
8/10/2011	EP300-EP312	0	Morning perimeter survey
8/10/2011	EP300-EP312	0	Monitoring construction activities
8/10/2011	EP300-EP312	0	Evening perimeter survey
8/10/2011	EP227, EP232, EP258, EP314, EP317, EP348, EP349	0	Site clearance survey
8/9/2011	I-8 Island	3	Morning perimeter survey at 10:30am
8/9/2011	I-8 Island	18	Evening perimeter survey at 4:30pm - 5:06pm
8/9/2011	EP263B-EP267	0	Site clearance survey
8/9/2011	EP269-EP271	0	Monitoring construction activities
8/9/2011	EP270-EP271	0	Monitoring construction activities
8/9/2011	EP270-EP273	0	Monitoring construction activities
8/9/2011	EP274-EP278	0	Monitoring construction activities
8/9/2011	EP279-294	0	Monitoring construction activities
8/9/2011	EP300-EP306	0	Monitoring construction activities
8/9/2011	EP305	0	Monitoring construction activities
8/9/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/9/2011	EP269-EP273	0	Site clearance survey
8/9/2011	EP294	0	Monitoring construction activities
8/9/2011	EP300-EP312	0	Morning perimeter survey
8/9/2011	EP300-EP312	0	Monitoring construction activities
8/9/2011	EP300-EP312	0	Evening perimeter survey
8/8/2011	I-8 Island	4	Morning perimeter survey at 9:45am - 9:55am
8/8/2011	I-8 Island	22	Evening perimeter survey at 4:24pm - 5:14pm
8/8/2011	EP279-294	3	Monitoring construction activities
8/8/2011	EP263B-EP267	0	Site clearance survey
8/8/2011	EP269-EP271	0	Monitoring construction activities
8/8/2011	EP270-EP271	0	Monitoring construction activities
8/8/2011	EP273	0	Monitoring construction activities
8/8/2011	EP274-EP278	0	Monitoring construction activities
8/8/2011	EP300-EP306	0	Monitoring construction activities
8/8/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/8/2011	EP269-EP273	0	Site clearance survey
8/8/2011	EP294	0	Monitoring construction activities
8/8/2011	EP300-EP312	0	Morning perimeter survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
8/8/2011	EP300-EP312	0	Monitoring construction activities
8/8/2011	EP300-EP312	0	Evening perimeter survey
8/8/2011	EP301-EP324, EP259-3, EP259B	0	Monitoring construction activities
8/8/2011	EP290-EP300	0	Site clearance survey
8/7/2011	I-8 Island	27	Evening perimeter survey at 6:00pm - 6:45
8/7/2011	EP263B-EP267	0	Site clearance survey
8/7/2011	EP270-EP271	0	Monitoring construction activities
8/7/2011	EP274-EP278	0	Monitoring construction activities
8/7/2011	EP279-294	0	Monitoring construction activities
8/7/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/7/2011	EP269-EP273	0	Evening perimeter survey
8/7/2011	EP300-EP312	0	Evening perimeter survey
8/6/2011	EP278 & EP277	0	Monitoring construction activities
8/6/2011	I-8 Island	12	Afternoon perimeter survey at 1:20pm
8/6/2011	EP263B-EP267	0	Site clearance survey
8/6/2011	EP269-EP271	0	Monitoring construction activities
8/6/2011	EP270-EP271	0	Monitoring construction activities
8/6/2011	EP274-EP278	0	Monitoring construction activities
8/6/2011	EP279-294	0	Monitoring construction activities
8/6/2011	EP300-EP306	0	Monitoring construction activities
8/6/2011	EP262, EP266, EP267	0	Site clearance survey
8/6/2011	EP269-EP273	0	Monitoring construction activities
8/6/2011	EP307-EP315	0	Morning perimeter survey
8/6/2011	EP307-EP316	0	Monitoring construction activities
8/6/2011	EP307-EP317	0	Evening perimeter survey
8/5/2011	EP263B-EP267	0	Site clearance survey
8/5/2011	EP271, EP273, EP274, EP277 and EP278	0	Monitoring construction activities
8/5/2011	EP274-EP278	0	Monitoring construction activities
8/5/2011	EP279-294	0	Monitoring construction activities
8/5/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/5/2011	EP269-EP273	0	Monitoring construction activities
8/5/2011	EP294	0	Monitoring construction activities
8/5/2011	EP307-EP312	0	Morning perimeter survey
8/5/2011	EP307-EP313	0	Monitoring construction activities
8/5/2011	EP307-EP314	0	Evening perimeter survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
8/4/2011	I-8 Island	23	Evening perimeter survey at 4:00pm - 4:33pm
8/4/2011	EP263B-EP267	0	Site clearance survey
8/4/2011	EP269-EP271	0	Monitoring construction activities
8/4/2011	EP270-EP271	0	Monitoring construction activities
8/4/2011	EP274-EP278	0	Monitoring construction activities
8/4/2011	EP279-294	0	Monitoring construction activities
8/4/2011	EP300-EP306	0	Monitoring construction activities
8/4/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/4/2011	EP269-EP273	0	Monitoring construction activities
8/4/2011	EP294	0	Monitoring construction activities
8/3/2011	I-8 Island	17	Evening perimeter survey at 5:45pm - 6:05pm
8/3/2011	EP256-EP263	0	Monitoring construction activities
8/3/2011	EP263B-EP267	0	Site clearance survey
8/3/2011	EP269-EP271	0	Monitoring construction activities
8/3/2011	EP270-EP271	0	Monitoring construction activities
8/3/2011	EP274-EP278	0	Monitoring construction activities
8/3/2011	EP279-294	0	Monitoring construction activities
8/3/2011	EP290-EP312	0	Monitoring construction activities
8/3/2011	EP300-EP306	0	Monitoring construction activities
8/3/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/3/2011	EP269/EP270 Pullsite	0	Monitoring construction activities
8/3/2011	EP269-EP273	0	Monitoring construction activities
8/3/2011	EP271	0	Monitoring construction activities
8/3/2011	EP294	0	Monitoring construction activities
8/3/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/3/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
8/3/2011	I-8 Island	0	Monitoring construction activities
8/2/2011	I-8 Island	12	Morning perimeter survey at 9:50am
8/2/2011	I-8 Island	23	Evening perimeter survey at 4:30pm
8/2/2011	EP263B-EP267	0	Site clearance survey
8/2/2011	EP269-EP271	0	Monitoring construction activities
8/2/2011	EP270-EP271	0	Monitoring construction activities
8/2/2011	EP279-294	0	Monitoring construction activities
8/2/2011	EP300-EP306	0	Monitoring construction activities
8/2/2011	EP269/EP270 Pullsite	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
8/2/2011	EP269-EP273	0	Monitoring construction activities
8/2/2011	EP271 and EP273	0	Monitoring construction activities
8/2/2011	EP273	0	Monitoring construction activities
8/2/2011	EP274-EP278	0	Monitoring construction activities
8/2/2011	EP294	0	Monitoring construction activities
8/1/2011	I-8 Island	19	Morning perimeter survey at 10:00 - 10:20am
8/1/2011	I-8 Island	1	Evening perimeter survey at 4:30pm
8/1/2011	EP263B-EP267	0	Site clearance survey
8/1/2011	EP269-EP271	0	Monitoring construction activities
8/1/2011	EP270-EP271	0	Monitoring construction activities
8/1/2011	EP274-EP278	0	Monitoring construction activities
8/1/2011	EP279-294	0	Monitoring construction activities
8/1/2011	EP290-EP312	0	Monitoring construction activities
8/1/2011	EP300-EP306	0	Monitoring construction activities
8/1/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
8/1/2011	EP269	0	Monitoring construction activities
8/1/2011	EP269-EP273	0	Monitoring construction activities
8/1/2011	EP272	0	Monitoring construction activities
8/1/2011	EP291 & EP301-EP304	0	Monitoring construction activities
8/1/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
8/1/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
7/31/2011	I-8 Island	24	Evening perimeter survey at 5:55pm
7/31/2011	EP263B-EP267	0	Site clearance survey
7/31/2011	EP270-EP271	0	Monitoring construction activities
7/31/2011	EP274-EP278	0	Monitoring construction activities
7/31/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/31/2011	EP269-EP273	0	Evening perimeter survey
7/31/2011	EP279-EP294	0	Site clearance survey
7/31/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
7/30/2011	EP271	1	Morning perimeter survey at 7:00am
7/30/2011	EP256-EP263A-2, AER Yard	6	Monitoring during construction activities. These sheep were outside of all work areas and associated buffers and did not impact work.
7/30/2011	I-8 Island	11	Morning perimeter survey at 10:15am - 11:07
7/30/2011	I-8 Island	7	Evening perimeter survey at 4:12pm
7/30/2011	EP263B-EP267	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
7/30/2011	EP269	0	Site clearance survey
7/30/2011	EP269-EP272	0	Monitoring construction activities
7/30/2011	EP270-EP271	0	Monitoring construction activities
7/30/2011	EP274-EP278	0	Monitoring construction activities
7/30/2011	EP279-294	0	Monitoring construction activities
7/30/2011	EP300-EP306	0	Monitoring construction activities
7/30/2011	EP269	0	Monitoring construction activities
7/30/2011	EP269-EP273	0	Site clearance survey
7/30/2011	EP270-EP271	0	Monitoring construction activities
7/30/2011	EP300-EP312, EP290-EP294	0	Site clearance survey
7/30/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities
7/29/2011	I-8 Island	14	Morning perimeter survey at 8:55am
7/29/2011	I-8 Island	2	Evening perimeter survey at 4:00pm
7/29/2011	EP263B-EP267	0	Site clearance survey
7/29/2011	EP269	0	Site clearance survey
7/29/2011	EP269-EP272	0	Monitoring construction activities
7/29/2011	EP270-EP271	0	Monitoring construction activities
7/29/2011	EP274-EP278	0	Monitoring construction activities
7/29/2011	EP279-294	0	Monitoring construction activities
7/29/2011	EP300-EP306	0	Monitoring construction activities
7/29/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/29/2011	EP269	0	Monitoring construction activities
7/29/2011	EP269-EP273	0	Site clearance survey
7/29/2011	EP270	0	Monitoring construction activities
7/29/2011	EP300-EP312	0	Morning perimeter survey
7/29/2011	EP300-EP312	0	Monitoring construction activities
7/29/2011	EP300-EP312	0	Evening perimeter survey
7/29/2011	EP303	0	Monitoring construction activities
7/28/2011	EP269	4	Monitoring during construction activities
7/28/2011	I-8 Island	11	Morning perimeter survey at 9:19am
7/28/2011	I-8 Island	8	Evening perimeter survey at 4:00pm - 4:50pm
7/28/2011	EP279-294	0	Monitoring construction activities
7/28/2011	EP263B-EP267	0	Site clearance survey
7/28/2011	EP269	0	Site clearance survey
7/28/2011	EP270-EP271	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
7/28/2011	EP274-EP278	0	Monitoring construction activities
7/28/2011	EP300-EP306	0	Monitoring construction activities
7/28/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/28/2011	EP269	0	Monitoring construction activities
7/28/2011	EP270	0	Monitoring construction activities
7/28/2011	EP300-EP312	0	Morning perimeter survey
7/28/2011	EP300-EP312	0	Monitoring construction activities
7/28/2011	EP300-EP312	0	Evening perimeter survey
7/28/2011	AER CY	0	Site clearance survey
7/27/2011	I-8 Island	13	Evening perimeter survey at 6:30pm - 7:00pm
7/27/2011	EP279-294	0	Monitoring construction activities
7/27/2011	EP263B-EP267	0	Site clearance survey
7/27/2011	EP268 - EP263	0	Monitoring construction activities
7/27/2011	EP269	0	Site clearance survey
7/27/2011	EP270-EP271	0	Monitoring construction activities
7/27/2011	EP274-EP278	0	Monitoring construction activities
7/27/2011	EP300-EP306	0	Monitoring construction activities
7/27/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/27/2011	EP269-EP273	0	Morning perimeter survey
7/27/2011	EP269-EP273	0	Evening perimeter survey
7/27/2011	EP300-EP312	0	Morning perimeter survey
7/27/2011	EP300-EP312	0	Monitoring construction activities
7/27/2011	EP300-EP312	0	Evening perimeter survey
7/26/2011	Devils Canyon Bridge1, Hwy 8	1	Monitoring during construction activities
7/26/2011	I-8 Island	24	Morning perimeter survey at 9:46am - 10:45am
7/26/2011	I-8 Island	7	Evening perimeter survey at 6:17pm - 6:50pm
7/26/2011	EP263B-EP267	0	Site clearance survey
7/26/2011	EP269	0	Site clearance survey
7/26/2011	EP270	0	Monitoring construction activities
7/26/2011	EP274-EP278	0	Monitoring construction activities
7/26/2011	EP279-294	0	Monitoring construction activities
7/26/2011	EP300-EP306	0	Monitoring construction activities
7/26/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/26/2011	EP269-EP273	0	Morning perimeter survey
7/26/2011	EP269-EP273	0	Evening perimeter survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
7/26/2011	EP300-EP312	0	Monitoring construction activities
7/26/2011	EP300-EP312	0	Morning perimeter survey
7/26/2011	EP300-EP312	0	Monitoring construction activities
7/26/2011	EP300-EP312	0	Evening perimeter survey
7/25/2011	I-8 Island	21	Morning perimeter survey at 8:47am
7/25/2011	I-8 Island	20	Evening perimeter survey at 6:37am
7/25/2011	EP263B-EP267	0	Site clearance survey
7/25/2011	EP269	0	Site clearance survey
7/25/2011	EP270	0	Monitoring construction activities
7/25/2011	EP274-EP278	0	Monitoring construction activities
7/25/2011	EP279-294	0	Monitoring construction activities
7/25/2011	EP300-EP306	0	Monitoring construction activities
7/25/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/25/2011	EP269-EP273	0	Morning perimeter survey
7/25/2011	EP269-EP273	0	Evening perimeter survey
7/25/2011	EP300 & EP302	0	Monitoring construction activities
7/25/2011	EP300-EP312	0	Morning perimeter survey
7/25/2011	EP300-EP312	0	Monitoring construction activities
7/25/2011	EP300-EP312	0	Evening perimeter survey
7/25/2011	EP276	0	Monitoring construction activities
7/24/2011	I-8 Island	13	Evening perimeter survey at 6:25pm
7/24/2011	EP263B-EP267	0	Site clearance survey
7/24/2011	EP269	0	Site clearance survey
7/24/2011	EP270	0	Monitoring construction activities
7/24/2011	EP279-294	0	Monitoring construction activities
7/24/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/24/2011	EP269-EP273	0	Evening perimeter survey
7/24/2011	EP274-EP278	0	Evening perimeter survey
7/24/2011	EP300-EP312	0	Evening perimeter survey
7/23/2011	EP263B-EP267	0	Site clearance survey
7/23/2011	EP269	0	Site clearance survey
7/23/2011	EP270	0	Monitoring construction activities
7/23/2011	EP279-294	0	Monitoring construction activities
7/23/2011	EP300-EP312	0	Monitoring construction activities
7/23/2011	EP300-EP312	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
7/23/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/23/2011	EP269-EP276	0	Morning perimeter survey
7/23/2011	EP274-EP278	0	Morning perimeter survey
7/23/2011	EP274-EP278	0	Evening perimeter survey
7/23/2011	I-8 Island	0	Morning perimeter survey
7/22/2011	I-8 Island	18	Evening perimeter survey at 6:35pm
7/22/2011	EP263B-EP267	0	Site clearance survey
7/22/2011	EP269	0	Site clearance survey
7/22/2011	EP269-EP270	0	Monitoring construction activities
7/22/2011	EP270	0	Monitoring construction activities
7/22/2011	EP300-EP312	0	Monitoring construction activities
7/22/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/22/2011	EP269-EP273	0	Morning perimeter survey
7/22/2011	EP269-EP273	0	Evening perimeter survey
7/22/2011	EP274-EP278	0	Site clearance survey
7/22/2011	EP274-EP278	0	Monitoring construction activities
7/21/2011	I-8 Island	18	Evening perimeter survey at 6:35pm
7/21/2011	EP263B-EP267	0	Site clearance survey
7/21/2011	EP269	0	Site clearance survey
7/21/2011	EP269-EP270	0	Monitoring construction activities
7/21/2011	EP270	0	Monitoring construction activities
7/21/2011	EP279-294	0	Monitoring construction activities
7/21/2011	EP300-EP312	0	Monitoring construction activities
7/21/2011	EP300-EP306	0	Site clearance survey
7/21/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/21/2011	EP269-EP273	0	Morning perimeter survey
7/21/2011	EP269-EP273	0	Evening perimeter survey
7/21/2011	EP274-EP278	0	Morning perimeter survey
7/21/2011	EP274-EP278	0	Evening perimeter survey
7/20/2011	I-8 Island	4	Evening perimeter survey at 6:50pm
7/20/2011	EP269-EP273	0	Morning perimeter survey
7/20/2011	EP269-EP273	0	Evening perimeter survey
7/20/2011	EP263B-EP267	0	Site clearance survey
7/20/2011	EP269	0	Site clearance survey
7/20/2011	EP270	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
7/20/2011	EP279-294	0	Monitoring construction activities
7/20/2011	EP300-EP312	0	Monitoring construction activities
7/20/2011	EP300-EP306	0	Site clearance survey
7/20/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/20/2011	EP274-EP278	0	Morning perimeter survey
7/20/2011	EP274-EP278	0	Evening perimeter survey
7/19/2011	I-8 Island	10	Morning perimeter survey at 9:10am
7/19/2011	I-8 Island	17	Evening perimeter survey at 4:00pm - 6:40pm
7/19/2011	EP269-EP273	0	Morning perimeter survey
7/19/2011	EP269-EP273	0	Evening perimeter survey
7/19/2011	EP269	0	Site clearance survey
7/19/2011	EP270	0	Monitoring construction activities
7/19/2011	EP279-294	0	Monitoring construction activities
7/19/2011	EP300-EP312	0	Monitoring construction activities
7/19/2011	EP300-EP306	0	Site clearance survey
7/19/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/19/2011	EP274-EP278	0	Morning perimeter survey
7/19/2011	EP274-EP278	0	Evening perimeter survey
7/19/2011	EP263B-EP267	0	Site clearance survey
7/18/2011	I-8 Island	21	Evening perimeter survey at 7:10pm
7/18/2011	EP263B-EP267	0	Site clearance survey
7/18/2011	EP269	0	Site clearance survey
7/18/2011	EP270	0	Monitoring construction activities
7/18/2011	EP279-294	0	Monitoring construction activities
7/18/2011	EP300-EP312	0	Monitoring construction activities
7/18/2011	EP300-EP306	0	Site clearance survey
7/18/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/18/2011	EP274-EP278	0	Morning perimeter survey
7/18/2011	EP274-EP278	0	Evening perimeter survey
7/18/2011	EP269-EP273	0	Site clearance survey
7/17/2011	I-8 Island	17	Evening perimeter survey at 5:55pm - 6:25
7/17/2011	EP263B-EP267	0	Site clearance survey
7/17/2011	EP269	0	Site clearance survey
7/17/2011	EP270	0	Monitoring construction activities
7/17/2011	EP300-EP312	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
7/17/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/17/2011	EP274-EP278	0	Evening perimeter survey
7/17/2011	EP279-EP294	0	Site clearance survey
7/17/2011	EP269-EP273	0	Site clearance survey
7/16/2011	I-8 Island	1	Morning perimeter survey at 8:35am
7/16/2011	EP263B-EP267	0	Site clearance survey
7/16/2011	EP269	0	Site clearance survey
7/16/2011	EP270	0	Monitoring construction activities
7/16/2011	EP300-EP306	0	Monitoring construction activities
7/16/2011	EP300-EP312	0	Monitoring construction activities
7/16/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/16/2011	EP274-EP278	0	Morning perimeter survey
7/16/2011	EP279-EP294	0	Morning perimeter survey
7/16/2011	EP279-EP294	0	Site clearance survey
7/16/2011	EP279-EP294	0	Monitoring construction activities
7/16/2011	EP269-EP273	0	Site clearance survey
7/15/2011	EP273-1	1	Evening perimeter survey at 4:30pm
7/15/2011	I-8 Island	12	Evening perimeter survey at 6:35pm - 7:00pm
7/15/2011	EP263B-EP267	0	Site clearance survey
7/15/2011	EP269	0	Site clearance survey
7/15/2011	EP270	0	Monitoring construction activities
7/15/2011	EP279-294	0	Monitoring construction activities
7/15/2011	EP300-EP306	0	Monitoring construction activities
7/15/2011	EP300-EP312	0	Monitoring construction activities
7/15/2011	EP256-EP263A-2, AER Yard	0	Site clearance survey
7/15/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/15/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/15/2011	EP269-EP273	0	Site clearance survey
7/15/2011	EP274-EP278	0	Morning perimeter survey
7/15/2011	EP274-EP278	0	Evening perimeter survey
7/14/2011	I-8 Island	3	Evening perimeter survey at 4:10pm
7/14/2011	I-8 Island		7:15am - 9:30am PBHS were at above point
7/14/2011	EP263B-EP267	0	Site clearance survey
7/14/2011	EP269	0	Site clearance survey
7/14/2011	EP270	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
7/14/2011	EP279-294	0	Monitoring construction activities
7/14/2011	EP300-EP306	0	Monitoring construction activities
7/14/2011	EP300-EP312	0	Monitoring construction activities
7/14/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/14/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/14/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/14/2011	EP274-EP278	0	Morning perimeter survey
7/14/2011	EP274-EP278	0	Evening perimeter survey
7/14/2011	EP269-EP273	0	Site clearance survey
7/13/2011	I-8 Island	21	Evening perimeter survey at 4:40pm
7/13/2011	EP263B-EP267	0	Site clearance survey
7/13/2011	EP269	0	Site clearance survey
7/13/2011	EP270	0	Monitoring construction activities
7/13/2011	EP279-294	0	Monitoring construction activities
7/13/2011	EP300-EP306	0	Monitoring construction activities
7/13/2011	EP300-EP312	0	Monitoring construction activities
7/13/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/13/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/13/2011	EP269-EP273	0	Site clearance survey
7/12/2011	EP256-EP263A-2, AER Yard	15	Monitoring during construction activities @ 7:40am - 11:00am
7/12/2011	I-8 Island	17	Evening perimeter survey at 4:00pm
7/12/2011	EP263B-EP267	0	Site clearance survey
7/12/2011	EP269	0	Site clearance survey
7/12/2011	EP270	0	Monitoring construction activities
7/12/2011	EP279-294	0	Monitoring construction activities
7/12/2011	EP300-EP306	0	Monitoring construction activities
7/12/2011	EP300-EP312	0	Monitoring construction activities
7/12/2011	EP274-EP278	0	Morning perimeter survey
7/12/2011	EP274-EP278	0	Evening perimeter survey
7/12/2011	EP269-EP273	0	Site clearance survey
7/11/2011	I-8 Island	29	Evening perimeter survey at 4:40pm
7/11/2011	EP263B-EP267	0	Site clearance survey
7/11/2011	EP269	0	Site clearance survey
7/11/2011	EP270	0	Monitoring construction activities
7/11/2011	EP279-294	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
7/11/2011	EP300-EP306	0	Monitoring construction activities
7/11/2011	EP300-EP312	0	Monitoring construction activities
7/11/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/11/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/11/2011	EP269-EP273	0	Site clearance survey
7/11/2011	EP274-EP278	0	Morning perimeter survey
7/11/2011	EP274-EP278	0	Evening perimeter survey
7/10/2011	I-8 Island	8	Perimeter survey
7/10/2011	I-8 Island	20	Monitoring construction activities
7/10/2011	EP269	0	Site clearance survey
7/10/2011	EP270	0	Monitoring construction activities
7/10/2011	EP279-294	0	Monitoring construction activities
7/10/2011	EP300-EP312	0	Monitoring construction activities
7/10/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/10/2011	EP274-EP278, EP265-EP267	0	Site clearance survey
7/9/2011	EP263A-2	11	Evening perimeter survey
7/9/2011	EP263B-EP267	0	Site clearance survey
7/9/2011	EP269-EP274	0	Monitoring construction activities
7/9/2011	EP279-294	0	Monitoring construction activities
7/9/2011	EP300-EP307	0	Monitoring construction activities
7/9/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/9/2011	EP269-EP273	0	Site clearance survey
7/9/2011	EP274-EP278	0	Morning perimeter survey
7/9/2011	EP310	0	Monitoring construction activities
7/8/2011	EP263B-EP267	0	Site clearance survey
7/8/2011	EP300-EP312	0	Monitoring construction activities
7/8/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/8/2011	EP269-EP273	0	Site clearance survey
7/8/2011	EP274-EP278	0	Morning perimeter survey
7/8/2011	EP274-EP278	0	Evening perimeter survey
7/8/2011	EP303	0	Monitoring construction activities
7/8/2011	EP279-EP294	0	Monitoring construction activities
7/7/2011	I-8 Island	8	Evening perimeter survey at 7:00pm
7/7/2011	EP263B-EP267	0	Site clearance survey
7/7/2011	EP269-EP273	0	Monitoring construction activities

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
7/7/2011	EP300-EP312	0	Monitoring construction activities
7/7/2011	EP300-EP307	0	Monitoring construction activities
7/7/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/7/2011	EP269-EP273	0	Site clearance survey
7/7/2011	EP274-EP278	0	Morning perimeter survey
7/7/2011	EP274-EP278	0	Evening perimeter survey
7/7/2011	EP303 & EP304	0	Monitoring construction activities
7/7/2011	EP306-EP312	0	Site clearance survey
7/6/2011	EP263A-2	2	Evening perimeter survey
7/6/2011	EP263B-EP267	0	Site clearance survey
7/6/2011	EP269-EP272	0	Monitoring construction activities
7/6/2011	EP300-EP312	0	Monitoring construction activities
7/6/2011	EP300-EP307	0	Monitoring construction activities
7/6/2011	EP303	0	Site clearance survey
7/6/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/6/2011	EP274-EP278	0	Morning perimeter survey
7/6/2011	EP274-EP278	0	Evening perimeter survey
7/6/2011	EP305 to EP304	0	Monitoring construction activities
7/6/2011	I-8 Island	0	Monitoring construction activities
7/6/2011	EP269-EP273	0	Site clearance survey
7/5/2011	EP270	14	Morning perimeter survey at 6:30am - 10:00am
7/5/2011	EP270	9	Evening perimeter survey at 5:00pm
7/5/2011	I-8 Island	7	Evening perimeter survey at 6:20pm
7/5/2011	EP269-EP273	0	Morning perimeter survey
7/5/2011	EP269-EP273	0	Evening perimeter survey
7/5/2011	EP263B-EP267	0	Site clearance survey
7/5/2011	EP269-EP271	0	Monitoring construction activities
7/5/2011	EP300-EP312	0	Monitoring construction activities
7/5/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/5/2011	EP274-EP278	0	Morning perimeter survey
7/5/2011	EP274-EP278	0	Evening perimeter survey
7/5/2011	EP307 to EP305	0	Monitoring construction activities
7/5/2011	I-8 Island	0	Site clearance survey
7/4/2011	EP270	9	Perimeter survey
7/4/2011	EP263B-EP267	0	Site clearance survey

**PBS Monitoring Report - Week Ending 12/10/2011**

Date	Location	Number observed	Comments
7/4/2011	EP300-EP312	0	Monitoring construction activities
7/4/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/4/2011	EP269-EP273	0	Site clearance survey
7/4/2011	EP274-EP278	0	Evening perimeter survey
7/4/2011	I-8 Island	0	Site clearance survey
7/2/2011	EP263B-EP267	0	Site clearance survey
7/2/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/2/2011	EP269-EP273	0	Site clearance survey
7/2/2011	EP274-EP278	0	Morning perimeter survey
7/2/2011	I-8 Island	0	Site clearance survey
7/1/2011	EP263B-EP267	0	Site clearance survey
7/1/2011	EP300-EP312	0	Monitoring construction activities
7/1/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities
7/1/2011	EP269-EP273	0	Site clearance survey
7/1/2011	EP274-EP278	0	Morning perimeter survey
7/1/2011	EP274-EP278	0	Evening perimeter survey
7/1/2011	I-8 Island	0	Site clearance survey
6/30/2011	EP300-EP312	0	Monitoring construction activities
6/29/2011	EP310-EP312	0	Monitoring construction activities
4/15/2011	EP210, EP211, EP213-EP215, EP217-EP219	0	Monitoring construction activities
3/26/2011	EP105	0	Site clearance survey

Raven Control Monitoring Report - Week Ending 12/10/2011							
Date	Location	Number of Ravens observed	Raven Activity				
			Nesting	Flying	Perching	Roosting	Scavaging
12/10/2011	EP306 & EP306/EP307 Pullsite	3		3			
12/9/2011	IV Substation	1		1			
12/9/2011	EP308 & EP306/EP307 Pullsite	2		2			
12/9/2011	EP291 & EP291/EP292 Pullsite	2		2			
12/8/2011	S2 Yard	3					3
12/8/2011	IV Substation	1		1			
12/8/2011	EP301	2		2			
12/8/2011	EP300-EP309	2		2			
12/8/2011	EP291/EP292 Pullsite	2	2				
12/8/2011	EP281	2		2			
12/7/2011	IV Substation	1		1			
12/7/2011	EP301	1			1		
12/7/2011	EP291/EP292 Pullsite	1			1		
12/7/2011	EP281	7		4	2	1	
12/7/2011	S2 Yard	2			2		
12/6/2011	S2 Yard	3				3	
12/6/2011	EP301	2			2		
12/6/2011	EP281	5		4		1	
12/5/2011	S2 Yard	2					2
12/5/2011	IV Substation	2		2			
12/5/2011	EP363	2		2			
12/5/2011	EP281	6		6			
12/4/2011	S2 Yard	3				3	
12/4/2011	IV Substation	2		2			
12/4/2011	Fromm CY	2				1	1
12/4/2011	EP294	1		1			
12/3/2011	EP281	1		1			
12/2/2011	IV Substation	1		1			
12/1/2011	S2 Yard	2					2
11/30/2011	S2 Yard	2			2		
11/29/2011	S2 Yard	2			2		
11/28/2011	S2 Yard	4			4		
11/28/2011	EP290-EP301	5		2	3		
11/27/2011	S2 Yard	1		1			
11/26/2011	No ravens observed						
11/25/2011	NO WORK: DAY AFTER THANKSGIVING						
11/24/2011	NO WORK: THANKSGIVING						
11/23/2011	Plaster City Yard	3					3
11/22/2011	S2 Yard	4			4		
11/22/2011	IV Substation	1			1		
11/21/2011	S2 Yard	4				4	
11/21/2011	IV Substation	1		1			
11/21/2011	EP281	2			2		
11/20/2011	EP360	2			2		
11/20/2011	IV Substation	2		2			

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed	
			Nesting	Flying	Perching	Roosting	Scavaging		
11/19/2011			No ravens observed						
11/18/2011	EP358 and IV Substation	2		2				no	
11/17/2011			No ravens observed						
11/16/2011	S2 Yard	5			5			no	
11/15/2011	EP330-1	2					2	no	
11/15/2011	EP304; EP330	1			1			no	
11/14/2011	S2 Yard	6			6			no	
11/13/2011			No ravens observed						
11/12/2011	Dunaway CY	1			1			no	
11/11/2011	Dunaway CY	4					4	no	
11/11/2011	S2 Yard	5					5	no	
11/10/2011	Fromm CY	2					2	no	
11/10/2011	EP355	1		1				no	
11/9/2011	Dunaway CY	1			1			no	
11/8/2011	S2 Yard	5			5			no	
11/8/2011	Dunaway CY	2			2			no	
11/7/2011	S2 Yard	3					3	no	
11/7/2011	EP308-EP310	1					1	no	
11/7/2011	EP301 Pullsite	7		6	1			no	
11/6/2011			No ravens observed						
11/5/2011	S2 Yard	7			7			no	
11/5/2011	IV Substation	1			1			no	
11/4/2011	S2 Yard	5			5			no	
11/3/2011	S2 Yard	5			3		2	no	
11/3/2011	IV Substation	1			1			no	
11/3/2011	Fromm CY	1				1		no	
11/3/2011	EP303 and EP302	2			2			no	
11/3/2011	EP281	2			2			no	
11/2/2011	S2 Yard	4			4			no	
11/2/2011	IV Substation	1		1				no	
11/2/2011	EP305, EP310, EP311	1		1				no	
11/1/2011	S2 Yard	2			2			no	
11/1/2011	IV Substation	1		1				no	
11/1/2011	EP305 and EP312	1			1			no	
10/31/2011	S2 Yard	5			5			no	
10/31/2011	AER and Fromm CY	1				1		no	
10/30/2011			No ravens observed						
10/29/2011	IV Substation	3		3				no	
10/28/2011	IV Substation	1		1				no	
10/28/2011	EP256, EP357 & EP358	5		5				no	
10/27/2011	EP356, EP358 & EP362	2		2				no	
10/27/2011	EP305, EP307, EP310-EP312	1		1				no	
10/26/2011	EP306, EP307 & EP310	2		2				no	
10/25/2011	IV Substation	1		1				no	
10/25/2011	EP310	1		1				no	
10/24/2011	S2 Yard	3					3	no	

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
10/24/2011	EP305	1			1			no
10/23/2011	S2 Yard	3			3			no
10/22/2011	No ravens observed							
10/21/2011	Dunaway CY	1			1			no
10/20/2011	S2 Yard	2					2	no
10/20/2011	Dunaway CY	5					5	no
10/19/2011	EP314	1		1				no
10/19/2011	EP290	5		5				no
10/18/2011	No ravens observed							
10/17/2011	EP301	3		3				no
10/16/2011	No ravens observed							
10/15/2011	S2 Yard	2					2	no
10/15/2011	Dunaway CY	1				1		no
10/15/2011	EP315	2					2	no
10/15/2011	EP301	3			3			no
10/14/2011	Fromm CY	3				3		no
10/14/2011	EP305	2		2				no
10/14/2011	EP301	3			3			no
10/13/2011	S2 Yard	2					2	no
10/13/2011	Dunaway CY	5					5	no
10/13/2011	Fromm CY	1					1	no
10/13/2011	EP354-EP363	2			2			no
10/13/2011	EP301	4		4				no
10/12/2011	EP300-EP301	2		2				no
10/11/2011	Plaster City Yard	2			2			no
10/11/2011	IV Substation	2					2	no
10/10/2011	Fromm CY	2				2		no
10/10/2011	EP359-EP360	2		2				no
10/10/2011	EP355-EP363	2		2				no
10/10/2011	EP301	3		3				no
10/9/2011	S2 Yard	3					3	no
10/9/2011	EP300	6		6				no
10/8/2011	EP357	2			2			no
10/8/2011	EP306	3					3	no
10/7/2011	Dunaway CY	1		1				no
10/7/2011	EP291-EP301	3		3				no
10/6/2011	Fromm CY	2					2	no
10/5/2011	Dunaway CY	2		2				no
10/5/2011	EP303-2	2		2				no
10/4/2011	EP310 & EP311	2		2				no
10/4/2011	EP301	3					3	no
10/4/2011	EP293	2		2				no
10/3/2011	S2 Yard	2					2	no
10/3/2011	Dunaway CY	2			2			no
10/2/2011	EP356-EP363	2		1	1			no
10/1/2011	Plaster City Yard	2					2	no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
10/1/2011	EP360	2			2			no
9/30/2011	S2 Yard	2					2	no
9/30/2011	EP355	1		1				no
9/30/2011	EP314	2		2				no
9/30/2011	EP301	2		1	1			no
9/29/2011	EP291/EP292 Pullsite	1			1			no
9/28/2011	EP361	1			1			no
9/27/2011	EP315	2		1	1			no
9/27/2011	EP309	1		1				no
9/27/2011	EP301 & EP304	4		3	1			no
9/27/2011	EP290	1			1			no
9/26/2011	EP362	2			2			no
9/26/2011	Fromm CY	1				1		no
9/25/2011	No ravens observed							
9/24/2011	Plaster City Yard	2					2	no
9/24/2011	EP317	1		1				no
9/24/2011	EP309	1		1				no
9/23/2011	EP362	4			4			no
9/23/2011	EP303	2		2				no
9/22/2011	Fromm CY	1				1		no
9/22/2011	EP303	2		2				no
9/22/2011	EP301	2		2				no
9/22/2011	EP295-EP322	3		3				no
9/21/2011	S2 Yard	3			3			no
9/21/2011	Fromm CY	1					1	no
9/21/2011	EP303	1		1				no
9/20/2011	S2 Yard	2			2			no
9/20/2011	Fromm CY	1				1		no
9/19/2011	S2 Yard	3			3			no
9/19/2011	EP304, EP307, EP309	1		1				no
9/18/2011	S2 Yard	3				3		no
9/18/2011	EP281	1		1				no
9/17/2011	S2 Yard	3					3	no
9/17/2011	EP362	1			1			no
9/17/2011	Fromm CY	3				3		no
9/16/2011	EP363	2			2			no
9/16/2011	Fromm CY	1					1	no
9/16/2011	EP304	2		2				no
9/16/2011	EP290	1		1				no
9/15/2011	S2 Yard	4			4			no
9/15/2011	Fromm CY	3					3	no
9/15/2011	EP296	1		1				no
9/15/2011	EP306	2					2	no
9/15/2011	EP304	1		1				no
9/15/2011	EP301	2		2				no
9/14/2011	Plaster City Yard	1			1			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
9/14/2011	EP361	2			2			no
9/14/2011	Fromm CY	1				1		no
9/14/2011	EP308	1					1	no
9/14/2011	EP301	5		4	1			no
9/14/2011	EP292	3		3				no
9/13/2011	S2 Yard	10			10			no
9/13/2011	EP348	3		3				no
9/13/2011	EP345	2		2				no
9/13/2011	EP326	1					1	no
9/13/2011	EP325	2		2				no
9/13/2011	EP326	1		1				no
9/13/2011	EP304	7		7				no
9/13/2011	EP291	7		7				no
9/12/2011	S2 Yard	3			3			no
9/12/2011	EP350	1		1				no
9/12/2011	EP304	1		1				no
9/12/2011	EP301	1		1				no
9/11/2011	S2 Yard	2				2		no
9/10/2011	S2 Yard	2					2	no
9/9/2011	EP304	1			1			no
9/8/2011	S2 Yard	3					3	no
9/7/2011	S2 Yard	3					3	no
9/6/2011	No ravens observed							
9/5/2011	No ravens observed							
9/4/2011	No ravens observed							
9/3/2011	No ravens observed							
9/2/2011	EP348	1		1				no
9/2/2011	S2 Yard	1		1				no
9/2/2011	EP303	1		1				no
9/2/2011	EP363	2		2				1 at IV Sub
9/1/2011	EP303	2					2	no
9/1/2011	EP293	1					1	no
9/1/2011	EP304	2					2	no
8/31/2011	S2 Yard	1		1				no
8/31/2011	EP308	1		1				no
8/31/2011	EP305-3	2					2	no
8/31/2011	EP303	2		2				no
8/30/2011	EP303	1		1				no
8/29/2011	S2 Yard	1		1				no
8/29/2011	EP303	1		1				no
8/28/2011	No ravens observed							
8/27/2011	EP305	3			3			no
8/26/2011	EP301	2		2				no
8/25/2011	S2 Yard	2					2	no
8/25/2011	EP301	2		2				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
8/24/2011	S2 Yard	3				3		no
8/23/2011	EP292-1	3		3				no
8/22/2011	No ravens observed							
8/21/2011	No ravens observed							
8/20/2011	S2 Yard	2				2		no
8/20/2011	EP312	2		2				no
8/20/2011	S2 Yard	2					2	no
8/20/2011	EP312	2		2				no
8/19/2011	EP307	2			2			no
8/19/2011	EP296	1		1				no
8/18/2011	S2 Yard	2				1	1	no
8/18/2011	EP301	Flock		x				no
8/17/2011	S2 Yard	2				1	1	no
8/17/2011	EP301	3			3			no
8/16/2011	S2 Yard	1					1	no
8/16/2011	EP301	1		1				no
8/15/2011	No ravens observed							
8/14/2011	No ravens observed							
8/13/2011	S2 Yard	2					2	no
8/12/2011	IV Substation	2				2		no
8/12/2011	S2 Yard	3				3	3	no
8/11/2011	EP294	4			4			no
8/11/2011	S2 Yard	3				3	3	no
8/10/2011	S2 Yard	3				2	1	no
8/9/2011	S2 Yard	not specified						no
8/8/2011	EP294	2			2			no
8/8/2011	S2 Yard	1						no
8/7/2011	No ravens observed							
8/6/2011	S2 Yard	1						no
8/5/2011	EP301	3		3				no
8/4/2011	S2 Yard	not specified						no
8/3/2011	S2 Yard	2		2				no
8/3/2011	S2 Yard	1						no
8/2/2011	S2 Yard	3					3	no
8/1/2011	EP314	not specified		x				no
7/31/2011	No ravens observed							
7/30/2011	EP314	3		2			1	no
7/30/2011	S2 Yard	1					1	no
7/29/2011	S2 Yard	1						no
7/28/2011	EP319	4	1	2	1			no
7/28/2011	S2 Yard	not specified						no
7/27/2011	S2 Yard	not specified						no
7/26/2011	No ravens observed							
7/25/2011	EP290	1			1			no
7/24/2011	No ravens observed							
7/23/2011	No ravens observed							

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
7/22/2011	EP290	2		1	1			no
7/21/2011	S2 Yard	1		1				no
7/20/2011	Ocotillo, CA	5						no
7/19/2011	Ocotillo, CA	1						no
7/18/2011	CP40-2	not specified						no
7/18/2011	CP41-2	not specified						no
7/18/2011	CP42-1	not specified						no
7/17/2011	No ravens observed							
7/16/2011	CP42-1	not specified						no
7/15/2011	No ravens observed							
7/14/2011	EP357	not specified						no
7/14/2011	EP358	not specified						no
7/14/2011	EP359	not specified						no
7/14/2011	Plaster City Yard	2		2				no
7/13/2011	EP313-EP314 PS	not specified						no
7/13/2011	S2 Yard	3					3	no
7/12/2011	CP18-1	not specified						no
7/12/2011	CP19-1	not specified						no
7/12/2011	CP22-1	not specified						no
7/11/2011	EP304-EP314	not specified						no
7/10/2011	No ravens observed							
7/9/2011	EP351	not specified						no
7/9/2011	EP353	not specified						no
7/9/2011	EP354	not specified						no
7/9/2011	EP355	not specified						no
7/9/2011	not specified	not specified						no
7/9/2011	S2 Yard	3					3	no
7/8/2011	EP303	2			1		1	no
7/8/2011	EP303	1		1				no
7/8/2011	S2 Yard	3					3	no
7/1/11-7/7/11	No ravens observed							
6/30/2011	EP300	3		3				no
6/21/11-6/29/11	No ravens observed							
6/20/2011	S2 Yard	2					2	no
6/1/11-6/19/11	No ravens observed							
5/1/11-5/31/11	No ravens observed							
4/22/11-4/30/11	No ravens observed							
4/21/2011	EP341	1	1					no
4/1/11-4/20/11	No ravens observed							
3/1/11-3/31/11	No ravens observed							
2/1/11-2/28/11	No ravens observed							
1/21/11-1/31/11	No ravens observed							
1/21/2011	Rough Acres Yard	not specified						no