



This report provides a summary of environmental monitoring and compliance activities conducted by Burns and McDonnell (BMcD) staff and BMcD subconsultants for the San Diego Gas & Electric (SDG&E) Sunrise Powerlink Project during the above weekly time period.

Training

- SWEAP and PBS training continued for new Project personnel every Tuesday and Thursday.
 Additional trainings were provided as requested.
- Flat-tailed horned lizard (FTHL) trainings were provided to any new crew members or monitors
 prior to construction per mitigation measure B-7b and in accordance with the FTHL Rangewide
 Management Strategy. During morning tailboard meetings, guidelines were provided about
 recognizing, protecting, and notification requirements for FTHL. FTHL information cards were
 made available to any crew members or monitors as needed.
- Monthly monitoring meeting was held on February 23, 2012 to address schedule, radio use, helicopter safety, and any questions the monitors had.

Pre/Post Construction

- Avian biologists surveyed for nesting birds prior to work commencing in inactive areas. For sites
 off of USFS lands, the results of those surveys were submitted to the CPUC/BLM biologist for
 review and concurrence. For USFS lands, the results of those surveys were submitted to the
 USFS for review and concurrence. For any active nests found, a buffer was established and no
 construction activities were permitted within the buffer area without consultation with the
 CPUC/BLM/USFS biologist. Active nests were mapped and monitored for success or failure and
 updated on the nest monitoring log.
- Footing QA/QC near EP10-2, EP21-1 to EP24-1, and EP33-1.
- As-built survey of structure near CP75-1 and CP83.
- Surveyed concrete block anchor locations near EP62A-1, EP79, EP80, EP83, and EP106.
- Additional signs and stakes were repaired as needed. Due to traffic and narrow access roads, broken stakes and run over signs were replaced. Maintenance (e.g., writing over faded signs, reinforcing signs/stakes in the ground, replacing zip ties, and adding additional signs) was performed as needed. The ESA Team conducted the following activities during this reporting period:
 - Repaired, refreshed, replaced, and maintained the previously installed project signs and ESAs near the intersection of Deerhorn Valley and Cinnamon Drive, EP84, EP85, EP205, EP220, EP109 access road, EP113, EP112, EP130, EP79, EP74, EP73, CP16, CP28, CP57, CP77, EP24, CP35, CP40, EP105, EP247, EP190, EP187, and EP171.

Construction

- Monitors were present during construction activities to ensure compliance with mitigation
 measures as identified in the Final EIR/EIS Mitigation Monitoring, Compliance, and Reporting
 Program. Archaeologists, Paleontologists, and Native American Monitors were present at sites
 where required as identified prior to construction activity and as approved in the NTPs. On
 average, the following number of monitors were on the Project throughout the week:
 - 133 Biological monitors.





- 2 Archaeological monitors.
- 2 Native American monitors.
- 8 SWPPP monitors.
- Project staff carpooled to site reviews, kick-off tailgates, and off-site meetings. Construction and traffic control crews were observed carpooling from yards to work areas.
- Deterrents were utilized to discourage bird nest building activities throughout the Project.
 Deterrents are determined depending upon the location and type of possible nesting areas and may include metallic flagging, compact discs, plastic owls, and the presence of biological monitors.
- The table below demonstrates the construction progress to date:

	OVER	RHEAD					
Agency	Foundations Completed	Towers Erected	Wire Installed				
Non-Federal	154 of 169	121 of 169	74 of 169 CP24 to CP29 CP31				
Bureau of Land Management	161 of 179	133 of 179	110 of 179 EP170 to EP177				
Miramar	14 of 14	14 of 14	11 of 14				
U.S. Forest Service	39 of 76	17 of 76	17 of 76				
	UNDER	GROUND					
Agency	Vaults Ir	nstalled	Trenches Excavated & Backfilled				
Non-Federal	40 of	40	42 of 42				
	SUBSTATIO	N UPGRADES					
	3 of 7 C	ompleted					
	SUNCREST	SUBSTATION					
95 Percent Complete							

Overhead Construction

- Link 1
 - Final grading at EP218-1, EP219-1 pull sites, EP344 pull site, EP346 to EP349, EP352, EP353, EP355, and EP358.
 - Fence repairs made at EP186-1.





- Preparing for micropile redrills at EP147 and EP148-1.
- Micropile trimming at EP147.
- Micropile cap work at EP146 and EP189-3.
- Tower assembly at EP194-3, EP221-2, EP225-1, EP233-1, EP234-1, EP236-1, EP239-1, EP246, and EP249-1.
- Miscellaneous tower work (anti-climbing guards, bird deterrents, and/or signage) at EP313 to EP318-1 and EP320-1 to EP355.
- QA/QC at EP190, EP198, EP221A, and EP225-1.
- Ground rod testing at EP191 and at EP193 to EP195.
- Demobilization of equipment at EP170 pull site.
- Haulback and conductor flown from EP170 to EP177.
- OPGW sock line flown from EP170 to EP177.
- OPGW flown from EP176 to EP187-2.
- Sagging from EP170 to EP187-2.
- Clipping in at EP170 and EP180.
- Deadend work, training fiber, and spacer work at EP187-2.
- Snubs removed from McCain Valley Yard.
- Spacers installed at EP174 to EP176 and EP180 to EP187-2.
- Spacers adjusted at EP360 to EP362.
- Guard structure removal at EP219-1 and EP220-1.
- BMP installation/maintenance at:
 - EP144 to EP152-2, EP170 to EP184, EP170-N to EP201-3-E, EP186-1 to EP188-1, EP190-2 to EP217-1 (including guard structures and pull sites), EP219-1 pull sites, EP220-1 guard structure to EP231A, EP235-1 to EP238-1 (including the EP237-1 pull site), EP246, EP249-1, EP251, EP251 guard structure, EP314, EP315-1, and EP317.
- BMP removal from EP343 to EP347 (including the pull site).
- Desert pavement restoration at EP343 to EP345.
- Seeding at EP200A-1, EP203-3, EP204-3, EP215, and EP219-1 pull site.
- Weed abatement at EP255-2 to EP258-3, HMMP site near EP265-2, EP313, EP313 pull site, EP316-2, EP318-1, EP320-1 to EP324 pull site, EP325-2 to EP360 (including the EP339, EP349, and EP356 pull sites), and EP362.
- Trained FTHL monitors and Visible Emission Evaluators (VEEs) were onsite as required.

• Link 2

 During this reporting period, the PAL Levels were as follows: Tuesday-C, Wednesday-C, Thursday-D, Friday-D, and Saturday-D. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

USFS Land

- Vegetation maintenance at EP22-1, EP23-2, EP35-1, EP118-2, and EP123-1.
- Grading at EP12-3 and EP12-3 pull site.
- Access road construction at EP36-1-E.
- Gate work at EP116-1.
- Cattle guard repairs at EP105-2-E-A.
- Site prep at EP35-1.
- Micropile drilling at from EP14-1 to EP17, EP19-1, EP21-1, EP28-3, EP34-1, EP37-2, EP109-1, EP114-2, EP117-2, EP118-2, EP122-1, and EP123-1.
- Grouting at EP108-2, EP111-4, EP114-2, EP116-1, and EP143-1.
- Micropile capping crew at EP17, EP18, and EP58-2.





- Conventional drilling at EP11-3.
- Ground rod installation at EP9-1.
- Ground resistance testing at EP112-3 and EP112A-1.
- Tower assembly at EP113-5.
- BMP maintenance at:
 - EP5-2 to EP9-1, EP9-1 pull site, EP10-2, EP11-3 to EP22-1, EP28-1, EP29-2, EP33-1, EP36-1, EP36-1-E, EP112-3, EP113-5, EP118-2, EP121-3, EP125-E-A to EP131-E, EP128 to EP131, EP125 pull site, EP130-1 pull site, EP141 pull sites, EP142-1, and GS-USFS-2.

BLM Land

- Vegetation maintenance at EP40-1 and EP41.
- Prep drilling at EP68.
- Micropile drilling at EP102A-1.
- Micropile cap work at EP75-2.
- Conventional drilling at EP68.
- Tower assembly at EP94 to EP99-2 and EP103A.
- Arroyo toad fencing installed and/or maintained at EP76-2.
- BMP maintenance at:
 - EP39-1 to EP42 pull site, EP47-2 to EP51-1, EP53-3, EP69, EP75, EP76-2, EP94 to EP101-2 pull site (including access roads), EP103-2, and EP103A.

Non-Federal Land

- Access road construction and/or maintenance at CY-Bartlett-E and EP84-E.
- Blasting at EP65-1.
- Conventional drilling at EP65-1.
- Miscellaneous foundation work at EP67.
- Site prep at EP65-1.
- Micropile drilling at EP82, EP87-1, EP107-3, and EP119-2.
- Micropile cap work at EP62A-1and EP86-1.
- Tower assembly at EP26-1, EP27-1, EP30-2, EP81, EP84, EP86-1, EP93, and EP104-2.
- QA/QC at EP26-1, EP27-1, and EP30-2.
- Ground rod installation at EP32-1.
- Grounding at EP91 and EP92.
- Insulator work at EP26-1, EP27-1, and EP30-2.
- Arroyo toad fencing installed and/or maintained at EP78-E and EP78A.
- BMP installation/maintenance at:
 - EP1-4 to EP4-3, EP11-3-N, EP13-3, EP26-1, EP27-1, EP30-2, EP30-2 pull site, EP32-1, EP64-1 to EP67, EP65-1, EP66-E, EP77 to EP79, EP78/78A pull site, EP83, EP84, EP86-1 to EP89-1, EP89-1 pull site, EP91 to EP93, EP91 pull site, EP104-2, EP105-2, EP106-3, EP107-3, GS-NF-23, GS-NF-24, and GS-NF-25.

Link 5

 During this reporting period, the PAL Levels were as follows: Tuesday-C, Wednesday-C, Thursday-D, Friday-D, and Saturday-D. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

USFS Land

Cleanup at CP99-2 and CP100-1.





- Hydroseeding at CP100-1.
- BMP maintenance at CP99-2, CP99-2-N, CP100-1, and CP100-1-N.

BLM Land

- Tower assembly at CP60.
- OA/OC at CP59, CP60, and CP62A.
- Cleanup at CP58-1, CP60, and CP61-1.
- Travelers installed from CP58-1 to CP62A.
- BMP installation and maintenance at:
 - CP58-1 to CP60 and CP62A.

Non-Federal Land

- Grouting at CP32-2, CP33A, CP33-3, CP34-2, CP36-1, CP48-2, and CP49-1.
- Micropile trimming at CP32-2, CP33A, CP33-2, CP34-2, and CP36-1.
- Micropile cap work at CP32-2, CP33A, CP33-2, CP34-2, CP35-2, CP62-2, CP78-2, CP79-1, and CP86.
- Tower assembly at CP37-2, CP39, CP43, CP44-1, CP45-1, CP46-2, CP47-2, CP50, CP62-2, CP63-3, and CP86.
- Miscellaneous tower work (bird deterrents, signs, etc.) at CP74-2.
- OA/OC at CP27, CP28-1, CP56-1, and CP62-2 to CP64-2.
- Cleanup at CP47-2, CP54-1, CP55, CP56-1, CP62-2, CP63-3, CP64-2, and CP98-1.
- Ground rod installation at CP37-2 and CP39.
- Concrete block anchors set at CP39.
- Mobilization of equipment at CP65-1 pull site.
- Sock line, hardline, and conductor installed on all phases from CP23 to CP31-2.
- OPGW installed from CP15-1 to CP31-2.
- OPGW deadend work from CP15-1 to CP16-1.
- Spacers installed from CP76-1 to CP86.
- Jumpers installed at CP23 and CP27.
- Clipping in at CP23.
- Dampeners installed from CP80-2 to CP88-1.
- Traveler work at CP56-1, CP57, and CP62-2 to CP64-2.
- Deadend work at CP27.
- Marker ball installation from CP80-2 to CP87-1.
- BMP installation and maintenance at:
 - CP16 to CP26, CP31, CP36-1, CP42 to CP44, CP44 guard structure, CP46, CP46 guard structure, CP48-2 to CP50, CP52 to CP56-1 (including the pull site access road), CP62-2 to CP64-3, CP71, CP72-2, CP74-2 to CP86, CP95/CP96 pull site, and CP98-1.
- Hydroseeding at CP23 pull site north and CP96-1 pull site.

Miramar

- Access road construction at CP10 and CP11-1.
- OPGW deadend work from CP15-1 to CP16-1.
- BMP installation and maintenance from CP3 to CP15-1 (including guard structures).

12kV

No work occurred this reporting period.





<u>Underground Construction (Link 4)</u>

- Revitalization Alpine Blvd.
- Grading Bauer Property & V19R
- Raised Necking V10R, V15R, V16R, V17R, and V18R
- BMP Maintenance Entire ROW.
- Grouting –V14R, V15R, V16R, V17R, and V18R.
- Fiber Phase Comparison V2R, V10R, V11R, V12R, V13R, V14R, V15R, V16R, and V17R.
- Kinetrics Manholes 1 & 20
- Paving V16R and V17R.
- Sending & Receiving CalTrans Bore Site.
- Slope Compaction & Asphalt Removal Bauer property
- Test Set Up V2L, V2R, V3L, V3R, V4L, V4R, V5L, V5R, V6L, V6R, V7L, V7R, V8L, V8R, V9L, V10L, V10R, V11L, V12L, V12R, V13L, V13R, V14L, and V14R.

Suncrest Substation Construction (Link 3)

- Crushing class 2 base and select fill material.
- Installing insulators and conductors in the 230kV and 500kV yards.
- Wiring inside the control shelter.
- Fence installation activities around the substation perimeter.
- Finish grading around the maintenance shelter and class 2 base placement.
- Paving the entrance road to the substation and the parking area around the maintenance shelter.
- Paving the bottom portion of the substation entrance road and installing the curb along Bell Bluff Truck Trail.
- Excavating the brow ditch and placing rebar along the entrance road to the substation.
- Erecting and priming steel frame for the warehouse.
- Placing class 2 base in the southeast corner of the 500 kV yard.
- Coating the insulators in the 230 kV yard.
- Pouring concrete for the brow ditches along the substation entrance road.
- Rough grading along eastern perimeter of the substation pad.

Substation Upgrades

San Luis Rey:

• Wiring crews working inside the control house.

Encina:

- SDG&E relay crews performing wiring near the control house.
- Roel building forms outside the 138kV switchyard and organizing materials for next phase of work.
- Security camera contractor working on wiring in the 230kV switchyard.

Imperial Valley:

• No Sunrise-related work.

Sycamore:

- SDG&E Kearny Mesa crews building disconnects and bus for 69kV upgrades in southern portion of substation.
- Roel Construction crew working on conduit installation for the new 230 kV transformer.
- Crew also preparing the work area to set A-frame structures over new transformer north of the 69 kV rack.





Construction Yards

- Sycamore Yard Dust suppression, helicopter operations, water staging, and staging for road, micropile, habitat assessment, wire, and BMP crews.
- Helix Yard Helicopter operations, weed wash station, dust suppression, hooking, and staging for micropile, assembly, wire, erection, BMP, and QC crews.
- El Monte Yard Demobilizing equipment from the yard.
- Alpine Yard Equipment/Materials staging, water staging, dust suppression, weed wash station, and staging for ESA, habitat assessment, road, BMP, conventional foundation, and QC crews.
- Wilson Yard Helicopter operations and staging for QC crews.
- SWAT Yard Water staging, helicopter operations, dust suppression, tower assembly, weed wash station, vegetation maintenance, and staging for micropile assembly, road, conventional foundation, habitat assessment, vegetation maintenance, and BMP crews.
- Barrett Canyon Yard Staging for vegetation maintenance and BMP crews.
- Kreutzkamp Yard Helicopter operations, weed wash station, water staging, dust suppression, vegetation maintenance, and staging for road, conventional foundation, and BMP crews.
- Bartlett-Hauser Yard Water staging, helicopter operations, weed wash station, dust suppression, tower assembly, repair access road BMPs, and staging for micropile, erection, toad survey, QC, and BMP crews.
- Thing Valley Yard Helicopter operations, water staging, dust suppression, BMP maintenance, and staging for BMP and micropile crews.
- McCain Valley Yard Helicopter operations, water staging, dust suppression, weed wash station, and tower assembly.
- Rough Acres Yard Helicopter operations, water staging, dust suppression, tower assembly, staging for equipment/materials, weed wash station, and staging for erection, QC, wire, road, micropile, and BMP crews.
- Jacumba Valley Ranch (JVR) Yard Helicopter operations, weed wash station, water staging, dust suppression, and staging for habitat assessment, BMP, micropile and erection crews.
- AER Yard Restored.
- Fromm Yard Shut down due to end of big horn sheep work window.
- S2 Yard Restored
- Plaster City Yard Water staging, dust suppression, and staging for road and BMP crews.
- Dunaway Yard Restored.
- Imperial Valley Yard Restored.

Wildlife Reporting

The following listed or Species of Special Concern were found dead in Project construction limits during this reporting period:

• Silvery Legless Lizard (*Anniella pulchra*) – Two (2) silvery legless lizards were found dead; one (1) at EP109-1 and one (1) at EP14-1.

The following listed or Species of Special Concern were relocated during construction activities this reporting period:

• Coast Horned Lizard (*Phrynosoma blainvillii*) – Two (2) coast horned lizards were relocated; one (1) from the access road to EP99 and one (1) from access road to EP36-1.





Spills/Hazardous Waste

- Minor leaks, drips, and releases on USFS lands were submitted to the USFS in a weekly HazMat log.
- No reportable spills occurred outside the USFS during this reporting period.

Customer Complaints

• No customer complaints were received during this reporting period.

Non-Compliances

• No non-compliances were issued during this reporting period.

Variances and TEWS

• Variance #38 was approved on February 22, 2012, for installing a gate on private property.

Weather

- No rain events occurred during this reporting period.
- BMPs were installed or maintained as needed throughout Project areas. In accordance with the Construction General Permit (CGP), daily site BMP inspections, photos, and appropriate BMPs for stormwater and non-stormwater were implemented. Any sites requiring repairs began within 72 hours of identification.

Appendices

Flat-Tailed Horned Lizard Monitoring Report Raven Control Monitoring Report

	Flat Tailed Horned L	izard Co	unts - W	eek End	ing 02/2!	5/2012			
Date	Location	Obse	rved	Inju	ıred	Relo	cated	De	ead
	Post RCLMP*	Day	Night	Day	Night	Day	Night	Day	Night
2/23/2012	West side of AR to EP324	1						<u> </u>	
11/1/2011	Dunaway CY					1			
10/13/2011	AR to EP354							1	
9/20/2011	AR btwn EP357 and EP358							1	
9/19/2011	AR btwn EP352 and EP353	1							
9/12/2011	EP325					1			
9/9/2011	AR to EP363	1							
9/6/2011	AR to EP360/361					1			
9/6/2011	EP360					2			
9/6/2011	EP359					1			
9/3/2011	SWPL AR to EP324					1			
9/3/2011	SWPL AR to EP342					1			
9/3/2011	SWPL AR to EP345							1	
9/3/2011	SWPL AR to EP344 and EP345					1			
8/31/2011	EP324					1			
8/31/2011	SWPL AR to EP325-2					1			
8/30/2011	SWPL AR to EP346 and EP347					1			
8/29/2011	SWPL AR to EP353 and EP354							1	
8/29/2011	SWPL AR to EP324							1	
8/27/2011	EP349					1			
8/25/2011	EP360							1	
8/25/2011	Btwn EP320/321					1			
8/24/2011	SWPL AR near EP346					1			
8/23/2011	EP349					1			
8/21/2011	SWPL AR btwn EP344/345					1			
8/21/2011	SWPL AR to EP345							1	
8/19/2011	SWPL AR to EP339					1			
8/20/2011	SWPL AR to IV Sub							1	
8/20/2011	SWPL AR btwn EP346/347					1			
8/19/2011	EP338/339 Pullsite					1			
8/19/2011	EP355/356 Pullsite					1			
8/18/2011	EP347					1			
8/18/2011	SWPL AR to EP353							1	
8/11/2011	SWPL AR by EP348					1			
8/11/2011	EP348/EP349 Pullsite					1			
8/10/2011	EP347					1			
8/8/2011	SWPL AR to EP351					2			
8/6/2011	BLM AR near EP327							1	
8/1/2011	IV Substation Yard	1							
8/1/2011	EP325					1			
8/1/2011	AR to EP345					1			
7/30/2011	EP322					1			
7/28/2011	EP355/EP356 Pullsite					1			

	Flat Tailed Horned L	izard Co	unts - W	eek End	ing 02/2!	5/2012			
Date	Location	Obse	erved	Inju	ured	Relo	cated	De	ead
7/27/2011	Near EP316-2	1							
7/26/2011	SWPL AR to EP344	1							
	Post RCLMP*	Day	Night	Day	Night	Day	Night	Day	Night
7/26/2011	EP347					1			
7/26/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/22/2011	AR to IV Sub					1			
7/21/2011	EP360					1			
7/21/2011	AR to EP326					1			
7/19/2011	SWPL AR to IV Sub	1							
7/19/2011	EP353					1			
7/19/2011	AR to Dunaway CY					1			
7/18/2011	EP318					1			
7/17/2011	EP355					1			
7/15/2011	EP359	1							
7/15/2011	EP352	1							
7/15/2011	EP350	1							
7/14/2011	Spur Rd to EP355							1	
7/14/2011	EP322	1							
7/13/2011	EP357	1							
7/12/2011	EP344	1							
7/12/2011	SWPL AR btwn EP348/345							1	
ТО	TAL POST RCLMP	13	0	0	0	43	0	12	
	Prior to RCLMP	D	ay	D	ay	D	ay	D	ay
7/11/2011	AR to EP352						2		
7/11/2011	AR to EP345						2		
7/10/2011	EP358						1		
7/10/2011	SWPL AR to EP354						2		
7/9/2011	AR to EP330		1						
7/8/2011	Spur Rd. to EP352		1						
7/7/2011	EP324						1		
7/7/2011	EP355						1		
7/6/2011	SWPL AR btwn EP362/363								1
7/5/2011	EP354						1		
7/1/2011	AR to EP353		1						
6/30/2011	AR between EP310/311								1
6/30/2011	EP358		1						
6/30/2011	EP360		1						
6/30/2011	AR to EP312								1
6/30/2011	EP360								1
6/27/2011	EP350						1		
6/27/2011	SWPL AR to IV Substation		2						

	Flat Tailed Horned L	izard Counts - W	eek Ending 02/2	5/2012	
Date	Location	Observed	Injured	Relocated	Dead
6/26/2011	IV Substation			1	
6/25/2011	SWPL AR to EP361	1			
6/24/2011	EP359			1	
6/23/2011	SWPL AR to EP360			2	
6/22/2011	SWPL AR to EP355			1	
6/20/2011	EP356	2			
6/20/2011	SWPL AR to EP359	1			
6/20/2011	Near EP356	2			
6/20/2011	AR between EP358/357				1
6/18/2011	AR to Dunaway CY				1
6/17/2011	Near EP322	1			
6/7/2011	Near EP355	1			
6/7/2011	EP361			1	
6/7/2011	AR btwn EP343/EP344				1
6/7/2011	AR between EP324/325				1
6/6/2011	SWPL AR btwn EP344/EP345			1	
6/3/2011	EP359			1	
6/3/2011	SWPL AR EP362			1	
6/2/2011	AR to EP358			1	
6/2/2011	SWPL AR to EP316-2				1
6/2/2011	AR east of EP325				1
6/1/2011	SWPL AR btwn EP319/EP320			1	
6/1/2011	SWPL AR to EP318			1	
5/31/2011	SWPL AR btwn EP359/EP360			1	
5/31/2011	SWPL AR to EP320			1	
5/31/2011	EP360				1
5/27/2011	EP357			1	
5/26/2011	SWPL AR to EP359			1	
5/25/2011	Spur Rd to EP321			1	
5/23/2011	EP323			1	
5/21/2011	EP324			1	
5/20/2011	IV CY			1	
5/20/2011	AR to EP362			1	
5/20/2011	AR btwn EP324/EP325			1	
5/20/2011	SWPL AR btwn EP326/EP327			1	
5/20/2011	IV Substation			3	
5/19/2011	IV Substation			5	
5/19/2011	EP324			1	
5/18/2011	IV Substation Yard			1	
5/18/2011	IV Substation Yard				1
5/17/2011	AR to IV Substation				1
5/16/2011	IV Substation Yard			1	
5/13/2011	SWPL AR Near EP362-1	1			
5/12/2011	AR to EP355			1	

	Flat Tailed Horned Lizard Counts - Week Ending 02/25/2012									
Date	Location	Observed	Injured	Relocated	Dead					
5/11/2011	EP360	1								
5/11/2011	Dunaway CY	3								
5/11/2011	Dunaway Yard			4						
5/10/2011	EP322	1								
5/10/2011	AR to Dunaway CY	1								
5/9/2011	Dunaway Yard			4						
5/7/2011	EP322	1								
5/7/2011	Spur Road to EP344	1								
5/7/2011	Dunaway Yard			1						
5/6/2011	AR to EP321-1	1								
5/5/2011	AR to EP321-1	1								
5/5/2011	AR to Dunaway CY	2								
5/5/2011	Dunaway Yard			2						
5/4/2011	AR btwn EP343/EP344			1						
5/3/2011	SWPL AR btwn EP320/EP321	1								
4/27/2011	AR to EP322	2								
4/26/2011	EP322	1								
4/25/2011	Plaster City CY	1								
4/20/2011	Plaster City			1						
4/18/2011	Plaster City			1						
4/14/2011	AR to IV Substation	1								
4/2/2011	Dunaway CY	1								
TOTA	AL PRIOR TO RCLMP	35	0	60	13					
	YTD	48	0	103	25					

^{*}RCLMP refers to the Revised Construction Lighting Mitigation Plan

	Raven Control I	Monitoring Rep	ort - Wee	k Ending (02/25/2012			
Date	Location	Number of Ravens observed			Raven Activ			FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
2/25/2012			No ravens	observed				
2/24/2012	EP355	3		3				no
2/23/2012	EP355	1		1				no
2/22/2012	EP347	2		2				no
2/22/2012	EP343/EP344 Pullsite	2					2	no
2/21/2012			No ravens	observed				
2/20/2012	EP313-EP354	2		2				no
2/19/2012	EP360-EP362	2		2				no
2/18/2012			No ravens	observed	l			
2/17/2012			No ravens	observed				
2/16/2012	S2 Yard	3		3				no
2/15/2012	S2 Yard	5		5				no
2/14/2012	S2 Yard	2		2				no
2/13/2012			No ravens	observed	l			
2/12/2012			No ravens	observed	l			
2/11/2012			No ravens	observed	l			
2/10/2012			No ravens	observed				
2/9/2012	S2 Yard	2		2				no
2/8/2012	S2 Yard	3		2			1	no
2/7/2012	S2 Yard	3		2			1	no
2/6/2012	S2 Yard	3		2			1	no
2/5/2012			No ravens	observed			•	
2/4/2012	S2 Yard	2			2			no
2/3/2012			No ravens	observed			<u>. </u>	
2/2/2012	Pull site EP338/EP339	2			2			no
2/2/2012	S2 Yard	1		1				no
2/1/2012	Pull site EP338/EP339	3		3				no
1/31/2012	EP330	2		2				no
1/30/2012			No ravens	observed				
1/29/2012			No ravens	observed	1			
1/28/2012			No ravens					
1/27/2012	Plaster City Yard	2					2	no
1/26/2012	S2 Yard	2	<u> </u>	2				no
1/26/2012	EP341	2	<u> </u>		2			no
1/26/2012	EP316	2		2				no
1/25/2012	EP324	1		1				no
1/24/2012	2. 32 1		No ravens					
1/23/2012			No ravens					
1/22/2012		No ravens observed						
1/21/2012			No ravens					
1/20/2012			No ravens					
1/19/2012	EP326-EP328	2	1.0 1070113	2				no
1/18/2012	EP334	1	 	1				no
1/17/2012	EP329-1	2	 		2			
1/1//2012	EP329-1		I				<u> </u>	no

Date	Location	Number of Ravens observed			Raven Activ	vity		FTHL observed
		Observed	Nesting	Flying	Perching	Roosting	Scavaging	
1/16/2012			No ravens	observed				
1/15/2012			No ravens	observed				
1/14/2012			No ravens	observed				
1/13/2012			No ravens	observed				
1/12/2012			No ravens	observed				
1/11/2012			No ravens	observed				
1/10/2012			No ravens	observed				
1/9/2012			No ravens	observed				
1/8/2012			No ravens	observed				
1/7/2012			No ravens	observed				
1/6/2012			No ravens	observed				
1/5/2012			No ravens	observed				
1/4/2012			No ravens	observed				
1/3/2012			No ravens	observed				
1/2/2012			No ravens	observed				
1/1/2012			No ravens	observed				
12/31/2011			No ravens	observed				
12/30/2011			No ravens	observed				
12/29/2011	EP313-EP304 & EP295-EP292	P313-EP304 & EP295-EP292 2 2						
12/28/2011	EP294	20			20			no
12/27/2011	EP292	2			2			
12/26/2011	EP292	2					2	no
12/25/2011			No ravens	observed				
12/24/2011	EP281, EP281GS & EP290	5		5				no
12/23/2011			No ravens	observed				
12/22/2011	EP300-1, EP301 & EP304	3		3				no
12/21/2011			No ravens	observed				
12/20/2011	EP290-EP291/EP292 Pullsite	2			2			no
12/19/2011			No ravens	observed				
12/18/2011			No ravens	observed				
12/17/2011	EP325	1		1				no
12/17/2011	S2 Yard	3					3	no
12/16/2011			No ravens	observed				
12/15/2011	IV Substation	1			1			no
12/15/2011	EP293	2		2				no
12/15/2011	S2 Yard	3					3	no
12/14/2011	S2 Yard	3					3	no
12/13/2011	S2 Yard	2					2	no
12/12/2011	S2 Yard	2					2	no
12/11/2011	S2 Yard	2					2	no
12/10/2011	EP306 & EP306/EP307 Pullsite	3		3				no
12/9/2011	IV Substation	1		1				no
12/9/2011	EP308 &EP306/EP307 Pullsite	2		2				no
12/9/2011	EP291 & EP291/EP292 Pullsite	2		2				no
12/8/2011	S2 Yard	3					3	no

Date	Location	Number of Ravens observed			Raven Activ	•		FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
12/8/2011	IV Substation	1		1				no
12/8/2011	EP301	2		2				no
12/8/2011	EP300-EP309	2		2				no
12/8/2011	EP291/EP292 Pullsite	2	2					no
12/8/2011	EP281	2		2				no
12/7/2011	IV Substation	1		1				no
12/7/2011	EP301	1			1			no
12/7/2011	EP291/EP292 Pullsite	1			1			no
12/7/2011	EP281	7		4	2	1		no
12/7/2011	S2 Yard	2			2			no
12/6/2011	S2 Yard	3				3		no
12/6/2011	EP301	2			2			no
12/6/2011	EP281	5		4		1		no
12/5/2011	S2 Yard	2					2	no
12/5/2011	IV Substation	2		2				no
12/5/2011	EP363	2		2				no
12/5/2011	EP281	6		6				no
12/4/2011	S2 Yard	3				3		no
12/4/2011	IV Substation	2		2				no
12/4/2011	Fromm CY	2				1	1	no
12/4/2011	EP294	1		1				no
12/3/2011	EP281	1		1				no
12/2/2011	IV Substation	1		1				no
12/1/2011	S2 Yard	2					2	no
11/30/2011	S2 Yard	2			2			no
11/29/2011	S2 Yard	2			2			no
11/28/2011	S2 Yard	4			4			no
11/28/2011	EP290-EP301	5		2	3			no
11/27/2011	S2 Yard	1		1				no
11/26/2011			No ravens					
11/25/2011			K: DAY AFT					
11/24/2011			WORK: TH	IANKSGIV	ING	1	•	
11/23/2011	Plaster City Yard	3					3	no
11/22/2011	S2 Yard	4			4			no
11/22/2011	IV Substation	1			1			no
11/21/2011	S2 Yard	4					4	no
11/21/2011	IV Substation	1		1				no
11/21/2011	EP281	2			2			no
11/20/2011	EP360	2			2			no
11/20/2011	IV Substation	2		2				no
11/19/2011			No ravens				1	
11/18/2011	EP358 and IV Substation	2		2				no
11/17/2011			No ravens	observed				
11/16/2011	S2 Yard	5			5			no
11/15/2011	EP330-1	2					2	no

Date	Location	Number of Ravens observed			Raven Activ			FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
11/15/2011	EP304; EP330	1			1			no
11/14/2011	S2 Yard	6			6			no
11/13/2011			No ravens	observed			1	
11/12/2011	Dunaway CY	1			1			no
11/11/2011	Dunaway CY	4					4	no
11/11/2011	S2 Yard	5					5	no
11/10/2011	Fromm CY	2					2	no
11/10/2011	EP355	1		1				no
11/9/2011	Dunaway CY	1			1			no
11/8/2011	S2 Yard	5			5			no
11/8/2011	Dunaway CY	2			2			no
11/7/2011	S2 Yard	3					3	no
11/7/2011	EP308-EP310	1					1	no
11/7/2011	EP301 Pullsite	7		6	1			no
11/6/2011			No ravens	observed	l			
11/5/2011	S2 Yard	7			7			no
11/5/2011	IV Substation	1			1			no
11/4/2011	S2 Yard	5			5			no
11/3/2011	S2 Yard	5			3		2	no
11/3/2011	IV Substation	1			1			no
11/3/2011	Fromm CY	1				1		no
11/3/2011	EP303 and EP302	2			2			no
11/3/2011	EP281	2			2			no
11/2/2011	S2 Yard	4			4			no
11/2/2011	IV Substation	1		1				no
11/2/2011	EP305, EP310, EP311	1		1				no
11/1/2011	S2 Yard	2			2			no
11/1/2011	IV Substation	1		1				no
11/1/2011	EP305 and EP312	1			1			no
10/31/2011	S2 Yard	5			5			no
10/31/2011	AER and Fromm CY	1				1		no
10/30/2011			No ravens	observed				
10/29/2011	IV Substation	3		3				no
10/28/2011	IV Substation	1		1				no
10/28/2011	EP256, EP357 & EP358	5		5				no
10/27/2011	EP356, EP358 & EP362	2		2				no
10/27/2011	EP305, EP307, EP310-EP312	1		1				no
10/26/2011	EP306, EP307 & EP310	2		2				no
10/25/2011	IV Substation	1		1				no
10/25/2011	EP310	1		1				no
10/24/2011	S2 Yard	3					3	no
10/24/2011	EP305	1			1			no
10/23/2011	S2 Yard	3			3			no
10/22/2011			No ravens	observed				
10/21/2011	Dunaway CY	1	12.70.70		1			no

Date	Location	Number of Ravens observed			Raven Activ	vity		FTHL observed
		observed	Nesting	Flying	Perching	Roosting	Scavaging	
10/20/2011	S2 Yard	2					2	no
10/20/2011	Dunaway CY	5					5	no
10/19/2011	EP314	1		1				no
10/19/2011	EP290	5		5				no
10/18/2011			No ravens	observed	ł			
10/17/2011	EP301	3		3				no
10/16/2011			No ravens	observed	d			
10/15/2011	S2 Yard	2					2	no
10/15/2011	Dunaway CY	1				1		no
10/15/2011	EP315	2					2	no
10/15/2011	EP301	3			3			no
10/14/2011	Fromm CY	3				3		no
10/14/2011	EP305	2		2				no
10/14/2011	EP301	3			3			no
10/13/2011	S2 Yard	2					2	no
10/13/2011	Dunaway CY	5					5	no
10/13/2011	Fromm CY	1					1	no
10/13/2011	EP354-EP363	2			2			no
10/13/2011	EP301	4		4				no
10/12/2011	EP300-EP301	2		2				no
10/11/2011	Plaster City Yard	2			2			no
10/11/2011	IV Substation	2					2	no
10/10/2011	Fromm CY	2				2		no
10/10/2011	EP359-EP360	2		2				no
10/10/2011	EP355-EP363	2		2				no
10/10/2011	EP301	3		3				no
10/9/2011	S2 Yard	3					3	no
10/9/2011	EP300	6		6				no
10/8/2011	EP357	2			2			no
10/8/2011	EP306	3					3	no
10/7/2011	Dunaway CY	1		1				no
10/7/2011	EP291-EP301	3		3				no
10/6/2011	Fromm CY	2					2	no
10/5/2011	Dunaway CY	2		2				no
10/5/2011	EP303-2	2		2				no
10/4/2011	EP310 & EP311	2		2				no
10/4/2011	EP301	3					3	no
10/4/2011	EP293	2		2				no
10/3/2011	S2 Yard	2					2	no
10/3/2011	Dunaway CY	2			2			no
10/2/2011	EP356-EP363	2		1	1			no
10/1/2011	Plaster City Yard	2					2	no
10/1/2011	EP360	2			2			no
9/30/2011	S2 Yard	2					2	no
9/30/2011	EP355	1		1				no

Date	Location	Number of Ravens observed		Raven Activity				FTHL observed
		observed.	Nesting	Flying	Perching	Roosting	Scavaging	
9/30/2011	EP314	2		2				no
9/30/2011	EP301	2		1	1			no
9/29/2011	EP291/EP292 Pullsite	1			1			no
9/28/2011	EP361	1			1			no
9/27/2011	EP315	2		1	1			no
9/27/2011	EP309	1		1				no
9/27/2011	EP301 & EP304	4		3	1			no
9/27/2011	EP290	1			1			no
9/26/2011	EP362	2			2			no
9/26/2011	Fromm CY	1				1		no
9/25/2011			No ravens	observed	t			
9/24/2011	Plaster City Yard	2					2	no
9/24/2011	EP317	1		1				no
9/24/2011	EP309	1		1				no
9/23/2011	EP362	4			4			no
9/23/2011	EP303	2		2				no
9/22/2011	Fromm CY	1				1		no
9/22/2011	EP303	2		2				no
9/22/2011	EP301	2		2				no
9/22/2011	EP295-EP322	3		3				no
9/21/2011	S2 Yard	3			3			no
9/21/2011	Fromm CY	1					1	no
9/21/2011	EP303	1		1				no
9/20/2011	S2 Yard	2			2			no
9/20/2011	Fromm CY	1				1		no
9/19/2011	S2 Yard	3			3			no
9/19/2011	EP304, EP307, EP309	1		1				no
9/18/2011	S2 Yard	3				3		no
9/18/2011	EP281	1		1				no
9/17/2011	S2 Yard	3					3	no
9/17/2011	EP362	1			1			no
9/17/2011	Fromm CY	3				3		no
9/16/2011	EP363	2			2			no
9/16/2011	Fromm CY	1					1	no
9/16/2011	EP304	2		2				no
9/16/2011	EP290	1		1				no
9/15/2011	S2 Yard	4			4			no
9/15/2011	Fromm CY	3					3	no
9/15/2011	EP296	1		1				no
9/15/2011	EP306	2					2	no
9/15/2011	EP304	1		1				no
9/15/2011	EP301	2		2				no
9/14/2011	Plaster City Yard	1			1			no
9/14/2011	EP361	2			2			no
9/14/2011	Fromm CY	1				1		no

Date	Location	Number of Ravens			Raven Activ	vity		FTHL observed
		observed	Nesting	Flying	Perching	Roosting	Scavaging	
9/14/2011	EP308	1					1	no
9/14/2011	EP301	5		4	1			no
9/14/2011	EP292	3		3				no
9/13/2011	S2 Yard	10			10			no
9/13/2011	EP348	3		3				no
9/13/2011	EP345	2		2				no
9/13/2011	EP326	1					1	no
9/13/2011	EP325	2		2				no
9/13/2011	EP326	1		1				no
9/13/2011	EP304	7		7				no
9/13/2011	EP291	7		7				no
9/12/2011	S2 Yard	3			3			no
9/12/2011	EP350	1		1				no
9/12/2011	EP304	1		1				no
9/12/2011	EP301	1		1				no
9/11/2011	S2 Yard	2				2		no
9/10/2011	S2 Yard	2					2	no
9/9/2011	EP304	1			1			no
9/8/2011	S2 Yard	3					3	no
9/7/2011	S2 Yard	3					3	no
9/6/2011			No ravens	observed	ł			
9/5/2011			No ravens	observed	ł			
9/4/2011			No ravens	observed	ł			
9/3/2011			No ravens	observed	1			
9/2/2011	EP348	1		1				no
9/2/2011	S2 Yard	1		1				no
9/2/2011	EP303	1		1				no
9/2/2011	EP363	2		2				1 at IV Sub
9/1/2011	EP303	2					2	no
9/1/2011	EP293	1					1	no
9/1/2011	EP304	2					2	no
8/31/2011	S2 Yard	1		1				no
8/31/2011	EP308	1		1				no
8/31/2011	EP305-3	2					2	no
8/31/2011	EP303	2		2				no
8/30/2011	EP303	1		1				no
8/29/2011	S2 Yard	1		1				no
8/29/2011	EP303	1		1				no
8/28/2011			No ravens	observed				
8/27/2011	EP305	3			3			no
8/26/2011	EP301	2		2				no
8/25/2011	S2 Yard	2					2	no
8/25/2011	EP301	2		2				no
8/24/2011	S2 Yard	3				3		no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed				
		Observed	Nesting	Flying	Perching	Roosting	Scavaging					
8/23/2011	EP292-1	3		3				no				
8/22/2011	No ravens observed											
8/21/2011	No ravens observed											
8/20/2011	S2 Yard	2				2		no				
8/20/2011	EP312	2		2				no				
8/20/2011	S2 Yard	2					2	no				
8/20/2011	EP312	2		2				no				
8/19/2011	EP307	2			2			no				
8/19/2011	EP296	1		1				no				
8/18/2011	S2 Yard	2				1	1	no				
8/18/2011	EP301	Flock		Х				no				
8/17/2011	S2 Yard	2				1	1	no				
8/17/2011	EP301	3			3			no				
8/16/2011	S2 Yard	1					1	no				
8/16/2011	EP301	1		1				no				
8/15/2011	No ravens observed											
8/14/2011	No ravens observed											
8/13/2011	S2 Yard	2					2	no				
8/12/2011	IV Substation	2				2		no				
8/12/2011	S2 Yard	3				3	3	no				
8/11/2011	EP294	4			4			no				
8/11/2011	S2 Yard	3				3	3	no				
8/10/2011	S2 Yard	3				2	1	no				
8/9/2011	S2 Yard	not specified						no				
8/8/2011	EP294	2			2			no				
8/8/2011	S2 Yard	1						no				
8/7/2011		No ravens observed										
8/6/2011	S2 Yard	1						no				
8/5/2011	EP301	3		3				no				
8/4/2011	S2 Yard	not specified						no				
8/3/2011	S2 Yard	2		2				no				
8/3/2011	S2 Yard	1						no				
8/2/2011	S2 Yard	3					3	no				
8/1/2011	EP314	not specified		Х				no				
7/31/2011	No ravens observed											
7/30/2011	EP314	3		2			1	no				
7/30/2011	S2 Yard	1					1	no				
7/29/2011	S2 Yard	1						no				
7/28/2011	EP319	4	1	2	1			no				
7/28/2011	S2 Yard	not specified						no				
7/27/2011	S2 Yard	not specified						no				
7/26/2011			No ravens	observed								
7/25/2011	EP290	1			1			no				
7/24/2011	No ravens observed											
7/23/2011	No ravens observed											

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed	
			Nesting	Flying	Perching	Roosting	Scavaging		
7/22/2011	EP290	2		1	1			no	
7/21/2011	S2 Yard	1		1				no	
7/20/2011	Ocotillo, CA	5						no	
7/19/2011	Ocotillo, CA	1						no	
7/18/2011	CP40-2	not specified						no	
7/18/2011	CP41-2	not specified						no	
7/18/2011	CP42-1	not specified	<u> </u>	<u> </u>	<u> </u>			no	
7/17/2011		1	No ravens	observed	l I	ī			
7/16/2011	CP42-1	not specified	NI	-1				no	
7/15/2011	50057		No ravens	observed		I			
7/14/2011	EP357	not specified						no	
7/14/2011 7/14/2011	EP358 EP359	not specified not specified						no	
7/14/2011	Plaster City Yard	2		2				no	
7/13/2011	EP313-EP314 PS	not specified						no	
7/13/2011	S2 Yard	3					3	no no	
7/13/2011	CP18-1	not specified					3	no	
7/12/2011	CP19-1	not specified						no	
7/12/2011	CP22-1	not specified						no	
7/11/2011	EP304-EP314	not specified						no	
7/10/2011	2.00.2.02.		No ravens	observed					
7/9/2011	EP351	not specified						no	
7/9/2011	EP353	not specified						no	
7/9/2011	EP354	not specified						no	
7/9/2011	EP355	not specified						no	
7/9/2011	not specified	not specified						no	
7/9/2011	S2 Yard	3					3	no	
7/8/2011	EP303	2			1		1	no	
7/8/2011	EP303	1		1				no	
7/8/2011	S2 Yard	3					3	no	
7/1/11-7/7/11			No ravens	observed					
6/30/2011	EP300	3		3				no	
6/21/11-6/29/11			No ravens	observed	<u> </u>	T	ı		
6/20/2011	S2 Yard	2					2	no	
6/1/11-6/19/11			No ravens						
5/1/11-5/31/11	No ravens observed								
4/22/11-4/30/11	FD2.44		No ravens	observed		l l			
4/21/2011	EP341	1	1	observe:				no	
4/1/11-4/20/11	No ravens observed								
3/1/11-3/31/11	No ravens observed No ravens observed								
2/1/11-2/28/11	No ravens observed No ravens observed								
1/21/11-1/31/11	Pough Acros Vard	not specified	no ravens	observed				no	
1/21/2011	Rough Acres Yard	not specified]]	<u>I</u>	no	