



This report provides a summary of environmental monitoring and compliance activities conducted by Burns and McDonnell (BMcD) staff and BMcD subconsultants for the San Diego Gas & Electric (SDG&E) Sunrise Powerlink Project during the above weekly time period.

Training

- SWEAP and PBS training was held for new Project personnel on Tuesday. Additional trainings were provided as requested.
- Flat-tailed horned lizard (FTHL) trainings were provided to any new crew members or monitors prior to construction per mitigation measure B-7b and in accordance with the FTHL Rangewide Management Strategy. During morning tailboard meetings, guidelines were provided about recognizing, protecting, and notification requirements for FTHL. FTHL information cards were made available to any crew members or monitors as needed.

Pre/Post Construction

- Avian biologists surveyed for nesting birds prior to work commencing in inactive areas. For sites off of USFS lands, the results of those surveys were submitted to the CPUC/BLM biologist for review and concurrence. For USFS lands, the results of those surveys were submitted to the USFS for review and concurrence. For any active nests found, a buffer was established and no construction activities were permitted within the buffer area without consultation with the CPUC/BLM/USFS biologist. Active nests were mapped and monitored for success or failure and updated on the nest monitoring log.
- Post construction impact surveys occurred from EP324 to EP341, EP342 to EP363, and at Dunaway Road.
- Additional signs and stakes were repaired as needed. Due to traffic and narrow access roads, broken stakes and run over signs were replaced. Maintenance (e.g., writing over faded signs, reinforcing signs/stakes in the ground, replacing zip ties, and adding additional signs) was performed as needed. The ESA Team conducted the following activities during this reporting period:
 - Repaired, refreshed, replaced, and maintained the previously installed project signs and ESAs at the access road to Thing Valley, McCain Valley Road, EP205 access road to McCain Valley Road, access road to Wilson Yard, Thing Valley Yard, access road to EP90, and access road to Kreutzkamp.

Construction

- Monitors were present during construction activities to ensure compliance with mitigation measures as identified in the Final EIR/EIS Mitigation Monitoring, Compliance, and Reporting Program. Archaeologists, Paleontologists, and Native American Monitors were present at sites where required as identified prior to construction activity and as approved in the NTPs. On average, the following number of monitors were on the Project throughout the week:
 - 108 Biological monitors.
 - 1 Archaeological monitor.
 - 1 Native American monitor.
 - 8 SWPPP monitors.
- Project staff carpooled to site reviews, kick-off tailgates, and off-site meetings. Construction and traffic control crews were observed carpooling from yards to work areas.



Sunrise Powerlink Project
Weekly Report 89 – May 27, 2012 through June 02, 2012



- Deterrents were utilized to discourage bird nest building activities throughout the Project. Deterrents are determined depending upon the location and type of possible nesting areas and may include metallic flagging, compact discs, plastic owls, and the presence of biological monitors.
- The table below demonstrates the construction progress to date:

OVERHEAD					
Agency	Foundations Completed	Towers Erected	Wire Installed		
Non-Federal	169 of 169	169 of 169	156 of 169 EP104-2 to EP107-3		
Bureau of Land Management	179 of 179	179 of 179	152 of 179 EP101-2 to EP103A		
Miramar	14 of 14	14 of 14	14 of 14		
U.S. Forest Service	76 of 76	76 of 76	37 of 76 EP108-2 to EP113-5		
UNDERGROUND					
Agency	Vaults Installed	Trenches Excavated & Backfilled			
Non-Federal	40 of 40	42 of 42			
SUBSTATION UPGRADES					
4 of 7 Completed					
SUNCREST SUBSTATION					
100 Percent Complete					

Overhead Construction

- Link 1
 - Final grading from EP170 to EP177 (including pull sites), EP173-E, EP179 to EP182, EP235-N, EP236-N, EP240, and EP242 to EP246.
 - Fence work at EP215.
 - QA/QC from EP142-1 to EP152-2.
 - Work continued at EP215 regen site.
 - Marker balls hung from EP152-2 to EP170.
 - OPGW testing at EP170 and EP215.
 - BMP maintenance at EP172 to EP174, EP186-1 to EP190-2, EP192-2, EP192-2 pull site, EP193-2 pull site, EP194-3 to EP215, EP221-2, EP221A, EP223-1, EP224-1, EP226-1 pull site to EP228, GS-BLM-1, and GS-NF-33.
 - Hydromulching at EP144 to EP146, EP188-1, EP231-1, EP231A, and EP243.



- Link 2

- During this reporting period, the PAL levels were as follows: Tuesday-Ev, Wednesday-D, Thursday-Ev, Friday-Ev, and Saturday-C. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

USFS Land

- Arroyo toad fence repairs made at EP76-2-E.
- Fence grounding at EP12-3, EP13-3, EP35-1, and EP36-1.
- Micropile capping work at EP18-1 and EP108-2 to EP111-4.
- Tower assembly at EP14-1, EP17 to EP21-1, EP36-1, EP57-1, EP58-2, EP108-2 to EP112-3, EP113-5 pull sites, and EP114-2 to EP122.
- Miscellaneous tower work at EP9-1 to EP12-3, EP22-1 to EP24-1, EP110-2, EP111-4, and EP114-2 to EP116-1.
- QA/QC at EP20-2, EP24-1, EP108-2, EP112-3, and EP113-5.
- Ground resistance testing at EP17, EP18-1, EP115-1 to EP117-2, EP120-4, and EP120A.
- OPGW sock line flown from EP9-1 to EP12-3.
- Hardline and conductor pulled from EP30-2 to EP42.
- Conductor pulling continued from EP125 to EP130-1.
- Sagging at EP30-2 to EP42, EP108-2, EP112A-1, and EP125 to EP130-1.
- Sagging, clipping in, dead-end, and spacing work from EP125 to EP131.
- Clipping in and dead-end work from EP30-2 to EP42 and EP125 to EP130-1.
- Dampener work from EP9-1 to EP12-3.
- Jumper work at EP30-2 to EP42, and EP112-3.
- Spacers installed at EP108-2, EP113-5, and EP125 to EP130-1.
- Marker ball installation from EP9-1 to EP12-3.
- BMP maintenance at EP5-2 to EP12-3 (including pull sites), EP15, EP16-1, EP19-1, EP20-2, EP22-1 to EP24-1 (including pull sites), EP29-2, EP108-2 to EP112A, EP114-2, EP117-2, EP120-4 to EP124, EP125-E-A to EP141-E-B, EP140-1, EP141, GS-USFS-2, GS-USFS-3, and GS-USFS-4.
- Hydromulching at EP143-1.

BLM Land

- Arroyo toad fence repairs made at EP76-2-E.
- Micropile capping work at EP53-2.
- Tower assembly at EP50, EP51-1, EP53-2, EP56-4, and EP69.
- Miscellaneous tower work at EP47-2, EP50, EP53-2, EP73-1 to EP76-2, EP102-3, and EP102A-1.
- QA/QC at EP94 to EP99-2 and EP103-2.
- Ground rod installation at EP48 and EP53-2.
- Hardline and conductor pulled from EP30-2 to EP42.
- Sock line, haulback, and conductor pulled from EP67 to EP78.
- Wire prep from EP70 to EP76-2.
- Sock line pulled from EP70 to EP76-2.
- OPGW flown from EP70 to EP76-2.
- Traveler work at/from EP67 to EP78.
- Sagging and clipping from EP30-2 to EP42 and EP67 to EP78.
- Dead-end work from EP30-2 to EP42.
- Jumper work from EP30-2 to EP42 and EP70 to EP78.
- Clipping in from EP30-2 to EP42 and EP70 to EP78.
- Spacers installed from EP99-2 to EP102-3.



Sunrise Powerlink Project
Weekly Report 89 – May 27, 2012 through June 02, 2012



- BMP installation/maintenance at EP47-2, EP47-2 pull site, EP48, EP50, EP63, EP71 to EP76-2, EP94 to EP99-2, EP103-2, and EP103A.
- Hydromulching at EP101-2, EP102-3, and EP102A-1.

Non-Federal Land

- Arroyo toad fence repairs made at EP76-2-E.
- Tower assembly at/from EP52-1, EP62A-1, EP66, EP67, and EP119-2.
- Miscellaneous tower work at EP26-1, EP31-1, EP52-1, EP77, EP80 to EP82, and EP86-1 to EP88-2.
- QA/QC at EP77, EP80 to EP89-1, EP91 to EP93, and EP119-2.
- Ground rod installation from EP65-1 to EP67.
- Regen work continued near EP54-1.
- Haulback and conductor pulled from EP67 to EP78.
- Hardline and conductor pulled from EP30-2 to EP42.
- OPGW flown from EP67 to EP78.
- OPGW work at EP32-1 and EP67 to EP78.
- Traveler work at EP67 to EP78.
- Sagging and clipping in at EP30-2 to EP42 and EP67 to EP78.
- Jumper work at EP30-2 to EP42, EP67 to EP78, and EP106-3.
- Dead-end work from EP30-2 to EP42.
- BMP installation/maintenance at EP1-3, EP25-1, EP26-1, EP27-1, EP31-1, EP52-1, EP54-1, EP62A-1, EP67 pull sites, EP78 to EP79, EP104-1, EP105-2, EP119-2, GS-NF-14, GS-NF-17, GS-NF-21, and GS-NF-22.
- Hydromulching at EP83 pull sites, EP86-1, and EP88-2.

• **Link 5**

- During this reporting period, the PAL levels were as follows: Tuesday-Ev, Wednesday-D, Thursday-Ev, Friday-Ev, and Saturday-C. Work activities ended each day in accordance with the fire plan and the approved Ev letter as appropriate.

USFS Land

- Miscellaneous tower work at CP69-2 and CP105-1.
- Ground resistance testing at CP103-2 and CP104-1.
- Spacer and jumper work at CP69-2.
- BMP maintenance at CP99-2, CP100-1, and CP105-1.
- BMP removal at CP99-2, CP100-1, and CP100-1-N.

BLM Land

- BMP maintenance at CP59.

Non-Federal Land

- Rock stabilization at CP47A-1.
- Miscellaneous tower work at CP70-3, CP71, CP87-1, CP88, CP95-1, CP96-1, and CP106-1.
- BMP installation and maintenance at CP18-1, CP19-1, CP29-1, CP31-2, CP31-2 pull sites, CP39 to CP44-1 (including guard structure), CP44-1, CP49-1 pull site, CP54-1, CP55 pull site, CP72-1, CP73-2, CP75-1 pull sites, CP98-1, GS-NF-1, and GS-NF-8.
- BMP removal at CP98-N-B, CP98-1, CP99-N, and CP100-1-N.
- Restoration at CP43-1 pull sites, CP43-1 wash station, CP49-1-PS-N, and CP49-1 pull site.



Miramar

- Final grade and restoration at CP6-1, CP7, and CP10.
- Equipment demobed from CP6-1.
- Grounding at CP8-2.
- BMP installation and maintenance at CP2, CP3, CP3 pull site, CP8-2, CP12-1, CP14, and CP15-1.

Underground Construction (Link 4)

- Revitalization – Alpine Blvd.
- Splicing inside V20R.
- Installing lightning arresters and jumpers on CP96 at Loritz property.
- UPC working at Loritz/Slay properties.
- Cleanup activities at the bore site.
- Backfilling at the bore pit on the north side of I-8.
- Splicing inside Vault 1.
- Cooling system work – Bore Site.
- Testing setup at Loritz property.
- Asphalt striping along Alpine Blvd.
- Work inside Vault 20.

Suncrest Substation Construction (Link 3)

- Work inside the control shelter.
- Beta crew working on removing the skirting and decking from the office trailers.
- SDG&E crew working on the transformers.
- Removing office trailers from the site.
- Pinnick/Marina working on irrigation system and slope repair.
- SDG&E synchronizing disconnect switches.

Substation Upgrades

San Luis Rey:

- Bird sweeps/surveys are ongoing to identify and deter nest building.
- Switching leads on transformers.

Encina:

- SDG&E relay and wiring crews performing wiring near the control house.

Scripps:

- No Sunrise-related work.

Pomerado:

- No Sunrise-related work.

Sycamore:

- On-going bird sweeps/surveys ahead of planned work for the following week.

Construction Yards

- Sycamore Yard – Occasional helicopter operations and staging for road crews.
- Helix Yard – Occasional helicopter operations and staging for QC, assembly, and BMP crews.



- El Monte Yard – No activity.
- Alpine Yard – Hub for equipment/materials staging, weed wash station, vegetation maintenance and staging for QC, gate, habitat assessment, BMP, regen, and road crews.
- Wilson Yard – Intermittent helicopter operations and staging for QC crews.
- SWAT Yard – Frequent helicopter operations, weed wash station, and staging for assembly, erection, wire, grout, and QC crews.
- Barrett Canyon Yard – No activity.
- Kreutzkamp Yard – Intermittent helicopter operations, weed wash station, and staging for erection and regen crews.
- Bartlett Hauser Yard – Frequent helicopter operations, weed wash station, and staging for wire, QC, road, micropile, hydromulch, grout, erection, and BMP crews.
- Thing Valley Yard – Occasional helicopter operations and staging for assembly, hydromulch, BMP, erection, wire, and QC crews.
- McCain Valley Yard – Intermittent helicopter operations. Various crews staging out of Rough Acres also use this yard for materials.
- Rough Acres Yard – Frequent helicopter operations, material hauling and staging, weed wash station, and staging for road, BMP, QC, erection, and wire crews.
- Jacumba Valley Ranch (JVR) Yard – Occasional helicopter operations, weed wash station, and staging for hydromulch and habitat assessment crews.

NOTE: In addition, all active yards typically have miscellaneous activities throughout the day such as materials delivery and staging, equipment mobilization/demobilization, water supply and dust control, and porta-potty maintenance.

Wildlife Reporting

The following listed or Species of Special Concern were found dead in Project construction limits during this reporting period:

- Coast Horned Lizard (*Phrynosoma coronatum blainvillii*) – One (1) coast horned lizard was found dead east of Alpine, south of I-8, and west of Hwy 79.

The following listed or Species of Special Concern were relocated during construction activities this reporting period:

- Coast Horned Lizard (*Phrynosoma coronatum blainvillii*) – Two (2) coast horned lizards were relocated; (1) one from EP117-3 and (1) one from Thing Valley Construction Yard.
- California Legless Lizard (*Anniella pulchra*) – Four (4) California legless lizards were relocated from McCain Valley Road on access road between SRPL structures EP171 and EP172.
- Coronado Skink (*Plestiodon skiltonianus interparietalis*) – Eight (8) Coronado skinks were relocated from McCain Valley Road on access road between SRPL structures EP171 and EP172.
- Two-striped Garter Snake (*Thamnophis hammondii*) – One (1) two-striped garter snake was relocated from Kreutzkamp Yard.

Spills/Hazardous Waste

- Access Road to Kreutzkamp Yard – A PAR street sweeper released approximately 15 gallons of hydraulic oil due to a broken hose. The hydraulic hose used to control the cleaning brushes failed and leaked the entire tank, approximately 15 gallons of hydraulic oil. Most of the spill was along the approved asphalt roadway, a few gallons infiltrated the adjacent dirt road and no sensitive



Sunrise Powerlink Project
Weekly Report 89 – May 27, 2012 through June 02, 2012



resources or waterways were affected. Geosyntec HazMat monitors were notified and facilitated the cleanup. PAR's environmental crew and an SDG&E environmental spill representative handled the clean-up. The spill was not near any jurisdictional waters.

Customer Complaints

- A customer complaint was received on May 31, 2012, regarding helicopters flying over a customer's property and an aircraft dropping streaming liquid. Sunrise Flight Operations conducted an investigation into the allegations and found that one aircraft did fly into SDG&E's self-imposed no-fly area on May 30. The investigation into the streaming liquid concluded that it was water utilized for dust suppression activities. All SDG&E and contracted pilots have been advised to honor the no-fly area and to stay as far away from the property as safely possible while conducting the remainder of construction activities. Public Affairs responded to the customer's email and explained the findings of the investigation and informed them of SDG&E's actions. No further action is required at this time.

Non-Compliances

- No non-compliances were received during this reporting period.

Variances and TEWS

- TEWS #38 was approved on May 29, 2012, for extra work space at EP119.

Weather

- No rain events occurred during this reporting period.
- BMPs were installed or maintained as needed throughout Project areas. In accordance with the Construction General Permit (CGP), daily site BMP inspections, and photos, appropriate BMPs for stormwater and non-stormwater were implemented. Any sites requiring repairs began within 72 hours of identification.

Appendices

Flat-Tailed Horned Lizard Monitoring Report

Raven Control Monitoring Report

Flat Tailed Horned Lizard Counts - Week Ending 06/02/2012									
Date	Location	Observed		Injured		Relocated		Dead	
	Post RCLMP*	Day	Night	Day	Night	Day	Night	Day	Night
5/7/2012	AR btwn EP321 and EP320							1	
4/18/2012	AR btwn EP354-N and EP354	1							
2/23/2012	West side of AR to EP324	1							
11/1/2011	Dunaway CY				1				
10/13/2011	AR to EP354							1	
9/20/2011	AR btwn EP357 and EP358							1	
9/19/2011	AR btwn EP352 and EP353	1							
9/12/2011	EP325					1			
9/9/2011	AR to EP363	1							
9/6/2011	AR to EP360/361				1				
9/6/2011	EP360					2			
9/6/2011	EP359					1			
9/3/2011	SWPL AR to EP324					1			
9/3/2011	SWPL AR to EP342					1			
9/3/2011	SWPL AR to EP345							1	
9/3/2011	SWPL AR to EP344 and EP345					1			
8/31/2011	EP324					1			
8/31/2011	SWPL AR to EP325-2					1			
8/30/2011	SWPL AR to EP346 and EP347					1			
8/29/2011	SWPL AR to EP353 and EP354							1	
8/29/2011	SWPL AR to EP324							1	
8/27/2011	EP349					1			
8/25/2011	EP360							1	
8/25/2011	Btwn EP320/321					1			
8/24/2011	SWPL AR near EP346					1			
8/23/2011	EP349					1			
8/21/2011	SWPL AR btwn EP344/345					1			
8/21/2011	SWPL AR to EP345							1	
8/19/2011	SWPL AR to EP339					1			
8/20/2011	SWPL AR to IV Sub							1	
8/20/2011	SWPL AR btwn EP346/347					1			
8/19/2011	EP338/339 Pullsite					1			
8/19/2011	EP355/356 Pullsite					1			
8/18/2011	EP347					1			
8/18/2011	SWPL AR to EP353							1	
8/11/2011	SWPL AR by EP348					1			
8/11/2011	EP348/EP349 Pullsite					1			
8/10/2011	EP347					1			
8/8/2011	SWPL AR to EP351					2			
8/6/2011	BLM AR near EP327							1	
8/1/2011	IV Substation Yard	1							
8/1/2011	EP325					1			
8/1/2011	AR to EP345					1			

Flat Tailed Horned Lizard Counts - Week Ending 06/02/2012								
Date	Location	Observed		Injured		Relocated		Dead
7/30/2011	EP322					1		
7/28/2011	EP355/EP356 Pullsite					1		
7/27/2011	Near EP316-2	1						
7/26/2011	SWPL AR to EP344	1						
Post RCLMP*		Day	Night	Day	Night	Day	Night	Day
7/26/2011	EP347					1		
7/26/2011	AR to IV Sub					1		
7/25/2011	AR to IV Sub					1		
7/25/2011	AR to IV Sub					1		
7/25/2011	AR to IV Sub					1		
7/22/2011	AR to IV Sub					1		
7/21/2011	EP360					1		
7/21/2011	AR to EP326					1		
7/19/2011	SWPL AR to IV Sub	1						
7/19/2011	EP353					1		
7/19/2011	AR to Dunaway CY					1		
7/18/2011	EP318					1		
7/17/2011	EP355					1		
7/15/2011	EP359	1						
7/15/2011	EP352	1						
7/15/2011	EP350	1						
7/14/2011	Spur Rd to EP355							1
7/14/2011	EP322	1						
7/13/2011	EP357	1						
7/12/2011	EP344	1						
7/12/2011	SWPL AR btwn EP348/345							1
TOTAL POST RCLMP		14	0	0	0	43	0	13
Prior to RCLMP		Day	Day	Day	Day			
7/11/2011	AR to EP352					2		
7/11/2011	AR to EP345					2		
7/10/2011	EP358					1		
7/10/2011	SWPL AR to EP354					2		
7/9/2011	AR to EP330	1						
7/8/2011	Spur Rd. to EP352	1						
7/7/2011	EP324					1		
7/7/2011	EP355					1		
7/6/2011	SWPL AR btwn EP362/363							1
7/5/2011	EP354					1		
7/1/2011	AR to EP353	1						
6/30/2011	AR between EP310/311							1
6/30/2011	EP358	1						
6/30/2011	EP360	1						
6/30/2011	AR to EP312							1

Flat Tailed Horned Lizard Counts - Week Ending 06/02/2012					
Date	Location	Observed	Injured	Relocated	Dead
6/30/2011	EP360				1
6/27/2011	EP350			1	
6/27/2011	SWPL AR to IV Substation	2			
6/26/2011	IV Substation			1	
6/25/2011	SWPL AR to EP361	1			
6/24/2011	EP359			1	
6/23/2011	SWPL AR to EP360			2	
6/22/2011	SWPL AR to EP355			1	
6/20/2011	EP356	2			
6/20/2011	SWPL AR to EP359	1			
6/20/2011	Near EP356	2			
6/20/2011	AR between EP358/357				1
6/18/2011	AR to Dunaway CY				1
6/17/2011	Near EP322	1			
6/7/2011	Near EP355	1			
6/7/2011	EP361			1	
6/7/2011	AR btwn EP343/EP344				1
6/7/2011	AR between EP324/325				1
6/6/2011	SWPL AR btwn EP344/EP345			1	
6/3/2011	EP359			1	
6/3/2011	SWPL AR EP362			1	
6/2/2011	AR to EP358			1	
6/2/2011	SWPL AR to EP316-2				1
6/2/2011	AR east of EP325				1
6/1/2011	SWPL AR btwn EP319/EP320			1	
6/1/2011	SWPL AR to EP318			1	
5/31/2011	SWPL AR btwn EP359/EP360			1	
5/31/2011	SWPL AR to EP320			1	
5/31/2011	EP360				1
5/27/2011	EP357			1	
5/26/2011	SWPL AR to EP359			1	
5/25/2011	Spur Rd to EP321			1	
5/23/2011	EP323			1	
5/21/2011	EP324			1	
5/20/2011	IV CY			1	
5/20/2011	AR to EP362			1	
5/20/2011	AR btwn EP324/EP325			1	
5/20/2011	SWPL AR btwn EP326/EP327			1	
5/20/2011	IV Substation			3	
5/19/2011	IV Substation			5	
5/19/2011	EP324			1	
5/18/2011	IV Substation Yard			1	
5/18/2011	IV Substation Yard				1

Flat Tailed Horned Lizard Counts - Week Ending 06/02/2012					
Date	Location	Observed	Injured	Relocated	Dead
5/17/2011	AR to IV Substation				1
5/16/2011	IV Substation Yard			1	
5/13/2011	SWPL AR Near EP362-1	1			
5/12/2011	AR to EP355			1	
5/11/2011	EP360	1			
5/11/2011	Dunaway CY	3			
5/11/2011	Dunaway Yard			4	
5/10/2011	EP322	1			
5/10/2011	AR to Dunaway CY	1			
5/9/2011	Dunaway Yard			4	
5/7/2011	EP322	1			
5/7/2011	Spur Road to EP344	1			
5/7/2011	Dunaway Yard			1	
5/6/2011	AR to EP321-1	1			
5/5/2011	AR to EP321-1	1			
5/5/2011	AR to Dunaway CY	2			
5/5/2011	Dunaway Yard			2	
5/4/2011	AR btwn EP343/EP344			1	
5/3/2011	SWPL AR btwn EP320/EP321	1			
4/27/2011	AR to EP322	2			
4/26/2011	EP322	1			
4/25/2011	Plaster City CY	1			
4/20/2011	Plaster City			1	
4/18/2011	Plaster City			1	
4/14/2011	AR to IV Substation	1			
4/2/2011	Dunaway CY	1			
TOTAL PRIOR TO RCLMP		35	0	60	13
YTD		49	0	103	26

*RCLMP refers to the Revised Construction Lighting Mitigation Plan

Raven Control Monitoring Report - Week Ending 06/02/2012							
Date	Location	Number of Ravens observed	Raven Activity				
			Nesting	Flying	Perching	Roosting	Scavaging
6/2/2012			No ravens observed				
6/1/2012			No ravens observed				
5/31/2012			No ravens observed				
5/30/2012			No ravens observed				
5/29/2012			No ravens observed				
5/28/2012			No ravens observed				
5/27/2012			No ravens observed				
5/26/2012			No ravens observed				
5/25/2012			No ravens observed				
5/24/2012			No ravens observed				
5/23/2012			No ravens observed				
5/22/2012			No ravens observed				
5/21/2012			No ravens observed				
5/20/2012			No ravens observed				
5/19/2012			No ravens observed				
5/18/2012			No ravens observed				
5/17/2012			No ravens observed				
5/16/2012			No ravens observed				
5/15/2012			No ravens observed				
5/14/2012			No ravens observed				
5/13/2012			No ravens observed				
5/12/2012	EP355/356 SWPL line and EP348	3		1	2		no
5/11/2012			No ravens observed				
5/10/2012			No ravens observed				
5/9/2012			No ravens observed				
5/8/2012			No ravens observed				
5/7/2012			No ravens observed				
5/6/2012			No ravens observed				
5/5/2012			No ravens observed				
5/4/2012			No ravens observed				
5/3/2012			No ravens observed				
5/2/2012			No ravens observed				
5/1/2012			No ravens observed				
4/30/2012			No ravens observed				
4/29/2012			No ravens observed				
4/28/2012			No ravens observed				
4/27/2012	EP314 Pullsite	1		1			no
4/26/2012			No ravens observed				
4/25/2012			No ravens observed				
4/24/2012			No ravens observed				
4/23/2012	EP348/EP349 Pullsite	1		1			no
4/22/2012			No ravens observed				
4/21/2012			No ravens observed				
4/20/2012	EP348/EP349 Pullsite	1			1		no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed	
			Nesting	Flying	Perching	Roosting	Scavaging		
4/19/2012			No ravens observed						
4/18/2012			No ravens observed						
4/17/2012			No ravens observed						
4/16/2012			No ravens observed						
4/15/2012			No ravens observed						
4/14/2012			No ravens observed						
4/13/2012			No ravens observed						
4/12/2012			No ravens observed						
4/11/2012			No ravens observed						
4/10/2012			No ravens observed						
4/9/2012			No ravens observed						
4/8/2012			No ravens observed						
4/7/2012			No ravens observed						
4/6/2012			No ravens observed						
4/5/2012			No ravens observed						
4/4/2012			No ravens observed						
4/3/2012			No ravens observed						
4/2/2012	S2 Yard	1		1				no	
4/1/2012			No ravens observed						
3/31/2012			No ravens observed						
3/30/2012			No ravens observed						
3/29/2012			No ravens observed						
3/28/2012			No ravens observed						
3/27/2012			No ravens observed						
3/26/2012			No ravens observed						
3/25/2012			No ravens observed						
3/24/2012			No ravens observed						
3/23/2012			No ravens observed						
3/22/2012			No ravens observed						
3/21/2012	Plaster City Yard	2			2			no	
3/20/2012			No ravens observed						
3/19/2012			No ravens observed						
3/18/2012			No ravens observed						
3/17/2012			No ravens observed						
3/16/2012	EP363	1			1			no	
3/15/2012			No ravens observed						
3/14/2012			No ravens observed						
3/13/2012	Plaster City Yard	6		4			2	no	
3/12/2012	Plaster City Yard	5		2			3	no	
3/11/2012			No ravens observed						
3/10/2012			No ravens observed						
3/9/2012			No ravens observed						
3/8/2012	Plaster City Yard	3		2			1	no	
3/8/2012	EP326	2		2				no	
3/7/2012	Plaster City Yard	1			1			no	
3/6/2012	EP350	1			1			no	

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed	
			Nesting	Flying	Perching	Roosting	Scavaging		
3/5/2012			No ravens observed						
3/4/2012			No ravens observed						
3/3/2012			No ravens observed						
3/2/2012	EP352	2			2			no	
3/2/2012	Plaster City Yard	1					1	no	
3/2/2012	EP357	2		2				no	
3/1/2012			No ravens observed						
2/29/2012	EP359-EP362	5		5				no	
2/28/2012	EP357 and EP359	3			3			no	
2/28/2012	EP349	2	2					no	
2/27/2012			No ravens observed						
2/26/2012	EP351	1			1			no	
2/25/2012			No ravens observed						
2/24/2012	EP355	3		3				no	
2/23/2012	EP355	1		1				no	
2/22/2012	EP347	2		2				no	
2/22/2012	EP343/EP344 Pullsite	2					2	no	
2/21/2012			No ravens observed						
2/20/2012	EP313-EP354	2		2				no	
2/19/2012	EP360-EP362	2		2				no	
2/18/2012			No ravens observed						
2/17/2012			No ravens observed						
2/16/2012	S2 Yard	3		3				no	
2/15/2012	S2 Yard	5		5				no	
2/14/2012	S2 Yard	2		2				no	
2/13/2012			No ravens observed						
2/12/2012			No ravens observed						
2/11/2012			No ravens observed						
2/10/2012			No ravens observed						
2/9/2012	S2 Yard	2		2				no	
2/8/2012	S2 Yard	3		2			1	no	
2/7/2012	S2 Yard	3		2			1	no	
2/6/2012	S2 Yard	3		2			1	no	
2/5/2012			No ravens observed						
2/4/2012	S2 Yard	2			2			no	
2/3/2012			No ravens observed						
2/2/2012	Pull site EP338/EP339	2			2			no	
2/2/2012	S2 Yard	1		1				no	
2/1/2012	Pull site EP338/EP339	3		3				no	
1/31/2012	EP330	2		2				no	
1/30/2012			No ravens observed						
1/29/2012			No ravens observed						
1/28/2012			No ravens observed						
1/27/2012	Plaster City Yard	2					2	no	
1/26/2012	S2 Yard	2		2				no	
1/26/2012	EP341	2			2			no	

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
1/26/2012	EP316	2		2				no
1/25/2012	EP324	1		1				no
1/24/2012	No ravens observed							
1/23/2012	No ravens observed							
1/22/2012	No ravens observed							
1/21/2012	No ravens observed							
1/20/2012	No ravens observed							
1/19/2012	EP326-EP328	2		2				no
1/18/2012	EP334	1		1				no
1/17/2012	EP329-1	2			2			no
1/16/2012	No ravens observed							
1/15/2012	No ravens observed							
1/14/2012	No ravens observed							
1/13/2012	No ravens observed							
1/12/2012	No ravens observed							
1/11/2012	No ravens observed							
1/10/2012	No ravens observed							
1/9/2012	No ravens observed							
1/8/2012	No ravens observed							
1/7/2012	No ravens observed							
1/6/2012	No ravens observed							
1/5/2012	No ravens observed							
1/4/2012	No ravens observed							
1/3/2012	No ravens observed							
1/2/2012	No ravens observed							
1/1/2012	No ravens observed							
12/31/2011	No ravens observed							
12/30/2011	No ravens observed							
12/29/2011	EP313-EP304 & EP295-EP292	2			2			no
12/28/2011	EP294	20			20			no
12/27/2011	EP292	2			2			
12/26/2011	EP292	2					2	no
12/25/2011	No ravens observed							
12/24/2011	EP281, EP281GS & EP290	5		5				no
12/23/2011	No ravens observed							
12/22/2011	EP300-1, EP301 & EP304	3		3				no
12/21/2011	No ravens observed							
12/20/2011	EP290-EP291/EP292 Pullsite	2			2			no
12/19/2011	No ravens observed							
12/18/2011	No ravens observed							
12/17/2011	EP325	1		1				no
12/17/2011	S2 Yard	3					3	no
12/16/2011	No ravens observed							
12/15/2011	IV Substation	1			1			no
12/15/2011	EP293	2		2				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
12/15/2011	S2 Yard	3					3	no
12/14/2011	S2 Yard	3					3	no
12/13/2011	S2 Yard	2					2	no
12/12/2011	S2 Yard	2					2	no
12/11/2011	S2 Yard	2					2	no
12/10/2011	EP306 & EP306/EP307 Pullsite	3		3				no
12/9/2011	IV Substation	1		1				no
12/9/2011	EP308 &EP306/EP307 Pullsite	2		2				no
12/9/2011	EP291 & EP291/EP292 Pullsite	2		2				no
12/8/2011	S2 Yard	3					3	no
12/8/2011	IV Substation	1		1				no
12/8/2011	EP301	2		2				no
12/8/2011	EP300-EP309	2		2				no
12/8/2011	EP291/EP292 Pullsite	2	2					no
12/8/2011	EP281	2		2				no
12/7/2011	IV Substation	1		1				no
12/7/2011	EP301	1			1			no
12/7/2011	EP291/EP292 Pullsite	1			1			no
12/7/2011	EP281	7		4	2	1		no
12/7/2011	S2 Yard	2			2			no
12/6/2011	S2 Yard	3				3		no
12/6/2011	EP301	2			2			no
12/6/2011	EP281	5		4		1		no
12/5/2011	S2 Yard	2					2	no
12/5/2011	IV Substation	2		2				no
12/5/2011	EP363	2		2				no
12/5/2011	EP281	6		6				no
12/4/2011	S2 Yard	3				3		no
12/4/2011	IV Substation	2		2				no
12/4/2011	Fromm CY	2				1	1	no
12/4/2011	EP294	1		1				no
12/3/2011	EP281	1		1				no
12/2/2011	IV Substation	1		1				no
12/1/2011	S2 Yard	2					2	no
11/30/2011	S2 Yard	2			2			no
11/29/2011	S2 Yard	2			2			no
11/28/2011	S2 Yard	4			4			no
11/28/2011	EP290-EP301	5		2	3			no
11/27/2011	S2 Yard	1		1				no
11/26/2011	No ravens observed							
11/25/2011	NO WORK: DAY AFTER THANKSGIVING							
11/24/2011	NO WORK: THANKSGIVING							
11/23/2011	Plaster City Yard	3					3	no
11/22/2011	S2 Yard	4			4			no
11/22/2011	IV Substation	1			1			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
11/21/2011	S2 Yard	4					4	no
11/21/2011	IV Substation	1		1				no
11/21/2011	EP281	2			2			no
11/20/2011	EP360	2			2			no
11/20/2011	IV Substation	2		2				no
11/19/2011	No ravens observed							
11/18/2011	EP358 and IV Substation	2		2				no
11/17/2011	No ravens observed							
11/16/2011	S2 Yard	5			5			no
11/15/2011	EP330-1	2					2	no
11/15/2011	EP304; EP330	1			1			no
11/14/2011	S2 Yard	6			6			no
11/13/2011	No ravens observed							
11/12/2011	Dunaway CY	1			1			no
11/11/2011	Dunaway CY	4					4	no
11/11/2011	S2 Yard	5					5	no
11/10/2011	Fromm CY	2					2	no
11/10/2011	EP355	1		1				no
11/9/2011	Dunaway CY	1			1			no
11/8/2011	S2 Yard	5			5			no
11/8/2011	Dunaway CY	2			2			no
11/7/2011	S2 Yard	3					3	no
11/7/2011	EP308-EP310	1					1	no
11/7/2011	EP301 Pullsite	7		6	1			no
11/6/2011	No ravens observed							
11/5/2011	S2 Yard	7			7			no
11/5/2011	IV Substation	1			1			no
11/4/2011	S2 Yard	5			5			no
11/3/2011	S2 Yard	5			3		2	no
11/3/2011	IV Substation	1			1			no
11/3/2011	Fromm CY	1				1		no
11/3/2011	EP303 and EP302	2			2			no
11/3/2011	EP281	2			2			no
11/2/2011	S2 Yard	4			4			no
11/2/2011	IV Substation	1		1				no
11/2/2011	EP305, EP310, EP311	1		1				no
11/1/2011	S2 Yard	2			2			no
11/1/2011	IV Substation	1		1				no
11/1/2011	EP305 and EP312	1			1			no
10/31/2011	S2 Yard	5			5			no
10/31/2011	AER and Fromm CY	1				1		no
10/30/2011	No ravens observed							
10/29/2011	IV Substation	3		3				no
10/28/2011	IV Substation	1		1				no
10/28/2011	EP256, EP357 & EP358	5		5				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
10/27/2011	EP356, EP358 & EP362	2		2				no
10/27/2011	EP305, EP307, EP310-EP312	1		1				no
10/26/2011	EP306, EP307 & EP310	2		2				no
10/25/2011	IV Substation	1		1				no
10/25/2011	EP310	1		1				no
10/24/2011	S2 Yard	3					3	no
10/24/2011	EP305	1			1			no
10/23/2011	S2 Yard	3			3			no
10/22/2011	No ravens observed							
10/21/2011	Dunaway CY	1			1			no
10/20/2011	S2 Yard	2					2	no
10/20/2011	Dunaway CY	5					5	no
10/19/2011	EP314	1		1				no
10/19/2011	EP290	5		5				no
10/18/2011	No ravens observed							
10/17/2011	EP301	3		3				no
10/16/2011	No ravens observed							
10/15/2011	S2 Yard	2					2	no
10/15/2011	Dunaway CY	1				1		no
10/15/2011	EP315	2					2	no
10/15/2011	EP301	3			3			no
10/14/2011	Fromm CY	3				3		no
10/14/2011	EP305	2		2				no
10/14/2011	EP301	3			3			no
10/13/2011	S2 Yard	2					2	no
10/13/2011	Dunaway CY	5					5	no
10/13/2011	Fromm CY	1					1	no
10/13/2011	EP354-EP363	2			2			no
10/13/2011	EP301	4		4				no
10/12/2011	EP300-EP301	2		2				no
10/11/2011	Plaster City Yard	2			2			no
10/11/2011	IV Substation	2					2	no
10/10/2011	Fromm CY	2				2		no
10/10/2011	EP359-EP360	2		2				no
10/10/2011	EP355-EP363	2		2				no
10/10/2011	EP301	3		3				no
10/9/2011	S2 Yard	3					3	no
10/9/2011	EP300	6		6				no
10/8/2011	EP357	2			2			no
10/8/2011	EP306	3					3	no
10/7/2011	Dunaway CY	1		1				no
10/7/2011	EP291-EP301	3		3				no
10/6/2011	Fromm CY	2					2	no
10/5/2011	Dunaway CY	2		2				no
10/5/2011	EP303-2	2		2				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
10/4/2011	EP310 & EP311	2		2				no
10/4/2011	EP301	3					3	no
10/4/2011	EP293	2		2				no
10/3/2011	S2 Yard	2					2	no
10/3/2011	Dunaway CY	2			2			no
10/2/2011	EP356-EP363	2		1	1			no
10/1/2011	Plaster City Yard	2					2	no
10/1/2011	EP360	2			2			no
9/30/2011	S2 Yard	2					2	no
9/30/2011	EP355	1		1				no
9/30/2011	EP314	2		2				no
9/30/2011	EP301	2		1	1			no
9/29/2011	EP291/EP292 Pullsite	1			1			no
9/28/2011	EP361	1			1			no
9/27/2011	EP315	2		1	1			no
9/27/2011	EP309	1		1				no
9/27/2011	EP301 & EP304	4		3	1			no
9/27/2011	EP290	1			1			no
9/26/2011	EP362	2			2			no
9/26/2011	Fromm CY	1				1		no
9/25/2011	No ravens observed							
9/24/2011	Plaster City Yard	2					2	no
9/24/2011	EP317	1		1				no
9/24/2011	EP309	1		1				no
9/23/2011	EP362	4			4			no
9/23/2011	EP303	2		2				no
9/22/2011	Fromm CY	1				1		no
9/22/2011	EP303	2		2				no
9/22/2011	EP301	2		2				no
9/22/2011	EP295-EP322	3		3				no
9/21/2011	S2 Yard	3			3			no
9/21/2011	Fromm CY	1					1	no
9/21/2011	EP303	1		1				no
9/20/2011	S2 Yard	2			2			no
9/20/2011	Fromm CY	1				1		no
9/19/2011	S2 Yard	3			3			no
9/19/2011	EP304, EP307, EP309	1		1				no
9/18/2011	S2 Yard	3				3		no
9/18/2011	EP281	1		1				no
9/17/2011	S2 Yard	3					3	no
9/17/2011	EP362	1			1			no
9/17/2011	Fromm CY	3				3		no
9/16/2011	EP363	2			2			no
9/16/2011	Fromm CY	1					1	no
9/16/2011	EP304	2		2				no
9/16/2011	EP290	1		1				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
9/15/2011	S2 Yard	4			4			no
9/15/2011	Fromm CY	3					3	no
9/15/2011	EP296	1		1				no
9/15/2011	EP306	2					2	no
9/15/2011	EP304	1		1				no
9/15/2011	EP301	2		2				no
9/14/2011	Plaster City Yard	1			1			no
9/14/2011	EP361	2			2			no
9/14/2011	Fromm CY	1				1		no
9/14/2011	EP308	1					1	no
9/14/2011	EP301	5		4	1			no
9/14/2011	EP292	3		3				no
9/13/2011	S2 Yard	10			10			no
9/13/2011	EP348	3		3				no
9/13/2011	EP345	2		2				no
9/13/2011	EP326	1					1	no
9/13/2011	EP325	2		2				no
9/13/2011	EP326	1		1				no
9/13/2011	EP304	7		7				no
9/13/2011	EP291	7		7				no
9/12/2011	S2 Yard	3			3			no
9/12/2011	EP350	1		1				no
9/12/2011	EP304	1		1				no
9/12/2011	EP301	1		1				no
9/11/2011	S2 Yard	2				2		no
9/10/2011	S2 Yard	2					2	no
9/9/2011	EP304	1			1			no
9/8/2011	S2 Yard	3					3	no
9/7/2011	S2 Yard	3					3	no
9/6/2011	No ravens observed							
9/5/2011	No ravens observed							
9/4/2011	No ravens observed							
9/3/2011	No ravens observed							
9/2/2011	EP348	1		1				no
9/2/2011	S2 Yard	1		1				no
9/2/2011	EP303	1		1				no
9/2/2011	EP363	2		2				1 at IV Sub
9/1/2011	EP303	2					2	no
9/1/2011	EP293	1					1	no
9/1/2011	EP304	2					2	no
8/31/2011	S2 Yard	1		1				no
8/31/2011	EP308	1		1				no
8/31/2011	EP305-3	2					2	no
8/31/2011	EP303	2		2				no
8/30/2011	EP303	1		1				no
8/29/2011	S2 Yard	1		1				no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
8/29/2011	EP303	1		1				no
8/28/2011			No ravens observed					
8/27/2011	EP305	3			3			no
8/26/2011	EP301	2		2				no
8/25/2011	S2 Yard	2					2	no
8/25/2011	EP301	2		2				no
8/24/2011	S2 Yard	3				3		no
8/23/2011	EP292-1	3		3				no
8/22/2011			No ravens observed					
8/21/2011			No ravens observed					
8/20/2011	S2 Yard	2				2		no
8/20/2011	EP312	2		2				no
8/20/2011	S2 Yard	2					2	no
8/20/2011	EP312	2		2				no
8/19/2011	EP307	2			2			no
8/19/2011	EP296	1		1				no
8/18/2011	S2 Yard	2				1	1	no
8/18/2011	EP301	Flock		x				no
8/17/2011	S2 Yard	2				1	1	no
8/17/2011	EP301	3			3			no
8/16/2011	S2 Yard	1					1	no
8/16/2011	EP301	1		1				no
8/15/2011			No ravens observed					
8/14/2011			No ravens observed					
8/13/2011	S2 Yard	2					2	no
8/12/2011	IV Substation	2				2		no
8/12/2011	S2 Yard	3				3	3	no
8/11/2011	EP294	4			4			no
8/11/2011	S2 Yard	3				3	3	no
8/10/2011	S2 Yard	3				2	1	no
8/9/2011	S2 Yard	not specified						no
8/8/2011	EP294	2			2			no
8/8/2011	S2 Yard	1						no
8/7/2011			No ravens observed					
8/6/2011	S2 Yard	1						no
8/5/2011	EP301	3		3				no
8/4/2011	S2 Yard	not specified						no
8/3/2011	S2 Yard	2		2				no
8/3/2011	S2 Yard	1						no
8/2/2011	S2 Yard	3					3	no
8/1/2011	EP314	not specified		x				no
7/31/2011			No ravens observed					
7/30/2011	EP314	3		2			1	no
7/30/2011	S2 Yard	1					1	no
7/29/2011	S2 Yard	1						no
7/28/2011	EP319	4	1	2	1			no

Date	Location	Number of Ravens observed	Raven Activity					FTHL observed
			Nesting	Flying	Perching	Roosting	Scavaging	
7/28/2011	S2 Yard	not specified						no
7/27/2011	S2 Yard	not specified						no
7/26/2011	No ravens observed							
7/25/2011	EP290	1			1			no
7/24/2011	No ravens observed							
7/23/2011	No ravens observed							
7/22/2011	EP290	2		1	1			no
7/21/2011	S2 Yard	1		1				no
7/20/2011	Ocotillo, CA	5						no
7/19/2011	Ocotillo, CA	1						no
7/17/2011	No ravens observed							
7/15/2011	No ravens observed							
7/14/2011	EP357	not specified						no
7/14/2011	EP358	not specified						no
7/14/2011	EP359	not specified						no
7/14/2011	Plaster City Yard	2		2				no
7/13/2011	EP313-EP314 PS	not specified						no
7/13/2011	S2 Yard	3				3		no
7/11/2011	EP304-EP314	not specified						no
7/10/2011	No ravens observed							
7/9/2011	EP351	not specified						no
7/9/2011	EP353	not specified						no
7/9/2011	EP354	not specified						no
7/9/2011	EP355	not specified						no
7/9/2011	not specified	not specified						no
7/9/2011	S2 Yard	3				3		no
7/8/2011	EP303	2			1		1	no
7/8/2011	EP303	1		1				no
7/8/2011	S2 Yard	3					3	no
7/1/11-7/7/11	No ravens observed							
6/30/2011	EP300	3		3				no
6/21/11-6/29/11	No ravens observed							
6/20/2011	S2 Yard	2					2	no
6/1/11-6/19/11	No ravens observed							
5/1/11-5/31/11	No ravens observed							
4/22/11-4/30/11	No ravens observed							
4/21/2011	EP341	1	1					no
4/1/11-4/20/11	No ravens observed							
3/1/11-3/31/11	No ravens observed							
2/1/11-2/28/11	No ravens observed							
1/21/11-1/31/11	No ravens observed							
1/21/2011	Rough Acres Yard	not specified						no