California Public Utilities Commission

Pipeline Safety and Reliability Project -

New Natural Gas Line 3602 and De-rating Line 1600 (PSRP)

Appendix E

Vegetation Communities and Special Status Plants in the Biological Resources Survey Area Figure


for

CEQA Master Environmental Assessment


Prepared by:

Ecology and Environment, Inc.

November 2018



Sources: ESRI 2012; SanGIS 2016; SDG&E 2017; USMC 2017







Key:			Appendix E
ROW	Right-o	of-Way	Vegetation Communities and
			Special Status Plants in the
	(Biological Resources Survey Area
			Page 2 of 61
			Pipeline Safety and Reliability
			Project - New Natural Gas
0	250	500	Line 3602 and De-rating
 			Line 1600
	Feet		San Diego County, CA



		ENGELMANN	AK		
Ŕ	1 Milepost	Surveyed Vegetation - PSRP	Key:		Appendix E
	— Line 3602	Bog and Marsh	ROW	Right-of-Way	Vegetation Communities and
SAN DIEGO COUNTY	Bore Pits	Disturbed or Developed Habitat			Special Status Plants in the Biological Resources Survey Area
	Workspace Boundary	Grasslands, Vernal Pools, Meadows,			Page 3 of 61
~ • • • • •	Biological Resources Survey Area	and Other Herb Communities			Pipeline Safety and Reliability
L A	Municipal Boundary	Riparian and Bottomland Habitat			Project - New Natural Gas
Pacific Occan	PSRP - Plants	Scrub and Chaparral	0	250 500	Line 3602 and De-rating Line 1600
Comment States	_	Woodland		Feet	San Diego County, CA
Sources: ESRI 2012,	2018a; SanGIS 2016, 2017; SDG&E 20	17; USMC 2017			<u> </u>






1 Milepost	Surveyed Vegetation - PSRP	Key: Appendix E
san Line 3602	Disturbed or Developed Habitat	ROW Right-of-Way Vegetation Communities and Special Status Plants in the
DIEGO COUNTY Workspace Boundary	Grasslands, Vernal Pools, Meadows,	Biological Resources Survey Area
Biological Resources Survey	Area and Other Herb Communities	Page 5 of 61
Municipal Boundary	Riparian and Bottomland Habitat	Pipeline Safety and Reliability Project - New Natural Gas
	Scrub and Chaparral	0 250 500 Line 3602 and De-rating
PSRP - Plants	Woodland	Line 1600
Sources: ESRI 2012, 2018a; SanGIS 2016, 2017; SDG&E 20		Feet San Diego County, CA




6
A researchist E




Grasslands, Vernal Pools, Meadows,
and Other Herb Communities

- Riparian and Bottomland Habitat
 - Scrub and Chaparral

Woodland




Appendix E Vegetation Communities and Special Status Plants in the Biological Resources Survey Area Page 6 of 61 Pipeline Safety and Reliability Project - New Natural Gas Line 3602 and De-rating Line 1600 San Diego County, CA



ur	urveyed Vegetation - PSRP				
	Disturbed or Developed Habitat				
	Grasslands, Vernal Pools, Meadows, and Other Herb Communities				
	Riparian and Bottomland Habitat				
	Scrub and Chaparral				
	Woodland				

Appendix E				
Vegetation Communities and				
Special Status Plants in the				
Biological Resources Survey Area				
Page 7 of 61				
Pipeline Safety and Reliability				
Project - New Natural Gas				
Line 3602 and De-rating				
Line 1600				
San Diego County, CA				








Surveyed Vegetation - PSRP					
Disturbed or Developed Habitat					
Grasslands, Vernal Pools, Meadows, and Other Herb Communities					
Riparian and Bottomland Habitat					
Scrub and Chaparral					
· · · · ·					

Key:			Appendix E
ROW	Right-c	of-Way	Vegetation Communitie
			Special Status Plants ir
			Biological Resources Surv
			Page 10 of 61
			Pipeline Safety and Relial
			Project - New Natural G
0	250	500	Line 3602 and De-ratin
			Line 1600
	Feet		San Diego County, Ci



- Biological Resources Survey Area Municipal Boundary
- Surveyed Vegetation PSRP


Disturbed or Developed Habitat

Scrub and Chaparral


Woodland

> 0 250 500 + Feet


Special Status Plants in the Biological Resources Survey Area Page 11 of 61 Pipeline Safety and Reliability Project - New Natural Gas Line 3602 and De-rating Line 1600 San Diego County, CA




nbow\Maps\MXD\Biology\AppendixE Veg













+


San Diego County, CA

Feet

Surveyed Vegetation - PSRP

Bog and Marsh








		ECREPT RECEIVING PT	
Milepost	Surveyed Vegetation - PSRP	Кеу:	Appendix E
Line 3602	Disturbed or Developed Habitat	ROW Right-of-Way	-
Diego country — Tie-Ins & Extensio			Special Status Plants in the Biological Resources Survey Area
Bore Pits	and Other Herb Communities		Page 19 of 61
	Riparian and Bottomland Habitat		Pipeline Safety and Reliability
			Project - New Natural Gas Line 3602 and De-rating
Biological Reso	urces Survey Area	0 250 500	Line 3602 and De-rating Line 1600
Portfol Green	dary	Feet	San Diego County, CA







Sources: ESRI 2012, 2018a; SanGIS 2016, 2017; SDG&E 2017; USMC 2017







Sources: ESRI 2012, 2018a; SanGIS 2016, 2017; SDG&E 2017; USMC 2017













Sources: ESRI 2012, 2018a; SanGIS 2016, 2017; SDG&E 2017; USMC 2017






11/3/2018



City of Escondido, San Diego County Unincorporated San Diego County ity of Escondido, an Diego County



Sources: ESRI 2012, 2018a; SanGIS 2016, 2017; SDG&E 2017; USMC 2017


\MXD\Bi



Sources: ESRI 2012, 2018a; SanGIS 2016, 2017; SDG&E 2017; USMC 2017












Unincorporated San Diego County 11/3/2018







M:\San_Francisco\Rainbow\Maps\MXD\Biology\AppendixE_Veg_60pg.mx

Surveyed Vegetation - PSRP

- Disturbed or Developed Habitat
 - Grasslands, Vernal Pools, Meadows, and Other Herb Communities
- Riparian and Bottomland Habitat
- Woodland








	Municipal Boundary			
Surveyed Vegetation - PSRP				
	Disturbed or Developed Habitat			
	Grasslands, Vernal Pools, Meadows and Other Herb Communities			
	Riparian and Bottomland Habitat			
	Woodland			






Sources: ESRI 2012, 2018a; SanGIS 2016, 2017; SDG&E 2017; USMC 2017









Existing Pipelines

SAN DIEGO COUNTY

- Existing Line 1600
- Workspace Boundary
- Biological Resources Survey Area
- Municipal Boundary

Surveyed Vegetation - PSRP



Woodland

Appendix E Vegetation Communities and Special Status Plants in the Biological Resources Survey Area Page 44 of 61 Pipeline Safety and Reliability Project - New Natural Gas Line 3602 and De-rating Line 1600 San Diego County, CA 500


0

+

250


Feet


0



ہ.	Existing Pipelines	Surveyed Vegetation - PSRP		Appendix E
A SAN	Existing Line 1600	Disturbed or Developed Habitat		Vegetation Communities and Special Status Plants in the
	Workspace Boundary			Biological Resources Survey Area
	Biological Resources Survey Area			<i>Page 45 of 61</i> Pipeline Safety and Reliability
	Municipal Boundary			Project - New Natural Gas
			0 250 500	Line 3602 and De-rating
Pacific Ocean			Feet	Line 1600 San Diego County, CA
Sources: ESRI 2012	2018a: SanGIS 2016, 2017: SDG&E 2017: LISM	IC 2017		

- Biological Resources Survey Area
- Municipal Boundary









Sources: ESRI 2012, 2018a; SanGIS 2016, 2017; SDG&E 2017; USMC 2017



Distribution System Modification	Surveyed Vegetation - PSRP			Appendix E
Existing Pipelines	Bog and Marsh			Vegetation Communities and
SAN DIEGO COUNTY - Existing Line 1600	Disturbed or Developed Habitat			Special Status Plants in the Biological Resources Survey Area
Workspace Boundary	Grasslands, Vernal Pools, Meadows,			Page 50 of 61
Biological Resources Survey Area	and Other Herb Communities			Pipeline Safety and Reliability
MCAS Miramar	Riparian and Bottomland Habitat	0	250 500	Project - New Natural Gas Line 3602 and De-rating
Participal Boundary	Scrub and Chaparral	0		Line 1600
Sources: ESPI 2012, 2018a: SanGIS 2016, 2017; SDG&E 20	Woodland		Feet	San Diego County, CA





Disturbed or Developed Habitat Grasslands, Vernal Pools, Meadows, and Other Herb Communities

Scrub and Chaparral

Woodland


500

+

0 250 Feet

Appendix E Vegetation Communities and Special Status Plants in the Biological Resources Survey Area Page 51 of 61 Pipeline Safety and Reliability Project - New Natural Gas Line 3602 and De-rating Line 1600 San Diego County, CA San Diego County, CA







A	Milepost Disturbed or Developed Habitat	Key: Appendix E
R.	Line 3602 Grasslands, Vernal Pools, Meadows,	ROW Right-of-Way Vegetation Communities and
SAN DIEGO	Distribution System Modification and Other Herb Communities	Special Status Plants in the
COUNTY	Workspace Boundary	Biological Resources Survey Area
	Biological Resources Survey Area	Page 54 of 61 Pipeline Safety and Reliability
	Municipal Boundary Woodland	Project - New Natural Gas
	Surveyed Vegetation - PSRP	0 250 500 Line 3602 and De-rating
Pacific Ocean	Bog and Marsh	Image: Feet Line 1600 Feet San Diego County, CA

Sources: ESRI 2012, 2018a; SanGIS 2016, 2017; SDG&E 2017; USMC 2017







