



235 Montgomery Street, Suite 935, San Francisco, CA 94104 Tel. 415-955-4775, Fax 415-955-4776, www.aspeneg.com

PROJECT MEMORANDUM

CRESSEY-GALLO 115 KV POWER LINE PROJECT

To: Billie Blanchard, Project Manager, CPUC **From:** Vida Strong, Aspen Project Manager

Date: February 13, 2015

Subject: Monitoring Report #11: February 2 to 8, 2015

This report provides a summary of the construction and compliance activities associated with the Pacific Gas and Electric (PG&E) Cressey-Gallo 115 kV Power Line Project.

A summary of the Notices to Proceed (NTPs) for construction and Minor Project Change (MPC) activities are provided in Tables 1 and 2, respectively (below).

CPUC Environmental Monitor (EM): David DuBois was on site February 3, 2015.

Work Schedule: Work occurred Monday through Friday during the subject period. No work occurred Saturday or Sunday.

CPUC NTPs

NTP #1: Gallo Property & Cressey Substation

NTP #1 was issued on 10/21/14 for Installation and removal of the Shoo-Fly at the Gallo Winery, expansion work at the Gallo Substation, construction of the single and double circuit 115 kV pole lines on the Gallo Property, and modification work at the Cressey Substation. NTP #1 included conditions that had to be satisfied prior to the start of construction.

Summary of Activity:

- 1. Construction activities continued at the Cressey Substation during the subject period. Material delivery and storage, trenching, backfilling, and structure installation occurred (see Figure 1).
- 2. The staging area at the Gallo Winery is being used for storing materials.
- 3. Construction activities continued at the Gallo Substation during the subject period. Augering, earth moving, and foundation installation occurred (see Figure 2).
- 4. New electrical lines were installed on recently erected poles, adjacent to the Shoo-Fly Route, during the subject period (see Figure 3).
- 5. A tubular steel pole (TSP) was installed along Magnolia Avenue during the subject period.

Environmental Compliance:

- Buffers are maintained around sensitive resources. As recorded in previous monitoring reports, the
 Applicant has requested that some demolition work be allowed to occur within a buffer established
 for an elderberry bush at the Cressey Substation. The request was conditionally approved requiring
 that certain protective measures be implemented during demolition to ensure that no resource
 damage occurs and that post-demolition monitoring is conducted to survey for the health of the
 plant. Demolition work is pending.
- 2. All crews receive environmental training. Training sign-in sheets were available for the CPUC EM's review.

Agoura Hills • San Francisco • Sacramento • Inland Empire • Palm Springs • Phoenix



- 3. Erosion control devices were installed and functioning appropriately per the Storm Water Pollution Prevention Plan (SWPPP) (see Figure 4).
- 4. Ingress/egress driveways to roadways are monitored for track out and swept as needed to remove track out.
- 5. Crews took measures during refueling to capture any unintentional spills or drips.
- 6. Augured holes were securely covered at the end of work. Trenches had escape ramps for wildlife.

NTP #2: 115 kV Construction

NTP #2 was issued on 12/22/14 for installation of remaining TSPs, construction of the re-route area north of Livingston Canal, construction of single circuit 115 kV pole lines within ½ mile buffers for Swainson's hawk nesting areas east of Howard Street, and pulling of conductor. NTP #2 included conditions that had to be satisfied prior to the start of construction.

Summary of Activity:

- 1. Flagging of sensitive resources and pole locations, and staging of poles continued in NTP #2 areas during the subject period.
- 2. Some pole replacement work occurred in NTP #2 areas within a Swainson's hawk buffer (nest not currently active).

Environmental Compliance:

- 1. Flagging remains in place around sensitive resources (biological/cultural).
- 2. Biological preconstruction surveys were conducted in NTP #2 areas on February 3, 4, and 6 for nesting birds, amphibians, reptiles and bats. No sensitive species and no nests or nesting birds were observed.

Notices to Proceed

Table 1 summarizes the Notices to Proceed (NTP) for Cressey-Gallo 115 kV Power Line Project.

Table 1 Notice to Proceeds (NTPs)

(Updated 2/13/15)

	Date	Date		
NTP#	Requested	Issued	Phase	Description
NTP #1	9/12/14	10/21/14	Gallo Substation and Shoo-Fly, Cressey Substation	Installation and removal of the Shoo-Fly, expansion work at the Gallo Substation, construction of the single and double circuit 115 kV pole lines on the Gallo Property, and modification work at the Cressey Substation.
NTP #2	12/11/14	12/22/14	115 kV Power Line	Installation of remaining TSPs, construction of the re-route area north of Livingston Canal, construction of single circuit 115 kV pole lines within ½ mile buffers for Swainson's hawk nesting areas east of Howard Street, and pulling of conductor.

Minor Project Changes

Table 2 summarizes the Minor Project Changes for the Cressey-Gallo 115 kV Power Line Project.

Table 2 Minor Project Changes (MPCs)

(Updated 2/13/15)

MPC#	Date Requested	Date Issued	Phase	Description
MPC#1	10/01/14	10/08/14	Gallo	Use of an existing alternative staging area 75
			Substation	feet west of the proposed Staging Area 001
			and Shoo-Fly	located southeast of the Gallo Substation

PROJECT PHOTOGRAPHS







Figure 1 – Structure installation occurred at the Cressey Substation during the subject period. View from southeast corner of substation facing northwest, 01/08/15 top 01/20/15 middle, 02/03/15 bottom.







Figure 3 – Construction continued at the Gallo Substation during the subject period. View northeast from southwest corner of future substation area, 01/20/15 top, 01/29/15 middle, 02/03/15 bottom.



Figure 3 – Installation of conductor along recently installed transmission poles occurred adjacent to the temporary Shoo Fly poles. View northeast, 02/03/15.



Figure 4 – Soil pile containment is in place at the Cressey Substation work area. View northwest, 02/03/15.