Table 2. Proposed Environmentally Sensitive Area (ESA) and Monitoring Mitigation for the SRPL FESSR

Section	Impact Area	Site Designation	Ownership	USGS Quad	Description	NRHP/CRHR Status	Proposed Mitigation
10B	EP352 work area	IMP-8665	BLM	Yuha Basin	Prehistoric Artifact Scatter	Undetermined	20 m ESA buffer around site boundary within work area
10B	EP350 work area	IMP-8766	BLM	Yuha Basin	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around site boundary within work area
10B	EP347 access road	IMP-1015/4348/8744	BLM	Plaster City	Prehistoric Artifact Scatter	Undetermined	ESA along existing access road; monitor road grading
10B	EP345 work area	IMP-3773	BLM	Plaster City	Prehistoric Lithic Scatter/Historic Refuse	Undetermined	20 m ESA buffer around site boundary within work area
10B	EP344 work area	IMP-8740	BLM	Plaster City	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around site boundary within work area
10B	EP344 string site	IMP-8739	BLM	Plaster City	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around site boundary within string site
10B	Construction Yard	AGH-5	BLM	Plaster City	Prehistoric Rock Feature	Undetermined	20 m ESA buffer around entire site boundary
10B	Construction Yard	BW-50	BLM	Plaster City	Prehistoric Rock Feature	Undetermined	20 m ESA buffer around entire site boundary
10B	EP338 work area	10B-8	Private	Plaster City	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around site boundary within work area
10B	EP326 access road	IMP-4237	BLM	Painted Gorge	Prehistoric Lithic Scatter	Undetermined	ESA along existing access road; monitor road grading
10B	EP321-1 work area	BW-S-09	BLM	Painted Gorge	Prehistoric Ceramic Scatter	Undetermined	20 m ESA buffer around site boundary within work area
10B	EP293 work area	BW-35	BLM	In-Ko-Pah Gorge	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around site boundary within work area
10B	EP291-1 access road	IMP-103/3710	BLM	In-Ko-Pah Gorge	Prehistoric Habitation, Trail	Undetermined	ESA along existing road
10B	EP290 access road	IMP-3708	BLM	In-Ko-Pah Gorge	Prehistoric Artifact Scatter and Trail	Undetermined	ESA along existing road

10A	EP275-1 helipad	BW-25	BLM	In-Ko-Pah Gorge	Prehistoric Habitation	Undetermined	20 m ESA buffer around site boundary within helipad
10A	EP269-1 access road	IMP-7886	BLM	In-Ko-Pah Gorge	Historic Highway 80	Eligible	ESA along existing road
<mark>9C</mark>	EP267-2 helipad		BLM	In-Ko-Pah Gorge		Undetermined	20 m ESA buffer around site boundary within helipad
9C	EP266-2 helipad	IMP-4706	BLM	In-Ko-Pah Gorge	Prehistoric Artifact Scatter	Undetermined	20 m ESA buffer around site boundary within helipad
9C	EP263A-2 helipad	BC-60	Private	In-Ko-Pah Gorge	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around site boundary within helipad
9C	EP262-4 helipad	BC-61	Private	In-Ko-Pah Gorge	Prehistoric Artifact Scatter	Undetermined	20 m ESA buffer around site boundary within helipad
9C	EP259-3 helipad	BC-57	Private	In-Ko-Pah Gorge	Prehistoric Artifact Scatter	Undetermined	20 m ESA buffer around site boundary within helipad
9C	EP257 construction yard	SDI-19890	Private	In-Ko-Pah Gorge	Prehistoric Artifact Scatter/Historic Refuse	Undetermined	20 m ESA buffer around site boundary within construction yard
9C	EP255-2 access road	SDI-7073/7083/8306	Private	In-Ko-Pah Gorge	Prehistoric Artifact Scatter	Undetermined	ESA along existing road
9C	EP252A-1 access road	SDI- 7074/7075/7076/15879	Private	In-Ko-Pah Gorge	Prehistoric Bedrock Milling	Undetermined	ESA along existing road
9C	EP251 and EP250 access road	SDI-7060	BLM	Jacumba	Prehistoric Artifact Scatter	Undetermined	ESA along existing road
9C	EP248 and EP249 access road	SDI- 6776/7051/7059/19035	BLM	Jacumba	Prehistoric Artifact Scatter	Undetermined	ESA along existing road and monitor grading
9C	EP247 access road	SDI-19882	BLM	Jacumba	Prehistoric Artifact Scatter	Undetermined	ESA along existing road
9C	EP245-1 access road	SDI-7043/7045	Private	Jacumba	Prehistoric Lithic Scatter	Undetermined	ESA along existing road
9C	EP244 string site	AGH-1	Private	Jacumba	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around entire site boundary
9C	EP242 construction yard	SDI-19905	Private	Jacumba	Prehistoric Artifact Scatter	Undetermined	20 m ESA buffer around entire site boundary
9C	EP242 construction	SDI-19907	Private	Jacumba	Prehistoric Lithic	Undetermined	20 m ESA buffer around

	yard				Scatter		entire site boundary
9C	EP242 construction yard	SDI-19908	Private	Jacumba	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around entire site boundary
9C	EP242 construction yard	SDI-19909	Private	Jacumba	Prehistoric Artifact Scatter	Undetermined	20 m ESA buffer around entire site boundary
9C	EP237-1/EP236-1 string site access road	SDI-19303	Private	Jacumba	Prehistoric Bedrock Milling	Undetermined	ESA along existing road and monitor grading
9C	EP231A work area and helipad	SDI-19893	Private	Jacumba	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around site boundary within work area and helipad
9C	EP221-2 work area	SDI-19276	Private	Jacumba	Prehistoric Artifact Scatter	Undetermined	20 m ESA buffer around site boundary within work area
9C	EP221-2 work area	SDI-19914	Private	Jacumba	Historic Mining	Undetermined	20 m ESA buffer around site boundary within work area
9C	EP220-1/EP219-1 string site access road	P-37-031313	Private	Jacumba	Prehistoric Lithic Scatter	Undetermined	ESA along existing road and monitor grading
9C	EP220-1/EP219-1 string site access road	SDI-6893/16823	Private	Live Oak Springs	Historic Refuse	Undetermined	ESA along existing road and monitor grading
9C	EP220-1/EP219-1 string site access road	SDI- 6902	Private	Live Oak Springs	Historic Refuse and Prehistoric Bedrock Milling	Recommended Ineligible	ESA along existing road and monitor grading
9C	EP220-1/EP219-1 string site access road	SDI-19901	Private	Live Oak Springs	Historic Refuse	Undetermined	ESA along existing road and monitor grading
9B	EP215 string site	SDI-19856	Private	Live Oak Springs	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around site boundary within string site
9B	EP206-1 access road	SDI-4788	BLM	Live Oak Springs	Prehistoric Bedrock Milling	Undetermined	ESA along existing road
9B	Construction Yard	SDI-19872	Private	Live Oak Springs	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around entire site boundary
9B	EP203-3 work area	SDI-19870	BLM	Live Oak Springs	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around entire site boundary
9B	EP201-3 work area	SDI-19869	BLM	Live Oak Springs	Prehistoric Artifact Scatter	Undetermined	20 m ESA buffer around site boundary within work

	ED102.5				Durkistania Antifact		area 20 m ESA buffer around
9B	EP192-5 access road	SDI-19849	BLM	Live Oak Springs	Prehistoric Artifact Scatter	Undetermined	site boundary within acces
9B	EP190-2 work area	SDI-19854	BLM	Live Oak Springs	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around site boundary within work area
9B	EP187-2 string site access road	SDI-19935	BLM	Sombrero Peak	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around site boundary within access road
9B	EP187-2 string site and access road	SDI-19874	BLM	Sombrero Peak	Prehistoric Bedrock Milling	Undetermined	20 m ESA buffer around site boundary within string site and access road
9B	EP185-1 work area	SDI-19298	Private	Sombrero Peak	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around site boundary within work area
9B	EP184-1 access road	SDI-19859	Private	Sombrero Peak	Prehistoric Artifact Scatter	Undetermined	20 m ESA buffer around site boundary within access road
9B	EP170 string site	SDI-19860	BLM	Sombrero Peak	Prehistoric Bedrock Milling	Undetermined	20 m ESA buffer around entire site boundary
9B	EP144 helipad	SDI-19864	BLM	Mount Laguna	Historic Mining	Undetermined	20 m ESA buffer around site boundary within helipad
9B	EP139-1 access road	P-37-031277	USFS	Mount Laguna	Historic Road	Undetermined	ESA along existing road
9A	EP130-1 work area	SDI-19840	USFS	Mount Laguna	Prehistoric Bedrock Milling	Undetermined	20 m ESA buffer around site boundary within work area
9A	EP130-1 construction yard	SDI-19841	USFS	Mount Laguna	Prehistoric Ceramic Scatter	Undetermined	20 m ESA buffer around entire site boundary
8E	EP118-2 helipad	SDI-19836	USFS	Cameron Corners	Prehistoric Bedrock Milling	Undetermined	20 m ESA buffer around entire site boundary
8E	EP110-2 helipad	SDI-19833	USFS	Cameron Corners	Prehistoric Bedrock Milling	Undetermined	20 m ESA buffer around site boundary within helipad
8E	EP109-1 work area	SDI-19815	USFS	Cameron Corners	Prehistoric Bedrock Milling	Undetermined	20 m ESA buffer around site boundary within work area
8D	EP79 work area	SDI-19813	Private	Morena Reservoir	Prehistoric Bedrock	Undetermined	20 m ESA buffer around

					Milling		site boundary within work area
8D	EP78 work area	SDI-19039	Private	Morena Reservoir	Prehistoric Artifact Scatter	Undetermined	20 m ESA buffer around site boundary within work area
8D	EP77 access road	SDI-10040	USFS/Private	Morena Reservoir	Prehistoric Bedrock Milling	Undetermined	ESA along existing road
8C	Construction Yard	SDI-17989	Private	Morena Reservoir	Prehistoric Bedrock Milling	Recommended Ineligible	20 m ESA buffer around site boundary within construction yard
8C	EP53-2/EP52-1 access road	SDI-8440	BLM/Private	Morena Reservoir/Barrett Lake	Prehistoric Bedrock Milling	Undetermined	ESA along existing road
8C	EP51-1	SDI-19797	BLM	Barrett Lake	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around site boundary within work area
Suncrest	Access Road (Bell Bluff Truck)	SDI-19771	Private	Viejas Mountain	Prehistoric Bedrock Milling	Undetermined	ESA along existing road
Suncrest	CP106-1 string site	SDI-19776	Private	Viejas Mountain	Prehistoric Lithic Scatter	Undetermined	20 m ESA buffer around site boundary within string site
6	CP71 access road	P-37-019275	City of SD	El Cajon Mountain	Historic Road	Undetermined	ESA along existing road
5	Construction Yard	SDI-19761	Private	El Cajon Mountain	Prehistoric Bedrock Milling	Undetermined	20 m ESA buffer around site boundary within construction yard
5	Construction Yard	SDI-19762	Private	El Cajon Mountain	Prehistoric Artifact Scatter	Undetermined	20 m ESA buffer around entire site boundary
5	CP44-1 access road	SDI-13651	Private	San Vicente Reservoir	Prehistoric Bedrock Milling	Undetermined	ESA along new road and monitor grading
4A	CP31-2 access road	SDI-12821	SD County	San Vicente Reservoir	Historic Trail	Undetermined	ESA along existing road
4A	CP31-2 string site	SDI-18436	Private	San Vicente Reservoir	Prehistoric Bedrock Milling	Undetermined	20 m ESA buffer around site boundary within string site
4A	CP12-1 work area and access road	P-37-014261	Military	Poway	Historic Military	Recommended Ineligible	20 m ESA buffer around site boundary within work area and access road