

December 13, 2010

I. REPRESENTATIVES, LOCATIONS AND DATES

Clarence Brown of the Viejas Tribe served as the Tribal representative to monitor construction at Vault locations 14L, 15L, 16L, 17L, 18L, and 19L from December 6-10, 2010.

II. CONSTRUCTION ACTIVITIES

Construction activity consisted of drilling, jackhammering and excavating at these locations.

III. OBSERVATIONS

Many of the locations monitored had already been disturbed and consisted of digging in fill soils. A few locations contained what appeared to be natural (undisturbed) soils. No cultural material was noted at any of the locations.

IV. CONCERNS EXPRESSED

No concerns were expressed at this time.

V. SUMMARY

No further concerns were noted with regard to cultural resources.

VI. SUMMARY PREPARER

Hillary Murphy, Project Archaeologist, Tierra Environmental Services, Inc.
Joseph M. Nixon, Senior Anthropologist, Tierra Environmental Services, Inc.