

June 21, 2011

I. REPRESENTATIVES, LOCATIONS AND DATES

LINK 1: Plaster City and Ocotillo Desert Region

- Richard Alvanez, Cocopah, served as monitor at the IV yard on June 13 and 14.
- Cody Elliott, Kumeyaay Native, served as the monitor at Plaster City on June 13 through 17.
- David Elliott Sr., Kumeyaay Native, monitored on June 14 through 17.
- Jonathon Jones, Campo, served as monitor from June 13 to 17. His reports have yet to be submitted.
- Darlene Mack, Campo, served as monitor for June 17. Her report has yet to be submitted.
- Ed Mercado, Campo, served as monitor June 13 through 17.
- Jesse Pinto, Jamul, served as monitor for June 16 and 17.
- Albert Quihuis of Campo served as monitor June 13, 14 and 16. His report has yet to be received.
- Veronica Santos, Manzanita, served as monitor from June 13 to 17.
- Kenneth Stokes, Jr. of the Kumeyaay nation served as monitor from June 13 through 18.
- Larry Sutton, Viejas, served as monitor on June 17.
- Boe Willey, Kumeyaay Native, performed as monitor on June 13 through 17.

LINK 2: Various Locations

- No monitors required at this location for this week.

LINK 3: Suncrest Substation

- No monitors required at this location for this week.

LINK 4: Alpine Underground; Alpine Construction Yard

- Clarence Brown, Viejas, served as monitor for Alpine Blvd from June 13 to 17.
- Josh Craddock, Viejas, served as monitor for the Alpine Construction Yard on June 13. His report has yet to be received.
- Larry Sutton, Viejas, served as monitor for the Alpine Construction Yard on June 14 to 16.

LINK 5: Various Locations

- No monitors required at this location for this week.

II. CONSTRUCTION ACTIVITIES

LINK 1: Plaster City and Ocotillo Desert Region

Mr. Stokes noted shoveling, drilling, grading, and bulldozing. Mr. Willey noted watering, bulldozing, compacting, and grading. Mr. D. Elliott reports drilling, watering, skiploading, bulldozing, and tower construction. Mr. C. Elliott reports survey activities this week.

LINK 2: Various Locations

No monitors required at this location for this week.

LINK 3: Suncrest Substation

No monitors required at this location for this week.

LINK 4: Alpine Underground; Alpine Construction Yard

Mr. Brown reports trenching activities along the Underground this week.

LINK 5: Various Locations

No monitors required at this location for this week.

III. OBSERVATIONS

LINK 1: Plaster City and Ocotillo Desert Region

On June 16, Mr. C. Elliott one core fragment in the middle of a road which was collected by the archaeologist on site.

On June 17, Mr. Sutton saw a single obsidian flake.

LINK 2: Various Locations

No monitors required at this location for this week.

LINK 3: Suncrest Substation

No monitors required at this location for this week.

LINK 4: Alpine Underground; Alpine Construction Yard

No resources observed during construction efforts this week.

LINK 5: Various Locations

No monitors required at this location for this week.

IV. CONCERNS EXPRESSED

LINK 1: Plaster City and Ocotillo Desert Region

No concerns expressed this week other than it getting hot.

LINK 2: Various Locations

No monitors required at this location for this week.

LINK 3: Suncrest Substation

No monitors required at this location for this week.



Native American Representative Summary Report

Week 36: June 13-19, 2011

LINK 4: Alpine Underground; Alpine Construction Yard

No concerns expressed this week.

LINK 5: Various Locations

No monitors required at this location for this week.

V. SUMMARY

No concerns were made this week along the line related to cultural resources.

VI. SUMMARY PREPARER

Hillary Murphy, Project Archaeologist, Tierra Environmental Services, Inc.
Joseph M. Nixon, Senior Anthropologist, Tierra Environmental Services, Inc.