



This report provides a summary of environmental monitoring and compliance activities conducted by Burns and McDonnell (BMcD) staff and BMcD subconsultants for the San Diego Gas & Electric (SDG&E) Sunrise Powerlink Project during the above weekly time period.

**Training**

- SWEAP, PBS, and additional training are held as requested.

**Pre/Post Construction**

- Additional signs and stakes were repaired as needed. Due to traffic and narrow access roads, broken stakes and run over signs were replaced. Maintenance (e.g., writing over faded signs, reinforcing signs/stakes in the ground, replacing zip ties, and adding additional signs) was performed as needed.

**Construction**

- Monitors were present during construction activities to ensure compliance with mitigation measures as identified in the Final EIR/EIS Mitigation Monitoring, Compliance, and Reporting Program. Archaeologists, Paleontologists, and Native American Monitors were present at sites where required as identified prior to construction activity and as approved in the NTPs.
- Project staff carpooled to site reviews, kick-off tailgates, and off-site meetings. Construction and traffic control crews were observed carpooling from yards to work areas.

The table below demonstrates the construction progress to date:

<b>SUBSTATION UPGRADES</b>
4 of 7 Completed

<b>PROJECT WIDE JOB SITE CLOSEOUT AND CLEANUP</b>				
Agency	TSAP	Roads	Pull Sites	Tower Sites
Non-Federal	63 of 63	61 of 61	33 of 33	169 of 169
Bureau of Land Management	63 of 63	107 of 107	24 of 24	179 of 179
Miramar	0 of 0	10 of 10	4 of 4	14 of 14
U.S. Forest Service	49 of 49	19 of 19	11 of 11	76 of 76

Overhead Construction

- Link 1, 2, and 5



- No work occurred during this reporting period.
- 230 kV and 500 kV
  - No work occurred during this reporting period.

Suncrest Substation Construction (Link 3)

- No work was performed on Link 3 during this reporting period.

Substation Upgrades

San Luis Rey:

- No Sunrise-related work during this reporting period.

Encina:

- No Sunrise-related work during this reporting period.

Scripps:

- No Sunrise-related work during this reporting period.

Pomerado:

- No Sunrise-related work during this reporting period

Sycamore:

- No Sunrise-related work during this reporting period

IV:

- No Sunrise-related work during this reporting period.

Construction Yards

- Sycamore Yard – No activity (yard is complete).
- Helix Yard – No activity (yard is complete).
- El Monte Yard – No activity (yard is complete).
- Alpine Yard – No activity (yard is complete).
- Wilson Yard – No activity (yard is complete).
- SWAT Yard – No activity (yard is complete).
- Barrett Canyon Yard – No activity (yard is complete).
- Kreuzkamp Yard – No activity (yard is complete).
- Bartlett Hauser Yard – No activity (yard is complete).
- Thing Valley Yard – No activity (yard is complete).
- McCain Valley Yard – No activity (yard is complete).
- Rough Acres Yard – No activity (yard is complete).
- Jacumba Valley Ranch (JVR) Yard – No activity (yard is complete).
- Fromm Yard – No activity (yard is complete).
- Plaster City Yard – No activity (yard is complete).

NOTE: In addition, all active yards typically have miscellaneous activities throughout the day such as materials delivery and staging, equipment mobilization/demobilization, water supply and dust control, and porta-potty maintenance.



### **Wildlife Reporting**

The following listed or Species of Special Concern were found dead in Project construction limits during this reporting period:

- No listed or Species of Special Concern were found dead in Project construction limits during this reporting period.

The following listed or Species of Special Concern were relocated during construction activities this reporting period:

- No listed or Species of Special Concern were relocated during construction activities this reporting period

### **Spills/Hazardous Waste**

- No spills were reported during this reporting period.

### **Customer Complaints**

- No customer complaints were received during this reporting period.

### **Non-Compliances**

- No non-compliances were received during this reporting period.

### **Variances and TEWS**

- No variiances or TEWS were approved during this reporting period.

### **Weather**

- No rain events occurred during this reporting period.
- BMPs were installed or maintained as needed in all active project areas currently undergoing stabilization and restoration activities. In accordance with the Construction General Permit (CGP), daily visual inspections of the BMPs are being performed by the contractor on sites that have yet to be stabilized and appropriate BMPs for stormwater and non-stormwater discharges were implemented. Any active, non-stabilized sites requiring repairs began within 72-hours of identification.