



This report provides a summary of environmental monitoring and compliance activities conducted by Burns and McDonnell (BMcD) staff and BMcD subconsultants for the San Diego Gas & Electric (SDG&E) Sunrise Powerlink Project during the above weekly time period.

#### **Training**

- SWEAP training continued for new Project personnel every Tuesday and Thursday. Additional trainings were provided as requested.
- Flat-tailed horned lizard (FTHL) trainings were provided to any new crew members or monitors
  prior to construction per mitigation measure B-7b and in accordance with the FTHL Rangewide
  Management Strategy. During morning tailboard meetings, guidelines were provided about
  recognizing, protecting, and notification requirements for FTHL. FTHL information cards were
  made available to any crew members or monitors as needed.
- Barefoot banded gecko trainings were provided to crews prior to pre-construction activities per the California Department of Fish and Game (CDFG) 2081 Incidental Take Permit.

#### **Preconstruction**

- Avian biologists continue to survey for nesting raptors. No active raptors nests were found during
  this period; however, surprisingly, one new active passerine nest was discovered during a
  protocol survey. This nest is the only active nest along the alignment.
- Staked and refreshed work areas at CP28-1, CP29-1, CP31-2, EP90-1, EP113-5, EP117-2, EP118-2, EP119-2, EP219/220-1 pull site, EP223-1, EP224-1, and EP225-1/226-1 pull site.
- Temporary platform staking at EP69, EP70, and EP74-1.
- TSAP topography at EP69, EP70, and EP74-1.
- The ESA Team conducted the following activities during this reporting period:
  - Repaired, refreshed, and maintained the previously installed project signs and ESAs from EP293 to EP329 and at EP362.
  - Installed ESAs at a newly recorded unanticipated discovery within the McCain Valley Yard.
  - Inspected ESAs at the access road leading to EP236/237 pull site, EP291, EP292, and EP342 to EP344.
  - Replaced red reflecting tape from EP293 to EP329, EP331 to EP340, and at EP362.
  - Replaced degraded rope at EP255.
  - Installed T-post/sign ESAs along EP234-1-E access road and EP237-1-PS-A access road.

#### Construction

- Monitors were present during construction activities to ensure compliance with mitigation
  measures as identified in the Final EIR/EIS Mitigation Monitoring, Compliance, and Reporting
  Program. Archaeologists, Paleontologists, and Native American Monitors were present at sites
  where required as identified prior to construction activity and as approved in the NTPs.
  - 12 Archaeological Monitors were present.
  - 106 Biological Monitors were present.
  - 12 Native American Monitors were present.
  - 2 Paleontological Monitors were present.





- 8 SWPPP Monitors were present.
- Project staff carpooled to site reviews, kick-off tailgates, and off-site meetings. Construction and traffic control crews were observed carpooling from yards to work areas.
- Deterrents were utilized to discourage bird nest building activities throughout the Project.
   Deterrents are determined depending upon the location and type of possible nesting areas and may include metallic flagging, compact discs, plastic owls, and the presence of biological monitors.

The table below demonstrates the construction progress to date:

	OVERHEAD	
Agency	Foundations Completed	Towers Erected
Non-Federal	57 of 168	21 of 168
Bureau of Land Management	68 of 180	46 of 180
Miramar	1 of 12	1 of 12
US Forest Service	0 of 76	0 of 76
	UNDERGROUND	
Agency	Vaults Installed	Trenches Excavated & Backfilled
Non-Federal	38 of 40	34 of 42
	SUBSTATIONS	
	2 of 7 Completed	





#### Overhead

Link 1-Vegetation clearing, boulder removal, and site preparations at: EP145, EP145 TSAP, EP146, EP146 TSAP, EP146 communication pad, EP147, EP148-1, EP150, EP261-2, EP263A-2, EP263B-2, EP270-2, EP271-2, EP275-1, EP276-1, and EP278-1. Grading and site preparation at the following tower sites: EP145 TSAP, EP146 communication pad, EP146 TSAP, EP147, EP147 TSAP, EP148-1, EP148-1 TSAP, EP149 TSAP, EP150 TSAP, EP151 TSAP, EP255, EP255 pull site, EP263B-2, EP275, and EP278-1. Driveway entrance construction from EP252A to EP255. Access road maintenance: McCain Valley Road from Rough Acres Yard to McCain Valley Yard and along the SWPL road from EP342 to EP363. Temporary platform installation at EP263B-2. Micropile drilling at EP269-1, EP272-3, EP273-1, EP276-1, EP278-1, EP281, and EP305-3 (redrill leg A, piles 3 and 4). Grouting at EP273-1, EP280-2, and EP305-3. Proof testing at EP312 and EP317. Micropile cap work at EP310, EP311-1, EP312, EP314, EP315-1, and EP317. Conventional drilling at EP323-1, EP324, and EP258-3. Various foundation work (capping, curing, cage installation, grounding, etc.) at EP239-1, EP292-1, EP323-1, and EP324. Concrete pouring at EP239-1, EP290, EP292-1, EP323-1, and EP324. Form removal and cleanup at EP239-1, EP290, EP292-1, EP323-1, and EP324. Foundation repairs at EP351 and EP353. Tower assembly at EP215, EP219, EP293, EP294, EP301, EP303-2, EP304, EP319, EP325, EP328, and EP349.

• QA/QC at/from EP290 to EP309, EP313, EP316, EP349, and EP340 to EP354.

resistance testing at EP295, EP296, EP298, EP299, EP300, EP301, EP313, and EP349.





_		Cyand
•	structures removed from Highway 8 (EP341 and EP342).	Guard
•	installed at the EP355/356 pull site.	Snubs
•	spacers installed at EP337 to EP346.	Conductor
•	installed from EP331 to EP341.	Dampeners
•	delivered and installed at EP349 to EP355.	Travelers
•	C-phase of the conductor sock line pulled from EP349 to EP355.	A-phase and
•	line flown from EP347 to EP355.	B-phase sock
•	(Optical ground wire) sock line pulled from EP347 to EP355.	OPGW
•	haul-back on C phase from EP349 to EP355 and on B-phase from EP348 to	Hard line to EP355. Wire boat set-
_	up at the EP355/356 pull site and the EP348 pull site.	
•	insulators at dead-end tower EP341, Phases A and B.	Installed
•	clipped in from EP343 to EP347.	OPGW
•	travelers installed from EP349 to EP355.	OPGW
•	installed from EP341 to EP342.	Marker balls
•	work at EP342.	Dead-end
•	installed from EP331 to EP341.	Dampeners
•	between EP342 and EP347.	Sagging
•	installation at:	BMP
	■ EP146 TSAP, EP146 communication pad, EP147, EP150, and EP1	EP146, 51.
•	performed maintenance from EP290 to EP363.	BMP crew
•	maintained along access roads at/from:	BMPs
	EP263A-2, EP265-2, and EP290 to EP363.	EP262-4,
•	FTHL monitors, BBG monitors, and Visible Emission Evaluators (VEEs) required.	Trained were onsite as
•	were conducted each day in BBG habitat.	BBG sweeps
	reporting period, there was 1 day with a PAL Level of D and 5 days with I	Link 2 During this PAL levels of





EV. Work activities ended each day in accordance with the fire plan and the approved EV letter.

- Access road construction at:
  - EP42N access road; along La Posta Road from the edge of pavement to EP125, EP126, EP127, EP125 spur road, EP126 spur road, EP127 spur road, and EP130 spur road.
- Grading at:
  - EP124/125 pull site, EP125, EP126-1, EP127, EP130, EP139 TSAP, and EP144 TSAP.
- Topsoil salvage at EP125 and EP130 pull sites.
- Arroyo toad surveys were performed along the access road between EP50 and EP53.
- Arroyo toad exclusionary fencing installation along the access road between EP50 and EP53.
- Vegetation removal/site set-up at EP39-1, EP42, EP43, EP44, EP45, EP91, EP130/131 pull site and spur road, EP137, EP137 TSAP, EP139, EP139 TSAP, EP144, and EP144 TSAP.
- Soil boring at EP113-5 and EP127.
- Micropile prep at EP47-2.
- Pre-drilling for conventional foundations at EP1-3.
- Tower assembly at EP89-1, EP90-1, and EP92.
- Temporary fencing installed at EP125, EP125 pull site, EP126, EP127, and EP130.
- BMP installation from:
  - La Posta Road to EP125, EP125, EP125 pull site, and La Posta Road to EP126.
- Link 5
  - During this reporting period, there was 1 day with a PAL Level of D and 5 days with PAL levels of EV. Work activities ended each day in accordance with the fire plan and the approved EV letter.
  - Vegetation removal and site preparation at CP44-1, CP47-2, CP55, CP56-1,
     CP56-1 TSAP, CP60, CP61-1, CP62, CP68, CP98-1, and CP98-1 access road.
  - Repaired temporary gate at the entrance to CP49-1E pull site.
  - Grading at CP70-3, CP70-3 access road, and CP98-1.
  - Micropile drilling at CP21, CP23, CP65-1, CP66-2, CP67-3, CP72-2, and CP73-2.
  - Grouting at CP21 and CP23.
  - Foundation repairs at CP40.
  - Equipment removal from CP42-1.
  - Steel erection at CP40-2, CP41-2, and CP89-1.
  - BMP installation at CP70-3.
  - BMPs maintained at CP17-1, CP18-1, CP19-1, CP20, CP21, and CP22-1.
  - Vegetation clearing for pole replacement on the 12kV line occurred at Locations #1, #2, #5, and #9.

• 69kV

• No work occurred on the 69kV line during this reporting period.

### Underground

- Redevelopment/Revitalization at Alpine Boulevard (Alpine Elementary School).
- Trenching from V10L to V11L, V18R to V19R, and V20L to riser pole.
- Pouring of encasement from V20L to riser pole.
- Pre-racking/Racking and cleaning manholes for ABB (and jointing/splicing) at V4R to V5R, V6L, and V9L.
- Proofing from V10L to V11L and V11R to V13R.





- Paving (including prep) near V2R to Cal Trans bore site, V9L to V11L, V11R to V12R, and Viejas Creek to V19R.
- Cable pulling (and cable testing) from V13R to V15R.
- Installed risers at Loritz Property.
- Grading at Bauer Property (Slay Property).
- Fiber testing at V17R.
- Formed concrete and bridge attachment at Viejas Creek Bridge.

#### **Suncrest Substation**

- Rough grading on the substation pad and along Bell Bluff Truck Trail.
- Crushing rock for select fill material.
- Pier drilling for foundations.
- Forming pads for foundations and pouring concrete.
- Excavating vaults and trenching between vaults for underground utilities and clearing vegetation at culverts along Bell Bluff Truck Trail.
- Constructing the soil nail wall on the eastern slope.
- Grading on the southwest quadrant of the pad and around the northern sediment detention basin.
- Drilling and blasting on the eastern section of the pad.

### Substation Upgrades

- Encina Switchyard
  - Roel excavated around pads for wire pull boxes, conduit trenches, control room, and transformer pads.
  - Chula Vista Electric performed conduit installation into the control room shelter.
  - Concrete slurry was poured into conduit trench and around wire pull boxes.
  - Roel trenched for a fire wall near the new control house.
  - Roel and contracted masons worked on fire retaining wall near new control house.
  - SDG&E crews wired in and around control house.
- Imperial Valley (IV)
  - Roel formed, framed, and built new maintenance building.
  - SDG&E crews laid out bridges ready for installation from EP362 to EP363.
  - Poured concrete.
- San Luis Rev
  - SDG&E crew worked on wiring in control room.
- Sycamore Canyon
  - SDG&E crews built bus and disconnect supports for Bays 15 and 21.

#### Construction Yards

- AER Yard Tower assembly and equipment/materials delivery.
- Alpine Construction Yard Materials staging, weed wash station, and steel deliveries.
- Barrett Canyon Yard Building access road to sites and yard and BMP installation.
- Bartlett-Hauser Yard Skycrane tower pickups, water staging, and weed wash station.
- Dunaway Yard Water supply for dust control, staging for wire stringing, and water staging.
- Fromm Yard Tower assembly and steel delivery.
- El Monte Yard Tower assembly.
- Helix Yard Staging Crux helicopter operations, weed wash station, tower lifts, and water staging.
- Imperial Valley Yard Water staging.
- Jacumba Valley Ranch (JVR) Yard Helicopter operations, steel hauling, weed wash station, and





water staging.

- Kreutzkamp Yard Tower assembly, helicopter operations, weed wash station, staging for arroyo toad fencing crews, and steel delivery.
- McCain Valley Yard Vegetation clearing and perimeter fencing.
- Plaster City Yard Concrete and water staging.
- Rough Acres Yard Helicopter operations, air crane delivery, clearing equipment to tower sites, materials staging, tower assembly, and weed wash station.
- S2 Yard Tower assembly, concrete foundations staging, QA/QC, water staging, and steel staging. Night work was concluded at this yard during this reporting period.
- SWAT Yard Tower assembly, weed wash station, water staging, and materials deliveries.
- Sycamore Yard Crux helicopter operations and weed wash station.
- Thing Valley Yard Vegetation clearing.
- Wilson Yard Staging materials for Suncrest Substation and tower assembly.

#### Wildlife Reporting

The following listed or Species of Special Concern were found dead in Project construction limits during this reporting period:

- San Diego Desert Woodrat (*Neotoma lepida*) One (1) San Diego desert woodrat was found dead at EP255 due to grading activities.
- Flat-tailed Horned Lizard (*Phrynosoma mcallii*) Three (3) flat-tailed horned lizards were found dead; one on the SWPL access road between EP353 and EP354, one on the SWPL access road near EP345, and one on the SWPL access road near EP324.

The following listed or Species of Special Concern were relocated during construction activities this reporting period:

- Flat-tailed Horned Lizard (*Phrynosoma mcallii*) Six (6) flat-tailed horned lizards were relocated; one from the SWPL access road between EP344 and EP345, one from EP324, one from EP325-2, one from EP342, one from EP346/EP347, and one from the spur road at EP324.
- San Diego Desert Woodrat (*Neotoma lepida*) Two (2) San Diego desert woodrats were found at Thing Valley Yard and relocated out of the construction area into suitable habitat. One (1) San Diego desert woodrat was found injured at EP126. The injury was not Project related.
- San Diego Coast Horned Lizard (*Phrynosoma blainvillei*) Eleven (11) San Diego coast horned lizards were relocated; six (6) from Thing Valley Yard, one (1) from EP130, two (2) from EP125, one (1) from EP39-1, and one (1) from EP126.
- San Diego Ring-necked Snake (*Diadophis punctatus similis*) One (1) San Diego ring-necked snake was found at Thing Valley Yard and relocated out of the construction area into suitable habitat.
- Coronado Skink (*Plestiodon skiltonianus interparietalis*) One (1) Coronado skink was found at Kreutzcamp Yard and relocated out of the construction area into suitable habitat.

The following non-listed (<u>not</u> Species of Special Concern) were relocated during construction activities this reporting period:

• EP42 – One (1) granite night lizard was relocated.





- McCain Valley Yard Seven (7) Merriam's kangaroo rats, seven (7) Dulzura kangaroo rats, one (1) Southern Pacific rattlesnake, one (1) San Diego gopher snake, two (2) American deer mice, and one (1) brush mouse were relocated.
- Thing Valley Yard Twelve (12) kangaroo rats, one (1) side-blotched lizard, and one (1) Southern Pacific rattlesnake were relocated.
- S2 Yard One (1) leaf-nosed snake was relocated.
- Bartlett/Hauser Creek Yard One (1) squirrel was relocated.
- Suncrest Substation One (1) gopher snake was relocated.

### Spills/Hazardous Waste

• On August 26, 2011, approximately 32 ounces of diesel fuel was released near 2754 Alpine Blvd., Alpine, CA 91901. The release was caused when a construction truck had diesel fuel drain out from the fuel tank vent. Conditions leading to the release were a combination of ambient heat expansion and being parked on a slope. The above release was immediately contained and cleaned up. This release was reported on August 31, 2011, as part of the monthly summary to the County of San Diego, Department of Public Works, and Watershed Protection.

### **Customer Complaints**

• No customer complaints were received during this reporting period.

#### **Non-Compliances**

• No non-compliances were issued during this reporting period.

#### Variances and TEWS

• Variance #24 was approved on August 25, 2011, for vegetation clearing/fire safety at Suncrest Substation.

#### Weather

- During this period a rain event occurred on Monday, August 29, 2011.
  - Bartlett/Hauser Yard 0.1 inches
- BMPs were installed or maintained as needed throughout Project areas.





Granite night lizard relocated from EP42-N access road. *Photo courtesy of Marina Heberer*.





Temporary fence installation at EP126. Photo courtesy of Rosina Gallego.







Coast Horned Lizards being relocated. Photo courtesy of Lorena Bernal.

# **Appendices**

Peninsular Big Horn Sheep Monitoring Report
Flat-Tailed Horned Lizard Monitoring Report
Raven Control monitoring Report

PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments	
9/3/2011	EP300-EP312	0	Monitoring Construction Activities	
9/3/2011	EP300-EP312	0	Site clearance survey	
9/3/2011	EP300-EP306	0	Monitoring Construction Activities	
9/3/2011	EP300-EP306	0	Site clearance survey	
9/3/2011	EP271	0	Monitoring Construction Activities	
9/3/2011	EP269-EP273	0	Monitoring Construction Activities	
9/3/2011	EP269-EP273	0	Site clearance survey	
9/3/2011	EP269-EP281	0	Monitoring Construction Activities	
9/3/2011	EP256-EP263A, AER and Fromm Yards	0	Monitoring Construction Activities	
9/3/2011	EP256-EP263A, AER and Fromm Yards	0	Site clearance survey	
9/3/2011	EP278-EP294	0	Evening perimeter survey	
9/3/2011	EP278-EP294	0	Monitoring Construction Activities	
9/3/2011	EP278-EP294	0	Morning perimeter survey	
9/3/2011	EP269-1 & EP269/EP270 Pull site	0	Monitoring Construction Activities	
9/2/2011	I-8 Island	9	Evening perimeter survey 4:45pm - 5:08pm	
9/2/2011	I-8 Island	12	Morning perimeter survey 8:35am	
9/2/2011	EP300-EP312	0	Monitoring Construction Activities	
9/2/2011	EP300-EP312	0	Site clearance survey	
9/2/2011	EP272 & EP276	0	Monitoring Construction Activities	
9/2/2011	EP269-EP273	0	Monitoring Construction Activities	
9/2/2011	EP269-EP273	0	Site clearance survey	
9/2/2011	EP256-EP263A, AER and Fromm Yards	0	Monitoring Construction Activities	
9/2/2011	EP256-EP263A, AER and Fromm Yards	0	Site clearance survey	
9/2/2011	EP278-EP294	0	Evening perimeter survey	
9/2/2011	EP278-EP294	0	Monitoring Construction Activities	
9/2/2011	EP278-EP294	0	Morning perimeter survey	
9/2/2011	EP269-EP272	0	Monitoring Construction Activities	
9/2/2011	EP269-EP272	0	Site clearance survey	
9/2/2011	EP263B-EP267	0	Site clearance survey	
9/1/2011	I-8 Island	12	Evening perimeter survey 4:45pm - 5:40pm	
9/1/2011	I-8 Island	12	Morning perimeter survey 8:35am	
9/1/2011	EP300-EP312	0	Monitoring Construction Activities	
9/1/2011	EP300-EP312	0	Site clearance survey	
9/1/2011	EP269-EP273	0	Monitoring Construction Activities	
9/1/2011	EP269-EP273	0	Site clearance survey	

	PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments		
9/1/2011	EP256-EP263A-2	0	Site clearance survey		
9/1/2011	EP255	0	Monitoring Construction Activities		
9/1/2011	EP300-EP306	0	Site clearance survey		
9/1/2011	EP278-EP294	0	Evening perimeter survey		
9/1/2011	EP278-EP294	0	Monitoring Construction Activities		
9/1/2011	EP278-EP294	0	Morning perimeter survey		
9/1/2011	EP269-EP272	0	Monitoring Construction Activities		
9/1/2011	EP269-EP272	0	Site clearance survey		
9/1/2011	EP263B-EP267	0	Site clearance survey		
8/31/2011	I-8 Island	0	Site clearance survey		
8/31/2011	EP308	0	Monitoring Construction Activities		
8/31/2011	EP300-EP312	0	Monitoring Construction Activities		
8/31/2011	EP300-EP312	0	Site clearance survey		
8/31/2011	EP269-EP273	0	Monitoring Construction Activities		
8/31/2011	EP269-EP273	0	Site clearance survey		
8/31/2011	EP300-EP306	0	Site clearance survey		
8/31/2011	EP278-EP294	0	Evening perimeter survey		
8/31/2011	EP278-EP294	0	Monitoring Construction Activities		
8/31/2011	EP278-EP294	0	Morning perimeter survey		
8/31/2011	EP269-EP272	0	Monitoring Construction Activities		
8/31/2011	EP263B-EP267	0	Site clearance survey		
8/30/2011	I-8 Island	16	Evening perimeter survey 4:30pm		
8/30/2011	I-8 Island	9	Morning perimeter survey 9:10am - 9:30am		
8/30/2011	EP300-EP312	0	Monitoring Construction Activities		
8/30/2011	EP300-EP312	0	Site clearance survey		
8/30/2011	EP269-EP273	0	Monitoring Construction Activities		
8/30/2011	EP269-EP273	0	Site clearance survey		
8/30/2011	EP300-EP306	0	Site clearance survey		
8/30/2011	EP278-EP294	0	Evening perimeter survey		
8/30/2011	EP278-EP294	0	Monitoring Construction Activities		
8/30/2011	EP278-EP294	0	Morning perimeter survey		
8/30/2011	EP274-EP278	0	Monitoring Construction Activities		
8/30/2011	EP274-EP278	0	Site clearance survey		
8/30/2011	EP269-EP272	0	Monitoring Construction Activities		
8/30/2011	EP269-EP272	0	Site clearance survey		

PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments	
8/30/2011	EP263B-EP267	0	Site clearance survey	
8/29/2011	I-8 Island	4	Morning perimeter survey 8:55am	
8/29/2011	I-8 Island	12	Evening perimeter survey 4:35pm to 5:00pm	
8/29/2011	EP300-EP312	0	Monitoring Construction Activities	
8/29/2011	EP300-EP312	0	Site clearance survey	
8/29/2011	EP278-2	0	Monitoring Construction Activities	
8/29/2011	EP269-EP273	0	Monitoring Construction Activities	
8/29/2011	EP269-EP273	0	Site clearance survey	
8/29/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities	
8/29/2011	EP300-EP306	0	Site clearance survey	
8/29/2011	EP274-EP278	0	Monitoring Construction Activities	
8/29/2011	EP274-EP278	0	Site clearance survey	
8/29/2011	EP269-EP272	0	Monitoring Construction Activities	
8/29/2011	EP269-EP272	0	Site clearance survey	
8/29/2011	EP263B-EP267	0	Site clearance survey	
8/28/2011	I-8 Island	15	Morning perimeter survey @9:22am	
8/28/2011	EP305	0	Monitoring Construction Activities	
8/28/2011	EP281	0	Monitoring Construction Activities	
8/28/2011	EP273	0	Monitoring Construction Activities	
8/28/2011	EP269-EP273	0	Monitoring Construction Activities	
8/28/2011	EP269-EP273	0	Site clearance survey	
8/28/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities	
8/28/2011	EP300-EP306	0	Morning perimeter survey	
8/28/2011	EP278-EP294	0	Evening perimeter survey	
8/28/2011	EP278-EP294	0	Monitoring Construction Activities	
8/28/2011	EP278-EP294	0	Morning perimeter survey	
8/28/2011	EP274-EP278	0	Monitoring Construction Activities	
8/28/2011	EP274-EP278	0	Site clearance survey	
8/28/2011	EP269-EP272	0	Monitoring Construction Activities	
8/28/2011	EP269-EP272	0	Site clearance survey	
8/28/2011	EP263-B, EP267	0	Site clearance survey	
8/27/2011	I-8 Island	0	Site clearance survey	
8/27/2011	EP305	0	Monitoring Construction Activities	
8/27/2011	EP300-EP306, EP269-EP273	0	Monitoring Construction Activities	
8/27/2011	EP300-EP306, EP269-EP273	0	Site clearance survey	

PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments	
8/27/2011	I-8 Island	0	Morning perimeter survey	
8/27/2011	EP305	0	Monitoring Construction Activities	
8/27/2011	EP300-EP306, EP269-EP273	0	Site clearance survey	
8/27/2011	EP300-EP306, EP269-EP273	0	Monitoring Construction Activities	
8/27/2011	EP272-3	0	Monitoring Construction Activities	
8/27/2011	EP261	0	Monitoring Construction Activities	
8/27/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities	
8/27/2011	EP278-EP294	0	Site clearance survey	
8/27/2011	EP278-EP294	0	Monitoring Construction Activities	
8/27/2011	EP274-EP278	0	Site clearance survey	
8/27/2011	EP274-EP278	0	Monitoring Construction Activities	
8/27/2011	EP269-EP272	0	Monitoring Construction Activities	
8/27/2011	EP269-EP272	0	Site clearance survey	
8/27/2011	EP263B-EP267	0	Site clearance survey	
8/26/2011	I-8 Island	0	Morning perimeter survey	
8/26/2011	EP269-EP273	0	Monitoring Construction Activities	
8/26/2011	EP269-EP273	0	Morning perimeter survey	
8/26/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities	
8/26/2011	EP300-EP306	0	Monitoring Construction Activities	
8/26/2011	EP278-EP294	0	Evening perimeter survey	
8/26/2011	EP278-EP294	0	Monitoring Construction Activities	
8/26/2011	EP278-EP294	0	Morning perimeter survey	
8/26/2011	EP274-EP278	0	Monitoring Construction Activities	
8/26/2011	EP274-EP278	0	Site clearance survey	
8/26/2011	EP269-EP272	0	Monitoring Construction Activities	
8/26/2011	EP269-EP272	0	Morning perimeter survey	
8/25/2011	I-8 Island	0	Morning perimeter survey	
8/25/2011	EP269-EP273	0	Monitoring Construction Activities	
8/25/2011	EP269-EP273	0	Morning perimeter survey	
8/25/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities	
8/25/2011	EP278-EP294	0	Evening perimeter survey	
8/25/2011	EP278-EP294	0	Monitoring Construction Activities	
8/25/2011	EP278-EP294	0	Morning perimeter survey	
8/25/2011	EP274-EP278	0	Monitoring Construction Activities	
8/25/2011	EP274-EP278	0	Site clearance survey	

PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments	
8/25/2011	EP270-EP272	0	Site clearance survey	
8/25/2011	EP269-EP272	0	Monitoring Construction Activities	
8/25/2011	EP269-EP272	0	Morning perimeter survey	
8/24/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities	
8/24/2011	EP300-EP312, EP263B-EP267	0	Site clearance survey	
8/24/2011	EP269-EP273	0	Monitoring Construction Activities	
8/24/2011	EP269-EP273	0	Site clearance survey	
8/24/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities	
8/24/2011	EP278-EP294	0	Evening perimeter survey	
8/24/2011	EP278-EP294	0	Monitoring Construction Activities	
8/24/2011	EP278-EP294	0	Morning perimeter survey	
8/24/2011	EP274-EP278	0	Monitoring Construction Activities	
8/24/2011	EP274-EP278	0	Site clearance survey	
8/23/2011	I-8 Island	0	Morning perimeter survey	
8/23/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities	
8/23/2011	EP300-EP312, EP263B-EP267	0	Site clearance survey	
8/23/2011	EP269-EP273	0	Monitoring Construction Activities	
8/23/2011	EP269-EP273	0	Site clearance survey	
8/23/2011	EP278-EP294	0	Evening perimeter survey	
8/23/2011	EP278-EP294	0	Monitoring Construction Activities	
8/23/2011	EP278-EP294	0	Morning perimeter survey	
8/23/2011	EP274-EP278	0	Monitoring Construction Activities	
8/23/2011	EP274-EP278	0	Morning perimeter survey	
8/23/2011	EP270-EP272	0	Morning perimeter survey	
8/23/2011	EP269-EP272	0	Morning perimeter survey	
8/22/2011	EP300-EP312, EP263B-EP267	0	Monitoring Construction Activities	
8/22/2011	EP300-EP312, EP263B-EP267	0	Morning perimeter survey	
8/22/2011	EP269-EP273	0	Monitoring Construction Activities	
8/22/2011	EP269-EP273	0	Monitoring Construction Activities	
8/22/2011	EP269-EP273	0	Morning perimeter survey	
8/22/2011	EP263B	0	Monitoring Construction Activities	
8/22/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities	
8/22/2011	EP291	0	Monitoring Construction Activities	
8/22/2011	EP278-EP294	0	Evening perimeter survey	
8/22/2011	EP278-EP294	0	Monitoring Construction Activities	

PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments	
8/22/2011	EP278-EP294	0	Morning perimeter survey	
8/21/2011	I-8 Island	11	Evening perimeter survey - 6:00pm	
8/21/2011	EP269-EP273	0	Site clearance survey	
8/21/2011	EP256-EP263A-2, AER Yard	0	Monitoring Construction Activities	
8/21/2011	EP256-EP263	0	Monitoring Construction Activities	
8/21/2011	EP256-EP263	0	Site clearance survey	
8/21/2011	EP279-EP294	0	Afternoon clearance survey	
8/21/2011	EP274-EP278	0	Evening perimeter survey	
8/21/2011	EP269-EP272	0	Evening perimeter survey	
8/21/2011	EP263B-EP267	0	Site clearance survey	
8/20/2011	18 and Moutain Spring Rd	3	Morning perimeter survey 9:20am	
8/20/2011	18 and Moutain Spring Rd	4	Evening perimeter survey 6:40pm	
8/20/2011	EP300-EP312	0	Monitoring construction activities	
8/20/2011	EP300-EP312	0	Site clearance survey	
8/20/2011	EP269-EP273	0	Monitoring construction activities	
8/20/2011	EP269-EP273	0	Site clearance survey	
8/20/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
8/20/2011	EP300-EP306	0	Morning perimeter survey	
8/20/2011	EP274-EP294	0	Monitoring construction activities	
8/20/2011	EP274-EP294	0	Site clearance survey	
8/20/2011	EP270-EP271	0	Morning perimeter survey	
8/20/2011	EP269-EP271	0	Monitoring construction activities	
8/20/2011	EP263B-EP267	0	Site clearance survey	
8/19/2011	Radiator Water Tower 17	7	Site clearance survey	
8/19/2011	EP298, EP300 & EP307	0	Site clearance survey	
8/19/2011	EP296, EP300	0	Monitoring construction activities	
8/19/2011	EP296, EP300	0	Site clearance survey	
8/19/2011	EP269-EP273	0	Monitoring construction activities	
8/19/2011	EP269-EP273	0	Site clearance survey	
8/19/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
8/19/2011	EP291-EP293	0	Monitoring construction activities	
8/19/2011	EP279-EP294	0	Monitoring construction activities	
8/19/2011	EP274-EP278	0	Monitoring construction activities	
8/19/2011	EP274-EP278	0	Site clearance survey	
8/19/2011	EP263B-EP267	0	Site clearance survey	

PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments	
8/18/2011	EP269-EP273	0	Monitoring construction activities	
8/18/2011	EP269-EP273	0	Site clearance survey	
8/18/2011	EP349, EP293	0	Monitoring construction activities	
8/18/2011	EP279-EP312	0	Monitoring construction activities	
8/18/2011	EP274-EP278	0	Monitoring construction activities	
8/18/2011	EP274-EP278	0	Site clearance survey	
8/18/2011	EP263B-EP267	0	Site clearance survey	
8/17/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities	
8/17/2011	EP300-EP312, EP290-EP294	0	Site clearance survey	
8/17/2011	EP269-EP273	0	Monitoring construction activities	
8/17/2011	EP269-EP273	0	Site clearance survey	
8/17/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
8/17/2011	EP279-EP294	0	Monitoring construction activities	
8/17/2011	EP279-EP294	0	Site clearance survey	
8/17/2011	EP274-EP278	0	Monitoring construction activities	
8/17/2011	EP274-EP278	0	Site clearance survey	
8/17/2011	EP263B-EP267	0	Site clearance survey	
8/16/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities	
8/16/2011	EP300-EP312, EP290-EP294	0	Site clearance survey	
8/16/2011	EP269-EP273	0	Monitoring construction activities	
8/16/2011	EP269-EP273	0	Site clearance survey	
8/16/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
8/16/2011	EP279-EP294	0	Monitoring construction activities	
8/16/2011	EP279-EP294	0	Site clearance survey	
8/16/2011	EP274-EP278	0	Monitoring construction activities	
8/16/2011	EP274-EP278	0	Site clearance survey	
8/16/2011	EP265	0	Monitoring construction activities	
8/16/2011	EP263B-EP267	0	Site clearance survey	
8/15/2011	Fromm and AER Construction Yard	0	Monitoring construction activities	
8/15/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities	
8/15/2011	EP300-EP312, EP290-EP294	0	Site clearance survey	
8/15/2011	EP294	0	Monitoring construction activities	
8/15/2011	EP269-EP273	0	Site clearance survey	
8/15/2011	EP269-EP273	0	Monitoring construction activities	
8/15/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	

PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments	
8/15/2011	EP279-EP294	0	Monitoring construction activities	
8/15/2011	EP279-EP294	0	Site clearance survey	
8/15/2011	EP274-EP278	0	Monitoring construction activities	
8/15/2011	EP274-EP278	0	Site clearance survey	
8/15/2011	EP263B-EP267	0	Site clearance survey	
8/14/2011	EP274-EP278	0	Monitoring construction activities	
8/14/2011	EP263B-EP267	0	Site clearance survey	
8/14/2011	EP274-EP278	0	Evening perimeter survey	
8/14/2011	EP279-294	0	Monitoring construction activities	
8/14/2011	EP269-EP273	0	Evening perimeter survey	
8/14/2011	EP300-EP312	0	Site clearance survey	
8/14/2011	EP300-EP312	0	Monitoring construction activities	
8/13/2011	Fromm Construction Yard	0	Site clearance survey	
8/13/2011	I-8 Island	19	Morning perimeter survey at 9:54am - 10:45am	
8/13/2011	I-8 Island	6	Evening perimeter survey at 4:35pm	
8/13/2011	EP263B-EP267	0	Site clearance survey	
8/13/2011	EP269-EP271	0	Monitoring construction activities	
8/13/2011	EP270-EP271	0	Monitoring construction activities	
8/13/2011	EP274-EP278	0	Monitoring construction activities	
8/13/2011	EP279-294	0	Monitoring construction activities	
8/13/2011	EP300-EP306	0	Monitoring construction activities	
8/13/2011	EP259B	0	Site clearance survey	
8/13/2011	EP269-EP273	0	Monitoring construction activities	
8/13/2011	EP300-EP312, EP290-EP294	0	Site clearance survey	
8/13/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities	
8/12/2011	I-8 Island	26	Evening perimeter survey at 4:25pm - 5:45	
8/12/2011	EP263B-EP267	0	Site clearance survey	
8/12/2011	EP269-EP271	0	Monitoring construction activities	
8/12/2011	EP270-EP271	0	Monitoring construction activities	
8/12/2011	EP279-294	0	Monitoring construction activities	
8/12/2011	EP300-EP306	0	Monitoring construction activities	
8/12/2011	EP300-EP312	0	Monitoring construction activities	
8/12/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
8/12/2011	EP259B	0	Site clearance survey	
8/12/2011	EP269-EP273	0	Monitoring construction activities	

PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments	
8/12/2011	EP274-EP278, EP290-EP294	0	Site clearance survey	
8/12/2011	EP274-EP278, EP290-EP294	0	Monitoring construction activities	
8/12/2011	EP294	0	Monitoring construction activities	
8/11/2011	I-8 Island	12	Morning perimeter survey at 10:50am	
8/11/2011	I-8 Island	28	Evening perimeter survey at 6:19pm	
8/11/2011	EP263B-EP267	0	Site clearance survey	
8/11/2011	EP269-EP271	0	Monitoring construction activities	
8/11/2011	EP270-EP271	0	Monitoring construction activities	
8/11/2011	EP279-294	0	Monitoring construction activities	
8/11/2011	EP300-EP306	0	Monitoring construction activities	
8/11/2011	EP300-EP312	0	Monitoring construction activities	
8/11/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
8/11/2011	EP259B	0	Site clearance survey	
8/11/2011	EP269-EP273	0	Monitoring construction activities	
8/11/2011	EP274-EP278	0	Site clearance survey	
8/11/2011	EP274-EP278	0	Monitoring construction activities	
8/11/2011	EP292-EP356	0	Monitoring construction activities	
8/11/2011	EP294	0	Monitoring construction activities	
8/10/2011	I-8 Island	16	Evening perimeter survey at 4:55pm - 5:08	
8/10/2011	EP263B-EP267	0	Site clearance survey	
8/10/2011	EP269-EP271	0	Monitoring construction activities	
8/10/2011	EP270-EP271	0	Monitoring construction activities	
8/10/2011	EP273	0	Monitoring construction activities	
8/10/2011	EP300-EP306	0	Monitoring construction activities	
8/10/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
8/10/2011	EP259B	0	Site clearance survey	
8/10/2011	EP269-EP273	0	Monitoring construction activities	
8/10/2011	EP294	0	Monitoring construction activities	
8/10/2011	EP300-EP312	0	Morning perimeter survey	
8/10/2011	EP300-EP312	0	Monitoring construction activities	
8/10/2011	EP300-EP312	0	Evening perimeter survey	
8/10/2011	EP227, EP232, EP258, EP314, EP317, EP348, EP349	0	Site clearance survey	
8/9/2011	I-8 Island	3	Morning perimeter survey at 10:30am	
8/9/2011	I-8 Island	18	Evening perimeter survey at 4:30pm - 5:06pm	
8/9/2011	EP263B-EP267	0	Site clearance survey	

	PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments		
8/9/2011	EP269-EP271	0	Monitoring construction activities		
8/9/2011	EP270-EP271	0	Monitoring construction activities		
8/9/2011	EP270-EP273	0	Monitoring construction activities		
8/9/2011	EP274-EP278	0	Monitoring construction activities		
8/9/2011	EP279-294	0	Monitoring construction activities		
8/9/2011	EP300-EP306	0	Monitoring construction activities		
8/9/2011	EP305	0	Monitoring construction activities		
8/9/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities		
8/9/2011	EP269-EP273	0	Site clearance survey		
8/9/2011	EP294	0	Monitoring construction activities		
8/9/2011	EP300-EP312	0	Morning perimeter survey		
8/9/2011	EP300-EP312	0	Monitoring construction activities		
8/9/2011	EP300-EP312	0	Evening perimeter survey		
8/8/2011	I-8 Island	4	Morning perimeter survey at 9:45am - 9:55am		
8/8/2011	I-8 Island	22	Evening perimeter survey at 4:24pm - 5:14pm		
8/8/2011	EP279-294	3	Monitoring construction activities		
8/8/2011	EP263B-EP267	0	Site clearance survey		
8/8/2011	EP269-EP271	0	Monitoring construction activities		
8/8/2011	EP270-EP271	0	Monitoring construction activities		
8/8/2011	EP273	0	Monitoring construction activities		
8/8/2011	EP274-EP278	0	Monitoring construction activities		
8/8/2011	EP300-EP306	0	Monitoring construction activities		
8/8/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities		
8/8/2011	EP269-EP273	0	Site clearance survey		
8/8/2011	EP294	0	Monitoring construction activities		
8/8/2011	EP300-EP312	0	Morning perimeter survey		
8/8/2011	EP300-EP312	0	Monitoring construction activities		
8/8/2011	EP300-EP312	0	Evening perimeter survey		
8/8/2011	EP301-EP324, EP259-3, EP259B	0	Monitoring construction activities		
8/8/2011	EP290-EP300	0	Site clearance survey		
8/7/2011	I-8 Island	27	Evening perimeter survey at 6:00pm - 6:45		
8/7/2011	EP263B-EP267	0	Site clearance survey		
8/7/2011	EP270-EP271	0	Monitoring construction activities		
8/7/2011	EP274-EP278	0	Monitoring construction activities		
8/7/2011	EP279-294	0	Monitoring construction activities		

	PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments		
8/7/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities		
8/7/2011	EP269-EP273	0	Evening perimeter survey		
8/7/2011	EP300-EP312	0	Evening perimeter survey		
8/6/2011	EP278 & EP277	0	Monitoring construction activities		
8/6/2011	I-8 Island	12	Afternoon perimeter survey at 1:20pm		
8/6/2011	EP263B-EP267	0	Site clearance survey		
8/6/2011	EP269-EP271	0	Monitoring construction activities		
8/6/2011	EP270-EP271	0	Monitoring construction activities		
8/6/2011	EP274-EP278	0	Monitoring construction activities		
8/6/2011	EP279-294	0	Monitoring construction activities		
8/6/2011	EP300-EP306	0	Monitoring construction activities		
8/6/2011	EP262, EP266, EP267	0	Site clearance survey		
8/6/2011	EP269-EP273	0	Monitoring construction activities		
8/6/2011	EP307-EP315	0	Morning perimeter survey		
8/6/2011	EP307-EP316	0	Monitoring construction activities		
8/6/2011	EP307-EP317	0	Evening perimeter survey		
8/5/2011	EP263B-EP267	0	Site clearance survey		
8/5/2011	EP271, EP273, EP274, EP277 and EP278	0	Monitoring construction activities		
8/5/2011	EP274-EP278	0	Monitoring construction activities		
8/5/2011	EP279-294	0	Monitoring construction activities		
8/5/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities		
8/5/2011	EP269-EP273	0	Monitoring construction activities		
8/5/2011	EP294	0	Monitoring construction activities		
8/5/2011	EP307-EP312	0	Morning perimeter survey		
8/5/2011	EP307-EP313	0	Monitoring construction activities		
8/5/2011	EP307-EP314	0	Evening perimeter survey		
8/4/2011	I-8 Island	23	Evening perimeter survey at 4:00pm - 4:33pm		
8/4/2011	EP263B-EP267	0	Site clearance survey		
8/4/2011	EP269-EP271	0	Monitoring construction activities		
8/4/2011	EP270-EP271	0	Monitoring construction activities		
8/4/2011	EP274-EP278	0	Monitoring construction activities		
8/4/2011	EP279-294	0	Monitoring construction activities		
8/4/2011	EP300-EP306	0	Monitoring construction activities		
8/4/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities		
8/4/2011	EP269-EP273	0	Monitoring construction activities		

	PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments		
8/4/2011	EP294	0	Monitoring construction activities		
8/3/2011	I-8 Island	17	Evening perimeter survey at 5:45pm - 6:05pm		
8/3/2011	EP256-EP263	0	Monitoring construction activities		
8/3/2011	EP263B-EP267	0	Site clearance survey		
8/3/2011	EP269-EP271	0	Monitoring construction activities		
8/3/2011	EP270-EP271	0	Monitoring construction activities		
8/3/2011	EP274-EP278	0	Monitoring construction activities		
8/3/2011	EP279-294	0	Monitoring construction activities		
8/3/2011	EP290-EP312	0	Monitoring construction activities		
8/3/2011	EP300-EP306	0	Monitoring construction activities		
8/3/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities		
8/3/2011	EP269/EP270 Pullsite	0	Monitoring construction activities		
8/3/2011	EP269-EP273	0	Monitoring construction activities		
8/3/2011	EP271	0	Monitoring construction activities		
8/3/2011	EP294	0	Monitoring construction activities		
8/3/2011	EP300-EP312, EP290-EP294	0	Site clearance survey		
8/3/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities		
8/3/2011	I-8 Island	0	Monitoring construction activities		
8/2/2011	I-8 Island	12	Morning perimeter survey at 9:50am		
8/2/2011	I-8 Island	23	Evening perimeter survey at 4:30pm		
8/2/2011	EP263B-EP267	0	Site clearance survey		
8/2/2011	EP269-EP271	0	Monitoring construction activities		
8/2/2011	EP270-EP271	0	Monitoring construction activities		
8/2/2011	EP279-294	0	Monitoring construction activities		
8/2/2011	EP300-EP306	0	Monitoring construction activities		
8/2/2011	EP269/EP270 Pullsite	0	Monitoring construction activities		
8/2/2011	EP269-EP273	0	Monitoring construction activities		
8/2/2011	EP271 and EP273	0	Monitoring construction activities		
8/2/2011	EP273	0	Monitoring construction activities		
8/2/2011	EP274-EP278	0	Monitoring construction activities		
8/2/2011	EP294	0	Monitoring construction activities		
8/1/2011	I-8 Island	19	Morning perimeter survey at 10:00 - 10:20am		
8/1/2011	I-8 Island	1	Evening perimeter survey at 4:30pm		
8/1/2011	EP263B-EP267	0	Site clearance survey		
8/1/2011	EP269-EP271	0	Monitoring construction activities		

PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments	
8/1/2011	EP270-EP271	0	Monitoring construction activities	
8/1/2011	EP274-EP278	0	Monitoring construction activities	
8/1/2011	EP279-294	0	Monitoring construction activities	
8/1/2011	EP290-EP312	0	Monitoring construction activities	
8/1/2011	EP300-EP306	0	Monitoring construction activities	
8/1/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
8/1/2011	EP269	0	Monitoring construction activities	
8/1/2011	EP269-EP273	0	Monitoring construction activities	
8/1/2011	EP272	0	Monitoring construction activities	
8/1/2011	EP291 & EP301-EP304	0	Monitoring construction activities	
8/1/2011	EP300-EP312, EP290-EP294	0	Site clearance survey	
8/1/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities	
7/31/2011	I-8 Island	24	Evening perimeter survey at 5:55pm	
7/31/2011	EP263B-EP267	0	Site clearance survey	
7/31/2011	EP270-EP271	0	Monitoring construction activities	
7/31/2011	EP274-EP278	0	Monitoring construction activities	
7/31/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/31/2011	EP269-EP273	0	Evening perimeter survey	
7/31/2011	EP279-EP294	0	Site clearance survey	
7/31/2011	EP300-EP312, EP290-EP294	0	Site clearance survey	
7/30/2011	EP271	1	Morning perimeter survey at 7:00am	
			Monitoring during construction activities. These sheep were outside of all work	
7/30/2011	EP256-EP263A-2, AER Yard	6	areas and associated buffers and did not impact work.	
7/30/2011	I-8 Island	11	Morning perimeter survey at 10:15am - 11:07	
7/30/2011	I-8 Island	7	Evening perimeter survey at 4:12pm	
7/30/2011	EP263B-EP267	0	Site clearance survey	
7/30/2011	EP269	0	Site clearance survey	
7/30/2011	EP269-EP272	0	Monitoring construction activities	
7/30/2011	EP270-EP271	0	Monitoring construction activities	
7/30/2011	EP274-EP278	0	Monitoring construction activities	
7/30/2011	EP279-294	0	Monitoring construction activities	
7/30/2011	EP300-EP306	0	Monitoring construction activities	
7/30/2011	EP269	0	Monitoring construction activities	
7/30/2011	EP269-EP273	0	Site clearance survey	
7/30/2011	EP270-EP271	0	Monitoring construction activities	

PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments	
7/30/2011	EP300-EP312, EP290-EP294	0	Site clearance survey	
7/30/2011	EP300-EP312, EP290-EP294	0	Monitoring construction activities	
7/29/2011	I-8 Island	14	Morning perimeter survey at 8:55am	
7/29/2011	I-8 Island	2	Evening perimeter survey at 4:00pm	
7/29/2011	EP263B-EP267	0	Site clearance survey	
7/29/2011	EP269	0	Site clearance survey	
7/29/2011	EP269-EP272	0	Monitoring construction activities	
7/29/2011	EP270-EP271	0	Monitoring construction activities	
7/29/2011	EP274-EP278	0	Monitoring construction activities	
7/29/2011	EP279-294	0	Monitoring construction activities	
7/29/2011	EP300-EP306	0	Monitoring construction activities	
7/29/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/29/2011	EP269	0	Monitoring construction activities	
7/29/2011	EP269-EP273	0	Site clearance survey	
7/29/2011	EP270	0	Monitoring construction activities	
7/29/2011	EP300-EP312	0	Morning perimeter survey	
7/29/2011	EP300-EP312	0	Monitoring construction activities	
7/29/2011	EP300-EP312	0	Evening perimeter survey	
7/29/2011	EP303	0	Monitoring construction activities	
7/28/2011	EP269	4	Monitoring during construction activities	
7/28/2011	I-8 Island	11	Morning perimeter survey at 9:19am	
7/28/2011	I-8 Island	8	Evening perimeter survey at 4:00pm - 4:50pm	
7/28/2011	EP279-294	0	Monitoring construction activities	
7/28/2011	EP263B-EP267	0	Site clearance survey	
7/28/2011	EP269	0	Site clearance survey	
7/28/2011	EP270-EP271	0	Monitoring construction activities	
7/28/2011	EP274-EP278	0	Monitoring construction activities	
7/28/2011	EP300-EP306	0	Monitoring construction activities	
7/28/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/28/2011	EP269	0	Monitoring construction activities	
7/28/2011	EP270	0	Monitoring construction activities	
7/28/2011	EP300-EP312	0	Morning perimeter survey	
7/28/2011	EP300-EP312	0	Monitoring construction activities	
7/28/2011	EP300-EP312	0	Evening perimeter survey	
7/28/2011	AER CY	0	Site clearance survey	

	PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments		
7/27/2011	I-8 Island	13	Evening perimeter survey at 6:30pm - 7:00pm		
7/27/2011	EP279-294	0	Monitoring construction activities		
7/27/2011	EP263B-EP267	0	Site clearance survey		
7/27/2011	EP268 - EP263	0	Monitoring construction activities		
7/27/2011	EP269	0	Site clearance survey		
7/27/2011	EP270-EP271	0	Monitoring construction activities		
7/27/2011	EP274-EP278	0	Monitoring construction activities		
7/27/2011	EP300-EP306	0	Monitoring construction activities		
7/27/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities		
7/27/2011	EP269-EP273	0	Morning perimeter survey		
7/27/2011	EP269-EP273	0	Evening perimeter survey		
7/27/2011	EP300-EP312	0	Morning perimeter survey		
7/27/2011	EP300-EP312	0	Monitoring construction activities		
7/27/2011	EP300-EP312	0	Evening perimeter survey		
7/26/2011	Devils Canyon Bridge1, Hwy 8	1	Monitoring during construction activities		
7/26/2011	I-8 Island	24	Morning perimeter survey at 9:46am - 10:45am		
7/26/2011	I-8 Island	7	Evening perimeter survey at 6:17pm - 6:50pm		
7/26/2011	EP263B-EP267	0	Site clearance survey		
7/26/2011	EP269	0	Site clearance survey		
7/26/2011	EP270	0	Monitoring construction activities		
7/26/2011	EP274-EP278	0	Monitoring construction activities		
7/26/2011	EP279-294	0	Monitoring construction activities		
7/26/2011	EP300-EP306	0	Monitoring construction activities		
7/26/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities		
7/26/2011	EP269-EP273	0	Morning perimeter survey		
7/26/2011	EP269-EP273	0	Evening perimeter survey		
7/26/2011	EP300-EP312	0	Monitoring construction activities		
7/26/2011	EP300-EP312	0	Morning perimeter survey		
7/26/2011	EP300-EP312	0	Monitoring construction activities		
7/26/2011	EP300-EP312	0	Evening perimeter survey		
7/25/2011	I-8 Island	21	Morning perimeter survey at 8:47am		
7/25/2011	I-8 Island	20	Evening perimeter survey at 6:37am		
7/25/2011	EP263B-EP267	0	Site clearance survey		
7/25/2011	EP269	0	Site clearance survey		
7/25/2011	EP270	0	Monitoring construction activities		

PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments	
7/25/2011	EP274-EP278	0	Monitoring construction activities	
7/25/2011	EP279-294	0	Monitoring construction activities	
7/25/2011	EP300-EP306	0	Monitoring construction activities	
7/25/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/25/2011	EP269-EP273	0	Morning perimeter survey	
7/25/2011	EP269-EP273	0	Evening perimeter survey	
7/25/2011	EP300 & EP302	0	Monitoring construction activities	
7/25/2011	EP300-EP312	0	Morning perimeter survey	
7/25/2011	EP300-EP312	0	Monitoring construction activities	
7/25/2011	EP300-EP312	0	Evening perimeter survey	
7/25/2011	EP276	0	Monitoring construction activities	
7/24/2011	I-8 Island	13	Evening perimeter survey at 6:25pm	
7/24/2011	EP263B-EP267	0	Site clearance survey	
7/24/2011	EP269	0	Site clearance survey	
7/24/2011	EP270	0	Monitoring construction activities	
7/24/2011	EP279-294	0	Monitoring construction activities	
7/24/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/24/2011	EP269-EP273	0	Evening perimeter survey	
7/24/2011	EP274-EP278	0	Evening perimeter survey	
7/24/2011	EP300-EP312	0	Evening perimeter survey	
7/23/2011	EP263B-EP267	0	Site clearance survey	
7/23/2011	EP269	0	Site clearance survey	
7/23/2011	EP270	0	Monitoring construction activities	
7/23/2011	EP279-294	0	Monitoring construction activities	
7/23/2011	EP300-EP312	0	Monitoring construction activities	
7/23/2011	EP300-EP312	0	Site clearance survey	
7/23/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/23/2011	EP269-EP276	0	Morning perimeter survey	
7/23/2011	EP274-EP278	0	Morning perimeter survey	
7/23/2011	EP274-EP278	0	Evening perimeter survey	
7/23/2011	I-8 Island	0	Morning perimeter survey	
7/22/2011	I-8 Island	18	Evening perimeter survey at 6:35pm	
7/22/2011	EP263B-EP267	0	Site clearance survey	
7/22/2011	EP269	0	Site clearance survey	
7/22/2011	EP269-EP270	0	Monitoring construction activities	

PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments	
7/22/2011	EP270	0	Monitoring construction activities	
7/22/2011	EP300-EP312	0	Monitoring construction activities	
7/22/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/22/2011	EP269-EP273	0	Morning perimeter survey	
7/22/2011	EP269-EP273	0	Evening perimeter survey	
7/22/2011	EP274-EP278	0	Site clearance survey	
7/22/2011	EP274-EP278	0	Monitoring construction activities	
7/21/2011	I-8 Island	18	Evening perimeter survey at 6:35pm	
7/21/2011	EP263B-EP267	0	Site clearance survey	
7/21/2011	EP269	0	Site clearance survey	
7/21/2011	EP269-EP270	0	Monitoring construction activities	
7/21/2011	EP270	0	Monitoring construction activities	
7/21/2011	EP279-294	0	Monitoring construction activities	
7/21/2011	EP300-EP312	0	Monitoring construction activities	
7/21/2011	EP300-EP306	0	Site clearance survey	
7/21/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/21/2011	EP269-EP273	0	Morning perimeter survey	
7/21/2011	EP269-EP273	0	Evening perimeter survey	
7/21/2011	EP274-EP278	0	Morning perimeter survey	
7/21/2011	EP274-EP278	0	Evening perimeter survey	
7/20/2011	I-8 Island	4	Evening perimeter survey at 6:50pm	
7/20/2011	EP269-EP273	0	Morning perimeter survey	
7/20/2011	EP269-EP273	0	Evening perimeter survey	
7/20/2011	EP263B-EP267	0	Site clearance survey	
7/20/2011	EP269	0	Site clearance survey	
7/20/2011	EP270	0	Monitoring construction activities	
7/20/2011	EP279-294	0	Monitoring construction activities	
7/20/2011	EP300-EP312	0	Monitoring construction activities	
7/20/2011	EP300-EP306	0	Site clearance survey	
7/20/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/20/2011	EP274-EP278	0	Morning perimeter survey	
7/20/2011	EP274-EP278	0	Evening perimeter survey	
7/19/2011	I-8 Island	10	Morning perimeter survey at 9:10am	
7/19/2011	I-8 Island	17	Evening perimeter survey at 4:00pm - 6:40pm	
7/19/2011	EP269-EP273	0	Morning perimeter survey	

PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments	
7/19/2011	EP269-EP273	0	Evening perimeter survey	
7/19/2011	EP269	0	Site clearance survey	
7/19/2011	EP270	0	Monitoring construction activities	
7/19/2011	EP279-294	0	Monitoring construction activities	
7/19/2011	EP300-EP312	0	Monitoring construction activities	
7/19/2011	EP300-EP306	0	Site clearance survey	
7/19/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/19/2011	EP274-EP278	0	Morning perimeter survey	
7/19/2011	EP274-EP278	0	Evening perimeter survey	
7/19/2011	EP263B-EP267	0	Site clearance survey	
7/18/2011	I-8 Island	21	Evening perimeter survey at 7:10pm	
7/18/2011	EP263B-EP267	0	Site clearance survey	
7/18/2011	EP269	0	Site clearance survey	
7/18/2011	EP270	0	Monitoring construction activities	
7/18/2011	EP279-294	0	Monitoring construction activities	
7/18/2011	EP300-EP312	0	Monitoring construction activities	
7/18/2011	EP300-EP306	0	Site clearance survey	
7/18/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/18/2011	EP274-EP278	0	Morning perimeter survey	
7/18/2011	EP274-EP278	0	Evening perimeter survey	
7/18/2011	EP269-EP273	0	Site clearance survey	
7/17/2011	I-8 Island	17	Evening perimeter survey at 5:55pm - 6:25	
7/17/2011	EP263B-EP267	0	Site clearance survey	
7/17/2011	EP269	0	Site clearance survey	
7/17/2011	EP270	0	Monitoring construction activities	
7/17/2011	EP300-EP312	0	Monitoring construction activities	
7/17/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/17/2011	EP274-EP278	0	Evening perimeter survey	
7/17/2011	EP279-EP294	0	Site clearance survey	
7/17/2011	EP269-EP273	0	Site clearance survey	
7/16/2011	I-8 Island	1	Morning perimeter survey at 8:35am	
7/16/2011	EP263B-EP267	0	Site clearance survey	
7/16/2011	EP269	0	Site clearance survey	
7/16/2011	EP270	0	Monitoring construction activities	
7/16/2011	EP300-EP306	0	Monitoring construction activities	

PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments	
7/16/2011	EP300-EP312	0	Monitoring construction activities	
7/16/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/16/2011	EP274-EP278	0	Morning perimeter survey	
7/16/2011	EP279-EP294	0	Morning perimeter survey	
7/16/2011	EP279-EP294	0	Site clearance survey	
7/16/2011	EP279-EP294	0	Monitoring construction activities	
7/16/2011	EP269-EP273	0	Site clearance survey	
7/15/2011	EP273-1	1	Evening perimeter survey at 4:30pm	
7/15/2011	I-8 Island	12	Evening perimeter survey at 6:35pm - 7:00pm	
7/15/2011	EP263B-EP267	0	Site clearance survey	
7/15/2011	EP269	0	Site clearance survey	
7/15/2011	EP270	0	Monitoring construction activities	
7/15/2011	EP279-294	0	Monitoring construction activities	
7/15/2011	EP300-EP306	0	Monitoring construction activities	
7/15/2011	EP300-EP312	0	Monitoring construction activities	
7/15/2011	EP256-EP263A-2, AER Yard	0	Site clearance survey	
7/15/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/15/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey	
7/15/2011	EP269-EP273	0	Site clearance survey	
7/15/2011	EP274-EP278	0	Morning perimeter survey	
7/15/2011	EP274-EP278	0	Evening perimeter survey	
7/14/2011	I-8 Island	3	Evening perimeter survey at 4:10pm	
7/14/2011	I-8 Island		7:15am - 9:30am PBHS were at above point	
7/14/2011	EP263B-EP267	0	Site clearance survey	
7/14/2011	EP269	0	Site clearance survey	
7/14/2011	EP270	0	Monitoring construction activities	
7/14/2011	EP279-294	0	Monitoring construction activities	
7/14/2011	EP300-EP306	0	Monitoring construction activities	
7/14/2011	EP300-EP312	0	Monitoring construction activities	
7/14/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey	
7/14/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/14/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey	
7/14/2011	EP274-EP278	0	Morning perimeter survey	
7/14/2011	EP274-EP278	0	Evening perimeter survey	
7/14/2011	EP269-EP273	0	Site clearance survey	

PBHS Monitoring Report - Week Ending 09/03/11			
Date	Location	Number observed	Comments
7/13/2011	I-8 Island	21	Evening perimeter survey at 4:40pm
7/13/2011	EP263B-EP267	0	Site clearance survey
7/13/2011	EP269	0	Site clearance survey
7/13/2011	EP270	0	Monitoring construction activities
7/13/2011	EP279-294	0	Monitoring construction activities
7/13/2011	EP300-EP306	0	Monitoring construction activities
7/13/2011	EP300-EP312	0	Monitoring construction activities
7/13/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/13/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/13/2011	EP269-EP273	0	Site clearance survey
7/12/2011	EP256-EP263A-2, AER Yard	15	Monitoring during construction activities @ 7:40am - 11:00am
7/12/2011	I-8 Island	17	Evening perimeter survey at 4:00pm
7/12/2011	EP263B-EP267	0	Site clearance survey
7/12/2011	EP269	0	Site clearance survey
7/12/2011	EP270	0	Monitoring construction activities
7/12/2011	EP279-294	0	Monitoring construction activities
7/12/2011	EP300-EP306	0	Monitoring construction activities
7/12/2011	EP300-EP312	0	Monitoring construction activities
7/12/2011	EP274-EP278	0	Morning perimeter survey
7/12/2011	EP274-EP278	0	Evening perimeter survey
7/12/2011	EP269-EP273	0	Site clearance survey
7/11/2011	I-8 Island	29	Evening perimeter survey at 4:40pm
7/11/2011	EP263B-EP267	0	Site clearance survey
7/11/2011	EP269	0	Site clearance survey
7/11/2011	EP270	0	Monitoring construction activities
7/11/2011	EP279-294	0	Monitoring construction activities
7/11/2011	EP300-EP306	0	Monitoring construction activities
7/11/2011	EP300-EP312	0	Monitoring construction activities
7/11/2011	EP256-EP263A-2, AER Yard	0	Morning perimeter survey
7/11/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey
7/11/2011	EP269-EP273	0	Site clearance survey
7/11/2011	EP274-EP278	0	Morning perimeter survey
7/11/2011	EP274-EP278	0	Evening perimeter survey
7/10/2011	I-8 Island	8	Perimeter survey
7/10/2011	I-8 Island	20	Monitoring construction activities

PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments	
7/10/2011	EP269	0	Site clearance survey	
7/10/2011	EP270	0	Monitoring construction activities	
7/10/2011	EP279-294	0	Monitoring construction activities	
7/10/2011	EP300-EP312	0	Monitoring construction activities	
7/10/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey	
7/10/2011	EP274-EP278, EP265-EP267	0	Site clearance survey	
7/9/2011	EP263A-2	11	Evening perimeter survey	
7/9/2011	EP263B-EP267	0	Site clearance survey	
7/9/2011	EP269-EP274	0	Monitoring construction activities	
7/9/2011	EP279-294	0	Monitoring construction activities	
7/9/2011	EP300-EP307	0	Monitoring construction activities	
7/9/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/9/2011	EP269-EP273	0	Site clearance survey	
7/9/2011	EP274-EP278	0	Morning perimeter survey	
7/9/2011	EP310	0	Monitoring construction activities	
7/8/2011	EP263B-EP267	0	Site clearance survey	
7/8/2011	EP300-EP312	0	Monitoring construction activities	
7/8/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/8/2011	EP269-EP273	0	Site clearance survey	
7/8/2011	EP274-EP278	0	Morning perimeter survey	
7/8/2011	EP274-EP278	0	Evening perimeter survey	
7/8/2011	EP303	0	Monitoring construction activities	
7/8/2011	EP279-EP294	0	Monitoring construction activities	
7/7/2011	I-8 Island	8	Evening perimeter survey at 7:00pm	
7/7/2011	EP263B-EP267	0	Site clearance survey	
7/7/2011	EP269-EP273	0	Monitoring construction activities	
7/7/2011	EP300-EP312	0	Monitoring construction activities	
7/7/2011	EP300-EP307	0	Monitoring construction activities	
7/7/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities	
7/7/2011	EP269-EP273	0	Site clearance survey	
7/7/2011	EP274-EP278	0	Morning perimeter survey	
7/7/2011	EP274-EP278	0	Evening perimeter survey	
7/7/2011	EP303 & EP304	0	Monitoring construction activities	
7/7/2011	EP306-EP312	0	Site clearance survey	
7/6/2011	EP263A-2	2	Evening perimeter survey	

	PBHS Monitoring Report - Week Ending 09/03/11				
Date	Location	Number observed	Comments		
7/6/2011	EP263B-EP267	0	Site clearance survey		
7/6/2011	EP269-EP272	0	Monitoring construction activities		
7/6/2011	EP300-EP312	0	Monitoring construction activities		
7/6/2011	EP300-EP307	0	Monitoring construction activities		
7/6/2011	EP303	0	Site clearance survey		
7/6/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities		
7/6/2011	EP274-EP278	0	Morning perimeter survey		
7/6/2011	EP274-EP278	0	Evening perimeter survey		
7/6/2011	EP305 to EP304	0	Monitoring construction activities		
7/6/2011	I-8 Island	0	Monitoring construction activities		
7/6/2011	EP269-EP273	0	Site clearance survey		
7/5/2011	EP270	14	Morning perimeter survey at 6:30am - 10:00am		
7/5/2011	EP270	9	Evening perimeter survey at 5:00pm		
7/5/2011	I-8 Island	7	Evening perimeter survey at 6:20pm		
7/5/2011	EP269-EP273	0	Morning perimeter survey		
7/5/2011	EP269-EP273	0	Evening perimeter survey		
7/5/2011	EP263B-EP267	0	Site clearance survey		
7/5/2011	EP269-EP271	0	Monitoring construction activities		
7/5/2011	EP300-EP312	0	Monitoring construction activities		
7/5/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities		
7/5/2011	EP274-EP278	0	Morning perimeter survey		
7/5/2011	EP274-EP278	0	Evening perimeter survey		
7/5/2011	EP307 to EP305	0	Monitoring construction activities		
7/5/2011	I-8 Island	0	Site clearance survey		
7/4/2011	EP270	9	Perimeter survey		
7/4/2011	EP263B-EP267	0	Site clearance survey		
7/4/2011	EP300-EP312	0	Monitoring construction activities		
7/4/2011	EP256-EP263A-2, AER Yard	0	Evening perimeter survey		
7/4/2011	EP269-EP273	0	Site clearance survey		
7/4/2011	EP274-EP278	0	Evening perimeter survey		
7/4/2011	I-8 Island	0	Site clearance survey		
7/2/2011	EP263B-EP267	0	Site clearance survey		
7/2/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities		
7/2/2011	EP269-EP273	0	Site clearance survey		
7/2/2011	EP274-EP278	0	Morning perimeter survey		

	PBHS Monitoring Report - Week Ending 09/03/11								
Date	Location	Number observed	Comments						
7/2/2011	I-8 Island	0	Site clearance survey						
7/1/2011	EP263B-EP267	0	Site clearance survey						
7/1/2011	EP300-EP312	0	Monitoring construction activities						
7/1/2011	EP256-EP263A-2, AER Yard	0	Monitoring construction activities						
7/1/2011	EP269-EP273	0	Site clearance survey						
7/1/2011	EP274-EP278	0	Morning perimeter survey						
7/1/2011	EP274-EP278	0	Evening perimeter survey						
7/1/2011	I-8 Island	0	Site clearance survey						
6/30/2011	EP300-EP312	0	Monitoring construction activities						
6/29/2011	EP310-EP312	0	Monitoring construction activities						
4/15/2011	EP210, EP211, EP213-EP215, EP217-EP219	0	Monitoring construction activities						
3/26/2011	EP105	0	Site clearance survey						

			rned Liza						
Date	Location		erved	-	ıred		cated		ead
0/0/2011	Post RCLMP*	Day	Night	Day	Night	Day	Night	Day	Night
9/3/2011	SWPL AR to EP324					1			
9/3/2011	SWPL AR to EP342					1			
9/3/2011	SWPL AR to EP345							1	
9/3/2011	SWPL AR to EP344 and EP345					1			
8/31/2011	EP324					1			
8/31/2011	SWPL AR to EP325-2					1			
8/30/2011	SWPL AR to EP346 and EP347					1			
8/29/2011	SWPL AR to EP353 and EP354							1	
8/29/2011	SWPL AR to EP324					_		1	
8/27/2011	EP349					1			
8/25/2011	EP360					_		1	
8/25/2011	Btwn EP320/321					1			
8/24/2011	SWPL AR near EP346					1			
8/23/2011	EP349					1			
8/21/2011	SWPL AR btwn EP344/345					1			
8/21/2011	SWPL AR to EP345					_		1	
8/19/2011	SWPL AR to EP339					1			
8/20/2011	SWPL AR to IV Sub							1	
8/20/2011	SWPL AR btwn EP346/347					1			
8/19/2011	EP338/339 Pullsite					1			
8/19/2011	EP355/356 Pullsite					1			
8/18/2011	EP347					1			
8/18/2011	SWPL AR to EP353					_		1	
8/11/2011	SWPL AR by EP348					1			
8/11/2011	EP348/EP349 Pullsite					1			
8/10/2011	EP347					1			
8/8/2011	SWPL AR to EP351					2			
8/6/2011	BLM AR near EP327							1	
8/1/2011	IV Substation Yard	1				_			
8/1/2011	EP325					1			
8/1/2011	AR to EP345					1			
7/30/2011	EP322					1			
7/28/2011	EP355/EP356 Pullsite					1			
7/27/2011	Near EP316-2	1							
7/26/2011	SWPL AR to EP344	1				_			
7/26/2011	EP347					1			
7/26/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/25/2011	AR to IV Sub					1			
7/22/2011	AR to IV Sub					1			
7/21/2011	EP360					1			
7/21/2011	AR to EP326					1			

	Flat Tailed Horned Lizard Counts									
Date	Location		rved	Inju	ıred	Relocated		Dead		
7/19/2011	SWPL AR to IV Sub	1								
7/19/2011	EP353					1				
7/19/2011	AR to Dunaway CY					1				
7/18/2011	EP318					1				
7/17/2011	EP355					1				
7/15/2011	EP359	1								
7/15/2011	EP352	1								
7/15/2011	EP350	1								
7/14/2011	Spur Rd to EP355							1		
7/14/2011	EP322	1								
7/13/2011	EP357	1								
7/12/2011	EP344	1								
7/12/2011	SWPL AR btwn EP348/345							1		
	TOTAL	10	0	0	0	37	0	10		
	Prior to RCLMP	D	ay	D	ay	D	ay	D	ay	
7/11/2011	AR to EP352		-		-		2			
7/11/2011	AR to EP345						2			
7/10/2011	EP358					1				
7/10/2011	SWPL AR to EP354						2			
7/9/2011	AR to EP330		1							
7/8/2011	Spur Rd. to EP352		1							
7/7/2011	EP324						1			
7/7/2011	EP355						1			
7/6/2011	SWPL AR btwn EP362/363								1	
7/5/2011	EP354						1			
7/1/2011	AR to EP353		1							
6/30/2011	AR between EP310/311								1	
6/30/2011	EP358		1							
6/30/2011	EP360		1							
6/30/2011	AR to EP312								1	
6/30/2011	EP360								1	
6/27/2011	EP350						1			
6/27/2011	SWPL AR to IV Substation		2							
6/26/2011	IV Substation						1			
6/25/2011	SWPL AR to EP361		1							
6/24/2011	EP359						1			
6/23/2011	SWPL AR to EP360						<u>-</u> 2			
6/22/2011	SWPL AR to EP355					ł	 1			
6/20/2011	EP356		2							
6/20/2011	SWPL AR to EP359		<u></u> 1							
6/20/2011	Near EP356		2							
6/20/2011	AR between EP358/357		_						1	
6/18/2011	AR to Dunaway CY								<u>-</u> 1	
6/17/2011	Near EP322		1			<del> </del>			_	
0/1//2011	itcai Li JZZ		-			1				

		illea Hornea Liza	Tu Counts		
Date	Location	Observed	Injured	Relocated	Dead
6/7/2011	Near EP355	1			
6/7/2011	EP361			1	
6/7/2011	AR btwn EP343/EP344				1
6/7/2011	AR between EP324/325				1
6/6/2011	SWPL AR btwn EP344/EP345			1	
6/3/2011	EP359			1	
6/3/2011	SWPL AR EP362			1	
6/2/2011	AR to EP358			1	
6/2/2011	SWPL AR to EP316-2				1
6/2/2011	AR east of EP325				1
6/1/2011	SWPL AR btwn EP319/EP320			1	
6/1/2011	SWPL AR to EP318			1	
5/31/2011	SWPL AR btwn EP359/EP360			1	
5/31/2011	SWPL AR to EP320			1	
5/31/2011	EP360				1
5/27/2011	EP357			1	
5/26/2011	SWPL AR to EP359			1	
5/25/2011	Spur Rd to EP321			1	
5/23/2011	EP323			1	
5/21/2011	EP324			1	
5/20/2011	IV CY			1	
5/20/2011	AR to EP362			1	
5/20/2011	AR btwn EP324/EP325			1	
5/20/2011	SWPL AR btwn EP326/EP327			1	
5/20/2011	IV Substation			3	
5/19/2011	IV Substation			5	
5/19/2011	EP324			1	
5/18/2011	IV Substation Yard			1	
5/18/2011	IV Substation Yard				1
5/17/2011	AR to IV Substation				1
5/16/2011	IV Substation Yard			1	
5/13/2011	SWPL AR Near EP362-1	1			
5/12/2011	AR to EP355			1	
5/11/2011	EP360	1			
5/11/2011	Dunaway CY	3			
5/11/2011	Dunaway Yard			4	
5/10/2011	EP322	1			
5/10/2011	AR to Dunaway CY	1			
5/9/2011	Dunaway Yard			4	
5/7/2011	EP322	1			
5/7/2011	Spur Road to EP344	1			
5/7/2011	Dunaway Yard			1	
5/6/2011	AR to EP321-1	1			
5/5/2011	AR to EP321-1	1			

Date	Location	Observed	Injured	Relocated	Dead
5/5/2011	AR to Dunaway CY	2			
5/5/2011	Dunaway Yard			2	
5/4/2011	AR btwn EP343/EP344			1	
5/3/2011	SWPL AR btwn EP320/EP321	1			
4/27/2011	AR to EP322	2			
4/26/2011	EP322	1			
4/25/2011	4/25/2011 Plaster City CY				
4/20/2011	Plaster City			1	
4/18/2011	Plaster City			1	
4/14/2011	AR to IV Substation	1			
4/2/2011	4/2/2011 Dunaway CY				
	TOTAL		0	60	13
	YTD	45	0	97	23

<sup>\*</sup>RCLMP refers to the Revised Construction Lighting Mitigation Plan

### RAVEN CONTROL MONITORING Week Ending 09/03/2011

9/3/2011 9/2/2011 9/2/2011 9/2/2011	Location EP348	Number of Ravens observed			Raven Activ	vity		FTHL observed
9/2/2011 9/2/2011 9/2/2011	EP348	observed		RAVEII ACTIVITY				
9/2/2011 9/2/2011 9/2/2011	EP348		Nesting	Flying	Perching	Roosting	Scavaging	
9/2/2011 9/2/2011	EP348		No	ravens ol	bserved			
9/2/2011		1		1				no
· · ·	S2 Yard	1		1				no
0/2/2011	EP303	1		1				no
9/2/2011	EP363	2		2				1 at IV Sub
9/1/2011	EP303	2					2	no
9/1/2011	EP293	1					1	no
9/1/2011	EP304	2					2	no
8/31/2011	S2 Yard	1		1				no
8/31/2011	EP308	1		1				no
8/31/2011	EP305-3	2		_			2	no
8/31/2011	EP303	2		2				no
8/30/2011	EP303	1		1				no
8/29/2011	S2 Yard	1		1				no
8/29/2011	EP303	1	No	1				no
8/28/2011	ED20E	3	NO	ravens ol				
8/27/2011 8/26/2011	EP305 EP301	2		2	3			no
8/25/2011	S2 Yard	2					2	no no
8/25/2011	EP301	2		2				no
8/24/2011	S2 Yard	3				3		no
8/23/2011	EP292-1	3		3				no
8/22/2011	L1 232 1		No	ravens ol	hserved			110
8/21/2011				ravens of				
8/20/2011	S2 Yard	2				2		no
8/20/2011	EP312	2		2				no
8/20/2011	S2 Yard	2					2	no
8/20/2011	EP312	2		2				no
8/19/2011	EP307	2			2			no
8/19/2011	EP296	1		1				no
8/18/2011	S2 Yard	2				1	1	no
8/18/2011	EP301	Flock		х				no
8/17/2011	S2 Yard	2				1	1	no
8/17/2011	EP301	3			3			no
8/16/2011	S2 Yard	1					1	no
8/16/2011	EP301	1		1				no
8/15/2011			No	ravens ol	bserved			
8/14/2011			No	ravens ol	bserved			
8/13/2011	S2 Yard	2					2	no
8/12/2011	IV Substation	2				2		no
8/12/2011	S2 Yard	3				3	3	no
8/11/2011	EP294	4			4			no
8/11/2011	S2 Yard	3				3	3	no
8/10/2011	S2 Yard	3			1	2	1	no
8/9/2011	S2 Yard	not specified						no
8/8/2011	EP294	2			2			no
8/8/2011	S2 Yard	1						no
8/7/2011	62.4		No	ravens ol	oserved			
8/6/2011	S2 Yard	1		2	1			no
8/5/2011	EP301	3		3	-			no
8/4/2011	S2 Yard	not specified		3	1			no
8/3/2011	S2 Yard	2		2				no
8/3/2011	S2 Yard	1					2	no
8/2/2011	S2 Yard	3			1		3	no
8/1/2011 7/31/2011	EP314	not specified	NIS	x ravens ol	bconved			no

1

Date	Location	Number of Ravens observed		Raven Activity				
		observed	Nesting	Flying	Perching	Roosting	Scavaging	
7/30/2011	EP314	3		2			1	no
7/30/2011	S2 Yard	1					1	no
7/29/2011	S2 Yard	1						no
7/28/2011	EP319	4	1	2	1			no
7/28/2011	S2 Yard	not specified						no
7/27/2011	S2 Yard	not specified						no
7/26/2011			No	ravens of	oserved	,		
7/25/2011	EP290	1			1			no
7/24/2011			No	ravens of	oserved	,		
7/23/2011			No	ravens ol	oserved			
7/22/2011	EP290	2		1	1			no
7/21/2011	S2 Yard	1		1				no
7/20/2011	Ocotillo, CA	5						no
7/19/2011	Ocotillo, CA	1						no
7/18/2011	CP40-2	not specified						no
7/18/2011	CP41-2	not specified						no
7/18/2011	CP42-1	not specified						no
7/17/2011			No	ravens ol	oserved			
7/16/2011	CP42-1	not specified						no
7/15/2011		·	No	ravens ol	served	Į.	ļ.	
7/14/2011	EP357	not specified						no
7/14/2011	EP358	not specified						no
7/14/2011	EP359	not specified						no
7/14/2011	Plaster City Yard	2		2				no
7/13/2011	EP313-EP314 PS	not specified						no
7/13/2011	S2 Yard	3					3	no
7/12/2011	CP18-1	not specified						no
7/12/2011	CP19-1	not specified						no
7/12/2011	CP22-1	not specified						no
7/11/2011	EP304-EP314	not specified						no
7/10/2011		'	No	ravens ol	served	<u>!</u>	<u> </u>	
7/9/2011	EP351	not specified						no
7/9/2011	EP353	not specified						no
7/9/2011	EP354	not specified						no
7/9/2011	EP355	not specified						no
7/9/2011	not specified	not specified						no
7/9/2011	S2 Yard	3					3	no
7/8/2011	EP303	2			1		1	no
7/8/2011	EP303	1		1				no
7/8/2011	S2 Yard	3					3	no
7/1/11 - 7/7/11			No	ravens ol	oserved			
6/30/2011	EP300	3		3				no
6/21/11 - 6/29/11			No	ravens ol	oserved			
6/20/2011	S2 Yard	2					2	no
6/1/11 - 6/19/11			No	ravens ol	oserved			
5/1/11 - 5/31/11				ravens ol				
4/22/11 - 4/30/11			No	ravens ol	oserved			
4/21/2011	EP341	1	1					no
4/1/11 - 4/20/11				ravens ol	oserved			
3/1/11 - 3/31/11	No ravens observed							
2/1/11 - 2/28/11	No ravens observed							
1/21/11 - 1/31/11	No ravens observed							
1/21/2011	Rough Acres Yard	not specified						no
-,,		specifica	!	!	!	!	!	110