

Sunrise Powerlink Transmission Project

Weekly Monitoring Report No. 00010

From: 11/21/2010 Through: 11/27/2010

INTRODUCTION

During the week of 11/21/2010 through 11/27/2010, construction continued at the Alpine RFO, Alpine Construction Yards, San Luis Rey Substation, Encina Switchyard, the Rough Acres Construction Yard and the Thomas Yard.

Pre-Construction Activity with appropriate monitors:

Link 1: one crew on 11/23/2010, marking 12 kV relocation and staking TSAPs.

Link 4, Field review of alignment with CPUC Lead Monitor and Link Lead, one pot-hole conducted to verify UG utilities, monitors present, 11/24/2010.

Link 5, six crews marked towers, reference points (RPs) and ESAs along with GPS verification, 11/22/2010. Four crews marked towers, RPs and GPS verification, 11/23/2010.

ALL LINKS

Note: 11/25/2010 and 11/26/2010 Holidays

The following is a summary of construction activity where monitors were on site.

Alpine RFO: Minimal contractor activity on site as clean-up was performed and all crews stayed within flagged areas.

Alpine Construction Yard: Equipment and reels delivered on a limited basis.

San Luis Rey Substation: Installation of capacitor banks and other equipment continued. A small area of excavation conducted for a transformer pad and containment.

Rough Acres Construction Yard: Two or three deliveries of reels per day. Storage within air strip.

Encina Switchyard: No ground disturbing work being conducted. Only SDG&E on site until early December.

Thomas Yard: Deliveries of material conducted, including 11/26/2010 and 11/27/2010.

A rain event occurred on 11/23/2010 and 11/24/2010. Precipitation amounts observed: .75 at Encina Switchyard; trace amount at Alpine RFO and Construction Yards. Pre and post rain event inspection of BMPs were made with no deficiencies.

ENVIRONMENTAL MONITORS

LINK: 1

Burns & McDonnell	Janice Rodgers
Burns & McDonnell	Kelly Goocher
Chambers Group	Chris Bugbee
Chambers Group	Erik Strods
Chambers Group	Seth Reimers
Pangea Biological	Dean Lambert
Pangea Biological	Don Spires

LINK: 4

ASM Affiliates, Inc.	Thomas Taylor
Burns & McDonnell	Ken Katsuda
Chambers Group	Rob Fletcher
Chambers Group	Seth Reimers

Sunrise Powerlink Transmission Project

Weekly Monitoring Report No. 00010

From: 11/21/2010 Through: 11/27/2010

ENVIRONMENTAL MONITORS

LINK: 4

Pangea Biological Mark Meridith

LINK: ALL

Chambers Group Seth Reimers

LINK: NA

Chambers Group Brent Riemer
TRC Solutions, Inc. Lauralyn Jensen

ENVIRONMENTAL COMPLIANCE

Mitigation Measure	A	B	C	D	E	F	G	H
Date	(Y/N)	Species	Loc UTM Lat-Long	Cause	Issue	Action	Comments	Tower

LINK: 1

B-1c

11/22/2010	Y						Remarks: All work activity in compliance	Thomas Yard
------------	---	--	--	--	--	--	--	-------------

Mitigation Measure in Compliance? Y

Environ Monitor

11/22/2010	Y						area in compliance Remarks: none	Rough Acres
------------	---	--	--	--	--	--	-------------------------------------	-------------

Mitigation Measure in Compliance? Y
compliance

11/22/2010	Y						all work compliant	Thomas Yard
------------	---	--	--	--	--	--	--------------------	-------------

Mitigation Measure in Compliance? Y
Bio

11/22/2010	Y							Rough Acres
------------	---	--	--	--	--	--	--	-------------

Mitigation Measure in Compliance? Y
Bio-Monitoring

11/23/2010	Y						Remarks: All work activity in compliance	Thomas Yard
------------	---	--	--	--	--	--	--	-------------

Mitigation Measure in Compliance? Y
Environ Monitor

11/23/2010	Y						all work compliant	Thomas Yard
------------	---	--	--	--	--	--	--------------------	-------------

Mitigation Measure in Compliance? Y
Bio

Sunrise Powerlink Transmission Project

Weekly Monitoring Report No. 00010

From: 11/21/2010 Through: 11/27/2010

ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: 1								
B-1c								
11/24/2010	Y						All construction activities were in compliance with the mitigation measures and APMs	Rough Acres Ranch
Mitigation Measure in Compliance? Y								
compliance								
11/24/2010	Y						all work compliant	Thomas Yard
Mitigation Measure in Compliance? Y								
Bio								
11/26/2010	Y						all unloading and material sorting activities were in compliance with the mitigation measures and APMs	Thomas laydown yard
Mitigation Measure in Compliance? Y								
compliance								
11/27/2010	Y						All work was in compliance. A biologist was onsite.	Thomas Yard
Mitigation Measure in Compliance? Y								
compliance								
11/27/2010	Y						all unloading activities met the APMs and the mitigation measures were met	Thomas laydown yard
Mitigation Measure in Compliance? Y								
compliance								
11/27/2010	Y						All required monitors on site observing contractor activity.	Thomas Yard
Mitigation Measure in Compliance? Y								
Compliance								
P-3b								
11/27/2010	N						No vehicles idled unnecessarily.	Thomas Yard
Mitigation Measure in Compliance? Y								
compliance								
WQ-APM-13								
11/27/2010	N						No leaks or spills were discovered.	Thomas Yard
Mitigation Measure in Compliance? Y								
compliance								
11/27/2010	N						Contractor equipment and work area visually inspected throughout the day. No leaks or spills observed.	Thomas Yard
Mitigation Measure in Compliance? Y								
compliance								

Sunrise Powerlink Transmission Project

Weekly Monitoring Report No. 00010

From: 11/21/2010 Through: 11/27/2010

ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
-------------------------	---------	-----------	--------------------	---------	---------	----------	------------	---------

LINK: 4

B-1c

11/22/2010 Y

Mitigation Measure in Compliance? Y
compliance

All MMs and APMs were in compliance throughout the day

Alpine Yards

11/22/2010 Y

Mitigation Measure in Compliance? Y
compliance

the construction yard is in compliance with all APMs and the mitigation measures were met

upper Alpine construction yard

11/24/2010 Y

Mitigation Measure in Compliance? Y

PAR excavated and backfilled one 2x2 hole to verify location of underground utilities. No vegetation was impacted by work activities and all required monitors were on site.

Link 4 underground west of Peutz Valley Rd.

Remarks: All activities remained within approved work areas.

11/24/2010 Y

Mitigation Measure in Compliance? Y
Compliance

Remarks: All construction activities were within compliance with the SRPL MMCRP.

Link 4 underground Alpine Blvd.

C-1e

11/24/2010 Y

Mitigation Measure in Compliance? Y

No cultural material was observed

Western edge of Section 4

LINK: ALL

B-1c

11/23/2010 Y

Mitigation Measure in Compliance? Y
compliance

no activities took place at the construction yard that violated the mitigation measures or APMs

Rough Acres Construction Yard

11/23/2010 Y

Mitigation Measure in Compliance? Y
compliance

all activities complied with the mitigation measures and the APMs

upper Alpine construction yard

Sunrise Powerlink Transmission Project

Weekly Monitoring Report No. 00010

From: 11/21/2010 Through: 11/27/2010

ENVIRONMENTAL COMPLIANCE

Mitigation Measure Date	A (Y/N)	B Species	C Loc UTM Lat-Long	D Cause	E Issue	F Action	G Comments	H Tower
LINK: ALL								
BIO-APM-3								
11/23/2010	Y						A water truck was used to keep the soil moist with the high winds and all vehicle operators obeyed the 5 mph speed limit to eliminate fugitive dust	Rough Acres Ranch
Mitigation Measure in Compliance? Y								
dust								
LINK: NA								
B-1c								
11/22/2010	Y						Remarks: Checked trenches for wildlife.	SLR Sub Station
Mitigation Measure in Compliance? Y								
11/22/2010	Y						Conducted biological monitoring Remarks: Conducted biological monitoring	Encina Substation
Mitigation Measure in Compliance? Y								
BIO monitoring								
11/23/2010	Y						Remarks: Checked trenches for wildlife.	SLR Sub Station
Mitigation Measure in Compliance? Y								
11/24/2010	Y						Remarks: Checked trenches for wildlife.	SLR Sub Station
Mitigation Measure in Compliance? Y								
N-1a								
11/22/2010	N						Remarks: No excessive idling of vehicles.	SLR Sub Station
Mitigation Measure in Compliance? Y								
11/23/2010	N						Remarks: No excessive idling of vehicles.	SLR Sub Station
Mitigation Measure in Compliance? Y								
11/24/2010	N						Remarks: No excessive idling of vehicles.	SLR Sub Station
Mitigation Measure in Compliance? Y								