

October 10, 2011

## **I. REPRESENTATIVES, LOCATIONS AND DATES**

### **LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region**

- Ms. Darlene Mack, Campo, served as monitor on October 3. Her report has yet to be received.
- Mr. Ed Mercado of La Posta served as monitor on October 3 and 7.
- Ms. Andrea Najera, Campo, served as monitor on October 4. Her reports have yet to be received.
- Mr. Phillip Paipa, Campo, served as monitor for October 5.
- Mr. Carlos Quevedo, Campo, served as monitor for October 6 and 7.
- Mr. Bert Quihuis, Campo, served as monitor for October 3 through 6.
- Mr. Frank Salazar III, Campo, served as monitor on October 5 and 7.
- Mr. Santiago Santos, Manzanita, served as monitor from October 3 through 7.
- Ms. Veronica Santos, Manzanita, served as monitor from October 3 through 7.
- Mr. Ethian Thomas of Cocopah served as monitor from October 4 through 9.
- Mr. David Thompson, Manzanita, served as monitor on October 6 and 7.
- Mr. Daniel Tsosie, Campo, served as monitor on October 4, 5, and 6.
- Mr. Boe Willey of Manzanita served as monitor on October 4 and 5.

### **LINK 2: Bartlett-Hauser Yard/ Kreutzkamp Yard**

- Mr. Ed Mercado of La Posta served as monitor on October 8.
- Mr. David Thompson of Manzanita served as monitor on October 8.
- Mr. Larry Sutton of Viejas served as monitor on October 8.

### **LINK 3: Suncrest Substation**

- No monitors required at this location for this week.

### **LINK 4: Alpine Underground**

- Mr. Larry Sutton, Viejas, served as monitor on October 7.
- Ms. Vera Tucker, Viejas, served as monitor on October 3, 5 and 6. Her reports have yet to be received.

### **LINK 5: Various Locations**

- No monitors required at this location for this week.

---

## **II. CONSTRUCTION ACTIVITIES**

### **LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region**

Activities along this Link this week consist of rough road grading, brush clearing, drilling, moving boulders,

### **LINK 2: Bartlett-Hauser Yard**

Brush clearing and wood chipping, and grading are the activities reported from this Link this week.

**LINK 3: Suncrest Substation**

No monitors required at this location for this week.

**LINK 4: Alpine Underground**

No monitors required at this location for this week.

**LINK 5: Various Locations**

Wood chipping, trenching, grading, excavating, and clearing vegetation.

---

**III. OBSERVATIONS**

**LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region**

Mr. Paipa noted observing ceramic with a design on it on October 5.

On October 5, Mr. Salazar noted “medium density lithics. Medium density ceramics. Low density groundstone/milling. Rock shelters.” On the 7<sup>th</sup> he reported similar materials.

Mr. Santos noted that a piece of ceramic was identified, GPS’d and collected on October 5.

On October 6, Ms. Santos noted and collected 18 flakes including volcanic, quartzite, and quartz specimens found in a pullsite area. The artifacts were collected and a small ESA was established nearby.

On October 8, Mr. Thomas located a feature consisting of a circle of stones inside of which was a barrel cactus. He also identified flakes and shatter, all of which were out of the construction area. On October 9, he noted two chipping stations, two flakes, and a scraper.

**LINK 2: Bartlett-Hauser Yard**

On October 8, Mr. Thompson noted a “chipping place” near an ESA.

**LINK 3: Suncrest Substation**

No monitors required at this location for this week.

**LINK 4: Alpine Underground**

No monitors required at this location for this week.

**LINK 5: Various Locations**

No cultural material observed this week.

---

**IV. CONCERNS EXPRESSED**

**LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region**

Ms. Santos noted that direct impact areas should be better surveyed.

---



Mr. Thompson noted on October 7 that three Border Patrol agents on ATV's were driving through an ESA.

**LINK 2: Bartlett-Hauser Yard**

No concerns expressed this week.

**LINK 3: Suncrest Substation**

No concerns expressed this week.

**LINK 4: Alpine Underground**

No concerns expressed this week.

**LINK 5: Various Locations**

No concerns expressed this week.

---

**V. SUMMARY**

Most of the construction efforts this week are located along Link 1 in the plateau region west of the desert. As such many artifacts were identified this week in comparison to recent weeks passed. As a result, one concern was made that the construction areas be surveyed more thoroughly.

---

**VI. SUMMARY PREPARER**

Hillary Murphy, Project Archaeologist, Tierra Environmental Services, Inc.  
Joseph M. Nixon, Senior Anthropologist, Tierra Environmental Services, Inc.  
Kyle Stankowski, Associate Archaeologist, Tierra Environmental Services, Inc.