

December 12, 2011

I. REPRESENTATIVES, LOCATIONS AND DATES

LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region

- Mr. Clarence Brown of Viejas served as monitor on December 6.
- Mr. Jonathon Jones, Campo, served as monitor on December 9 and 10.
- Mr. Ed Mercado, La Posta, served as monitor on December 5 through 10.
- Ms. Andrea Najera, Campo, served as monitor on December 7 and 8.
- Mr. Phillip Paipa of Campo served as monitor on December 9.
- Mr. Frank Salazar III of Campo served as monitor on December 10.
- Mr. Santiago Santos, Manzanita, served as monitor on December 5, 7, 8, and 10.
- Ms. Veronica Santos, Manzanita, served as monitor on December 5 through 10.
- Mr. Larry Sutton, Viejas, served as monitor on December 9.
- Mr. David Thompson, Manzanita, served as monitor on December 5, 6, 7, and 9.
- Mr. Dan Tsosie of Campo, served as monitor on December 8 and 11.
- Mr. Boe Willey served as monitor on December 6.

LINK 2: Bartlett-Hauser Yard, Kreutzkamp Yard, Thing Valley Yard

- Mr. Clarence Brown of Viejas served as monitor on December 5 and 7.
- Mr. Frank Brown, Viejas, served as monitor on December 9 and 10.
- Mr. Josh Craddock, Viejas, served as monitor December 6.
- Mr. Jonathan Jones of Campo served as monitor on December 8.
- Ms. Mistie Okwusogu of Campo served as monitor on December 5 and 7.
- Mr. Phillip Paipa served as monitor on December 6 and 9.
- Mr. Jesse Pinto, Jamul, served as monitor on December 6, 7 and 10. His logs have yet to be received.
- Mr. Frank Salazar III of Campo served as monitor on December 8 and 9.
- Mr. Larry Sutton, Viejas, served as monitor on December 8.
- Mr. Boe Willey of Manzanita served as monitor on December 8.

LINK 3: Suncrest Substation & Wilson Yard

- No monitors scheduled on this Link for this week.

LINK 4: Alpine Underground

- Mr. Clarence Brown, Viejas, served as monitor on December 8 and 9.
- Mr. Josh Craddock, Viejas, served as monitor December 5.

LINK 5: Various Locations

- No monitors scheduled on this Link for this week.

II. CONSTRUCTION ACTIVITIES

LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region

Construction activities noted along this Link for this week include grading, tree trimming, pole netting, drilling, construction, ground resistance testing, blasting, and tower assembly.

LINK 2: Bartlett-Hauser Yard, Kreutzkamp Yard, Thing Valley Yard

Activities along this link consisted of hand excavation, drilling, breaking rock, watering, lifting, grading, drilling, fencing, and tree and brush trimming.

LINK 3: Suncrest Substation & Wilson Yard

No monitors scheduled on this Link for this week.

LINK 4: Alpine Underground

Activities along this link consisted of minor archaeological testing and excavation.

LINK 5: Various Locations

No monitors scheduled on this Link for this week.

III. OBSERVATIONS

LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region

A few established ESAs and recorded cultural sites were noted nearby in some cases.

On December 9, Mr. Sutton notes identifying a “look out rock – marker rock.”

LINK 2: Bartlett-Hauser Yard, Kreutzkamp Yard, Thing Valley Yard

On December 8, Mr. Sutton noted five pieces of lithic scatter.

LINK 3: Suncrest Substation & Wilson Yard

No monitors scheduled on this Link for this week.

LINK 4: Alpine Underground

No cultural materials noted on this Link for this week.

LINK 5: Various Locations

No monitors scheduled on this Link for this week.

IV. CONCERNS EXPRESSED

LINK 1: Jacumba Valley, McCain Valley, Boulevard, Plaster City, and Ocotillo Desert Region

On December 10, Mr. Santos expressed that work crews need to keep out of the established ESAs.

Ms. Santos notes on December 7, 8, 9, 10 that there need to be more frequent restroom facilities and that she doesn't feel the location where she was watching drilling activities warrants monitoring as they were drilling in rock apparently.

Mr. Thompson, December 6, felt that the wire being pulled across the ground should not be handled in such a manner to disturb the surface and potential artifacts in the path.

LINK 2: Bartlett-Hauser Yard, Kreutzkamp Yard, Thing Valley Yard

On December 9, Mr. F Brown noted eastern winds and expressed fire concerns as a result. Additionally, he telephoned me about this and I sent emails to SDGE who said they would contact Mr. Brown directly.

LINK 3: Suncrest Substation & Wilson Yard

No monitors scheduled on this Link for this week.

LINK 4: Alpine Underground

No concerns expressed on this Link for this week.

LINK 5: Various Locations

No monitors scheduled on this Link for this week.

V. SUMMARY

Very few resources were noted along the Powerlink this week. A few concerns were made in regard to the convenience of restroom facilities, potential fire risk, the dragging of wire across pads, crew members remaining outside of ESAs, and the drilling of rock not being necessary for monitoring efforts.

VI. SUMMARY PREPARER

Hillary Murphy, Project Archaeologist, Tierra Environmental Services, Inc.
Joseph M. Nixon, Senior Anthropologist, Tierra Environmental Services, Inc.
Kyle Stankowski, Associate Archaeologist, Tierra Environmental Services, Inc.