

Southern California Edison
RTRP A.15-04-013

DATA REQUEST SET A1504013 ED-SCE-02

To: CPUC

Prepared by: Gary Busteed

Title: Sr. Environmental Project Manager

Dated: 03/14/2017

Question Cul-1:

Provide GIS data to confirm that the marshalling yard at Etiwanda Avenue has been adequately surveyed for cultural and paleontological resources.

In Data Request #1 (entry number 10), dated March 9, 2016, the CPUC requested cultural resource GIS survey data for locations along the proposed project alignment that have not been adequately surveyed. Please confirm that the staging yard at Etiwanda Avenue has been adequately surveyed and provide additional GIS data and survey results as necessary.

Response to Question Cul-1:

The Etiwanda Avenue staging yard was surveyed for cultural resources. The GIS survey layers are provided in SCE's response to question Cul-2 of this Data Request.

Southern California Edison
RTRP A.15-04-013

DATA REQUEST SET A1504013 ED-SCE-02

To: CPUC

Prepared by: Gary Busteed

Title: Sr. Environmental Project Manager

Dated: 03/14/2017

Question Cul-2:

Provide GIS data to confirm that the GDAD areas have been adequately surveyed for cultural and paleontological resources.

The CPUC has received the addendum to SCE's Riverside Transmission Reliability Project cultural report that covers the areas identified in the gap analysis. Please confirm that all GDAD areas which might include ground disturbance have been adequately surveyed and provide additional GIS data and survey results as necessary. Identify any areas that have not been surveyed due to access restrictions.

Response to Question Cul-2:

Attached below are the GIS survey area boundaries that include the GDAD areas and laydown yards. The confidential survey results will be shared in a separate transmittal to the appropriate CPUC Cultural Resource specialist.