

# PROJECT MEMORANDUM SYCAMORE-PEÑASQUITOS 230-KV TRANSMISSION LINE PROJECT

Date:	December 15, 2017
To:	Billie Blanchard, CPUC Project Manager
From:	Sheila Hoyer, CPUC Monitoring Supervisor
Subject:	Weekly Report #49 – December 4 to December 9, 2017

## **INTRODUCTION**

This report provides a summary of the construction and compliance activities associated with the SDG&E Sycamore-Peñasquitos 230-kV Transmission Line Project for the week of December 4 to December 9, 2017.

A summary of the Notices to Proceed, Minor Project Refinement, and Temporary Extra Workspace Requests are provided in Tables 1, 2, and 3, respectively. A summary of Noncompliance, Project Memoranda and Incidents is provided in Table 4. Daily Inspection Reports are provided in Appendix A.

CPUC/Panorama Environmental Monitors (EMs): No inspections were performed during this reporting period due to the restricted construction required by the Red Flag Warnings

## **STAGING YARDS**

Summary of Activity:

#### **Stonebridge Staging Yard:**

1. Inspecting BMPs.

#### **Driving Range Staging Yard:**

1. Delivering and removing materials and equipment; and maintaining BMPs.

#### **Vulcan Staging Yard:**

1. No activity.

#### **Crestmar Point Staging Area:**

1. Delivering materials and equipment; and inspecting BMPs.

## **Underground Transmission Line:**

1. Nighttime construction in Segment 5 along Sections 18 through 20 (approximately at Stations 295+00 to 312+00): Mandreling conduit.

2. Daytime construction in Segment 3 in Sections 5 through 14 (approximately at Stations 86+00 to 244+00): Installing cable and bracketing within vaults.

## **Overhead Transmission Line:**

1. No activity.

## Peñasquitos Substation:

1. No activity.

## Sycamore Substation:

1. Backfilling conduit trench on December 5, 2017; however, due to the Red Flag Warning, these activities ceased on the same day.

Environmental Compliance:

- 1. All pavement was kept clean during this reporting period. No winds occurred that were higher than 20 mph. All off-road diesel-powered construction equipment met a minimum of EPA Tier 3 standards.
- 2. Monitoring for special-status species was implemented to avoid and minimize impacts to biological resources. No special-status species were observed during the monitoring period. All project equipment arrived clean and free of mud and/or vegetation.
- 3. During this reporting period, there were no ground-disturbing activities occurring; therefore, there were no archaeological, paleontological, and/or Native American monitors on site.
- 4. No hazardous materials releases occurred during this reporting period.
- 5. All construction activities occurred in accordance with the approved Construction Fire Prevention Plan. All construction vehicles were equipped with the required fire tools. During this reporting period, a Red Flag Warning was issued by the National Weather Service on December 4 through December 9, 2017, for the Inland & Coastal Orange County (Zones 552 & 554) and the San Diego County Coast (Zone 243). These zones cover the entirety of the Project work areas. In accordance with the Fire Plan, construction activities were restricted from December 4 through December 9, 2017, at 8:00 P.M. However, per the approval of the SDG&E Fire Coordinator and in accordance with the Fire Plan, the following activities were allowed to continue during this time: equipment deliveries into the Crestmar and Driving Range Staging Yards, nighttime mandreling within the vaults, and daytime cable installation and bracketing. No fire incidents were reported during this reporting period.
- 6. Daytime underground construction activities occurred Monday through Friday, from 8:30 am to 3:30 pm. Nighttime underground construction activities occurred Sunday through Thursday, from 9:00 pm to 5:00 am. Daytime and nighttime construction activities occurred in accordance with the City of San Diego approved Traffic Control Permits.
- 7. Project personnel parked their personal vehicles within a designated personal vehicle parking area within the project limits within the Stonebridge Staging Yard. Workers parked within the work limits of the Driving Range Staging Yard or parked on the adjacent public street. Traffic Control Permits were obtained from the City of San Diego.

- 8. The QSP conducted required daily inspections during this reporting period. A vacuum was used to collect excess water, and a street sweeper was used to clean up excess sediment/dust during sawcutting activities. All equipment staged along the ROW, at the overhead sites, and stored in the staging yards, had drip pans or absorbent pads in place to capture oil drips/leaks. No housekeeping items were noted by the QSP during this reporting period.
- 9. All construction and compliance personnel on site during this reporting period completed the Project Safety and Environmental Awareness Program (SEAP). To date, approximately 1,613 project personnel have received the required SEAP training, and 1,509 project personnel have received the UXO training.
- 10. There were no Compliance Level Incidents during this reporting period.
- 11. No complaints were received during this reporting period.

#### Agency Representatives during Construction (other than CPUC EMs): None

#### **CPUC NOTICES TO PROCEED (NTPs)**

CPUC NTPs

Table 1

Table 1 summarizes the CPUC NTP activity for the SDG&E Sycamore-Peñasquitos 230-kV Transmission Line Project to date.

	CFUC INF3			
NTP #	Date Submitted	Date Issued	Segment #	Description
1	12/05/16	12/29/16	N/A	Mobilize and begin operations at the construction staging yards.
2	01/23/17	02/07/17	Segment B	Construct the underground portion of the Project from Sycamore Substation to Structure P03, and from Structure P05 to Structure CC MM CP.
3	02/03/17	02/27/17	Segment A Segment C	<ol> <li>Overhead construction from Sycamore Substation to Structure P06</li> <li>Overhead construction from Structure CC MM CP to the Peñasquitos Substation</li> <li>Deenwoll AC mitigation installation</li> </ol>
				<ol> <li>Deepwell AC mitigation installation</li> <li>Construction activities at Sycamore Canyon and Peñasquitos Substations</li> </ol>

## MINOR PROJECT REFINEMENT & TEMPORARY EXTRA WORKSPACE REQUESTS

Tables 2 and 3 summarize the Minor Project Refinements (MPRs) and Temporary Extra Workspace (TEWS) Requests have been submitted to date.

MPR Request	Date Submitted	Date Issued	Segment #	Description
#1	12/06/16	1/11/17	Segment A	Underground 230-kV getaway from Sycamore Substation to Structure P03.
#2	01/17/17	01/24/17	Segment B	Realignment of the 230-kV underground transmission line from Miramar Road north on Black Mountain Road and west on Activity Road.
#3	03/06/17	03/08/17	Segment A	Provides temporary power to the SDG&E trailer at the Stonebridge Staging Yard through the existing power box located outside of the existing Project boundary.
#4	04/18/17	04/20/17	Segment B	Modifies the approved 2.61-acre Vulcan Mine Yard location approximately 884 feet to the west to an approximately 1.71-acre paved area.
#5	07/10/17	07/11/17	Segment B	Establishes staging yards along southern perimeter of Pomerado Road and temporary work spaces north of P05 and P06
#6	08/03/17	08/04/17	Segment B	Establishes staging yards along southern and northern perimeters of Pomerado Road
#7	08/25/17	08/28/17	Segments B, C	Establishes a staging yard at the southwest corner of the intersection of Pomerado Road and Avenue of Nations (previously approved in TEWS #1), and extends the temporary work space surrounding Structure E40
#8	09/12/17	Denied	South of Segment C	Adds temporary work areas around 16 poles and 14 guard structures south of Carroll Canyon Road and east of Interstate 805. The refinement area extends approximately 2 miles south of CC MM CP
#9	10/06/17	10/11/17	Segment B	Adds a paved, developed area off Crestmar Point for use as a staging area for vehicles and construction equipment.
#10	11/29/17	11/29/17	Segment B	Authorizes a newly identified underground route option for the crossing of Interstate-15, using a tunnel bore machine to install the 230-kV line
#11	11/22/17	11/29/17	Segment A	Adds approximately 0.13 acre of temporary work space to accommodate the installation of the 138-kV and 230-kV trench packages north of Sycamore Canyon Substation

 Table 2
 Minor Project Refinement (MPR) Requests

TEWS Request	Date Submitted	Date Issued	Segment #	Description
#1	06/29/17	07/05/17	В	Additional staging area located at the southwest corner of the intersection of Pomerado Road and Avenue of Nations
#2	07/19/17	07/19/17	В	Addition to approved temporary work area on Pomerado Road.
#3	09/02/17	09/04/17	С	New location for temporary guard structure 06 in a paved parking lot at the intersection of Lusk Blvd. and Wateridge Circle.

#### Table 3 Temporary Extra Workspace (TEWS) Requests

## NON-COMPLIANCES, PROJECT MEMORANDA & INCIDENTS

There were no non-compliances, memoranda or incidents reported during this reporting period.

Table 4	Non-Compliances, Project Memoranda, and Other Incidents				
Туре	Date	Location	Description		
Level 1	04/12/2017	Segment B	Potable water was used in a street sweeper		
Memoranda	04/19/2017	Segment B	Traffic incident at Driving Range Staging Yard		
Level 1	04/24/2017	Segment B	Presence of trash along the project alignment		
Level 1	05/01/2017	Segment B	Working outside of City-approved hours		
Memoranda	05/03/2017	Segment B	Traffic incident at Snapple/7-Up Plant		
Memoranda	05/18/2017	Segment B	Traffic incident at Station 169+89		
Memoranda	05/23/2017	Segment B	Unauthorized non-stormwater discharge		
Level 1	06/08/2017	Segment B	Non-adherence to approved Fire Plan		
Level 2	06/15/2017	Segment B	Non-adherence to approved Fire Plan		
Memoranda	07/06/2017	Segment B	Traffic incident at Carroll Canyon Road		
Level 1	07/20/2017	Segment B	Non-adherence to approved Fire Plan		
Memoranda	07/20/2017	Segment B	Traffic incident at Miralani Drive		
Memoranda	08/03/2017	Segment B	Traffic incident at Pomerado Road		
Memoranda	08/10/2017	Segment B	Unauthorized non-stormwater discharge		
Level 1	08/16/2017	Segment B	Staging equipment outside of approved limits		

#### Table 4 Non Compliances Project Memoranda, and Other Incidents

Туре	Date	Location	Description
Level 3	08/28/2017	Segment B	Non-adherence to approved Fire Plan Non-adherence to SEAP training requirement Working outside of approved limits
Level 1	08/29/2017	Segment C	Driving equipment on non-approved access road
Memoranda	09/07/2017	Segment B	Unauthorized non-stormwater discharge
Memoranda	09/14/2017	Segment B	Spot fire on Pomerado Road caused by grinding activity spark